

Customer	KOLA
Unit No	D107-002
Work Order	7907972

PARTS SIGN-OUT | ALIDA, SK

[illegible]



Scheduled 250HR Truck
Inspection "A" Maintenance Report

Date Sept 28/2024
Unit # 107-002
Plate # _____
Tank Inspection Expires
V _____ K _____ I _____ P _____ L _____ T _____

Odometer _____ Inspection "A" _____
Truck Hours _____ WO# _____
CVIP Expiry _____

Inspection "A"	OK	Repaired	Inspection "A"	OK	Repaired
Chassis	✓		Power Steering Level	✓	
Check All Lights	✓		Exhaust Rubbers	✓	
Cab Cleanliness	✓		Transmission Leaks	✓	
Low Air Warning Device	✓		Diff Leaks - 1	✓	
Radiator & Heater Hoses	✓		Diff Leaks - 2	✓	
Oil Leaks, Fuel Leaks	✓		Diff Leaks - 3	✓	
Steering Linkage	✓		Windshield Washer Level	✓	
Brake Adjustment	✓		Motor Oil Level	✓	
Suspension Inspection	✓		Rear Shocks	✓	
Air Leaks	✓		Dust Shields	✓	
Windows & Mirrors (S.7)	✓		Mud Flaps	✓	
Tires, Wheels, Rims & Hubs (S.28)	✓		Body Damage	✓	
Retorque Lug Nuts	✓		Fan Belt	✓	
Greased	✓		A/C Belt	✓	
All Fittings Taking Grease	✓		ABS Light On	✓	
Front Shocks	✓		Check Engine Light On	✓	
Front Wheel Oil Level	✓		Alcohol Evaporator Level	✓	
Coolant Level	✓		Fire Extinguisher Bracket	✓	
License Plate Condition	✓		Fire Extinguisher Expiry	✓	

Tire Pressures:			
<u>100</u>	<u>100</u>	<u>100</u>	<u>100</u>
<u>100</u>	<u>100</u>	<u>100</u>	<u>100</u>

Comments:

P/S leak, added 1L of oil, press front lining cover leak
Hydraulic leak underneath



I certify that I have inspected all the above mentioned components. I also certify that I have completed all necessary repairs.

Deacon Eilers
Mechanic Name

[Signature]
Mechanic Signature

Entered in Maestro :



WORK ORDER

Unit # 107-002-

Date: APRIL-13-2022

BRUCE WARREN

Person requesting Repairs (please print)

[Signature]

Signature

REPAIRS NEEDED:

ENGINE FAN SOLINOID STICKS

WORK PERFORMED:

REPLACE ENG FAN SOLINOID

Lock out procedures followed:

Yes ☒

No ☐

Lock out performed by:

BRUCE WARREN

Initial: BW

Air quality has been tested (if applicable)

Yes ☐

No ☒

Date repairs completed:

APRIL-13-2022

Odometer Reading:

96124

Hour Reading

8069

BRUCE WARREN

Repairs completed by (please print)

[Signature]

Signature

[Signature]



WORK ORDER

Unit # 107-002

Date: April 12/2022

Ged Vandenberg

Person requesting Repairs (please print)

[Signature]

Signature

REPAIRS NEEDED:

WORK PERFORMED:

- diagnose no power to PTO, repaired wiring by PTO solenoid and replaced fuses in panel and repaired connection on PTO switch
- replaced drivers door inside door latch handle
- replaced hydraulic handle mount on control tank
- put coupler ends on wash hose and wash gun
- put spare steam wand in van

Lock out procedures followed:

Yes ☒

No ☐

Lock out performed by:

Terry Doble

Initial: TD

Air quality has been tested (if applicable)

Yes ☐

No ☒

Date repairs completed:

April 12/2022

Odometer Reading: 96123 km

Hour Reading 8068 hr

Terry Doble

Repairs completed by (please print)

[Signature]

Signature

Ged



VERTEX

WORK ORDER

Unit # 107-002

Date: Aug 28/21

John Stewart

Person requesting Repairs (please print)

[Signature]

Signature

REPAIRS NEEDED:

coil and flow ~~meter~~ valve ~~is~~ for Hotsy need to
be replaced

WORK PERFORMED:

- R&R coil and coil wrap
- replaced and cleaned ignitor electrodes
- replaced plumbing fittings
- replaced flow control ~~valve~~
- test repairs with water

Lock out procedures followed:

Yes ☒

No ☐

Lock out performed by:

Terry Doble

Initial: TD

Air quality has been tested (if applicable)

Yes ☐

No ☒

Date repairs completed:

Aug 31/2021

Odometer Reading: 72056 kpm

Hour Reading 7763 hr

Terry Doble

Repairs completed by (please print)

Signature

[Signature]
OK Gedd

Monitor Daily Bump Log

Monitor Unit Number or Serial Number	Name	Monitor Bumped Yes/No	Date
5495	John Stewart	Yes	Aug 20/2021
5490	Leah Saucy	YES	Aug 20/21
5349	CODY HUBER	YES BUMP AND CALIBRATION	AUG 20/21
5382	Ken Kozuch	Yes/ Cal	Aug 21/21
5569	Jason	yes	Aug 21 /2021
5499	GLENN	YES	08 21 21
5569	Jason	yes	Aug 22 21
5382	Ken	Yes	Aug 22/21
5499	GLENN	YES	AUG/22/21
5377	SHAUN GIBSON	YES	AUGUST 23RD/21
5382	Ken Kozuch	Yes	Aug 23/2021
5499	GLENN	YES	AUG/23/21
6180	Ed	Yes	Aug. 23/21
5499	GLENN	YES	AUG/24/21
6180	Ed	Yes	Aug. 24/21
5382	Ken	Yes	" "
5569	Jason	yes	Aug 25 2021
5490	Leah	YES Bump & Calibration	Aug 25, 2021
5377	SHAUN GIBSON	YES	AUGUST 25th/2021
	JASON YARR	Yes	Aug 25 /2021
5499	GLENN	YES	AUG/25/21
6180	Ed	yes	Aug. 25/21

light years

VEHICLE PRE/POST TRIP INSPECTION REPORT

To be completed at the beginning and end of each shift.



DATE Aug 17, 2021 TIME 4:30 AM

LOCATION OF INSPECTION 4428-49 Ave Brockton

DRIVER Leah Sweeney

PLEASE PRINT FULL NAME

UNIT # 101-002 TRAILER # ---

MAKE OF MOTOR VEHICLE Peterbilt

TYPE MOTOR VEHICLE: ☐ Truck / Tractor ☐ Trailer

WINTER SEASON ONLY - WINTERIZED EQUIPMENT PRE-TRIP ☐ POST-TRIP ☐

LAST CONTAINED UN ---

MILEAGE START 7741
MILEAGE END 7748
HOURS START 91742
HOURS FINISH 91961

WORK ORDER # ---

CHECK DEFICIENT ITEMS ONLY

TRUCK

- Documents**
- ☐ Registration (Valid)
 - ☐ Pink Card (Valid)
 - ☐ Safety Fitness Certificate
 - ☐ MSD Sheets, Bill of Lading
 - ☐ Permits (Current)
 - ☐ Inspection Decal (Valid) CVIP

Safety Equipment

- ☐ Advance Warning Devices
- ☐ Fire Extinguisher
- ☐ First Aid Kit
- ☐ Flares - Flares - Fuses
- ☐ Tire Chock Blocks
- ☐ Tire Chains
- ☐ Doors/Emergency Exits
- ☐ Passenger Compartment

CAB

- ☐ Doors
- ☐ Defrost/Heater
- ☐ Horn (electric-air)
- ☐ Mirrors
- ☐ Seat Belt
- ☐ Steering Wheel
- ☐ Turn Indicators
- ☒ Windows/Wipers

Mechanical

- ☐ Air Gauge/Warning System
- ☐ Air Lines/Connections
- ☐ Axle/U-bolts
- ☐ Belts (Engine)
- ☐ Body/Fenders

POST

- ☐ Brakes 2" (1.5 B.C.)
- ☐ Clutch
- ☐ Compressor
- ☐ Driveline
- ☐ Fifth Wheel/Allowable Movement
- ☐ Fluids (Engine)
- ☐ Frame
- ☐ Fuel Tanks (System)
- ☐ Governor cut out
- ☐ Mud Flaps / Fenders
- ☐ Springs/Suspension (System)
- ☐ Steering Components
- ☐ Tires/Wheels/Rims/Fasteners
- ☐ Tractor Protection Valve
- ☐ Wing Bolts (Vac Unit)
- ☐ Exhaust System

LIGHTS

- ☐ Head
- ☐ I.D. Lights
- ☐ Reflectors
- ☐ Tail/Signal/Brake

TRAILER

- ☐ Hitch/Safety Chains/Cables
- ☐ Landing Gear
- ☐ Load Securement/Covering
- ☐ Springs/Suspension
- ☐ Tail Doors
- ☐ Tires/Wheels/Rims/Lug-Nuts

DANGEROUS GOODS

- ☐ Placards
- ☐ Tank Inspection

CARGO SECUREMENT

- ☐ Approved Device

NOTED DEFECTS:

- rock chip in window
- water hoses ~~are~~ broken (2nd)

* The inspection was conducted in accordance with NSC 13 Sch 1, Sch 2, Alberta Regulation AR121/2009, Saskatchewan Regulation H3.01 Reg 4, Ontario Regulation 199/07, Manitoba Regulation 95/08 & B.C. Reg. 304/2001; am. B.C. Reg. 135/2003.

PRE-TRIP

☐ NO DEFECTS FOUND DURING INSPECTION

[Signature]
DRIVER'S SIGNATURE

CHASSIS FUEL TANK ONLY

TIME	LOCATION (LEAVING PUBLIC RD / BORDER XING)	ODOMETER	FUEL UP		OIL ADDED
			LITRES	PROVINCE	
	End of the Day				
					COOLANT ADDED
	Start of the Day				

☐ ABOVE DEFECTS CORRECTED

☐ ABOVE EFFECTS NEED NOT BE CORRECTED FOR SAFE OPERATION OF VEHICLE

Signature of Authorized Repair Person

Date

069250



VERTEX

WORK ORDER

Unit # 107-002

Date: Aug 17, 2021

Leah Sorey

Person requesting repairs (please print)

Th Q

Signature

REPAIRS NEEDED:

- 2nd rail from bottom the pressure line is blown (broke)

WORK PERFORMED:

REPLACE WATER LINE FROM HOSTY TO
MIDDLE REEL,

Lock out procedures followed:

Yes

☒

No

☐

Lock out performed by:

BRUCE WARREN

Initial:

BW

Air quality has been tested (if applicable)

Yes

☐

No

☒

Date repairs completed:

AUG-24-2021

Odometer Reading:

91968

Hour Reading

~~91968~~ 7753

BRUCE WARREN

Repairs completed by (please print)

[Signature]

Signature

OG Geo



Scheduled 250HR Truck

Date	July-02-2021	Odometer	91050
Unit #	107-002	Hubometer	
Plate #	336 LSN.	Truck Hours	7661

Inspection "A" _____
WO # _____

[illegible][illegible]

Tire Pressures:

	100	100
100	96	100
100	100	100
	98	100

Comments:

Comments: REPLACE FIRE EXTINGUISHER

☒ I certify that I have inspected all the above mentioned components. I also certify that I have completed all necessary repairs.

BRUCE WARREN
Mechanic Name

Mechanic Signature

OK Good

VEHICLE PRE/POST TRIP INSPECTION REPORT

To be completed at the beginning and end of each shift.



DATE June 23, 2021 TIME 7:30am

LOCATION OF INSPECTION 4428-49 Ave Bycroft AB

DRIVER Leah Soong
PLEASE PRINT FULL NAME

UNIT # 167-002 TRAILER #

MAKE OF MOTOR VEHICLE Peterbilt

TYPE MOTOR VEHICLE: ☐ Truck / Tractor ☐ Trailer

WINTER SEASON ONLY - WINTERIZED EQUIPMENT PRE-TRIP ☐ POST-TRIP ☐

LAST CONTAINED UN

MILEAGE START 7654
MILEAGE END 7661
HOURS START 90969
HOURS FINISH 91049

WORK ORDER #

CHECK DEFICIENT ITEMS ONLY

TRUCK

- ☐ ☐ Documents
☐ Registration (Valid)
☐ Pink Card (Valid)
☐ Safety Fitness Certificate
☐ MSD Sheets, Bill of Lading
☐ Permits (Current)
☐ Inspection Decal (Valid) CVIP

Safety Equipment

- ☐ Advance Warning Devices
☐ Fire Extinguisher
☐ First Aid Kit
☐ Flags - Flares - Fuses
☐ Tire Chock Blocks
☐ Tire Chains
☐ Doors/Emergency Exits
☐ Passenger Compartment

CAB

- ☐ ☐ Doors
☐ Defrost/Heater
☐ Horn (electric-air)
☐ Mirrors
☐ Seat Belt
☐ Steering Wheel
☐ Turn Indicators
☒ Windows/Wipers

Mechanical

- ☐ Air Gauge/Warning System
☐ Air Lines/Connections
☐ Axle/U-bolts
☐ Belts (Engine)
☐ Body/Fenders

POST

- ☐ Brakes 2" (1.5 B.C.)
☐ Clutch
☐ Compressor
☐ Driveline
☐ Fifth Wheel/Allowable Movement
☐ Fluids (Engine)
☐ Frame
☐ Fuel Tanks (System)
☐ Governor cut out
☐ Mud Flaps / Fenders
☐ Springs/Suspension (System)
☐ Steering Components
☐ Tires/Wheels/Rims/Fasteners
☐ Tractor Protection Valve
☐ Wing Bolts (Vac Unit)
☐ Exhaust System

LIGHTS

- ☐ Head
☐ I.D. Lights
☐ Reflectors
☐ Tail/Signal/Brake

TRAILER

- ☐ Hitch/Safety Chains/Cables
☐ Landing Gear
☐ Load Securement/Covering
☐ Springs/Suspension
☐ Tail Doors
☐ Tires/Wheels/Rims/Lug-Nuts

DANGEROUS GOODS

- ☐ Placards
☐ Tank Inspection

CARGO SECUREMENT

- ☐ Approved Device

NOTED DEFECTS:

rock chip in window

* The inspection was conducted in accordance with NSC 13 Sch 1, Sch 2, Alberta Regulation AR121/2009, Saskatchewan Regulation H3.01 Reg 4, Ontario Regulation 199/07, Manitoba Regulation 95/08 & B.C. Reg. 304/2001; am. B.C. Reg. 135/2003.

PRE-TRIP POST-TRIP

☐ NO DEFECTS FOUND DURING INSPECTION

hh
DRIVER'S SIGNATURE

CHASSIS FUEL TANK ONLY

TIME	LOCATION (LEAVING PUBLIC RD / BORDER XING)	ODOMETER	FUEL UP		OIL ADDED
			LITRES	PROVINCE	
	End of the Day				
					COOLANT ADDED
	Start of the Day				

☐ ABOVE DEFECTS CORRECTED

☐ ABOVE EFFECTS NEED NOT BE CORRECTED FOR SAFE OPERATION OF VEHICLE

Signature of Authorized Repair Person

Date

069226



WORK ORDER

Unit # 107002

Date: 6 APR 21

Darrel Anderson

Person requesting Repairs (please print)

Signature

REPAIRS NEEDED:

leak on tank. Hydraulic tank

WORK PERFORMED:

-tightened fittings on tank sight glass

Lock out procedures followed:

Yes ☒

No ☐

Lock out performed by:

Terry Dose

Initial: TD

Air quality has been tested (if applicable)

Yes ☐

No ☒

Date repairs completed:

April 30/2021

Odometer Reading: 90170

Hour Reading 7573

Terry Dose

Repairs completed by (please print)

Signature

TD Gedd



WORK ORDER

Unit # 107-002

Date: Mar 18/2021

Geoff Vondeloo

Person requesting Repairs (please print)

[Signature]

Signature

REPAIRS NEEDED:

WORK PERFORMED:

- replaced two ~~the~~ wash hoses and ends
- put quick connect ends on wash guns
- rehooked hose to manifold from reel

Lock out procedures followed:

Yes ☒

No ☐

Lock out performed by:

Terry Doble

Initial: TD

Air quality has been tested (if applicable)

Yes ☐

No ☒

Date repairs completed:

Mar 17/2021

Odometer Reading: 89864 Km

Hour Reading 7548 hr

Terry Doble

Repairs completed by (please print)

[Signature]

Signature

[Signature]



Date Feb 17/2021
Unit # 107-002
Plate # 336 LSN

Odometer 88635 km
Hubometer _____
Truck Hours 7471 hr

Inspection "A" _____
WO # _____

[illegible][illegible]

100	100	
100 / 100	100 / 100	
100 / 100	100 / 100	

Comments:

- topped up washer fluid
- replaced spring in flow control valve to repair hydraulic leaks

☒ I certify that I have inspected all the above mentioned components. I also certify that I have completed all necessary repairs.

Terry Doble
Mechanic Name

Mechanic Signature _____



WORK ORDER

Unit # 107-002

Date: Feb 8/2021

Ged Vondel
Person requesting Repairs (please print)

[Signature]
Signature

REPAIRS NEEDED:

WORK PERFORMED:

- did acid flush after flushing pool with hotsy
- cleaned out manifold
- flushed acid out with water and flushed all plumbing
- test hotsy system through all hoses
- blew down complete system after test

Lock out procedures followed:

Yes ☒

No ☐

Lock out performed by:

Terry Dask

Initial: TD

Air quality has been tested (if applicable)

Yes ☐

No ☒

Date repairs completed:

Feb 8/2021

Odometer Reading:

87288 km

Hour Reading

7368 hr

Terry Dask Ben R
Repairs completed by (please print)

[Signature]
Signature