

TIS-1

03978849 PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspections
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-955-0920

Manitoba
A944349

Date Inspection Started: 11/3 DAY, 01/6 MO, 21/5 YR.
Date Inspection Completed: 11/4 DAY, 01/6 MO, 21/5 YR.
Inspection Expiry Date: 3/0 DAY, 01/6 MO, 21/6 YR.

Station Number: A161237 Highway Fleet Maintenance WPC
Mechanic Number: M11017910
Mechanic Signature: [Signature]
City: [Blank] Province: [Blank] Postal Code: [Blank] Phone: [Blank]

Vehicle Owner: PTS PRITCHARD TRANSPORT SERVICES LTD.
Address: [Blank] City: [Blank] Province: [Blank] Postal Code: [Blank] Phone: [Blank]

License Number: T1D441711 Prov. MB NSC # MB1102092
Vehicle Identification Number: 2121D1P1F31231717J10415181716
Make: L-KING Model: Fleet Year: 2007 Unit #: 427A

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P R Mark "X" under "P" item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

Section 1 - Power Train: Defects (if any)

Section 2 Suspension: Defects (if any)

Section 3 - Brake Systems: 3H (3A) Defects (if any) Circle Brake Type

Brake Inspection Type: (A) B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	NEW	NEW	16.570	16.571	1 1/4	1 1/4
2	NEW	NEW	16.571	16.570	1 1/4	1 1/4
3	11/16	11/16	16.570	16.572	1 1/4	1 1/4
4						
5						

Final Measurement

8.A SRS Valve Not operational proper
16.A 1st Axle Right Side S-Cam Bushings worn

Section 4 - Steering: Defects (if any)

Section 5 - Instruments & Auxiliary Equipment: Defects (if any)

Section 6 - Lamps: Defects (if any) 1st Marker Light Lens is clouded

Section 7 - Electrical System: Defects (if any)

Section 8 - Body: Defects (if any)

Section 9 - Tire & Wheel: Defects (if any)

Axle	Tread Depth 32nds				Air Pressure PSI			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	8	8	11	11	8	8	11	11
2	12	11	11	09	12	11	11	09
3	11	11	11	11	11	11	11	11
4								
5								

Section 10 - Coupling Devices: Defects (if any)