

04063781

PERIODIC MANDATORY VEHICLE  
INSPECTION CERTIFICATEManitoba Vehicle Safety  
Box 40044 Regent Postal Centre  
Winnipeg, MB, R2C 5C7  
1-204-985-0920Manitoba  C055960

Date Inspection Started: 26 01 216  
Date Inspection Completed: 26 01 216  
Inspection Expiry Date: 31 01 217

Station Number: A519512 Station Name: kmms LTD City: Virden  
Mechanic Number: M10208 Mechanic Signature: [Signature] Station Phone Number: 2048512038

Vehicle Owner: Integrity Maintenance Ltd  
Address: Box 275 City: Carleton Place Province: SK Postal Code: S0C0R0 Phone: [Blank]

License Number: 316104414 Prov: SK NSC #: 0026955 Odometer Reading: 98720 Odom. Type:  km  mi

Vehicle Identification Number: 1W1K1D1X1B1E1X1461R198191218 Make: Kw Model: T800 Year: 06 Unit #: 101

Pass/Safe Vehicle  
 Fail/Unsafe Vehicle  
 Fail/Hazardous

Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck  GWR  KGS  Truck Tractor  Trailer  Semi-Trailer  Bus  School Bus  Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

P	R	Section																																																																							
X		Section 1 - Power Train: Defects (if any)																																																																							
X		Section 2 Suspension: Defects (if any)																																																																							
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type																																																																							
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>.70</td> <td>.70</td> <td>16.52</td> <td>16.52</td> <td>2 1/2</td> <td>2 1/2</td> </tr> <tr> <td>2</td> <td>.60</td> <td>.40</td> <td>16.53</td> <td>16.57</td> <td>2 1/2</td> <td>2 1/2</td> </tr> <tr> <td>3</td> <td>.70</td> <td>.70</td> <td>16.54</td> <td>16.55</td> <td>2 1/2</td> <td>2 1/2</td> </tr> <tr> <td>4</td> <td>.60</td> <td>.50</td> <td>16.56</td> <td>16.57</td> <td>2 1/2</td> <td>2 1/2</td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	.70	.70	16.52	16.52	2 1/2	2 1/2	2	.60	.40	16.53	16.57	2 1/2	2 1/2	3	.70	.70	16.54	16.55	2 1/2	2 1/2	4	.60	.50	16.56	16.57	2 1/2	2 1/2	5																													
Axle	Lining			Drum/Rotor		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	.70	.70	16.52	16.52	2 1/2	2 1/2																																																																			
2	.60	.40	16.53	16.57	2 1/2	2 1/2																																																																			
3	.70	.70	16.54	16.55	2 1/2	2 1/2																																																																			
4	.60	.50	16.56	16.57	2 1/2	2 1/2																																																																			
5																																																																									
X		Section 4 - Steering: Defects (if any)																																																																							
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																							
X		Section 6 - Lamps: Defects (if any)																																																																							
X		Section 7 - Electrical System: Defects (if any)																																																																							
X		Section 8 - Body: Defects (if any)																																																																							
X		Section 9 - Tire & Wheel: Defects (if any)																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <td></td> <td>L</td> <td>R</td> <td>L</td> <td>R</td> <td>L</td> <td>R</td> <td>L</td> <td>R</td> </tr> </thead> <tbody> <tr> <td>1</td> <td>15</td> <td>12</td> <td></td> <td></td> <td>100</td> <td>100</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>24</td> <td>24</td> <td>30</td> <td>30</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td>25</td> <td>25</td> <td>30</td> <td>30</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>4</td> <td>29</td> <td>29</td> <td>29</td> <td>29</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	15	12			100	100			2	24	24	30	30	100	100	100	100	3	25	25	30	30	100	100	100	100	4	29	29	29	29	100	100	100	100	5								
Axle	Tread Depth				Air Pressure																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	15	12			100	100																																																																			
2	24	24	30	30	100	100	100	100																																																																	
3	25	25	30	30	100	100	100	100																																																																	
4	29	29	29	29	100	100	100	100																																																																	
5																																																																									
X		Section 10 - Coupling Devices: Defects (if any)																																																																							

- THIS INSPECTION IS NOT A WARRANTY -  
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: \_\_\_\_\_  
Signature

Date: \_\_\_\_\_