

03938162

PERIODIC MANDATORY VEHICLE  
INSPECTION CERTIFICATE

Manitoba



K18-3

Vehicle Standards and Ins.  
Box 45064 Regent Postal O.  
Winnipeg, MB, R2C 5C7  
1-204-955-0920

Manitoba



A931352

Date Inspection Started: DAY 26 MO. 05 YR. 25

Date Inspection Completed: DAY 26 MO. 05 YR. 25

Inspection Expiry Date: DAY 31 MO. 05 YR. 26

Station Number: A 61111

Mechanic Number: M 81115

Station Name: Regent Sales & Service Ltd.

Mechanic Signature: [Signature]

Station Phone Number: 268-565-1111

Vehicle Owner: LCB 66-1999-1999 SALES LTD

Address: City: Province: Postal Code: Phone:

- ☐ Pass/Safe Vehicle
- ☐ Fail/Unsafe Vehicle
- ☐ Fail/Hazardous

Licence Number: 71011737

Prov. MB

NSC #

Odometer Reading: -

Odom. Type: km mi

Vehicle Identification Number: 20517119831411799315

Make: MAZDA

Model: BULK

Year: 2001

Unit #: 321

☐ Confirmed legible Vehicle Identification Number on vehicle

## THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
X		Section 1 - Power Train: Defects (if any)																																																																						
		Section 2 Suspension: Defects (if any)																																																																						
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type																																																																						
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>1/2</td> <td>1/16</td> <td>16.554</td> <td>16.554</td> <td>1.5</td> <td>1.5</td> </tr> <tr> <td>2</td> <td>1/2</td> <td>1/2</td> <td>16.573</td> <td>16.573</td> <td>1.5</td> <td>1.5</td> </tr> <tr> <td>3</td> <td>9/16</td> <td>5/8</td> <td>16.554</td> <td>16.567</td> <td>1.5</td> <td>1.5</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> <td colspan="4">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	1/2	1/16	16.554	16.554	1.5	1.5	2	1/2	1/2	16.573	16.573	1.5	1.5	3	9/16	5/8	16.554	16.567	1.5	1.5	4							5										Final Measurement																		
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	1/2	1/16	16.554	16.554	1.5	1.5																																																																		
2	1/2	1/2	16.573	16.573	1.5	1.5																																																																		
3	9/16	5/8	16.554	16.567	1.5	1.5																																																																		
4																																																																								
5																																																																								
			Final Measurement																																																																					
X		Section 4 - Steering: Defects (if any)																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X	X	Section 6 - Lamps: Defects (if any) 6-2-2 No rear reflector w type																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X		Section 8 - Body: Defects (if any)																																																																						
X		Section 9 - Tire & Wheel: Defects (if any)																																																																						
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>11</td> <td>11</td> <td>10</td> <td>10</td> <td>110</td> <td>110</td> <td>110</td> <td>110</td> </tr> <tr> <td>2</td> <td>11</td> <td>11</td> <td>15</td> <td>15</td> <td>110</td> <td>110</td> <td>110</td> <td>110</td> </tr> <tr> <td>3</td> <td>10</td> <td>10</td> <td>10</td> <td>10</td> <td>110</td> <td>110</td> <td>110</td> <td>110</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	11	11	10	10	110	110	110	110	2	11	11	15	15	110	110	110	110	3	10	10	10	10	110	110	110	110	4									5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	11	11	10	10	110	110	110	110																																																																
2	11	11	15	15	110	110	110	110																																																																
3	10	10	10	10	110	110	110	110																																																																
4																																																																								
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

## - THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date: