

03931620

PERIODIC MANDATORY VEHICLE  
INSPECTION CERTIFICATE

Manitoba



Vehicle Standards and Inspection  
Box 45064 Regent Postal Outlet  
Winnipeg, MB, R2C 5C7  
1-204-985-0920

Manitoba



A925929

Date Inspection Started DAY: 11 MO: 12 YR: 24	Station Number A6154	Station Name Cornerstone Equipment Inc	City Wpg
Date Inspection Completed DAY: 11 MO: 12 YR: 24	Mechanic Number M46111	Mechanic Signature <i>[Signature]</i>	Station Phone Number 204 470 3430
Inspection Expiry Date DAY: 31 MO: 12 YR: 25	Vehicle Owner 6038361 Manitoba Ltd.		
Address _____ City _____ Province _____ Postal Code _____ Phone _____			
<input checked="" type="checkbox"/> Pass/Safe Vehicle <input type="checkbox"/> Fail/Unsafe Vehicle <input type="checkbox"/> Fail/Hazardous	Licence Number N/R	Prov. _____ NSC # _____	Odometer Reading 694476
Vehicle Identification Number 1M1AW1348BM001015		Make MACK	Model C800 614
<input checked="" type="checkbox"/> Confirmed legible Vehicle Identification Number on vehicle		Year 11	Unit # _____
Odom. Type <input checked="" type="checkbox"/> km <input type="checkbox"/> mi			

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR \_\_\_\_\_ KGS ☒ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
X		Section 1 - Power Train: Defects (if any)																																																																						
X		Section 2 Suspension: Defects (if any)																																																																						
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type																																																																						
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table><thead><tr><th rowspan="2">Axle</th><th colspan="2">Lining</th><th colspan="2">Drum/Rotor</th><th colspan="2">Stroke</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>11/16</td><td>5/8</td><td>16.545</td><td>16.550</td><td>1"</td><td>1"</td></tr><tr><td>2</td><td>7/8</td><td>3/4</td><td>16.550</td><td>16.560</td><td>1.25"</td><td>1.25"</td></tr><tr><td>3</td><td>3/4</td><td>3/4</td><td>16.50</td><td>16.565</td><td>1.25"</td><td>1.25"</td></tr><tr><td>4</td><td>7/8</td><td>3/4</td><td>16.50</td><td>16.570</td><td>1.25"</td><td>1.25"</td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td colspan="7">Final Measurement</td></tr></tbody></table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	11/16	5/8	16.545	16.550	1"	1"	2	7/8	3/4	16.550	16.560	1.25"	1.25"	3	3/4	3/4	16.50	16.565	1.25"	1.25"	4	7/8	3/4	16.50	16.570	1.25"	1.25"	5							Final Measurement																					
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	11/16	5/8	16.545	16.550	1"	1"																																																																		
2	7/8	3/4	16.550	16.560	1.25"	1.25"																																																																		
3	3/4	3/4	16.50	16.565	1.25"	1.25"																																																																		
4	7/8	3/4	16.50	16.570	1.25"	1.25"																																																																		
5																																																																								
Final Measurement																																																																								
X		Section 4 - Steering: Defects (if any)																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X		Section 6 - Lamps: Defects (if any)																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X		Section 8 - Body: Defects (if any)																																																																						
X		Section 9 - Tire & Wheel: Defects (if any)																																																																						
		<table><thead><tr><th rowspan="3">Axle</th><th colspan="4">Tread Depth</th><th colspan="4">Air Pressure</th></tr><tr><th colspan="2">Initial</th><th colspan="2">Corrected</th><th colspan="2">Initial</th><th colspan="2">Corrected</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>22</td><td>22</td><td></td><td></td><td>100</td><td>100</td><td></td><td></td></tr><tr><td>2</td><td>28</td><td>28</td><td>28</td><td>28</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>3</td><td>28</td><td>28</td><td>28</td><td>28</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>4</td><td>28</td><td>28</td><td>28</td><td>28</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	22	22			100	100			2	28	28	28	28	100	100	100	100	3	28	28	28	28	100	100	100	100	4	28	28	28	28	100	100	100	100	5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	22	22			100	100																																																																		
2	28	28	28	28	100	100	100	100																																																																
3	28	28	28	28	100	100	100	100																																																																
4	28	28	28	28	100	100	100	100																																																																
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: \_\_\_\_\_

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: \_\_\_\_\_ Signature \_\_\_\_\_ Date: \_\_\_\_\_