

03931602

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspect
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-955-0920

Manitoba

A925912

Date Inspection Started DAY: 21 MO: 11 YR: 24	Station Number A6154	Station Name Cornerstone Equipment	City Winnipeg
Date Inspection Completed DAY: 21 MO: 11 YR: 24	Mechanic Number M46111	Mechanic Signature <i>John Doe</i>	Station Phone Number 204 470 3430
Inspection Expiry Date DAY: 30 MO: 11 YR: 25	Vehicle Owner 6038361 Manitoba Ltél		
Address _____ City _____ Province _____ Postal Code _____ Phone _____			
<input checked="" type="checkbox"/> Pass/Safe Vehicle <input type="checkbox"/> Fail/Unsafe Vehicle <input type="checkbox"/> Fail/Hazardous	Licence Number D1A4549	Prov. MB	NSC # _____
	Vehicle Identification Number 1XKDP4E87R998533	Make KW	Model T800
	<input checked="" type="checkbox"/> Confirmed legible Vehicle Identification Number on vehicle	Year 07	Unit # 734123
	Odometer Reading 904562	Odom. Type <input checked="" type="checkbox"/> km <input type="checkbox"/> mi	

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

 _____ Truck _____ GVWR _____ KGS ☒ Truck Tractor _____ Trailer _____ Semi-Trailer _____ Bus _____ School Bus _____ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
X		Section 1 - Power Train: Defects (if any)																																																																						
X		Section 2 Suspension: Defects (if any)																																																																						
X		Section 3 - Brake Systems: 3H <u>3A</u> Defects (if any) Circle Brake Type																																																																						
		Brake Inspection Type: <u>A</u> B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>11/16</td> <td>11/16</td> <td>16.535</td> <td>16.535</td> <td>1"</td> <td>1"</td> </tr> <tr> <td>2</td> <td>11/16</td> <td>5/8</td> <td>16.540</td> <td>16.535</td> <td>1.25"</td> <td>1.25"</td> </tr> <tr> <td>3</td> <td>11/16</td> <td>13/16</td> <td>16.540</td> <td>16.534</td> <td>1.25"</td> <td>1.25"</td> </tr> <tr> <td>4</td> <td>11/16</td> <td>13/16</td> <td>16.540</td> <td>16.540</td> <td>1.25"</td> <td>1.25"</td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	11/16	11/16	16.535	16.535	1"	1"	2	11/16	5/8	16.540	16.535	1.25"	1.25"	3	11/16	13/16	16.540	16.534	1.25"	1.25"	4	11/16	13/16	16.540	16.540	1.25"	1.25"	5							Final Measurement																					
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	11/16	11/16	16.535	16.535	1"	1"																																																																		
2	11/16	5/8	16.540	16.535	1.25"	1.25"																																																																		
3	11/16	13/16	16.540	16.534	1.25"	1.25"																																																																		
4	11/16	13/16	16.540	16.540	1.25"	1.25"																																																																		
5																																																																								
Final Measurement																																																																								
X		Section 4 - Steering: Defects (if any)																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X		Section 6 - Lamps: Defects (if any)																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X		Section 8 - Body: Defects (if any)																																																																						
X		Section 9 - Tire & Wheel: Defects (if any)																																																																						
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial mm</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>8</td> <td>8</td> <td></td> <td></td> <td>100</td> <td>100</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>11</td> <td>10</td> <td>11</td> <td>12</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td>13</td> <td>12</td> <td>13</td> <td>13</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>4</td> <td>13</td> <td>13</td> <td>13</td> <td>13</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial mm		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	8	8			100	100			2	11	10	11	12	100	100	100	100	3	13	12	13	13	100	100	100	100	4	13	13	13	13	100	100	100	100	5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial mm			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	8	8			100	100																																																																		
2	11	10	11	12	100	100	100	100																																																																
3	13	12	13	13	100	100	100	100																																																																
4	13	13	13	13	100	100	100	100																																																																
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date: