

03970868

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE



Vehicle Standards and Inspection
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920



A965770

Date Inspection Started
DAY: 14 MO: 07 YR: 215

Date Inspection Completed
DAY: 15 MO: 07 YR: 215

Inspection Expiry Date
DAY: 31 MO: 07 YR: 216

Station Number
A15181016

Station Name
Sigfusson Northern Ltd

City
Lundar

Mechanic Number
M71336

Mechanic Signature

Station Phone Number
204-762-5500

Vehicle Owner
Sigfusson Northern Ltd

Address
R-51

City
Lundar

Province
MB

Postal Code
R0C 1X0

Phone
204-762-5500

☒ Pass/Safe Vehicle
☐ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number
T1A914915

Prov.
MB

NSC #

Odometer Reading

Odom. Type
km mi

Vehicle Identification Number
21A914B6534X5037045

Make
Acura

Model
Integra

Year
1999

Unit #
7113

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR KGS Truck Tractor Trailer ☒ Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
		Section 1 - Power Train: Defects (if any)																																																																						
X		Section 2 Suspension: Defects (if any)																																																																						
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type																																																																						
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table><thead><tr><th rowspan="2">Axle</th><th colspan="2">Lining</th><th colspan="2">Drum/Rotor</th><th colspan="2">Stroke</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>5/16</td><td>9/16</td><td>16.55</td><td>16.55</td><td>1.5</td><td>1.5</td></tr><tr><td>2</td><td>13/16</td><td>5/8</td><td>16.54</td><td>16.56</td><td>1.5</td><td>1.5</td></tr><tr><td>3</td><td>13/16</td><td>3/4</td><td>16.54</td><td>16.54</td><td>1.5</td><td>1.5</td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td colspan="7">Final Measurement</td></tr></tbody></table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	5/16	9/16	16.55	16.55	1.5	1.5	2	13/16	5/8	16.54	16.56	1.5	1.5	3	13/16	3/4	16.54	16.54	1.5	1.5	4							5							Final Measurement																					
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	5/16	9/16	16.55	16.55	1.5	1.5																																																																		
2	13/16	5/8	16.54	16.56	1.5	1.5																																																																		
3	13/16	3/4	16.54	16.54	1.5	1.5																																																																		
4																																																																								
5																																																																								
Final Measurement																																																																								
X		Section 4 - Steering: Defects (if any)																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X		Section 6 - Lamps: Defects (if any)																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X		Section 8 - Body: Defects (if any)																																																																						
X		Section 9 - Tire & Wheel: Defects (if any)																																																																						
		<table><thead><tr><th rowspan="3">Axle</th><th colspan="4">Tread Depth</th><th colspan="4">Air Pressure</th></tr><tr><th colspan="2">Initial</th><th colspan="2">Corrected</th><th colspan="2">Initial</th><th colspan="2">Corrected</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>13/32</td><td>13/32</td><td>18/32</td><td>18/32</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>2</td><td>13/32</td><td>13/32</td><td>18/32</td><td>18/32</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>3</td><td>17/32</td><td>17/32</td><td>26/32</td><td>29/32</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	13/32	13/32	18/32	18/32	100	100	100	100	2	13/32	13/32	18/32	18/32	100	100	100	100	3	17/32	17/32	26/32	29/32	100	100	100	100	4									5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	13/32	13/32	18/32	18/32	100	100	100	100																																																																
2	13/32	13/32	18/32	18/32	100	100	100	100																																																																
3	17/32	17/32	26/32	29/32	100	100	100	100																																																																
4																																																																								
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date: