

03852971

PERIODIC MANDATORY VEHICLE  
INSPECTION CERTIFICATE

Manitoba



K21-2

Vehicle Standards and Inspect  
Box 45064 Regent Postal Centre  
Winnipeg, MB, R2C 6C7  
1-204-985-0920

Manitoba



A855305

Date Inspection Started: DAY 06 MO. 10 YR. 24

Date Inspection Completed: DAY 06 MO. 10 YR. 24

Inspection Expiry Date: DAY 31 MO. 10 YR. 25

Station Number: A6039 ADVANCE Truck & Trailer

Mechanic Number: A26311

Station Name: City: 284498 2-222

Mechanic Signature: Station Phone Number:

Vehicle Owner: COAST CAPITAL EQUIPMENT FINANCE LTD

Address: City: Province: Postal Code: Phone:

☐ Pass/Safe Vehicle ☐ Fail/Unsafe Vehicle ☐ Fail/Hazardous

Licence Number: C145186 Prov. MB NSC # MBM16630 Odometer Reading: 1626725 Odom. Type: ☐ km ☐ mi

Vehicle Identification Number: 1FUTALB8193F16GV2364 Make: FTL Model: CWS Year: 2015 Unit #: 5720

☐ Confirmed legible Vehicle Identification Number on vehicle

## THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☒ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
X		Section 1 - Power Train: Defects (if any)																																																																							
X	X	Section 2 Suspension: Defects (if any) 7-C Rear Shock Leaks																																																																							
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type 3-A Air - 6.6c Air - 10.6																																																																							
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>5/8</td> <td>5/8</td> <td>16.560</td> <td>16.562</td> <td>1.5</td> <td>1.5</td> </tr> <tr> <td>2</td> <td>11/16</td> <td>9/16</td> <td>16.543</td> <td>16.559</td> <td>1.5</td> <td>1.5</td> </tr> <tr> <td>3</td> <td>9/16</td> <td>9/16</td> <td>16.573</td> <td>16.580</td> <td>1.5</td> <td>1.5</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	5/8	5/8	16.560	16.562	1.5	1.5	2	11/16	9/16	16.543	16.559	1.5	1.5	3	9/16	9/16	16.573	16.580	1.5	1.5	4							5							Final Measurement																						
Axle	Lining			Drum/Rotor		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	5/8	5/8	16.560	16.562	1.5	1.5																																																																			
2	11/16	9/16	16.543	16.559	1.5	1.5																																																																			
3	9/16	9/16	16.573	16.580	1.5	1.5																																																																			
4																																																																									
5																																																																									
Final Measurement																																																																									
X		Section 4 - Steering: Defects (if any)																																																																							
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																							
X		Section 6 - Lamps: Defects (if any)																																																																							
X		Section 7 - Electrical System: Defects (if any)																																																																							
X		Section 8 - Body: Defects (if any)																																																																							
X		Section 9 - Tire & Wheel: Defects (if any)																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>12</td> <td>14</td> <td></td> <td></td> <td>100</td> <td>100</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>11</td> <td>13</td> <td></td> <td></td> <td>100</td> <td>100</td> <td></td> <td></td> </tr> <tr> <td>3</td> <td>11</td> <td>11</td> <td>6</td> <td>7</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	12	14			100	100			2	11	13			100	100			3	11	11	6	7	100	100	100	100	4									5								
Axle	Tread Depth				Air Pressure																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	12	14			100	100																																																																			
2	11	13			100	100																																																																			
3	11	11	6	7	100	100	100	100																																																																	
4																																																																									
5																																																																									
X	X	Section 10 - Coupling Devices: Defects (if any) 1-2 244 - White - 11.5c - 11.5c																																																																							

- THIS INSPECTION IS NOT A WARRANTY -  
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature

Date: