

03889260

PERIODIC MANDATORY VEHICLE  
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspection  
Box 4504 Rogers Postal Outlet  
Winnipeg, MB R2C 1C7  
1-204-985-0920

Manitoba

A867787

Date Inspection Started DAY: 24 MO: 10 YR: 24	Station Number C0543	Station Name Lakeside Colony	City Cart. 27
Date Inspection Completed DAY: 24 MO: 10 YR: 24	Mechanic Number M917168	Mechanic Signature Michael J. J.	Station Phone Number 201 918 4029
Inspection Expiry Date DAY: 31 MO: 10 YR: 25	Vehicle Owner Lakeside Colony	Address 5800 Assiniboine Rd	City Carterville
	Province MB	Postal Code R4K 1C3	Phone 918 4029
<input checked="" type="checkbox"/> Pass/Safe Vehicle <input type="checkbox"/> Fail/Unsafe Vehicle <input type="checkbox"/> Fail/Hazardous	Licence Number TFD4188	Prov. MB	NSC #
	Vehicle Identification Number 1RN4181A2916R03516117	Make Ram	Model TRAP
	<input checked="" type="checkbox"/> Confirmed legible Vehicle Identification Number on vehicle	Year 2016	Unit #

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck 40823 KGS Truck Tractor Trailer ☒ Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
<input checked="" type="checkbox"/>		Section 1 - Power Train: Defects (if any)																																																																							
<input checked="" type="checkbox"/>		Section 2 Suspension: Defects (if any)																																																																							
<input checked="" type="checkbox"/>		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type																																																																							
		Brake Inspection Type: A <input checked="" type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E Circle appropriate Letter for Internal Brake Component Inspection																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>1/2</td> <td>9/16</td> <td>16.548</td> <td>16.52</td> <td>1/4</td> <td>3/8</td> </tr> <tr> <td>2</td> <td>3/8</td> <td>1/2</td> <td>16.557</td> <td>16.532</td> <td>1/4</td> <td>1 5/8</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	1/2	9/16	16.548	16.52	1/4	3/8	2	3/8	1/2	16.557	16.532	1/4	1 5/8	3							4							5							Final Measurement																						
Axle	Lining			Drum/Rotor		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	1/2	9/16	16.548	16.52	1/4	3/8																																																																			
2	3/8	1/2	16.557	16.532	1/4	1 5/8																																																																			
3																																																																									
4																																																																									
5																																																																									
Final Measurement																																																																									
<input checked="" type="checkbox"/>		Section 4 - Steering: Defects (if any)																																																																							
<input checked="" type="checkbox"/>		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																							
<input checked="" type="checkbox"/>		Section 6 - Lamps: Defects (if any)																																																																							
<input checked="" type="checkbox"/>		Section 7 - Electrical System: Defects (if any)																																																																							
<input checked="" type="checkbox"/>		Section 8 - Body: Defects (if any)																																																																							
<input checked="" type="checkbox"/>		Section 9 - Tire & Wheel: Defects (if any)																																																																							
<input checked="" type="checkbox"/>		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>16</td> <td>16</td> <td>16</td> <td>16</td> <td>90</td> <td>90</td> <td>90</td> <td>90</td> </tr> <tr> <td>2</td> <td>16</td> <td>16</td> <td>4</td> <td>7</td> <td>90</td> <td>90</td> <td>90</td> <td>90</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	16	16	16	16	90	90	90	90	2	16	16	4	7	90	90	90	90	3									4									5								
Axle	Tread Depth				Air Pressure																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	16	16	16	16	90	90	90	90																																																																	
2	16	16	4	7	90	90	90	90																																																																	
3																																																																									
4																																																																									
5																																																																									
<input checked="" type="checkbox"/>		Section 10 - Coupling Devices: Defects (if any)																																																																							

THIS INSPECTION IS NOT A WARRANTY -  
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature

Date: