

03921757

PERIODIC MANDATORY VEHICLE  
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspection  
Box 45064 Regent Postal Outlet  
Winnipeg, MB, R2C 5C7  
1-204-985-0920

Manitoba

A924893

Date Inspection Started DAY: 27 MO: 02 YR: 25	Station Number A5329	Station Name Parkville Trailers Inc.	City M. Soper	Phone K06-6
Date Inspection Completed DAY: 27 MO: 02 YR: 25	Mechanic Number M5343	Mechanic Signature [Signature]	Station Phone Number	
Inspection Expiry Date DAY: 28 MO: 02 YR: 26	Vehicle Owner 6038361 MB LTD.			
Address		City	Province	Postal Code
<input checked="" type="checkbox"/> Pass/Safe Vehicle <input type="checkbox"/> Fail/Unsafe Vehicle <input type="checkbox"/> Fail/Hazardous		Licence Number: TG8026 Prov. MB NSC # [ ] Odometer Reading: N/A Vehicle Identification Number: 5MAPA5322JA043717 Make: MAC Model: Cort Side Year: 18 Unit #: 2209 <input checked="" type="checkbox"/> Confirmed legible Vehicle Identification Number on vehicle		

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

 Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
		Section 1 - Power Train: Defects (if any)																																																																						
X		Section 2 Suspension: Defects (if any)																																																																						
X		Section 3 - Brake Systems: 3H (3A) Defects (if any) Circle Brake Type																																																																						
		Brake Inspection Type: A (B) C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>7/16</td> <td>7/16</td> <td>16.585</td> <td>16.585</td> <td>1.5</td> <td>1.5</td> </tr> <tr> <td>2</td> <td>5/16</td> <td>7/16</td> <td>16.590</td> <td>16.80</td> <td>1.5</td> <td>1.5</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	7/16	7/16	16.585	16.585	1.5	1.5	2	5/16	7/16	16.590	16.80	1.5	1.5	3							4							5							Final Measurement																					
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	7/16	7/16	16.585	16.585	1.5	1.5																																																																		
2	5/16	7/16	16.590	16.80	1.5	1.5																																																																		
3																																																																								
4																																																																								
5																																																																								
Final Measurement																																																																								
		Section 4 - Steering: Defects (if any)																																																																						
		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X		Section 6 - Lamps: Defects (if any)																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X	X	Section 8 - Body: Defects (if any) 22, 15 mud flap and bracket - Missing																																																																						
X		Section 9 - Tire & Wheel: Defects (if any)																																																																						
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>16</td> <td>16</td> <td>11</td> <td>11</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>2</td> <td>13</td> <td>13</td> <td>12</td> <td>10</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	16	16	11	11	100	100	100	100	2	13	13	12	10	100	100	100	100	3									4									5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	16	16	11	11	100	100	100	100																																																																
2	13	13	12	10	100	100	100	100																																																																
3																																																																								
4																																																																								
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date: