

03921490

PERIODIC MANDATORY VEHICLE  
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspection  
Box 45064 Regent Postal Outlet  
Winnipeg, MB, R2C 5C7  
1-204-985-0920

Manitoba

W37-1

Date Inspection Started DAY: 27 MO: 10 YR: 24	Station Number A161294	Station Name TOP WRENCH TRUCK	City Winnipeg	Postal Code R2P0N6	Phone 204-869-8382
Date Inspection Completed DAY: 28 MO: 10 YR: 24	Mechanic Number M106151	Mechanic Signature <i>[Signature]</i>			
Inspection Expiry Date DAY: 31 MO: 10 YR: 25	Vehicle Owner 10068244	Address 54 Manxen Crescent	City Winnipeg	Province MB	Postal Code R2P0N6

☒ Pass/Safe Vehicle  
☒ Fail/Unsafe Vehicle  
☐ Fail/Hazardous

Licence Number: [ ] Prov. [ ] NSC # [ ]  
 Vehicle Identification Number: 1E912739281E1110106 Make: En-Tyre Model: Goose Neck Year: 2001 Unit # [ ]  
☒ Confirmed legible Vehicle Identification Number on vehicle

## THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

 Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
X		Section 1 - Power Train: Defects (if any)																																																																						
X	X	Section 2 Suspension: Defects (if any) X-7(c) - All six shock absorbers level 2 leak.																																																																						
X		Section 3 - Brake Systems: 3H (3A) Defects (if any) Circle Brake Type																																																																						
		Brake Inspection Type: (A) B C D E Circle appropriate letter for Internal Brake Component Inspection																																																																						
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>3/4</td> <td>3/4</td> <td>16.50</td> <td>16.50</td> <td>1.5</td> <td>1.5</td> </tr> <tr> <td>2</td> <td>3/4</td> <td>3/4</td> <td>16.54</td> <td>16.54</td> <td>1.5</td> <td>1.5</td> </tr> <tr> <td>3</td> <td>3/4</td> <td>3/4</td> <td>16.54</td> <td>16.54</td> <td>1.5</td> <td>1.5</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	3/4	3/4	16.50	16.50	1.5	1.5	2	3/4	3/4	16.54	16.54	1.5	1.5	3	3/4	3/4	16.54	16.54	1.5	1.5	4							5																												
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	3/4	3/4	16.50	16.50	1.5	1.5																																																																		
2	3/4	3/4	16.54	16.54	1.5	1.5																																																																		
3	3/4	3/4	16.54	16.54	1.5	1.5																																																																		
4																																																																								
5																																																																								
X		Section 4 - Steering: Defects (if any)																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X		Section 6 - Lamps: Defects (if any)																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X		Section 8 - Body: Defects (if any)																																																																						
X		Section 9 - Tire & Wheel: Defects (if any)																																																																						
X		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>9</td> <td>10</td> <td>8</td> <td>9</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>2</td> <td>10</td> <td>9</td> <td>7</td> <td>8</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td>8</td> <td>10</td> <td>11</td> <td>9</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	9	10	8	9	100	100	100	100	2	10	9	7	8	100	100	100	100	3	8	10	11	9	100	100	100	100	4									5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	9	10	8	9	100	100	100	100																																																																
2	10	9	7	8	100	100	100	100																																																																
3	8	10	11	9	100	100	100	100																																																																
4																																																																								
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -  
 This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Police Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Received without repairs by:

Signature

Date:

1-(R-09/15)

PRESENT THIS COPY WHEN REGISTERING VEHICLE

Ce document peut être obtenu en français sur demande.