

Date Inspection Started

13

06

05

DAY

MO.

YR.

Date Inspection Completed

18

06

05

DAY

MO.

YR.

Inspection Expiry Date

30

06

26

DAY

MO.

YR.

Station Number

11724

Station Name

Manitoba WPG

City

Mechanic Number

10826

Mechanic Signature

Mike Lee

Station Phone Number

204940-1564

Vehicle Owner

C. King Investments Ltd

Address

City

Province

Postal Code

Phone

☒ Pass/Safe Vehicle

☐ Fail/Unsafe Vehicle

☐ Fail/Hazardous

Licence Number

6DU403

Prov.

AB

NSC #

Odometer Reading

438150

Odom. Type

☐ km ☒ mi

Vehicle Identification Number

1U1Y4USP533BP138318

Make

Volvo

Model

460

Year

2011

Unit #

1968

☐ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck

GVWR

KGS

Truck Tractor

Trailer

☒ Semi-Trailer

Bus

School Bus

Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
<input checked="" type="checkbox"/>		Section 1 - Power Train: Defects (if any)
<input checked="" type="checkbox"/>		Section 2 Suspension: Defects (if any)
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type 16-A Rear Axle + L/R Cam Tubes WORN. 14-A R/R maxi 16T
<input checked="" type="checkbox"/>		Section 4 - Steering: Defects (if any)
<input checked="" type="checkbox"/>		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
<input checked="" type="checkbox"/>		Section 6 - Lamps: Defects (if any)
<input checked="" type="checkbox"/>		Section 7 - Electrical System: Defects (if any)
<input checked="" type="checkbox"/>		Section 8 - Body: Defects (if any)
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Section 9 - Tire & Wheel: Defects (if any) 5-A L/R HOUSCAP CRACKED, 1-B L/R INNER TIRE CURVED OUT 4-A INFLATION PRESSURES
<input checked="" type="checkbox"/>		Section 10 - Coupling Devices: Defects (if any)

Axle	Tread Depth				Air Pressure									
	Initial		Corrected		Initial		Corrected							
	L	R	L	R	L	R	L	R						
1	12	9	10	9	12		87	83	88	87	90	90	90	90
2	13	15	13	13			86	90	88	89		90	90	90
3														
4														
5														

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date: