

04010333

PERIODIC MANDATORY VEHICLE  
INSPECTION CERTIFICATE

Manitoba



MK2-2

Vehicle Standards and Insp.  
Box 45064 Regent Postal Out  
Winnipeg, MB, R2G 5C7  
1-204-985-0920

Manitoba



C001443

Date Inspection Started: 01 08 25  
Date Inspection Completed: 11 08 25  
Inspection Expiry Date: 31 08 26

Station Number: A0077  
Station Name: Maxim Truck & Trail  
City: 204-725-4580  
Mechanic Number: M9646  
Mechanic Signature: [Signature]  
Station Phone Number: 204-725-4580  
Vehicle Owner: Dominion Leasing Inc  
Address: 161-2055 Premier Way Sherwood Park AB  
City: [Blank] Province: [Blank] Postal Code: [Blank] Phone: 184 062

☒ Pass/Safe Vehicle  
☒ Fail/Unsafe Vehicle  
☐ Fail/Hazardous  
Licence Number: 018MGY Prov: SK NSC # [Blank]  
Odometer Reading: 961917 Odom. Type: ☒ km ☐ mi  
Vehicle Identification Number: SKJJBHD17JLJK5838 Make: [Blank] Model: 5700 Year: 2018 Unit #: 15-345  
☒ Confirmed legible Vehicle Identification Number on vehicle

## THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

\_\_\_ Truck 63500 KGS X Truck Tractor \_\_\_ Trailer \_\_\_ Semi-Trailer \_\_\_ Bus \_\_\_ School Bus \_\_\_ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
<u>X</u>		Section 1 - Power Train: Defects (if any)																																																																							
<u>X</u>		Section 2 Suspension: Defects (if any)																																																																							
<u>X</u>	<u>X</u>	Section 3 - Brake Systems: <u>3H</u> <u>3A</u> Defects (if any) Circle Brake Type <u>2g air leak by compressor</u> <u>16th brake stroke measures</u> <u>difference between is greater</u> <u>than 1/4" on an axle</u> Brake Inspection Type: <u>A</u> B C D E Circle appropriate Letter for Internal Brake Component Inspection <table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>13/16</td> <td>13/16</td> <td>16.517</td> <td>16.517</td> <td>1 1/2</td> <td>1 1/2</td> </tr> <tr> <td>2</td> <td>13/16</td> <td>13/16</td> <td>16.510</td> <td>16.501</td> <td>1 1/2</td> <td>1 1/4</td> </tr> <tr> <td>3</td> <td>3/4</td> <td>3/4</td> <td>16.517</td> <td>16.517</td> <td>1 1/2</td> <td>1 1/2</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	13/16	13/16	16.517	16.517	1 1/2	1 1/2	2	13/16	13/16	16.510	16.501	1 1/2	1 1/4	3	3/4	3/4	16.517	16.517	1 1/2	1 1/2	4							5							Final Measurement																						
Axle	Lining			Drum/Rotor		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	13/16	13/16	16.517	16.517	1 1/2	1 1/2																																																																			
2	13/16	13/16	16.510	16.501	1 1/2	1 1/4																																																																			
3	3/4	3/4	16.517	16.517	1 1/2	1 1/2																																																																			
4																																																																									
5																																																																									
Final Measurement																																																																									
<u>X</u>		Section 4 - Steering: Defects (if any)																																																																							
<u>X</u>		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																							
<u>X</u>	<u>X</u>	Section 6 - Lamps: Defects (if any) <u>1a top cab light dim, RH Top working light,</u> <u>no licence plate lgt, LH reverse lgt, LH head lgt</u>																																																																							
<u>X</u>		Section 7 - Electrical System: Defects (if any)																																																																							
<u>X</u>	<u>X</u>	Section 8 - Body: Defects (if any) <u>13b windshield glass cracked</u> <u>ala mudflaps do not covering the full tread width</u> <u>of the tires</u>																																																																							
<u>X</u>		Section 9 - Tire & Wheel: Defects (if any)																																																																							
<u>X</u>	<u>X</u>	Section 10 - Coupling Devices: Defects (if any) <u>7d 5th wheel latching mechanism adjust</u> <table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>9</td> <td>7</td> <td></td> <td></td> <td>102</td> <td>100</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>16</td> <td>15</td> <td>16</td> <td>16</td> <td>102</td> <td>106</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td>15</td> <td>15</td> <td>13</td> <td>15</td> <td>110</td> <td>110</td> <td>106</td> <td>102</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	9	7			102	100			2	16	15	16	16	102	106	100	100	3	15	15	13	15	110	110	106	102	4									5								
Axle	Tread Depth				Air Pressure																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	9	7			102	100																																																																			
2	16	15	16	16	102	106	100	100																																																																	
3	15	15	13	15	110	110	106	102																																																																	
4																																																																									
5																																																																									

## - THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date: