

03598684

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba



B23-5

Vehicle Standards and Inspections
Box 45064 Regent Postal Centre
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

DECAL



A831311

Date Inspection Started: DAY 17, MO. 11, YR. 25
 Date Inspection Completed: DAY 17, MO. 11, YR. 25
 Inspection Expiry Date: DAY 30, MO. 11, YR. 26

Station Number: C10537
 Station Name: Ba B Landscape
 City: 204 339 4643
 Mechanic Number: M9906
 Mechanic Signature: [Signature]
 Station Phone Number: 339 4643
 Vehicle Owner: Ba B Landscape & Cartage
 Address: 2nd St West
 City: MB
 Province: MB
 Postal Code: R2P0G5
 Phone: 339 4643

Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Hazardous

Licence Number: CHR118
 Prov. MB
 NSC #: 9671065
 Odometer Reading: 163536
 Odom. Type: km mi

Vehicle Identification Number: 1M3GR56C7KMO01185
 Make: MAERX
 Model: 80713
 Year: 19
 Unit #: 41

Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ^(G.V.W.R.) 24500 KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P R Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

Section 1 - Power Train: Defects (if any)

Section 2 Suspension: Defects (if any)

Section 3 - Brake Systems: 3H 3A
 Defects (if any) Circle Brake Type

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	9/16	9/16	16590	16568	1/2	1/2
2	3/4	3/4	16532	16523	1/2	1/2
3	9/16	1/2	16572	16575	1/2	1/2
4						
5						

Final Measurement

Section 4 - Steering: Defects (if any)

Section 5 - Instruments & Auxiliary Equipment: Defects (if any)

Section 6 - Lamps: Defects (if any)

Section 7 - Electrical System: Defects (if any)

Section 8 - Body: Defects (if any)

Section 9 - Tire & Wheel: Defects (if any)

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	13	11			110	110		
2	12	11	12	20	100	100	100	100
3	16	17	16	16	100	100	100	100
4								
5								

Section 10 - Coupling Devices: Defects (if any)

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature _____ Date: _____