

04099363

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE



Vehicle Safety Box 45064 Regent Postal Office Winnipeg, MB, R2C 5C7 1-204-985-0920



C030342

Date Inspection Started: 26 04 26
Date Inspection Completed: 26 04 26
Inspection Expiry Date: 30 04 27

Station Number: A59512
Station Name: kmmt LTD
City: Vird
Mechanic Number: MD20F
Mechanic Signature: Mark JH
Station Phone Number: 204-251-038
Vehicle Owner: Silvana O.H. 11500
Address: Box 757
City: Vird
Province: MB
Postal Code: R0M2C0
Phone:

Pass/Safe Vehicle
Licence Number: P1487F
Prov: MB
NSC #: 0886207
Odometer Reading: 751971
Odom. Type: km
Vehicle Identification Number: 2HEKTA9T45J000416
Make: I.H.
Model: 5700
Year: 05
Unit #: 222

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck
GVWR: 36500
KGS
Truck Tractor
Trailer
Semi-Trailer
Bus
School Bus
Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Section 1 - Power Train: Defects (if any)
Section 2 Suspension: Defects (if any)
Section 3 - Brake Systems: 3H 3A
Brake Inspection Type: A B C D E
Section 4 - Steering: Defects (if any)
Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
Section 6 - Lamps: Defects (if any)
Section 7 - Electrical System: Defects (if any)
Section 8 - Body: Defects (if any)
Section 9 - Tire & Wheel: Defects (if any)
Section 10 - Coupling Devices: Defects (if any)

Table with columns: Axle, Lining (L, R), Drum/Rotor (L, R), Stroke (L, R). Contains handwritten measurements for axles 1-5.

Table with columns: Axle, Tread Depth (Initial, Corrected), Air Pressure (Initial, Corrected). Contains handwritten data for axles 1-5.

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date: