

Dec 11, 2022 07:

## Work Order Details

This report was run on: Nov 24, 2024 02:49:42 PM

with the following parameters

Opened After: Nov 24, 2022 02:38:00 PM Opened Before: Nov 24, 2024 02:38:00 PM

Kris Williams - Finning

Parent Asset: "Articulated Rock Truck (19-45-014)"

Kris Williams - Finning

Dec 10, 2022

Dec 02, 2022 05:06:56 PM

Asset Category: "All" Assigned User: "All" Maintenance Type: "All" Priority: "All"

Articulated Rock Truck

Status: "All"

**Date Created Due Date Date Completed Days Late** Status Work **Work Order Description** Dec 02, 2022 Dec 02, 2022 Closed, Completed Corrective 62605 Needs boost 03:58:08 PM 05:06:56 PM **Assigned To** Completed By **Date Completed Est Hours** Spent Hours **Task Description** Asset

02 December 2022 - Kris Wlocate unit unit will not start get grader to come over boost unit with cat to cat cables leave unit running for night shift finning and prhp service reports

Vork 52825	Work Order Description Interior light. Front left strut requires a charge	Status Closed, (	Type Completed Correcti	Date Crea ve Dec 05, 08:52:39	2022	Date Completed Dec 07, 2022 09:54:49 AM	1.00 Pays Late
	Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
		Articulated Rock Truck	Rey Contreras				192-91
	Mark Milne Dec 6 2022	Articulated Rock Truck	Mark Milne	Mark Milne	Dec 06, 2022 05:13:0	0 AM	3.00

ork	Work Order Description	t was	Status		Туре	Date Created	Due Date	Date Completed	Days Late
2919	Front right strut needs to be inspected. Bolt is moving around	l inside	Closed, Co	ompleted	Corrective	Dec 06, 2022		Dec 07, 2022	
	where the strut bolts on					11:50:40 PM		05:17:36 AM	
T	ask Description	Asset		Assigned	То	Completed By	Date Completed	Est Hours	Spent Hour
_		Articulate	d Rock Truck	Christophe	er Paul	Nick Vanderkooi	Dec 07, 2022 05:17:36	AM	
lork _	Work Order Description		Status		Туре	Date Created	Due Date	Date Completed	Days Late
3074	Truck 745 014		Closed, Co	ompleted	Corrective	Dec 09, 2022 07:19:02 AM		Dec 10, 2022 08:37:20 AM	
	Missing 4 way switch.								
	Needs new wiper.								
Т	ask Description	Asset		Assigned	То	Completed By	Date Completed	Est Hours	Spent Hour
Re	emoved 4 way from truck in the bone yard. Removed broken switch from truck 14. istalled switch in truck 14. Sent back to work	Articulate	d Rock Truck	Thomas R	agan	Thomas Ragan	Dec 10, 2022 08:37:20	AM 2.00	
_								2.00	

Closed, Completed

Corrective

63182 Seat needs to be replaced. Won't adjust at all. Shorter drivers are

Night shift

unable to drive it.		07:28:34 PM	47:35 AM
	•		

_	Fask Description	Asset		Assigned		Completed By	Date Completed		t Hours	Spent Hour
	Thecked the seat. Every function works on the seats was able to pull right up to the teering wheel and push it all the way back to no problems	Articulated	Rock Truck	Thomas R	agan	Thomas Ragan	Dec 11, 2022 07:47:35 A	AM	1.00	
									1.00	
rk 105	Work Order Description		Status		Туре	Date Created	Due Date	Date Completed	Da	ys Late
195	Riding extremely ruff and bucking. Very noticeable reference day before.	from the	Closed, C	ompleted	Corrective	Dec 11, 2022 05:01:33 AM		Jun 10, 2023 12:26:00 AM		:
_	Fask Description	Asset		Assigned		Completed By	Date Completed		Hours	Spent Hou
	Drove unit. The Aframe and steering pins are very worn and you can feeling while braking and Accelerating. Unit needs work	Articulated	Rock Truck	Thomas R	agan	Nick Vanderkooi	Jun 09, 2023 12:26:20 A	м	1.00	
rk -	Work Order Description		Status		Туре	Date Created	Due Dete	D. 4. C   1	1.00	
295	Parking break is sticking on. Break pressure code comes on t	hon	Closed, C	ampleted.			Due Date	Date Completed	Day	ys Late
293	switches to a yellow warning that prompts me to press ok, the sometimes the brake disengages. Usually stays stuck for a m	en	Cioseu, C	impieted	Corrective	Dec 12, 2022 04:17:03 PM		Dec 12, 2022 09:34:50 PM		** .
	2, and now for longer than 3 minutes	(4)						1 - 1		•
	Task Description	Asset		Assigned	То	Completed By	Date Completed	Est	Hours	Spent Hou
	Dec 12 2022 DS Had to fill one of the accumlator and found leaking. Brake line replaced. Fixed issue		Rock Truck	Jay Dhillon	,	Jay Dhillon	Dec 12, 2022 09:34:50 P	M	2.00	
rk -	Work Order Description		Status		Туре	Date Created	Due Date	Data Camulata d	2.00	
458	Two way radio needs to be replaced. Did a radio check with o	trivor' Ho		ampleted				Date Completed	Day	/s Late
470	could hear me and d I couldn't hear him. Gave the driver a higher now		Ciosea, C	mpieteu	Corrective	Dec 15, 2022 09:29:38 AM		Dec 15, 2022 08:24:28 PM		
7	Task Description	Asset		Assigned	To	Completed By	Date Completed	Est	Hours	Spent Hou
F	Replace radio	Articulated	Rock Truck	Nick Misen			Dec 15, 2022 08:24:23 P		2.00	2.0
5 T C	.5 December 2022 - Sebastian C - STARTED DIAGNOSING 13-85-503R AND PACE SETTER SHOWER UP AND TOOK OVER FALK TO FOREMAN DAN AND WAS TOLD TO PUT RADIO IN 745C SRABBED RADIO FROM FOREEMAN AND WAITED AT MOBERLY RUCK NEVER SHOWED UP, CALLED TRUCK FOREMAN WAS TOLD TO GO TO DAM	Articulated	Rock Truck	Sebastian	Cepeda - Brandt	Sebastian Cepeda - Brandt				
5 T C V T F N	STARTED DIAGNOSING 13-85-503R AND PACE SETTER SHOWER UP AND TOOK OVER ALK TO FOREMAN DAN AND WAS TOLD TO PUT RADIO IN 745C SRABBED RADIO FROM FOREEMAN AND WAITED AT MOBERLY RUCK NEVER SHOWED UP, CALLED TRUCK FOREMAN WAS TOLD TO GO TO DAM CORE VAITED FROM TRUCK, WIRED IN NEW RADIO AND INSTALLED RIED RADIO AND RADIO WAS NOT WORKING, RADIO GIVEN BY FOREMAN WAS AULTY TO RADIO SIN MAIN OFFICE	Articulated	Rock Truck	Sebastian	Cepeda - Brandt					
5 T C V T F N	ITARTED DIAGNOSING 13-85-503R AND PACE SETTER SHOWER UP AND TOOK OVER ALK TO FOREMAN DAN AND WAS TOLD TO PUT RADIO IN 745C SRABBED RADIO FROM FOREEMAN AND WAITED AT MOBERLY RUCK NEVER SHOWED UP, CALLED TRUCK FOREMAN WAS TOLD TO GO TO DAM CORE VAITED FROM TRUCK, WIRED IN NEW RADIO AND INSTALLED RIED RADIO AND RADIO WAS NOT WORKING, RADIO GIVEN BY FOREMAN WAS AULTY	Articulated	Rock Truck	Sebastian	Cepeda - Brandt				2.00	2.5
S T C V T F N III	TARTED DIAGNOSING 13-85-503R AND PACE SETTER SHOWER UP AND TOOK OVER ALK TO FOREMAN DAN AND WAS TOLD TO PUT RADIO IN 745C SRABBED RADIO FROM FOREMAN AND WAITED AT MOBERLY RUCK NEVER SHOWED UP, CALLED TRUCK FOREMAN WAS TOLD TO GO TO DAM ONE WAITED FROM TRUCK, WIRED IN NEW RADIO AND INSTALLED RIED RADIO AND RADIO WAS NOT WORKING, RADIO GIVEN BY FOREMAN WAS AULTY TO RADIO SIN MAIN OFFICE NFORMED FOREMAN AND WAS GIVEN ANOTHER JOB  WORK Order Description		Status		Туре	Sebastian Cepeda - Brandt  Date Created	Dec 15, 2022 01:17:00 A	M  Date Completed	2.00 Day	2.:
S T C C V T F N       -	TARTED DIAGNOSING 13-85-503R AND PACE SETTER SHOWER UP AND TOOK OVER ALK TO FOREMAN DAN AND WAS TOLD TO PUT RADIO IN 745C SRABBED RADIO FROM FOREMAN AND WAITED AT MOBERLY RUCK NEVER SHOWED UP, CALLED TRUCK FOREMAN WAS TOLD TO GO TO DAM CORE WAITED FROM TRUCK, WIRED IN NEW RADIO AND INSTALLED RIED RADIO AND RADIO WAS NOT WORKING, RADIO GIVEN BY FOREMAN WAS AULTY TO RADIO SIN MAIN OFFICE NO RADIOS IN MAIN OFFICE NFORMED FOREMAN AND WAS GIVEN ANOTHER JOB		Status		,	Sebastian Cepeda - Brandt	Dec 15, 2022 01:17:00 A	м	_	2.:
S T C C T C C T F N III	ITARTED DIAGNOSING 13-85-503R AND PACE SETTER SHOWER UP AND TOOK OVER ALK TO FOREMAN DAN AND WAS TOLD TO PUT RADIO IN 745C SRABBED RADIO FROM FOREEMAN AND WAITED AT MOBERLY RUCK NEVER SHOWED UP, CALLED TRUCK FOREMAN WAS TOLD TO GO TO DAM CORE VAITED FROM TRUCK, WIRED IN NEW RADIO AND INSTALLED RIED RADIO AND RADIO WAS NOT WORKING, RADIO GIVEN BY FOREMAN WAS YOULTY TO RADIOS IN MAIN OFFICE NFORMED FOREMAN AND WAS GIVEN ANOTHER JOB  Work Order Description  Windshield wiper is non-working. I don't mind getting out and every so often  I can hear the crank turning back and forth but it's like the ac	l wiping It	Status		Туре	Sebastian Cepeda - Brandt  Date Created Dec 18, 2022	Dec 15, 2022 01:17:00 A	Date Completed Jan 15, 2023	_	2.:
S T C C T C C T F N III	STARTED DIAGNOSING 13-85-503R AND PACE SETTER SHOWER UP AND TOOK OVER ALK TO FOREMAN DAN AND WAS TOLD TO PUT RADIO IN 745C SRABBED RADIO FROM FOREEMAN AND WAITED AT MOBERLY RUCK NEVER SHOWED UP, CALLED TRUCK FOREMAN WAS TOLD TO GO TO DAM CORE VAITED FROM TRUCK, WIRED IN NEW RADIO AND INSTALLED RIED RADIO AND RADIO WAS NOT WORKING, RADIO GIVEN BY FOREMAN WAS YOULTY TO RADIOS IN MAIN OFFICE NFORMED FOREMAN AND WAS GIVEN ANOTHER JOB  Work Order Description  Windshield wiper is non-working. I don't mind getting out and every so often	l wiping It	Status		Туре	Sebastian Cepeda - Brandt  Date Created Dec 18, 2022	Dec 15, 2022 01:17:00 A	Date Completed Jan 15, 2023	_	2.:
5 T C V T F N	ITARTED DIAGNOSING 13-85-503R AND PACE SETTER SHOWER UP AND TOOK OVER ALK TO FOREMAN DAN AND WAS TOLD TO PUT RADIO IN 745C SRABBED RADIO FROM FOREEMAN AND WAITED AT MOBERLY RUCK NEVER SHOWED UP, CALLED TRUCK FOREMAN WAS TOLD TO GO TO DAM CORE VAITED FROM TRUCK, WIRED IN NEW RADIO AND INSTALLED RIED RADIO AND RADIO WAS NOT WORKING, RADIO GIVEN BY FOREMAN WAS YOULTY TO RADIOS IN MAIN OFFICE NFORMED FOREMAN AND WAS GIVEN ANOTHER JOB  Work Order Description  Windshield wiper is non-working. I don't mind getting out and every so often  I can hear the crank turning back and forth but it's like the ac	l wiping It	Status		Туре	Sebastian Cepeda - Brandt  Date Created Dec 18, 2022	Dec 15, 2022 01:17:00 A	Date Completed Jan 15, 2023	_	2.
S T G G G G G G G G G G G G G G G G G G	TRAFTED DIAGNOSING 13-85-503R AND PACE SETTER SHOWER UP AND TOOK OVER ALK TO FOREMAN DAN AND WAS TOLD TO PUT RADIO IN 745C STRABBED RADIO FROM FOREMAN AND WAITED AT MOBERLY RUCK NEVER SHOWED UP, CALLED TRUCK FOREMAN WAS TOLD TO GO TO DAM ORE VAITED FROM TRUCK, WIRED IN NEW RADIO AND INSTALLED RIED RADIO AND RADIO WAS NOT WORKING, RADIO GIVEN BY FOREMAN WAS AULTY TO RADIOS IN MAIN OFFICE NFORMED FOREMAN AND WAS GIVEN ANOTHER JOB  Work Order Description  Windshield wiper is non-working. I don't mind getting out and every so often  I can hear the crank turning back and forth but it's like the ac wiper came loose.	l wiping It	Status		Type Corrective	Date Created Dec 18, 2022 08:29:39 AM	Dec 15, 2022 01:17:00 A	Date Completed Jan 15, 2023 02:02:20 PM	_	2.: 4.: rs Late
S T G G T T G G T T G G T T G G T T G G G G T T G	ITARTED DIAGNOSING 13-85-503R AND PACE SETTER SHOWER UP AND TOOK OVER ALK TO FOREMAN DAN AND WAS TOLD TO PUT RADIO IN 745C SRABBED RADIO FROM FOREMAN AND WAITED AT MOBERLY RUCK NEVER SHOWED UP, CALLED TRUCK FOREMAN WAS TOLD TO GO TO DAM CORE WAITED FROM TRUCK, WIRED IN NEW RADIO AND INSTALLED RIDED RADIO AND RADIO WAS NOT WORKING, RADIO GIVEN BY FOREMAN WAS AULTY TO RADIOS IN MAIN OFFICE NFORMED FOREMAN AND WAS GIVEN ANOTHER JOB  Work Order Description  Windshield wiper is non-working. I don't mind getting out and every so often  I can hear the crank turning back and forth but it's like the ac wiper came loose.	l wiping it	Status Closed, Co	ompleted	Type Corrective	Date Created Dec 18, 2022 08:29:39 AM	Due Date	Date Completed Jan 15, 2023 02:02:20 PM	Day	2.5 4.5 rs Late
S T C C C V C T T C C V C T T C C V C T T C C V C C C C	STARTED DIAGNOSING 13-85-503R AND PACE SETTER SHOWER UP AND TOOK OVER ALK TO FOREMAN DAN AND WAS TOLD TO PUT RADIO IN 745C SRABBED RADIO FROM FOREEMAN AND WAITED AT MOBERLY RUCK NEVER SHOWED UP, CALLED TRUCK FOREMAN WAS TOLD TO GO TO DAM CORE VAITED FROM TRUCK, WIRED IN NEW RADIO AND INSTALLED RIED RADIO AND RADIO WAS NOT WORKING, RADIO GIVEN BY FOREMAN WAS YOULTY OF RADIOS IN MAIN OFFICE NFORMED FOREMAN AND WAS GIVEN ANOTHER JOB  Work Order Description  Windshield wiper is non-working. I don't mind getting out and every so often  I can hear the crank turning back and forth but it's like the ac wiper came loose.  Fask Description  Dec18 2022ns	l wiping it	Status Closed, Co	ompleted Assigned	Type Corrective	Date Created Dec 18, 2022 08:29:39 AM	Due Date  Date Completed	Date Completed Jan 15, 2023 02:02:20 PM	Day Hours	2.: 4.5
S T C V V T T F N III	STARTED DIAGNOSING 13-85-503R AND PACE SETTER SHOWER UP AND TOOK OVER ALK TO FOREMAN DAN AND WAS TOLD TO PUT RADIO IN 745C SRABBED RADIO FROM FOREEMAN AND WAITED AT MOBERLY RUCK NEVER SHOWED UP, CALLED TRUCK FOREMAN WAS TOLD TO GO TO DAM CORE VAITED FROM TRUCK, WIRED IN NEW RADIO AND INSTALLED RIED RADIO AND RADIO WAS NOT WORKING, RADIO GIVEN BY FOREMAN WAS YOULTY OF RADIOS IN MAIN OFFICE NFORMED FOREMAN AND WAS GIVEN ANOTHER JOB  Work Order Description  Windshield wiper is non-working. I don't mind getting out and every so often  I can hear the crank turning back and forth but it's like the ac wiper came loose.  Fask Description  Dec18 2022ns	l wiping it	Status Closed, Co	ompleted Assigned	Type Corrective	Date Created Dec 18, 2022 08:29:39 AM	Due Date  Date Completed	Date Completed Jan 15, 2023 02:02:20 PM	Hours 0.50 0.50	2.: 4.5
S T G G T T G G T T G G T T G G T T G G G G T T G	STARTED DIAGNOSING 13-85-503R AND PACE SETTER SHOWER UP AND TOOK OVER ALK TO FOREMAN DAN AND WAS TOLD TO PUT RADIO IN 745C SRABBED RADIO FROM FOREEMAN AND WAITED AT MOBERLY RUCK NEVER SHOWED UP, CALLED TRUCK FOREMAN WAS TOLD TO GO TO DAM CORE VAITED FROM TRUCK, WIRED IN NEW RADIO AND INSTALLED RIDED RADIO AND RADIO WAS NOT WORKING, RADIO GIVEN BY FOREMAN WAS AULTY OF RADIOS IN MAIN OFFICE NFORMED FOREMAN AND WAS GIVEN ANOTHER JOB  Work Order Description  Windshield wiper is non-working. I don't mind getting out and every so often  I can hear the crank turning back and forth but it's like the act wiper came loose.  Fask Description  Dec18 2022ns leed new wiper blade	l wiping it	Status Closed, Co	Assigned Jay Dhillon	Type Corrective	Date Created Dec 18, 2022 08:29:39 AM  Completed By Nick Vanderkooi  Date Created Dec 31, 2022	Due Date  Due Completed  Jan 15, 2023 02:02:20 PM	Date Completed Jan 15, 2023 02:02:20 PM  Est  Date Completed Dec 31, 2022	Hours 0.50 0.50	4.5 rs Late
S T C C V T F F N III	STARTED DIAGNOSING 13-85-503R AND PACE SETTER SHOWER UP AND TOOK OVER ALK TO FOREMAN DAN AND WAS TOLD TO PUT RADIO IN 745C SRABBED RADIO FROM FOREEMAN AND WAITED AT MOBERLY RUCK NEVER SHOWED UP, CALLED TRUCK FOREMAN WAS TOLD TO GO TO DAM CORE WAITED FROM TRUCK, WIRED IN NEW RADIO AND INSTALLED RIDED RADIO AND RADIO WAS NOT WORKING, RADIO GIVEN BY FOREMAN WAS AULTY TO RADIOS IN MAIN OFFICE NFORMED FOREMAN AND WAS GIVEN ANOTHER JOB  Work Order Description  Windshield wiper is non-working. I don't mind getting out and every so often  I can hear the crank turning back and forth but it's like the act wiper came loose.  Fask Description  Dec18 2022ns  Jeed new wiper blade  Work Order Description	l wiping it	Status Closed, Co Rock Truck	Assigned Jay Dhillon	Type Corrective  To  Type Corrective	Date Created Dec 18, 2022 08:29:39 AM  Completed By Nick Vanderkooi  Date Created Dec 31, 2022 01:11:40 AM	Due Date  Due Completed  Jan 15, 2023 02:02:20 PM	Date Completed Jan 15, 2023 02:02:20 PM  Est  Date Completed Dec 31, 2022 04:43:13 AM	Hours 0.50 0.50	4.5 /s Late  Spent Hour
ST TO TO TO TO THE PART OF THE	STARTED DIAGNOSING 13-85-503R AND PACE SETTER SHOWER UP AND TOOK OVER ALK TO FOREMAN DAN AND WAS TOLD TO PUT RADIO IN 745C SRABBED RADIO FROM FOREEMAN AND WAITED AT MOBERLY RUCK NEVER SHOWED UP, CALLED TRUCK FOREMAN WAS TOLD TO GO TO DAM CORE VAITED FROM TRUCK, WIRED IN NEW RADIO AND INSTALLED RIED RADIO AND RADIO WAS NOT WORKING, RADIO GIVEN BY FOREMAN WAS YOULTY TO RADIOS IN MAIN OFFICE NFORMED FOREMAN AND WAS GIVEN ANOTHER JOB  Work Order Description  Windshield wiper is non-working. I don't mind getting out and every so often  I can hear the crank turning back and forth but it's like the act wiper came loose.  Fask Description  Dec18 2022ns leed new wiper blade  Work Order Description  Needs boost	l wiping it tual Asset Articulated	Status Closed, Co Rock Truck Status Closed, Co	Assigned Jay Dhillon	Type Corrective  To  Type Corrective To	Date Created Dec 18, 2022 08:29:39 AM  Completed By Nick Vanderkooi  Date Created Dec 31, 2022 01:11:40 AM Completed By	Due Date  Date Completed Jan 15, 2023 02:02:20 PN  Due Date	Date Completed Jan 15, 2023 02:02:20 PM  Est  Date Completed Dec 31, 2022 04:43:13 AM Est	Hours 0.50 0.50	4.5 rs Late

		 				1	.00 1.00
Work	Work Order Description	Status	Туре	Date Created	Due Date	Date Completed	Days Late
64178	Needs new wiper blade	Closed, Co	mpleted Corrective	<b>,</b> ,		Jan 03, 2023	
				11:29:11 PM	1	04:08:00 AM	
	Box pins need to be tightened						
_	ask Description	 Asset	Assigned To	Completed By	Date Completed	Est Ho	urs Spent Hours
2	Jan 23-Tony.B-NS-	Articulated Rock Truck	Anthony Balint	Daniel Reid	jan 03, 2023 04:08:00 AN	М	2.00

Inspected unit, Found Rear Right Box pin retaining bolt loose-Tightened bolt, Complaint about wiper blade, Wiper was in good condition was just frozen-Fixed

<b>Work</b> 64179	Work Order Description  Park break continuously gets stuck on and audible alarm go	Status Des off. Closed, (	Type Completed Corrective	Date Creat Jan 03, 2 01:16:12	023	Date Completed Da Jan 04, 2023 04:22:00 AM	nys Late
Ta	ask Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
2)	an 23-Tony.B-NS-	Articulated Rock Truck	Mark Milne	Anthony Balint	Jan 03, 2023 05:00:00 A	AM .	2.00
Te Dr Fo Di Wi Ma Jai Da Tr Ch	arted up unit, isted park brake and was disengaging fine-Couldn't get it to fail, rove unit to shop, rove unit to shop to shop to shop to rove unit to shop to shop to rove unit	Articulated Rock Truck	Mark Milne	Mark Milne	Jan 03, 2023 05:12:00 F	'M	3.00

2.00

ırk	Work Order Description	Status	Time	Date Casalad	David Bada	The Association 1	5.00
541	Front left strut needs recharge (needs strut changed, bottom failed)	bearing Closed, C	•	09:04:33 PM		Jan 15, 2023 01:26:56 AM	ays Late
	ask Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
-W -já -r: -s: -s	3 Jan 2023 - Diego Z vash unit ack/support unit emoved tire tart pulling top strut pin got cockeyed at angle uspect to due jacking needs to be repositioned	Articulated Rock Truck	Blair Townley - Finning	Diego Zamora	Jan 14, 2023 05:09:00 AN		7.50
13 cla	aude white white	Articulated Rock Truck		Claude White	Jan 14, 2023 05:08:00 AM	1	2.00
	elped with removing front left strut L-14-23-REY CONTRERAS	Articulated Rock Truck	Rey Contreras	Rey Contreras	Jan 14, 2023 05:16:00 PM		11.50
R	EMOVED AND INSTALLED STRUT LEFT SIDE FRONT.						
IN	ISTALLED MUD PLUP						
14 -fi -s: -c	HARGING GREASE 4 Jan 2023-Diego Z inished strut install et ride height to spec leade rim and reinstalled wheel orqued wheel nuts to spec	Articulated Rock Truck		Diego Zamora	Jan 15, 2023 05:11:00 AM	ı	9.00
-te •p Ja	est drive, grease check over-good arked	Articulated Rock Truck	Kal Tire	Kal Tire	Jan 17, 2023 11:02:00 AM	ı	

Work	Work Order Description		Status		Туре	Date Created	Due Date	Date Completed	Day	/s Late
64645	Won't regenerate.		Closed, Co	mpleted	Corrective	Jan 12, 2023 02:00:54 AM		Jan 12, 2023 12:29:17 PM	<b>54</b> )	, a Cate
	Task Description	Asset		Assigned	То	Completed By	Date Completed		Hours	Spent Hour
, ( (	12 JAN 2023 - RANDY - NS ASSIST IN EMISSIONS DIAG CLEAR CODES REGEN MONITOR VALUES, SOOT LOADING DOSENT CHANGE, TEMPS DROP QUICKLY WHEN ARD CYCLES	Articulated	J Rock Truck	Randy Kla	tt	Randy Klatt	Jan 12, 2023 05:00:00 AN	м		1.0
1	NSPECT SYSTEM FOUND DPF CLAMP BROKEN AND LEAKING NEEDS NEW CLAMP an 12 2023 tyler penkoff	Articulated	1 Rock Truck			Tyler Penkoff	Jan 12, 2023 05:16:00 AN	4	1.00	1.0
	assisted randy									
: (	1.2 January 2023 - Blair T - Complaint DISPATCHED BY NICK MISSIONS/DPF LEAK/LOW STRUT	Articulated	f Rock Truck	Blair Town	iley - Finning	Blair Townley - Finning	Jan 12, 2023 01:44:00 PM	1		3.0
	Correction/Repair Process Comments OCATE UNIT (UNIT NOT AT TRUCK LAYDOWN/SHOP YARD AS DIRECTED) DPEN HOOD AND RE-POSITION/DPF CLAMP AND TIGHTEN CHECK STRUTS AND FIND R/H STRUT LOWER BEARING FAILED AND LEFT HAND LOOK WORN CONNECT ET AND FIND SOOT LOAD @ 135% FIRE UP/WARM UP ATTEMPT REGEN (FAIL DUE TO LOW EXH TEMP) CLEAR PERMANENT LOCKOUT EVENT RUN UNIT/TORQUE STALL AND GET ENGINE ABOVE 160F PERFORM REGEN (SUCCESS) CLEAN UP NFORM FOREMAN THAT UNIT NEEDS TO COME TO SHOP FOR STRUT REPAIR SVC RPT	5								
-	3VC (N 1								1.00	5.00
Work -	Work Order Description		Status		Туре	Date Created	Due Date	Date Completed		s Late
64863	Accumulator gas pressure faults.		Closed, Co	mpleted	Corrective	Jan 16, 2023 09:17:41 AM		Jan 16, 2023 04:55:04 PM	٠	
_	Task Description	Asset		Assigned		Completed By	Date Completed		Hours	Spent Hours
	Accumulator gas pressure test over due was the code. Went through sis and did the steps to pump off the brakes. Kicked in the test. Test failed because of low brake accumulators under the box. The Schrader valve on		l Rock Truck	Thomas R	agan	Thomas Ragan	Jan 16, 2023 04:55:04 PM	1	6.50	
(   	one of the accumulators was leaking so that valve was replaced and accumulator was recharged. Retried the test. Stilled fail. Removed the right side panel. Grab a new Accumulator from the warehouse and charged at the shop removed accumulator from unit and installed new accumulator. Retested. Test was successful. Reinstalled side shield									
, ,	recharged. Retried the test. Stilled fail. Removed the right side panel. Grab a new Accumulator from the warehouse and charged at the shop removed accumulator from unit and installed new accumulator. Retested. Test was successful. Reinstalled side shield								6.50	
Work	recharged. Retried the test. Stilled fail. Removed the right side panel. Grab a new Accumulator from the warehouse and charged at the shop removed accumulator from unit and installed new accumulator. Retested. Test was successful. Reinstalled side shield Work Order Description		Status Closed, Co	mpleted	Type Corrective	Date Created Jan 17, 2023 09:19:27 AM		Date Completed Jan 17, 2023 03:39:05 PM		s Late
Work 64912	recharged. Retried the test. Stilled fail. Removed the right side panel. Grab a new Accumulator from the warehouse and charged at the shop removed accumulator from unit and installed new accumulator. Retested. Test was successful. Reinstalled side shield  Work Order Description  Oil leak from base of engine.  Task Description			mpleted Assigned	Corrective	jan 17, 2023		Jan 17, 2023 03:39:05 PM		s Late Spent Hours
Work 64912	recharged. Retried the test. Stilled fail. Removed the right side panel. Grab a new Accumulator from the warehouse and charged at the shop removed accumulator from unit and installed new accumulator. Retested. Test was successful. Reinstalled side shield  Work Order Description  Oil leak from base of engine.	Asset Articulated			Corrective	Jan 17, 2023 09:19:27 AM		Jan 17, 2023 03:39:05 PM Est	Day	
Work 64912	recharged. Retried the test. Stilled fail. Removed the right side panel. Grab a new accumulator from the warehouse and charged at the shop removed accumulator from unit and installed new accumulator. Retested. Test was successful. Reinstalled side shield  Work Order Description Oil leak from base of engine.  Task Description Removed the Inspection hatch, started unit and let run to operating temperature. Didn't find any oil leaks did see oil from the crank case vent. Looks like the crank case vent has saturated the dirt in the belly. Put some spill pads to help soak up that esidual oil.	Asset Articulated	Closed, Co	Assigned	Corrective	Jan 17, 2023 09:19:27 AM Completed By	Date Completed	Jan 17, 2023 03:39:05 PM Est	<b>Da</b> y Hours	
Work 64912	recharged. Retried the test. Stilled fail. Removed the right side panel. Grab a new Accumulator from the warehouse and charged at the shop removed accumulator from init and installed new accumulator. Retested. Test was successful. Reinstalled side shield  Work Order Description Oil leak from base of engine.  Task Description Removed the Inspection hatch, started unit and let run to operating temperature. Didn't find any oil leaks did see oil from the crank case vent. Looks like the crank case vent has saturated the dirt in the belly. Put some spill pads to help soak up that esidual oil.  Work Order Description	Asset Articulated	Closed, Co	<b>Assigned</b> Thomas Ra	Corrective To agan Type	Jan 17, 2023 09:19:27 AM Completed By Thomas Ragan	Date Completed Jan 17, 2023 03:39:05 PM Due Date	Jan 17, 2023 03:39:05 PM Est	Day Hours 2.00  2.00  Day	
Work 64912 Work 65153	recharged. Retried the test. Stilled fail. Removed the right side panel. Grab a new Accumulator from the warehouse and charged at the shop removed accumulator from unit and installed new accumulator. Retested. Test was successful. Reinstalled side shield  Work Order Description Oil leak from base of engine.  Task Description Removed the Inspection hatch, started unit and let run to operating temperature. Didn't find any oil leaks did see oil from the crank case vent. Looks like the crank case vent has saturated the dirt in the belly. Put some spill pads to help soak up that residual oil.  Work Order Description 745C PM2 500 Service Hours	Asset Articulated	Closed, Co	<b>Assigned</b> Thomas Ra	Corrective To	Jan 17, 2023 09:19:27 AM Completed By Thomas Ragan	Date Completed Jan 17, 2023 03:39:05 PM  Due Date Jan 23, 2023	Jan 17, 2023 03:39:05 PM Est	Day Hours 2.00	Spent Hours
Work 64912 Work 65153	recharged. Retried the test. Stilled fail. Removed the right side panel. Grab a new Accumulator from the warehouse and charged at the shop removed accumulator from init and installed new accumulator. Retested. Test was successful. Reinstalled side shield  Work Order Description Oil leak from base of engine.  Task Description Removed the Inspection hatch, started unit and let run to operating temperature. Didn't find any oil leaks did see oil from the crank case vent. Looks like the crank case vent has saturated the dirt in the belly. Put some spill pads to help soak up that esidual oil.  Work Order Description	Asset Articulated	Closed, Co	<b>Assigned</b> Thomas Ra	To again  Type Preventive Planned	Jan 17, 2023 09:19:27 AM Completed By Thomas Ragan  Date Created Jan 22, 2023	Date Completed Jan 17, 2023 03:39:05 PM  Due Date Jan 23, 2023	Jan 17, 2023 03:39:05 PM Est Date Completed Jan 22, 2023 08:15:32 AM	Day Hours 2.00  2.00  Day	Spent Hours

-	it was throwing a bunch of audible alarms a d dash lights?	Asset	Assigned	·	Complet	11:08:51 AM	Date Completed	01:46:47 PM		Spent Hours
65209	Truck is broken down at L6. Cross shift didn't put it in the app		Completed	Corrective		lan 23, 2023		Ian 23, 2023	Day	s Late
Work –	Work Order Description	Status		Туре		Date Created	Due Date	Date Completed		s Late
							, 25, 2025 11.05.00 AF		4.00	· <u></u> -
	ransmission and Transfer Gear Breather - Replace	Articulated Rock Truck			PMtech		Jan 29, 2023 11:09:00 AM	1	2.00	
	ransmission Clutch Calibrations - Complete	Articulated Rock Truck			FMIECH		Jan 29, 2023 11:09:00 AM	ı	2.00	
	ollover Protective Structure (ROPS) - Inspect orque Converter, Transmission, and Transfer Gear Oil - Change	Articulated Rock Truck Articulated Rock Truck			PMtech		Inc. 20, 2022 11:00:00 AM	•	2.00	
	scillating Hitch - Adjust	Articulated Rock Truck								
	lydraulic Tank Strainer - Clean/Inspect/Replace	Articulated Rock Truck			PMtech		Jan 29, 2023 11:09:00 AM	1	2.00	
	lydraulic System Oil Filter Inspect (Cut Filter and Record Findings)	Articulated Rock Truck								
	ydraulic System Oil Filter and Screen - Clean/Inspect/Replace	Articulated Rock Truck			PMtech		Jan 29, 2023 11:09:00 AM		2.00	
	uel Tank Cap Filter - Replace	Articulated Rock Truck								
C	ab Recirc Air Filter Element (Inner) - Replace	Articulated Rock Truck	PMtech		PMtech		Jan 29, 2023 11:09:00 AM		2.00	
В	rake Tank Strainer - Clean/Inspect/Replace	Articulated Rock Truck	PMtech		PMtech		Jan 29, 2023 11:09:00 AM		2.00	
	rake Oil Filter - Replace	Articulated Rock Truck			PMtech		Jan 29, 2023 11:09:00 AM	I	2.00	
_	attery or Battery Cable - inspect/Replace	Articulated Rock Truck				-				-,
т	ask Description	Asset	Assigned	Planned	Complet	08:15:32 AM ed Bv	08:15:00 AM Date Completed	11:09:44 AM Est H	lours	Spent Hou
55155	745C PM3 1000 Service Hours	Closed,	Completed	Preventive	- '	Jan 22, 2023		Jan 29, 2023	0	
Work	Work Order Description	Status		Type		Date Created	The state of the s	Date Completed	-	/s Late
									7.00	
5	uspension System - Check	Articulated Rock Truck	PMtech							
	ervice Brake Wear Indicator - Check	Articulated Rock Truck								
	efrigerant Dryer - Replace	Articulated Rock Truck								
	ydraulic Tank Breather - Replace	Articulated Rock Truck			PMtech		Jan 29, 2023 11:07:00 AM	l	1.00	
	rame and Body - Inspect	Articulated Rock Truck								
E	ngine Valve Łash - Check	Articulated Rock Truck	PMtech							
E	ngine Compression Brake Valve Lash - Check	Articulated Rock Truck	PMtech		PMtech		Jan 29, 2023 11:07:00 AM		1.00	
Þ	iff and Final Drive Oil - Change (note particulates on mag plug and idicate findings)	Articulated Rock Truck	PMtech		PMtech		Jan 29, 2023 11:07:00 AM		1.00	
	reather (Brake Tank) - Replace	Articulated Rock Truck	PMtech		PMtech		Jan 29, 2023 11:07:00 AM		1.00	
	rake System Air - Purge	Articulated Rock Truck			PMtech		Jan 29, 2023 11:07:00 AM		1.00	
	rake Oil - Change	Articulated Rock Truck			PMtech		Jan 29, 2023 11:07:00 AM		1.00	
	xie Breathers - Clean/Replace	Articulated Rock Truck		110	PMtech	ed by	(an 29, 2023 11:07:00 AM		1.00	Spent Hou
	ask Description	Asset	Assigned	Planned	Complet	08:15:32 AM	08:15:00 AM Date Completed	11:08:27 AM Est H		C 11
55154	745C PM4 2000 Service Hours	Closed,	Completed	Preventive	-	Jan 22, 2023		Jan 29, 2023	0	
Nork	Work Order Description	Status		Туре		Date Created	Due Date	Date Completed	Day	/s Late
_										
Tr	ransmission Oil Filter - Inspect (Cut Filter and Record Findings.)	Articulated Rock Truck	: PMtech							
Tı	ransmission Oil Filter Replace	Articulated Rock Truck	PMtech							
Tr	ransfer Gear Oil Sample - Obtain	Articulated Rock Truck	PMtech							
	orque Converter and Transmission Oil Sample - Obtain	Articulated Rock Truck								
	teering System Oil Sample - Obtain	Articulated Rock Truck								
	econdary Steering - Test	Articulated Rock Truck								
	oist System and Brake System Oil Sample - Obtain	Articulated Rock Truck								
	uel System Secondary Filter - Replace	Articulated Rock Truck								
	ngine Oil Filter Inspect (Cut Filter and Record Findings) uel System Primary Filter - Replace	Articulated Rock Truck Articulated Rock Truck								
	ngine Oil and Filter - Change	Articulated Rock Truck								
	ngine Air Filter Secondary Element (Outer) - Replace	Articulated Rock Truck								
	ifferential and Final Drive Oil Sample - Obtain	Articulated Rock Truck								
* * * * * * * * * * * * * * * * * * * *	ndings)									
	iff & Final Drive Oil Level - Check (note particulates on mag plug and indicate	Articulated Rock Truck	c PMtech							

Jay Dhillon

Articulated Rock Truck

Date Completed Jan 23, 2023 01:46:47 PM

Completed By Jay Dhillon

k 147	Work Order Description  Sun visor won't stay in place. Continuously retracting while and button is broke off	driving.	Status Closed, Coi	mpleted	Type Corrective		Date Created Jan 25, 2023 03:04:48 PM	Due Date	pate Completed jan 25, 2023 07:11:50 PM	Day	s Late
Т	ask Description	Asset		Assigned	To	Complete	ed By	Date Completed	Est i	lours	Spent Ho
R	eplace visor	Articulated	Rock Truck	Nick Miser	ner	Nick Miser	ier	Jan 25, 2023 07:11:45 PN		1.00	]
_								· · · · · · · · · · · · · · · · · · ·		1.00	1
k -	Work Order Description		Status		Тура		Date Created	Due Date	Date Completed		s Late
53	745C PM2 500 Service Hours		Closed, Cor	nnleted	Preventive -	_	lan 29, 2023	lan 30, 2023	lan 29. 2023	0	·
	7-36 11/12 300 36. 1166 1166.3		Ciosca, Coi	iipicteu	Planned		11:10:13 AM		11:10:13 AM	U	
т	ask Description	Asset		Assigned		Complete		Date Completed		lours	Spent Ho
B	rake Accumulator (Service) - Check	Articulated	Rock Truck	PMtech		•					
8	rake Pads - Check	Articulated	Rock Truck	PMtech							
В	raking System - Test	Articulated	Rock Truck	PMtech							
	iff & Final Drive Oil Level - Check (note particulates on mag plug and indicate	Articulated	Rock Truck	PMtech							
	ndings) ifferential and Final Drive Oil Sample - Obtain	Articulated	Rock Truck	PMtech							
	ngine Air Filter Secondary Element (Outer) - Replace	Articulated		PMtech							
	ngine Oil and Filter - Change	Articulated		PMtech							
	ngine Oil Filter Inspect (Cut Filter and Record Findings)	Articulated		PMtech							
F	uel System Primary Filter - Replace	Articulated	Rock Truck	PMtech							
F	uel System Secondary Filter - Replace	Articulated	Rock Truck	PMtech							
Н	oist System and Brake System Oil Sample - Obtain	Articulated	Rock Truck	PMtech							
S	econdary Steering - Test	Articulated	Rock Truck	PMtech							
	teering System Oil Sample - Obtain	Articulated :	Rock Truck	PMtech							
	orque Converter and Transmission Oil Sample - Obtain	Articulated		PMtech							
	ransfer Gear Oil Sample - Obtain	Articulated I		PMtech							
	ransmission Oil Filter Replace ransmission Oil Filter - Inspect (Cut Filter and Record Findings.)	Articulated   Articulated		PMtech PMtech							
_ =											
k ·	Work Order Description		Status		Туре		Date Created	Due Date	Date Completed	-	Late
554	745C PM2 500 Service Hours		Closed, Cor		Preventive - Planned		Jan 29, 2023 11:10:16 AM	11:10:00 AM	Jan 29, 2023 11:10:16 AM	0	
	ask Description	Asset		Assigned	То	Complete	d By	Date Completed	Est H	lours	Spent Ho
	rake Accumulator (Service) - Check	Articulated		PMtech							
	rake Pads - Check	Articulated I		PMtech							
	raking System - Test	Articulated (		PMtech		D441 I-					
	iff & Final Drive Oil Level - Check (note particulates on mag plug and indicate ndings)	Articulated I	HOCK Truck	PMtech		PMtech		Jan 29, 2023 11:11:00 AM	İ	1.00	
Ď	ifferential and Final Drive Oil Sample - Obtain	Articulated I	Rock Truck	PMtech		PMtech		Jan 29, 2023 11:11:00 AM	Ì	1.00	
E	ngine Air Filter Secondary Element (Outer) - Replace	Articulated I	Rock Truck	PMtech		PMtech		Jan 29, 2023 11:11:00 AM	I	1.00	
	ngine Oil and Filter - Change	Articulated I	Rock Truck	PMtech		PMtech		Jan 29, 2023 11:11:00 AM		1.00	
	ngine Oil Filter Inspect (Cut Filter and Record Findings)	Articulated I		PMtech							
	uel System Primary Filter - Replace	Articulated I		PMtech		PMtech		Jan 29, 2023 11:11:00 AM	1	1.00	
	uel System Secondary Filter - Replace	Articulated I		PMtech		PMtech		Jan 29, 2023 11:11:00 AM	I	1.00	
	oist System and Brake System Oil Sample - Obtain	Articulated I		PMtech		PMtech		Jan 29, 2023 11:11:00 AM	I	1.00	
	econdary Steering - Test	Articulated I		PMtech							
	teering System Oil Sample - Obtain	Articulated i		PMtech		PMtech		Jan 29, 2023 11:11:00 AM		1.00	
	orque Converter and Transmission Oil Sample - Obtain	Articulated I		PMtech		PMtech		jan 29, 2023 11:11:00 AM		1.00	
	ransfer Gear Oil Sample - Obtain ransmission Oll Filter Replace	Articulated I Articulated I		PMtech PMtech		PMtech		Jan 29, 2023 11:11:00 AM		1.00	
	ransmission Oil Filter - Inspect (Cut Filter and Record Findings.)	Articulated I		PMtech PMtech		PMtech		jan 29, 2023 11:11:00 AM	I	1.00	
-	manuscription on their impreed (ede theer and necord thidings.)	or discussion in	NOUN TIUCK	rimitetti					1	1.00	
·k –	Work Order Description		Status		Туре		Date Created	Due Date	Date Completed		Late
	Needs new wiper blade		Closed, Con	nnleted	Corrective		lan 31, 2023		lan 31, 2023	/-	
544											

	ask Description	Asset	N1- T	Assigned		Completed By	Date Completed Jan 31, 2023 11:36:00 AM	Est Hours	Spent Hou
ia	n 31 2023 tyler penkoff	Articulated F Articulated F			COTT		Jan 31, 2023 11:36:00 AM Jan 31, 2023 04:41:00 PM		1.0
ví	per changed and operation good.			<u></u>					
. =	Maria Baranda Maria		Status		Туре	Date Created	Due Date	Date Completed Da	ys Late
ork 5999	Work Order Description Chock block bracket is bent.			Completed	Corrective	Feb 07, 2023 02:12:35 PM		Feb 08, 2023 08:26:14 AM	,
т	ask Description	Asset		Assigne		Completed By	Date Completed	Est Hours	Spent Hou
_		Articulated F	Rock Truck	Nick Mise	ner	Nick Misener	Feb 08, 2023 08:26:14 AM	1 <u> </u>	
ork _	Work Order Description		Status		Туре	Date Created	Due Date	•	ys Late
5020	Blind side small mirror fell off		Closed,	Completed	Corrective	Feb 08, 2023 02:09:03 AM	A contract of the contract of	Feb 08, 2023 08:26:07 AM	
	ask Description	Asset		Assigne		Completed By	Date Completed	Est Hours	Spent Ho
Re —	eplace mirror	Articulated F	Rock Truck	Nick Mise	ner	Nick Misener	Feb 08, 2023 08:26:07 AM	4 1.00 1.00	<del>.</del>
ork	Work Order Description		Status		Туре	Date Created	Due Date		ys Late
6060	Drivers seat is leaning to the left.		Closed,	Completed	Corrective	Feb 08, 2023 06:27:19 PM		Feb 09, 2023 02:41:45 AM	•
	ask Description	Asset		Assigne		Completed By	Date Completed	Est Hours	Spent Ho
Fr D	eb 08 2023 NS rove out to unit-checked seat and adjusted seat guide found no other issue	Articulated F	Rock Truck	Jay Dhillo	ר	Jay Dhillon	Feb 09, 2023 02:41:45 AN	1.00	
_						-		1.00	
ork 6074	Work Order Description  Left side hoist cylinder grease Point ( bottom) won't take gre		Status Closed,	Completed	Type Corrective	Pate Created Feb 09, 2023	and the second s	Feb 09, 2023	ys Late
7	ask Description	Asset		Assigne	1 To	07:43:48 AM Completed By	Date Completed	10:33:34 AM Est Hours	Spent Ho
<u>.</u>	ask Description	Articulated F	Rock Truck				Feb 09, 2023 10:33:34 AM		··
								·	
ork –	Work Order Description		Status	-	Type	Date Created	Due Date	Date Completed Da	ys Late
	Work Order Description Possible transmission leak			Completed	Type Corrective	Date Created Feb 11, 2023 08:02:18 AM	La capacita de la composición del composición de la composición de	Date Completed Da Feb 13, 2023 04:11:42 PM	ys Late
6154	•	Asset	Closed,	Assigne	Corrective	Feb 11, 2023	La capacita de la composición del composición de la composición de	Feb 13, 2023	•
_	Possible transmission leak		Closed,	Assigned Kory Kaes	Corrective	Feb 11, 2023 08:02:18 AM Completed By		Feb 13, 2023 04:11:42 PM Est Hours	Spent Ho
6154 <u>T</u> fo fo se se se se se re	Possible transmission leak	Asset Articulated F	Closed,	Assigned Kory Kaes	Corrective  I To  model - Wajax	Feb 11, 2023 08:02:18 AM Completed By	Date Completed	Feb 13, 2023 04:11:42 PM Est Hours	ys Late Spent Hou 6.
6154  T  fc  m  si  si  p  p	Possible transmission leak  ask Description  ebruary 12/23 -Kory K-Wajax  ound transfer case output seal was leaking. Went to wearhouse got parts. Went to nachine removed driveshaft. U joints were dry replaced both ujoints. Removed old eal. Installed new seal into case shop dosent have proper seal installed to install peedy sleeve onto the yoke. carefully tapped seal into place with a hammer and lece of wood. got in fully seated. isntalled yoke and driveline. took truck for test dive eal is still leaking, took outdirveshaft again, found spedy sleve on yoke is cracked. emoved seal. wearhouse dosent have anymore seals. crossed with foreman. have	Asset Articulated F	Closed, Rock Truck Rock Truck	Assigned Kory Kaes Kory Kaes	Corrective  I To  model - Wajax	Feb 11, 2023 08:02:18 AM Completed By Kory Kaesmodel - Wajax	Date Completed	Feb 13, 2023 04:11:42 PM Est Hours	Spent Ho
5154  Fr  fc  m  ss  si  p  fc  fc  fc  fc  fc  fc  fc  fc  fc	Possible transmission leak  Task Description  ebruary 12/23 -Kory K-Wajax  bund transfer case output seal was leaking. Went to wearhouse got parts. Went to achine removed driveshaft. U joints were dry replaced both ujoints. Removed old eal. Installed new seal into case shop dosent have proper seal installed to install peedy sleeve onto the yoke. carefully tapped seal into place with a hammer and iece of wood. got in fully seated. isntalled yoke and driveline. took truck for test dive eal is still leaking. took outdirveshaft again, found spedy sleve on yoke is cracked emoved seal. wearhouse dosent have anymore seals. crossed with foreman. have alanner looking for another po that has a seal in it.	Asset Articulated F Articulated F	Closed, Rock Truck Rock Truck	Assigned Kory Kaes Kory Kaes	Corrective i To model - Wajax model - Wajax	Feb 11, 2023 08:02:18 AM Completed By Kory Kaesmodel - Wajax	<b>Date Completed</b> Feb 12, 2023 08:24:00 Af	Feb 13, 2023 04:11:42 PM Est Hours	Spent Ho
6154  T  fc  fc  fc  fc  fc  fc  fc  fc  fc	Possible transmission leak  Task Description  ebruary 12/23 -Kory K-Wajax  bund transfer case output seal was leaking. Went to wearhouse got parts. Went to hackine removed driveshaft. U joints were dry replaced both ujoints. Removed old eal. Installed new seal into case shop dosent have proper seal installed to install peedy sleeve onto the yoke. carefully tapped seal into place with a hammer and lece of wood. got in fully seated, isntalled yoke and driveline, took truck for test dive eal is still leaking, took outdriveshaft again, found spedy sleeve on yoke is cracked, emoved seal, wearhouse dosent have anymore seals, crossed with foreman, have lanner looking for another po that has a seal in it.  ebruary 13/23 -kory K-Wajax  become had machinist makea drive for seal isntalled new speedy sleeve onto yoke, shalled into truck and driveline. Torqued ujoint cap bolts. Ram machine took for livive around shop verified it wasent leaking. Pulled into lube bay topped up transmission oil level and parked in up line, called unit up.	Asset Articulated F Articulated F	Closed,  Rock Truck Rock Truck	Assigned Kory Kaes Kory Kaes	Corrective i To model - Wajax model - Wajax	Feb 11, 2023 08:02:18 AM Completed By Kory Kaesmodel - Wajax Kory Kaesmodel - Wajax	Date Completed Feb 12, 2023 08:24:00 AM Feb 13, 2023 01:58:00 PM	Feb 13, 2023 04:11:42 PM Est Hours	Spent Ho
6154  T  fc  n  ss  ss  r  p  F  fc  fc  fc  fc  fc  fc  fc  fc  fc	Possible transmission leak  Task Description  ebruary 12/23 -Kory K-Wajax  bund transfer case output seal was leaking. Went to wearhouse got parts. Went to nachine removed driveshaft. U joints were dry replaced both ujoints. Removed old eal. Installed new seal into case shop dosent have proper seal installed to install peedy sleeve onto the yoke, carefully tapped seal into place with a hammer and lece of wood, got in fully seated, isntalled yoke and driveline, took truck for test dive eal is still leaking, took outdirveshaft again, found spedy sleeve on yoke is cracked, emoved seal, wearhouse dosent have anymore seals, crossed with foreman, have lanner looking for another po that has a seal in it.  ebruary 13/23 -kory K-Wajax  breman had machinist makea drive for seal isntalled new speedy sleeve onto yoke, sintalled into truck and driveline. Torqued ujoint cap bolts, Ram machine took for lrive around shop verified it wasent leaking. Pulled into lube bay topped up	Asset Articulated F Articulated F	Closed,  Rock Truck  Rock Truck  Rock Truck	Assigned Kory Kaes Kory Kaes	Corrective i To model - Wajax model - Wajax	Feb 11, 2023 08:02:18 AM Completed By Kory Kaesmodel - Wajax	Date Completed Feb 12, 2023 08:24:00 AM Feb 13, 2023 01:58:00 PM	Feb 13, 2023 04:11:42 PM Est Hours	Spent Hou

"locate unit unit has high soot load permanent regen lock out soot load 135% clear permanent lock out with FPS warm unit up to temp perform regen soot load drops to 0%"

ork	Work Order Description		Status		Type	Date Created	Due Date	Date Completed	Days Late	
314	Recliner seat portion has lots of play.		Closed, Co	ompleted	Corrective	Feb 14, 2023 10:04:38 PM		Feb 15, 2023 09:16:00 PM	Days tate	
	ask Description	Asset		Assigned	d To		Date Completed	Est Hou	ırs Speni	t Ho
	February 2023 - Gabe Elnamer eplaced seat	Articulated	d Rock Truck	Gabe Elna	amer	Gabe Elnamer	Feb 15, 2023 09:16:00 PI	м		-
rk —	Work Order Description		Status	<del>-</del>	Туре	Date Created	Due Date	Date Completed	Days Late	2
390	Accumulator gas pressure fault		Closed, Co	mpleted	Corrective	Feb 16, 2023 07:08:45 AM		Feb 17, 2023 05:07:38 AM	Days cate	
Ta	ask Description	Asset		Assigned	i To		Date Completed	Est Hou	ırs Speni	Ho:
Re	moved and replaced accumalators charged up rear and front		d Rock Truck d Rock Truck	Christoph	er Paul		Feb 17, 2023 05:07:38 AF Feb 17, 2023 05:07:00 PM	м		3
_										3
ork 1442	Work Order Description Transfer case leaking / Both left & right top mirrors are loose.		Status Closed, Co	mpleted	Type Corrective	Date Created Feb 17, 2023	Due Date	Date Completed Feb 18, 2023	Days Late	
	Telescopic steering not working, only moves up & down not in and low brake accumulator pressure / will need accumulators			•		10:42:24 AM		04:57:33 AM		
	replaced.									
Ta	sk Description	Asset		Assigned	l To	Completed By	Date Completed	Est Hou	rs Spent	Ha
	Feb 23-Tony.B-N5-		Rock Truck	Christophe			<u> </u>	<u> </u>	- Брине	
Re Re Ins	moved driveshaft, moved old seal, stalled new seal,	Articulated	1 Rock Truck	Anthony B	saiint	Anthony Balint	Feb 18, 2023 04:00:00 AM	И		
Re Ins Ins To Fix Ins Co	moved driveshaft, moved old seal, stalled new seal, stalled driveshaft, pped up Trans Fluid, sed loose mirrors, spected steering column, spected steering linkages, infirm Telescopic steering function,	Articulated	HOCK TRUCK	Anthony B	alint	Anthony Balint	Feb 18, 2023 04:00:00 AM	4		
Re Ins Ins To Fix Ins Co	moved driveshaft, moved old seal, stalled new seal, stalled driveshaft, pped up Trans Fluid, sed loose mirrors, spected steering column, spected steering linkages,	Articulated	HOCK TRUCK	Anthony B	alint	Anthony Balint	Feb 18, 2023 04:00:00 AM			_
Re Re Ins Ins Ins Co Pa	moved driveshaft, moved old seal, stalled new seal, stalled driveshaft, pped up Trans Fluid, sed loose mirrors, spected steering column, spected steering linkages, infirm Telescopic steering function, rked in Up line,  Work Order Description		Status	Anthony B	Type	Date Created		Date Completed	Days Late	_
Re Re Ins Ins Ins Co Pa	moved driveshaft, moved old seal, stalled new seal, stalled driveshaft, pped up Trans Fluid, sed loose mirrors, spected steering column, spected steering linkages, infirm Telescopic steering function, riked in Up line,  Work Order Description  Exhaust/fumes coming into cab along right side fixed window exhaust pipe. Could just be the window seal.	near		mpleted	Type Corrective	Date Created Feb 18, 2023 08:52:33 AM	Due Date	Date Completed Feb 18, 2023 03:36:40 PM	. •	_
Re Re Ins To Fix Ins Co Pa	moved driveshaft, moved old seal, stalled new seal, stalled driveshaft, pped up Trans Fluid, sed loose mirrors, spected steering column, spected steering linkages, infirm Telescopic steering function, rked in Up line,  Work Order Description  Exhaust/fumes coming into cab along right side fixed window i exhaust pipe. Could just be the window seal.	near Asset	Status Closed, Co	mpleted Assigned	Type Corrective	Date Created Feb 18, 2023 08:52:33 AM Completed By	Due Date	Date Completed Feb 18, 2023 03:36:40 PM Est Hou	rs Spent	Ho
Re Re Ins	moved driveshaft, moved old seal, stalled new seal, stalled driveshaft, pped up Trans Fluid, sed loose mirrors, spected steering column, spected steering linkages, infirm Telescopic steering function, rked in Up line,  Work Order Description  Exhaust/fumes coming into cab along right side fixed window i exhaust pipe. Could just be the window seal.	near Asset	Status	mpleted	Type Corrective	Date Created Feb 18, 2023 08:52:33 AM Completed By	Due Date	Date Completed Feb 18, 2023 03:36:40 PM Est Hou	rs Spent 33	Ho
Re Re Ins	moved driveshaft, moved old seal, stalled new seal, stalled driveshaft, pped up Trans Fluid, sed loose mirrors, spected steering column, spected steering column, spected steering inkages, infirm Telescopic steering function, rked in Up line,  Work Order Description  Exhaust/fumes coming into cab along right side fixed window exhaust pipe. Could just be the window seal. isk Description  f leaking at clamp. Ckeaned soot and tighten clamps	near Asset	Status Closed, Co	mpleted Assigned	Type Corrective To	Date Created Feb 18, 2023 08:52:33 AM Completed By	<b>Due Date</b> Date Completed  Teb 18, 2023 03:36:35 PM	Date Completed Feb 18, 2023 03:36:40 PM Est Hou	rs Spent	Ha
Re Re Ins	moved driveshaft, moved old seal, stalled new seal, stalled driveshaft, pped up Trans Fluid, sed loose mirrors, spected steering column, spected steering linkages, infirm Telescopic steering function, riked in Up line,  Work Order Description  Exhaust/fumes coming into cab along right side fixed window exhaust pipe. Could just be the window seal.  Isk Description  If leaking at clamp. Ckeaned soot and tighten clamps  at drove ok	near Asset	Status Closed, Co	mpleted Assigned Nick Misen	Type Corrective	Date Created Feb 18, 2023 08:52:33 AM Completed By Nick Misener  Date Created Feb 18, 2023	Due Date  Date Completed  Teb 18, 2023 03:36:35 PM  Due Date	Date Completed Feb 18, 2023 03:36:40 PM Est Hou 1.1 Date Completed Feb 18, 2023	rs Spent 33	Ho
Re Re Institute	moved driveshaft, moved old seal, stalled new seal, stalled new seal, stalled driveshaft, pped up Trans Fluid, sed loose mirrors, spected steering column, spected steering flinkages, infirm Telescopic steering function, rked in Up line,  Work Order Description Exhaust/fumes coming into cab along right side fixed window exhaust pipe. Could just be the window seal. Isk Description If leaking at clamp. Ckeaned soot and tighten clamps st drove ok  Work Order Description Telescopic/tilt steering not fixed. *Done*  T-Case still small leak.	near Asset	Status Closed, Co Rock Truck Status	mpleted Assigned Nick Misen	Type Corrective To	Date Created Feb 18, 2023 08:52:33 AM Completed By Nick Misener	Due Date  Date Completed  Teb 18, 2023 03:36:35 PM  Due Date	Date Completed Feb 18, 2023 03:36:40 PM Est Hou	rs Spent	Ha
Regions instance in the instan	moved driveshaft, moved old seal, stalled new seal, stalled new seal, stalled driveshaft, pped up Trans Fluid, sed loose mirrors, spected steering column, spected steering linkages, infirm Telescopic steering function, rked in Up line,  Work Order Description  Exhaust/fumes coming into cab along right side fixed window in exhaust pipe. Could just be the window seal. Sets Description It leaking at clamp. Ckeaned soot and tighten clamps st drove ok  Work Order Description  Telescopic/tilt steering not fixed. *Done*  T-Case still small leak. Brake accumulators 2nd picture is where driver believes the exhaust is leaking out	near Asset Articulated	Status Closed, Co Rock Truck Status	mpleted Assigned Nick Misen	Type Corrective To ner  Type Corrective	Date Created Feb 18, 2023 08:52:33 AM Completed By Nick Misener  Date Created Feb 18, 2023 09:18:48 AM	Due Date  Date Completed  Teb 18, 2023 03:36:35 PM  Due Date	Date Completed Feb 18, 2023 03:36:40 PM Est Hou 1.1 Date Completed Feb 18, 2023	rs Spent 33 33 Days Late	1

3.00

24 April 2023 - Shaure S - REPLACED TRANSMISSION REAR OUTPUT SEAL AND SPEEDY SLEEVE, ACTIVE EMISSION CODES, WILL NOT PERFORM REGEN, FOUND LOOSE WIRING TO SPARK IGNITION AND REPAIRED, PERFORMED REGEN, ACCUMULATOR GASS PRESSURE FAL E1528-1, FOLLOWED TROUBLESHOOTING AND PERFORMED ACCUMULATOR SERVICE PROCEDURE, FAILED WITH LOW ACCUMULATOR CHARGE CODE, CHARGED UP BOTH REAR ACCUMLATORS, CODE STILL ACTIVE, COULD NOT RECHARGE FRONT	<u> </u>	Shaune Shigoka - Wajax	Shaune Shigoka - Wajax	Apr 24, 2023 01:40:00 PM	1	12.00
ACCUMULATOR - DID NOT HAVE PROPER FITTING. 25 April 2023 - Shaune S - SEARCHED FOR FITTING TO CHARGE UP FRONT BRAKE ACCUMULATOR, COULD NOT FIND. CHECKED REAR BRAKE ACCUMULATORS TO MAKE SURE THEY WERE NOT	Articulated Rock Truck	Shaune Shigoka - Wajax	Shaune Shigoka - Wajax	Apr 25, 2023 05:05:00 PM		2.00
LEAKING. CONFIRMED HOLDING CHARGE FROM YESTERDAY. May 11/23 -Matt D-Wajax	Articulated Rock Truck	Matt Derfler - Wajax	Matt Derfler - Wajax	May 11, 2023 10:30:00 AM		1.50
drive to machine boost bring truck to shop.						
May 11/23 -Sebastian C-Brandt	Articulated Rock Truck	Sebastian Cepeda - Brand	lt Sebastian Cepeda - Brandt	May 11, 2023 06:23:00 AM		3.50
"REMOVED GUARDS FROM 19-45-026 DRAINED COOLANT STARTED REMOVING COOLING PACKAGE AND DROP GEAR BOX "						

	Work Order Description	Etatua		T	B-1- G1-1	D D		.00	20.
72	Battery is dead dead needs boost.	Status Closed, C		Туре	Date Created May 20, 20		Pate Completed May 20, 2023	Day	s Late
_	!- <b>D</b> !			_	06:59:51 A		08:22:38 AM		
_	ask Description	Asset	Assigned		Completed By	Date Completed	Est Ho		Spent Hou
<u></u>	mp started unit	Articulated Rock Truck	Thomas Ra	gan	Thomas Ragan	May 20, 2023 08:22:38		L.00	
. –	Work Order Description	Status		*	B-4- 0			.00	
68				Туре	Date Created	Due Date	Date Completed	Day	s Late
00	Throwing codes.accumulater /brake pressure	Closed, C	ompietea	Corrective	May 21, 202		May 22, 2023		
Ta	ask Description	Asset	Assigned 1	ro ·	08:16:26 PN Completed By	n Date Completed	10:44:12 AM Est Ho		Spent Hou
		Articulated Rock Truck	Andy Boetto		Andy Boettger	May 22, 2023 04:00:00		UIS	3pent 1100
cl	leared emissions code,		,	-	· ····································	1.0, 22, 2023 04,00.00	Zu-1		₹.
21	Lst May 2023 - Andy Boettger								
-C	heck brake accumulator code (won't clear need to service accumulator)								
-T	ruck was de-rated did manual regen Lst May 2023 - Gabe Elnamer	nate to care of the	a						
	tst may 2023 - Gabe Emarter Theck brake accumulator code (won't clear need to service accumulator)	Articulated Rock Truck	Gabe Elnam	ier	Gabe Elnamer	May 21, 2023 05:06:00	AM		4
	ruck was de-rated did manual regen.								
	ay 22/23 -Sebastian C- Brandt	Articulated Rock Truck	Sebastian C	epeda - Brandt	t Sebastian Cepeda - Brandt	May 22, 2023 11:58:00	AM		5
"0	PROVE TO UNTI AND HOOKED UP ET					r			
	DUND CODE E1528-2								
	ARMED TRANSMISSION UOP TO TEMP								
	RIED THE SERVICE BRAKE TEST THROUGH THE MONITOR								
	EST PASSED BUT CODE DID NOT CLEAR								
CH	HARGED BOTH REAR BREAK ACCUMULATORS TO 1150PSI BOTH WERE DOWN								
10	00PSI								
	ETRIED TEST, PASSED BUT CODE DID NOT CLEAR								
	RIED PARKING BRAKE TEST AND PASSED, CODE DID NOT CLEAR								
	EMOVED SIDE GUARD AND CHECKED PARKING BRAKE ACCUMUALTOR, NOT								
	ERVICABLE								
	RIED SOURCING OUT ADAPTER TO CHECK AND CHARGE FRONT BRAKE								
	COMULATOR BUT NOONE HAD IT								
	ERIFIED WHEEL SPEED WAS 0 DURING TEST AND BRAKE POSTION WAS COMING ON NO OFF WITH APPLICATION								
	HUT UNIT DOWN, TURNED NIGHT SWITCH OFF, RETRIED SERVICE BRAKE TEST,								
	ASSED CODE DID NOT CLEAR								
	RONT BRAKE ACCUMULATOR SHOULD BE CHARGED								
	AREHOUSE HAS REPLACEMENT ACCUMULATOR FOR PARK BRAKE JUST NEED								
	DAPTER TO FILL								
	STALLED PLASTIC BACK ON AND NOTIFIED FOREMAN NICK OF FINDINGS								
н									
_	<del>-</del>								13.

Туре

**Date Created** 

Due Date

**Date Completed** 

Days Late

Status

**Work Order Description** 

72020	, , , , , , , , , , , , , , , , , , , ,	A	Closed, C	•	4 <b>T</b> a	May 24, 20 03:03:53 F	PM ,	May 24, 2023 09:38:25 PM	•4	Č Navos
	Task Description	Asset Articulated	d Rock Truck	Assigne		Completed By Ian Knott	May 24, 2023 09:38:25	PM	ours	Spent Hours
Work	Work Order Description		Status		Туре	Date Create	1 Due Date	Date Completed	Day	s Late
72041	AC blows warm , note found on seat that taps are turned off		Closed, C	ompleted	•	May 24, 20 09:25:03 F		May 24, 2023 09:34:52 PM		
-	Task Description	Asset Articulated	d Rock Truck	Assigne	i To	Completed By Ian Knott	Date Completed May 24, 2023 09:34:52	PM Est H	ours	Spent Hours
Work	Work Order Description	:10	Status	one of shoot	Type	Date Created	· · · · · · · · · · · · · · · · · · ·	Date Completed	Day	s Late
72047	Operator reported sparks coming from under the machine wh driving, park brake ?  Task Description	Asset	Ciosea, C	ompleted Assigner	Corrective	May 25, 20 12:56:20 A Completed By		May 25, 2023 08:20:28 AM Est H	loure	Spent Hours
	"TRAVELLED TO UNIT AND INSPECTED FOR SPARKS WHEN DRIVING		d Rock Truck				t May 25, 2023 08:20:28		Ours	3.00
   	INSPECTED ALL 4 DRIVELINES INSPECTED AROUND WHEELS INSPECTED PARKING BRAKE ON DRIVE LINE COULD NOT FIND SOURCE OF SPARKS CALLED TRUCK PUSH AND WAS TOLD TRUCK NEEDED A/C FIXED DIAGNOSED A/C NOT WORKING INSTALLED NEW CONTROLLER INSIDE CAB VERIFIED PROPER OPERATION OF A/C SYSTEM"									
										3.00
Work	Work Order Description		Status		Туре	Date Created		Date Completed	Day	s Late
72303			Closed, C	•		May 28, 20 08:03:32 P	Μ	May 29, 2023 04:21:23 AM		
	Task Description May 29	Asset	d Rock Truck	Assigned Nick Mise		Nick Misener	May 29, 2023 04:21:07	Est H	2.83	Spent Hours 2.83
	Dpf high No associated codes Manual regen						<del> </del>		2.83	2.83
Work	Work Order Description		Status		Туре	Date Created	Due Date	Date Completed		s Late
72383			Closed, C	ompleted	Corrective	May 30, 20 04:14:36 A	)23	May 30, 2023 02:16:21 PM	•	
	Task Description	Asset		Assigned		Completed By	Date Completed	Est H	ours	Spent Hours
	31-05-23 Andy Boettger wiper arm bent	Articulated	I Rock Truck	Andy Boe	ttger	Menno Buhler	May 30, 2023 02:16:21	РМ		1.00
	removed and replaced wiper arm and installed new wiper blade									1.00
Work	Work Order Description		Status		Туре	Date Created	Due Date	Date Completed	Day	s Late
72488	High DPF level & shut down immediately		Closed, C	ompleted		May 31, 20 07:48:57 P		Jun 01, 2023 02:02:34 AM		
	Task Description	Asset		Assigned		Completed By	Date Completed	Est H		Spent Hours
	Manual regen	Articulated	d Rock Truck	Nick Mise	ner	Nick Misener	jun 01, 2023 02:02:29 A	_	2.83	2.83
									2.83	2.83
Work	Work Order Description		Status		Туре	Date Created		Date Completed	Day	s Late
72577			Closed, C		Corrective	Jun 02, 202 06:01:27 P	M	jun 07, 2023 09:24:36 AM		
	Task Description	Asset	t Barrie Tarrett	Assigned		Completed By	Date Completed	Est H		Spent Hours
	Regen temp low and secondary air press codes 140.5 soot load factory lock out 07 June 2023 - Kris W -		i Rock Truck		ms - Finning ms - Finning	Menno Buhler Kris Williams - Finning	Jun 07, 2023 09:24:36 A Jun 07, 2023 07:51:00 A		1.83	3.00
	"locate unit unit has code for aftertreatment loss of combustion code unit also has high dpf soot load code clear combustion code									

warm unit up to temp -perform regen soot load drops from 127% to 0% clean work area\*

	Marie Order Description		Status		Turne	Date Created	Due Date	Data Camalatad	1.83	3.0
ork 3043	Work Order Description  Left rear rad needs to be cleaned			ompleted	Туре	Jun 09, 2023 08:47:01 PM	DUO DATO	Jun 10, 2023 03:51:09 AM	Va	ys Late
7	ask Description	Asset		Assigned	i To	Completed By	Date Completed	+	t Hours	Spent Hou
_		Articulated	Rock Truck	Rey Contr	eras	Nick Vanderkooi	Jun 10, 2023 03:51:09 Af	M		
ork –	Work Order Description		Status		Туре	Date Created	Due Date	Date Completed	Day	/s Late
3044	Codes for low fan speeds		Closed, C	ompleted		Jun 09, 2023 08:51:07 PM		jun 10, 2023 03:41:37 AM		
1	ask Description	Asset		Assigned	l To	Completed By	Date Completed	Est	: Hours	Spent Hour
c	ooked at unit. No active fan codes. Fan was running. Put unit in to a regeneration to omfirm the fan would stay running. Fan worked. Sent unit to washbay to have the ads cleaned.	Articulated	Rock Truck	Thomas R	agan	Thomas Ragan	jun 10, 2023 03:41:37 AN	м	2.50	
- /ork	Work Order Description		Status		Туре	Date Created	Due Date	Date Completed	2,50	/s Late
	_ ·			ompleted			Due Date	•	D-0;	/S Late
3164	Overgreased Equipment		Cioseu, C	•	Corrective	Jun 11, 2023 05:39:58 PM		Jun 16, 2023 02:58:17 PM		
	Task Description	Asset Articulated	Darle Tarrel	Assigned Grease Ta			Date Completed		Hours	Spent Hour
-	overgreased Equipment	Articulated	ROCK Truck	Grease 1a	sk Force	Grease Task Force	Jun 16, 2023 02:58:11 PN	1 	0.00	0.0
_							- <del></del>		0.00	0.0
lork	Work Order Description		Status		Туре	Date Created	Due Date	Date Completed	Day	/s Late
3171	High DPF level shut down immediately	•	Closed, C	ompleted	Corrective	Jun 11, 2023 07:48:14 PM		Jun 27, 2023 04:34:56 PM		:
1	ask Description	Asset		Assigned	To	Completed By	Date Completed	Est	Hours	Spent Hour
r t	stored low air pressure code. Did a regen and a function test. Both passed. Check the ubber lines for the air system. They look good. Checked the turbo as et said. The urbo is contacting the housing. Unit will need a turbo baniel Reid. June 26/23	Articulated  Articulated		Thomas R	agan				3.00	4.0
r 1. V 1. V	ubber lines for the air system. They look good. Checked the turbo as et said. The urbo is contacting the housing. Unit will need a turbo baniel Reid June 26/23 Vent to unit on up stream laydown and foundtruck still mobile. Had forman get truck brought to shop. Removed turbo. Janiel Reid June 27/23 Vashed belly pan and wiped out inside of belly pan inspection door. Coolant leak was	Articulated Articulated	Rock Truck	Thomas R	agan				3.00	
r 1. V 1. V	ubber lines for the air system. They look good. Checked the turbo as et said. The urbo is contacting the housing. Unit will need a turbo baniel Reid June 26/23 Vent to unit on up stream laydown and foundtruck still mobile. Had forman get truck rought to shop. Removed turbo. baniel Reid June 27/23	Articulated Articulated	Rock Truck	Thomas R	agan				3.00 3.00	1.0
r 1. V 1. V	ubber lines for the air system. They look good. Checked the turbo as et said. The urbo is contacting the housing. Unit will need a turbo baniel Reid June 26/23 Vent to unit on up stream laydown and foundtruck still mobile. Had forman get truck brought to shop. Removed turbo. Janiel Reid June 27/23 Vashed belly pan and wiped out inside of belly pan inspection door. Coolant leak was	Articulated Articulated	Rock Truck	Thomas R	agan Type	Date Created	Due Date	Date Completed	3.00	1.0
r C V b C -	ubber lines for the air system. They look good. Checked the turbo as et said. The urbo is contacting the housing. Unit will need a turbo baniel Reid June 26/23 Vent to unit on up stream laydown and foundtruck still mobile. Had forman get truck brought to shop. Removed turbo. Daniel Reid June 27/23 Vashed belly pan and wiped out inside of belly pan inspection door. Coolant leak was esiduale from repair.	Articulated Articulated	Rock Truck Rock Truck				Due Date Jun 18, 2023 02:49:09 PM	Date Completed Jun 17, 2023 02:49:09 PM	3.00	1.0 <b>5.0</b>
r 0 2 2 5 4 6 7 7 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	ubber lines for the air system. They look good. Checked the turbo as et said. The urbo is contacting the housing. Unit will need a turbo baniel Reid June 26/23 Vent to unit on up stream laydown and foundtruck still mobile. Had forman get truck rought to shop. Removed turbo. Daniel Reid June 27/23 Vashed belly pan and wiped out inside of belly pan inspection door. Coolant leak was esiduale from repair.  Work Order Description 745C PM2 500 Service Hours  Fask Description	Articulated Articulated	Rock Truck Rock Truck Status Closed, C	ompleted Assigned	Type Preventive Planned	Jun 17, 2023	Jun 18, 2023	Jun 17, 2023 02:49:09 PM	3.00 Day	1.0 5.0
v v b c v v v v v v v v v v v v v v v v	ubber lines for the air system. They look good. Checked the turbo as et said. The urbo is contacting the housing. Unit will need a turbo laniel Reid June 26/23  Vent to unit on up stream laydown and foundtruck still mobile. Had forman get truck grought to shop. Removed turbo. Daniel Reid June 27/23  Vashed belly pan and wiped out inside of belly pan inspection door. Coolant leak was esiduale from repair.  Work Order Description  745C PM2 500 Service Hours	Articulated Articulated Articulated Asset Articulated	Rock Truck  Rock Truck  Status Closed, C	ompleted  Assigned PMtech	Type Preventive Planned	Jun 17, 2023 02:49:09 PM	Jun 18, 2023 02:49:09 PM	Jun 17, 2023 02:49:09 PM	3.00 Day 0	4.0 1.0 5.0 's Late Spent Hour
vork 3473	ubber lines for the air system. They look good. Checked the turbo as et said. The urbo is contacting the housing. Unit will need a turbo baniel Reid June 26/23 Vent to unit on up stream laydown and foundtruck still mobile. Had forman get truck rought to shop. Removed turbo. Daniel Reid June 27/23 Vashed belly pan and wiped out inside of belly pan inspection door. Coolant leak was esiduale from repair.  Work Order Description 745C PM2 500 Service Hours Fask Description Take Accumulator (Service) - Check Brake Pads - Check	Articulated  Articulated  Asset  Articulated  Articulated	Rock Truck  Status Closed, C  Rock Truck Rock Truck	ompleted  Assigned  PMtech  PMtech	Type Preventive Planned	Jun 17, 2023 02:49:09 PM	Jun 18, 2023 02:49:09 PM	Jun 17, 2023 02:49:09 PM	3.00 Day 0	1.0 5.0
vork 34.73	ubber lines for the air system. They look good. Checked the turbo as et said. The urbo is contacting the housing. Unit will need a turbo laniel Reid June 26/23  Vent to unit on up stream laydown and foundtruck still mobile. Had forman get truck grought to shop. Removed turbo. Daniel Reid June 27/23  Vashed belly pan and wiped out inside of belly pan inspection door. Coolant leak was esiduale from repair.  Work Order Description  745C PM2 500 Service Hours  Fask Description  Grake Accumulator (Service) - Check Brake Accumulator - Check Brake Pads - Check	Articulated  Articulated  Asset  Articulated  Articulated  Articulated  Articulated	Rock Truck  Rock Truck  Status Closed, C  Rock Truck Rock Truck Rock Truck	ompleted  Assigned PMtech PMtech PMtech PMtech	Type Preventive Planned	Jun 17, 2023 02:49:09 PM	Jun 18, 2023 02:49:09 PM	Jun 17, 2023 02:49:09 PM	3.00 Day 0	5.0 5.0
Vork 2473	ubber lines for the air system. They look good. Checked the turbo as et said. The urbo is contacting the housing. Unit will need a turbo baniel Reid June 26/23 Vent to unit on up stream laydown and foundtruck still mobile. Had forman get truck rought to shop. Removed turbo. Daniel Reid June 27/23 Vashed belly pan and wiped out inside of belly pan inspection door. Coolant leak was esiduale from repair.  Work Order Description 745C PM2 500 Service Hours Fask Description Brake Accumulator (Service) - Check Brake Pads - Check Braking System - Test Diff & Final Drive Oil Level - Check (note particulates on mag plug and indicate indings)	Articulated  Articulated  Asset  Articulated Articulated Articulated Articulated Articulated	Rock Truck  Status Closed, C  Rock Truck Rock Truck Rock Truck Rock Truck	Ompleted  Assigned  PMtech  PMtech  PMtech  PMtech  PMtech	Type Preventive Planned	Jun 17, 2023 02:49:09 PM	Jun 18, 2023 02:49:09 PM	Jun 17, 2023 02:49:09 PM	3.00 Day 0	1.0 5.0
Vork 19473	ubber lines for the air system. They look good. Checked the turbo as et said. The urbo is contacting the housing. Unit will need a turbo laniel Reid June 26/23. Went to unit on up stream laydown and foundtruck still mobile. Had forman get truck rought to shop. Removed turbo. Daniel Reid June 27/23. Washed belly pan and wiped out inside of belly pan inspection door. Coolant leak was esiduale from repair.  Work Order Description 745C PM2 500 Service Hours  Fask Description  Prake Accumulator (Service) - Check Brake Accumulator (Service) - Check Brake Accumulator - Test Diff & Final Drive Oil Level - Check (note particulates on mag plug and indicate indings).	Articulated  Articulated  Asset  Articulated  Articulated  Articulated  Articulated  Articulated  Articulated  Articulated	Rock Truck  Rock Truck  Status Closed, C  Rock Truck Rock Truck Rock Truck Rock Truck Rock Truck Rock Truck	Ompleted  Assigned PMtech PMtech PMtech PMtech PMtech PMtech	Type Preventive Planned	Jun 17, 2023 02:49:09 PM	Jun 18, 2023 02:49:09 PM	Jun 17, 2023 02:49:09 PM	3.00 Day 0	5.0 5.0
dork :3473	ubber lines for the air system. They look good. Checked the turbo as et said. The urbo is contacting the housing. Unit will need a turbo laniel Reid June 26/23. Went to unit on up stream laydown and foundtruck still mobile. Had forman get truck rought to shop. Removed turbo. Daniel Reid June 27/23. Washed belly pan and wiped out inside of belly pan inspection door. Coolant leak was esiduale from repair.  Work Order Description 745C PM2 500 Service Hours  Fask Description Prake Accumulator (Service) - Check Brake Accumulator (Service) - Check Braking System - Test Diff & Final Drive Oil Level - Check (note particulates on mag plug and indicate indings) Differential and Final Drive Oil Sample - Obtain Engine Air Filter Secondary Element (Outer) - Replace	Articulated  Articulated  Asset  Articulated Articulated Articulated Articulated Articulated Articulated Articulated	Rock Truck  Rock Truck  Status  Closed, C  Rock Truck	Ompleted  Assigned PMtech PMtech PMtech PMtech PMtech PMtech PMtech	Type Preventive Planned	Jun 17, 2023 02:49:09 PM	Jun 18, 2023 02:49:09 PM	Jun 17, 2023 02:49:09 PM	3.00 Day 0	1.0 5.0
Vork 23473	ubber lines for the air system. They look good. Checked the turbo as et said. The urbo is contacting the housing. Unit will need a turbo baniel Reid June 26/23 Vent to unit on up stream laydown and foundtruck still mobile. Had forman get truck rought to shop. Removed turbo. Daniel Reid June 27/23 Vashed belly pan and wiped out inside of belly pan inspection door. Coolant leak was esiduale from repair.  Work Order Description 745C PM2 500 Service Hours  Fask Description  Take Accumulator (Service) - Check Brake Pads - Check Braking System - Test Diff & Final Drive Oil Level - Check (note particulates on mag plug and indicate indings) Differential and Final Drive Oil Sample - Obtain Engine Air Fitter Secondary Element (Outer) - Replace	Articulated	Rock Truck  Rock Truck  Status Closed, C  Rock Truck	Ompleted  Assigned PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech	Type Preventive Planned	Jun 17, 2023 02:49:09 PM	Jun 18, 2023 02:49:09 PM	Jun 17, 2023 02:49:09 PM	3.00 Day 0	5.0 5.0
Vork (34.73)	ubber lines for the air system. They look good. Checked the turbo as et said. The urbo is contacting the housing. Unit will need a turbo baniel Reid June 26/23 Vent to unit on up stream laydown and foundtruck still mobile. Had forman get truck rought to shop. Removed turbo. Daniel Reid June 27/23 Vashed belly pan and wiped out inside of belly pan inspection door. Coolant leak was esiduale from repair.  Work Order Description 745C PM2 500 Service Hours  Fask Description Take Accumulator (Service) - Check Braking System - Test Diff & Final Drive Oil Level - Check (note particulates on mag plug and indicate indings)  Interential and Final Drive Oil Sample - Obtain Engine Air Filter Secondary Element (Outer) - Replace Engine Oil Filter Inspect (Cut Filter and Record Findings)	Articulated  Articulated  Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated	Rock Truck  Status Closed, C  Rock Truck	Ompleted  Assigned PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech	Type Preventive Planned	Jun 17, 2023 02:49:09 PM	Jun 18, 2023 02:49:09 PM	Jun 17, 2023 02:49:09 PM	3.00 Day 0	5.0 5.0
Vork (3473)	ubber lines for the air system. They look good. Checked the turbo as et said. The urbo is contacting the housing. Unit will need a turbo baniel Reid June 26/23 Vent to unit on up stream laydown and foundtruck still mobile. Had forman get truck rought to shop. Removed turbo. Daniel Reid June 27/23 Vashed belly pan and wiped out inside of belly pan inspection door. Coolant leak was esiduale from repair.  Work Order Description 745C PM2 500 Service Hours Fask Description Brake Accumulator (Service) - Check brake Pads - Check Diff & Final Drive Oil Level - Check (note particulates on mag plug and indicate indings) Differential and Final Drive Oil Sample - Obtain fingine Air Filter Secondary Element (Outer) - Replace ingine Oil and Filter - Change Engine Oil Filter Inspect (Cut Filter and Record Findings) Final Oil Filter Inspect (Cut Filter and Record Findings) Final Oil Filter Inspect (Cut Filter and Record Findings) Final Oil Filter Inspect (Cut Filter and Record Findings) Final Primary Filter - Replace	Articulated  Articulated  Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated	Rock Truck  Status Closed, C  Rock Truck	Assigned PMtech	Type Preventive Planned	Jun 17, 2023 02:49:09 PM	Jun 18, 2023 02:49:09 PM	Jun 17, 2023 02:49:09 PM	3.00 Day 0	1.0 5.0 /s Late
Vork 23473	ubber lines for the air system. They look good. Checked the turbo as et said. The urbo is contacting the housing. Unit will need a turbo laniel Reid June 26/23. Went to unit on up stream laydown and foundtruck still mobile. Had forman get truck rought to shop. Removed turbo. Daniel Reid June 27/23. Washed belly pan and wiped out inside of belly pan inspection door. Coolant leak was esiduale from repair.  Work Order Description 745C PM2 500 Service Hours  Fask Description Prake Accumulator (Service) - Check Brake Accumulator (Service) - Check Brake Accumulator (Service) - Check Brake Pads - Check	Articulated	Rock Truck  Status Closed, C  Rock Truck	Ompleted  Assigned  PMtech	Type Preventive Planned	Jun 17, 2023 02:49:09 PM	Jun 18, 2023 02:49:09 PM	Jun 17, 2023 02:49:09 PM	3.00 Day 0	1.0 5.0 /s Late
# # # # # # # # # # # # # # # # # # #	ubber lines for the air system. They look good. Checked the turbo as et said. The urbo is contacting the housing. Unit will need a turbo laniel Reid June 26/23. Went to unit on up stream laydown and foundtruck still mobile. Had forman get truck rought to shop. Removed turbo. Daniel Reid June 27/23. Washed belly pan and wiped out inside of belly pan inspection door. Coolant leak was esiduale from repair.  Work Order Description 745C PM2 500 Service Hours  Fask Description Fask Accumulator (Service) - Check Braking System - Test Diff & Final Drive Oil Level - Check (note particulates on mag plug and indicate indings) Differential and Final Drive Oil Sample - Obtain Engine Air Filter Secondary Element (Outer) - Replace Engine Oil Filter Inspect (Cut Filter and Record Findings) Filter System Primary Filter - Replace Filel System Description - Replace Filel System Brimary Filter - Replace Filel System Brocondary Filter - Replace	Articulated  Articulated  Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated	Rock Truck  Rock Truck  Status  Closed, C  Rock Truck	Assigned PMtech	Type Preventive Planned	Jun 17, 2023 02:49:09 PM	Jun 18, 2023 02:49:09 PM	Jun 17, 2023 02:49:09 PM	3.00 Day 0	5.0 5.0
/ork 3473	ubber lines for the air system. They look good. Checked the turbo as et said. The urbo is contacting the housing. Unit will need a turbo laniel Reid June 26/23. Went to unit on up stream laydown and foundtruck still mobile. Had forman get truck rought to shop. Removed turbo. Daniel Reid June 27/23. Washed belly pan and wiped out inside of belly pan inspection door. Coolant leak was esiduale from repair.  Work Order Description 745C PM2 500 Service Hours  Fask Description Prake Accumulator (Service) - Check Brake Accumulator (Service) - Check Brake Accumulator (Service) - Check Brake Pads - Check	Articulated	Rock Truck  Rock Truck  Status Closed, C  Rock Truck	Ompleted  Assigned PMtech	Type Preventive Planned	Jun 17, 2023 02:49:09 PM	Jun 18, 2023 02:49:09 PM	Jun 17, 2023 02:49:09 PM	3.00 Day 0	1.0 5.0 /s Late
Vork (3473)	ubber lines for the air system. They look good. Checked the turbo as et said. The urbo is contacting the housing. Unit will need a turbo baniel Reid June 26/23 Vent to unit on up stream laydown and foundtruck still mobile. Had forman get truck rought to shop. Removed turbo. Daniel Reid June 27/23 Vashed belly pan and wiped out inside of belly pan inspection door. Coolant leak was esiduale from repair.  Work Order Description 745C PM2 500 Service Hours  Fask Description Fask Pads - Check Frake Pads - Check Frake Pads - Check Frake Pads - Check Fraking System - Test Diff & Final Drive Oil Level - Check (note particulates on mag plug and indicate indings) Fingine Air Filter Secondary Element (Outer) - Replace Fingine Oil Filter Inspect (Cut Filter and Record Findings) Fingle Oil Filter Inspect (Cut Filter and Record Findings) Fingle System Secondary Filter - Replace Fingle System and Brake System Oil Sample - Obtain Fingle System and Brake System Oil Sample - Obtain Fingle System Secondary Filter - Replace	Articulated  Articulated  Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated Articulated	Rock Truck  Rock Truck  Status Closed, C  Rock Truck	Ompleted  Assigned PMtech	Type Preventive Planned	Jun 17, 2023 02:49:09 PM	Jun 18, 2023 02:49:09 PM	Jun 17, 2023 02:49:09 PM	3.00 Day 0	5.0 5.0

Transmission Oil Filter Replace
Transmission Oil Filter - Inspect (Cut Filter and Record Findings.)

Articulated Rock Truck
Articulated Rock Truck

PMtech PMtech

k	Work Order Description	Status	5 ·	Туре	Date Create	d Due Date	Date Completed	Day	s Late
174	745C PM2 500 Service Hours	Close	ed, Completed	Preventive Planned	- Jun 17, 20 02:49:55 F		jun 17, 2023 02:49:55 PM	0	
	Task Description	Asset	Assigne		Completed By	Date Completed		lours	Spent Ho
	Brake Accumulator (Service) - Check	Articulated Rock Ti	uck PMtech						-
	Brake Pads - Check	Articulated Rock Ti	uck PMtech						
	Braking System - Test	Articulated Rock Te							
1	Diff & Final Drive Oil Level - Check (note particulates on mag plug and indicate findings)	Articulated Rock Tr			PMtech	Jun 17, 2023 02:51:00 P		2.00	
	Differential and Final Drive Oil Sample - Obtain	Articulated Rock Tr			PMtech	Jun 17, 2023 02:51:00 P	М	2.00	
	Engine Air Filter Secondary Element (Outer) - Replace	Articulated Rock Tr			PMtech	Jun 17, 2023 02:51:00 P	M	2.00	
	Engine Oil and Filter - Change	Articulated Rock Tr			PMtech	jun 17, 2023 02:51:00 P	М	2.00	
	Engine Oil Filter Inspect (Cut Filter and Record Findings)	Articulated Rock Tr							
	Fuel System Primary Filter - Replace	Articulated Rock Tr	uck PMtech		PMtech	Jun 17, 2023 02:51:00 P	М	2.00	
	Fuel System Secondary Filter - Replace	Articulated Rock Tr	uck PMtech		PMtech	Jun 17, 2023 02:51:00 P	М	2.00	
	Hoist System and Brake System Oil Sample - Obtain	Articulated Rock Tr	uck PMtech		PMtech	Jun 17, 2023 02:51:00 P	M	2.00	
!	Secondary Steering - Test	Articulated Rock Tr	uck PMtech						
	Steering System Oil Sample - Obtain	Articulated Rock Tr	uck PMtech		PMtech	Jun 17, 2023 02:51:00 P	М	2.00	
•	Torque Converter and Transmission Oil Sample - Obtain	Articulated Rock Tr	uck PMtech		PMtech	Jun 17, 2023 02:51:00 P	М	2.00	
,	Transfer Gear Oil Sample - Obtain	Articulated Rock Tr	uck PMtech		PMtech	Jun 17, 2023 02:51:00 P	М	2.00	
•	Transmission Oil Filter Replace	Articulated Rock Tr	uck PMtech		PMtech	Jun 17, 2023 02:51:00 P		2.00	
	Transmission Oil Filter - Inspect (Cut Filter and Record Findings.)	Articulated Rock Tr	uck PMtech			,			
			· <b></b> -		<del></del>			22.00	
	Work Order Description	Status	ı	Туре	Date Created	Due Date	Date Completed	Day:	s Late
79	ARD fan speed low shut down safely.	Close	d, Completed	Corrective	Jun 28, 203 10:19:56 A		Jun 29, 2023 10:13:43 AM	-	
	Task Description	Asset	Assigned	То	Completed By	Date Completed	Est H	lours	Spent H
1	Check continutly of pin A of plug to pin 1 of J1 of engine ECM. Found good (0.9 ohms). Check again pin B of plug to pin 31 of J1 plug at ECM. Continuity but high resistance. Inspected harness as much as I feasibly could. Found a previous repair that appeared to be good. Harness runs through hood assembly so not easily accessable. Run an overlander wire as closely tied to the harness as I could. Run an ARD ignition test, no faults. Run an aftertreatment functional test, no faults. Machine does also have a secondary speed sensor fault. Using ET the ECM is seeing a	Articulated Rock Tr	uck Silas Ange	ll - Wajax	Silas Angell - Wajax	jun 29, 2023 12:30:00 Pl	м		
1	good RPM signal from sensor. Checked resistance of sensor, found within range (1,100 ohms). No further troubleshooting as called to another job.								. 13
1	ohms). No further troubleshooting as called to another job.			Tuna	Date Ct	Due Dete	D=4= C====l=4= -		
k	ohms). No further troubleshooting as called to another job.  Work Order Description	Status		Туре	Date Created		Date Completed	Days	s Late
k 70	Work Order Description ARD fan speed code and E1190(3), TRUCK IS LOADED !!!!	Status Close	d, Completed	Corrective	Jun 29, 202 09:12:19 P	23 M	Date Completed Jun 30, 2023 05:27:23 AM	Day	
70	ohms). No further troubleshooting as called to another job.  Work Order Description  ARD fan speed code and E1190(3), TRUCK IS LOADED !!!!  Task Description	Status Close	d, Completed  Assigned	Corrective	Jun 29, 202 09:12:19 P Completed By	23 M Date Completed	Jun 30, 2023 05:27:23 AM Est H	lours	
70	work Order Description ARD fan speed code and E1190(3), TRUCK IS LOADED !!!!  Task Description june 30 2023 tyler penkoff followed wired under hood and located bad ground, repaired wiring and preformed	Status Close	d, Completed  Assigned	Corrective	Jun 29, 202 09:12:19 P	23 M	Jun 30, 2023 05:27:23 AM Est H		
70	work Order Description ARD fan speed code and E1190(3). TRUCK IS LOADED !!!!  Task Description june 30 2023 tyler penkoff	Status Close	d, Completed  Assigned	Corrective	Jun 29, 202 09:12:19 P Completed By	23 M Date Completed	Jun 30, 2023 05:27:23 AM Est H	lours	Spent Ho

	stop a regen. Regen unit. Once completed i did a function test to see if any problems come up. Nothing popped up.			_				3.6	
i	Task Description  Pulled the codes. Only active code was for the soot load. No stored codes that would	Asset Articulated	Rock Truck	Assigned Thomas R		Completed By Thomas Ragan	Date Completed Jul 09, 2023 09:28:37 AM	Est Hou	
4602	•		Closed, Co	•		Jul 09, 2023 03:42:51 AM		Jul 09, 2023 09:28:37 AM	
ork	Work Order Description		Status	ادعفماممم	Туре	Date Created	Due Date	Date Completed	Days Late
	***************************************					nvr			
	shut unit down to reset code now cleared"								
1	boost unit run unit check charging system good								
	unit does not start find lights left on								
i	in previous experience this code is caused from low batteries attempt to start unit								
	"locate unit find unit has 1404-11 code	Articulated	Rock Truck	Kris Willia	ms - Finning	Kris Williams - Finning	jul 07, 2023 01:45:21 PM		•
	Task Description	Asset		Assigned	і То	11:33:11 AM Completed By	Date Completed	01:45:21 PM Est Hou	rs Spent Ho
4521	Trans sol fault		Closed, Co	mpleted	Corrective	Jul 07, 2023		Jul 07, 2023	
ork .	Work Order Description		Status		Туре	Date Created	Due Date	Date Completed	Days Late
	soot load drops from 110% to 0%"				***	-			
1	"locate unit warm unit up to temp perform regen	Articulated	Rock Truck	Kris Willia	ıms - Finning	Kris Williams - Finning	Jul 05, 2023 03:02:43 PM		
_	Task Description	Asset		Assigne		Completed By	Date Completed	Est Hou	
4398	Truck won't go into manual regen. Regen icon and high exhau icon illuminated on dash.	ust temp	Closed, Co	mpleted	Corrective	Jul 05, 2023 07:26:05 AM		Jul 05, 2023 03:02:43 PM	
ork	Work Order Description		Status		Туре	Date Created	Due Date	Date Completed	Days Late
ı i	repaired the broken plastic, installed fan cover with three new bolts, reused the 1 remaining bolt,								
ī	01-07-23 Andy Boettger removed plastic fan cover	Articulated	l Rock Truck	Andy Boe		Daniel Reid	Jul 01, 2023 04:20:00 AM		
	Task Description	Asset		Assigne	d To	01:52:33 AM Completed By	Date Completed	04:20:00 AM	rs Spent Ho
4225			Closed, Co	mpleted	.,,,,	Jul 01, 2023		Jul 01, 2023	Days Late
ork -	Work Order Description		Status		Туре	Date Created	Due Date	Date Completed	Days Late
	30-06-23 ANdy Boettger boosted truck once another wiggle showed up,	Articulated	Rock Truck	Andy Bos	ettger	Andy Boettger	Jun 30, 2023 08:00:00 PM	n	
	barely turns over. Task Description	Asset		Assigne		Completed By	Date Completed	08:11:00 PM Est Hou	

Status

Туре

**Date Created** 

**Due Date** 

**Date Completed** 

Days Late

Work Order Description

74869	Truck is repeatedly kicking into regen all day long.		Closed, Co	mpleted	Corrective	Jul 13, 2023 01:14:14 PM	•	Jul 14, 2023 05:18:27 PM	÷
7	ask Description	Asset		Assigned	l To	Completed By	Date Completed	Est Hour	s Spent Hour
-	OC forgot to get clean about 3 months ago.	Articulate	I Rock Truck	Kris Willia	ms - Finning	Menno Buhter	Jul 14, 2023 05:18:27 PM		
Work	Work Order Description		Status		Туре	Date Created	Due Date	Date Completed	Days Late
75121	Upper right mirror loose		Closed, Co	mpleted	Corrective	Jul 18, 2023 01:42:28 PM		jul 18, 2023 07:34:24 PM	**
1	ask Description	Asset		Assigned	l To	Completed By	Date Completed	Est Hour	s Spent Hour
_		Articulated	I Rock Truck	Ken Conno	on	Nick Vanderkooi	Jul 18, 2023 07:34:24 PM		
– Work	Work Order Description		Status		Туре	Date Created	Due Date	Date Completed	Days Late
75247	DPF level high		Closed, Co	mpleted	Corrective	Jul 21, 2023 05:12:33 AM		Jul 21, 2023 09:45:52 AM	
1	ask Description	Asset		Assigned	То	Completed By	Date Completed	Est Hour	s Spent Hour
fe c p	1-07-23 Andy Boettger ound truck on wedge laydown, onfirmed truck reading high dpf, erformed manual regen, egen complete	Articulated	l Rock Truck	Andy Boet	tger	Andy Boettger	Jul 21, 2023 09:00:00 AM		2.5
_									2.50
Work	Work Order Description		Status		Туре	Date Created	Due Date	Date Completed	Days Late
75278	Oil level sensor replaced. Oil change.		Closed, Co	mpleted	Corrective	Jul 21, 2023 07:30:31 PM		Jul 22, 2023 02:21:36 PM	
1	ask Description	Asset		Assigned	To		Date Completed	Est Hours	s Spent Hour
1 fi a	ne rear timing gear gasket and leaking down. {possible p/n - 155-9524 seal integral, 66-9144 gasket}. Also replaced an oring on a hose and tightened up hydraulic oil lter. Low level engine oil flashed up, engine oil overfull required drained down some, nd checked with ET. truck took to worlshop, drained down oil removed under engine uard replaced level sensor, rechecked level refitted truck code cleared level correct.								
t 1 fi a	66-9144 gasket). Also replaced an oring on a hose and tightened up hydraulic oil lter. Low level engine oil flashed up, engine oil overfull required drained down some, nd checked with ET. truck took to worlshop, drained down oil removed under engine								7.0
ti 1 fi a 9	66-9144 gasket). Also replaced an oring on a hose and tightened up hydraulic oil lter. Low level engine oil flashed up, engine oil overfull required drained down some, nd checked with ET. truck took to worlshop, drained down oil removed under engine		Status		Type	Date Created	Due Date	Date Completed	7.0 Days Late
ti 1 fi a 9 	66-9144 gasket). Also replaced an oring on a hose and tightened up hydraulic oil lter. Low level engine oil flashed up, engine oil overfull required drained down som nd checked with ET. truck took to worlshop, drained down oil removed under engine uard replaced level sensor, rechecked level refitted truck code cleared level correct.		Status Closed, Con	mpleted	Type Corrective	jul 24, 2023		Jul 24, 2023	
ti 1 6 9 - Work 75382	66-9144 gasket). Also replaced an oring on a hose and tightened up hydraulic oil lter. Low level engine oil flashed up, engine oil overfull required drained down som nd checked with ET. truck took to worlshop, drained down oil removed under engine uard replaced level sensor, rechecked level refitted truck code cleared level correct.  Work Order Description			mpleted Assigned	Corrective	Jul 24, 2023 06:00:12 AM			Days Late
### 1	66-9144 gasket). Also replaced an oring on a hose and tightened up hydraulic oil lter. Low level engine oil flashed up, engine oil overfull required drained down somend checked with ET. truck took to worlshop, drained down oil removed under engine uard replaced level sensor, rechecked level refitted truck code cleared level correct.  Work Order Description  Coolant leak	Asset		Assigned	Corrective To	Jul 24, 2023 06:00:12 AM	Date Completed	Jul 24, 2023 09:52:15 AM Est Hour	Days Late  S Spent Hours 5.0
# 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	66-9144 gasket). Also replaced an oring on a hose and tightened up hydraulic oil lter. Low level engine oil flashed up, engine oil overfull required drained down some, nd checked with ET. truck took to worlshop, drained down oil removed under engine uard replaced level sensor, rechecked level refitted truck code cleared level correct.  Work Order Description  Coolant leak  Task Description  coolant leak, Line from the NRS cooler to ARD system failed. Removed and replaced ne, refilled coolant, tested.	Asset	Closed, Col	Assigned	Corrective To Ilemiss - Wajax -	Jul 24, 2023 06:00:12 AM Completed By Dane Middlemiss - Wajax -	<b>Date Completed</b> Jul 24, 2023 09:52:15 AM	Jul 24, 2023 09:52:15 AM Est Houn	S Spent Hours 5.00
# 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	66-9144 gasket). Also replaced an oring on a hose and tightened up hydraulic oil liter. Low level engine oil flashed up, engine oil overfull required drained down som nd checked with ET. truck took to worlshop, drained down oil removed under engine uard replaced level sensor, rechecked level refitted truck code cleared level correct.  Work Order Description  Coolant leak  ask Description  coolant leak, Line from the NRS cooler to ARD system failed. Removed and replaced ne, refilled coolant, tested.	Asset	Closed, Col	Assigned Dane Midd	To llemiss - Wajax -	Jul 24, 2023 06:00:12 AM Completed By Dane Middlemiss - Wajax -	Date Completed	Jul 24, 2023 09:52:15 AM Est Houn	Days Late  S Spent Hours 5.0
Work 75382	66-9144 gasket). Also replaced an oring on a hose and tightened up hydraulic oil liter. Low level engine oil flashed up, engine oil overfull required drained down som nd checked with ET. truck took to worlshop, drained down oil removed under engine uard replaced level sensor, rechecked level refitted truck code cleared level correct.  Work Order Description  Coolant leak  Task Description  oolant leak, Line from the NRS cooler to ARD system failed. Removed and replaced ne, refilled coolant, tested.  Work Order Description  Overgreased Equipment	<b>Asset</b> Articulated	Closed, Col	Assigned Dane Midd	To  Ilemiss - Wajax -  Type  Corrective	Jul 24, 2023 06:00:12 AM Completed By Dane Middlemiss - Wajax - Date Created Jul 24, 2023 03:42:02 PM	Date Completed Jul 24, 2023 09:52:15 AM  Due Date	Jul 24, 2023 09:52:15 AM Est Houn Date Completed Jul 24, 2023 04:41:12 PM	S Spent Hours 5.00 5.00 Days Late
Work 75402	66-9144 gasket}. Also replaced an oring on a hose and tightened up hydraulic oil lter. Low level engine oil flashed up, engine oil overfull required drained down some, nd checked with ET. truck took to worlshop, drained down oil removed under engine uard replaced level sensor, rechecked level refitted truck code cleared level correct.  Work Order Description  Coolant leak  Task Description  coolant leak, Line from the NRS cooler to ARD system failed. Removed and replaced ne, refilled coolant, tested.  Work Order Description  Overgreased Equipment  Task Description	<b>Asset</b> Articulated	Closed, Col Rock Truck  Status Closed, Col	Assigned Dane Midd  mpleted  Assigned	To  Ilemiss - Wajax -  Type  Corrective  To	Jul 24, 2023 06:00:12 AM Completed By Dane Middlemiss - Wajax - Date Created Jul 24, 2023 03:42:02 PM Completed By	Date Completed Jul 24, 2023 09:52:15 AM  Due Date  Date Completed	Jul 24, 2023 09:52:15 AM Est Hound Date Completed Jul 24, 2023 04:41:12 PM Est Hound	S Spent Hourn 5.0  5.0  Days Late
Work 75402	66-9144 gasket). Also replaced an oring on a hose and tightened up hydraulic oil liter. Low level engine oil flashed up, engine oil overfull required drained down som nd checked with ET. truck took to worlshop, drained down oil removed under engine uard replaced level sensor, rechecked level refitted truck code cleared level correct.  Work Order Description  Coolant leak  Task Description  oolant leak, Line from the NRS cooler to ARD system failed. Removed and replaced ne, refilled coolant, tested.  Work Order Description  Overgreased Equipment	<b>Asset</b> Articulated	Closed, Col	Assigned Dane Midd	To  Ilemiss - Wajax -  Type  Corrective  To	Jul 24, 2023 06:00:12 AM Completed By Dane Middlemiss - Wajax - Date Created Jul 24, 2023 03:42:02 PM Completed By	Date Completed Jul 24, 2023 09:52:15 AM  Due Date	Jul 24, 2023 09:52:15 AM Est Hound Date Completed Jul 24, 2023 04:41:12 PM Est Hound	S Spent Hours 5.00  5.00  Days Late
Work 75402	66-9144 gasket}. Also replaced an oring on a hose and tightened up hydraulic oil lter. Low level engine oil flashed up, engine oil overfull required drained down some, nd checked with ET. truck took to worlshop, drained down oil removed under engine uard replaced level sensor, rechecked level refitted truck code cleared level correct.  Work Order Description  Coolant leak  Task Description  coolant leak, Line from the NRS cooler to ARD system failed. Removed and replaced ne, refilled coolant, tested.  Work Order Description  Overgreased Equipment  Task Description	<b>Asset</b> Articulated	Closed, Col Rock Truck  Status Closed, Col	Assigned Dane Midd  mpleted  Assigned	To  Ilemiss - Wajax -  Type  Corrective  To	Jul 24, 2023 06:00:12 AM Completed By Dane Middlemiss - Wajax - Date Created Jul 24, 2023 03:42:02 PM Completed By	Date Completed Jul 24, 2023 09:52:15 AM  Due Date  Date Completed	Jul 24, 2023 09:52:15 AM Est Hound Date Completed Jul 24, 2023 04:41:12 PM Est Hound	S Spent Hours 5.00 5.00 Days Late
Work 75402	66-9144 gasket}. Also replaced an oring on a hose and tightened up hydraulic oil lter. Low level engine oil flashed up, engine oil overfull required drained down some, nd checked with ET. truck took to worlshop, drained down oil removed under engine uard replaced level sensor, rechecked level refitted truck code cleared level correct.  Work Order Description  Coolant leak  Task Description  oolant leak, Line from the NRS cooler to ARD system failed. Removed and replaced ne, refilled coolant, tested.  Work Order Description  Overgreased Equipment  Task Description  Overgreased Equipment	<b>Asset</b> Articulated	Closed, Col Rock Truck  Status Closed, Col Rock Truck	Assigned Dane Midd  mpleted  Assigned  Grease Ta:	To  Ilemiss - Wajax -  Type Corrective To sk Force	Jul 24, 2023 06:00:12 AM Completed By Dane Middlemiss - Wajax  Date Created Jul 24, 2023 03:42:02 PM Completed By Grease Task Force  Date Created Jul 25, 2023	Date Completed Jul 24, 2023 09:52:15 AM  Due Date  Date Completed Jul 24, 2023 04:42:59 PM  Due Date	Jul 24, 2023 09:52:15 AM	S Spent Hours 5.00  5.00  Days Late  S Spent Hours
Work 75382  Work 75402  Work 75447	66-9144 gasket}. Also replaced an oring on a hose and tightened up hydraulic oil lter. Low level engine oil flashed up, engine oil overfull required drained down some, nd checked with ET. truck took to worlshop, drained down oil removed under engine uard replaced level sensor, rechecked level refitted truck code cleared level correct.  Work Order Description  Coolant leak  Task Description  oolant leak, Line from the NRS cooler to ARD system failed. Removed and replaced ne, refilled coolant, tested.  Work Order Description  Overgreased Equipment  Task Description  Overgreased Equipment  Work Order Description	<b>Asset</b> Articulated	Rock Truck  Status Closed, Col Rock Truck	Assigned Dane Midd  mpleted  Assigned  Grease Ta:	To  Ilemiss - Wajax -  Type Corrective To sk Force  Type	Jul 24, 2023 06:00:12 AM Completed By Dane Middlemiss - Wajax  Date Created Jul 24, 2023 03:42:02 PM Completed By Grease Task Force  Date Created Jul 25, 2023 01:32:47 PM	Date Completed Jul 24, 2023 09:52:15 AM  Due Date  Date Completed Jul 24, 2023 04:42:59 PM  Due Date	Jul 24, 2023 09:52:15 AM Est Hound Date Completed Jul 24, 2023 04:41:12 PM Est Hound	S Spent Hours 5.00  Days Late S Spent Hours Days Late
Work 75382  Work 75402	66-9144 gasket). Also replaced an oring on a hose and tightened up hydraulic oil liter. Low level engine oil flashed up, engine oil overfull required drained down som di checked with ET. truck took to worlshop, drained down oil removed under engine uard replaced level sensor, rechecked level refitted truck code cleared level correct.  Work Order Description  Coolant leak  'ask Description  colant leak, Line from the NRS cooler to ARD system failed. Removed and replaced ne, refilled coolant, tested.  Work Order Description  Overgreased Equipment  'ask Description  Overgreased Equipment  Work Order Description  Truck won't regen. Truck is loaded	Asset Articulated Asset Articulated	Rock Truck  Status Closed, Col Rock Truck	Assigned Dane Midd  mpleted  Assigned Grease Ta:	To  Ilemiss - Wajax -  Type Corrective To sk Force  Type	Jul 24, 2023 06:00:12 AM Completed By Dane Middlemiss - Wajax  Date Created Jul 24, 2023 03:42:02 PM Completed By Grease Task Force  Date Created Jul 25, 2023 01:32:47 PM Completed By Completed By	Date Completed Jul 24, 2023 09:52:15 AM  Due Date  Date Completed Jul 24, 2023 04:42:59 PM  Due Date	Date Completed Jul 24, 2023 09:52:15 AM Est Hourn  Date Completed Jul 24, 2023 04:41:12 PM Est Hourn  Date Completed Jul 25, 2023 08:49:03 PM	S Spent Hours 5.00 Days Late S Spent Hours Days Late
Work 75382  Work 75402  Work 75447	66-9144 gasket). Also replaced an oring on a hose and tightened up hydraulic oil liter. Low level engine oil flashed up, engine oil overfull required drained down som di checked with ET. truck took to worlshop, drained down oil removed under engine uard replaced level sensor, rechecked level refitted truck code cleared level correct.  Work Order Description  Coolant leak  'ask Description  colant leak, Line from the NRS cooler to ARD system failed. Removed and replaced ne, refilled coolant, tested.  Work Order Description  Overgreased Equipment  'ask Description  Overgreased Equipment  Work Order Description  Truck won't regen. Truck is loaded	Asset Articulated Asset Articulated	Rock Truck  Status Closed, Col Rock Truck  Status Closed, Col	Assigned Dane Midd  mpleted  Assigned Grease Ta:	To  Ilemiss - Wajax -  Type Corrective To sk Force  Type	Jul 24, 2023 06:00:12 AM Completed By Dane Middlemiss - Wajax  Date Created Jul 24, 2023 03:42:02 PM Completed By Grease Task Force  Date Created Jul 25, 2023 01:32:47 PM Completed By Completed By	Date Completed Jul 24, 2023 09:52:15 AM  Due Date  Date Completed Jul 24, 2023 04:42:59 PM  Due Date  Date Completed	Date Completed Jul 24, 2023 09:52:15 AM Est Hourn  Date Completed Jul 24, 2023 04:41:12 PM Est Hourn  Date Completed Jul 25, 2023 08:49:03 PM	S Spent Hours 5.00 Days Late S Spent Hours Days Late

Tl-Daviation			11:12:43 PM	-	56 AM		
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hou		t Ho
Burn down and brought to shop	Articulated Rock Truck	Nick Misener				.83	
27 July 2023-Diego Z -removed emissions package	Articulated Rock Truck	Diego Zamora	Diego Zamora	Jul 28, 2023 05:18:00 AM	1		9
-removed emissions package -found multiple leaks, marked with red tape							
pulled right starter, both needed to be resealed, pump o-ring on timing cover, hose							
on transmission							
uly 28/23 Kristian Z /DS	Articulated Rock Truck	Kristian Zimmer	Kristian Zimmer	Jul 28, 2023 05:17:00 PM			11
emoved the Aftertreatment module							
Removed the Combustion exhaust							
Removed the DPF							
-Started to create a parts list, but been pulled to another job working on 13-85-504R swapping GPS with Nick Wik							
July 29/23 Kristian Z /DS	Articulated Rock Truck	Kristian Zimmer	Kristian Zimmer	Jul 29, 2023 05:23:00 PM	I		6
Resealed pass side starter with new o rings and gasket. Placed starter back on the				,			·
pass side and Tighten bolts with loctite and placed gasket maker to get a good seal							
Removed drivers side starter and washed it Replacing O rings and rubber balls							
Note:							
-Cone housing needs to be bolted on							
-Cone nousing needs to be boiled on -The rest of the starter needs to be installed. Old gasket is still sitting on the starter							
mount on the engine. Needs to be removed and cleaned.							
Few more areas marked with red tape that need to be resealed							
-Mount starter and the rest of the emissions exhaust assembly 29 July 2023-Diego Z	Articulated Rock Truck	Diego Zamora	Diogo Zamosa	U-1-20, 2023 DE-17-00 AM	•		
re-sealed and installed left starter	Articolated Nock Frack	Diego Zamora	Diego Zamora	Jul 30, 2023 05:17:00 AM			5
-started re-assembling emissions package							
uly 30/23 Kristian Z /DS	Articulated Rock Truck	Kristian Zimmer	Kristian Zimmer				1:
-Assembling the Emissions Exhaust module, with new inlet and outlet Nox sensors and							
Aftertreatment burner spark module							
-Attached the module on the unit.							
-Clamped on the bottom exhaust and top exhaust -Assembled the rest of the wiring and tubing on the unit							
Note:							
-Where the red tapes are indication for leaks, must repair them							
-Install Side panel and bottom belly pan							
-Check all fluids, grease and lights -Do a Test run and a burn on the unit			-				
-DO & restricting the a position the drift							
	Articulated Rock Truck	Diego Zamora	Diego Zamora	Jul 31, 2023 02:26:00 AM	1		8
-washed unit		-	÷				-
-performed ash service and dpf regen -got soot level down to 1 percent							
spent hours diagnosing engine oil leaks, and conclude timing cover leaking, which							
means oil pan , front main will also be resealed							
-gave parts number to supervision							
cleaned up July 31/23 Kristian Z /DS	Articulated Rock Truck	Kristian Zimmer	Kristian Zimmer	Jul 31, 2023 12:04:00 PM			3
		STATUTE GUIDILE	-wisden Zimiliti	JOI 31, 2023 12:04:00 PM			3
-Assembled the rest of the panels back on -Checked all fluids, lights and A/C. All are working							
Rear wiper wasn't working due to a blown fuse. Changed the fuse with a new one							
			<del></del>	-	2.1	83	54
Work Order Description	Status	Туре	Date Created	Due Date	Date Completed	Days Late	
Shifter knob is super loose.	Closed, Co	ompleted Corrective	Aug 03, 202	3	Aug 04, 2023		
		•	10:17:24 PM		02:19:28 AM		
Task Description 04-08-23 Andy Boettger	Asset	Assigned To	Completed By	Date Completed	Est Hou	rs Spent I	
	Articulated Rock Truck	Andy Boettger	Menno Buhler	Aug 04, 2023 02:19:28 A	М		-1
found the wrong screw installed in knob, removed and installed proper screw,							

rk	Work Order Description	Status		Туре		Date Created	Due Date	Date Completed	Days	Late
011	745C PM2 500 Service Hours	Closed, C	ompleted	Preventive - Planned		Aug 04, 2023 12:54:15 PM		Aug 04, 2023	0	
т	ask Description	Asset	Assigned		Complete		Date Completed	12:54:15 PM Est Ho	Lire	Spent H
_	rake Accumulator (Service) - Check	Articulated Rock Truck	PMtech			,			u. 3	Spentin
В	rake Pads - Check	Articulated Rock Truck	PMtech							
В	raking System - Test	Articulated Rock Truck	PMtech							
D	iff & Final Drive Oil Level - Check (note particulates on mag plug and indicate ndings)	Articulated Rock Truck	PMtech							
	ifferential and Final Drive Oil Sample - Obtain	Articulated Rock Truck	PMtech							
Eı	ngine Air Filter Secondary Element (Outer) - Replace	Articulated Rock Truck	PMtech							
Ei	ngine Oil and Filter - Change	Articulated Rock Truck	PMtech							
	ngine Oil Filter Inspect (Cut Filter and Record Findings)	Articulated Rock Truck	PMtech							
F	el System Primary Filter - Replace	Articulated Rock Truck	PMtech							
Ft	uel System Secondary Filter - Replace	Articulated Rock Truck	PMtech							
Н	oist System and Brake System Oil Sample - Obtain	Articulated Rock Truck	PMtech							
S	econdary Steering - Test	Articulated Rock Truck	PMtech							
St	eering System Oil Sample - Obtain	Articulated Rock Truck	PMtech							
Te	orque Converter and Transmission Oil Sample - Obtain	Articulated Rock Truck	PMtech							
Tı	ransfer Gear Oil Sample - Obtain	Articulated Rock Truck	PMtech							
Ťı	ransmission Oil Filter Replace	Articulated Rock Truck	PMtech							
Ti	ransmission Oil Filter - Inspect (Cut Filter and Record Findings.)	Articulated Rock Truck	PMtech							
_										
k	Work Order Description	Status		Туре		Date Created	Due Date	Date Completed	Days	Late
12	745C PM2 500 Service Hours	Closed, C	ompleted	Preventive - Planned		Aug 04, 2023 12:54:19 PM	Aug 05, 2023 12:54:19 PM	Aug 04, 2023 12:54:19 PM	0	
	ask Description	Asset	Assigned	l To	Complete	ed By	Date Completed	Est Ho	urs	Spent H
	rake Accumulator (Service) - Check	Articulated Rock Truck	PMtech							
В	rake Pads - Check	Articulated Rock Truck	PMtech							
	raking System - Test	Articulated Rock Truck	PMtech							
fir	iff & Final Drive Oil Level - Check (note particulates on mag plug and indicate indings)	Articulated Rock Truck	PMtech		PMtech		Aug 04, 2023 12:56:00 P		.00	
	fferential and Final Drive Oil Sample - Obtain	Articulated Rock Truck	PMtech		PMtech		Aug 04, 2023 12:56:00 P		.00	
	ngine Air Filter Secondary Element (Outer) - Replace	Articulated Rock Truck	PMtech		PMtech		Aug 04, 2023 12:56:00 P	_	.00	
	ngine Oil and Filter - Change	Articulated Rock Truck	PMtech		PMtech		Aug 04, 2023 12:56:00 P	M 2	.00	
	ngine Oil Filter Inspect (Cut Filter and Record Findings)	Articulated Rock Truck	PMtech							
	uel System Primary Filter - Replace	Articulated Rock Truck	PMtech		PMtech		Aug 04, 2023 12:56:00 P	M 2	.00	
	uel System Secondary Filter - Replace	Articulated Rock Truck	PMtech		PMtech		Aug 04, 2023 12:56:00 P	M 2	.00	
	oist System and Brake System Oil Sample - Obtain	Articulated Rock Truck	PMtech		PMtech		Aug 04, 2023 12:56:00 P	M 2	.00	
	econdary Steering - Test	Articulated Rock Truck	PMtech							
	teering System Oil Sample - Obtain	Articulated Rock Truck	PMtech		PMtech		Aug 04, 2023 12:56:00 P	M 2	.00.	
To	orque Converter and Transmission Oll Sample - Obtain	Articulated Rock Truck	PMtech		PMtech		Aug 04, 2023 12:56:00 P	M 2	.00	
	ransfer Gear Oil Sample - Obtain	Articulated Rock Truck	PMtech		PMtech	,	Aug 04, 2023 12:56:00 P	M 2	.00.	
Ti	ansmission Oll Filter Replace	Articulated Rock Truck	PMtech		PMtech		Aug 04, 2023 12:56:00 P	M 2	.00	
Tı	ransmission Oil Filter - Inspect (Cut Filter and Record Findings.)	Articulated Rock Truck	PMtech							
_	"							22	.00	
k	Work Order Description	Status		Туре		Date Created	Due Date	Date Completed	Days	Late
)14	745C PM3 1000 Service Hours	Closed, Co	ompleted	Preventive - Planned		Aug 04, 2023 12:58:28 PM	Aug 05, 2023 12:58:28 PM	Aug 04, 2023 12:59:52 PM	0	
_	ask Description	Asset	Assigned		Complete		Date Completed	Est Ho	ırs	Spent H
В	attery or Battery Cable - Inspect/Replace	Articulated Rock Truck	PMtech							
В	rake Oil Filter - Replace	Articulated Rock Truck	PMtech	!	PMtech		Aug 04, 2023 12:59:00 P	M 1	.00	
В	rake Tank Strainer - Clean/Inspect/Replace	Articulated Rock Truck	PMtech		PMtech		Aug 04, 2023 12:59:00 P		.00	
_	ab Recirc Air Filter Element (Inner) - Replace	Articulated Rock Truck	PMtech		PMtech		Aug 04, 2023 12:59:00 P		.00	
Ç	· · · · · · · · · · · · · · · · · · ·						•			
	uel Tank Cap Filter - Replace	Articulated Rock Truck	PMtech	1	PMtech		Aug 04, 2023 12:59:00 P	M 1	.00	

	lydraulic System Oil Filter Inspect (Cut Filter and Record Findings)	Articulated Ro		PMtech							
	lydraulic Tank Strainer - Clean/Inspect/Replace	Articulated Ro		PMtech		PMtech		Aug 04, 2023 12:59:00 Pl	М	1.00	
	Osciliating Hitch - Adjust tollover Protective Structure (ROPS) - Inspect	Articulated Ro Articulated Ro		PMtech PMtech							
	orque Converter, Transmission, and Transfer Gear Oil - Change	Articulated Ro		PMtech		PMtech		Aug 04, 2023 12:59:00 PI	м	1.00	
	ransmission Clutch Calibrations - Complete	Articulated Ro		PMtech		rivitecti		Aug 04, 2023 12.35.00 Fi	MI	1.00	
	ransmission and Transfer Gear Breather - Replace	Articulated Ro		PMtech		PMtech		Aug 04, 2023 12:59:00 Pf	ч	1.00	
-										8.00	
Work	Work Order Description	St	tatus	•	Туре		Date Created	Due Date	Date Completed	Day	/s Late
76295	Brake fault	С	losed, Com	pleted	-		Aug 10, 2023 11:17:19 AM	3	Aug 11, 2023 01:24:38 PM		
-	Fask Description	Asset		Assigned	To	Complet		Date Completed		Hours	Spent Hours
_		Articulated Ro	ick Truck	Pacesetter		Justin Kun	g	Aug 11, 2023 01:24:38 Pf	ч		
Work	Work Order Description		tatus		T		Date Created	Due Dete	Data Completed		
	•			nlotod	Туре				Date Completed	Day	/s Late
76621	Ard 1 Combustion loss (double)	C	losed, Com	pietea			Aug 17, 2023		Aug 17, 2023		
	Task Description	Asset		Assigned	To	Complete	10:13:04 AM	Date Completed	01:51:50 PM	Hours	S Harre
-	ask Description	Articulated Ro		Assigned	10	Nick Vand		Aug 17, 2023 01:51:50 PM		Hours	Spent Hours
-		Articulated No.	- TIBER			NICK VAIIG		Aug 17, 2023 01.31.30 Fr	"		<del></del>
Work	Work Order Description	St	tatus		Туре		Date Created	Due Date	Date Completed	Day	rs Late
76631	ARD combustion loss.	C	losed, Com				Aug 17, 2023		Aug 18, 2023		
				p			01:49:41 PM		06:38:10 AM		
	Dpf level high shut down immediately. Truck shut off on drive	er.					02170112111		00.50120 74.4		
•	Task Description	Asset		Assigned '	To	Complete	ed By	Date Completed	Est	Hours	Spent Hours
-	CHRIS WISEMAN AUG 18/2023 CHECKED CODES NO CODES CHECKED SOOT LEVEL ONLY 14 PERCENT. SOMEONE ALREADY REGENED. LOW L/S FRONT TIRE TOOK TO KAL TIRE	Articulated Ro	ck Truck								1.00
											1 00
Work	Work Order Description	St	atus		Type		Date Created	Due Date	Date Completed	Day	1.00
	Work Order Description Degreasing				Type Preventive		Date Created		Date Completed		's Late
<b>Work</b> 76699	Work Order Description Degreasing		losed, Com		Preventive		Aug 19, 2023	Aug 20, 2023	May 26, 2024	<b>Day</b> 280	's Late
76699			losed, Com	pleted	Preventive Planned	Complete	Aug 19, 2023 05:03:46 AM	Aug 20, 2023	May 26, 2024 02:26:33 PM	280	's Late )
76699	Degreasing	C	losed, Com		Preventive Planned		Aug 19, 2023 05:03:46 AM	Aug 20, 2023 05:03:46 AM	May 26, 2024 02:26:33 PM		's Late
76699	Degreasing	C	losed, Com	pleted Assigned	Preventive Planned		Aug 19, 2023 05:03:46 AM	Aug 20, 2023 05:03:46 AM	May 26, 2024 02:26:33 PM	280	's Late )
76699	Degreasing Fask Description Degreassing	Asset Articulated Roo	losed, Com	<b>Assigned</b> PMtech	Preventive Planned To		Aug 19, 2023 05:03:46 AM ed By	Aug 20, 2023 05:03:46 AM Date Completed	May 26, 2024 02:26:33 PM Est	280 Hours	S Late ) Spent Hours
76699	Degreasing Fask Description Degreassing Work Order Description	Asset Articulated Roo Articulated Roo	ck Truck	pleted Assigned PMtech	Preventive Planned To		Aug 19, 2023 05:03:46 AM ed By Date Created	Aug 20, 2023 05:03:46 AM Date Completed	May 26, 2024 02:26:33 PM Est	280 Hours	's Late )
76699	Degreasing Fask Description Degreassing	Asset Articulated Roo Articulated Roo	losed, Com	pleted Assigned PMtech	Preventive Planned To		Aug 19, 2023 05:03:46 AM ed By Date Created Sep 03, 2023	Aug 20, 2023 05:03:46 AM Date Completed	May 26, 2024 02:26:33 PM Est Date Completed Sep 15, 2023	280 Hours	s Late ) Spent Hours
76699 Work 77396	Degreasing  Fask Description  Degreassing  Work Order Description  Front left strut bottom bearing failure, Steel line leaking under	Asset Articulated Roo Articulated Roo Ster cab Cl	ck Truck ck Truck ck Truck tatus losed, Com	Assigned PMtech	Preventive Planned To Type Corrective	Complete	Aug 19, 2023 05:03:46 AM ed By Date Created Sep 03, 2023 11:31:10 AM	Aug 20, 2023 05:03:46 AM Date Completed	May 26, 2024 02:26:33 PM Est Pate Completed Sep 15, 2023 04:40:35 PM	280 Hours Day	s Late ) Spent Hours
76699 Work 77396	Degreasing Fask Description Degreassing Work Order Description	Asset Articulated Roi Articulated Roi Ster cab Cl	ck Truck ck Truck ck Truck	Assigned PMtech  pleted Assigned	Preventive Planned To  Type Corrective		Aug 19, 2023 05:03:46 AM ed By Date Created Sep 03, 2023 11:31:10 AM	Aug 20, 2023 05:03:46 AM Date Completed	May 26, 2024 02:26:33 PM Est Pate Completed Sep 15, 2023 04:40:35 PM	280 Hours	s Late ) Spent Hours
76699 Work 77396	Degreasing Fask Description Degreassing  Work Order Description Front left strut bottom bearing failure, Steel line leaking under Fask Description	Asset Articulated Roy Articulated Roy Ster cab Cl Asset Articulated Roy	ck Truck ck Truck ck Truck catus losed, Com	Assigned PMtech  pleted Assigned Christopher	Preventive Planned To  Type Corrective To	Complete	Aug 19, 2023 05:03:46 AM ed By Date Created Sep 03, 2023 11:31:10 AM ed By	Aug 20, 2023 05:03:46 AM Date Completed  Due Date  Date Completed	May 26, 2024 02:26:33 PM Est Date Completed Sep 15, 2023 04:40:35 PM Est	280 Hours Day	Spent Hours  Spent Hours  State  Spent Hours
76699  Work 77396	Degreasing  Fask Description  Degreassing  Work Order Description  Front left strut bottom bearing failure, Steel line leaking under Task Description  Sept 05/23 Kristian 2 /DS	Asset Articulated Roi Articulated Roi Ster cab Cl	ck Truck ck Truck ck Truck catus losed, Com	Assigned PMtech  pleted Assigned	Preventive Planned To  Type Corrective To	Complete	Aug 19, 2023 05:03:46 AM ed By Date Created Sep 03, 2023 11:31:10 AM ed By	Aug 20, 2023 05:03:46 AM Date Completed	May 26, 2024 02:26:33 PM Est Date Completed Sep 15, 2023 04:40:35 PM Est	280 Hours Day	Spent Hours  Spent Hours  State  Spent Hours
76699  ! Work 77396	Degreasing  Fask Description  Degreassing  Work Order Description  Front left strut bottom bearing failure, Steel line leaking under Fask Description  Gept 05/23 Kristian Z /DS  Removed leaking hydraulic hose The pipe that the transmission hose is rubbing on is rubbed threw and needs to be	Asset Articulated Roy Articulated Roy Ster cab Cl Asset Articulated Roy	ck Truck ck Truck ck Truck catus losed, Com	Assigned PMtech  pleted Assigned Christopher	Preventive Planned To  Type Corrective To	Complete	Aug 19, 2023 05:03:46 AM ed By Date Created Sep 03, 2023 11:31:10 AM ed By	Aug 20, 2023 05:03:46 AM Date Completed  Due Date  Date Completed	May 26, 2024 02:26:33 PM Est Date Completed Sep 15, 2023 04:40:35 PM Est	280 Hours Day	Spent Hours  Spent Hours  State  Spent Hours
76699 Work 77396	Degreasing  Fask Description  Degreasing  Work Order Description  Front left strut bottom bearing failure, Steel line leaking under Fask Description  Sept 05/23 Kristian Z /DS  Removed leaking hydraulic hose The pipe that the transmission hose is rubbing on is rubbed threw and needs to be emoved to get the welders to patch the hole up (438-5874)	Asset Articulated Roy Articulated Roy Ster cab Cl Asset Articulated Roy	ck Truck ck Truck ck Truck catus losed, Com	Assigned PMtech  pleted Assigned Christopher	Preventive Planned To  Type Corrective To	Complete	Aug 19, 2023 05:03:46 AM ed By Date Created Sep 03, 2023 11:31:10 AM ed By	Aug 20, 2023 05:03:46 AM Date Completed  Due Date  Date Completed	May 26, 2024 02:26:33 PM Est Date Completed Sep 15, 2023 04:40:35 PM Est	280 Hours Day	s Late ) Spent Hours
76699 Work 77396	Degreasing  Fask Description  Degreassing  Work Order Description  Front left strut bottom bearing failure, Steel line leaking under Fask Description  Gept 05/23 Kristian Z /DS  Removed leaking hydraulic hose The pipe that the transmission hose is rubbing on is rubbed threw and needs to be	Asset Articulated Roy Articulated Roy Ster cab Cl Asset Articulated Roy	ck Truck ck Truck  catus losed, Comp	Assigned PMtech  pleted Assigned Christopher	Preventive Planned To  Type Corrective To Paul Immer	Complete	Aug 19, 2023 05:03:46 AM ed By Date Created Sep 03, 2023 11:31:10 AM ed By	Aug 20, 2023 05:03:46 AM Date Completed  Due Date  Date Completed	May 26, 2024 02:26:33 PM Est Date Completed Sep 15, 2023 04:40:35 PM Est	280 Hours Day	Spent Hours  Spent Hours  Spent Hours  5.50
76699 Work 77396	Degreasing  Pegreasing  Work Order Description  Front left strut bottom bearing failure, Steel line leaking under Task Description  Sept 05/23 Kristian Z /DS  Removed leaking hydraulic hose is rubbing on is rubbed threw and needs to be emoved to get the welders to patch the hole up (438-5874)  New hose made up and is sitting in front of the unit sept 6/23 Kristian Z /DS	Asset Articulated Ron Articulated Ron Ster Cab Cl Asset Articulated Ron Articulated Ron Articulated Ron	ck Truck ck Truck  catus losed, Comp	PMtech  PMtech  pleted  Assigned  Christopher  Kristian Zim	Preventive Planned To  Type Corrective To Paul Immer	Complete	Aug 19, 2023 05:03:46 AM ed By Date Created Sep 03, 2023 11:31:10 AM ed By	Aug 20, 2023 05:03:46 AM Date Completed  Due Date  Date Completed	May 26, 2024 02:26:33 PM Est Date Completed Sep 15, 2023 04:40:35 PM Est	280 Hours Day	Spent Hours  Spent Hours  State  Spent Hours
76699 Work 77396	Degreasing  Fask Description  Degreasing  Work Order Description  Front left strut bottom bearing failure, Steel line leaking under Fask Description  Sept 05/23 Kristian Z /DS  Removed leaking hydraulic hose The pipe that the transmission hose is rubbing on is rubbed threw and needs to be emoved to get the welders to patch the hole up (438-5874)  New hose made up and is sitting in front of the unit	Asset Articulated Ron Articulated Ron Ster Cab Cl Asset Articulated Ron Articulated Ron Articulated Ron	ck Truck ck Truck  catus losed, Comp	PMtech  PMtech  pleted  Assigned  Christopher  Kristian Zim	Preventive Planned To  Type Corrective To Paul Immer	Complete	Aug 19, 2023 05:03:46 AM ed By Date Created Sep 03, 2023 11:31:10 AM ed By	Aug 20, 2023 05:03:46 AM Date Completed  Due Date  Date Completed	May 26, 2024 02:26:33 PM Est Date Completed Sep 15, 2023 04:40:35 PM Est	280 Hours Day	Spent Hours  Spent Hours  Spent Hours  5.50
76699 Work 77396	Degreasing  Pegreasing  Work Order Description  Front left strut bottom bearing failure, Steel line leaking under Steel Description  Front left strut bottom bearing failure, Steel line leaking under Steel Description  Sept 05/23 Kristian Z /DS  Removed leaking hydraulic hose The pipe that the transmission hose is rubbing on is rubbed threw and needs to be emoved to get the welders to patch the hole up (438-5874)  New hose made up and is sitting in front of the unit leave to the sept of 1/23 Kristian Z /DS  Placed on mount clap for the hoses and zip tied some, so they aren't touching the other parts  Topped up transmission oil	Asset Articulated Ron Articulated Ron Ster Cab Cl Asset Articulated Ron Articulated Ron Articulated Ron	ck Truck ck Truck  catus losed, Comp	PMtech  PMtech  pleted  Assigned  Christopher  Kristian Zim	Preventive Planned To  Type Corrective To Paul Immer	Complete	Aug 19, 2023 05:03:46 AM ed By Date Created Sep 03, 2023 11:31:10 AM ed By	Aug 20, 2023 05:03:46 AM Date Completed  Due Date  Date Completed	May 26, 2024 02:26:33 PM Est Date Completed Sep 15, 2023 04:40:35 PM Est	280 Hours Day	Spent Hours  Spent Hours  Spent Hours  5.50
76699 Work 77396	Degreasing  Fask Description  Degreasing  Work Order Description  Front left strut bottom bearing failure, Steel line leaking under Steel OS/23 Kristian Z /DS  Removed leaking hydraulic hose The pipe that the transmission hose is rubbing on is rubbed threw and needs to be emoved to get the welders to patch the hole up (438-5874)  New hose made up and is sitting in front of the unit lept 6/23 Kristian Z /DS  Placed on mount clap for the hoses and zip tied some, so they aren't touching the other parts Topped up transmission oil  Ran the unit to check if any leaks are present. No leaks present	Asset Articulated Ron Articulated Ron Ster Cab Cl Asset Articulated Ron Articulated Ron Articulated Ron	ck Truck ck Truck  catus losed, Comp	PMtech  PMtech  pleted  Assigned  Christopher  Kristian Zim	Preventive Planned To  Type Corrective To Paul Immer	Complete	Aug 19, 2023 05:03:46 AM ed By Date Created Sep 03, 2023 11:31:10 AM ed By	Aug 20, 2023 05:03:46 AM Date Completed  Due Date  Date Completed	May 26, 2024 02:26:33 PM Est Date Completed Sep 15, 2023 04:40:35 PM Est	280 Hours Day	Spent Hours  Spent Hours  Spent Hours  5.50
76699 Work 77396	Degreasing  Work Order Description  Front left strut bottom bearing failure, Steel line leaking under Steel Strut bottom bearing failure, Steel line leaking under Steel OS/23 Kristian Z /DS  Removed leaking hydraulic hose The pipe that the transmission hose is rubbing on is rubbed threw and needs to be emoved to get the welders to patch the hole up (438-5874)  New hose made up and is sitting in front of the unit leater of C/3 Kristian Z /DS  Placed on mount clap for the hoses and zip tied some, so they aren't touching the other parts Topped up transmission oil  Ran the unit to check if any leaks are present. No leaks present Bolted back on the bottom plates and pinned the cab back on the unit. Bolted on rear pin cover and rear left panel	Asset Articulated Ron Articulated Ron Ster Cab Cl Asset Articulated Ron Articulated Ron Articulated Ron	ck Truck ck Truck  catus losed, Comp	PMtech  PMtech  pleted  Assigned  Christopher  Kristian Zim	Preventive Planned To  Type Corrective To Paul Immer	Complete	Aug 19, 2023 05:03:46 AM ed By Date Created Sep 03, 2023 11:31:10 AM ed By	Aug 20, 2023 05:03:46 AM Date Completed  Due Date  Date Completed	May 26, 2024 02:26:33 PM Est Date Completed Sep 15, 2023 04:40:35 PM Est	280 Hours Day	Spent Hours  Spent Hours  Spent Hours  5.50
76699 Work 77396	Degreasing  Work Order Description  Pegreassing  Work Order Description Front left strut bottom bearing failure, Steel line leaking under Lask Description  Front left strut bottom bearing failure, Steel line leaking under Lask Description  Sept 05/23 Kristian Z /DS  Removed leaking hydraulic hose The pipe that the transmission hose is rubbing on is rubbed threw and needs to be emoved to get the welders to patch the hole up (438-5874)  New hose made up and is sitting in front of the unit leave the sept of 23 Kristian Z /DS  Placed on mount clap for the hoses and zip tied some, so they aren't touching the other parts Topped up transmission oil Ran the unit to check if any leaks are present. No leaks present Bolted back on the bottom plates and pinned the cab back on the unit. Bolted on rear pin cover and rear left panel Drove unit to down line, cause its waiting for a right side strut	Articulated Roc Articulated Roc Ster Cab Cl Asset Articulated Roc Articulated Roc Articulated Roc Articulated Roc	ck Truck ck Truck  ck Truck  ck Truck  ck Truck  ck Truck  ck Truck	pleted  Assigned  PMtech  pleted  Assigned  Christopher  Kristian Zim	Preventive Planned To  Type Corrective To Paul Immer	Complete Kristian Zi	Aug 19, 2023 05:03:46 AM ed By  Date Created Sep 03, 2023 11:31:10 AM ed By  mmer	Aug 20, 2023 05:03:46 AM Date Completed  Due Date  Date Completed  Sep 05, 2023 05:19:00 PM	May 26, 2024 02:26:33 PM Est Date Completed Sep 15, 2023 04:40:35 PM Est	280 Hours Day	Spent Hours  Spent Hours  5.50
76699 Work 77396	Degreasing  Work Order Description  Front left strut bottom bearing failure, Steel line leaking under Steel Strut bottom bearing failure, Steel line leaking under Steel OS/23 Kristian Z /DS  Removed leaking hydraulic hose The pipe that the transmission hose is rubbing on is rubbed threw and needs to be emoved to get the welders to patch the hole up (438-5874)  New hose made up and is sitting in front of the unit leater of C/3 Kristian Z /DS  Placed on mount clap for the hoses and zip tied some, so they aren't touching the other parts Topped up transmission oil  Ran the unit to check if any leaks are present. No leaks present Bolted back on the bottom plates and pinned the cab back on the unit. Bolted on rear pin cover and rear left panel	Asset Articulated Ron Articulated Ron Ster Cab Cl Asset Articulated Ron Articulated Ron Articulated Ron	ck Truck ck Truck  ck Truck  ck Truck  ck Truck  ck Truck  ck Truck	PMtech  PMtech  pleted  Assigned  Christopher  Kristian Zim	Preventive Planned To  Type Corrective To Paul Immer	Complete	Aug 19, 2023 05:03:46 AM ed By  Date Created Sep 03, 2023 11:31:10 AM ed By  mmer	Aug 20, 2023 05:03:46 AM Date Completed  Due Date  Date Completed	May 26, 2024 02:26:33 PM Est Date Completed Sep 15, 2023 04:40:35 PM Est	280 Hours Day	Spent Hours  Spent Hours  Spent Hours  5.50

-Removed old strut and cleaned off all the grease and dirt -Placed on new strut with one new pin and a good used pin -Lowered unit and filled the strut with oil -Bolted on hose guard on Final

NOTE: Ordered overhaul and brake service kits, cause the right front final is starting to seep out a bit of oil. Still good to drive for now. A Crossover is on unit Sept 18/23- Kal tire

Retorqued #1,2 positions

Articulated Rock Truck

Asset

Kal Tire

Kal Tire

Sep 18, 2023 12:16:00 PM

Est Hours

**Spent Hours** 

**Date Completed** 

_							20.5
ork	Work Order Description	Status	Туре	Date Created	Due Date	Date Completed	Days Late
8105	Won't start	Closed, C	ompleted Corrective	Sep 16, 202 06:59:05 PM		Sep 16, 2023 10:26:26 PM	
-	Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hou	rs Spent Hou
_		Articulated Rock Truck	Austin Heino	Menno Buhler	Sep 16, 2023 10:26:26 P	М	
ork	Work Order Description	Status	Туре	Date Created	Due Date	Date Completed	Days Late
8281	Dead battery, truck boost needed. Operator left lights on	Closed, C	ompleted	Sep 21, 2023 11:03:59 AM		Sep 21, 2023 02:12:36 PM	
-	Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hou	rs Spent Hou
-		Articulated Rock Truck	Ken Connon	Nick Vanderkooi	Sep 21, 2023 02:12:36 P		
ork	Work Order Description	Status	Туре	Date Created	Due Date	Date Completed	Days Late
8409	Headlights stopped working	Closed, Co	ompleted	Sep 25, 2023 04:37:39 AM		Sep 25, 2023 09:43:58 AM	
-	Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hou	rs Spent Hou
3	Sourced and replaced headlight switch	Articulated Rock Truck	Ken Connon	Ken Connon	Sep 25, 2023 09:43:58 A		<u> </u>
-	111				<u> </u>	2.0	00
ork -	Work Order Description	Status	Туре	Date Created	Due Date	Date Completed	Days Late
3481	745C PM2 500 Service Hours	Closed, Co	ompleted Preventive Planned	- Sep 26, 2023 02:47:42 PM		Sep 26, 2023 02:47:42 PM	0
-	Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hou	rs Spent Hou
	Brake Accumulator (Service) - Check	Articulated Rock Truck	PMtech		-		•
E	Brake Pads - Check	Articulated Rock Truck	PMtech				
E	Braking System - Test	Articulated Rock Truck	PMtech				
f	Diff & Final Drive Oil Level - Check (note particulates on mag plug and indicate indings)	Articulated Rock Truck	PMtech	PMtech	Sep 26, 2023 02:48:00 P		
	Differential and Final Drive Oil Sample - Obtain	Articulated Rock Truck	PMtech	PMtech	Sep 26, 2023 02:48:00 PI		
	Engine Air Filter Secondary Element (Outer) - Replace	Articulated Rock Truck	PMtech	PMtech	Sep 26, 2023 02:48:00 P		
	Engine Oil and Filter - Change Engine Oil Filter Inspect (Cut Filter and Record Findings)	Articulated Rock Truck	PMtech	PMtech	Sep 26, 2023 02:48:00 Pl	M 2.6	00
	Fuel System Primary Filter - Replace	Articulated Rock Truck	PMtech	SM1++	5 05 2000 00 40 00 D		
	Fuel System Secondary Filter - Replace	Articulated Rock Truck Articulated Rock Truck	PMtech	PMtech PMtech	Sep 26, 2023 02:48:00 Pl		
	Hoist System and Brake System Oil Sample - Obtain	Articulated Rock Truck	PMtech PMtech	PMtech	Sep 26, 2023 02:48:00 Pt		
	Secondary Steering - Test	Articulated Rock Truck	PMtech	rMtech	Sep 26, 2023 02:48:00 P	M 2.0	00
	Steering System Oil Sample - Obtain	Articulated Rock Truck	PMtech	PMtech	Sep 26, 2023 02:48:00 PI	м 2.0	00
	Forque Converter and Transmission Oil Sample - Obtain	Articulated Rock Truck	PMtech	PMtech	Sep 26, 2023 02:48:00 PI		
	Fransfer Gear Oil Sample - Obtain	Articulated Rock Truck	PMtech	PMtech	Sep 26, 2023 02:48:00 PI		
	Fransmission Oil Filter Replace	Articulated Rock Truck	PMtech	PMtech	Sep 26, 2023 02:48:00 PI		
1	Fransmission Oil Filter - Inspect (Cut Filter and Record Findings.)	Articulated Rock Truck	PMtech		OCP 20, 2020 02:40:00 1	-·	
	The state of the s					22.6	00
ork -	Work Order Description	Status	Туре	Date Created	Due Date	Date Completed	Days Late
8482	745C PM2 500 Service Hours	Closed, Co	ompleted Preventive Planned	- Sep 26, 2023 02:49:25 PM		Sep 26, 2023 02:49:25 PM	0
	Task Description	Asset	Assigned To	Completed By	しん・マン・ムン ドバリ	ひん・マタ・んり FM	

Completed By

**Assigned To** 

**Task Description** 

Work	Work Order Description	**	Status		Туре	Ð	ate Created	Due Date	Date Completed	Days Late	0.50
	Boost unit						••	01. 00, 2023 07.47.39 2	xr-9		
_	Task Description D8 Oct. 2023 - Gabe Elnamer	Asset Articulated	Rock Truck	Assigned Gabe Elna		Completed Gabe Elname	Ву	Date Completed Oct 08, 2023 07:47:59 A	Est Hou	s Spe	nt Hour
78984	Truck lay down		Closed, Co	mpleted	Corrective	_	ct 08, 2023 6:55:02 AM		Oct 08, 2023 07:47:59 AM		
Work	Work Order Description		Status		Туре	D	ate Created	Due Date	Date Completed	Days Late	à
г	MPORTANT NOTE: When machine comes back with another centre bottom bushing eplacement, the front A Frame needs to be removed and machined. The bearing slipped in easily.										10.
- v - -	Installed new centre pin bearing and sleeve with anti seize Bolted main hold down washer and tighten the three bolts to 118 ft lbs and hit the washer till it will no longer move Bolted on the bottom grease cover Greased the bottom bearing and the rest of the fittings Did a FillCal twice on the unit. Was a success Marvin moved unit to the upline										
	CHECKED OUT THE MACHINE. IT WAS CONFIRMED FRONT SUSPENSION FRAME MOVING BY ABOUT 1/4 INCH. WASHED THE WORK AREA AND BROUGHT MACHINE NSIDE THE SHOP. REMOVED A-FRAME BOTTOM BEARING CAP. VERIFIED PLAY BY USING FLOOR JACK AND IT WAS CONFIRMED BEARING WAS LOOSE. DISCONNECTED FRONT DRIVE SHAFT AND LOWERED THE A-FRAME USING PRESS, TOOK THE BEARING OUT, WASHED AND REMOVED LEEVE FOR REUSE. WASHED ALL PARTS REMOVED AFTER. LOOK FOR NEW BEARING INSIDE AND OUT THE SHOP BUT NOTHING FOUND. DIS TO CONTINUE.  OCT 4/23 Kristian Z /NS	Articulated	Rock Truck	Kristian Zi	mmer	Kristian Zimr	ner	Oct 05, 2023 04:44:00 A	м		5.
	OCT 03, 2023-MARVIN C-	Articulated	Rock Truck Rock Truck	Marvin Co	rpuz	Marvin Corps	JZ	Oct 03, 2023 01:15:00 A	<b>M</b>		5.
	Task Description	Asset		Assigned		Completed		Date Completed	Est Hou	s Spe	ent Hou
78797	Center pin needs fixed		Closed, Co	mpleted		_	oct 03, 2023 3:55:07 PM		Oct 05, 2023 03:09:17 AM		
Work	Work Order Description		Status		Туре	D	ate Created	Due Date	Date Completed	Days Lat	
-		Articulated	Rock Truck	Rey Contr	eras	Nick Vander	kooi	Sep 30, 2023 04:23:11	РМ		
-	Task Description	Asset		Assigned		Completed		Date Completed	04:23:11 PM Est Hou	s Spe	ent Hou
78631			Closed, Co	mpleted	Туре	S	ep 29, 2023	Due Date	Date Completed Sep 30, 2023	Days Lat	à
Work	Work Order Description		Status		T		ate Created		0-1-0		
1	Fransmission Oil Filter - Inspect (Cut Filter and Record Findings.)	Articulated	Rock Truck	PMtech							
	Fransmission Oil Filter Replace		Rock Truck	PMtech							
	Forque Converter and Transmission Oil Sample - Obtain Fransfer Gear Oil Sample - Obtain		Rock Truck Rock Truck	PMtech PMtech							
	Steering System Oil Sample - Obtain		Rock Truck	PMtech							
	Secondary Steering - Test		Rock Truck	PMtech							
	Hoist System and Brake System Oil Sample - Obtain		Rock Truck	PMtech							
	Fuel System Secondary Filter - Replace		Rock Truck	PMtech							
	Engine Oil Filter Inspect (Cut Filter and Record Findings) Fuel System Primary Filter - Replace		Rock Truck Rock Truck	PMtech PMtech							
	Engine Oil and Filter - Change		Rock Truck	PMtech							
	Engine Air Filter Secondary Element (Outer) - Replace		Rock Truck	PMtech							
[	Differential and Final Drive Oil Sample - Obtain		Rock Truck	PMtech							
	Diff & Final Drive Oil Level - Check (note particulates on mag plug and indicate findings)	Articulated	Rock Truck	PMtech							
	Braking System - Test		Rock Truck	PMtech							
E											

Closed, Completed Corrective

Oct 12, 2023 06:53:30 AM Oct 12, 2023 03:14:21 PM

	Task Description	Asset	Assigned to	Completed By	Date Completed	Est Hours	Spent Hours
		Articulated Rock Truck	Andy Boettger	Menno Buhler	Oct 12, 2023 03:14:21	РМ	
Work	Work Order Description	Status	Туре	Date Created	Due Date	Date Completed D	ays Late
79623	Brake oil filter restricted	Closed, Co	ompleted Corrective	Oct 23, 2023 02:32:24 AM		Oct 24, 2023 11:53:20 AM	ining. Pangangan
	Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
	Oct 23/23- Sebastian C- Brandt	Articulated Rock Truck	Sebastian Cepeda - Brandt	Sebastian Cepeda - Brandt	Oct 23, 2023 08:17:00	AM	5.00

"TRAVELLED TO UNIT AND CHECKED CODES
CODES FOR BRAKE FILTER RESTRICTION AND LOW ACCUMUALTOR BRAKE PRESSURE
WERE LOGGED
RAN BRAKE TEST AND FAILED
CHECKED CHARGE ON ACCUMULATORS AND CHARGED
RE RUN TEST AND PASSED
CONNECTED GAUGE AND READ BRAKE COOLING PUMP PRESSURE
PRESSURE WAS LOW
REMOVED FILTER AND FOUND AN EXCESSIVE AMMOUNT OF CONTAMINATION COMING
FROM BRAKE GROUPS
DAMPER MATERIAL FOUND
REPLACED FILTER AND RECHECKED PRESSURE, PRESSURE WAS WITH IN SPEC
REMOVED GUARDS AND GOT READY TO GO INTO WASH BAY
WAITED BUT COULD NOT GET INTO WASH BAY
FINISHED OFF DAY BY TRAVELLING TO BRANCHCH AND PICKING UP PARTS "

Oct 24/23- Sebastian C- Brandt

Articulated Rock Truck

Sebastian Cepeda - Brandt Sebastian Cepeda - Brandt Oct 24, 2023 08:18:00 AM

5.50

"WASHED UNIT AND GOT READY FOR REPAIR
DRAINED BRAKE TANK
REMOVED HOSES CLAMPS AND ELECTRICAL FROM TANK
REMOVED TOP OF TANK
VACCUMED AND CLEANED OUT TANK
REINSTALLED COVER, HOHSES, CLAMPS AND ELECTRICAL
FILLED UP TANK AND INSTALLED NEW FILTER
INSTALLED GUARDS
RAN MACHINE UP TO TEMP AND RAN AROUND
CHECKED PUMP PRESSURE AND IT WAS UP TO SPEC
TRUCK PERFORMED A REGEN
DROPPED FILTER AND INSTALLED NEW ONE
VERIFIED NO LEAKS OR CODES WERE EVIDENT"

										10.50
Work	Work Order Description	9	tatus		Туре		Date Created	Due Date	Date Completed	Days Late
79679	Hydraulic leak	C	Closed, C	ompleted			Oct 24, 2023 03:59:42 PM		Oct 25, 2023 07:57:07 AM	
	Task Description	Asset		Assigned	To	Complet	ted By	Date Completed	Est Hou	rs Spent Hours
		Articulated Re	ock Truck	Nick Miser	er	Ian Knott		Oct 25, 2023 07:57:07 A	М	
Work	Work Order Description	S	itatus		Туре		Date Created	Due Date	Date Completed	Days Late
79732	745C PM4 2000 Service Hours	C	Closed, C	ompleted	Preventive Planned	-	Oct 25, 2023 03:31:13 PM	,	Oct 25, 2023 03:33:20 PM	0
	Task Description	Asset		Assigned		Complet		Date Completed	Est Hou	rs Spent Hours
	Axle Breathers - Clean/Replace	Articulated Ro	ock Truck	PMtech		PMtech		Oct 25, 2023 03:32:00 P	M 1.	00
	Brake Oil - Change	Articulated Re	ock Truck	PMtech		PMtech		Oct 25, 2023 03:32:00 P	M 1.	00
	Brake System Air - Purge	Articulated Ro	ock Truck	PMtech		PMtech		Oct 25, 2023 03:32:00 P	М 1.	00
	Breather (Brake Tank) - Replace	Articulated Ro	ock Truck	PMtech		PMtech		Oct 25, 2023 03:32:00 P	M 1.	00
	Diff and Final Drive Oil - Change (note particulates on mag plug and idicate findings)	Articulated Ro	ock Truck	PMtech		PMtech		Oct 25, 2023 03:32:00 P		· ·
	Engine Compression Brake Valve Lash - Check	Articulated Ro	ock Truck	PMtech						

	ingine Valve Lash - Check	Articulated Rock Tru	ick PMtech							
	rame and Body - Inspect	Articulated Rock Tru								
	lydraulic Tank Breather - Replace	Articulated Rock Tru			PMtech		Oct 25, 2023 03:32:00 P		1.00	
	Refrigerant Dryer - Replace	Articulated Rock Tru			MILECTI		OCC 23, 2023 03.32,00 P	14(	1.00	
	ervice Brake Wear Indicator - Check	Articulated Rock Tru								
	suspension System - Check	Articulated Rock Tru								
<del>-</del>									6.00	
Nork	Work Order Description	Status		Туре		Date Created	Due Date	Date Completed	Days	Late
79733	745C PM2 500 Service Hours	Closed	d, Completed	Preventive Planned	-	Oct 25, 2023 03:33:04 PM		Oct 25, 2023 03:33:04 PM	0	
-	Task Description	Asset	Assigne		Comple		Date Completed		Hours	Spent Hou
Ē	rake Accumulator (Service) - Check	Articulated Rock Tru	ck PMtech			•				
F	rake Pads - Check	Articulated Rock Tru	ck PMtech							
F	raking System - Test	Articulated Rock Tru	ck PMtech							
f	off & Final Drive Oil Level - Check (note particulates on mag plug and indicate indings)	Articulated Rock Tru								
	Offerential and Final Drive Oil Sample - Obtain	Articulated Rock Tru								
	ingine Air Filter Secondary Element (Outer) - Replace	Articulated Rock Tru-								
	ingine Oil and Filter - Change	Articulated Rock Tru-								
	uel System Primary Filter - Replace	Articulated Rock True								
	ingine Oil Filter Inspect (Cut Filter and Record Findings)	Articulated Rock True								
	ransmission Oil Filter - Inspect (Cut Filter and Record Findings.)	Articulated Rock True								
	ransmission Oil Filter Replace	Articulated Rock True	-							
	ransfer Gear Oil Sample - Obtain	Articulated Rock True								
	orque Converter and Transmission Oil Sample - Obtain	Articulated Rock True								
	econdary Steering - Test	Articulated Rock True								
	loist System and Brake System Oil Sample - Obtain	Articulated Rock True								
	uel System Secondary Filter - Replace Iteering System Oil Sample - Obtain	Articulated Rock True Articulated Rock True								
Work	Work Order Description	Status	-	Туре		Date Created	Due Date	Date Completed	Dave	Late
70735	745C PM2 500 Service Hours	Closed	Completed	Droventive		Oct 25 2022		=	•	
	745C PM2 500 Service Hours		i, Completed	Preventive - Planned		Oct 25, 2023 03:34:57 PM	Oct 26, 2023 03:34:57 PM	Oct 25, 2023 03:34:57 PM	0	
1	ask Description	Asset	Assigned	Planned	Comple	03:34:57 PM	Oct 26, 2023 03:34:57 PM Date Completed	Oct 25, 2023 03:34:57 PM Est I	0 Hours	
<u>1</u>	Task Description Transmission Oil Filter Replace	Asset Articulated Rock True	<b>Assigned</b> ck PMtech	Planned		03:34:57 PM	Oct 26, 2023 03:34:57 PM	Oct 25, 2023 03:34:57 PM Est I	0	
1 T	Task Description  ransmission Oil Filter Replace  ransmission Oil Filter - Inspect (Cut Filter and Record Findings.)	Asset Articulated Rock True Articulated Rock True	Assigned Ck PMtech Ck PMtech	Planned	<b>Comple</b> PMtech	03:34:57 PM	Oct 26, 2023 03:34:57 PM Date Completed Oct 25, 2023 03:35:00 PM	Oct 25, 2023 03:34:57 PM Est I	0 Hours 2.00	
1 T	Task Description ransmission Oil Filter Replace ransmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransfer Gear Oil Sample - Obtain	Asset  Articulated Rock True Articulated Rock True Articulated Rock True	Assigned ck PMtech ck PMtech ck PMtech	Planned	<b>Comple</b> PMtech	03:34:57 PM	Oct 26, 2023 03:34:57 PM Date Completed Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM	Oct 25, 2023 03:34:57 PM Est I	0 Hours 2.00	
1 1 1	Task Description ransmission Oil Filter Replace ransmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain	Asset  Articulated Rock True Articulated Rock True Articulated Rock True Articulated Rock True	Assigned CK PMtech CK PMtech CK PMtech CK PMtech CK PMtech	Planned	Comple PMtech PMtech PMtech	03:34:57 PM	Oct 26, 2023 03:34:57 PM Date Completed Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM	Oct 25, 2023 03:34:57 PM Est I	0 Hours 2.00 2.00 2.00	
1 1 1 2 2	Task Description  ransmission Oil Filter Replace  ransmission Oil Filter - Inspect (Cut Filter and Record Findings.)  ransfer Gear Oil Sample - Obtain  orque Converter and Transmission Oil Sample - Obtain  teering System Oil Sample - Obtain	Asset  Articulated Rock Truc	Assigned CK PMtech CK PMtech CK PMtech CK PMtech CK PMtech CK PMtech	Planned	<b>Comple</b> PMtech	03:34:57 PM	Oct 26, 2023 03:34:57 PM Date Completed Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM	Oct 25, 2023 03:34:57 PM Est I	0 Hours 2.00	
1 7 7 1 2 8	ransmission Oil Filter Replace ransmission Oil Filter Replace ransmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain teering System Oil Sample - Obtain econdary Steering - Test	Asset  Articulated Rock Truc	Assigned  Ck PMtech	Planned	Complei PMtech PMtech PMtech PMtech	03:34:57 PM	Oct 26, 2023 03:34:57 PM Date Completed Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM	Oct 25, 2023 03:34:57 PM Est I	2.00 2.00 2.00 2.00 2.00	
1 7 7 1 9 9	Task Description  ransmission Oil Filter Replace  ransmission Oil Filter - Inspect (Cut Filter and Record Findings.)  ransfer Gear Oil Sample - Obtain  orque Converter and Transmission Oil Sample - Obtain  teering System Oil Sample - Obtain  econdary Steering - Test  loist System and Brake System Oil Sample - Obtain	Asset  Articulated Rock Truc	Assigned Ck PMtech	Planned	Complei PMtech PMtech PMtech PMtech	03:34:57 PM	Oct 26, 2023 03:34:57 PM Date Completed Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM	Oct 25, 2023 03:34:57 PM Est I	0 Hours 2.00 2.00 2.00 2.00 2.00	
1 1 1 2 5 6	Task Description ransmission Oil Filter Replace ransmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain teering System Oil Sample - Obtain econdary Steering - Test loist System and Brake System Oil Sample - Obtain uel System Secondary Filter - Replace	Asset  Articulated Rock Truc Articulated Rock	Assigned Ck PMtech	Planned	Complei PMtech PMtech PMtech PMtech	03:34:57 PM	Oct 26, 2023 03:34:57 PM Date Completed Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM	Oct 25, 2023 03:34:57 PM Est I	2.00 2.00 2.00 2.00 2.00	
1 1 1 1 2 5 6 6 6	rask Description ransmission Oil Filter Replace ransmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain teering System Oil Sample - Obtain econdary Steering - Test loist System and Brake System Oil Sample - Obtain uel System Secondary Filter - Replace ngine Oil Filter Inspect (Cut Filter and Record Findings)	Asset  Articulated Rock Truc	Assigned  Ck PMtech	Planned I To	Completed PMtech	03:34:57 PM	Oct 26, 2023 03:34:57 PM Date Completed Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM	Oct 25, 2023 03:34:57 PM Est I	0 Hours 2.00 2.00 2.00 2.00 2.00 2.00	
1 1 1 2 5 5 6 6	ransmission Oil Filter Replace ransmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain teering System Oil Sample - Obtain econdary Steering - Test loist System and Brake System Oil Sample - Obtain uel System Secondary Filter - Replace ngine Oil Filter Inspect (Cut Filter and Record Findings) ngine Oil and Filter - Change	Asset  Articulated Rock Truc	Assigned  Ck PMtech	Planned I To	Complete PMtech	03:34:57 PM	Oct 26, 2023 03:34:57 PM Date Completed Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM	Oct 25, 2023 03:34:57 PM Est I	0 Hours 2.00 2.00 2.00 2.00 2.00 2.00 2.00	
1 1 1 1 2 2 3 4 6 6 6 6 6 6 6 6 6 6 6 6 6 7 7	ransmission Oil Filter Replace ransmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain teering System Oil Sample - Obtain econdary Steering - Test loist System and Brake System Oil Sample - Obtain uel System Secondary Filter - Replace ngine Oil Filter Inspect (Cut Filter and Record Findings) ngine Oil and Filter - Change ngine Oil and Filter - Secondary Element (Outer) - Replace	Asset  Articulated Rock Truc	Assigned  Ck PMtech	Planned I To	Complei PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech	03:34:57 PM	Oct 26, 2023 03:34:57 PM Date Completed Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM	Oct 25, 2023 03:34:57 PM Est I	0 Hours 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.0	
1 1 1 1 2 2 4 6 6 6 6 6 6 6 6 6 6 6 6 6 6 7 7 8 8 8 8	ransmission Oil Filter Replace ransmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain teering System Oil Sample - Obtain teering System Oil Sample - Obtain tecondary Steering - Test toist System and Brake System Oil Sample - Obtain uel System Secondary Filter - Replace ngine Oil Filter Inspect (Cut Filter and Record Findings) ngine Oil and Filter - Change ngine Air Filter Secondary Element (Outer) - Replace tifferential and Final Drive Oil Sample - Obtain oilf & Final Drive Oil Level - Check (note particulates on mag plug and indicate	Asset  Articulated Rock Truc	Assigned  Ck PMtech	Planned I To	Complete PMtech	03:34:57 PM	Oct 26, 2023 03:34:57 PM Date Completed Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM	Oct 25, 2023 03:34:57 PM Est I	0 Hours 2.00 2.00 2.00 2.00 2.00 2.00 2.00	
1	ransmission Oif Filter Replace ransmission Oif Filter - Inspect (Cut Filter and Record Findings.) ransfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain teering System Oil Sample - Obtain teering System Oil Sample - Obtain tecondary Steering - Test loist System and Brake System Oil Sample - Obtain uel System Secondary Filter - Replace ngine Oil Filter Inspect (Cut Filter and Record Findings) ngine Oil and Filter - Change ngine Air Filter Secondary Element (Outer) - Replace ifferential and Final Drive Oil Sample - Obtain	Articulated Rock Truc	Assigned  Ck PMtech	Planned I To	Complei PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech	03:34:57 PM	Oct 26, 2023 03:34:57 PM Date Completed Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM	Oct 25, 2023 03:34:57 PM Est I	0 Hours 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.0	
1	ransmission Oil Filter Replace ransmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain teering System Oil Sample - Obtain econdary Steering - Test loist System and Brake System Oil Sample - Obtain uel System Becondary Filter - Replace ngine Oil Filter Inspect (Cut Filter and Record Findings) ngine Oil and Filter - Change ngine Air Filter Secondary Element (Outer) - Replace ifferential and Final Drive Oil Sample - Obtain iff & Final Drive Oil Level - Check (note particulates on mag plug and indicate ndings)	Asset  Articulated Rock Truc	Assigned  Ck PMtech	Planned I To	Complei PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech	03:34:57 PM	Oct 26, 2023 03:34:57 PM Date Completed Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM	Oct 25, 2023 03:34:57 PM Est I	0 Hours 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.0	
1	ransmission Oif Filter Replace iransmission Oif Filter - Inspect (Cut Filter and Record Findings.) ransfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain teering System Oil Sample - Obtain econdary Steering - Test loist System and Brake System Oil Sample - Obtain uel System Secondary Filter - Replace ngine Oil Filter Inspect (Cut Filter and Record Findings) ngine Oil and Filter - Change ngine Air Filter Secondary Element (Outer) - Replace ifferential and Final Drive Oil Sample - Obtain iff & Final Drive Oil Level - Check (note particulates on mag plug and indicate ndings) raking System - Test	Articulated Rock Truc	Assigned  Ck PMtech	Planned I To	Complei PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech	03:34:57 PM	Oct 26, 2023 03:34:57 PM Date Completed Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM	Oct 25, 2023 03:34:57 PM Est I	0 Hours 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.0	
1	ransmission Oil Filter Replace ransmission Oil Filter Replace ransmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain teering System Oil Sample - Obtain teering System Oil Sample - Obtain teering System Brake System Oil Sample - Obtain uel System and Brake System Oil Sample - Obtain uel System Secondary Filter - Replace ngine Oil Filter Inspect (Cut Filter and Record Findings) ngine Oil and Filter - Change ngine Oil and Filter Secondary Element (Outer) - Replace ifferential and Final Drive Oil Sample - Obtain iff & Final Drive Oil Level - Check (note particulates on mag plug and indicate ndings) raking System - Test rake Pads - Check	Articulated Rock Truc	Assigned  Ck PMtech	Planned I To	Complei PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech	03:34:57 PM	Oct 26, 2023 03:34:57 PM Date Completed Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM	Oct 25, 2023 03:34:57 PM Est I	0 Hours 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.0	
1	ransmission Oil Filter Replace ransmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain teering System Oil Sample - Obtain econdary Steering - Test loist System and Brake System Oil Sample - Obtain uel System Secondary Filter - Replace Ingine Oil Filter Inspect (Cut Filter and Record Findings) Ingine Oil and Filter - Change Ingine Oil and Filter - Change Ingine Air Filter Secondary Element (Outer) - Replace Inifferential and Final Drive Oil Sample - Obtain Iff & Final Drive Oil Level - Check (note particulates on mag plug and indicate Indings) Iraking System - Test Irake Pads - Check Irake Accumulator (Service) - Check Irake Accumulator (Service) - Check Irake Accumulator (Service) - Check Ivake Accumulator Filter - Replace	Asset  Articulated Rock Truc	Assigned  Ck PMtech	Planned To	PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech	03:34:57 PM	Oct 26, 2023 03:34:57 PM Date Completed Oct 25, 2023 03:35:00 PM Oct 25, 2023 03:35:00 PM	Oct 25, 2023 03:34:57 PM Est I	0 Hours 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00	Spent Hou
- T T T T T T T T T T T T T T T T T T T	ransmission Oil Filter Replace ransmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain teering System Oil Sample - Obtain econdary Steering - Test loist System and Brake System Oil Sample - Obtain uel System Secondary Filter - Replace Ingine Oil Filter Inspect (Cut Filter and Record Findings) Ingine Oil and Filter - Change Ingine Oil and Filter - Change Ingine Air Filter Secondary Element (Outer) - Replace Inifferential and Final Drive Oil Sample - Obtain Iniff & Final Drive Oil Level - Check (note particulates on mag plug and indicate Indings) raking System - Test rake Pads - Check Irake Accumulator (Service) - Check Ivel System Primary Filter - Replace  Work Order Description	Asset  Articulated Rock Truc	Assigned  Ck PMtech   Planned	PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech	03:34:57 PM ted By	Oct 26, 2023 03:34:57 PM Date Completed Oct 25, 2023 03:35:00 PM	Oct 25, 2023 03:34:57 PM Est I	0 Hours 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00	Spent Hou	
1	ransmission Oil Filter Replace ransmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain teering System Oil Sample - Obtain econdary Steering - Test loist System and Brake System Oil Sample - Obtain uel System Secondary Filter - Replace ngine Oil Filter Inspect (Cut Filter and Record Findings) ngine Oil and Filter - Change ngine Air Filter Secondary Element (Outer) - Replace bifferential and Final Drive Oil Sample - Obtain biff & Final Drive Oil Level - Check (note particulates on mag plug and indicate ndings) raking System - Test rake Pads - Check trake Accumulator (Service) - Check uel System Primary Filter - Replace  Work Order Description Windshield sprayer not working (the end is broke or unhooke	Asset  Articulated Rock Truc	Assigned  Ck PMtech	Planned To	PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech	03:34:57 PM	Oct 26, 2023 03:34:57 PM Date Completed Oct 25, 2023 03:35:00 PM	Oct 25, 2023 03:34:57 PM Est I	0 Hours 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00	Spent Hou
1 1 1 2 2 3 4 6 6 6 6 6 6 6 6 7 7 9 9 6 7	ransmission Oil Filter Replace ransmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain teering System Oil Sample - Obtain econdary Steering - Test loist System and Brake System Oil Sample - Obtain uel System Secondary Filter - Replace Ingine Oil Filter Inspect (Cut Filter and Record Findings) Ingine Oil and Filter - Change Ingine Oil and Filter - Change Ingine Air Filter Secondary Element (Outer) - Replace Inifferential and Final Drive Oil Sample - Obtain Iniff & Final Drive Oil Level - Check (note particulates on mag plug and indicate Indings) raking System - Test rake Pads - Check Irake Accumulator (Service) - Check Ivel System Primary Filter - Replace  Work Order Description	Asset  Articulated Rock Truc	Assigned  Ck PMtech   Planned To  Type Corrective	PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech	03:34:57 PM ted By	Oct 26, 2023 03:34:57 PM Date Completed Oct 25, 2023 03:35:00 PM	Oct 25, 2023 03:34:57 PM Est I	0 Hours 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00	Spent Hour	

found washer fluid tank empty, trail of washer fluid down from the pump, replaced grommet seal and filled tank, found the nozzle no clipped to the arm, reinstalled nozzle, washer system works good,

								<u> </u>	1.0	
Work	Work Order Description	-	tatus		Туре	Date Created	Due Date	Date Completed	Days Late	
80023	2-way radio bracket really loose, needs to be tightened	Closed, Completed				Nov 03, 20		Nov 03, 2023	•	
	Tank Banadakina					04:19:58 A		04:06:11 PM		
-	Task Description	Asset	al Tarret	Assigned		Completed By	Date Completed	Est Hou	s Spent Hou	
-		Articulated Re	ock Truck	Christoph	er Paul	Nick Vanderkooi	Nov 03, 2023 04:06:11	. PM		
Work	Work Order Description	5	tatus		Туре	Date Created	Due Date	Date Completed	Davs Late	
80029	Head light lenses are effecting night time visibility	Closed, Completed			Nov 03, 20	23	Nov 03, 2023	,		
		•			06:06:02 A		04:05:59 PM			
_	Task Description	Asset		Assigned	l To	Completed By	Date Completed	Est Hour	s Spent Hou	
_		Articulated Ro	ock Truck	Christoph	er Paul	Nick Vanderkooi	Nov 03, 2023 04:05:59	РМ		
- Work	Work Order Description		tatus		Туре	Date Created	Due Date	Date Completed	Days Late	
80134	Transmission code, no reverse		losed, Co	mnleted	.,,,,	Nov 06, 20		•	Days Late	
		`	.103Cu, Co	mpicteu		07:56:34 A	Nov 07, 2023 05:16:43 AM			
7	Task Description	Asset		Assigned	To	Completed By	Date Completed	UD:10:45 AM Est Hour	s Spent Hou	
	06-11-23 Andy Boettger	Articulated Ro	ck Truck	Andy Boet		Andy Boettger	Date completed	£31 11001	s spent nour	
t	talked to operator over radio truck is apparently shifting fine for now nas all gears,	. <u>-</u>								
Work -	Work Order Description		tatus		Туре	Date Created	Due Date	Date Completed	Days Late	
80152	Won't start after shutting it down(running now)	C	Closed, Completed		Nov 06, 20	23	Nov 06, 2023	-		
			•			08:04:31 P	M	08:10:39 PM		
	Task Description	Asset		Assigned		Completed By	Date Completed	Est Hour	lours Spent Hou	
-	<u> </u>	Articulated Ro	ck Truck	Christophe	er Paul	Nick Vanderkooi	Nov 06, 2023 08:10:39	PM		
Work -	Work Order Description	S	tatus		Туре	Date Created	Due Date	Date Completed	Days Late	
80182		C	losed. Co	mpleted		Nov 07, 20		Nov 08, 2023	,	
		_				09:37:19 P		09:45:05 PM		
1	Task Description	Asset		Assigned	To	Completed By	Date Completed	Est Hour	Spent Hour	
_		Articulated Ro	ck Truck			Ian Knott	Nov 08, 2023 09:45:05	PM		
Work -	Work Order Description		tatus		Туре	Date Created	Due Date	Date Completed	Daws Lake	
80564	Wont start	-	losed, Cor	moleted	Corrective	Nov 18, 20		•	Days Late	
			iosea, coi	ilpieteo	Conective	03:14:11 P		Nov 18, 2023 04:05:53 PM		
1	Task Description	Asset		Assigned	To	Completed By	Date Completed	U4:U3:33 PM Est Hour	Spent Hour	
		Articulated Ro	ck Truck	Austin Hei		Menno Buhler	Nov 18, 2023 04:05:53		Spent Hour	
		A CICUIOCO NO								
- - Work	Work Order Description				Tyma	Data Caseta	Due Dete	Data Canadata	B	
- - Work 80681	Work Order Description	S	tatus		Туре	Date Created		Date Completed	Days Late	
80681	Front left rear duel tire low.	S		mpleted	Type Corrective	Date Created Nov 22, 20 05:47:38 A	23	Nov 22, 2023	Days Late	
80681 <u>1</u>	Front left rear duel tire low. Task Description	S	tatus	mpleted Assigned	Corrective	Nov 22, 202	23			
80681 <u>1</u>	Front left rear duel tire low.	Si	tatus Iosed, Cor		Corrective	Nov 22, 202 05:47:38 A	23 M	Nov 22, 2023 11:15:20 AM Est Hour		
80681 <u>1</u>	Front left rear duel tire low. Task Description	Si C Asset Articulated Ro	tatus Iosed, Cor	Assigned	Corrective	Nov 22, 202 05:47:38 A Completed By	23 M Date Completed Nov 22, 2023 11:15:20	Nov 22, 2023 11:15:20 AM Est Hour	Spent Hour	
80681	Front left rear duel tire low.  Fask Description Repaired #3 position	Asset Articulated Ro	tatus losed, Cor	<b>Assigned</b> Kal Tire	Corrective	Nov 22, 20: 05:47:38 Ai Completed By Kal Tire	23 M Date Completed Nov 22, 2023 11:15:20 Due Date	Nov 22, 2023 11:15:20 AM Est Hour		

Boost unit Driver turned off engine and left lights and ignition on Dec 5/23 Kristian Z /DS Articulated Rock Truck Articulated Rock Truck Nick Misener Kristian Zimmer

Nick Misener Kristian Zimmer Nov 29, 2023 01:54:04 PM Dec 05, 2023 05:18:00 PM 1.83

1.83 3.00

-Assisted Nick W in boosting the batteries
-After Rickys service, truck still has dead batteries. Weak batteries
-Got new batteries for unit and replaced the weak batteries with the new ones
-J bolts missing for hold down, so stole the two from unit 26 and placed then on unit

-PLaced all the cables back on and bolted back on step panel

		<del> </del>						1.83	4.
	Work Order Description	Status		Туре	Date Created		Date Completed		s Late
84	745C PM2 500 Service Hours	Closed, Co	ompleted	Preventive -		· · · · · ·	Dec 05, 2023	0	•
_		*	•	Planned	11:45:25 A		11:45:25 AM		
_	ask Description	Asset	Assigned	1 10	Completed By	Date Completed	EST	lours	Spent Ho
	ransmission Oil Filter - Inspect (Cut Filter and Record Findings.)	Articulated Rock Truck Articulated Rock Truck	PMtech <b>PMtech</b>						
	ransmission Oil Filter Replace								
	ransfer Gear Oil Sample - Obtain	Articulated Rock Truck	PMtech						
	orque Converter and Transmission Oil Sample - Obtain	Articulated Rock Truck	PMtech PMtech						
	reering System Oil Sample - Obtain	Articulated Rock Truck							
	econdary Steering - Test	Articulated Rock Truck	PMtech						
	oist System and Brake System Oil Sample - Obtain	Articulated Rock Truck	PMtech						
	uel System Secondary Filter - Replace	Articulated Rock Truck	PMtech						
	ngine Oil Filter Inspect (Cut Filter and Record Findings)	Articulated Rock Truck	PMtech						
	uel System Primary Filter - Replace	Articulated Rock Truck	PMtech						
	rake Accumulator (Service) - Check	Articulated Rock Truck	PMtech						
	ake Pads - Check	Articulated Rock Truck	PMtech						
	raking System - Test	Articulated Rock Truck	PMtech						
	iff & Final Drive Oil Level - Check (note particulates on mag plug and indicate	Articulated Rock Truck	PMtech						
	ndings) ifferential and Final Drive Oil Sample - Obtain	Articulated Rock Truck	PMtech .						
	ngine Air Filter Secondary Element (Outer) - Replace	Articulated Rock Truck	PMtech						
	ngine Oil and Filter - Change	Articulated Rock Truck	PMtech						
36	745C PM2 500 Service Hours	Closed, Co		Preventive -	Dec 05, 201	23 Dec 06, 2023			
_	1.5.			Planned	11:45:52 A		Dec 05, 2023 11:45:52 AM		
	ask Description	Asset	Assigned	l To	Completed By	Date Completed	11:45:52 AM Est F	lours	Spent Ho
Tri	ansmission Oil Filter - Inspect (Cut Filter and Record Findings.)	Articulated Rock Truck	PMtech	l To	Completed By PMtech	Dec 05, 2023 11:46:00 A	11:45:52 AM Est F	lours 2.00	Spent Ho
Tra Tra	ansmission Oil Filter - Inspect (Cut Filter and Record Findings.) ansmission Oil Filter Replace	Articulated Rock Truck Articulated Rock Truck	PMtech PMtech	l To	Completed By PMtech PMtech	Date Completed Dec 05, 2023 11:46:00 A Dec 05, 2023 11:46:00 A	11:45:52 AM Est F AM	2.00 2.00	Spent Ho
Tra Tra	ansmission Oil Filter - Inspect (Cut Filter and Record Findings.) ansmission Oil Filter Replace ansfer Gear Oil Sample - Obtain	Articulated Rock Truck Articulated Rock Truck Articulated Rock Truck	PMtech PMtech PMtech	l To	Completed By PMtech PMtech PMtech	Date Completed  Dec 05, 2023 11:46:00 A  Dec 05, 2023 11:46:00 A  Dec 05, 2023 11:46:00 A	11:45:52 AM Est H AM AM	2.00 2.00 2.00	Spent Ho
Tra Tra Tra To	ansmission Oil Filter - Inspect (Cut Filter and Record Findings.) ansmission Oil Filter Replace ansfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain	Articulated Rock Truck Articulated Rock Truck Articulated Rock Truck Articulated Rock Truck	PMtech PMtech PMtech PMtech	l To	PMtech PMtech PMtech PMtech PMtech PMtech PMtech	Date Completed  Dec 05, 2023 11:46:00 A	11:45:52 AM Est H AM AM AM AM	2.00 2.00 2.00 2.00 2.00	Spent Ho
Tra Tra Tra To Ste	ansmission Oil Filter - Inspect (Cut Filter and Record Findings.) ansmission Oil Filter Replace ansfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain reering System Oil Sample - Obtain	Articulated Rock Truck	PMtech PMtech PMtech PMtech PMtech	l To	Completed By PMtech PMtech PMtech	Date Completed  Dec 05, 2023 11:46:00 A  Dec 05, 2023 11:46:00 A  Dec 05, 2023 11:46:00 A	11:45:52 AM Est H AM AM AM AM	2.00 2.00 2.00	Spent Ho
Tra Tra Tra To Sta Se	ansmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransmission Oil Filter Replace ransfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain reering System Oil Sample - Obtain secondary Steering - Test	Articulated Rock Truck	PMtech PMtech PMtech PMtech PMtech PMtech	1 To	Completed By PMtech PMtech PMtech PMtech PMtech PMtech	Date Completed  Dec 05, 2023 11:46:00 A	11:45:52 AM Est H AM AM AM AM AM	2.00 2.00 2.00 2.00 2.00 2.00	Spent Ho
Tra Tra To Sta Se Ho	ansmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransmission Oil Filter Replace ransfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain reering System Oil Sample - Obtain secondary Steering - Test oist System and Brake System Oil Sample - Obtain	Articulated Rock Truck	PMtech PMtech PMtech PMtech PMtech PMtech PMtech	1 To	Completed By PMtech PMtech PMtech PMtech PMtech PMtech PMtech	Date Completed  Dec 05, 2023 11:46:00 A	11:45:52 AM Est H AM	2.00 2.00 2.00 2.00 2.00 2.00 2.00	Spent Ho
Tra Tra To Sto Se Ho Fu	ansmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransmission Oil Filter Replace ransfer Gear Oil Sample - Obtain receive Converter and Transmission Oil Sample - Obtain receive System Oil Sample - Obtain recondary Steering - Test oist System and Brake System Oil Sample - Obtain receive System Secondary Filter - Replace	Articulated Rock Truck	PMtech	1 To	Completed By PMtech PMtech PMtech PMtech PMtech PMtech	Date Completed  Dec 05, 2023 11:46:00 A	11:45:52 AM Est H AM	2.00 2.00 2.00 2.00 2.00 2.00	Spent Ho
Tra Tra To Sta See Ho Fu En	ansmission Oil Filter - Inspect (Cut Filter and Record Findings.) cansmission Oil Filter Replace cansfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain eeering System Oil Sample - Obtain econdary Steering - Test oist System and Brake System Oil Sample - Obtain uel System Secondary Filter - Replace ngine Oil Filter Inspect (Cut Filter and Record Findings)	Articulated Rock Truck	PMtech	l To	Completed By PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech	Date Completed  Dec 05, 2023 11:46:00 A	11:45:52 AM Est H AM AM AM AM AM AM	2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00	Spent Ho
Tra Tra To Ste Se Ho Fu En	ansmission Oil Filter - Inspect (Cut Filter and Record Findings.) cansmission Oil Filter Replace cansfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain eeering System Oil Sample - Obtain econdary Steering - Test oist System and Brake System Oil Sample - Obtain uel System Secondary Filter - Replace orgine Oil Filter Inspect (Cut Filter and Record Findings) orgine Oil and Filter - Change	Articulated Rock Truck	PMtech	1 To	Completed By PMtech	Date Completed  Dec 05, 2023 11:46:00 A	11:45:52 AM Est H AM AM AM AM AM AM AM	2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00	Spent Ho
Tra Tra To Sta Se Ho En En	ansmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransmission Oil Filter Replace ansfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain reering System Oil Sample - Obtain econdary Steering - Test oist System and Brake System Oil Sample - Obtain rel System Secondary Filter - Replace regine Oil Filter Inspect (Cut Filter and Record Findings) rigine Oil and Filter - Change rigine Air Filter Secondary Element (Outer) - Replace	Articulated Rock Truck	PMtech	1 To	Completed By PMtech	Date Completed  Dec 05, 2023 11:46:00 A	11:45:52 AM Est H  AM	2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00	Spent Ho
Tra Tra To Ste Se Ho En En	ansmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransmission Oil Filter Replace ransfer Gear Oil Sample - Obtain reque Converter and Transmission Oil Sample - Obtain reering System Oil Sample - Obtain recondary Steering - Test poist System and Brake System Oil Sample - Obtain rel System Secondary Filter - Replace rigine Oil Filter Inspect (Cut Filter and Record Findings) rigine Oil and Filter - Change rigine Air Filter Secondary Element (Outer) - Replace rigine Air Filter Secondary Element (Outer) - Replace	Articulated Rock Truck	PMtech	1 To	Completed By PMtech	Date Completed  Dec 05, 2023 11:46:00 A	11:45:52 AM Est H  AM	2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00	Spent Ho
Tra Tra To Ste Se Ho En En Diff	ansmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransmission Oil Filter Replace ansfer Gear Oil Sample - Obtain orque Converter and Transmission Oil Sample - Obtain reering System Oil Sample - Obtain econdary Steering - Test oist System and Brake System Oil Sample - Obtain uel System Secondary Filter - Replace gine Oil Filter Inspect (Cut Filter and Record Findings) rigine Oil and Filter - Change rigine Air Filter Secondary Element (Outer) - Replace fiferential and Final Drive Oil Sample - Obtain iff & Final Drive Oil Level - Check (note particulates on mag plug and indicate	Articulated Rock Truck	PMtech	1 To	Completed By PMtech	Date Completed  Dec 05, 2023 11:46:00 A	11:45:52 AM Est H  AM	2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00	Spent Ho
Tra Tra To Sta Se Ho En En Did fin Bra	ansmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransmission Oil Filter Replace ransfer Gear Oil Sample - Obtain reque Converter and Transmission Oil Sample - Obtain reering System Oil Sample - Obtain recondary Steering - Test pist System and Brake System Oil Sample - Obtain rel System Secondary Filter - Replace regine Oil Filter Inspect (Cut Filter and Record Findings) ragine Oil and Filter - Change righe Air Filter Secondary Element (Outer) - Replace righer Air Filter Secondary Element (Outer) - Replace righer Sinal Drive Oil Level - Check (note particulates on mag plug and indicate raking System - Test	Articulated Rock Truck	PMtech	1 To	Completed By PMtech	Date Completed  Dec 05, 2023 11:46:00 A	11:45:52 AM Est H  AM	2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00	Spent Ho
Tra Tra Tra Sta Se Ho En En Ditt Bri Bri	ansmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransmission Oil Filter Replace ransfer Gear Oil Sample - Obtain reque Converter and Transmission Oil Sample - Obtain reering System Oil Sample - Obtain recondary Steering - Test poist System and Brake System Oil Sample - Obtain rel System Secondary Filter - Replace regine Oil Filter Inspect (Cut Filter and Record Findings) regine Oil and Filter - Change regine Oil and Filter - Change regine Air Filter Secondary Element (Outer) - Replace referential and Final Drive Oil Sample - Obtain reff & Final Drive Oil Level - Check (note particulates on mag plug and indicate reaching System - Test rake Pads - Check	Articulated Rock Truck	PMtech	1 To	Completed By PMtech	Date Completed  Dec 05, 2023 11:46:00 A	11:45:52 AM Est H  AM	2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00	Spent Ho
Tra Tra Tra See Ho En En Ditt Bra Bra	ansmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransmission Oil Filter Replace ransfer Gear Oil Sample - Obtain reque Converter and Transmission Oil Sample - Obtain reque Converter and Transmission Oil Sample - Obtain requiper System Oil Sample - Obtain recondary Steering - Test resist System and Brake System Oil Sample - Obtain recondary Steering - Test resist System Secondary Filter - Replace regine Oil Filter Inspect (Cut Filter and Record Findings) regine Oil Filter Inspect (Cut Filter and Record Findings) regine Oil and Filter - Change regine Oil Filter Secondary Element (Outer) - Replace refferential and Final Drive Oil Sample - Obtain reff & Final Drive Oil Level - Check (note particulates on mag plug and indicate redings) raking System - Test rake Pads - Check rake Accumulator (Service) - Check	Articulated Rock Truck	PMtech	1 To	Completed By PMtech	Date Completed  Dec 05, 2023 11:46:00 A   11:45:52 AM Est H  AM	2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00	Spent Ho	
Tra Tra Tra See Ho En En Ditt Bra Bra	ansmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransmission Oil Filter Replace ransfer Gear Oil Sample - Obtain reque Converter and Transmission Oil Sample - Obtain reering System Oil Sample - Obtain recondary Steering - Test poist System and Brake System Oil Sample - Obtain rel System Secondary Filter - Replace regine Oil Filter Inspect (Cut Filter and Record Findings) regine Oil and Filter - Change regine Oil and Filter - Change regine Air Filter Secondary Element (Outer) - Replace referential and Final Drive Oil Sample - Obtain reff & Final Drive Oil Level - Check (note particulates on mag plug and indicate reaching System - Test rake Pads - Check	Articulated Rock Truck	PMtech	1 To	Completed By PMtech	Date Completed  Dec 05, 2023 11:46:00 A	11:45:52 AM Est H  AM	2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00	Spent Ho
Tra Tra Tra See Ho En En Diff Bra Bra	ansmission Oil Filter - Inspect (Cut Filter and Record Findings.) ransmission Oil Filter Replace ransfer Gear Oil Sample - Obtain reque Converter and Transmission Oil Sample - Obtain reque Converter and Transmission Oil Sample - Obtain requiper System Oil Sample - Obtain recondary Steering - Test resist System and Brake System Oil Sample - Obtain recondary Steering - Test resist System Secondary Filter - Replace regine Oil Filter Inspect (Cut Filter and Record Findings) regine Oil Filter Inspect (Cut Filter and Record Findings) regine Oil and Filter - Change regine Oil Filter Secondary Element (Outer) - Replace refferential and Final Drive Oil Sample - Obtain reff & Final Drive Oil Level - Check (note particulates on mag plug and indicate redings) raking System - Test rake Pads - Check rake Accumulator (Service) - Check	Articulated Rock Truck	PMtech	1 To	Completed By PMtech	Date Completed  Dec 05, 2023 11:46:00 A   11:45:52 AM Est H  AM	2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00	Spent Hc	

07:29:01 PM

44:15 PM

				07:29:01 PM		44:15 PM		
	Task Description	Asset	Assigned To	Completed By	Date Completed	Est Ho	urs	Spent Hours
		Articulated Rock Truck	Austin Heino	Menno Buhler	Dec 06, 2023 08:44:15	PM		
Vork	Work Order Description	Status	Туре	Date Created	Due Date	Date Completed	Day	rs Late
82057	Right rear tire leaking air.	Closed, Co	ompleted	Feb 24, 202 03:24:18 PM		Feb 24, 2024 04:58:47 PM		
	Task Description	Asset	Assigned To	Completed By	Date Completed	Est He	ours	Spent Hours
		Articulated Rock Truck	Kal Tire	Nick Vanderkooi	Feb 24, 2024 04:58:47	РМ		
Work	Work Order Description	Status	Туре	Date Created	Due Date	Date Completed	Day	s Late
82118	Dead battery wont start.	Closed, Co	ompleted	Feb 29, 202 08:20:07 AM		Feb 29, 2024 10:36:16 AM		
1	Task Description	Asset	Assigned To	Completed By	Date Completed	Est Ho	urs	Spent Hours
	Boosted	Articulated Rock Truck	Nick Vanderkooi	Nick Vanderkooi	Feb 29, 2024 10:36:16	AM		
Work	Work Order Description	Status	Туре	Date Created	Due Date	Date Completed	Day	s Late
_	Low tire air pressure on left middle.	Closed, Co	ompleted	May 31, 202 05:01:01 PM		May 31, 2024 05:01:01 PM		
	Task Description	Asset	Assigned To	Completed By	Date Completed	Est Ho	urs	Spent Hours
	Inflated tire to specs.	Articulated Rock Truck		Marvin Corpuz				1.00
								1.00
Work	Work Order Description	Status	Туре	Date Created	Due Date	Date Completed	Day	s Late
82984		Closed, Co	ompleted	Jun 01, 2024 05:06:24 PM		Jun 02, 2024 06:12:18 AM		
	Task Description	Asset	Assigned To	Completed By	Date Completed	Est Ho	urs	Spent Hours
	Cleaned cooling package and air filters.	Articulated Rock Truck	Austin Heino	Marvin Corpuz	Jun 02, 2024 06:12:18 A	.M		1.50
Work	Work Order Description	Status	Туре	Date Created	Due Date	Date Completed	Day	1,50 s Late
83003	Door won't lock	Closed, Co		jun 03, 2024 07:14:25 AM		Jun 03, 2024 04:02:13 PM	Jun 03, 2024	
	Task Description	Asset	Assigned To	Completed By	Date Completed	Est Ho	urs	Spent Hours
	Removed and straightened door striker bar and guard.	Articulated Rock Truck		Marvin Corpuz	Jun 03, 2024 04:02:13 P	M		1.00
								1.00
Work	Work Order Description	Status	Туре	Date Created	Due Date	Date Completed	Day	s Late
83006	Hydraulic leak	Closed, Co	ompleted	Jun 03, 2024 04:34:38 PM		Jun 04, 2024 05:25:47 PM		
	Task Description	Asset	Assigned To	Completed By	Date Completed	Est Ho	urs	Spent Hours
	Loose breather at the hydraulic tank. Refilled hydraulic tank, drained brake cooling o tank. Possible oil transferring, oil level was mark for monitoring.	il Articulated Rock Truck	Austin Heino	Marvin Corpuz	Jun 04, 2024 05:25:47 P	M		2.00
	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -							2.00
<b>Work</b> 83019	Work Order Description Break issue **not repairing	Status Closed, Co	Type ompleted	Date Created Jun 05, 2024	Due Date	Date Completed Jun 19, 2024	Day	s Late
				02:52:18 PM		11:50:16 AM		
	Task Description  Refilled hydraulic tank and drained brake cooling oil again and performed service	Articulated Rock Truck	Assigned To	Completed By	Date Completed	Est Ho		Spent Hours
	brake leak test, found left center brake hub causing the issue which was very bad leak.	Articulated Rock Truck					3.00	
	CHRIS WISEMAN JUNE 13/2024 -SET UP TRUCK DRAINED OIL -REMOVED L/S CENTRE HUB AND DISSEMBLED	Articulated Rock Truck						11.50
	CHRIS WISEMAN JUNE 14/2024 -FINISH DISSEMBLE , REMOVED BEARINGS TOOK TO UNDERGROUNG AND WASHED -CLEANED UP AND GATHERED UP PARTS	Articulated Rock Truck						10.50
	CHRIS WISEMAN JUNE 15/2024 -INSTALL BEARINGS	Articulated Rock Truck						2.00
	-INSTALL BEARINGS CHRIS WISEMAN JUNE 17/2024	Articulated Rock Truck						1.00

-START REASSEMBLY OF HUB TO MAKE IT A ROLLER CHRIS WISEMAN JUNE18/2024
-ASSEMBLE HUB
-ASSEMBLE FINAL DRIVE
CHRIS WISEMAN JUNE 19/2024
-FINISH ASSEMBLY AND INSTALL
-FILL BRAKE COOLING TANK AND DIFF
CHRIS WISEMAN JUNE 21/2024
-INSTALLED WHEEL
-INSTALLED WHEEL
-INSTALLED SIDE AXLE
-FILLED FINAL AND TOPPED UP BRAKE OIL
-TOOK TRUCK UP TO CRUSHER LINE AND LOCKED OUT

Articulated Rock Truck

Articulated Rock Truck

8.00

Articulated Rock Truck

Articulated Rock Truck

Articulated Rock Truck

5.00

2.00

3.00 40.00 Work **Work Order Description** Status Type Date Created **Due Date Date Completed** Days Late 83140 Degreasing Closed, Completed Preventive -Jun 16, 2024 Jun 17, 2024 Jun 16, 2024 o Planned 05:02:55 AM 05:02:55 AM 02:04:23 PM **Task Description** Asset Assigned To **Completed By Date Completed** Est Hours Spent Hours Articulated Rock Truck PMtech Degreassing Articulated Rock Truck Work **Work Order Description** Status **Date Created** Type **Due Date Date Completed** Days Late 83380 Degreasing Closed, Completed Preventive -Jul 07, 2024 Iul 08, 2024 Jul 13, 2024 5 Planned 05:02:50 AM 05:02:50 AM 01:55:58 PM **Task Description** Asset **Assigned To** Completed By Date Completed Est Hours Spent Hours

PMtech

213.50 320.33

Degreassing