



## Work Order Details

This report was run on: Nov 24, 2024 02:43:52 PM  
 with the following parameters  
 Opened After: Nov 24, 2022 02:38:00 PM  
 Opened Before: Nov 24, 2024 02:38:00 PM  
 Parent Asset: "Articulated Rock Truck (19-45-024)"  
 Asset Category: "All"  
 Assigned User: "All"  
 Maintenance Type: "All"  
 Priority: "All"  
 Status: "All"

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
62791	Wiper blade needs replacing	Closed, Completed	Corrective	Dec 05, 2022 05:55:29 AM		Dec 05, 2022 10:50:05 AM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
Replaced broken wiper		Articulated Rock Truck	Thomas Ragan	Thomas Ragan	Dec 05, 2022 10:50:05 AM	1.00	
		1.00					
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
62827	Front right strut	Closed, Completed	Corrective	Dec 05, 2022 09:23:42 PM		Dec 06, 2022 09:38:51 AM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
Dec 5/22 Kristian Z /NS		Articulated Rock Truck	Kristian Zimmer	Kristian Zimmer	Dec 05, 2022 11:00:00 PM		3.00
-Front drivers and pass side struts are low -Filled both struts and leveled to 27 in from top and bottom bolts -Drivers bottom strut bolt is loose. Retightened bottom bolt							
Dec 5/22 Chris P /NS		Articulated Rock Truck	Christopher Paul	Christopher Paul	Dec 05, 2022 11:00:00 PM		3.00
-Front drivers and pass side struts are low -Filled both struts and leveled to 27 in from top and bottom bolts -Drivers bottom strut bolt is loose. Retightened bottom bolt							
		6.00					
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
62920	No interior light, passenger side mirror broken	Closed, Completed	Corrective	Dec 07, 2022 12:11:05 AM		Dec 07, 2022 09:52:44 AM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
12/07/2022 JOSHUA R.		Articulated Rock Truck	Joshua Ravelo	Nick Vanderkooi	Dec 07, 2022 09:52:44 AM		
- ORDERED AND INSTALLED NEW MIRRORS		Articulated Rock Truck		Joshua Ravelo	Dec 07, 2022 05:09:00 PM		2.00
- WENT TO BONE YARD TO PICK UP LIGHTS AND INSTALLED ONTO UNIT							
		2.00					
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
62923	Box float not working. Truck in limp mode	Closed, Completed	Corrective	Dec 07, 2022 03:25:23 AM		Dec 07, 2022 09:54:33 AM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
12/07/2022 JOSHUA R.		Articulated Rock Truck	Joshua Ravelo	Nick Vanderkooi	Dec 07, 2022 09:54:33 AM		
- INSTALLED NEW FLOAT SENSOR		Articulated Rock Truck		Joshua Ravelo	Dec 07, 2022 05:08:00 PM		2.00
- STRAIGHTENED BRACKET							
- DROVE AROUND TO CHECKED IF UNIT THROUGH ALL GEARS - GOOD							
Mark Milne Dec 6 2022		Articulated Rock Truck	Mark Milne	Mark Milne	Dec 06, 2022 06:31:00 PM		2.50

Night shift  
Bring machine down to shop  
Do diagnostic work to identify codes

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
63018	All 4 rear tires are in very rough shape. Lots of cracks and quite bald	Closed, Completed	Corrective	Dec 08, 2022 10:49:31 AM		Dec 09, 2022 09:42:01 PM		4.50
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
DONE	Articulated Rock Truck	Kal Tire	Nick Vanderkooi	Dec 09, 2022 09:42:01 PM				
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
63026	Truck is binding and popping when transitioning from hill to flat. Rear A-frame bearing shot	Closed, Completed	Corrective	Dec 08, 2022 12:47:29 PM		Dec 23, 2022 09:32:33 PM		
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
Mark Milne Dec 9 2022 Night shift Road test machine See what pin is worn. Rear a frame pin needs replaced 17/12/22 claude white checked for coolant leak rear A frame 18/12/22 claude white inspected rear A frame pin and bushing transmission clutch calibration inertialsensor calibration Intall pin in center check grease lines install new bolts and nuts install drive line secure hose clamps top up coolant check for leaks could not find any leaks Dec 18/22 Kristian Z /NS	Articulated Rock Truck Articulated Rock Truck	Mark Milne Mark Milne	Mark Milne	Dec 09, 2022 04:54:00 AM		3.00		
	Articulated Rock Truck		Claude White	Dec 17, 2022 05:19:00 PM		6.00		
	Articulated Rock Truck		Claude White	Dec 18, 2022 05:22:00 PM		6.00		
	Articulated Rock Truck	Christopher Paul	Christopher Paul	Dec 17, 2022 06:09:00 PM	40.00	4.00		
	Articulated Rock Truck	Kristian Zimmer	Kristian Zimmer	Dec 18, 2022 11:00:00 PM		11.50		
-Removed driveshaft to get enough clearance to drop the front end of the A frame -Couldn't hammer pin out, so we cut the pin in half to get it out -Cleaned out bores on the bracket and front end of A Frame -Lifted A Frame back up an lined up to place in mounting pin -Got pin in, but cannot go all the way through. Jammed half way threw the second stage  Note: Must get Precision North (Paul) to push the pin all the way threw.  Dec 18/22 Chris P /NS								
	Articulated Rock Truck	Christopher Paul	Christopher Paul	Dec 18, 2022 11:00:00 PM		11.50		
-Removed driveshaft to get enough clearance to drop the front end of the A frame -Couldn't hammer pin out, so we cut the pin in half to get it out -Cleaned out bores on the bracket and front end of A Frame -Lifted A Frame back up an lined up to place in mounting pin -Got pin in, but cannot go all the way through. Jammed half way threw the second stage  Note: Must get Precision North (Paul) to push the pin all the way threw.  dec 22 2022 tyler penkoff								
	Articulated Rock Truck		Tyler Penkoff	Dec 22, 2022 06:03:00 AM		5.00		
finished up job by installing drive lie and torquing to specks. checked fluids and greased. 22 Dec 2022 - Gabe Elnamer -Check over, check all fluids -Repair shop air grease pump -Grease unit -Finish installing rear driveshaft/torque to spec.	Articulated Rock Truck	Gabe Elnamer	Gabe Elnamer	Dec 22, 2022 02:00:00 PM		6.00		
							40.00	53.00
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
63977	Low beam out	Closed, Completed	Corrective	Dec 27, 2022 07:00:40 PM		Dec 27, 2022 10:53:30 PM		

Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
Changed light		Articulated Rock Truck	Thomas Ragan	Thomas Ragan	Dec 27, 2022 10:53:30 PM	1.00	
							1.00
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
64005	Small coolant leak right side engine	Closed, Completed	Corrective	Dec 28, 2022 03:27:49 PM		Dec 29, 2022 01:13:54 AM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
Dec 28 2022NS Drove out to unit. Found machine. Checked. Coolant lvl it was low found a few drops of coolant. Leaking form the. Engine belly pan started unit amd lifted hood did not find a leak coming from the top of the engine drove unit down to the. Shop pulled it into a bay. Dropped the belly pan found leak to be. Coming from damage hose clamp replaced re topped up coolnat and re tested hose is not leaking found that both stater were cover in oil wiped off and re checked for. Leaks they look to be not leaking could of bin from the. Cold snap caused them to weap. Should be.		Articulated Rock Truck	Jay Dhillon	Jay Dhillon	Dec 29, 2022 01:13:54 AM	3.00	
							3.00
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
64020	Leaking right lift cylinder	Closed, Completed	Corrective	Dec 29, 2022 01:38:02 AM		Dec 31, 2022 03:27:50 PM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
Dec 31/22 -Ross W-SMS Attended morning safety meeting, complete all safety documents. Travel to machine location at truck laydown, perform a walk around of machine, check and confirm all fluid levels, start machine. Waited for machine to get to operating temperatures, got PRHP labourer to drive machine to maintenance shop, drove machine into shop, pulled service truck in behind machine. Staged work area and tools, LOTO. Opened hydraulic tank cap to relieve pressure from tank. Wrapped a sling close to the box end of the cylinder, used crane to support cylinder, removed pin retainer, removed pin. Safely lowered and swung cylinder out of the way of the machine, repositioned strap on cylinder so it would lift evenly. Removed hydraulic lines, plugged and capped as necessary. Got a 911 call to go to a different machine, cleaned work area and tools. Returned to machine, staged work area and tools. Lifted cylinder with crane, removed from end of the cylinder, lowered cylinder gently onto blocking. Locate rebuilt cylinders outside of maintenance shop, used skid steer to grab and drop new cylinder off behind rock truck in the shop. Picked cylinder up with crane, installed frame end of the cylinder first, confirm bolts are tight. Install hydraulic hoses ensuring to replace o-rings. Used crane to lift cylinder and place on the tire of the machine, held cylinder up with a strap. Acquired cherry picker and wheeled it across the shop. Used cherry picker to lift cylinder into place, bores would not line up as cylinder was slightly extended, Backed hoses off until rod end of the cylinder started to retract. Installed box end pin. Greased both pins and bushings. Start truck and park in the downline. Confirm work complete, clean work area and tools, complete paperwork.		Articulated Rock Truck	Ross Wiley - SMS	Ross Wiley - SMS	Dec 31, 2022 03:27:50 PM		7.50

								7.50
Work 64107	Work Order Description Sounds like an air line is leaking somewhere. As you give it fuel a high pitch air suction sound.	Status Closed, Completed	Type Corrective	Date Created Dec 31, 2022 08:00:04 PM	Due Date	Date Completed Dec 31, 2022 10:14:23 PM	Days Late	
Task Description Dec 31 2022 NS Drove out to unit found machine tested machine found there was a air leak found that there was a loose air to air clamp re tited and check the. Rest were good. Let operator test machine no more issue		Asset Articulated Rock Truck	Assigned To Jay Dhillon	Completed By Jay Dhillon	Date Completed Dec 31, 2022 10:14:23 PM	Est Hours 1.50	Spent Hours	
								1.50
Work 64134	Work Order Description Hood lift actuator is leaking oil	Status Closed, Completed	Type Corrective	Date Created Jan 01, 2023 06:56:49 PM	Due Date	Date Completed Jan 15, 2023 04:46:00 AM	Days Late	
Task Description ordered hood actuator Jan 1/23		Asset Articulated Rock Truck	Assigned To Tyler Penkoff	Completed By Daniel Reid	Date Completed Jan 15, 2023 04:46:00 AM	Est Hours	Spent Hours	
Work 64173	Work Order Description Truck smells of coolant. No visible leak	Status Closed, Completed	Type Corrective	Date Created Jan 02, 2023 09:11:37 PM	Due Date	Date Completed Jan 03, 2023 07:51:00 AM	Days Late	
Task Description Ask operator to drive unit and report back He did not smell coolant		Asset Articulated Rock Truck	Assigned To Nick Misener	Completed By Nick Misener	Date Completed Jan 03, 2023 07:50:53 AM	Est Hours 1.00	Spent Hours	1.00
								1.00
Work 64177	Work Order Description Truck temp gauge keeps climbing. Truck no longer has coolant in the sight glass. Operator can smell coolant burning. No visible leaks.	Status Closed, Completed	Type Corrective	Date Created Jan 02, 2023 11:03:21 PM	Due Date	Date Completed Jan 14, 2023 08:29:00 PM	Days Late	
Task Description		Asset Articulated Rock Truck	Assigned To Tyler Penkoff	Completed By Daniel Reid	Date Completed Jan 14, 2023 08:29:00 PM	Est Hours	Spent Hours	
Work 64180	Work Order Description Liding Access hatch open under the truck	Status Closed, Completed	Type Corrective	Date Created Jan 03, 2023 02:51:37 AM	Due Date	Date Completed Jan 03, 2023 04:07:00 AM	Days Late	
Task Description		Asset Articulated Rock Truck	Assigned To Joshua Ravelo	Completed By Daniel Reid	Date Completed Jan 03, 2023 04:07:00 AM	Est Hours	Spent Hours	
Work 64525	Work Order Description 745C PM2 500 Service Hours JOHN LEGGE	Status Closed, Completed	Type Preventive - Planned	Date Created Jan 09, 2023 11:45:22 AM	Due Date Jan 14, 2023 11:45:00 AM	Date Completed Jan 14, 2023 02:35:03 PM	Days Late 0	
Task Description Brake Accumulator (Service) - Check Brake Pads - Check Braking System - Test Diff & Final Drive Oil Level - Check (note particulates on mag plug and indicate findings) Differential and Final Drive Oil Sample - Obtain Engine Air Filter Secondary Element (Outer) - Replace Engine Oil and Filter - Change Engine Oil Filter Inspect (Cut Filter and Record Findings) Fuel System Primary Filter - Replace Fuel System Secondary Filter - Replace Hoist System and Brake System Oil Sample - Obtain Secondary Steering - Test Steering System Oil Sample - Obtain Torque Converter and Transmission Oil Sample - Obtain Transfer Gear Oil Sample - Obtain Transmission Oil Filter Replace		Asset Articulated Rock Truck Articulated Rock Truck Articulated Rock Truck Articulated Rock Truck Articulated Rock Truck Articulated Rock Truck Articulated Rock Truck Articulated Rock Truck Articulated Rock Truck Articulated Rock Truck Articulated Rock Truck Articulated Rock Truck Articulated Rock Truck Articulated Rock Truck Articulated Rock Truck	Assigned To PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech	Completed By PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech PMtech	Date Completed Jan 14, 2023 02:34:00 PM Jan 14, 2023 02:34:00 PM Jan 14, 2023 02:34:00 PM Jan 14, 2023 02:34:00 PM Jan 14, 2023 02:34:00 PM Jan 14, 2023 02:34:00 PM Jan 14, 2023 02:34:00 PM Jan 14, 2023 02:34:00 PM Jan 14, 2023 02:34:00 PM Jan 14, 2023 02:34:00 PM Jan 14, 2023 02:34:00 PM Jan 14, 2023 02:34:00 PM Jan 14, 2023 02:34:00 PM Jan 14, 2023 02:34:00 PM Jan 14, 2023 02:34:00 PM	Est Hours	Spent Hours 4.00	

Transmission Oil Filter - Inspect (Cut Filter and Record Findings.)

Articulated Rock Truck

PMtech

PMtech

Jan 14, 2023 02:34:00 PM

4.00

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
64575	Loud grinding sound under hood. Nothing looks wrong when checked under the hood but sounds like something in/with the motor.	Closed, Completed	Corrective	Jan 10, 2023 04:47:23 PM		Jan 11, 2023 04:40:00 AM	
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
10 Jan 23-Tony.B-NS-  Inspected unit, Started unit and heard turbo noise, Checked and found exhaust pipe off at turbo, Tightened clamp, Filled engine and HYD oil, Parked at truck laydown,	Articulated Rock Truck	Anthony Balint	Daniel Reid	Jan 11, 2023 04:40:00 AM		2.50	

2.50

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
64682	Throwing codes	Closed, Completed	Corrective	Jan 13, 2023 01:41:52 AM		Jan 13, 2023 01:58:04 AM	
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
13 JAN 2023 - RANDY - NS CONNECT TO ET, E1410(2) ACTIVE FOR SCR EFFICIENCY, NO RELATED CODES, CHECK NOX SENSOR ORIENTATION, INSPECT DEF TANK LEVEL, FULL, READS FULL IN ET, NO EXTERNAL LEAKS IN SYSTEM, DEF PRESS TEST, PERFORM AFT FUNCTIONAL TEST, PASSED THE TEST AND CODE WENT AWAY, REGEN, GOOD, NO CODES RETURNED	Articulated Rock Truck	Randy Klatt	Randy Klatt	Jan 13, 2023 02:00:00 AM		4.00	

4.00

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
64735	Engine codes and audible alarm	Closed, Completed	Corrective	Jan 14, 2023 12:19:51 AM		Jan 15, 2023 09:47:03 AM	
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
14 JAN 2023 - RANDY - NS SCR EFFICIENCY AND INDUCEMENT CODES AFT FUNCT TEST FAILS NOX SENSORS ORIENTED PROPERLY REMOVE DEF CAP SCREEN, FILLED WITH MUD REMOVE DEF HEADER DEF TANK CONTAMINATED, BOTH FILTERS DIRTY NEEDS DEF FLUSH jan 14 2023 tyler penkoff	Articulated Rock Truck	Tyler Penkoff	Randy Klatt	Jan 15, 2023 04:00:00 AM		3.00	
changed sock and def filter, changed hood accumulator.	Articulated Rock Truck		Tyler Penkoff	Jan 14, 2023 05:22:00 AM		8.00	
Jan 15 2023 Ken C /DS  Preformed aftertreatment function test, cleared up codes  Found soot load was 50% so I did a manual burn	Articulated Rock Truck	Ken Cannon	Ken Cannon	Jan 15, 2023 07:52:00 AM		3.00	

14.00

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
64843	Throwing codes again	Closed, Completed	Corrective	Jan 15, 2023 11:43:09 PM		Jan 16, 2023 12:56:34 PM	
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
16 JAN 2023 - RANDY - NS INFORMED IT PASSED REGEN, FAILED NOX TEST DUE TO ACTIVE CODES UNABLE TO CLEAR CHECK PARAMETERS FOR QUALITY SENSOR NO EXTERNAL LEAKS REMOVE DEF DOSER DEF PRESSURE TEST - NO LEAK AT TIP DEF ACCURACY TEST 3 TIMES, BETWEEN 110 AND 120ML EACH TIME, DEF SYSTEM FUNCTIONING PROPERLY DEF CONCENTRATION IN SPEC, FILTERS AND DEF CHANGED YESTERDAY RECOMMEND REPLACE NOX SENSORS	Articulated Rock Truck	Tyler Penkoff	Randy Klatt	Jan 16, 2023 04:00:00 AM		4.00	

01.16.2023 JOSHUA R.  
 - CONFIRMED THAT ISSUE WAS A NOx SENSOR  
 CODE: E1410 - NOx CONVERSION LOW  
 - REPLACED BOTH INLET AND OUTLET SENSORS  
 - RAN AFTER TREATMENT TEST = PASSED AND CLEARED CODES  
 - RAN NOx SENSOR TEST TO CONFIRM REPAIRS = PASSED  
 - RAN FORCED REGEN. = COMPLETE  
 - REPLACE 2 CLAMPS ON COOLANT LINES THE WERE LEAKING

Articulated Rock Truck

Joshua Ravelo

Jan 16, 2023 01:48:00 PM

4.00

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
64911	Exhaust fumes in cab  Strange clicking noise in the cab	Closed, Completed	Corrective	Jan 17, 2023 09:17:28 AM		Jan 17, 2023 02:08:50 PM		8.00
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
Ran unit. Inspected exhaust system. Found the turbo outlet clamp was not installed right so the pipe was together all of the way. Removed clamp and fixed the pipe. Ran unit and rechecked that area.	Articulated Rock Truck	Thomas Ragan	Thomas Ragan	Jan 17, 2023 02:08:50 PM	2.50			
Did not hear a clipping nosie in the cab								2.50
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
65210	Oil temp, Trans temp gouges keep rising getting close to red. Truck is running hot for some reasn?	Closed, Completed	Corrective	Jan 23, 2023 11:19:21 AM		Feb 02, 2023 04:19:04 AM		
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
	Articulated Rock Truck	Joshua Ravelo	Nick Vanderkooi	Feb 02, 2023 04:19:04 AM				
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
65409	Slash in front passenger tire	Closed, Completed	Corrective	Jan 26, 2023 03:43:19 PM		Jan 28, 2023 06:25:00 AM		
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
New tires on front.	Articulated Rock Truck	Kal Tire	Kal Tire	Jan 28, 2023 06:25:00 AM				2.00
								2.00
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
65489	745 24. Signal and retarder very loose syeering collumn is falling apart. Box light out. Sticks in 3rd gear.	Closed, Completed	Corrective	Jan 28, 2023 09:20:20 AM		Jan 29, 2023 07:46:40 PM		
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
Replace missing bolt on steering column	Articulated Rock Truck	Nick Misener	Nick Misener	Jan 29, 2023 07:46:35 PM	1.83			1.83
					1.83			1.83
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
65635	Needs new wiper blade	Closed, Completed	Corrective	Jan 31, 2023 07:25:45 AM		Jan 31, 2023 10:25:00 AM		
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
Jan 31 2023 tyler penkoff	Articulated Rock Truck	Tyler Penkoff	Daniel Reid	Jan 31, 2023 10:25:00 AM				1.00
wiper changed operation good.								
								1.00
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
65720	Driver complaining about his eyes burning when the air in cab is on, possible exhaust leak/fumes getting into cab.	Closed, Completed	Corrective	Feb 01, 2023 07:36:30 PM		Feb 19, 2023 10:59:19 AM		
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
02.02.23 JOSHUA R. - RAN UNIT AND CONFIRMED EXHAUST LEAK - UNIT RAN A REGEN. AND CAB WAS SMELLING LIKE EXHAUST	Articulated Rock Truck Articulated Rock Truck	Joshua Ravelo	Joshua Ravelo	Feb 02, 2023 04:24:00 AM				2.00

- BROUGHT INTO SHOP AND OPENED HOOD FOR INSPECTION
- FOUND EXHAUST MANIFOLD GASKETS HAVE FAILED
- HEAT SHIELD AND SURROUNDING PARTS OF THE MANIFOLD ARE COVERED IN SOOT
- ORDERED NEW MANIFOLD GASKETS AND TURBO GASKET

18 Feb 2023-Diego Z Articulated Rock Truck Diego Zamora Diego Zamora Feb 19, 2023 05:04:00 AM 12.00

- reinstalled all components, with new hardware , seals and gaskets where necessary
- all hardware torqued to spec
- filled coolant and bled system
- unit just needs check over and grease

Feb 19/23 Kristian Z /DS Articulated Rock Truck Kristian Zimmer Kristian Zimmer Feb 19, 2023 10:23:00 AM 5.00

- Placed the right side panel on and the rest of the brackets for the hoses
- Greased all fittings
- Checked the all the lights. The right signal and back work light are burnt out. Replaced them with new light bulbs
- Checked all fluids. Engine oil, transmission oil and coolant need to be topped up a bit
- Washed engine bay to clean the rest of the soot and the spilled coolant.
- Test the truck to smell and see if there's any exhaust leak. No more leaks :)

Note: Front windshield should get replaced. There's a crack obstructing driver's view  
Feb 18/23 Kristian Z /DS Articulated Rock Truck Kristian Zimmer Kristian Zimmer Feb 18, 2023 05:00:00 PM 11.50

- Drained coolant to pull out coolant hoses and coolant regulator to get to manifold
- Replaced the exhaust manifold with a new one with new gaskets.
- Placed on manifold studs and torqued them to 28 ft lbs

30.50

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
66564	Exhaust caught fire. Driver put it out with water bottles.	Closed, Completed	Corrective	Feb 20, 2023 02:39:35 AM		Feb 20, 2023 11:05:00 PM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
found rag on top of exhaust pipe coming from catalyst assembly. Removed rag and did a manual return. In this time i checked for any exhaust leaks and fires. This took about 3/4 of a hour. All is good		Articulated Rock Truck	Daniel Reid	Daniel Reid	Feb 20, 2023 11:05:00 PM		
20/02/23 claude white topped up radiator		Articulated Rock Truck		Claude White	Feb 20, 2023 02:48:00 AM		1.00

1.00

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
66635	Coolant leak/	Closed, Completed	Corrective	Feb 21, 2023 07:29:37 AM		Feb 23, 2023 12:51:00 AM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
Add to jugs of coolant. Started unit out side and let warm up. There is two spots were the coolant seems to be leaking from. Pulled unit in to the shop and pulled both inspection covers. Seems like the heater lines are the first possible leak. There is no shut off on the block so i had to drain the coolant. Lifted the cab and the zip ties. Removed the hose clamps and removed the lines. Installed new lines. Zipped tied the lines back in to place. Filled the coolant back up. Cooling system needs to be bled ran and topped up. Unit needs to have the cab repinned. Ran to op temp and check for leaks		Articulated Rock Truck	Thomas Ragan			10.00	
22/02/23 claude white bled cooling system topped coolant put outside and ran for a hour and checked for leaks kept dripping coolant unsure if its residual or an actual leak brought back in shop dropped skid pan ran truck checked for leaks,none to be found replaced skid pan repin the cab put covers back on		Articulated Rock Truck		Claude White	Feb 22, 2023 11:45:00 PM		6.00

10.00 6.00

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
66739	Coolant leak	Closed, Completed	Corrective	Feb 23, 2023 06:40:52 AM		Mar 14, 2023 04:59:16 AM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours

02-26-23- REY C.	Articulated Rock Truck	Rey Contreras	Rey Contreras	Feb 26, 2023 04:22:00 PM	7.00
REMOVED AND INSTALLED BELLY PAN					
REMOVED THE COVER OF AC/BOX I DISCOVERED THE HEATER CORE IS LEAKING					
PARKING THE MACHINE TO DOWN LINE TO WAITING PARTS.					
NOTE: OEDERED HEATER CORE AND OTHERS PARTS.					
Mar 13 2023- Thomas Ragan	Articulated Rock Truck				11.50
Brought unit in to the shop. Removed the side cover. evac the ac system. removed the heater lines. unhooked the harness from the ac box. unbolted the ac box and removed from unit. split box. removed the heater core. installed water vavle on new core. installed new core. reinstalled ac box. installed all removed parts. topped up coolant. charged ac system. ran unit and checked for leaks.					
14 March 2023 - Sebastain C -	Articulated Rock Truck	Sebastian Cepeda - Brandt	Sebastian Cepeda - Brandt	Mar 14, 2023 01:11:00 PM	3.25
"CHECKED PRESSURES ON ALL 5 BRAKE ACCUMUALTORS AND RE CHARGED					
INSTALLED GUARD ON SIDE OF CAB					
VERIFIED COOLING SYSTEM HAD BEEN PROPERLY BLED "					
14 March 2023 - Trevor I -	Articulated Rock Truck	Trevor Irwin - Brandt	Trevor Irwin - Brandt	Mar 14, 2023 01:18:00 PM	4.00
CHECK/TEST/CHARGE BRAKE ACCUMULATORS. INSTALL GAURDS, CHECK CLEAR CODES. PARK UNIT IN UP LINE.					

25.75

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
66858	Requires Degreasing	Closed, Completed	Corrective	Feb 25, 2023 09:43:31 AM		Feb 25, 2023 11:35:38 AM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
Requires Degreasing		Articulated Rock Truck	Grease Task Force	Grease Task Force	Feb 25, 2023 11:35:32 AM	0.00	0.00
						0.00	0.00

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
68005	Smells like burnt heater core. Windows also keep fogging up.	Closed, Completed	Corrective	Mar 19, 2023 07:44:15 PM		Mar 20, 2023 01:51:54 AM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
Cab was fogged up. Started unit. Closed the back window. Window defogged as the unit warm. Redirected the front vents to point more at the front window. No smell Was detected		Articulated Rock Truck	Thomas Ragan	Thomas Ragan	Mar 20, 2023 01:51:54 AM	1.50	
						1.50	

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
68173	Truck is having coolant issues.	Closed, Incomplete	Corrective	Mar 22, 2023 11:11:21 PM		Apr 01, 2023 05:24:59 PM	
Driver reported hissing air noise coming from coolant cap. Cab kept fogging up with coolant film.							
Low coolant alarm came on and then went away							
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
Looks like the heater core is leaking. Checked the heater line to core. Cut the ends off the hoses and replace the hose clamps. Oedered a new core		Articulated Rock Truck	Thomas Ragan	Timothy Zeluf	Apr 01, 2023 05:24:59 PM	1.00	
						1.00	

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
68228	Missing bolt from top of lift cylinder pin	Closed, Completed	Corrective	Mar 24, 2023 06:53:19 AM		Mar 24, 2023 03:03:32 PM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
March 24/23 -Sebastian C-Brandt		Articulated Rock Truck	Sebastian Cepeda - Brandt	Ian Knott	Mar 24, 2023 03:03:32 PM		
		Articulated Rock Truck	Sebastian Cepeda - Brandt	Sebastian Cepeda - Brandt	Mar 24, 2023 08:05:00 AM		4.00
"INSPECTED UNIT AND FOUND CYLINDER PIN ON LEFT SIDE WALKED OUT REMOVED PIN (PIN WAS HARD TO REMOVE AS IT WAS MUSHROOMED DROPPED CYLINDER AND CLEANED OUT BORES							
CLEANED OUT PIN AND VERIFIED GREASE WAS ABLE TO FLOW THROUGH							
GRINDED OUT INNER EAR AS IT HAD MUSHROOMED FROM PIN							
TAPPED OUT THREADS FOR RETAINER							
INSTALLED PIN BACK IN WITH NEW BOLT							
GREASED PIN AND BEARING							



CHECKED CYLINDER PINS ON 19-45-18 , RIGHT SIDE WAS STRIPPED  
 REMOVED BOLT AND INSTALELD LONGER BOLT WITH NUT ON THE BACK  
 APPLIED GREEN LOCTITE TO PREVENT NUT FROM COMING OFF  
 CHECKED CYLINDER PINS ON 19-45-31, BOTH WERE TIGHT  
 REMOVED EDGES ON GRADER 18-14-003 AND CLEANED SURFACE"

Work 68319	Work Order Description Heater core failed	Status Closed, Completed	Type Corrective	Date Created Mar 25, 2023 07:42:14 PM	Due Date	Date Completed Apr 08, 2023 11:00:53 AM	Days Late	4.00
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
07 APRIL 2023 Austin H -Drained coolant -Evacuated A/C -Removed R/H panel -Removed cooling lines and electrical connectors -Removed A/C box -Disassembled box and removed leaking heater core -Installed new core and installed A/C box -Installed all lines and connectors -Filled coolant and charged A/C -Bled cooling system and test drove unit. Checked for leaks, heater core is good but unit now has an intermittent brake fault code and hydraulic leak on steering line		Articulated Rock Truck	Austin Heino	Austin Heino				8.00
Work 69775	Work Order Description No AC in the truck. Heater vakve is all the way closed.	Status Closed, Completed	Type Corrective	Date Created Apr 18, 2023 09:00:27 AM	Due Date	Date Completed Apr 18, 2023 01:35:00 PM	Days Late	8.00
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
April 18/23 -Matt D-Wajax  wait at shop for truck, bring into shop, recover system found low, hook up nitrogen pressure test system held pressure for 30min, get new reciver dryer replace, pull vacuum on system charge system passed.		Articulated Rock Truck	Matt Derfler - Wajax	Matt Derfler - Wajax	Apr 18, 2023 01:35:00 PM			2.50
2.50								
Work 69885	Work Order Description Pushing on brakes and they feel very spongy but then they grab so hard	Status Closed, Completed	Type Corrective	Date Created Apr 20, 2023 12:23:59 AM	Due Date	Date Completed Apr 20, 2023 09:59:51 PM	Days Late	2.50
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
Test drove unit. Brakes do not feel spongy whatsoever and grab normally		Articulated Rock Truck	Nick Misener	Nick Misener	Apr 20, 2023 09:59:47 PM	2.00		2.00
2.00								
Work 70168	Work Order Description Oil leak	Status Closed, Completed	Type Corrective	Date Created Apr 25, 2023 06:10:15 AM	Due Date	Date Completed Apr 25, 2023 09:56:01 PM	Days Late	2.00
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
Started unit and let warm checked for leaks. Unit ran for 3 hours. No longer leaking		Articulated Rock Truck	Thomas Ragan	Thomas Ragan	Apr 25, 2023 09:56:01 PM	1.00		1.00
1.00								
Work 70195	Work Order Description oil leaking from under cab,	Status Closed, Completed	Type Corrective	Date Created Apr 25, 2023 05:28:06 PM	Due Date	Date Completed Apr 25, 2023 05:29:00 PM	Days Late	1.00
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
25-04-23 Andy inspected for oil leak, found transmission line on top right hand side loose tightened line, cleaned off checked levels and are good, 25th April 2023 - Gabe Elamer -Check oil leak found loose hose on top RH side of transmission		Articulated Rock Truck	Andy Boettger	Andy Boettger				0.50
		Articulated Rock Truck	Gabe Elamer	Gabe Elamer	Apr 25, 2023 05:33:00 PM			0.50

-Tighten hose (unit will need to be ran and checked for leaks)  
 08 May 2023 - Gabe Elamer  
 -Swapped out RH mirror assembly  
 09-05-23 Andy Boettger  
 tightened right side mirror,

Articulated Rock Truck	Gabe Elamer	Gabe Elamer	May 08, 2023 04:46:00 AM	1.50
Articulated Rock Truck	Andy Boettger	Andy Boettger	May 09, 2023 05:10:00 AM	2.00
				4.50

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
71162	Bushing on cylinder host missing	Closed, Completed	Corrective	May 09, 2023 10:42:08 AM		May 09, 2023 05:08:44 PM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
09 May 2023 - Kris W - "move unit to be worked on in yard remove LH hoist cylinder get new hoist cylinder brought over swap cylinder piping and fittings over install new hoist cylinder new upper pin used grease bearings test cylinder everything works OK no leaks park unit in up line clean work area"		Articulated Rock Truck	Kris Williams - Finning	Kris Williams - Finning	May 09, 2023 05:08:44 PM		6.00
				6.00			

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
71415	Bolt on cylinder lift need to be tightened	Closed, Completed	Corrective	May 13, 2023 07:11:15 AM		May 13, 2023 10:31:59 AM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
		Articulated Rock Truck	Kristian Zimmer	Ian Knott	May 13, 2023 10:31:59 AM		

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
71806	R side box cylinder bolt needs t8ghtening please.	Closed, Completed	Corrective	May 20, 2023 06:53:18 PM		May 20, 2023 07:48:04 PM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
		Articulated Rock Truck	Austin Heino	Menno Buhler	May 20, 2023 07:48:04 PM		

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
71910	AC quit no worky.	Closed, Completed	Corrective	May 22, 2023 07:32:41 PM		May 26, 2023 07:47:05 AM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
A/C NOT WORKING. TRAVEL TO UNIT , HOOK UP GAUGE SET AND MONITER A/C FUNCTION, SYSTEM IS CYCLING AS IT SHOULD, BLOWS COLD RAN A/C FOR A WHILE AT DIFFERENT ENGINE SPEEDS , NO ISSUES FOUND		Articulated Rock Truck	Trevor Irwin - Brandt	Trevor Irwin - Brandt	May 26, 2023 07:47:05 AM		2.50

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
72319	Check brake accumulator pressure.saying low.	Closed, Completed	Corrective	May 29, 2023 04:43:56 AM		May 29, 2023 09:29:22 AM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
"RAN ACCUMUALTOR PRESSURE CHECK TEST TEST FAILED CHECKED ALL 5 REAR BREAK ACCUMUALTORS ALL WERE LOW BY 250 PSI CAHRGED ALL 5 ACCUMUALTORS RE TRIED TEST AND IT WAS SUCCESFULL "		Articulated Rock Truck	Sebastian Cepeda - Brandt	Sebastian Cepeda - Brandt	May 29, 2023 09:29:22 AM		

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
72375	Headlight burnt out	Closed, Completed		May 29, 2023 09:13:08 PM		May 30, 2023 01:53:00 AM	
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
	Articulated Rock Truck	Nick Misener	Nick Misener	May 30, 2023 01:53:00 AM			
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
72538	LED back up light needs to be angled down some. Too many complaints from operators and drivers it's shining right at them & not the ground.	Closed, Completed	Corrective	Jun 02, 2023 02:49:01 AM		Jun 02, 2023 12:05:47 PM	
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
june 2 2023 tyler penkoff	Articulated Rock Truck	Tyler Penkoff	Menno Buhler	Jun 02, 2023 12:05:47 PM			1.00
adjusted light							
							1.00
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
72559	Front Brake hub transferring fluid Rear Brake hub is transferring fluid	Closed, Completed	Corrective	Jun 02, 2023 10:43:14 AM		Jun 03, 2023 05:11:48 PM	
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
03 June 23-Tony.B-DS	Articulated Rock Truck	Tyler Penkoff	Anthony Balint	Jun 03, 2023 05:00:00 PM			1.50
Went to unit, Was told front diff was over filled, Pulg leveling plug and drained excess fluid which filled half a spill tray, Noticed the brake oil was overfilled too, Likely one or both of the front hubs is leaking internally, Unit being brought to the shop 04 June 2023 - Gabe Elnamer -Wash unit -Bring outside drain overfilled brake oil tank -Test front braking system with application pressure to check for internal leakage (front brakes are holding pressure) -Bring unit inside tested both rear axle braking systems with application pressure (both are holding pressure) -Check front differential oil, was couple litres overfilled so drained to proper level -Check front differential lock and could hear clutch pack engage and disengage -Marked hydraulic and brake tanks (continue to monitor fluid levels)	Articulated Rock Truck	Gabe Elnamer	Gabe Elnamer	Jun 04, 2023 06:24:00 AM			8.00
04 June 2023 - Blair T - "Complaint DISPATCHED BY MENNO FRONT DIFF OVER FULL POSSIBLE OIL TRANSFER HYD TO BRAKE COOLING  Correction/Repair Process Comments SET UP UNIT IN YARD INSTRUCT PRHP APPRENTICE ON HOW TO TEST BRAKES FOR LEAKAGE SET UP TOOLING AND PRESSURE UP ALL AXLES INDIVIDUALLY (ALL AXLES HOLD 1200PSI) DO NOT SUSPECT A BYPASSING BRAKE SEAL GO OVER SCHEMATIC WITH APPRENTICE AND SYSTEMS OPERATION TO LOOK FOR POSSIBLE SOURCE OF OIL INTO DIFF FOR POSSIBLE OIL TRANSFER FOUND DIFF LOCK SOLENOID VLVS USE HYD OIL EXPLAIN TESTING PROCESS TO PRHP TECH PULLED OFF JOB PRHP TECH TO FINISH OFF CLEAN UP SVC RPT"	Articulated Rock Truck	Blair Townley - Finning	Blair Townley - Finning	Jun 04, 2023 10:43:00 PM			4.00
							13.50

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
72724	Front strut Bottom Bushing Gone	Closed, Completed	Corrective	Jun 05, 2023 02:25:24 AM		Jun 06, 2023 02:15:34 PM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
June 5 2023 - Donald Kearley Lance and remove strut pins remove strut		Articulated Rock Truck	Donald Kearley	Donald Kearley	Jun 05, 2023 04:45:00 PM		10.00
5th June 2023 - Gabe Elamer -Remove wheel well cover -Drain damaged strut -Pull strut pins needed to be lanced and pulled out with bigger ready rod -Repair damaged ears for strut on machine -Install new strut, pins and seals		Articulated Rock Truck	Gabe Elamer	Gabe Elamer	Jun 05, 2023 06:46:00 AM		11.50
06 June 2023 - Gabe Elamer -Fill strut with oil -Put wheel well cover back on -Re-install wheel & torque to spec. (put torque tag inside cab) -Adjust front LH and RH ride height to spec. -Test drive unit (steering and suspension feel good) -Re-adjust ride height again after test drive -Check all fluids and lights -Clean bay and put damaged struts from unit and shop on pallet outside		Articulated Rock Truck		Gabe Elamer	Jun 06, 2023 05:11:00 PM		6.50

28.00

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
73085	745C PM2 500 Service Hours JOHN LEGGE	Closed, Completed	Preventive - Planned	Jun 10, 2023 04:45:36 PM	Jun 10, 2023 04:45:00 PM	Jun 10, 2023 04:49:57 PM	0
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
Brake Accumulator (Service) - Check		Articulated Rock Truck	PMtech				
Brake Pads - Check		Articulated Rock Truck	PMtech				
Braking System - Test		Articulated Rock Truck	PMtech				
Diff & Final Drive Oil Level - Check (note particulates on mag plug and indicate findings)		Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:49:00 PM		1.50
Differential and Final Drive Oil Sample - Obtain		Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:49:00 PM		
Engine Air Filter Secondary Element (Outer) - Replace		Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:49:00 PM		
Engine Oil and Filter - Change		Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:49:00 PM		
Engine Oil Filter Inspect (Cut Filter and Record Findings)		Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:49:00 PM		
Fuel System Primary Filter - Replace		Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:49:00 PM		
Fuel System Secondary Filter - Replace		Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:49:00 PM		
Hoist System and Brake System Oil Sample - Obtain		Articulated Rock Truck	PMtech				
Secondary Steering - Test		Articulated Rock Truck	PMtech				
Steering System Oil Sample - Obtain		Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:49:00 PM		
Torque Converter and Transmission Oil Sample - Obtain		Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:49:00 PM		
Transfer Gear Oil Sample - Obtain		Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:49:00 PM		
Transmission Oil Filter Replace		Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:49:00 PM		
Transmission Oil Filter - Inspect (Cut Filter and Record Findings.)		Articulated Rock Truck	PMtech				

1.50

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
73089	745C PM3 1000 Service Hours JOHN LEGGE	Closed, Completed	Preventive - Planned	Jun 10, 2023 04:50:08 PM	Jun 10, 2023 04:50:00 PM	Jun 10, 2023 04:51:10 PM	0
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
Battery or Battery Cable - Inspect/Replace		Articulated Rock Truck	PMtech				
Brake Oil Filter - Replace		Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:50:00 PM		1.50
Brake Tank Strainer - Clean/Inspect/Replace		Articulated Rock Truck	PMtech				
Cab Recirc Air Filter Element (Inner) - Replace		Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:50:00 PM		
Fuel Tank Cap Filter - Replace		Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:50:00 PM		
Hydraulic System Oil Filter and Screen - Clean/Inspect/Replace		Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:50:00 PM		
Hydraulic System Oil Filter Inspect (Cut Filter and Record Findings)		Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:50:00 PM		
Hydraulic Tank Strainer - Clean/Inspect/Replace		Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:50:00 PM		

Oscillating Hitch - Adjust	Articulated Rock Truck	PMtech		
Rollover Protective Structure (ROPS) - Inspect	Articulated Rock Truck	PMtech		
Torque Converter, Transmission, and Transfer Gear Oil - Change	Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:50:00 PM
Transmission Clutch Calibrations - Complete	Articulated Rock Truck	PMtech		
Transmission and Transfer Gear Breather - Replace	Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:50:00 PM

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
73090	745C PM4 2000 Service Hours JOHN LEGGE	Closed, Completed	Preventive - Planned	Jun 10, 2023 04:51:18 PM	Jun 10, 2023 04:51:00 PM	Jun 10, 2023 04:51:59 PM	0	1.50
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
Axle Breathers - Clean/Replace	Articulated Rock Truck	PMtech						
Brake Oil - Change	Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:51:00 PM				1.00
Brake System Air - Purge	Articulated Rock Truck	PMtech						
Breather (Brake Tank) - Replace	Articulated Rock Truck	PMtech						
Diff and Final Drive Oil - Change (note particulates on mag plug and indicate findings)	Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:51:00 PM				
Engine Compression Brake Valve Lash - Check	Articulated Rock Truck	PMtech						
Engine Valve Lash - Check	Articulated Rock Truck	PMtech						
Frame and Body - Inspect	Articulated Rock Truck	PMtech						
Hydraulic Tank Breather - Replace	Articulated Rock Truck	PMtech	PMtech	Jun 10, 2023 04:51:00 PM				
Refrigerant Dryer - Replace	Articulated Rock Truck	PMtech						
Service Brake Wear Indicator - Check	Articulated Rock Truck	PMtech						
Suspension System - Check	Articulated Rock Truck	PMtech						

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
73342	Hydraulic leak at pivot articulation point passenger side Both Front Hubs Need Rebuilding	Closed, Completed	Corrective	Jun 14, 2023 07:28:46 PM		Jun 17, 2023 09:09:33 AM		1.00
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours		
Looks like the brake oil is getting in to hyd tank and pushing out of the breather June 15/23 -Kris W- Finning	Articulated Rock Truck	Thomas Ragan	Kris Williams - Finning	Jun 15, 2023 09:45:00 AM	1.00	3.00		
"locate unit find front diff overfull with brake cooling oil pressure up brake cooling system neither side holds pressure drain front diff to level get unit brought to shop"								
June 16/23 Kristian Z /DS	Articulated Rock Truck	Kristian Zimmer	Kristian Zimmer	Jun 16, 2023 05:27:00 PM		11.50		
-Installed new resealed final hub on the right front -Torqued back mounting final bolts to 400 ft-lbs -Assembled the rest of the parts -Filled final with 5w-30 oil -Bolted on tire and torqued to 400 ft lbs -Backed machine in and removed left front tire. CHRIS WISEMAN JUNE 16/2023 N/S	Articulated Rock Truck	Shopguest	Chris Wiseman			11.50		
-DISSEMBLE FINAL DRIVE -CLEANED UP PARTS -REPLACED PISTON SEALS DUO-CONES BEARINGS AND BROKEN RETAINER BOLTS -REASSEMBLED June 17/23 Kristian Z /DS	Articulated Rock Truck	Kristian Zimmer	Kristian Zimmer	Jun 18, 2023 09:00:00 AM		3.00		
-Checking over machine -Topped up hydraulic, braking cooling, front axle and finals with 5w-30 gear oil -Topped up transmission fluid -Left front strut is lower than the right. Charged up the strut with nitrogen to the right level -Coolant good -Lights good -A/C good -Wipers good -Tested brakes. Working good								

						1.00	29.00
Work 73535	Work Order Description Lift cylinder pin bolt loose	Status Closed, Completed	Type	Date Created Jun 18, 2023 04:07:01 PM	Due Date	Date Completed Jun 18, 2023 05:59:25 PM	Days Late
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
June 18/23 Kristian Z./DS		Articulated Rock Truck	Kristian Zimmer	Kristian Zimmer	Jun 18, 2023 05:24:00 PM		2.50
-Replaced the bolt with a new one, with a new spacer -Greased the lifting pins both sides		Articulated Rock Truck	Kristian Zimmer				
						2.50	
Work 73721	Work Order Description Hydraulic oil leaking from above rear diff. Spill tray in place	Status Closed, Completed	Type Corrective	Date Created Jun 21, 2023 07:14:17 PM	Due Date	Date Completed Jun 22, 2023 03:36:25 AM	Days Late
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
22-06-23 Andy Boettger found the supply line for the rear diff brakes is leaking, looked for new line at the shop, no line, robbed line of truck 26, removed and replaced line with new o rings, topped up fluid, inspected for leaks while running and pushing brakes, no leaks found, line #438-6863		Articulated Rock Truck	Andy Boettger	Menno Buhler	Jun 22, 2023 03:36:25 AM		6.50
						6.50	
Work 73963	Work Order Description Bottom right mirror loose	Status Closed, Completed	Type Corrective	Date Created Jun 26, 2023 11:31:05 AM	Due Date	Date Completed Jun 27, 2023 12:38:43 AM	Days Late
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
27-06-23 Andy Boettger tightened mirror		Articulated Rock Truck	Andy Boettger	Menno Buhler	Jun 27, 2023 12:38:43 AM		0.50
						0.50	
Work 74202	Work Order Description Overgreased Equipment	Status Closed, Completed	Type Corrective	Date Created Jun 30, 2023 01:21:09 PM	Due Date	Date Completed Jun 30, 2023 01:22:56 PM	Days Late
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
Overgreased Equipment		Articulated Rock Truck	Grease Task Force	Grease Task Force	Jun 30, 2023 01:22:10 PM	0.00	0.00
						0.00	0.00
Work 74368	Work Order Description Brake codes	Status Closed, Completed	Type Corrective	Date Created Jul 04, 2023 11:06:02 AM	Due Date	Date Completed Jul 03, 2023 11:07:00 AM	Days Late
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
Unit showed consistant brake codes when run up to check another function. Inspected brake accumulators, drained brake system pressure completely, restart unit and measure cycle times of cut in and cut out pressures. All within spec and codes disappeared. Service and park brake tests successfully carried out. Unsure of initial cause of code but brake system working correctly now.		Articulated Rock Truck	Silas Angell - Wajax	Silas Angell - Wajax	Jul 03, 2023 11:07:00 AM		2.00
						2.00	
Work 74600	Work Order Description Seat won't adjust	Status Closed, Completed	Type	Date Created Jul 09, 2023 01:18:01 AM	Due Date	Date Completed Jul 09, 2023 10:39:17 AM	Days Late
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
Tested all seat functions. The seat cushion is broken loose in the one corner by the seat seems fine		Articulated Rock Truck	Thomas Ragan	Thomas Ragan	Jul 09, 2023 10:39:17 AM	1.00	

1.00							
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
74960	Driver is complaining that the seat is on an angle. It's hunting one side of her back a d neck.	Closed, Completed	Corrective	Jul 15, 2023 08:56:05 AM		Jul 15, 2023 05:12:23 PM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
July 15 2023 tyler penkoff		Articulated Rock Truck	Tyler Penkoff	Menno Buhier	Jul 15, 2023 05:12:23 PM	2.00	
Replaced seat, unit should be comfy :) 15 July 2023 - Gabe Elnamer -Assist Tyler with lifting new seat for install		Articulated Rock Truck	Gabe Elnamer	Gabe Elnamer	Jul 15, 2023 06:55:00 AM		1.00

2.00							
1.00							
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
75001	PM 2 and inspection	Closed, Completed	Preventive - Planned	Jul 16, 2023 07:04:52 AM		Jul 16, 2023 07:04:52 AM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
Brake Accumulator (Service) - Check		Articulated Rock Truck					0.00
Brake Pads - Check		Articulated Rock Truck					0.00
Braking System - Test		Articulated Rock Truck					0.00
Diff & Final Drive Oil Level - Check (note particulates on mag plug and indicate findings)		Articulated Rock Truck					0.00
Differential and Final Drive Oil Sample - Obtain		Articulated Rock Truck					0.00
Engine Air Filter Secondary Element (Outer) - Replace		Articulated Rock Truck					0.00
Engine Oil and Filter - Change		Articulated Rock Truck					0.00
Engine Oil Filter Inspect (Cut Filter and Record Findings)		Articulated Rock Truck					0.00
Fuel System Primary Filter - Replace		Articulated Rock Truck					0.00
Fuel System Secondary Filter - Replace		Articulated Rock Truck					0.00
Hoist System and Brake System Oil Sample - Obtain		Articulated Rock Truck					0.00
Secondary Steering - Test		Articulated Rock Truck					0.00
Steering System Oil Sample - Obtain		Articulated Rock Truck					0.00
Torque Converter and Transmission Oil Sample - Obtain		Articulated Rock Truck					0.00
Transfer Gear Oil Sample - Obtain		Articulated Rock Truck					0.00
Transmission Oil Filter Replace		Articulated Rock Truck					0.00
Transmission Oil Filter - Inspect (Cut Filter and Record Findings.)		Articulated Rock Truck					0.00
Aftercooler Core - Inspect/Clean		Articulated Rock Truck					0.00
Automatic Lubrication Grease Tank - Fill		Articulated Rock Truck					0.00
Cab Fresh Air Filter (Outer)- Replace		Articulated Rock Truck					0.00
Cab Recirc Air Filter (Inner)- Inspect and Replace if Needed		Articulated Rock Truck					0.00
DEF Filter Screen - Clean		Articulated Rock Truck					0.00
Diesel Exhaust Fluid - Fill		Articulated Rock Truck					0.00
Engine Air Filter Primary Element (Outer) - Replace		Articulated Rock Truck					0.00
Engine Air Filter Secondary Element (Inner) - Inspect and Replace if Needed		Articulated Rock Truck					0.00
Ether Starting Aid Cylinder - Inspect/Replace		Articulated Rock Truck					0.00
Radiator Core - Clean		Articulated Rock Truck					0.00
Tire Inflation - Check		Articulated Rock Truck					0.00
Window Washer Reservoir - Fill		Articulated Rock Truck					0.00
Belt - Inspect/Replace		Articulated Rock Truck					0.00
Backup Alarm - Test		Articulated Rock Truck					0.00
Brakes, Indicators and Gauges - Test		Articulated Rock Truck					0.00
Engine Oil Level - Check		Articulated Rock Truck					0.00
Seat Belt - Inspect		Articulated Rock Truck					0.00
Wheel Nut Torque - Check (350 /-45 Ft.Lbs)		Articulated Rock Truck					0.00
Suspension and Suspension Cylinder Bearings - Lubricate		Articulated Rock Truck					0.00
Body Pivot Bearings - Lubricate		Articulated Rock Truck					0.00
Brake Oil Level - Check		Articulated Rock Truck					0.00
Cooling System Coolant Level - Check		Articulated Rock Truck					0.00
Fuel System Water Separator - Drain		Articulated Rock Truck					0.00
Fuel Tank Water and Sediment - Drain		Articulated Rock Truck					0.00
Fluids - Check for Leaks		Articulated Rock Truck					0.00
Hoist Cylinder Bearings - Lubricate		Articulated Rock Truck					0.00

Hydraulic System Oil Level - Check	Articulated Rock Truck						0.00
Oscillating Hitch - Lubricate	Articulated Rock Truck						0.00
Steering Cylinder Bearings - Lubricate	Articulated Rock Truck						0.00
Torque Converter, Transmission, and Transfer Gear Oil Level - Check	Articulated Rock Truck						0.00
Coolant Sample (Level 2) - Obtain(Test coolant and record freeze point)	Articulated Rock Truck						0.00
Engine Oil Sample - Obtain	Articulated Rock Truck						0.00
15th July 2023 - Gabe Elamer	Articulated Rock Truck	Gabe Elamer	Gabe Elamer	Jul 15, 2023 05:13:00 PM			4.00
-PM 2 service and inspect unit							
-Clean and wash lube bay afterwards							
							4.00

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
75137	2-way antenna busted off	Closed, Completed		Jul 18, 2023 08:44:10 PM		Jul 19, 2023 01:50:55 AM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
		Articulated Rock Truck	Ken Connon	Nick Vanderkooi	Jul 19, 2023 01:50:55 AM		

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
75138	Cab fan keeps cutting out. Kicks back on just enough to cool driver down then cuts out again.	Closed, Completed		Jul 18, 2023 09:16:53 PM		Jul 19, 2023 01:51:05 AM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
		Articulated Rock Truck	Ken Connon	Nick Vanderkooi	Jul 19, 2023 01:51:05 AM		

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
75322	Left cab strut low	Closed, Completed		Jul 22, 2023 07:42:04 PM		Jul 23, 2023 12:02:00 AM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
		Articulated Rock Truck	Christopher Paul	Nick Vanderkooi	Jul 23, 2023 12:02:00 AM		

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
75352	Strut needs charge	Closed, Completed	Corrective	Jul 23, 2023 12:28:55 PM		Jul 23, 2023 04:31:54 PM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
No description available		Articulated Rock Truck	Andy Boettger	Andy Boettger	Jul 23, 2023 03:47:26 PM	2.50	2.83
						2.50	2.83

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
75378	Degreasing	Closed, Completed	Preventive - Planned	Jul 24, 2023 05:04:48 AM	Jul 25, 2023 05:04:48 AM	Jul 21, 2024 05:27:55 AM	362
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
Degreasing		Articulated Rock Truck	PMtech				

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
75487	Dpf level high and regen locked out	Closed, Completed		Jul 26, 2023 07:33:27 AM		Jul 26, 2023 04:57:06 PM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
No associated codes dpf high Manual regeneration		Articulated Rock Truck	Nick Misener	Nick Misener	Jul 26, 2023 04:57:01 PM	2.00	2.00
						2.00	2.00

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
75600	Right side lift cylinder top bushing gone it is 1 look ever were.	Closed, Completed		Jul 28, 2023 07:15:56 AM		Jul 28, 2023 04:55:55 PM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
Replace right hoist cylinder		Articulated Rock Truck	Nick Misener	Nick Misener	Jul 28, 2023 04:55:50 PM	3.00	3.00
						3.00	3.00

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
------	------------------------	--------	------	--------------	----------	----------------	-----------



75807 Right headlight burnt out (Double up WO)

Closed, Completed

Aug 01, 2023  
07:35:11 AMAug 01, 2023  
04:12:12 PM

Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
	Articulated Rock Truck	Nick Misener	Ian Knott	Aug 01, 2023 04:12:12 PM		

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
75809	Left cab strut low again / Right head light out.	Closed, Completed		Aug 01, 2023 07:36:39 AM		Aug 03, 2023 09:50:00 AM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
Aug 2/23 Kristian Z /DS		Articulated Rock Truck	Kristian Zimmer	Kristian Zimmer	Aug 02, 2023 05:22:00 PM		6.00
-Right headlight not working, due to a burnt bulb. Replaced it with a new bulb -Checked to see if there's any leakage on the left strut. No leaks found -Drained nitrogen and dropped both struts. Purged and topped up struts with suspension oil.							
Note: -Struts need to be charged and leveled to right height AUGUST 03, 2022-MARVIN C- CONTINUE N/S WORK. LOOK FOR FITTINGS/CONNECTORS AND CHECKED AND CHARGED ALL FRONT AND REAR ACCUMULATORS. ALL OF THEM WAS JUST 100 PSI LOW FROM SPECS. CHARGED IT ALL UP TO CORRECT PRESSURE SETTING. RAN AND CHARGED THE SYSTEM AND TEST AND NO MORE BRAKE FAULT ISSUE CAME UP. CHECKED OVER UNIT, TOPPED UP COOLANT AND DROVE THE MACHINE OUT IN THE YARD. BRAKE AND FRONT SUSPENSION WAS ALL GOOD. PUT MACHINE BACK IN SERVICE.		Articulated Rock Truck		Marvin Corpuz	Aug 03, 2023 08:45:00 AM		3.50
						9.50	

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
76028	High DPF level shut down safely.	Closed, Completed	Corrective	Aug 04, 2023 04:35:44 PM		Aug 04, 2023 08:49:18 PM	
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
	Articulated Rock Truck	Austin Heino	Menno Buhler	Aug 04, 2023 08:49:18 PM			

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
76401	Left side mirror need replacing	Closed, Completed		Aug 12, 2023 06:40:06 PM		Aug 13, 2023 07:42:14 AM	
Task Description	Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
Replaced both right and left mirrors	Articulated Rock Truck	Ken Connon	Ken Connon	Aug 13, 2023 07:42:14 AM	1.00		
					1.00		

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
76428	Bottom right mirror loose	Closed, Completed	Corrective	Aug 13, 2023 03:02:34 PM		Aug 13, 2023 04:40:05 PM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
drive to machine tighten mirrors.		Articulated Rock Truck	Matt Derfler - Wajax	Matt Derfler - Wajax	Aug 13, 2023 04:40:05 PM		1.00

								1.00
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
76443	Dipstick needs replacing	Closed, Completed		Aug 13, 2023 07:55:38 PM		Aug 14, 2023 12:14:00 AM		
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
14-08-23 Andy Boettger stole dipstick from boneyard truck 20 removed and replaced dipstick.		Articulated Rock Truck	Andy Boettger	Daniel Reid	Aug 14, 2023 12:14:00 AM		2.00	

Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
76593	Missing right side lift cylinder bolt	Closed, Completed		Aug 16, 2023 06:48:31 PM		Aug 17, 2023 04:01:18 AM	

Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
Reinstall pin Threads stripped Put in longer bolt and nut on other side Had to find new spacer		Articulated Rock Truck	Nick Misener	Nick Misener	Aug 17, 2023 04:01:11 AM	2.00	2.00
						2.00	2.00
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
76665	Both front struts need to be charged.  Also drivers side ladder is bent	Closed, Completed		Aug 18, 2023 11:12:59 AM		Aug 18, 2023 07:55:00 PM	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
CHRIS WISEMAN AUG 18/2023 -CHARGED BOTH FRONT STRUTS -STRAIGHTENED L/S FENDER AND STEP -CHECKED CENTRE A-FRAME BOLTS. OK. BEARING SHOT OR FRAME NEEDS LINE BORE		Articulated Rock Truck Articulated Rock Truck	Chris Wiseman				2.00
							2.00
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
76714	745C PM2 500 Service Hours	Closed, Completed	Preventive - Planned	Aug 19, 2023 08:30:44 AM	Aug 20, 2023 08:30:44 AM	Aug 19, 2023 08:33:23 AM	0
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
Brake Accumulator (Service) - Check		Articulated Rock Truck	PMtech				
Brake Pads - Check		Articulated Rock Truck	PMtech				
Braking System - Test		Articulated Rock Truck	PMtech				
Diff & Final Drive Oil Level - Check (note particulates on mag plug and indicate findings)		Articulated Rock Truck	PMtech	PMtech	Aug 19, 2023 08:33:00 AM	2.00	
Differential and Final Drive Oil Sample - Obtain		Articulated Rock Truck	PMtech	PMtech	Aug 19, 2023 08:33:00 AM	2.00	
Engine Air Filter Secondary Element (Outer) - Replace		Articulated Rock Truck	PMtech	PMtech	Aug 19, 2023 08:33:00 AM	2.00	
Engine Oil and Filter - Change		Articulated Rock Truck	PMtech	PMtech	Aug 19, 2023 08:33:00 AM	2.00	
Engine Oil Filter Inspect (Cut Filter and Record Findings)		Articulated Rock Truck	PMtech				
Fuel System Primary Filter - Replace		Articulated Rock Truck	PMtech	PMtech	Aug 19, 2023 08:33:00 AM	2.00	
Fuel System Secondary Filter - Replace		Articulated Rock Truck	PMtech	PMtech	Aug 19, 2023 08:33:00 AM	2.00	
Hoist System and Brake System Oil Sample - Obtain		Articulated Rock Truck	PMtech	PMtech	Aug 19, 2023 08:33:00 AM	2.00	
Secondary Steering - Test		Articulated Rock Truck	PMtech				
Steering System Oil Sample - Obtain		Articulated Rock Truck	PMtech	PMtech	Aug 19, 2023 08:33:00 AM	2.00	
Torque Converter and Transmission Oil Sample - Obtain		Articulated Rock Truck	PMtech	PMtech	Aug 19, 2023 08:33:00 AM	2.00	
Transfer Gear Oil Sample - Obtain		Articulated Rock Truck	PMtech	PMtech	Aug 19, 2023 08:33:00 AM	2.00	
Transmission Oil Filter Replace		Articulated Rock Truck	PMtech	PMtech	Aug 19, 2023 08:33:00 AM	2.00	
Transmission Oil Filter - Inspect (Cut Filter and Record Findings.)		Articulated Rock Truck	PMtech				
						22.00	
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late
76717	745C PM3 1000 Service Hours	Closed, Completed	Preventive - Planned	Aug 19, 2023 08:34:40 AM	Aug 20, 2023 08:34:40 AM	Aug 19, 2023 08:35:44 AM	0
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours
Battery or Battery Cable - Inspect/Replace		Articulated Rock Truck	PMtech				
Brake Oil Filter - Replace		Articulated Rock Truck	PMtech	PMtech	Aug 19, 2023 08:35:00 AM	1.00	
Brake Tank Strainer - Clean/Inspect/Replace		Articulated Rock Truck	PMtech	PMtech	Aug 19, 2023 08:35:00 AM	1.00	
Cab Recirc Air Filter Element (Inner) - Replace		Articulated Rock Truck	PMtech	PMtech	Aug 19, 2023 08:35:00 AM	1.00	
Fuel Tank Cap Filter - Replace		Articulated Rock Truck	PMtech	PMtech	Aug 19, 2023 08:35:00 AM	1.00	
Hydraulic System Oil Filter and Screen - Clean/Inspect/Replace		Articulated Rock Truck	PMtech	PMtech	Aug 19, 2023 08:35:00 AM	1.00	
Hydraulic System Oil Filter Inspect (Cut Filter and Record Findings)		Articulated Rock Truck	PMtech				
Hydraulic Tank Strainer - Clean/Inspect/Replace		Articulated Rock Truck	PMtech	PMtech	Aug 19, 2023 08:35:00 AM	1.00	
Oscillating Hitch - Adjust		Articulated Rock Truck	PMtech				
Rollover Protective Structure (ROPS) - Inspect		Articulated Rock Truck	PMtech				
Torque Converter, Transmission, and Transfer Gear Oil - Change		Articulated Rock Truck	PMtech	PMtech	Aug 19, 2023 08:35:00 AM	1.00	
Transmission Clutch Calibrations - Complete		Articulated Rock Truck	PMtech				
Transmission and Transfer Gear Breather - Replace		Articulated Rock Truck	PMtech	PMtech	Aug 19, 2023 08:35:00 AM	1.00	
						8.00	
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late

Aug 22, 2023  
02:14:01 AM

Page 19 of 20

CLEANED AND INSTALLED.  
 WARMED UP MACHINE AND PERFORMED AFTERTREATMENT FUNCTIONAL TEST AND  
 FINALLY SHOWED RELEVANT FAULT CODE WHICH ARE REGEN TEMP LOW, AND HIGH  
 FUEL PRESSURE #2. CHECKED ALL INTAKE AND EXHAUST AIR LINES.  
 REMOVED ARD HEAD AND CHECKED/TEST FUEL LINES FITTING AND FOUND MAIN FUEL  
 INLET PLUGGED. REMOVED ARD HEAD FROM 745-026, TEST AND ITS GOOD. CLEANED  
 AND INSTALLED TO UNIT.  
 PERFORMED MANUAL REGEN AND IT WAS SUCCESSFUL AND WENT DOWN TO 0%.  
 NO MORE EMISSION ISSUE.

							65.50	21.50
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
80967	Get unit ready to tow in to shop.	Closed, Completed	Corrective	Dec 01, 2023 12:15:46 PM		Dec 09, 2023 06:53:33 PM		
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
DEC 02, 2023-MARVIN C- GET MACHINE READY FOR TOW IN THE SHOP. COORDINATE THE TOW WITH THE OPERATOR AND MOVED THE MACHINE IN THE SHOP SAFELY. DRAINED THE COOLANT AND REMOVED THE COOLING PACKAGE TO ACCESS AND ASSESS REPAIRS NEEDED.		Articulated Rock Truck	Marvin Corpuz	Marvin Corpuz	Dec 02, 2023 05:10:00 PM		7.50	
								7.50
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
81301	RT has a service code. Engine air filter restricted.	Closed, Completed		Dec 15, 2023 08:10:57 PM		Dec 15, 2023 04:14:25 PM		
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
CHRIS WISEMAN DEC 15/2023 -CHANGED PLUGGED AIR FILTERS AND CLEARED CODE		Articulated Rock Truck Articulated Rock Truck	Chris Wiseman	Nick Vanderkooi	Dec 15, 2023 04:14:25 PM		0.50	
								0.50
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
82116	Dead battery wont start.	Closed, Completed		Feb 29, 2024 08:18:20 AM		Feb 29, 2024 10:35:35 AM		
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
Boosted		Articulated Rock Truck	Nick Vanderkooi	Nick Vanderkooi	Feb 29, 2024 10:35:35 AM			
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
83721	Degreasing	Closed, Completed	Preventive - Planned	Aug 11, 2024 05:02:00 AM	Aug 12, 2024 05:02:00 AM	Aug 11, 2024 09:27:10 AM	0	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
Degreasing		Articulated Rock Truck Articulated Rock Truck	PMtech					
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
83845	Degreasing	Closed, Completed	Preventive - Planned	Sep 01, 2024 05:04:39 AM	Sep 02, 2024 05:04:39 AM	Sep 05, 2024 05:58:57 AM	3	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
Degreasing		Articulated Rock Truck Articulated Rock Truck	PMtech					
Work	Work Order Description	Status	Type	Date Created	Due Date	Date Completed	Days Late	
83955	Degreasing	On Hold	Preventive - Planned	Sep 26, 2024 05:05:29 AM	Sep 27, 2024 05:05:29 AM		58	
Task Description		Asset	Assigned To	Completed By	Date Completed	Est Hours	Spent Hours	
Degreasing		Articulated Rock Truck Articulated Rock Truck	PMtech					

177.33 349.42