

E18-2
NOV

COLUMBIA VALLEY FREIGHT
Maintenance and Service History

Unit 211 — 2024 Freightliner M2106

Prepared 8 October 2026 for a prospective purchaser.

This record is taken directly from Columbia Valley Freight's maintenance and accounting systems: work orders raised in our own shop, and invoices from outside suppliers.

Coverage. Supplier invoices are held from January 2026 and shop work orders from February 2026. Work carried out before those dates is not held in these systems and is not shown here. Labour hours are as entered on each work order; a number of records carry no hours. Meter readings in the service tables are those recorded at the time of service; the current reading comes from the vehicle telematics on the date shown.

CVIP. Inspection expiry dates reflect the current six-month inspection cycle. The certificate carried on the vehicle should be taken as authoritative.

No costs are shown in this record. Supplier invoices and shop labour costs are available on request.

Unit 211 — 2024 Freightliner M2106

Detail	
Unit number	211
Year / make / model	2024 Freightliner M2106
VIN	1FVACXFD1RHUW0849
Licence plate	VA9437 (British Columbia)
Configuration	Single drive
Registered GVW	15,000 kg
Tare weight	4,773 kg
CVIP expiry	30 April 2027
Scheduled service interval	25,000 km
Odometer	165,976 km
Engine hours	3,677 hours
Meter reading taken	7 October 2026, from vehicle telematics

Work carried out in our shop

Date	Meter	Work performed	Carried out by	Labour hrs
17–23 Apr 2026	149,212 km 3,211 h	Pre-CVIP inspection and repairs, driver-side mirror, grease and check-over. Rear brake pads replaced and wheels torqued (recorded as 1500 ft). The driver-side mirror, which was broken, was replaced. Truck greased and front bumper resecured.	S. Ferneyhough	5.0
28 Apr 2026	149,260 km 3,212 h	Reported: left rear power tailgate spring required replacement. Left rear power tailgate spring replaced and truck greased.	S. Ferneyhough	2.0

Work and parts supplied by outside vendors

Date	Supplier	Work / parts supplied
5 Jan 2026	Mountain Mechanical Sales & Service	Brake repair
10 Feb 2026	Maxim Truck & Trailer	Torsion springs (right and left side)
25 Feb 2026	New West Truck Centres	Fuel filter element, 7 micron
1 Apr 2026	New West Truck Centres	Parts supplied
14 Apr 2026	Amazon	Door mirror, black, with bracket arm (driver side)
23 Apr 2026	NAPA - CV Auto Parts	Brake pads
27 Apr 2026	Maxim Truck & Trailer	Torsion spring (left side)
30 Apr 2026	Walker's Repair Centre	Truck inspection
23 Jun 2026	New West Truck Centres	Water sensor probe assembly (FWS)
7 Jul 2026	Mayne Auto Glass	Service

Open items at the date of this record

No open work orders and no outstanding defects are recorded against this unit.

Prepared by Columbia Valley Freight from its maintenance and accounting records. Supplier invoices are available on request.