UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	25/09/2015	9700	Susp\AF	WEIGHT GAUGE	Fit Weight Gauge	0
161	XN87BD	25/09/2015	9701	Chassis	MUDFLAPS	Fit Mud Flaps To Rear Guards	0
161	XN87BD	24/10/2015	9828	DriCabRep	SUZI COILS - RUBBING ON DECK	Checked and Remounted Suzi Hoses.	15114
161	XN87BD	24/10/2015	9829	Elect\Lights	REAR LIGHT VERY CLOSE TO TRAILER WHEN BACKING INTO STEEP DRIVEWAYS	Checked and Adjusted Rear Light Mounts Forward.	15114
161	XN87BD	24/10/2015	9831	VehService	B SERVICE	First Service Completed by Brown & Hurley, Kyogle.	15114
161	XN87BD	19/11/2015	10050	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	35001
161	XN87BD	19/11/2015	10047	DriCabRep	SEAT LEAKING AIR WHEN SITTING AND IS GOING UP AND DOWN	CHECKED AND REPAIRED LOOSE AIR HOSE.	35001
161	XN87BD	12/12/2015	10422	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	53235
161	XN87BD	10/01/2016	10679	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	68922
161	XN87BD	2/02/2016	11001	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	85279
161	XN87BD	19/02/2016	11181	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	99384
161	XN87BD	25/02/2016	11322	Steering\WA	WHEEL ALIGNMENT	BIG WHEELS TRUCK ALIGNMENT - SHAKE & REPORT TYRES ARE FEATHERED. RECOMMEND GETTING RIGHT HAND STEER FLIPPED ON THE RIM. WHEEL ALIGNMENT REPORT READINGS, TOE ADJUSTMENT. CENTRALIZE STEERING WHEEL AND ROAD TESTING. DRIVE ALIGNMENT, RELOCATE AXLE TRACKING. ALIGNMENT SHIM 5/8X3.0MM.	104947
161	XN87BD	2/03/2016	11464	TYRES\STRIP/FIT	STRIP AND FIT TYRE	RAY HALL TYRES - STRIP AND FIT /FLIP ON RIM TO POS 2	106689
161	XN87BD	5/03/2016	11437	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	112540
161	XN87BD	11/03/2016	11470	TYRES\ROTATE	ROTATE TYRES	RAY HALL TYRES - ROTATED TYRES POS 1 TO POS 10	104347
161	XN87BD	22/03/2016	11646	TYRES\STEER	STEER TYRES	RAY HALL TYRES - SUPPLIED AND FITTED NEW CONTINENTAL 295/80R22.5 152/149M HS TYRE TO POS 1 & 2	124731
161	XN87BD	26/03/2016	11668	VehService\BS	B SERVICE	B SERVICE COMPLETED AS PER ATTACHED CHECKLIST	128100
161	XN87BD	21/04/2016	11953	VehService\AS	A SERVICE	A Service completed as per attached Checklist	147736
161	XN87BD	8/05/2016	12110	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	161360
161	XN87BD	1/06/2016	12622	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	180749
161	XN87BD	21/06/2016	12881	VehService\CS	C SERVICE	COMPLETED C SERVICE - ALL OK	194315
161	XN87BD	9/07/2016	13212	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	209758

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	19/07/2016	13267	Engine\ET	VALVE SET ADJUSTMENT	COMPLETED VALVE SET ADJUSTMENT	214855
161	XN87BD	10/08/2016	13516	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	230254
161	XN87BD	31/08/2016	13650	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	244208
161	XN87BD	9/09/2016	13990	TYRES\STEER	STEER TYRES	RAY HALL TYRES SUPPLIED AND FITTED NEW CONTINENTAL 295/80R22.5152 TO POS 1 & 2	247323
161	XN87BD	11/09/2016	13735	COMP\AI	ANNUAL COMPLIANCE INSPECTION	COMPLETED ANNUAL COMPLIANCE INSPECTION - PASSED - ALL OK	252720
161	XN87BD	18/09/2016	13854	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	257850
161	XN87BD	11/10/2016	14129	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	272150
161	XN87BD	11/10/2016	14629	TYRES\TP09	DRIVE TYRES	RAY HALL TYRES - FITTED NEW CONTINENTAL 11R22.5 148/145L TYRE TO POS 9, 10, 11, 12	273803
161	XN87BD	23/10/2016	14269	Elect\Lights	Lights	Replaced faulty RH stop/tail light, replaced number plate lights.	281166
161	XN87BD	30/10/2016	14325	VehService\CS	C SERVICE	COMPLETED C SERVICE - ALL OK	286133
161	XN87BD	6/11/2016	14746	TYRES\DRIVE	DRIVE TYRES	RAY HALL TYRES - FITTED NEW CONTINENTAL 11R22.5 148/145L HDR2+ TYRE TO POS 5, 6, 7, 8	289839
161	XN87BD	20/11/2016	14528	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	299834
161	XN87BD	10/12/2016	14833	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	314030
161	XN87BD	31/12/2016	14977	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK Degrease turntable and refill auto greaser.	328196
161	XN87BD	7/01/2017	15429	TYRES\STEER	TYRE ROTATION	RAY HALL TYRES ROTATED STEER TYRES	331523
161	XN87BD	26/01/2017	15352	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	345657
161	XN87BD	12/02/2017	15563	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	357406
161	XN87BD	14/02/2017	15569	Elect\BATT	BATTERIES	REMOVED AND REPLACED BATTERIES	357407
161	XN87BD	21/02/2017	15634	DrivLine\OL	AXLE GASKETS	REPLACED LEAKING AXLE GASKETS	362368
161	XN87BD	5/03/2017	15796	Chassis	LEFT HAND SIDE WHEEL SEAL	REPLACED WHEEL SEAL	372004
161	XN87BD	7/03/2017	15909	TYRES\TYROT	ROTATE DRIVE TYRES	RAY HALL TYRES ROTATED DRIVE TYRES - POS 5 TO 12	372004
161	XN87BD	16/03/2017	16015	TYRES\PUNT	PUNCTURE REPAIR	RAY HALL TYRES REPAIRED PUNCTURE TO POS 7	378750
161	XN87BD	17/03/2017	15933	VehService\CS	C SERVICE	COMPLETED C SERVICE - ALL OK	378758
161	XN87BD	17/03/2017	15934	DrivLine\DiffOil	DIFF OILS	Changed Diff oil and filter	378758
161	XN87BD	17/03/2017	15935	DrivLine\TransOil	TRANSMISSION OIL	Changed gearbox oil and filter	378758
161	XN87BD	8/04/2017	16100	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	397443

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	20/04/2017	16226	WAlign\WA	Wheel Alignment	Big Wheels as per invoice- Shake & report - slight feathering on steer tyres - all steering and suspension components appear OK. Wheel alignment report, readings, Toe adjustment, centralize steering wheel and road testing. Drive alignment, relocate axle tracking.	404502
161	XN87BD	28/04/2017	16564	TYRES\PUNCTURE	PUNCTURE REPAIR	RAY HALL TYRES REPAIRED PUNCTURE TO POS 7	402716
161	XN87BD	29/04/2017	16552	TYRES\STEER	STEER TYRES	RAY HALL TYRES FITTED NEW CONTINENTAL 295/80R22.5152/148MTL HSR2 TYRE TO POS 1 & 2	402476
161	XN87BD	2/05/2017	16307	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK r/h front axle seal leaking resealed	109667
161	XN87BD	16/05/2017	16413	Valve Set\VALVE SET	VALVE SET ADJUSTMENT	COMPLETED VALVE SET ADJUSTMENT	418382
161	XN87BD	21/05/2017	16768	TYRES\PUNCTURE	PUNCTURE REPAIR	RAY HALL TYRES - REPAIRED PUNCTURE TO TYRE IN POS 8	422742
161	XN87BD	1/06/2017	16669	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	429430
161	XN87BD	7/07/2017	17019	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	453946
161	XN87BD	22/07/2017	17205	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	464439
161	XN87BD	22/07/2017	17207	DrCabElect\Lights	HEADLIGHT COVER BROKEN - DRIVERS WEATHERSHEILD LOOSE	Replaced Headlight Shroud	464439
161	XN87BD	10/08/2017	17400	C Service\CS	C SERVICE	COMPLETED C SERVICE - ALL OK	480242
161	XN87BD	29/08/2017	18750	TYRES\STEER	STEER TYRES	RAY HALL TYRES FIT 2 X CONTINENTAL 295/80R22.5152/148MTL TO POS 1 & 2	494010
161	XN87BD	6/09/2017	17667	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	501575
161	XN87BD	15/09/2017	17788	COMP\AI	ANNUAL COMPLIANCE INSPECTION	COMPLETED ANNUAL COMPLIANCE INSPECTION - PASSED - ALL OK	507809
161	XN87BD	10/10/2017	18117	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	521783
161	XN87BD	10/10/2017	18119	Brakes	ADJUST BRAKES	ADJUSTED BRAKES	521783
161	XN87BD	12/10/2017	18406	TYRES\DRIVE	DRIVE TYRES	RAY HALL TYRES FIT 4 X CONTINENTAL 11R22.5 148/145L TYRE TO POS 9, 10, 11, 12.	523565
161	XN87BD	2/11/2017	18424	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	538958
161	XN87BD	2/11/2017	18425	Elect\Lights	Tail light	Replaced L/H brake light	538958
161	XN87BD	17/11/2017	18598	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	549160
161	XN87BD	21/12/2017	19526	TYRES\DRIVE	DRIVE TYRES	RAY HALL TYRES FIT 4 X CONTINENTAL 11R22.5 148/145L HDR2+ TYRE POS 9, 10, 11, 12.	571906
161	XN87BD	21/12/2017	19530	TYRES\ROTATE	ROTATE TYRES	RAY HALL TYRES ROTATED POS 9, 10, 11, 12, TO 5, 6, 7, 8,	571906

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	28/12/2017	18975	DrivLine\DiffOil	DIFF OILS	REPLACED DIFF OIL AND FILL WITH NEW OIL	577425
161	XN87BD	28/12/2017	18976	DrivLine\TransOil	TRANSMISSION OIL	DRAINED AND REPLACED GEARBOX OIL WITH NEW OIL	577425
161	XN87BD	29/12/2017	18973	VehService\CS	C SERVICE	COMPLETED C SERVICE - ALL OK	577425
161	XN87BD	29/12/2017	18981	AIRCON	COMPRESSOR	JEFF PRICHARD REPLACED A/C COMPRESSOR AND BELT TENSIONER AND IDLE BEARING.	577425
161	XN87BD	29/12/2017	18982	Brakes\BR	Brake reline	FULL DRIVE RELINE OF BRAKES	577425
161	XN87BD	1/02/2018	19492	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	596025
161	XN87BD	10/02/2018	19689	DrCabElect	AUTO TRANS JUMPS INTO NEUTRAL WHEN STOPPED	Brown & Hurley - PLUGGED IN AND CHECKED FAULT CODES. FOUND INACTIVE CODES FOR ECA SPEED SENSOR AND AUTO NEUTRAL. GREASED CLUTCH AND CROFT SHAFT. REMOVED ECA AND MOVED POSITION FOR SELF GREASE, REFITTED ECA WHEN BACKING OUT OF SHED TRUCK AUTO NEUTRAL. CARRIED OUT CLUTCH RESET. ADJUSTED CLUTCH. CARRIED OUT LAUNCHES. AUTO NEUTRALIED AGAIN. PULLED DASH APART TRYING TO FIND AUTO NEUTRAL SWITCH. FOUND HOB SWITCH AT BACK OF PARK BRAKE SWITCH. FOUND WIRES HAS BEEN SPLICED INTO IT. FOLLOWED WIRES AND FOUND PARK BRAKE ALARM WAS WIRED INTO IT. CUT PARK BRAKE ALARM OUT AND FIXED AUTO NEUTRAL WIRING. WIRED UP PARK BRAKE ALARM USING KENWORTH WIRING. FITTED A NEW HOB SWITCH FOR PARK BRAKE ALARM AND REPLACED AUTO NEUTRAL HUB SWITCH. TESTED ALARM AND ALL OK. TEST DROVE TRUCK AND CLUTCH ADJUSTMENT WAS INCORRECT. RE ADJUSTED CLUTCH. TEST DROVE ALL OK	601307
161	XN87BD	27/02/2018	20031	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	610821
161	XN87BD	2/03/2018	20093	DrCabElect\AC	KOOL CAT IN SLEEPER WILL NOT STAY ON	Briskair Invoice - Diagnose Koolkat A/C System Fault. Load test batteries - failed. Supply and install new batteries, clean out blocked evaporator filter, reset voltage paramaters in control module. Test gas pressures and vent temperatures.	612513
161	XN87BD	22/03/2018	20373	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	626139
161	XN87BD	23/03/2018	20445	Elect\SC	SUZI COILS	REPLACED SET OF SUZI COILS	626140

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	29/03/2018	20587	DrivLine\WB	WHEEL BEARINGS	Fitted new steer bearings LHS.	631822
161	XN87BD	29/03/2018	21510	TYRES\STEER	STEER TYRES	RAY HALL TYRES FIT 2 X FALKEN 295/80R22.5 152/148 RI151 TYRE TO POS 1 &2	631821
161	XN87BD	6/04/2018	20678	DrivLine\WB	WHEEL BEARINGS	Replaced RHS steer wheel bearings	635994
161	XN87BD	17/04/2018	20804	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	643371
161	XN87BD	22/04/2018	20997	WINDSCREEN\WSCR	WINDSCREEN	NORTHEAST AUTOGLASS - REPLACED WINDSCREEN.	645925
161	XN87BD	1/05/2018	21489	TYRES\PUNT	PUNCTURE REPAIR	RAY HALL TYRES REPAIRED PUNCTURE TO POS 8	650027
161	XN87BD	9/05/2018	21094	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	657384
161	XN87BD	26/05/2018	21406	VehService\CS	C SERVICE	COMPLETED C SERVICE - ALL OK	669919
161	XN87BD	19/06/2018	21904	Valve Set\VALVE SET	VALVE SET ADJUSTMENT	COMPLETED VALVE SET ADJUSTMENT	683383
161	XN87BD	21/06/2018	21875	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	685123
161	XN87BD	29/06/2018	22261	TYRES\PUNT	PUNCTURE REPAIR	RAY HALL TYRES REPAIRED PUNCTURE POS 9	690464
161	XN87BD	15/07/2018	22233	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	701126
161	XN87BD	25/07/2018	22471	Elect\E	REPLACE EBS PLUG	REPLACED A BROKEN EBS PLUG	705430
161	XN87BD	8/08/2018	22651	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	715588
161	XN87BD	30/08/2018	22976	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	728741
161	XN87BD	20/09/2018	23256	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	744887
161	XN87BD	20/09/2018	23295	COMP\AI	ANNUAL COMPLIANCE INSPECTION	COMPLETED ANNUAL COMPLIANCE INSPECTION - PASSED - ALL OK	744887
161	XN87BD	23/10/2018	23630	DrivLine\DiffOil	DIFF OILS	Replaced Diff oil and filter	759409
161	XN87BD	23/10/2018	23631	DrivLine\TransOil	TRANSMISSION OIL	Replaced gearbox oil and filter	759409
161	XN87BD	23/10/2018	23632	Engine\Comp	AIR COMPRESSOR	Removed and replaced worn out compressor	759409
161	XN87BD	23/10/2018	23633	Engine\IDLPDL	BELTS/PULLEYS	Removed radiator, then removed fan hub and replaced bearings. Removed all belts, idlers and tensioners. Replaced, all ok.	759409
161	XN87BD	23/10/2018	23634	Engine\WP	WATER PUMP	Removed coolant, replaced waterpump and thermostats. Replaced coolant hoses and clamps. Added new coolant, all ok.	759409
161	XN87BD	23/10/2018	23635	Engine\Turbo	TURBO	Removed and replaced worn out turbo, all ok.	759409
161	XN87BD	23/10/2018	23636	WBearings\Drive WB	WHEEL BEARINGS	Removed and replaced all steer and drive wheel bearings, all ok	759409
161	XN87BD	23/10/2018	23637	Elect\EP	Replace Electrical Plug	Replaced electrical plug, all ok.	759409
161	XN87BD	23/10/2018	23639	DrivLine\ClutchPack	Clutch	Removed and replaced a worn out clutch pack, all ok	759409

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	23/10/2018	23692	Elect\SM	Starter Motor	Replaced a faulty starter motor, all ok	759409
161	XN87BD	23/10/2018	23693	Elect\ALT2	Alternator	Replaced a faulty alternator, all ok.	759409
161	XN87BD	3/11/2018	23754	VehService\CS	C SERVICE	COMPLETED C SERVICE - ALL OK	759409
161	XN87BD	1/12/2018	24131	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	777086
161	XN87BD	14/12/2018	24700	TYRES\STEER	STEER TYRES	RAY HALL TYRES FIT 2 X MICHELIN 295/80R22.5 X MULTI Z 152/149MVM TYRE POS 1 & 2	786562
161	XN87BD	1/01/2019	24577	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	794196
161	XN87BD	22/01/2019	24979	TYRES\ROTATE	ROTATE TYRES	RAY HALL TYRES ROTATED TYRES POS 10 TO 6	803358
161	XN87BD	26/01/2019	24910	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	808761
161	XN87BD	24/02/2019	25287	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	826259
161	XN87BD	15/03/2019	25541	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK TENSIONED U-BOLTS ON STEER AXLE. OUTPUT SHAFT SEAL LEAKING	840934
161	XN87BD	16/04/2019	25833	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	856202
161	XN87BD	17/04/2019	25897	DrivLine	Aftertreatment faults, Leak in rear of gearbox	Brown & Hurley: Connected davie to read aftertreatment faults. Found adblue low level and empty faults. Checked adblue level. Cleared all faults then test drove. Observed adblue level on davie no faults. Found leak at output shaft seal of transmission. Removed bolts from trans output uni and centre bearing to lower tailshaft out of the way. Removed the two bolts out of the yoke and used puller to remove yoke. Removed speedo plug and rear seal carrier housing. Removed speed sensor R&R seal. Refit housing tension yoke bolts and refit shaft with new bolts on uni. Test drove no leaks, check oil ok(TC)	861655
161	XN87BD	21/04/2019	25987	VehService\AS	A SERVICE	COMPLETED A SERVICE ALL OK	870229
161	XN87BD	8/05/2019	26220	VehService\CS	C SERVICE	COMPLETED C SERVICE - ALL OK	886016
161	XN87BD	17/05/2019	26569	WINDSCREEN	Windscreen	Northeast Auto glass - Replaced cracked windscreen	894909
161	XN87BD	17/05/2019	26594	Steering	STEERING SHAKES SOMETIMES	Replaced worn draglink, all ok.	891360
161	XN87BD	17/05/2019	26595	Steering	Steering	Adjusted steering box, all ok.	891360
161	XN87BD	17/05/2019	26596	DrCabElect	Fuel gauge	Replaced faulty fuel sender gauge.	891360
161	XN87BD	21/05/2019	26477	TYRES\ROTATE	ROTATE TYRES	RAY HALL TYRES ROTATED TYRES POS 1 , 2	886016

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	13/06/2019	26679	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	899953
161	XN87BD	13/06/2019	26683	Brakes	ABS BRAKE CABLE BROKEN	REPLACED BROKEN CABLE. ALL OK	899953
161	XN87BD	22/06/2019	26970	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	915252
161	XN87BD	26/06/2019	27027	WAlign\WA	WHEEL ALIGNMENT	BIG WHEELS - SHAKE AND REPORT SLIGHT PLAY IN LH KING PIN. VERY SLIGHT PLAY IN REAR D/LINK END AND BOTH TIE ROD ENDS. STEER TYRES HAVE SLIGHT SHOULDER STEP WEAR ON BOTH INSIDE EDGES. 1ST DRIVE DIFF END TORQUE ROD BUSHES ARE STARTING TO PEEL OUT, NO PLAY.	905444
161	XN87BD	13/07/2019	27453	TYRES\ROTATE	ROTATE TYRES	RAY HALL TYRES ROTATED TYRES POS 1, 2	928341
161	XN87BD	17/07/2019	27274	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	928339
161	XN87BD	25/07/2019	27432	DrivLine	ORANGE CHECK ENGINE LIGHT ON	TOOK TO BROWN AND HURLEY COFFS HARBOUR FOR ENGINE LIGHT, FOUND FAULTY NOX SENSOR, REPLACED ALL OK	930818
161	XN87BD	31/07/2019	27581	DriCabRep\M	Mounts	Replaced front cab mounts.	937892
161	XN87BD	31/07/2019	27584	Brakes\BR	Brakes	Replace LHS front drive brakes and drum.	937892
161	XN87BD	8/08/2019	27568	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	943705
161	XN87BD	23/08/2019	27911	Breakdown\Breakdown	ELECTRICAL	OLIVERI HEAVY VEHICLE REPAIRS - CARRY OUR REPAIRS ON VEHICLE AS PER CUSTOMER REQUEST, REMOVED DAMAGED SUZI COILS, ABS AND ELECTRICAL COILS FOR TRAILER. REMOVED CHECKER PLATE AND STRAIGHTENED. REFIT CHECKER PLATE WITH NEW POGO STICK AND ABS PLUG. FIT NEW SUZI COILS AND ELECTRICAL WIRING FOR TRAILER. REPLACE 3 FUSES FOR TRAILER LIGHTS IN CABIN. CHECK ALL LIGHTS ON TRAILER. ALL OK.	953967
161	XN87BD	3/09/2019	27888	VehService\AS	A SERVICE	A SERVICE COMPLETED AS PER ATTACHED CHECKLIST	958321
161	XN87BD	3/09/2019	27890	COMP\AI	ANNUAL COMPLIANCE INSPECTION	COMPLETED ANNUAL COMPLIANCE INSPECTION - PASSED - ALL OK	958321
161	XN87BD	3/09/2019	27993	DrivLine\DiffOil	DIFF OIL	REPLACED DIFF OIL FILTER AND OIL	958321
161	XN87BD	3/09/2019	27994	DrivLine\TransOil	TRANSMISSION OIL	REPLACED TRANSMISISON OIL AND FILTERS	958321
161	XN87BD	10/09/2019	27968	Engine\CoolL	COOLANT LEAK	REPLACED LEAKING COOLANT HOSE & CLAMP	963509

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	14/09/2019	28084	DrCabElect\AC	AIR CONDITIONING	MURWILLUMBAH CAR & TRUCK ELECTRICS - REMOVED A/C COMPRESSOR AND FIT NEW ONE. REGAS AND LEAK TEST	966919
161	XN87BD	26/09/2019	28111	VehService\CS	C SERVICE	COMPLETED C SERVICE - ALL OK	973943
161	XN87BD	9/11/2019	28548	Engine\NEW	NEW ENGINE	BROWN & HURLEY Transmision wont select gears. Connected laptop, found active fault code, opened clutch with laptop. Tried pushing tab back, couldn't push it back. Carried out in vehicle reset, adjusted clutch - fault went inactive. Drove around yard, fault came active again. Wound caging bolts into clutch, wound bolts out, carried out clutch adjustment - fault went inactive. As soon as try to select gear, brings up active fault code 27. Followed troubleshooting, replacement of clutch was required. Found motor to be pressurizing. Removed and replaced with brand new crate motor.	987817
161	XN87BD	9/11/2019	28549	DrivLine\KPR	King Pins	Replaced worn King pins. All ok	987817
161	XN87BD	9/11/2019	28689	GEARBOX\ClutchPack	Clutch	Removed and replaced worn clutch pack.	987817
161	XN87BD	9/11/2019	28690	Engine	Radiator	Found worn radiator and bonnet mounts, replaced. Engine mounts replaced, all ok.	987817
161	XN87BD	9/11/2019	28691	WBearings\Steer W/B	Wheel bearings	Replaced steer wheel bearings and brake shoes	987817
161	XN87BD	30/11/2019	28908	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	999977
161	XN87BD	21/12/2019	29353	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	15128
161	XN87BD	24/12/2019	29379	Elect\BATT	BATTERIES	REMOVED AND REPLACED BATTERIES	15321
161	XN87BD	19/01/2020	29539	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	29174
161	XN87BD	13/02/2020	30078	DriCabRep\Seat	SEAT AIR LINES	REPAIRED BROKEN AIR LINES TO SEAT	43486
161	XN87BD	14/02/2020	29968	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	44456
161	XN87BD	14/02/2020	29998	DrivLine	DRUM SHOES	REPLACED DRUMS AND SHOES RHS FRONT DRIVE & REAR DRIVE BOTH SIDES	44456

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	26/02/2020	30531	Engine\FCODE	FAULTS	BROWN & HURLEY: K046 Rectify reason for the aftertreatment light on the dash. Inspect problem and read out fault code. Found codes 120, 121, 129 logged. NOx reduction level 2 not met. Inspect and read out NOx readings. Test drive and monitored readings. Found NOx readings after CAT reading higher then before the CAT. Tested adblue concentration to be at 32.5 % OK. Carried out autonomous test and liquid test (125ml) all OK. Found NOx sensors before and after CAT require replacing. Ordered new sensors. Truck had to go and returned 25/2/20. Removed and replaced both NOx sensors with new. Carried out test drive and monitored sensor readings. Found sensors reading correct, no warning and derate during test drive.	54331
161	XN87BD	12/03/2020	30321	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK REPLACED 1 X LIGHT. REPAIRED TAILGATE CORD	61293
161	XN87BD	2/04/2020	30639	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	75573
161	XN87BD	21/04/2020	31244	TYRES\STEER	STEER TYRES	RAY HALL TYRES FIT 2 X FALKEN 295/80R22.5 154/149M RI151 TYRE TO POS 1 & 2	83696
161	XN87BD	3/05/2020	31044	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK FIXED FUEL LEAK	90571
161	XN87BD	29/05/2020	31370	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK REPLACED AIR FILTER. FRONT TORQUE ROD BUSHES NEED REPLACING	106067
161	XN87BD	20/06/2020	31620	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK FRONT DRIVE TOURQUE ROD BUSHES NEED REPLACING	119630
161	XN87BD	14/07/2020	31733	VehService\CS	C SERVICE	COMPLETED C SERVICE - ALL OK	134777
161	XN87BD	14/07/2020	31830	ADBLUE\DiffOil	DIFF OIL	REPLACED DIFF OILS AND FILTER	134777
161	XN87BD	14/07/2020	31831	DrivLine\TransOil	TRANSMISSION OIL	REPLACED TRANSMISSION OIL AND FILTER	134777
161	XN87BD	7/08/2020	32038	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	151390
161	XN87BD	27/08/2020	32239	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	165028
161	XN87BD	12/09/2020	32454	TYRES\DRIVE	DRIVE TYRES	RAY HALL TYRES FIT 8 X FALKEN 11R22.5 146/143L BI830 ECORUN TO POS 5, 6 , 7, 8, 9, 10, 11, 12	129553

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	18/09/2020	32409	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	180801
161	XN87BD	18/09/2020	32551	COMP\AI	ANNUAL COMPLIANCE INSPECTION	COMPLETED ANNUAL COMPLIANCE INSPECTION - PASSED - ALL OK	180801
161	XN87BD	18/09/2020	32567	Engine\EXH	EXHAUST MANIFOLD SEALS	REPLACED LEAKING EXHAUST MANIFOLD SEALS, TEST DROVE, ALL OK	180801
161	XN87BD	19/09/2020	32761	TYRES\STEER	STEER TYRES	RAY HALL TYRES FIT 2 X KUMHO 295/80R22.5 XS10 152/148M TYRE TO POS 1 & 2	180834
161	XN87BD	8/10/2020	32851	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	194113
161	XN87BD	22/10/2020	32929	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK REPLACED DASH LIGHT, TIGHTENED ALL LOOSE DASH SCREW. FUEL TANK NEEDED WELDING, REMOVED TANK & SENT TO MARRISONS TO BE REPAIRED, REINSTALLED. ALL OK.	204930
161	XN87BD	18/11/2020	33275	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	219124
161	XN87BD	7/01/2021	33762	VehService\AS	A SERVICE	COMPLETED 'A' SERVICE, ALL OK	235421
161	XN87BD	7/01/2021	33830	VehService\CS	B SERVICE	COMPLETED B SERVICE, ALL OK. ADJUSTED TURNTABLE NEEDS ALL REAR SHOCKS, FRONT DRIVE BRAKES.	249948
161	XN87BD	13/01/2021	33912	Elect\BATT	STARTER BATTERY	REPLACED STARTER BATTERY	244805
161	XN87BD	26/01/2021	34170	Brakes	BRAKES	REPLACED FRONT DRIVE BRAKE SHOES	256607
161	XN87BD	26/01/2021	34171	Valve Set\VALVE SET	VALVE SET ADJUSTMENT	COMPLETED VALVE SET ADJUSTMENT	256607
161	XN87BD	28/01/2021	34208	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK REPLACED ALL DRIVE SHOCKS. REPLACED BLOWN ENGINE RETARDER DASH LIGHT GLOBE. LHS CAB AIR BAG LEAKING - SHOULD REPLACE BOTH	265382
161	XN87BD	4/02/2021	34272	Engine	GEARBOX	REMOVED AND REPLACED THE GEARBOX OIL COOLER	269272
161	XN87BD	11/02/2021	34935	DriCabRep	CAB AIRBAGS /SHOCKS	REPLACED CAB AIRBAGS AND SHOCKIES	269272
161	XN87BD	13/02/2021	34454	Engine\FTS	TRUCK RUNNING ROUGH	NUMBER 2 UNIT PUMP FAULTY. REPLACED. TEST DROVE. ALL OK.	238948
161	XN87BD	13/02/2021	34455	DriCabRep\WSCR	WINDSCREEN	REPLACED CRACKED WINDSCREEN	238952
161	XN87BD	23/02/2021	34509	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK REPLACED WIPER HEADS, REPLACED SIDE MARKER LED	280317

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	23/02/2021	34604	DrCabElect	BATTERY FOR KOOL KAT AIR NEEDS REPLACING	REPLACED COOLER BATTERIES	280317
161	XN87BD	13/03/2021	34792	AIRCON	NO AIR CONDITIONER	JEFF PRITCHARD - REMOVED FAULTY COMPRESSOR, EVAPORATOR AND TX VALVE. FLUSHED OUT A/C SYSTEM. INSTALLED NEW TX VALVE & REFIT EVAPORATOR. INSTALLED NEW COMPRESSOR AND RECEIVER/DRIER. PRESSURE TESTED. DIAGNOSE LEAKING HOSE. REMOVE, MAKE UP AND INSTALL NEW HOSE. EVACUATE SYSTEM. RECHARGE WITH R134A REFRIGERANT.	291118
161	XN87BD	13/03/2021	34799	DrCabElect\E	WIPERS DON'T TURN OFF	REMOVED AND REPLACED WIPER CONTROL MODULE BEHIND DASH AND INDICATOR STALK AND WIPER MOTOR	291118
161	XN87BD	19/03/2021	34854	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	296531
161	XN87BD	31/03/2021	35171	TYRES\STEER	STEER TYRES	RAY HALL TYRES FIT 2 X SAILUN 295/80R22.5 152M S629 TYRES TO POS 1 & 2	301389
161	XN87BD	17/04/2021	35137	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	309460
161	XN87BD	17/04/2021	35427	Driveline\TR	TIE ROD ENDS	REPLACED BOTH TIE ROD ENDS AND TOOK TO ALL ENGINES TO HAVE DEFECT CLEARED	308293
161	XN87BD	17/04/2021	35528	TYRES\PUNT	PUNCTURE	RAY HALL TYRES REPAIRED PUNCTURE POS 12	309451
161	XN87BD	30/04/2021	35369	DrivLine	WHEN FUEL GAUGE GETS TO 1/2 FUEL IT SHAKES AND IS UNREADABLE	REPLACED FAULTY FUEL GUAGE SENDER UNIT	314900
161	XN87BD	9/05/2021	35512	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK. REPLACED ROOF LIGHT	324911
161	XN87BD	28/05/2021	35773	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	338655
161	XN87BD	28/05/2021	35838	AIRCON	AIR CON FAN/BLOWER ONLY WORKING ON 4	REPLACED FAN SPEED ASSISTER.	338655
161	XN87BD	1/06/2021	35894	TYRES\ROTATE	TYRE ROTATION	RAY HALL TYRES ROTATED TYRES POS 1, 2, 5, 6, 7, 8, 9, 10, 11, 12	338879
161	XN87BD	24/06/2021	36172	VehService\AS	A SERVICE	COMPLETED 'A' SERVICE, ALL OK GEAR BOX OUTPUT SHAFT LEAKING. REAR DRIVE RIGHT SIDE BRAKE LINING LOW.	356416
161	XN87BD	24/06/2021	36190	DrivLine\TransOil	TRANSMISSION	REPLACED TRANSMISSION OIL AND FILTER.	344363
161	XN87BD	24/06/2021	36191	DrivLine\DiffOil	DIFF	REPLACED DIFF OIL AND FILTER	344363
161	XN87BD	30/06/2021	36329	Brakes\BR	BRAKES	REPLACED REAR DRIVE LHS AND RHS BRAKE SHOES	358263

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	8/07/2021	36456	DrivLine\OL	GEARBOX OUTPUT SEAL	REPLACED GEARBOX OUTPUT SEAL	363013
161	XN87BD	17/07/2021	36535	VehService\CS	C SERVICE	COMPLETED C SERVICE - ALL OK REPAIRED TANK WIRING	370174
161	XN87BD	17/07/2021	36565	Engine\OL	RESERVIOR	REPLACED OIL RESERVIOR - ALL OK	370174
161	XN87BD	28/07/2021	36685	Engine\FCODE	ENGINE LIGHT	BROWN AND HURLEY - CHECK AND REPAIR AFTER TREATMENT LIGHT ON. CONNECTED LAPTOP AND FOUND INACTIVE FAULTS FOR CAN COMMUNICATION BREAKDOWN. SOURCED WIRING DIAGRAM, CHECKED ALL POWERS, EARTHS TO NOX SENSORS & EAS UNIT. ALL GOOD. CHECKED RESISTANCE OF TERMINATING RESISTOR & OVERALL BACKBONE RESISTANCE, ALL GOOD. CLEARED FAULTS AND TEST DROVE, NO PROBLEMS OCCURRED. INSPECTED WIRING AND PERFORMED WRIGGLE TEST, NO PROBLEMS FOUND. FASTENED WIRES SECURELY IN ENGINE BAY AREA.	373663
161	XN87BD	7/08/2021	36888	Elec\Breakdown	ELECTRICAL	TRUCK-EEZ - CALL OUT - NO LIGHTS ON TRAILER CHECK AND FOUND BASE PLUG WIRES INCORRECTLY WIRED FOUND AND REPLACE 1 X 30AMP TRAILER ABS FUSE FOUND BROWN AND BLACK WIRES AROUND THE WRONG WAY FIT BLACK WIRE TO CENTER CLEARANCE PLUG ON TRAILER END OF LEAD. CHECK LIGHTS. ALL OK	382728
161	XN87BD	12/08/2021	36897	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK STEER SHOCKS NEED REPLACING	386428

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	27/08/2021	37230	Engine\FCODE	CHECK ENGINE LIGHT COMING ON	BROWN AND HURLEY - CONNECTED LAPTOP AND FOUND ACTIVE CODES FOR ADBLUE AIR PRESSURE TOO HIGH. REMOVED ALL AIR LINES AND CLEANED. TRIED TO REMOVE ADBLUE INJECTOR BUT BOLT SNAPPED OFF IN EXHAUST. TRIED TO REMOVE SNAPPED BOLT BUT WAS UNSUCCESSFUL. REMOVED EXHAUST, SENSORS & CATALYST. DRILLED OLD BOLT AND TAPED. REMOVED INJECTOR AND CLEANED. REFITTED INJECTOR, CATALYST, EXHAUST PIPES AND SENSORS. CLEARED CODES, TEST DROVE AND FAULTS CAME BACK. REMOVED ADBLUE DOSER MODULE, DISASSEMBLED & CLEANED OUT. REFITTED DOSER MODULE, CLEARED CODES AND TEST DROVE. FAULT CAME BACK AGAIN, ORDERED NEW DOSING MODULE. FITTED NEW DOSING MODULE AND TEST DROVE - ALL GOOD	396914
161	XN87BD	4/09/2021	37102	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK REPLACED POWER STEERING RESERVOIR GASKET	398992
161	XN87BD	4/09/2021	37104	COMP\AI	ANNUAL COMPLIANCE INSPECTION	COMPLETED ANNUAL COMPLIANCE INSPECTION - PASSED - ALL OK	398992
161	XN87BD	4/09/2021	37212	Susp\SA	STEER SHOCKS	REPLACED STEER SHOCKS	398992

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	22/09/2021	37411	Engine	FAULTS	BROWN & HURLEY - ENGINE RUNNING ROUGH ON START UP THEN AFTER TREATMENT LIGHT COMES ON. CONNECTED COMPUTER AND FOUND ACTVE CODE IN AFTERTREATMENT FOR NOX BEFORE CATALYST. FOUND FAULT IS CAUSED BY FAULT IN ENGINE SYSTEM. OPENED ENGINE FAULT CODES AND FOUND CYLINDER 1 PERFORMANCE FAULT. LEFT ENGINE IDLING, UNPLUGGED NUMBER 1 UNIT PUMP ENG ENGINE DIDN'T CHANGE. UNPLUGGED NUMBER 3 UNIT PUMP AND ENGINE STARTED RUNNING ROUGHER. REMOVED UNIT PUMP OFF A SECOND HAND ENGINE AND FITTED. STARTED AND TESTED AGAIN. ENGINE MISSED WHEN NUMBER 1 WAS UNPLUGGED. CLEARED FAULTS. ORDERED PART AND VEHICLE RETURNED. REMOVED UNIT PUMP AND FITTED NEW PUMP. PROGRAMMED TO ECU AND STARTED ENGINE -ALL GOOD	396914
161	XN87BD	2/10/2021	37452	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	413877
161	XN87BD	2/10/2021	37466	TYRES\ROTATE	ROTATE TYRES	HALLS TYRES - ROTATE POS 5, 6, 7, 8, 9, 10, 11, 12	413877
161	XN87BD	21/10/2021	37655	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	429050
161	XN87BD	24/10/2021	37722	DriCabRep	WINDOW	REMOVE DOOR CARD AND FAULTY REGULATOR. REPLACE REGULATOR AND REFIT DOOR CARD - TEST - OK	430740
161	XN87BD	5/11/2021	37876	Cooling\RAD	RADIATOR	FOUND RADIATOR TO BE CRACKED NEAR TOP PIPE REMOVED BONNET AND DROPPED ALL COOLANT REMOVED RADIATOR AND SWAPPED ALL CORRESPONDING PARTS ONTO NEW ONE REFITTED RADIATOR AND RUN NEW HOSES AND CLAMPS REASSEMBLED AND TEST DROVE - ALL OK	439440
161	XN87BD	5/11/2021	37877	Engine\ALT	ALTERNATOR	REMOVED AND REPLACED ALTERNATOR	439440
161	XN87BD	5/11/2021	37878	Engine\BLTS	BELTS AND PULLEYS	REMOVED AND REPLACED ALL BELTS, PULLEYS AND TENSIONERS	439440
161	XN87BD	13/11/2021	37916	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	445455
161	XN87BD	2/12/2021	38159	VehService\CS	C SERVICE	COMPLETED C SERVICE - ALL OK	460759

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	19/12/2021	38397	TYRES\DRIVE	DRIVE TYRES	HALLS TYRES - FIT 8 X FALKEN 11R22.5 148/145L BI852 TO POS 5, 6, 7, 8, 9, 10, 11, 12	473948
161	XN87BD	21/12/2021	38349	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	473948
161	XN87BD	21/12/2021	38357	Elect\Radio	REVERSE ALARM	INSTALLED REVERSING SQUARKER	473948
161	XN87BD	11/03/2022	39150	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK REPLACED ADBLUE FILTER AND BOWL	490674
161	XN87BD	1/04/2022	39286	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK REPLACED NUMBER PLATE LIGHT	504329
161	XN87BD	27/04/2022	39982	Elect\BATT	BATTERIES	REPLACED START BATTERIES	509274
161	XN87BD	14/05/2022	39798	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK NEEDS ALL UNI'S & CENTRE BEARING NEEDS ALL BOOSTERS	521145
161	XN87BD	15/05/2022	40877	TYRES\STEER	STEER TYRES	MHTS - AS PER INVOICE 0098 FIT 2 X NEW SAILUN 295/80R22.5 S629 TO POS 1 & 2	521145
161	XN87BD	17/05/2022	39884	Brakes\B	BRAKE BOOSTER	REMOVE AND REPLACE BRAKE BOOSTER AND ADJUST BRAKES	521161
161	XN87BD	5/06/2022	39970	Brakes\BR	DRIVE BRAKES	REMOVE AND REPLACE BRAKE DRUMS, SHOES AND ANCHOR PIN BUSHES ON FIRST DRIVE	531754
161	XN87BD	8/06/2022	40099	DrivLine\E	SPEED SENSOR	REPLACED BOTH SPEED SENSORS ON THE BACK OF THE GEAR BOX	531830
161	XN87BD	17/06/2022	40024	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK NEEDS EXHAUST FLEX AFTER MUFFLER	535745
161	XN87BD	19/06/2022	40068	Engine\EXH	EXHAUST	REPLACED EXHAUST - ALL OK	535486
161	XN87BD	28/06/2022	40166	DrivLine\Uni	UNI JOINTS	REMOVE JACK SHAFT AND MAIN DRIVE SHAFT AND REPLACE 5 UNI JOINTS AND CENTRE BEARING	541130
161	XN87BD	28/06/2022	40167	DrivLine\DiffS	DIFF SEALS	REMOVE AND REPLACE FRONT DIFF THROUGH SHAFT AND PINION SEAL	541130
161	XN87BD	2/07/2022	40199	Valve Set\VALVE SET	VALVE ADJUSTMENT	CARRY OUT VALVE ADJUSTMENT	542835
161	XN87BD	2/07/2022	40200	DrivLine\FwdDiff	FRONT DIFF	RE-SEAL FRONT DIFF	542835
161	XN87BD	2/07/2022	40201	WBearings\Replace	WHEEL BEARINGS	REMOVE AND REPLACE ALL DRIVE WHEEL BEARINGS AND SEALS	542835
161	XN87BD	2/07/2022	40202	DrivLine\TransOil	TRANSMISSION OIL CHANGE	REPLACE GEARBOX OIL AND FILTER	542835
161	XN87BD	2/07/2022	40203	DrivLine\DiffOil	DIFF OIL CHANGE	REPLACED DIFF OILS AND FILTER	542835

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	16/07/2022	40440	Susp	TORQUE RODS	REMOVED 5TH WHEEL TO ACCESS FRONT TWO TORQUE RODS. REMOVED AND REPLACED ALL REAR TORQUE RODS AND CHECKED TENSION OF CROSS MEMBER BOLTS	557987
161	XN87BD	21/07/2022	40644	VehService\CS	C SERVICE	COMPLETED C SERVICE - ALL OK	549433
161	XN87BD	21/07/2022	41639	DriCabRep	SPEEDO & SENSOR	REPLACED SPEEDO AND SPEED SENSOR	549433
161	XN87BD	27/07/2022	40666	Engine\Comp	COMPRESSOR	DRAIN COOLANT AND REMOVE COMPONENTS TO GAIN ACCESS TO AIR COMPRESSOR REMOVE COMPRESSOR. REPLACE COMPRESSOR AND REFIT COMPONENTS. FILL WITH COOLANT, REPLACE FUEL FILTER, BLEED SYSTEM AND ROAD TEST - ALL OK	549548
161	XN87BD	28/08/2022	41191	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK REPLACED AIR DRIER CHECKED DRIVE WHEEL BEARINGS - ALL OK	566049
161	XN87BD	10/09/2022	41389	COMP\AI	ANNUAL COMPLIANCE INSPECTION	COMPLETED ANNUAL COMPLIANCE INSPECTION - PASSED - ALL OK	573214
161	XN87BD	10/09/2022	41429	Brakes\B	BRAKE BOOSTER	REMOVED AND REPLACED LEFT HAND SIDE FRONT DRIVE BOOSTER	573214
161	XN87BD	22/09/2022	41554	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	578953
161	XN87BD	23/10/2022	42210	TYRES\STEER	STEER TYRES	MOORES HEAVY TYRE SERVICE- AS PER INVOICE 0574 ROTATE POS 1 & 2	591696
161	XN87BD	4/11/2022	42022	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK PUT RUBBER UNDER COOLANT PIPE REPLACED MIRROR LIGHT	594563
161	XN87BD	23/11/2022	42260	Brakes	BRAKES	REMOVED AND REPLACED REAR DRIVE BRAKES, DRUMS AND ADJUSTED WHEEL BEARINGS	599580
161	XN87BD	23/11/2022	42261	Brakes\B	DRIVE BOOSTERS	REPLACED 2 X REAR DRIVE BOOSTERS	599580

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	23/11/2022	42690	GEARBOX	GEARBOX NEUTRALISES INTERMITANTLY	BROWN & HURLEY - Check gearbox neutralises intermitantly, warning lights on dash EBS,ABS - resets after power down at isolator. Hooked up laptop and found faults for ECA and clutch mechanical failure. Checked ECA readings, and tried to perform various tests, tests would fail. ECA likely failed. Removed and replaced ECA as required. Performed a clutch adjustment and performed tests. All tests passed. Cleared faults and reset grease interval. Hooked up Bendix and found active faults for right hand rear drive output low at drive off and another fault relating to road speed. Released brakes and jacked up. Checked output on Bendix and found to be all good. Inspected harness and bearing end float, found bearing to have movement on both LH and RH side. Possible cause of fault occurring intermittently. Cleared faults and test drove. Rechecked work. All good.	599570
161	XN87BD	26/11/2022	42267	Brakes\B	BRAKE BOOSTERS	REMOVED AND REPLACED STEER BOOSTERS	600379
161	XN87BD	31/12/2022	42608	VehService\BS	B SERVICE	COMPLETED 'B' SERVICE - ALL OK REPLACED SIDE MARKER LIGHT	608425
161	XN87BD	4/01/2023	42700	Elect\BATT	BATTERIES	REPLACED DEAD START BATTERIES	608426
161	XN87BD	10/01/2023	43462	DriCabRep\WSCR	WINDSCREEN	NORTHEAST AUTOGLASS- AS PER INVOICE 13879 REPLACED WINDSCREEN	
161	XN87BD	4/03/2023	43155	VehService\AS	A SERVICE	COMPLETED 'A' SERVICE - ALL OK NEEDS POWER STEERING HOSES LEFT HAND SIDE 4 X MUDGUARD BRACKETS NEED DOING	623991
161	XN87BD	12/03/2023	43650	Chassis\Mud	MUDGUARD	REPLACED BROKEN MUDGUARD BRACKETS AND HUBCAP	625528
161	XN87BD	22/03/2023	43437	Engine\WP	WATER PUMP	REMOVED AND REPLACED THERMOSTAT, WATER PUMP AND HOSES	626998
161	XN87BD	22/03/2023	43438	Engine\BLTS	BELTS & PULLEYS	REMOVED AND REPLACED ALL BELTS AND PULLEYS	626998
161	XN87BD	22/03/2023	43439	Engine\Turbo	TURBO	REMOVED AND REPLACED TURBO AND EXHAUST MANIFOLD GASKETS AND BOOST HOSES. REFILL WITH COOLANT AND ROAD TEST - ALL OK	626998

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	22/03/2023	43440	Chassis\Mud	MUDGUARD	REPLACED REAR MUDGUARD AND LOOP KIT	626998
161	XN87BD	22/03/2023	43441	Steering\OL	POWER STEERING LEAK	REMOVED POWER STEERING HOSES AND GET NEW HOSES MADE. FITTED NEW HOSES	626998
161	XN87BD	22/03/2023	43442	Elect\ALT2	ALTERNATOR	REMOVED AND REPLACED ALTERNATOR - ALL OK	626998
161	XN87BD	22/03/2023	43443	Elect\SM	STARTER MOTOR	REMOVED AND REPLACED STARTER MOTOR - ALL OK	626998
161	XN87BD	9/04/2023	44557	TYRES\DRIVE	DRIVE TYRES	MHTS – AS PER INV 1067 FIT 8 X NEW FALKEN 11R22.5 148/145L BI852 TO POS 5, 6, 7, 8, 9, 10, 11, 12.	631001
161	XN87BD	10/05/2023	44098	DrivLine	ABS SENSORS	REPLACED ALL ABS SENSORS - ALL OK	637857
161	XN87BD	18/05/2023	44105	VehService\CS	C SERVICE	COMPLETED 'C' SERVICE - ALL OK	639825
161	XN87BD	18/06/2023	44729	Elect\BATT	BATTERIES	REPLACED BATTERIES	647740
161	XN87BD	22/06/2023	47591	Engine\EL	Engine\EL	BROWN & HURLEY - Connected computer and found active code 120-0, NOx concentration Level 1, followed trouble shooting, checked ad-blue concentration, it was all good. Removed ad-blue injector and cleaned injector (2 holes were blocked) ran an ad-blue test, results came back good. Had to repair threads for injector hold down bolt and replace bolt. Test drive and check before and after catalyst readings, after test drive fault code went inactive and results were good on test drive.	648325
161	XN87BD	26/06/2023	44854	Engine\FCODE	ORANGE CHECK ENGINE LIGHT IS ON	BROWN & HURLEY - Hooked up laptop and checked for fault codes. Found active code for NOX reduction efficiency not reached. Searched explanatory notes. Checked urea concentration. All good. Test drove and checked NOX readings, found before sensor to drop out. Removed and replaced before sensor checking power and earth to sensor, all good. Test drove again to confirm. All good. To be monitored.	648645
161	XN87BD	15/07/2023	44913	VehService\AS	A Service	COMPLETED 'A' SERVICE - ALL OK TIGHTENED WALKWAY CLAMPS	653660
161	XN87BD	20/07/2023	44965	Steering\Uni	Steering\Uni	REMOVED AND REPLACED 2 X WORN STEERING UNIJOINTS	654502

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	3/08/2023	45073	Susp	Susp	REMOVED AND REPLACED FRONT SHACKLE PINS AND BUSHES. WELDED ALL BUSHES ON SPRING EYES. REGREASED - ALL OK	656708
161	XN87BD	5/08/2023	45059	Elect\BATT	Elect\Batt	BATTERIES NOT HOLDING CHARGE - REPLACED X 2	656708
161	XN87BD	6/08/2023	45060	Elect\ALT1	Elect\ALT1	REMOVED AND REPLACED A FAULTY ALTERNATOR	656708
161	XN87BD	1/09/2023	45904	TYRES\STEER	TYRES\STEER	MHTS - AS PER INV 1573 FIT 2 X NEW BRIDGESTONE 295/80R22.5 152M R150 TO POS 1 & 2	662336
161	XN87BD	7/09/2023	45323	COMP\AI	ANNUAL COMPLIANCE INSPECTION	COMPLETED ANNUAL COMPLIANCE INSPECTION - PASSED - ALL OK	664451
161	XN87BD	22/09/2023	45463	VehService\BS	B SERVICE	COMPLETED 'B' SERVICE - ALL OK	668905
161	XN87BD	3/10/2023	45579	Engine\FCODE	Engine\Fcode	CHECKED FAULT CODES. REMOVED AND REPLACED FUEL PRESSURE SENSOR.	670292
161	XN87BD	23/11/2023	46037	VehService\AS	A SERVICE	COMPLETED 'A' SERVICE - ALL OK - CLEARED WINDSCREEN WASHER HOSES - REPLACED 2 ROD LIGHTS AND BOTH NUMBER PLATE LIGHTS	684458
161	XN87BD	28/12/2023	46280	Chassis	Chassis	FOUND HOLE FROM ROCK IN ADBLUE TANK. REMOVED BATTERIES AND COVERS AROUND ADBLUE TANK. REMOVED ADBLUE TANK AND TRANSFERRED OVER PICK AND LEVEL SENSOR TO NEW TANK. MOUNTED NEW ADBLUE TANK. REASSEMBLED COVERS AND PUT BATTERIES BACK IN. FILLED WITH ADBLUE, TEST DROVE - ALL OK	692274
161	XN87BD	3/02/2024	46605	VehService\BS	B SERVICE	COMPLETED 'B' SERVICE - ALL OK	699218
161	XN87BD	17/02/2024	46740	Body\AL	Body\AL	REPLACED LEAKING AIR FITTINGS ON FIRE WALL	702210
161	XN87BD	27/02/2024	46789	Chassis\AB	Chassis\AB	REMOVED AND REPLACED ALL DRIVE AIRBAGS	704624
161	XN87BD	27/02/2024	46790	DriCabRep	DriCabRep	REMOVED AND REPLACED CAB SHOCKS	704624
161	XN87BD	3/04/2024	47098	VehService\AS	A SERVICE	COMPLETED 'A' SERVICE - ALL OK REPLACED HORSE SHOE.	713583
161	XN87BD	13/04/2024	47270	Lights\Lights	PARK LIGHT DRIVERS SIDE AT FUEL TANK IS OUT	REPLACED RIGHT HAND TANK LIGHT	716134
161	XN87BD	26/04/2024	47372	DrivLine\DiffOil	DIFF OIL CHANGE	REMOVED AND REPLACED DIFF OILS AND FILTER	718222
161	XN87BD	26/04/2024	47373	DrivLine\TransOil	TRANSMISSION OIL CHANGE	REMOVED AND REPLACED TRANSMISSION OIL AND FILTER	718222

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	26/04/2024	47374	DrivLine\WB	DrivLine\WB	PULLED APART 1ST DRIVE LEFT HAND SIDE AND FOUND STUB TO HAVE BEEN HOT. REMOVED AND REPLACED WHEEL BEARING AND SEAL. TEST DROVE - ALL OK	718222
161	XN87BD	27/04/2024	47422	TYRES\PUNT	TYRES\PUNT	MHTS - AS PER INV 2257. PATCH & REPAIR TYRE POS 9	718224
161	XN87BD	30/04/2024	47460	Engine\-	ENGINE	BROWN & HURLEY - Exhaust manifold leak: Exhaust manifold leak on cylinders 1, 2 and 6. Remove air intake pipes and air cleaners, remove blow by hose, remove boost pipes, remove heat shields, remove exhaust studs and hold the exhaust manifold away from the block, remove old exhaust manifold gaskets, clean both manifold and head mating surfaces, install new gaskets, clean manifold studs and put anti seize on threads and torque up to required spec, reinstall heat shield covers, put boost pipe back on, put on blowby hose, reinstall air intake pipes and air cleaners, start and run and check for leaks.	718989
161	XN87BD	30/04/2024	47460	Engine\-	ENGINE	BROWN & HURLEY - Diesel leak near back of engine LHS: inspect for fuel leak, washdown motor, test drive truck, reinspect for fuel leak, weeping out of cylinder number 5 and 6 injector line going into cylinder head, unbolt fuel pro housing, un bolt quarter guard, loosen windscreen washer bottle, jack cab on the LHS slightly for removal of injector lines, remove both injector lines going to cylinder 5 and 6, install new injector lines and torque to required spec, let cab down and tighten cab mount bolts, reinstall LH quarter guard, reinstall fuel pro filter housing, bleed fuel system, start and test drive truck and check for leaks.	718989

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	30/04/2024	47460	Engine\-	ENGINE	BROWN & HURLEY - Engine Light - ABS/ESC light intermittent: Connected Bendix software and checked fault codes. Found 3x inactive fault codes with high counts for R/H rear drive wheel speed sensor. Inspected R/H drive rear axle wheel bearing and found to have excessive movement. Remove axle shaft, remove wheels, remove wheel speed sensor, adjust wheel bearings, cleaned & reinstall wheel speed sensor and set to correct distance required as per manufacturer spec, reinstall wheels. Cleared fault codes and test drove- OK	718989
161	XN87BD	18/06/2024	47763	VehService\CS	C SERVICE	COMPLETED 'C' SERVICE - ALL OK	729973
161	XN87BD	19/07/2024	47984	Valve Set\VALVE SET	Valve Set Adjustment	COMPLETED VALVE ADJUSTMENT - ALL OK	736991
161	XN87BD	19/07/2024	47985	AIRCON\AC	AIRCON	REPLACED A/C PRESSURE SENSOR	736991
161	XN87BD	3/09/2024	48398	Chassis\EXH	EXHAUST	REMOVED AND REPLACED EXHAUST STACK SHROUD	740589
161	XN87BD	20/11/2024	48874	COMP\AI	ANNUAL COMPLIANCE INSPECTION	COMPLETED ANNUAL COMPLIANCE INSPECTION - PASSED - ALL OK. TIGHTENED ALL WALKWAY CLAMPS AND GUARDS. REPLACED MISSING BOLTS ON MOTOR. ADJUSTED TURNTABLE AND REPLACED A WORN HORSESHOE	742384
161	XN87BD	20/11/2024	48998	Elect\BATT	BATTERIES	REMOVED AND REPLACED BATTERIES	741419
161	XN87BD	2/12/2024	48951	VehService\AS	A SERVICE	COMPLETED 'A' SERVICE - ALL OK. REMOVED AND REPLACED FAULTY MIRROR LIGHT	743867
161	XN87BD	4/02/2025	49510	DriCabRep\AL	DriCabRep\AL	REMOVED AND REPLACED FAULTY FOOT BRAKE VALVE AND 1 X FITTING	749908
161	XN87BD	21/02/2025	49604	Elect\Lights	RIGHT FRONT INDICATOR NOT WORKING	REMOVED AND REPLACED FAILED INDICATOR IN BONNET	751737
161	XN87BD	14/03/2025	49836	AIRCON\AC	AIR CON ONLY GOES WHEN FAN IS ON 4	FITTED NEW A/C FAN SPEED RESISTOR	753891
161	XN87BD	18/03/2025	49835	Chassis\Mud	MUDGUARD	REMOVED AND REPLACED REAR RIGHT HAND SIDE MUDGUARD	753893
161	XN87BD	3/04/2025	50049	TYRES\PUNT	PUNCTURE	MHTS - AS PER INV 3274. PATCH & REPAIR TYRE POS 12.	755101

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	8/05/2025	50208	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK. NEEDS REAR AXLE TYRES	759083
161	XN87BD	16/05/2025	50373	TYRES\DRIVE	DRIVE TYRES	MHTS - AS PER INV 3401. FIT 4 X NEW NEWPOWER 11R22.5 ND870 TO POS 9, 10, 11, 12.	760363
161	XN87BD	31/05/2025	50457	Chassis\TT	JAGGED WIRE ON TURNTABLE LOCK HANDLE RELEASE	REPLACED A WORN TURNTABLE PULL CORD	762182
161	XN87BD	13/06/2025	50540	Elect\E	EBS PLUG GOT RIPPED OFF	INSTALLED NEW EBS LEAD ON TRUCK	764721
161	XN87BD	5/07/2025	50660	Elect\Lights	LEFT REVERSE LIGHT NOT WORKING	REMOVED AND REPLACED RIGHT HAND TAIL LIGHT AND LEFT HAND REVERSE LIGHT. CLEANED WIRING AND TESTED	766805
161	XN87BD	23/07/2025	50940	TYRES\STEER	STEER TYRES	MHTS - AS PER INV 3585. FIT 2 X NEW BRIDGESTONE 295/80R22.5 152M R150 TO POS 1 & 2.	766808
161	XN87BD	18/10/2025	51458	AIRCON\AC	AIR CON HAS BEEN GETTING LESS FUNCTIONAL	JEFF PRITCHARD - AS PER INV 5945. Test for A/C intermittent fault. Diagnose & replace faulty connector at pressure switch.	772942
161	XN87BD	20/10/2025	51438	COMP\AI	ANNUAL COMPLIANCE INSPECTION	COMPLETED ANNUAL COMPLIANCE INSPECTION - PASSED - ALL OK. REMOVED AND REPLACED 3 X CLEARANCE LIGHTS ON LEFT HAND SIDE WING	772943
161	XN87BD	23/10/2025	51439	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK	773640
161	XN87BD	31/10/2025	51940	TYRES\ROTATE	ROTATE TYRES	MHTS - AS PER INV 3930. ROTATE TYRES POS 9, 10, 11, 12 TO POS 5, 6, 7, 8.	774222
161	XN87BD	31/10/2025	51941	TYRES\DRIVE	DRIVE TYRES	MHTS - AS PER INV 3930. FIT 4 X FALKEN 11R22.5 BI852 TO POS 9, 10, 11, 12.	774222
161	XN87BD	18/12/2025	51800	Brakes\-	BRAKE PEDAL WASNT SPRINGING BACK UP AND BRAKES WERE REMAINING LOCKED ON AT LOW SPEED.	REMOVED DAMAGED BRAKE PEDAL AND TREADLE VALVE. REPLACED VALVE, 2 X FITTINGS, EXTENDED 2 X AIR LINES. REPLACED PEDAL AND NEATENED ALL PLATES AND AIRLINES UP. MOUNTED ALL BACK UP AND TESTED - ALL OK	782459
161	XN87BD	16/01/2026	52014	AIRCON\AC	FAN NOT GOING PROPERLY.	REMOVED DASH PANELS TO GET TO BLOWER MOTOR. REMOVED AND REPLACED BLOWER MOTOR. REASSEMBLED AND TESTED - ALL OK	787340
161	XN87BD	28/01/2026	52013	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK. NEEDS FLEX PIPE ON EXHAUST	789063

UNIT	REGO	DATE	JOB NO.	CODE\SUBCODE	DESCRIPTION	COMPLETION COMMENTS	ODOMETER
161	XN87BD	31/01/2026	52085	EXH\EXH	EXHAUST	REMOVED AND REPLACED A BROKEN EXHAUST FLEX PIPE	789604
161	XN87BD	16/04/2026	52630	VehService\AS	A SERVICE	COMPLETED A SERVICE - ALL OK.	803915
161	XN87BD	24/04/2026	52750	DriCabRep\WBW	WINDSCREEN WASHER 3 WAY ADAPTOR BROKEN	REPLACED WINDSCREEN WASHER JOINER	805493
161	XN87BD	24/04/2026	52752	Engine\EL	AFTER TREAT LIGHT HAS COME ON	REPLACED 2 X BEFORE AND AFTER NOX SENSORS	805493
161	XN87BD	13/05/2026	52943	Elect\Lights	RIGHT HEADLIGHT FLICKERING	REPLACED HEADLIGHT	807817
161	XN87BD	13/05/2026	52944	Chassis\Mud	SPLIT MUDFLAP ON LEFT SIDE	REMOVED AND REPLACED BOTH FRONT DRIVE MUDFLAPS	807817
161	XN87BD	13/05/2026	52948	Engine\BLTREP	BELT REPLACEMENT	FOUND ENGINE BELTS WERE VERY WORN SO REMOVED AND REPLACED BOTH BELTS.	807817
161	XN87BD	14/07/2026	53265	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK	818331
161	XN87BD	24/09/2026	53798	COMP\AI	ANNUAL COMPLIANCE INSPECTION	COMPLETED ANNUAL COMPLIANCE INSPECTION - PASSED - ALL OK. REPLACED POWERSTEERING, AIRDRYER, AIR OIL AND AIR FILTERS. REPLACED STEER SHOCKS. REPLACED MARKER ON BACK OF CAB. ADJUSTED TURNTABLE.	831820
161	XN87BD	28/10/2026	54017	VehService\AS	A SERVICE	COMPLETED 'A' SERVICE - ALL OK	836588