FE 20-3



Chevallier Geo-Con Ltd. Bay 1 4027-44 Street Box 2040, Rocky Mountain House, Alberta T4T 1B5 403-844-2736

# Track Hoe Check List(NOT A WORK ORDER)

# Information **\bigcap 405** Field (General) Tuesday, April 2nd 2024, 2:53 PM (MDT -06:00) Information Date Inspection completed March 6, 2025 Hour meter Reading # 9771.5 **Checked By Austin Leavitt Unit Number** # 405 Condition Visual condition- Cracks, Leaks, Dents, Missing Etc ( Safe Oil, Fuel, Hydraulic Levels, Planetary Oil

Air Filters

Safe

(♥ Safe

Antifreeze Level, Color

Safe, Minor Defect, Fix Now

Low/added coolant

Fan Belts

Safe

**Emergency Shut Off** 

Safe

Hydraulic Hoses, Leaks

**⊘** Safe

Rollers, Pads, Bolts

<b>⊘</b> Safe	
Track Tension	
<b>⊘</b> Safe	
Bucket Condition (Teeth-cutting edge)	
<b>⊘</b> Safe	
Attached Properly (no missing bolts etc)	
Safe	
Boom moves freely	
<b>⊘</b> Safe	
Hydraulic Cylinder	
<b>⊘</b> Safe	
Thumb	
<b>⊘</b> Safe	
Cage in Front	
<b>⊘</b> Safe	
Yes No NA Greased?	
Hood Secure	
<b>⊘</b> Safe	
Glass, Mirrors, Lights	
Safe, Minor Defect	
One light out on cab	
Wiper Blade & Arm	
Safe	
Yes No NA General House Keeping	
Fire Extinguisher Expiry Date	🖽 January 9, 2025
First Aid Kit/Fire Extinguisher Condition  Safe	
-	
Radio/Gauges/Lights(warning)  Safe	
Seat Suspension	
Safe	

	_		
	_	•	Heater
~,	L.		MEATER



Safe

No

Yes



Lock Out Tag in Hoe?

Yes No



Grease Gun & Grease

### **Back Up Alarm**



### **Park Brake Function**



#### Horn





Fire standby equipment: Fire Spade, Backpack Water Sprayer

Is there a proper size clevis in the hoe? If not then one is needed.

Yes

### Original

## Austin Leavitt, Operator/labourer



April 2nd 2024, 2:53 PM (MDT -06:00)



52.3612894, -114.9051654

OK\_

# Revised on March 6th 2025, 1:47 PM (MST-07:00) Current View Travis Hansen(Sub), Operator(Sub) March 6th 2025, 1:47 PM (MST-07:00)



Safe

Chevallier Geo-Con Ltd Bay 1 4027-44 Street Box 2040 Rocky Mountain House, Albert T4T 1B 403-844-273

# Track Hoe Check List

Information		
<b>\( \)</b> 405		· · · · · · · · · · · · · · · · · · ·
Pield (General)		
Tuesday, December 3rd 2024, 2:55 PM [MST -07:00]		
Information		
Date Inspection completed		December 3, 2024
Hour meter Reading	#	9710
Checked By	<b>+</b>	Austin Leavitt
Unite Microsch co.		
Unit Number	#	405
Condition		
/isual condition- Cracks, Leaks, Dents, Missing Etc		
Safe		
Dil, Fuel, Hydraulic Levels, Planetary Oil		
<b>⊘</b> Safe		
air Filters		
<b>⊘</b> Safe		
ntifreeze Level, Color		
Safe		
an Belts		
Safe		
•		
mergency Shut Off		

	1	
Safe	.)	
	e e e e e e e e e e e e e e e e e e e	
Seat Suspension		

Safe

A/C & Heater

Safe

Yes

No

NA

Lock Out Tag in Hoe?

Yes

io N

Grease Gun & Grease

Back Up Alarm

Safe

**Park Brake Function** 

Safe

Horn



Yes



NI A

Fire standby equipment: Fire Spade, Backpack Water Sprayer

Is there a proper size clevis in the hoe? If not then one is needed.

Yes

### **Signatures**

Austin Leavitt, Operator/labourer

December 3rd 2024, 2:55 PM [MST -07:00]

0

52.3738249, -114.9195874

O.L



office

Chevallier Geo-Con Ltd Bay 1 4027-44 Street Box 2040 Rocky Mountain House, Alberta T4T 1B! 403-844-2736

# **Equipment Fall Check List**

Info	rmation	1		1. 	The second secon
$\Box$	405 fall	checkli	ist		
0	Field (Ge	eneral)			
	Monday	, Septe	ember 23rd 2024, 2:03 PM (MDT -06:00)	and the second s	•
		·	·:		
Equ	ipment	Info	and the second s	مشاهواندراد واستورستير بيرا أيسوس	
Date	of Inspec	ction		<b>=</b>	September 23, 2024
	ected By		and the second seco	*	Austin Leavitt
Unit	Number		en e	#	405
	r Meter R			#	9709.5
			<b>F</b> (1)		<b>*</b>
iter	ns To C	heck			
Anti	freeze Le	vel			
0	Full				
Yes	No No	NA	Is Antifreeze Temp Good to -40c?		
Wha	et is Batte	ery Vol	tage Reading?	=	27.9
					and the second of the second o
Yes	s No	NA	If Voltage is low, hook solar charger dire	ctly to batteries, not	through Master Switch
Cur	rent fuel			=	· Full
Ye	s No	NA	Add fuel conditioner (amount dependen	t on fuel level)	
Ye	s No	NA	Drain Fuel Water Separator	garan samuran	
Ye	s No	NA	Change Fuel Filters	and the second s	
	) No	 NA	Check heater blower - Does it work?	and the second second second	

(Yes)	No NA	Check heater blo	ower - ' blowing hot air?			) 	<del></del>	A
<b>⊘</b>	Shut Maste	r Switch OFF			e a succession de la companya de la			
<b>⊘</b>	Make sure I	Mice havnt started	nesting in the cab, check ur	nder the seat air ver	nts etc. Garbage r	must be cleaned out		
Corre	ctive Actio	on S					the second was a reconstruction over the state of	
What A	Action was ne	eeded?						
= '	Nada,					and the second of the second o	•	
Action	was by who	m?		<b>*</b>	Austin Leavitt			
Action	Date?	and the second s			September 23,	2024		
Empl	oyee Sign	ature						· · · · · · · · · · · · · · · · · · ·
Signat	ture			*	Austin Leavitt			

## Signatures

Austin Leavitt, Operator/labourer

September 23rd 2024, 2:03 PM [MDT -06:00]

52.3617771, -114.9050996

OF



Chevallier Geo-Con Ltd. Bay 1 4027-44 Street Box 2040, Rocky Mountain House, Alberta T4T 1B5 403-844-2736

## Work Order

Info	ormation		
	405		
0	Field (General)		
	Thursday, April 11th 2024, 1:19 PM (MDT -06:00)		
Equ	lipment Needing Worked On		
Unit	Number	=	405
Hou	rs	#	9670
Ord	ered By	<u> </u>	Travis Hansen(Sub)
Date	•		April 10, 2024
Mai	ntenance Required		
Maiı	ntenance Needed		
<b>=</b>	250 hr service		
	Repair lights		
	Fixed oil leak on boom		
	Fixed window latch		
	Inspected bucket cylinder		
	Fixed hydraulic pipe hold downs on the boom		

Completed By

Travis Hansen(Sub)

**Parts Required** 

**Mechanics Comments** 

**Signatures** 

Travis Hansen(Sub), Operator(Sub)

April 11th 2024, 1:19 PM (MDT -06:00)

Jen Je



14

1

Chevallier Geo-Con Ltd. Bay 1 4027-44 Street Box 2040, Rocky Mountain House, Alberta T4T 1B5 403-844-2736

# Track Hoe Check List

April 2, 2024

**Austin Leavitt** 

9641

405

# Information **405** Pield (General) Tuesday, April 2nd 2024, 2:53 PM (MDT -06:00) Information Date Inspection completed Hour meter Reading Checked By **Unit Number** Condition Visual condition- Cracks, Leaks, Dents, Missing Etc Safe Oil, Fuel, Hydraulic Levels, Planetary Oil ( Safe **Air Filters** Safe Antifreeze Level, Color Safe, Minor Defect, Fix Now Low/added coolant **Fan Belts ⊘** Safe **Emergency Shut Off**

Safe

(♥ Safe

**Hydraulic Hoses, Leaks** 

Rollers, Pads, Bolts

<b>⊘</b> Safe		
Track Tension		
<b>⊘</b> Safe		
Bucket Condition (Tee	eth-cutting edge)	and the second of the second o
Safe		
Attached Properly (no	missing bolts etc)	and the state of the second of
Safe		
Boom moves freely	er den er i ster er <del>en mene med den</del> den er er er en er	e Carlos Marianos (1996), e en esta de maria e maria e en e
Safe		
Hydraulic Cylinder		and the second of the second o
Safe		
Thumb		en de la companya de La companya de la co
Safe		
Cage in Front		
Safe		
Yes No NA Gre	ased?	
Hood Secure		
Safe		
Glass, Mirrors, Lights		
Safe, Minor Defect	t	
One light out on call	b	
Wiper Blade & Arm		
Safe		
	· · · · · · · · · · · · · · · · · · ·	

No NA General House Keeping

Fire Extinguisher Expiry Date

iii January 9, 2025

First Aid Kit/Fire Extinguisher Condition

Safe

Radio/Gauges/Lights(warning)

Safe

**Seat Suspension** 

Safe

### A/C & Heater

Safe

4



Lock Out Tag in Hoe?

No



Grease Gun & Grease

### **Back Up Alarm**

Safe

### **Park Brake Function**

Safe

### Horn



Fire standby equipment: Fire Spade, Backpack Water Sprayer

Is there a proper size clevis in the hoe? If not then one is needed.

Yes

### **Signatures**

### Austin Leavitt, Operator/labourer

April 2nd 2024, 2:53 PM (MDT -06:00)

52.3612894, -114.9051654



Chevallier Geo-Con Ltd.
Bay 1 4027-44 Street Box 2040, Rocky Mountain House,
Alberta T4T 1B5
403-844-2736

# **Track Hoe Check List**

Label





Chevallier Shop



Tuesday, May 24th 2022, 10:47 AM (MDT -06:00)

### Information

Date Inspection completed

May 24, 2022

Hour meter Reading

8432

Checked By

> Jessie Cinnamon

Unit Number

403

#### Condition

Visual condition- Cracks, Leaks, Dents, Missing Etc

Safe

Oil, Fuel, Hydraulic Levels, Planetary Oil

> Safe

Air Filters

> Safe, Minor Defect, Fix Now

Replaced outer air filter

Antifreeze Level, Color

Fan Belts

Safe

**Emergency Shut Off** 

> Safe

Hydraulic Hoses, Leaks

Safe

Rollers, Pads, Bolts

Safe

Track Tension

```
· Safe
  Bucket Condition (Teeth-cutting edge)
   > Safe
  Attached Properly (no missing bolts etc)
   > Safe
  Boom moves freely
   > Safe
  Hydraulic Cylinder
   > Safe
  Thumb
   > Safe
  Cage in Front
   > Safe
   YES NO N/A
                  Greased?
 Hood Secure
  > Safe
 Glass, Mirrors, Lights
  > Safe
 Wiper Blade & Arm
  > Safe
  YES NO N/A General House Keeping
 Fire Extinguisher Expiry Date
                                                             January 13, 2023
First Aid Fire Extinguisher Condition
  > Safe
Radio/Gauges/Lights(warning)
  Safe
Seat Suspension
  Safe
A/C & Heater
 > Safe
      SC N/A
               Lock Out Tag in Hoe?
          MZA
                Grease Gun & Grease
Back Up Alarm
Park Brake Function
```

Horn

. 🗦 "Safe

ves. N/A Fire standby equipment: Fire Spade, Backpack Water Sprayer

**Jessie Cinnamon,** *Operator/labourer* May 24th 2022, 10:47 AM (MDT -06:00)

Q 52.3615713, -114.9046176

Edd eim

# CHEVALLIER GEO-CON LTD.

Hoe	<b>)</b> .			Check List
Es:	77	75	`	CHOCK EIGE

Date: Feb 27/7c70	Client:
Location: Shop	Unit #: +405
Checked By: Checked By:	Hours: 6569

Condition:	Safe	Unsafe	Major Defect	Minor Defect	Fix Now	Fix Later	Comments:
Visual Condition –							Comments.
cracks, leaks, dents,	\i/					j	
missing, broken							1
Oil, Fuel, Hydraulic							
Levels, Planetary Oil						l	
Air Filters							
Antifreeze Level and							
Color	$  \vee  $	1					
Fan Belts							
Emergency Shut-off							
Hydraulic Hoses, Leaks	1 7						
Rollers, Pads, bolts	1,7						
Track Tension	1						
Bucket Condition	1 1/1						
Attached Properly	1 / 1						
Boom Moves Freely	1 1						
Hydraulic Cylinder	<del>                                     </del>						
Thumb	<del>  ,/  </del>						
Cage in Front	<del>  '/- -</del>		+				
Greased	<del>  \/  </del>						
Hood Secured	<del> </del>						
Glass, Mirrors, Lights	<del>                                     </del>			<del>+</del>			
Wiper Blade & Arm	1 7. 1						
General Housekeeping	<del>                                     </del>						
First Aid Kit / Fire	<del>-                                    </del>						
Extinguisher						į,	× 19 211
Radio/gauges/lights-idiot	_/-						Expires Jan 2021 = 9 216
Seat suspension	/						
A/C / Heater	./-						
Lock Out Tag	1/						
Grease Gun & Grease				<del></del>			
Spare Grease Nipples(5)							Tagar Na
Back Up Alarm							
Park Brake Functioning	<del></del>						
Horn	<del>-                                    </del>						
Fire Standby:	<u> </u>	<del></del>					રેમૂર.
Fire Spade	<del></del>						
Backpack Water Sprayer		<del></del>	<del></del>				
Taker opicayer							

Signature:	Weavitt	
------------	---------	--

CHEVALLIER	GEO-CC
CHEAVIDIE	•

Check List Client: Unit #: 405 (290G) Hours: 7430,1 Hoe Date: Apr. 15-12-1 Location: Yard Shee Checked By: Up:

ecked By: Üei		Unsafe	Major Defect	Minor Defect	Fix Now	Fix Later	Comments:
Condition:	Safe	Unsale	1				
Condition -	,						1
racks leaks, derits,	l	<del></del>	+	+			Fuel-full.
nissing, broken  Dil, Fuel, Hydraulic						+	
Oil, Fuel, Hydradio Levels, Planetary Oil	<b></b>	<del> </del>	+		+	+	
. Cillaro	<del> </del>	+	+			1	
Air Fillers Antifreeze Level and	1				1		
Color	+	+			_		
= Dolte	+						
The second Shulton	+	<u></u>		-	$\Box$		
The state of the s	+	<u> </u>					
Pollers, Pads, bolls	1		<del></del>				
Track Tension	1_			_			
Bucket Condition							
Attached Properly Boom Moves Freely	$\Box$						
Hydraulic Cylinder			-				
Thumb						-	
Cage in Front							Both mirrors broken.
Greased							Both Mills
- A Secured		6 X					
Close Mirrors, Lighton	-	-					
Diade & Allii						_	
Coneral Housekeepiin	9			1			
First Aid Kit / Fire							
	diot						AK Good-
Bodio/gauges/lights-t	<u> </u>						
Seat suspension		-		$\overline{\mathbf{L}}$			
A/C / Heater						,+	
Lock Out Tag Grease Gun & Grease	se						
Spare Grease Nipple	es(5)						
						+	
Park Brake Function	ning					1	
			$\overline{}$			1	
Horn Fire Standby:						+	
0 - 40							m /
Fire Spade  Backpack Water Space	<u>orayer</u>				•		Py/
Maril CI							1/41/

Mad checked over for courty

# CHEVALLIER GEO-CON LTD.

Hoe	<b>,</b> .	Chook Lie	1
Fe.b	77 /7 2	Check Lis	τ
1 17.13	41 / to 10	Client	_

Data: Fall Da /	Uneck List				
Date: Feb 27 /2020	Client:				
Location: Shop	Unit #: 4-05				
Checked By: Checked By:	Hours: 6569				

			Major	Minor	Eine	T =-	
Condition:	Safe	Unsafe	Defect	Defect	Fix Now	Fix Later	
Visual Condition -				-		Later	Comments:
cracks, leaks, dents,	i/				1	ĺ	
missing, broken	_		l		l		
Oil, Fuel, Hydraulic	/			<del></del>			
Levels, Planetary Oil	_						
Air Filters						<u> </u>	
Antifreeze Level and	1						
Color							
Fan Belts							
Emergency Shut-off							
Hydraulic Hoses, Leaks	Ty						
Rollers, Pads, bolts							
Track Tension							
Bucket Condition	V						
Attached Properly	1						
Boom Moves Freely							
Hydraulic Cylinder							
Thumb	1//						
Cage in Front							
Greased				<del></del>			
Hood Secured	17						
Glass, Mirrors, Lights	1			<del></del>	2.0		
Wiper Blade & Arm	1//				28		
General Housekeeping	1			1			
First Aid Kit / Fire	1.7			<u>.                                      </u>			
Extinguisher			<i>y</i>	<i>y</i> .	4 4	l.	2020
Radio/gauges/lights-idiot	1						all Per 1605 not 29 ight
Seat suspension	7						<b>*</b>
A/C / Heater	1						
Lock Out Tag	/						Sharps of
Grease Gun & Grease				.9			
Spare Grease Nipples(5)						<u> </u>	Marine to
Back Up Alarm	1/2		-				A STATE OF THE STA
Park Brake Functioning	7						
Horn	V				- 12		The state of the s
Fire Standby:							
Fire Spade						-+	<i>)</i>
Backpack.Water Sprayer							
•						_	\ <u>\</u>
Signature: <u>Neavith</u>							
			Olí	gnature	: <u>V &amp;</u>	-601	(III)
							$\bigcirc$ 10
							(1) 49
							V /
				*/.)			