Sales · Rentals · Parts · Service

2920 Idylwyld Drive Saskatoon, SK Canada S7L 5Y6 www.korpan.com

Toll Free: 1-800-667-7777 (306) 931-8888

Fax: E-mail: tech@korpan.com

IN STORE PICKUP

.. မ Ship

> ၉ Noice

KORPAN TRACTOR & PARTS

Branch				
2920 IDYLWYLD		*REPF	CNI	
Date	Time			Page
07/09/24	22:	00:12	(B)) 01
Account No.	Phone No.			Invoice No.
				W22743
Ship Via		Purchase	orde	ır
Sales Tax Licence No.		Federal Exemption No.		
			s	Salesperson TMP / SDA

Attention: Primary Contact

DESCRIPTION

STK#/FLEET#

PIN/EIN HRS

486747

WARRANTY DATE

HRS

K2791

TANDEM GRAVEL TRUC

1HTWGAZRX5J182002 ENG MODEL DT570

SEGMENT# 1 C C3S

05/31/24 06/12/24

Perform NTF Inspection

7400

COMPLAINT:

Unit sold to RM of White Valley. Went out 1/24/24, returned on 5/30/24 Cust wanted more HP. KMs: O-44,209 I-48,675 Last Eng Svc- 48,421 KM. Fuel: O-5/8 I-3/4. Used to be Unit K2640.

-PERFORM RENT RETURN/NTF INSPECTION-

CORRECTION:

- -486747 kms, 16400 eng hrs.
- -Called Diamond truck center to find correct horsepower
- rating for engine which is: 285HP.
- -Filled out NTF info form.
- -Removed old decals and installed new Korpan decals.
- -Operated unit and tested functions.
- -Cleaned off high side A/C Schrader valve and reinstalled.
- -Pressure tested A/C system with nitrogen, and it passed.
- -Pulled a vacuum on the system for 30 min, then charged with
- 2.25lbs of refrigerant.
- -Tested block heater, had a resistance of 4K ohms. Needs to be replaced.
- -F/L hub oil cap broken, leaking.
- -Both front tires are worn, tread depth: 6/32
- -2nd air tank gauge tight on gauge cluster ta broken.
- -Unit needs new wipers.
- -Engine oil pan gasket leaking
- -Air compressor leaking oil
- -Front crank seal leaking oi

-PTO pump leaking.









CONTINUED ON PAGE 02

x	Signature	Cate
PRINT NAME		

Sales · Rentals · Parts · Service

2920 Idylwyld Drive Saskatoon, SK Canada S7L 5Y6 www.korpan.com

2920 IDYLWYLD

07/09/24

Branch

Date

(306) 933-2100 Phone: Toll Free: 1-800-667-7777 (306) 931-8888 Fay: E-mail: tech@korpan.com

22:00:12 (B)

Phone No.

Page

02

nvoice No.

W22743

TMP

/ SDA

IN STORE PICKUP

မှ Ship

K

မှ Invoice

1 1	1 112		
Ship Via	Purchase Order		
Sales Tax Licence No.	Federal Exemption No.		
	Salespersor		

Attention: Primary Contact


DESCRIPTION

STK#/FLEET K2791	TANDEM GRAVEL TRUC 7400	 PIN/EIN 1HTWGAZRX5J1820 ENG MODEL DT570	DATE	HRS
-Box lift	t cylinder leaking.			

- -Replaced front left hub oil cap.
- -Removed old box lift cylinder, swapped fittings to new box lift cylinder.
- -Installed new box lift cylinder and tested operation.
- -Removed air compressor.
- -Put gasket maker on the bottom plate where it was leaking oil from.
- -Replaced all O-rings on the compressor.
- -Reinstalled air compressor, started and checked for leaks.
- -No leaks from compressor but the water pump was now leaking.
- -Checked A/C again and found the condenser was cracked and leaking, Ordered new condenser.
- -Ordered new water pump, removed old water pump, cleaned up mounting surfaces and hardware.
- -Installed new water pump and gasket.
- -Installed new A/C condenser.
- -Recovered refrigerant and put system under vacuum to remove excess oil that was causing a high pressure.
- -Recharged A/C system and tested operation.
- -Unit still needs repairs but no more time right now.
- -Repairs needed:
- -Block heater
- PART MUMBER YOU'LL EVER NEED -Wiper blades
- -Engine oil pan gasket
- -Gauge cluster bufb (secondary air tank gauge) -Possibly needs a new A/C accumilator
 AF4LES PAYTEND

AF41.ES AUT81355105

CONDENSER A





CONTINUED ON PAGE 03

x	Signature	Date
PRINT NAME_		

Sales · Rentals · Parts · Service

2920 Idylwyld Drive Saskatoon, SK Canada S7L 5Y6 www.korpan.com Phone: (306) 933-2100
Toll Free: 1-800-667-7777
Fax: (306) 931-8888
E-mail: tech@korpan.com

Ship To:

IN STORE PICKUP

KORPAN TRACTOR & PARTS

Invoice To

Branch				
2920 IDYLWYL	ď.			
Date	Time			Page
07/09/24	22:	00:12	(B)	03
Account No.	Phon	e No.		Invoice No.
				W22743
Ship Via	1	Purchas	se Order	_
Sales Tax Licence No.		Federal	Exemption	i No.
		L		sperson TMP / SDA

Attention: Primary Contact

DESCRIPTION

STK#/FLEET# K2791	TANDEM GRAVEL TRUC			HRS	
NTGC1405.5 UNITDECAL WWF 16X6.5 1612 1836235C1 1839415C91 1842468C1 1842665C93 8S9089		ENG MODEL DT. HYD CYL- STAGE K2613 - K3117 WASHER FLUID AF KORPAN EQ DECAL HUB CAP 6 BOLTS AIR COMP GSKT SENSOR-OILPRESS BELT SERP 8 RIB WATERPUMP KIT BOLT 1/2X4-1/2	1 N 1 2 1 N 1 N 1 N 1 N 1 N 1 N 1 N 2 PARTS LABOR		
	10660		SEGMENT TOTAL==>		

***** WORK ORDER TOTALS *****

INTERNAL

CUSTOMER

PARTS

LABOR

INTERNAL TOTAL



XSignature	Date

Sales · Rentals · Parts · Service

2920 Idylwyld Drive Saskatoon, SK Canada S7L 5Y6 www.korpan.com

Phone: (306) 933-2100 Toll Free: 1-800-667-7777 (306) 931-8888 Fax: tech@korpan.com E-mail:

IN STORE PICKUP

ဂ္ Ship

မှ

Invoice

KORPAN TRACTOR & PARTS INTERNAL ORDERS

Branch								
2920 IDYLWYLD		*REP	RIN	T *				
Date	Time					Page	3	
07/18/24	22:	00:10	(B)		01	ļ	
Account No.	Phon				Invo	ice N	0.	
					W2	279	94	
Ship Via		Purchas	se Ord	er				
Sales Tax Licence No.		Federal	Exem	ption	No.			
		<u> </u>			person		SDA	
						<u> </u>		-

Attention: Primary Contact

DESCRIPTION

STK#/FLEET#

PIN/EIN HRS

WARRANTY DATE

HRS

K2791

TANDEM GRAVEL TRUC

48688

1HTWGAZRX5J182002

ENG MODEL DT570

SEGMENT# 1 C CTB N/A

7400

07/09/24 07/09/24

General Repairs

COMPLAINT:

Unit went out on rent 7/8/24 and came back 7/9/24 due to the air dryer making noise and the engine stalling on the customer. Troubleshoot problems and repair based on findings.

CORRECTION:

- -PERFORMED MACHINE INSPECTION.
- -TOPPED UP COOLANT AND WASHER FLUID.
- -TROUBLESHOT ELECTRICAL SYSTEM MALFUNCTION.
- -UNIT HAD NO CRANK WHEN STARTING, CHECKED BATTERY VOLTAGE, FUSES, STARTER AND IGNITION RELAYS.
- -CHECKED GROUND ON PIN 85 RELAY.
- -RESISTANCE READINGS ARE WITHIN THE SPECS.
- -HOOKED UP GROUND TO PIN 85, ENGINE CRANKED BUT WOULD NOT START.
- -CHECKED ECM RELAY WHILE IGNITION KEY WAS IN ON POSITION,
- FOUND RELAY WAS DEFECTIVE, REPLACED ECM RELAY.
- -TEST RAN THE MACHINE AT OPERATING TEMPERATURE (180F) AND 20 PSI ENGINE OIL PRESSURE.
- -CUSTOMER STATEED THAT AIR DRYER HAS MAKING NOISE.
- -FOUND HANGER BEARING DUST CAP WAS NOT SITTING IN PLACE PROPERLY CAUSING GRINDING SOUND, REMOVED AND REPLACED HANGER BEARING.
- ITS OPERATION -PERFORMED ROAD TEST AND OBSERVED
- -GREASED MACHINE.
- *OBSERVE POWER STEERING

DS2101211X

CENTER BEARING





N

CONTINUED ON PAGE 02

x	Signature	Date
PRINT NAME		

Sales · Rentals · Parts · Service

2920 Idylwyld Drive Saskatcon, SK Canada S7L 5Y6 www.korpan.com

Phone: (306) 933-2100 Toll Free: 1-800-667-7777 (306) 931-8888 Fax: tech@korpan.com E-mail:

IN STORE PICKUP

۵ Ship

은

nvoice

KORPAN TRACTOR & PARTS INTERNAL ORDERS

2920 IDYLWYI	.n		
	Time	Page	
Date	Turne	1,000	
07/18/24	22:00:10	(B) 02	
Account No.	Phone No.	Invoice No.	
		W22794	
Ship Via	Purchase C	Order	
Sales Tax Licence No.	Federal Ex	emption No.	
		Salesperson	
		TEK / S	DA

Attention: Primary Contact

DESCRIPTION

STK#/FLEET#

K2791

MIN30

TANDEM GRAVEL TRUC

PIN/EIN HRS 1HTWGAZRX5J182002 48688

WARRANTY DATE

HRS

7400

3545580C2 87696396

MINI FUSE 30A

ENG MODEL DT570

IGN SWITCH HSG RELAY 35A 12V

1. N 1

PAKIS

LABOR

6087550

SEGMENT TOTAL ==>

***** WORK ORDER TOTALS ***** INTERNAL

CUSTOMER

PARTS

LABOR

INTERNAL TOTAL



XSignature	 Date
PRINT NAME	

KORPAN TRACTOR & PARTS	3
------------------------	---

Sales · Rentals · Parts · Service

2920 Idylwyld Drive Saskatoon, SK Canada S7L 5Y6 www.korpan.com

(306) 933-2100 Phone: Toll Free: 1-800-667-7777 (306) 931-8888 Fay: tech@korpan.com E-mail:

IN STORE PICKUP

Ship To:

EURO MK DEVELOPMENTS LTD

မှ nvoice

Branch					
2920 IDYLWYL	D	*REPI	*TNI		
Date	Time			Page	
07/22/24	22:	00:19	(B)_	01	
Account No.	Phon			Invoice No.	
				W22795	
Ship Via	Purchas	e Order			
Sales Tax Licence No.	Federal Exemption No.				
			Sale	rsperson	
				TEK / SDA	

Attention: Primary Contact

DESCRIPTION

STK#/FLEET#

PIN/EIN HRS

WARRANTY DATE

HRS

K2791

TANDEM GRAVEL TRUC

48688

1HTWGAZRX5J182002

ENG MODEL DT570

SEGMENT# 1 C MRB N/A 07/09/24 07/09/24

Fuel charge on return

COMPLAINT:

Unit returned not full of fuel

7400

DIESEL

DIESEL FUEL /LT

58

PARTS

10400

SEGMENT TOTAL ==>

***** WORK ORDER TOTALS *****

SUB TOTAL ==>

GST R124893322 CUSTOMER TOTAL

TLS07222024

Remit to: Korpan Tractor 2920 Idylwyld Dr. N Saskatoon, SK S7L 5Y6



х	Signature	Da	te
PRINT NAME			

K	O	R	P	Α	N	TF	₹А	C	ГΟ	R	&	PA	۱F	₹٦	S	į
---	---	---	---	---	---	----	----	---	----	---	---	----	----	----	---	---

Sales · Rentals · Parts · Service

2920 Idylwyld Drive Saskatoon, SK Canada S7L 5Y6 www.korpan.com

(306) 933-2100 Phone: 1-800-667-7777 Toll Free: (306) 931-8888 Fax: tech@korpan.com F-mail:

IN STORE PICKUP

ဥ Ship

> KORPAN TRACTOR & PARTS INTERNAL ORDERS

٩

5

Branch				
2920 IDYLWYLD	*TNT			
Date	Time			Page
11/06/24	22:	00:10	(B)	01
Account No.	Phon			Invoice No.
				W23020
Ship Via	Purchas	e Order		
Sales Tax Licence No.	Federal Exemption No.			
		<u> </u>	Sale	sperson
			ı	RWP

DESCRIPTION

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

HRS

K2791

INTERNATIONAL 7400

7400

X 1HTWGAZRX5J182002

ENG MODEL DT570

N/A SEGMENT# 1 C MIJ

10/30/24 10/30/24

Pre-Rental Inspection

COMPLAINT:

Pre-rental Inspection:

- -Check for oil/fluid leaks
- -Make unit is greased
- -Run unit to ensure all its features are operating correctly
- -Check all fluid levels
- -Check tire pressure
- -Inspect Glass and battery.

CORRECTION:

Did a pre-rental inspection

Found the rear crank seal leaking

Fuel tank leaking

power steering hose leaking.

no beacon

Installed a beacon

repaired the power steering hose

replaced the fuel tank

E-FM600

MAGNET BASE

1

E-661A

6" BEACON

1 1 N

FUELTANKU

FUEL TANK-USED

SE**GMENT** TOT

CONTINUED ON PAGE 02

RETURNS MUST BE MADE BEFORE 30 DAYS FROM DATE OF PURCHASE, A 20% RESTOCKING FEE MAY APPLY. SPECIAL ORDERS & ELECTRICAL PARTS ARE NON-RETURNABLE.
TERMS: NET 30 DAYS, INTEREST AT THE RATE OF 1 1/2% PER MONTH (18% PER ANNUM) WILL BE CHARGED ON OVERDUE ACCOUNTS. I HEREBY AUTHORIZE THE ABOVE WORK TO BE DONE
ALONG WITH THE USE OF NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE MACHINE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. I
AGREE TO PAY CASH ON DELIVERY OF MACHINE OR ON TERMS SATISFACTORY WITH YOU AND UNTIL PAID IN FULL AN EXPRESS MECHANICS LIEN IS ACKNOWLEDGED ON ABOVE MACHINE
TO SECURE THE AMOUNT OF REPAIRS THERETO, IT IS UNDERSTOOD THAT THIS COMPANY ASSUMES NO RESPONSIBILITY FOR LOSS OR DAMAGE BY THEFT OR FIRE PURPOSES ONLY AND IT IS NOT IMPLIED THAT ANY PART LISTED IS THE PRODUCT OF THESE MANUFACTURERS. F.O.B. KORPAN TRACTOR & PARTS, SASKATOON.

XSignature	Date
PRINT NAME	

KORPAN	TRACTOR	&	PARTS
---------------	----------------	---	--------------

WORK ORDER TOTALS

Sales · Rentals · Parts · Service

2920 Idylwyld Drive Saskatoon, SK Canada S7L 5Y6 www.korpan.com Phone: (306) 933-2100
Toll Free: 1-800-667-7777
Fax: (306) 931-8888
E-mail: tech@korpan.com

IN STORE PICKUP

Ship To

۴

KORPAN TRACTOR & PARTS INTERNAL ORDERS

Branch				
2920 IDYLWYL	D			
Date	Time			Page
11/06/24	22:	00:10	(B)	02
Account No.	Phon			Invoice No.
				W23020
Ship Via	Purchase	Order		
Sales Tax Licence No.	Federal Exemption No.			
			Sale	sperson
				RWP

DESCRIPTION

STK#/FLEET#

K2791

INTERNATIONAL 7400

7400

HRS PIN/EIN

WARRANTY DATE

HRS

X 1HTWGAZRX5J182002 ENG MODEL DT570

INTERNAL.

CUSTOMER

PARTS

LABOR

INTERNAL TOTAL



x	Signature	Date
PRINT NAME		

Sales · Rentals · Parts · Service

2920 Idylwyld Drive Saskatoon, SK Canada S7L 5Y6 www.korpan.com

Phone: (306) 933-2100 1-800-667-7777 Toll Free: (306) 931-8888 Fax: E-mail: tech@korpan.com

IN STORE PICKUP

၉ Ship

၉

KORPAN TRACTOR & PARTS INTERNAL ORDERS

Branch						
2920 IDYLWYLD		*REPF	NIS	T*		
Date	Time					Page
11/29/24	22:	00:21	(B)		01
Account No.	Phon				Invo	ice No.
				- 1	W2	3064
Ship Via	Purchase	e Ord	er			
Sales Tax Licence No.	Federal Exemption No.					
		L	<u> </u>	Salesp	ersor	1
				7	JR	

DESCRIPTION

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

HRS

K2791

INTERNATIONAL 7400

7400

X 1HTWGAZRX5J182002 ENG MODEL DT570

SEGMENT# 1 C MIJ NA 11/13/24 11/14/24

SERVICE CALL - STARTING ISSUES

CORRECTION:

Miles left in his personal vehicle to Lanigan site. DIAG

AND FOUND THE HIGH OIL PRESSURE WAS SHORTED

CAME BACK TO SASKATOON TO GET PART.

DROVE BACK OUT INSTALLED PART AND STILL NO START

HAD TO GET UNIT TOWED BACK TO SHOP

Travelled a total of 516 KMs.

ADDITIONAL DESCRIPTION:

DRIVE TO CUSTOMER SITE (LANIGAN)

CONTACT 306-3608758

TRUCK WILL NOT START

1878571C95

IPR VALVE KIT

1 N

PARTS

LABOR

SEGMENT TOTAL ==>

6087550

***** WORK ORDER TOTALS ***** INTERNAT. CUSTOMER

PARTS ONLY PART MUMBER INTERNAL

XSignature	Date	
DOINT NAME	K	(C

Sales · Rentals · Parts · Service

2920 Idylwyld Drive Saskatoon, SK Canada S7L 5Y6 www.korpan.com

(306) 933-2100 Phone: Toll Free: 1-800-667-7777 (306) 931-8888 Fax: tech@korpan.com E-mail:

IN STORE PICKUP

မှ

٩

Invoice

KORPAN TRACTOR & PARTS INTERNAL ORDERS

Branch							
2920 IDYLWYLD *REPRINT*							
Date	Time				Page		
01/24/25	22:	00:11	(B)		01		
Account No.	Phon			Inv	oice No.		
				W2	3081		
Ship Via	Purchas	e Order					
Sales Tax Licence No. Federal Exc			Exemption	n No.			
			Sale	sperso	n		
				RWI)		

DESCRIPTION

STK#/FLEET#

PIN/EIN HRS

WARRANTY DATE

HRS

K2791

INTERNATIONAL 7400

16428

1HTWGAZRX5J182002

ENG MODEL DT570

SEGMENT# 1 C MIJ

11/19/24 11/19/24

Rental Return Inspection

7400

COMPLAINT:

- -Rental return from TSL Mechanical on Nov 19/24.
- -Hours: O-16425(Nov 13/24), I-16428(Nov 19/24) = 3 hrs used.
- -KMs: O-487072 (Nov 13/24), I-487205 (Nov 9/24) = 133 KMs used.
- -Fuel: O-Full, I-Full
- *Won't start issues.

CORRECTION:

Brought unit into shop. started to diag its no start issue,

truck all the sudden stopped cranking over.

Diag and try to locate the problem. The start relay works when jumped but it is missing the ground to activate the relay. Looked up the wiring diagrams, traced the wiring to starter shutdown and then to ecm .

Ecm is not supplying the ground, ordered new ecm after

sending it out to be checked.

Brought truck back into shop, took it apart to get at the

After struggling got it out and found one plug that was missing the locking tabs, had to look up the plug and order from Diamond truck center.

Installed the new ecm after removing the doghouse to gain access.

Installed the wires in the plug, can't get wires to lock into the plug.

into the plug.

After many failed abtempts to get them in with finally unit will grank now but ecm is still not online

Opened up the wiring and traced wires after several hours i



CONTINUED ON PAGE 02

x	Signature	 	-	 Date
DOINT NAME				

Sales · Rentals · Parts · Service

2920 Idylwyld Drive Saskatoon, SK Canada S7L 5Y6 www.korpan.com

(306) 933-2100 Phone: Toll Free: 1-800-667-7777 (306) 931-8888 Fax:

E-mail: tech@korpan.com

IN STORE PICKUP

<u>:</u>

۵

KORPAN TRACTOR & PARTS INTERNAL ORDERS

Branch						
2920 IDYLWY	מב					
Date	Time					Page
01/24/25	22:	00:13	1	(B)_		02
Account No.	Phone	No.			Inve	oice No.
					W2	3081
Ship Via		Purch	250	Order		
Sales Tax Licence No.		Feder	al E	emption	No.	
				Sales	perso	n
					RWF)

DESCRIPTION

STK#/FLEET#

PIN/EIN HRS

WARRANTY DATE

HRS

K2791

INTERNATIONAL 7400

16428

1HTWGAZRX5J182002

ENG MODEL DT570

found damaged wires. Repaired and close up the harness again checked and the ecm is online. Unit cranks but will not start.

Added oil the truck to see if it needed priming.. Still no start. Removed the feed line to the compressor and cranked but no oil. Drained oil from the pan and remove the pan. The suctions tube had one loose bolt.

Remove the fan belt Pulled the harmonic Balancer to gain access to the oil pump. Found the pump had one broken bolt and two loose ones on both sides. Removed the pump and checked for damage.

Ordered new seal and bolts for pump as well as front and rear

crank seals. Drained oil from trans and remove starter to undo torque converter bolts. Pull out trans and flex plate. Remove the rear seal.

Installed the new seal. and reassembled the trans to the engine. Installed the oil pump and 3 bolts stripped out. Order new bolts and installed Healey coils. Assemble again and 3 other holes stripped, removed again and repaired 3 move

holes. installed and this time they all torqued up. had to repair one stripped out bolt on the oil pan. Filled with oil and installed a new filter, installed belt and tested . engine oranked and then started belt came apart

DS657018X

Order new belt and install

FREIGHT K080952

DELL BELT SERP 8

Test drove unit and its all 1 N 1 EVER NEED

CONTINUED ON PAGE 03

RETURNS MUST BE MADE BEFORE 30 DAYS FROM DATE OF PURCHASE, A 20% RESTOCKING FEE MAY APPLY. SPECIAL ORDERS & ELECTRICAL PARTS ARE NON-RETURNABLE RETURNS MUST BE MADE BEFORE 30 DAYS FROM DATE OF PURCHASE, A 20% RESTOCKING FEE MAY APPLY. SPECIAL ORDERS & ELECTRICAL PARTS ARE NON-RETURNABLE. THE RANGE WORK TO BE DONE TERMS: NET 30 DAYS, INTEREST AT THE RATE OF 1 1/2% PER MONTH (16% PER ANNUM) WILL BE CHARGED ON OVERDUE ACCOUNTS. I HEREBY AUTHORIZE THE ABOVE WORK TO BE DONE ALONG WITH THE USE OF NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE MACHINE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. I ALONG WITH THE USE OF NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE MACHINE FOR PURPOSES MECHANICS LIEN IS ACKNOWLEDGED ON ABOVE MACHINE AGREE TO PAY CASH ON DELIVERY OF MACHINE OR ON TERMS SATISFACTORY WITH YOU AND UNTIL PAID IN FULL AN EXPRESS MECHANICS LIEN IS ACKNOWLEDGED ON ABOVE MACHINE TO SECURE THE AMOUNT OF REPAIRS THEREFO. IT IS UNDERSTOOD THAT THIS COMPANY ASSUMES NO RESPONSIBILITY FOR LOSS OR DAMAGE BY THEFT OR FIRE PURPOSES ONLY AND IT TO SECURE THE AMOUNT OF REPAIRS THEREFO. IT IS UNDERSTOOD THAT THIS COMPANY ASSUMES NO RESPONSIBILITY FOR LOSS OR DAMAGE BY THEFT OR FIRE PURPOSES ONLY AND IT IS NOT IMPLIED THAT ANY PART LISTED IS THE PRODUCT OF THESE MANUFACTURERS, F.O.B. KORPAN TRACTOR & PARTS, SASKATOON.

х	Signature	Date
PRINT NAME		

Sales · Rentals · Parts · Service

2920 Idylwyld Drive Saskatoon, SK Canada S7L 5Y6 www.korpan.com

Phone: (306) 933-2100 Toll Free: 1-800-667-7777 (306) 931-8888 Fax: E-mail: tech@korpan.com

IN STORE PICKUP

ု Ship

မှ

KORPAN TRACTOR & PARTS INTERNAL ORDERS

Branch			
2920 IDYLWYLI		l	
Date	Time		Page
01/24/25	22:00:1	(B)	03
Account No.	Phone No.		Invoice No.
			W23081
Ship Via	Pure	chase Order	
Sales Tax Licence No.	Fed	eral Exempti	on No.
		Sa	lesperson
			RWP

DESCRIPTION

STK#/FLEET# K2791 INTERNATIONAL 7400 7400	HRS PIN/EIN 16428 1HTWGAZRX5J18200 ENG MODEL DT570 M8 HELICOIL KIT	WARRANTY DATE	HRS
1221308		1 N	
1833096C95	SEAL FRT CRANKS	4 37	
1833482C1	BOLT M8X25		
1836197C1	OIL PAN GASKET	1 N	
1841296C1	P/U TUBE GSKT	1 N	
1841350C1	SEAL -OIL PUMP	2 N	
1841938C1	CRANK SEAL-REAR	1 N	
1873220C92	DAMPER RET KIT	1 N	
3562311C1	CONNECTOR HSG	1 N	
3562313C1	COVER 24 PIN	1 N	
5W40B	BULK ENGINE OIL	45	• •
5012011R91	ECM	1 N	•
5012011R91C	ECM CORE	1 N	•
	ENG OIL FILTER	1 N	
7744XD	2 011 011	PARTS	
		LABOR	
6087550	SI	GMENT TOTAL ==>	

***** WORK ORDER TOTALS ***** CUSTOMER INTERNAL

PARTS LABOR INTERNAL TOTAL NUMBER

XSignature	Date
PRINT NAME	

Sales · Rentals · Parts · Service

2920 Idylwyld Drive Saskatoon, SK Canada S7L 5Y6 www.korpan.com

(306) 933-2100 Phone: 1-800-667-7777 Toll Free: (306) 931-8888 Fay: tech@korpan.com F-mail:

IN STORE PICKUP

၉

မှ

nvoice

KORPAN TRACTOR & PARTS INTERNAL ORDERS

Branch						
2920 IDYLWYLD		*REPI	ZI	NT*		
Date	Time					Page
03/31/25	22:	00:17	()	B)		01
Account No.	Phon				Inve	oice No.
					W2	3239
Ship Via		Purchas	e O	rder		
Sales Tax Licence No.		Federal	Exe	mption	No.	
		L		Sales	perso	n
					RWE)

DESCRIPTION

STK#/FLEET#

HRS PIN/EIN

03/20/25 03/21/25

WARRANTY DATE

HRS

K2791

INTERNATIONAL 7400

12762

1HTWGAZRX5J182002 ENG MODEL DT570

7400

SEGMENT# 1 C CBG

Rental Return Inspection

COMPLAINT:

- -Rental return from Forbes Bros on Mar 20/25.
- -Hours: 0-12662(Jan 28/25), I-12762(Mar 20/25) = 100 hrs

- -KMs: 0-294317, I-297718= 3401 KMs used.
- -Fuel: O-Full, I-Full
- ***Last Engine Service @294307 KMs

CORRECTION:

CBG

- -Started and allowed machine to warm up.
- -Tested bin functions.
- -Brought machine inside shop.
- -Topped up transmission oil.
- -Topped up power steering fluid.
- -Topped up coolant.
- -Topped up washer fluid.
- -Greased machine.
- -Cleaned all oils on engine and transmission.
- -Drove machine in yard so it could get to proper operating

temp.

-Brought machine back inside and checked for possible oil leaks.

-No oil leaks found

- -Heard air leak coming from under
- -Used soapy water to find air leak
- -Found air leak on suspension
- -Drained all air tanks.











CONTINUED ON PAGE 02

XSignature	Date
PRINT NAME	

Sales · Rentals · Parts · Service

2920 Idylwyld Drive Saskatoon, SK Canada S7L 5Y6 www.korpan.com

(306) 933-2100 Phone: Toll Free: 1-800-667-7777 (306) 931-8888 E-mail: tech@korpan.com

IN STORE PICKUP

မ Ship

မ

KORPAN TRACTOR & PARTS INTERNAL ORDERS

Branch					
2920 IDYLWYL	o _				
Date	Time				Page
03/31/25	22	00:17	(B)		02
Account No.	Phon			Inve	oice No.
	l			W2	3239
Ship Via		Purchase	Order		
Sales Tax Licence No.		Federal E	xemption	No.	
			Sale	sperso	
				RWE	·

DESCRIPTION

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

HRS

K2791

INTERNATIONAL 7400

12762 1HTWGAZRX5J182002 ENG MODEL DT570

7400

-Cut air line as quick coupler was seized.

- -Removed valve and linkage.
- -Tried using penetrating oil to free up quick coupler.
- -Not able to free up quick coupler.
- -Ordered new suspension valve.
- -Replaced primary air filter.
- -Removed wood panel on box to paint.
- -Ordered white paint and paint brush as none where in stock.
- -Painted wood panel to match other side.
- -Installed board onto box.
- -Hook up scanner to truck to diagnose ABS issue.
- -Code was for rear right speed sensor.
- -Checked for 5 volt reference at connector.
- -Connector had proper reference voltage.
- -Checked resistance between connector and frame ground.
- -Determined that ground wire was broken along harness.
- -Found broken ground wire rubber on frame before going into
- -Cut and repaired damaged wire.
- -Checked for resistance between connector and frame ground.
- -Had same results as before determined there was another

break in harness.

- -Checked resistance all the way to ecm from connector.
- -Resistance was proper
- vovil ever beed -Removed egm to dhere for correston on pine
- -No corrosion found ecm pins
- machine -Reset ecm codes and installed in
- -Test drove machine in yard
- -No abs codes come back.
- -Parked machine in wash bay to be cleaned.



CONTINUED ON PAGE 03

х	Signature	 Date
DRINT NAME		

Sales · Rentals · Parts · Service

2920 Idylwyld Drive Saskatoon, SK Canada S7L 5Y6 www.korpan.com Phone: (306) 933-2100
Toll Free: 1-800-667-7777
Fax: (306) 931-8888
E-mail: tech@korpan.com

IN STORE PICKUP

Ship To

မ

Invoice

KORPAN TRACTOR & PARTS

INTERNAL ORDERS

Branch 2920 IDYLWYLD Page Time 03 22:00:17 (B) 03/31/25 one No. Invoice No. Account No. W23239 9999 Purchase Order Ship Via Sales Tax Licence No Federal Exemption No. Salesperson RWP

DESCRIPTION

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

HRS

K2791

INTERNATIONAL 7400

12762

1HTWGAZRX5J182002

ENG MODEL DT570

ADDITIONAL DESCRIPTION:

7400

+Assist:CBG 60 minutes

RS4636

2507385C1

2507385C1 586 AIR FILTER-OUTR

VALVE HEIGHT CO

ALVE HEIGHT CO

1 N

1 N 1

POWER STEER FLU

PARTS

LABOR

6087550

SEGMENT TOTAL ==>

***** WORK ORDER TOTALS *****

INTERNAL

CUSTOMER

PARTS

LABOR

INTERNAL TOTAL



x	Signature	Date
PRINT NAME		

Sales · Rentals · Parts · Service

2920 Idylwyld Drive Saskatoon, SK Canada S7L 5Y6 www.korpan.com

(306) 933-2100 Phone: Toll Free: 1-800-667-7777 Fax: (306) 931-8888 E-mail: tech@korpan.com

IN STORE PICKUP

To : Ship

2

KORPAN TRACTOR & PARTS INTERNAL ORDERS

Branch	+ + + + + + + + + + + + + + + + + + + +	T. +
2920 IDYLWY	LD *REPRIN	
Date	Time	Page
05/16/25	22:00:09 (B) 01
Account No.	Phone No.	Invoice No.
		W23295
Ship Via	Purchase Orde	er
Sales Tax Licence No.	Federal Exemp	otion No.
		Salesperson
		AJR

DESCRIPTION

STK#/FLEET#

K2791

INTERNATIONAL 7400

7400

HRS PIN/EIN

WARRANTY DATE

HRS

X 1HTWGAZRX5J182002 ENG MODEL DT570

SEGMENT# 1 C C3S NA 05/06/25 05/06/25

CHECK LOW VOLTAGE READING

CORRECTION:

- -Replaced alternator which was not charging
- -verified unit was now charging
- -unit was returned with a complaint of the unit dying while driving
- -took the unit out by Martensville and back with no problems
- -checked the fuel regulator solenoid for excessive

resistance just to be sure there was no issue. found normal resistance reading

- -took unit out to Borden and climbed the hill both ways with
- a full legal load of gravel to confirm unit would not die
- -traveled back to shop and unit had no problems

ADDITIONAL DESCRIPTION:

CUSTOMER DROPPED OFF TRUCK MAY 05-2025

COMPLAINT:

- *LOW VOLTAGE READING
- *BROKEN RR WHEEL STUD

110775PN

ALTERNATOR

1 N

PARTS

LABOR

SEGMENT TOTAL ==> WORK ORD STOMER INTERNA

> PARTS CONTINUED ON PAGE 02

RETURNS MUST BE MADE BEFORE 30 DAYS FROM DATE OF PURCHASE, A 20% RESTOCKING FEE MAY APPLY, SPECIAL ORDERS & ELECTRICAL PARTS ARE NON-RETURNABLE.
TERMS: NET 30 DAYS, INTEREST AT THE RATE OF 1 1/2% PER MONTH (18% PER ANNUM) WILL BE CHARGED ON OVERDUE ACCOUNTS. I HEREBY AUTHORIZE THE ABOVE WORK TO BE DONE ALONG WITH THE USE OF NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE MACHINE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. I AGREE TO PAY CASH ON DELIVERY OF MACHINE OR ON TERMS SATISFACTORY WITH YOU AND UNTIL PAID IN FULL AN EXPRESS MECHANICS LIEN IS ACKNOWLEDGED ON ABOVE MACHINE TO SECURE THE AMOUNT OF REPAIRS THERETO, IT IS UNDERSTOOD THAT THIS COMPANY ASSUMES NO RESPONSIBILITY FOR LOSS OR DAMAGE BY THEFT OR FIRE PURPOSES ONLY AND IT IS NOT IMPLIED THAT ANY PART LISTED IS THE PRODUCT OF THESE MANUFACTURERS. F.O.B. KORPAN TRACTOR & PARTS, SASKATOON.

w.	
Signature	Date
PRINT NAME	

KORPAN TRACTOR & PARTS

Sales · Rentals · Parts · Service

2920 Idylwyld Drive Saskatoon, SK Canada S7L 5Y6 www.korpan.com

(306) 933-2100 Phone: Toll Free: 1-800-667-7777 (306) 931-8888 Fax:

tech@korpan.com E-mail:

IN STORE PICKUP

မှ Ship

ဥ

Invoice

KORPAN TRACTOR & PARTS INTERNAL ORDERS

Branch				
2920 IDYLWYL	D	1_		
Date	Time			Page
05/16/25	22:	00:09	(B)	02
Account No.	Phon	a No.		Invoice No.
				W23295
Ship Via		Purchas	e Order	
Sales Tax Licence No.		Federal	Exemptio	n No.
		L	Sale	esperson
		_		AJR

DESCRIPTION

STK#/FLEET#

K2791

INTERNATIONAL 7400

7400

HRS PIN/EIN

WARRANTY DATE

HRS

X 1HTWGAZRX5J182002 ENG MODEL DT570

LABOR

INTERNAL TOTAL



XSignature	Date
PRINT NAME	

Sales · Rentals · Parts · Service

2920 Idylwyld Drive Saskatoon, SK Canada S7L 5Y6 www.korpan.com

Phone: (306) 933-2100 Toll Free: 1-800-667-7777 (306) 931-8888 Fax: E-mail: parts@korpan.com

K2791

Ship To:

Invoice

မှ

KORPAN TRACTOR & PARTS

INTERNAL ORDERS

Branch					
2920 IDYLWYLD		*REPI	RINT*	CN	NYYY
Date	Time				Page
05/26/25	15:	58:03	(0)		01
Account No.	Phon	e No.		Inv	oice No.
				S2	4946
Ship Via		Purchas	o Order		
		CLAY'	TON S	3	
Sales Tax Licence No.		Federal	Exemptio	n No.	
			Sale	sperso	n
			ļ	INT	/ MWC

DESCRIPTION

ORDER#: 139284

UNIT 1: INTERNATIONAL 7400 T 1HTWGAZRX5J182002

7400

Part#	Description	Bin C	RD _	ISS S	SHP _	B/O UTTTT _	Price	Amount
5W40B 3543736C1	BULK SYN ENGOIL BUSS BAR 3-4	SHOP	2 1	2 1	2 1	1** 1**		
FREIGHT	Navistar part# : SPECIAL DELIV	150 SERIES XXX	3-4	(12 PIN)	1	1*		

STK#: K2791

ACC#: 6041020 MISC REPAIRS

TOTAL INTERNAL

Remit to: Korpan Tractor 2920 Idylwyld Dr. N Saskatoon, SK S7L 5Y6



XSignature	Date
PRINT NAME	

Sales · Rentals · Parts · Service

2920 Idylwyld Drive Saskatoon, SK Canada S7L 5Y6 www.korpan.com Phone: (306) 933-2100
Toll Free: 1-800-667-7777
Fax: (306) 931-8888
E-mail: tech@korpan.com

IN STORE PICKUP

Ship To:

٩

KORPAN TRACTOR & PARTS INTERNAL ORDERS

Branch					
2920 IDYLWYL	D	*REPI	*TNI		
Date	Time		-		Page
06/13/25	22	00:14	(B)		01
Account No.	Phon	e No.		Invo	sice No.
				W2	3330
Ship Via		Purchas	e Order		
Sales Tax Licence No.		Federal	Exemption	No.	
		l	Sale	sperso	n
				RWP	·

DESCRIPTION

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

HRS

K2819

INTERNATIONAL 7400 299712 1HTWGAZRX5J182002

7400

SEGMENT# 1 C MIJ N/A

06/02/25 06/03/25

New to fleet / Rental Return Inspection

COMPLAINT:

- -Unit returned from Sautner on May 29/25.
- -Perform rental return inspection.
- -Repair hydraulic tanks straps.
- ***UNIT REPURCHASED FROM SAUTNER THEN RETURNED***
- -FORMER K2791

CORRECTION:

- -Performed rental return inspection.
- -Checked the voltage bouncing on dash.
- -Alternator is an even 14.2volts.
- -Checked the coolant overflow to see if it was pressuring up
- road test and it was good.
- -Replaced the ignition switch for a no crank.
- -Replaced both hydraulic tank mounting straps.

ASA355C

TANK STRAP

2 N

3545580C2

IGN SWITCH HSG

1 N

PARTS

LABOR

10660

SEGMENT TOTAL ==>



XSignature	Date
PRINT NAME	

Sales · Rentals · Parts · Service

2920 Idylwyld Drive Saskatoon, SK Canada S7L 5Y6 www.korpan.com

Phone:

(306) 933-2100 Toll Free: 1-800-667-7777

(306) 931-8888 Fax: E-mail: tech@korpan.com

IN STORE PICKUP

2 Ship

2

nvoice

KORPAN TRACTOR & PARTS INTERNAL ORDERS

Branch 2920 IDYLWYI	D *REPRIN	1T*
Date	Time	Page
07/31/25	22:00:16 (E	3) 01
Account No.	Phone No.	Invoice No.
		W23393
Ship Via	Purchase Ord	der
Sales Tax Licence No.	Federal Exen	nption No.
		Salesperson
		AJR

DESCRIPTION

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

HRS

K2819

INTERNATIONAL 7400

X 1HTWGAZRX5J182002

7400

SEGMENT# 1 C MRB NA 07/18/25 07/18/25

REPLACE A/C COMPRESSOR AND BELT

CORRECTION:

- -BROUGHT MACHINE INSIDE SHOP TO REPLACE AC COMPRESSOR AND SERPENTINE BELT
- -EVACUATE REFRIGERANT ON AC SYSTEM
- -TOOK OFF PARTS AND PANELS TO GAIN ACCESS ON AC LINES AND AC COMPRESSOR
- -TOOK OFF LINES AND UNMOUNT OLD COMPRESSOR
- -COMPARED OLD COMPRESSOR TO NEW ONE AND CHECKED COMPRESSOR

OIL LEVEL

- -INSTALLED COMPRESSOR ASSEMBLY AND HOOKED UP LINES
- -PERFORMED VACUUM AND LEAK TEST ON AC SYSTEM AND ALL ARE

GOOD

- -FILL SYSTEM WITH REFRIGERANT, PAG OIL AND DYE AS PER SPECIFIED QUANTITY
- -RUN AND TEST AC AND ALL ARE GOOD
- -INSTALLED NEW SERPENTINE BELT AS WELL
- -PARKED MACHINE AFTER CERTAIN REPAIR WAS MADE
- -NOTE THAT NO OTHER REPAIRS WERE MADE ASIDE FROM AC SYSTEM

AS UNIT IS UP FOR SALE

K080952

3582435C1

BELT SERP 8 RIB AC COMPRESSOR

***** WORK ORDER TOTALS *****

x		 Data
Sig	nature	Date
PRINT NAME		

Sales · Rentals · Parts · Service

2920 ldylwyld Drive Saskatoon, SK Canada S7L 5Y6 www.korpan.com Phone: (306) 933-2100
Toll Free: 1-800-667-7777
Fax: (306) 931-8888
E-mail: tech@korpan.com

IN STORE PICKUP

Ship To

မှ

Invoice

, KORE

KORPAN TRACTOR & PARTS INTERNAL ORDERS

Branch						
2920 IDYLWYLI)					
Date	Time					Page
07/31/25	22:	00:1	6	(B)		02
Account No.	Phon				Inve	oice No.
					W2	3393
Ship Via		Purch	1888	Order		
Sales Tax Licence No.		Feds	ral E	xemption	No.	
				Sale	sperso	n
				36.10	AJF	

DESCRIPTION

STK#/FLEET#

K2819

TN

INTERNATIONAL 7400

7400

HRS PIN/EIN

WARRANTY DATE

HRS

X 1HTWGAZRX5J182002


INTERNAL

CUSTOMER

PARTS

LABOR

INTERNAL TOTAL



x	Signature	Date
DOINT NAME		

Sales · Rentals · Parts · Service

2920 Idylwyld Drive Saskatoon, SK Canada S7L 5Y6 www.korpan.com

Phone: (306) 933-2100 Toll Free: 1-800-667-7777 (306) 931-8888 Fax:

tech@korpan.com E-mail:

IN STORE PICKUP

၉ Ship

၉

Invoice

KORPAN TRACTOR & PARTS INTERNAL ORDERS

Branch						
2920 IDYLWYLD *1				INT	+	
Oate	Time					Page
08/29/25	22:	00:1	1_	(B)		01
Account No.	Phone No.		Inv	Invoice No.		
					W2	3450
Ship Via		Purchase Order				
Sales Tax Licence No.		Federal Exemption No.				
				Sale	esperso RWI	

DESCRIPTION

STK#/FLEET#

PIN/EIN HRS

WARRANTY DATE

HRS

K2819

INTERNATIONAL 7400

299713

1HTWGAZRX5J182002

7400

ENG MODEL DT570

SEGMENT# 1 C MRB N/A 08/25/25 08/28/25

Pre-Sale Inspection

CORRECTION:

- -Unit is working as it should aside from intermittent
- electrical issue and minor leak on front crank seal
- -Unit was checked not so long ago as AC compressor was

recently changed

ADDITIONAL DESCRIPTION:

Pre-Sale Inspection:

- -Check for oil/fluid leaks.
- -Run unit to ensure all its features are operating correctly.
- -Test battery ensure its strong.
- -Record machine meter hours.

LABOR

SEGMENT TOTAL ==>

6087550

***** WORK ORDER TOTALS ***** CUSTOMER INTERNAL

LABOR

INTERNAL THE CHLY PART MUMBER

RETURNS MUST BE MADE BEFORE 30 DAYS FROM DATE OF PURCHASE, A 20% RESTOCKING FEE MAY APPLY. SPECIAL ORDERS & ELECTRICAL PARTS ARE NON-RETURNABLE.
TERMS: NET 30 DAYS, INTEREST AT THE RATE OF 1 1/2% PER MONTH (18% PER ANNUM) WILL BE CHARGED ON OVERDUE ACCOUNTS. I HEREBY AUTHORIZE THE ABOVE WORK TO BE DONE
ALONG WITH THE USE OF NECESSARY MATERIALS. YOU AND YOUR EMPLOYES MAY OPERATE ABOVE MACHINE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. I
AGREE TO PAY CASH ON DELIVERY OF MACHINE OR ON TERMS SATISFACTORY WITH YOU AND UNTIL PAID IN FULL AN EXPRESS MECHANICS LIEN IS ACKNOWLEDGED ON ABOVE MACHINE
TO SECURE THE AMOUNT OF REPAIRS THERETO. IT IS UNDERSTOOD THAT THIS COMPANY ASSUMES NO RESPONSIBILITY FOR LOSS OR DAMAGE BY THEFT OR FIRE PURPOSES ONLY AND IT
IS NOT IMPLIED THAT ANY PART LISTED IS THE PRODUCT OF THESE MANUFACTURERS. F.O.B. KORPAN TRACTOR & PARTS, SASKATOON.

xs	ignature	Date
DOINT NAME		

KORPAN TRACTOR & PARTS