P.O. Box 5056 Bonnyville, AB T9N 2G3 P: 780-812-8788

Performed by (Sign): hances Bernman

WORK ORDER 0063

Energy Services Ltd.	Bonnyville, AB T9N 2G3 P: 780-812-8788 E: dawson@lyndenenergyservices.ca	Date	May 24/25	•	Unit #	409	
KM's 42953,00	Hours			OSA .		KKPALCK:	39 PAH 5 755
	REPAIRS PERF	ORMED		HRS		MATERIALS &	 & PARTS
-Changed	engine oil + filters.			25	QTY	PART	NUMBER
					2 puils	15W-40	Rotella
-Grewed	entire unit Pe	Fromod usual	inspection	2.5	2	P5521000	Oll Roller
					1	P550467	F/W separator
- Replaced	P/s cab marker /	cut a revine	needed)	2,5	. 1	P55 6917	7 77
A/50			symmetricall	1	1	12 766 785 A	•
(Use	ed one from Dawson	so they match	From this				
tr	uch in stack in s	ca can this one	,				
a	cut & rewire job.				·		
							
							
						<u> </u>	
 							
			TOTAL HOURS	2 -			
			IOIAL HOURS	Tr 7	<u> </u>		
Performed by (Print):	James Kemman		Approved by (Print):				

Approved by (Sign):





Date/Time: June 18/25

Equipment/Vehicle Checklist

	Date/Time: June 18/25		U	nit#:	409						
	Plate #:		Mile	age:	300	km miles					
Post	ng Legend: NA – Not Applicable		M – Passed but maintenance required								
	P - Passed in good w	condition	R – Reje	cted, rep	pair necessary before returning to service						
	Fluid Levels										
<u> </u>	Motor Oil	P	Power Steering		N/A	Brake Fluid					
1	Radiator	P	Windshield Washer	,	<u> </u>	Greasing Required					
P Oil Change Required? Mileage when done: <u>Duc</u> @ 16 \$770 hrs.											
	ers Compartment		· · · · · · · · · · · · · · · · · · ·		+						
<u>P</u>		P	Air Pressure Gauge		NYA	Booster Cable					
P	Windshield Wipers	P	Compressor Buildups		P	Hazard Warning Kit / Flares					
P	Side Windows	P	Windshield		P	Fire Extinguisher (Initial Tag)					
P	Air Leakage	P	Vehicle Inspection Tag		P	First Ald Kit					
P	Windshield	P	Instrument Lamps		NA	Survival Kit					
Body Exterior											
m	Head Lamp D/S low beam	P	Hazard Lamp		MIB	Glad Hands & Air System					
P	Tail Lamp	P	Turn Signal		MA	TDG Placards					
P	Marker Lamp	NA	Trailer Hitch		P	Fenders/Mud Flaps					
P	Clearance Lamp	NIA	Trailer Cord		P	Air Lines					
P	Stop Lamp	P	Tire Pressure								
Und	Under The Hood										
P	Exhaust System	P	Fan and Belt		NIA	Carburetor					
P	Air Filter	P	Battery and Wiring								
Und	Undercarriage										
LP	Muffler	P	Shock Absorbers		P	Springs					
P	Axel	P	Oil Pan								
	e, Tires, and Wheels	1									
<u> </u>	Brake Components	P	Reservoirs and Valves		N/A	Tire Iron					
P	Brake Lines and Hoses	NIA	Chains		NIA	Spare Tire					
P	Prum Disk Brake	P	Tire Wear		NIA	Jack					
P	Park Brake	P	Tire Pressure		P	Chock Block					
□ No Defects Found □ Defects Found											
Details of defect(s) detected:											
D/5 low beam out.											
Defects observed during operation of vehicle (time other than initial inspection):											
Certification of Repairs Completed											
I performed an inspection of the vehicle noted above using the criteria set out in Schedule 1 of NSC Standard 13 and as per Schedule 1 of											
Alberta's Commercial Vehicle Safety Regulation (AR121/2009). I certify that:											
☐ The above defects have been repaired.											
Above defects do not affect safe operation of vehicle; any minor defects identified will be addressed before next use of vehicle.											
	e of person inspecting: mes PECLYMAN	nature of person inspecting:			Date and time: June 18/25						
	Repairman Name (if applicable): Repairman Sign			ble):		Pate and time:					