

Filters: Start Date - 3/1/2020; End Date - 5/5/2026; Equipment - TRACTOR TANDEM KW T880 [9166]

Work Order:	9150	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Nick Depratto	Start Date:	3-9-2020
Kms:	8990	Stop Date:	3-10-2020
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
JAGER THOMPSON	1.50	RT Shop Mech Rky	\$50.00	\$75.00
			Total Labor	\$75.00
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$75.00

Item ID	Description	Completed By	Reported Hours
14087	PROGRAM ALL MODULES WITH DAVIES - MAKE SURE 12V CHARGER IS ON THE BATTERIES TO BE DONE NEXT SERVICE		1.00
14488	SOB - MIRROR HOUSING		0.00
15529	REPAIR BROKEN MUDFLAP		0.50

Work Order:	9442	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Shop Operations - RMH	Business Unit:	Trucks Heavy
Created by:	Darcy Hallock	Start Date:	3-21-2020
Kms:	8990	Stop Date:	3-21-2020
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	0.75	RT Shop Tire Tech	\$35.00	\$26.25
			Total Labor	\$26.25
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$26.25

Item ID	Description	Completed By	Reported Hours
16183	9166- PRESSURES/DEPTHS		0.75

Work Order: 9722
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Rocky Mountain House Shop
Created by: Colton Parker
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 4-3-2020
Stop Date: 4-7-2020

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
BRETT LANGFORD	10.00	RT Shop Mech Rky	\$50.00	\$500.00
			Total Labor	\$500.00
CAP-FUEL NON-LOCKING KW [K22-1024]	1.00	Each	\$59.19	\$59.19
FEMCO ISX/QSK M27X2.0M [10-27200-02]	1.00	Each	\$37.56	\$37.56
FILTER - AIR CAB INTERIOR [CF19012]	1.00	Each	\$25.70	\$25.70
FILTER LUBE OIL [LF14000NN]	1.00	Each	\$30.16	\$30.16
FILTER-AIR CLEANER [P621725]	1.00	Each	\$147.33	\$147.33
FUEL FILTER [FF5825 NN]	1.00	Each	\$37.20	\$37.20
FUEL/WATER SEPARATOR [FS19765]	1.00	Each	\$15.89	\$15.89
PARTICULATE FILTER [F37-1018]	1.00	Each	\$40.42	\$40.42
TEMPERATURE SENDER [Q21-1002]	1.00	Each	\$80.90	\$80.90
			Total Parts	\$474.35
			Total Equip	\$0.00
			Total Cost	\$974.35

Item ID	Description	Completed By	Reported Hours
15861	30k/400hr Service - All Filters Replaced		4.00
Perform regular check list with the below fluids & filters will be replaced every A service.			
14137	Cummins Idle Shutdown Update		1.00
Parameters to enable idle shutdown so it cannot be by passed with trailer brakes being left on. Please see attached printable parameters.			
15740	FABRICATE AND INSTALL GRAB HANDLES ON HEADACHE RACK		0.00
16775	PASSENGER SIDE FUEL CAP LEAKING		1.00
16776	REPLACE FUEL FILTER HOUSING		1.00
16832	REROUTE TOWER GROUND		3.00

Work Order: 10896
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Rocky Mountain House Shop
Created by: Colton Parker

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 5-21-2020

Kms: 8990
Hr: 9025

Stop Date: 5-25-2020

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
WALTER BOESCH	6.50	RT Shop Mech Rky	\$50.00	\$325.00
			Total Labor	\$325.00
QWIK TIE [QT967SS]	1.00	Each	\$239.23	\$239.23
			Total Parts	\$239.23
			Total Equip	\$0.00
			Total Cost	\$564.23

Item ID	Description	Completed By	Reported Hours
18757	BAD FRONT END VIBRATION		6.50

Work Order: 10901
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Shop Operations - RMH
Created by: Darcy Hallock
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 5-22-2020
Stop Date: 5-22-2020

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	2.00	RT Shop Tire Tech	\$35.00	\$70.00
			Total Labor	\$70.00
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$70.00

Item ID	Description	Completed By	Reported Hours
18771	9166- 05/21/2020		2.00

Work Order: 10906
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Shop Operations - RMH
Created by: Darcy Hallock
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 5-22-2020
Stop Date: 5-22-2020

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	1.50	RT Shop Tire Tech	\$35.00	\$52.50
			Total Labor	\$52.50

	Total Parts	\$0.00
	Total Equip	\$0.00
	Total Cost	\$52.50

Item ID	Description	Completed By	Reported Hours
18776	9166- 05/22/2020		1.50

Work Order:	11085	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Shop Operations - RMH	Business Unit:	Trucks Heavy
Created by:	Darcy Hallock	Start Date:	5-28-2020
Kms:	8990	Stop Date:	5-28-2020
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	0.25	RT Shop Tire Tech	\$35.00	\$8.75
			Total Labor	\$8.75
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$8.75

Item ID	Description	Completed By	Reported Hours
19076	9166- 05/28/2020		0.25

Work Order:	11147	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Colton Parker	Start Date:	5-29-2020
Kms:	8990	Stop Date:	6-1-2020
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
GARRY MELVIN	1.00	RT Shop Mech Field	\$54.00	\$54.00
			Total Labor	\$54.00
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$54.00

Item ID	Description	Completed By	Reported Hours
19183	LEVELING VALVE ISSUES		1.00

Work Order: 11421
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Rocky Mountain House Shop
Created by: Colton Parker
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 6-9-2020
Stop Date: 6-10-2020

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
TYLER SCHWARZ	9.00	RT Shop Mech Rky	\$50.00	\$450.00
			Total Labor	\$450.00
Hydraulic, Spin-On {HF6720} [P550387]	2.00	Each	\$13.80	\$27.60
			Total Parts	\$27.60
			Total Equip	\$0.00
			Total Cost	\$477.60

Item ID	Description	Completed By	Reported Hours
19658	CVIP -- Annual Perform annual CVIP. Change hydraulic filter if applicable.		4.00
19659	REPLACE HYDRAULIC FILTER		1.00
19719	ALL 4 REAR SHOCKS LOOSE		1.00
19720	COOLANT LEAK		1.00
19721	NO TAILLIGHTS		2.00

Work Order: 11544
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Rocky Mountain House Shop
Created by: Colton Parker
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 6-12-2020
Stop Date: 6-12-2020

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
WALTER BOESCH	1.00	RT Shop Mech Rky	\$50.00	\$50.00
			Total Labor	\$50.00
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$50.00

Item ID	Description	Completed By	Reported Hours
19885	A/C NOT WORKING		1.00

Work Order: 11551 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: **Business Unit:** Trucks Heavy
Created by: Trace Pidherney **Start Date:**
Kms: 8990 **Stop Date:**
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
CBL ASSY-L/D 4WAY STRT 12' 4 [19-4012]	1.00	Each	\$36.00	\$36.00
			Total Parts	\$36.00
			Total Equip	\$0.00
			Total Cost	\$36.00

Item ID	Description	Completed By	Reported Hours
19900	DRIVER REQUESTED		0.00

Work Order: 12057 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: **Business Unit:** Trucks Heavy
Created by: Maintain Administrator **Start Date:**
Kms: 8990 **Stop Date:**
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
4/W TRAILER CORD 12' - FOR TANDEM TRACTORS [19-4012]	1.00	Each	\$36.75	\$36.75
4/W TRAILER CORD 15' - TRIDEM TRACTORS [19-4015]	1.00	Each	\$42.85	\$42.85
4FT CHEATER CHAIN [GR7038X4FT]	2.00	Each	\$25.73	\$51.47
6X20' PLY TOW STRAP [TS540X20X2]	1.00	Each	\$118.90	\$118.90
7/W TRAILER CORD 15' W/P - FOR TRIDEM TRACTORS [30-2070]	1.00	Each	\$115.24	\$115.24
ALCOHOL INJECTOR [A72420]	1.00	Each	\$41.07	\$41.07
BREAKER [CB150PB]	1.00	Each	\$70.79	\$70.79
CIRCUIT BREAKER 15 AMP [BD280-1130-15/16]	1.00	Each	\$8.76	\$8.76
DEF TANK CAP- NON VENTED DEF TANK {572.3005} [908022301]	1.00	Each	\$39.78	\$39.78

EMISSIONS LABEL[Custom]	1.00 Each	\$244.85	\$244.85
GLADHAND SEAL CLOSE [FS312A]	13.00 Each	\$0.66	\$8.53
GLADHAND SEAL CLOSE [FS312A]	2.00 Each	\$0.58	\$1.17
GROTE LIGHT - 2 1/2" AMBER LED CLEARANCE MARKER LIGHT [G1033 {xr TL10250Y, 10375Y}]	2.00 Each	\$5.29	\$10.59
HEADLAMP 23762 [H11-55/BP]	2.00 Each	\$9.70	\$19.40
HUB CAP VENT PLUG [3595990]	2.00 Each	\$4.33	\$8.65
KENWORTH PLUG ADAPTER {KW123} [D19005773]	1.00 Each	\$36.07	\$36.07
LIGHT CORD 2 WIRE CABLE W' ENDS 15FT [21-2272]	1.00 Each	\$143.89	\$143.89
LIGHT CORD 2 WIRE CABLE W' ENDS 15FT [21-2272]	1.00 Each	\$176.30	\$176.30
LIGHT CORD TRAILER 4 WAY 15' [194015]	2.00 Each	\$48.75	\$97.50
LIGHT CORD TRAILER 4 WAY 15' [194015]	1.00 Each	\$44.04	\$44.04
MOTHERS -X REF 35316 [MOT35316]	1.00 Each	\$9.42	\$9.42
PADDED WASHER [HWC05782]	2.00 Each	\$8.68	\$17.36
RELEASE BOLT [3030RBZ]	2.00 Each	\$2.34	\$4.67
SUMMER TRUCK WIPER BLADE 22" - J-HOOK [WP22031]	2.00 Each	\$8.16	\$16.32
TIRE DRIVE LIGHT CHAIN 7MM TRIPLE [11R245CHAIN2]	2.00 Each	\$276.26	\$552.52
WIPER BLADE 22" WINTER *NOTES [WW2210]	1.00 Each	\$16.13	\$16.13
		Total Parts	\$1,933.02
		Total Equip	\$0.00
		Total Cost	\$1,933.02

Item ID	Description	Completed By	Reported Hours
20608	9166- DIRECT BILL		0.00
21896	LINDA TOOK PARTS	Randy Wearmouth	0.00

Work Order:	12796	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Randy Wearmouth	Start Date:	6-27-2020
Kms:	8990	Stop Date:	6-27-2020
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
REESE KOCH	2.00	RT Shop Mech Rky	\$50.00	\$100.00
			Total Labor	\$100.00
LS BRAKE CHAMBER, TYPE 3030LS, 3.00" STROKE [FLT3030LCB20]	1.00	Each	\$56.61	\$56.61
			Total Parts	\$56.61
			Total Equip	\$0.00
			Total Cost	\$156.61

Item ID	Description	Completed By	Reported Hours
21425	BRAKE POT		2.00

Work Order:	13727	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Colton Parker	Start Date:	7-17-2020
Kms:	8990	Stop Date:	7-20-2020
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
REESE KOCH	5.00	RT Shop Mech Rky	\$50.00	\$250.00
			Total Labor	\$250.00
CAB AIR FILTER [CFR19012]	1.00	Each	\$14.44	\$14.44
ENGINE AIR FILTER [P637453 {xr P621725}]	1.00	Each	\$83.51	\$83.51
ENGINE LUBE FILTER [DBL7900 {xr P559000, LF14000NN}]	1.00	Each	\$33.90	\$33.90
ENGINE PRIMARY FUEL FILTER [FS19765 {xr P550851}]	1.00	Each	\$16.06	\$16.06
FEMCO ISX/QSK M27X2.0M [10-27200-02]	1.00	Each	\$40.57	\$40.57
FILTER CABIN AIR [F37-1018 {xr PA30269JAB}]	1.00	Each	\$41.77	\$41.77
FUEL FILTER [FF5825 NN]	1.00	Each	\$38.35	\$38.35
WIPER-BLADE PREMIUM 22" [WP22031]	2.00	Each	\$4.27	\$8.54
			Total Parts	\$277.14
			Total Equip	\$0.00
			Total Cost	\$527.14

Item ID	Description	Completed By	Reported Hours
16823	FEMCO ISX/QSK M27X2.0M [10-27200-02] - SOB PARTS - PO 876	Colton Parker	0.00
	p.o 876		

22515	30k/400hr Service - All Filters Replaced	Colton Parker	5.00
-------	--	---------------	------

Perform regular check list with the below fluids & filters will be replaced every A service.

Work Order:	14220	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Colton Parker	Start Date:	8-7-2020
Kms:	8990	Stop Date:	8-8-2020
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
H. KANIELA JOHNSON	1.50	RT Shop Weld Rky	\$49.00	\$73.50

		Total Labor	\$73.50
1" WING NUT COUPLER [6125-16]	1.00 Each	\$99.85	\$99.85
		Total Parts	\$99.85
		Total Equip	\$0.00
		Total Cost	\$173.35

Item ID	Description	Completed By	Reported Hours
23771	REPAIR FENDERS FALLING OFF, REPLACE BOLTS ON OTHER SIDE ALSO	Kani Johnson	1.00
23772	REPLACE FITTING ON HYD WHIP LINES	Kani Johnson	0.50

Work Order: 14423 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Colton Parker **Start Date:** 8-14-2020
Kms: 8990 **Stop Date:** 8-17-2020
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
WALTER BOESCH	1.00	RT Shop Mech Rky	\$50.00	\$50.00
			Total Labor	\$50.00
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$50.00

Item ID	Description	Completed By	Reported Hours
24116	REPAIR BROKEN FENDERS	Walt Boesch	1.00

Work Order: 14864 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: **Business Unit:** Trucks Heavy
Created by: Nick Depratto **Start Date:**
Kms: 8990 **Stop Date:**
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
SPEEDY INV 8728-595161[Custom]	0.00	Each	\$400.00	\$0.00
TRUCK WINDSHEILD - PB 567 [DW02038]	1.00	Each	\$400.00	\$400.00

Total Parts	\$400.00
Total Equip	\$0.00
Total Cost	\$400.00

Item ID	Description	Completed By	Reported Hours
24897	9166 - VENDOR REPAIR INVOICES	Nick Depratto	0.00
24898	9166 - VENDOR WINDSHIELD INVOICES	Nick Depratto	0.00
24899	9166 - VENDOR TIRE REPAIR INVOICES	Nick Depratto	0.00

Work Order:	15238	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Colton Parker	Start Date:	9-10-2020
Kms:	8990	Stop Date:	9-11-2020
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CLAYTON OLSON	0.25	RT Shop Mech Rky	\$50.00	\$12.50
H. KANIELA JOHNSON	1.00	RT Shop Weld Rky	\$49.00	\$49.00
REESE KOCH	10.00	RT Shop Mech Rky	\$50.00	\$500.00
			Total Labor	\$561.50
BUNK FILTER - W/COVER PB 567 & KW T880 [CF19012]	1.00	Each	\$20.54	\$20.54
CAB FILTER - PB 567 & KW T880 [F37-1018 {xr PA30269JAB}]	1.00	Each	\$40.51	\$40.51
CAB FILTER - W/COVER PB 567 & KW T880 [CF19013]	1.00	Each	\$30.30	\$30.30
ENGINE AIR FILTER [P637453 {xr P621725}]	1.00	Each	\$109.15	\$109.15
ENGINE LUBE FILTER [DBL7900 {xr P559000, LF14000NN}]	1.00	Each	\$33.52	\$33.52
ENGINE SECONDARY FUEL FILTER [DBF6776 {xr FF5776, P555776, FF5825NN}]	1.00	Each	\$42.51	\$42.51
GLAD HAND SEAL CLOSE [H41736]	2.00	Each	\$0.77	\$1.54
PRIMARY ENGINE FUEL FILTER [P550849 {xr FS19764, FS19763}]	1.00	Each	\$15.87	\$15.87
			Total Parts	\$293.94
			Total Equip	\$0.00
			Total Cost	\$855.44

Item ID	Description	Completed By	Reported Hours
24557	CHECK GPS SERIAL# AND IGNITION STATE	Clayton Olson	0.25
25435	30k/400hr Service - All Filters Replaced	Reese Koch	11.00

Perform regular check list with the below fluids & filters will be replaced every A service.

Work Order: 15402
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Rocky Mountain House Shop
Created by: Colton Parker
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 9-16-2020
Stop Date: 9-16-2020

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
BRENT EVANS	8.00	RT Shop Mech Rky	\$50.00	\$400.00
H. KANIELA JOHNSON	5.00	RT Shop Weld Rky	\$49.00	\$245.00
Total Labor				\$645.00
Total Parts				\$0.00
Total Equip				\$0.00
Total Cost				\$645.00

Item ID	Description	Completed By	Reported Hours
26053	REPAIR BROKEN REAR FENDER MOUNTS	Brent Evans	13.00

Work Order: 16135
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Rocky Mountain House Shop
Created by: Colton Parker
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 10-14-2020
Stop Date: 10-14-2020

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CLAYTON OLSON	0.50	RT Shop Mech Rky	\$50.00	\$25.00
Total Labor				\$25.00
Total Parts				\$0.00
Total Equip				\$0.00
Total Cost				\$25.00

Item ID	Description	Completed By	Reported Hours
27583	AIR LEAK	Clayton Olson	0.50

Work Order: 16317
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Rocky Mountain House Shop
Created by: Colton Parker
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 10-21-2020
Stop Date: 10-23-2020

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
KYLE DRANEY	1.50	RT Shop Weld Rky	\$49.00	\$73.50
			Total Labor	\$73.50
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$73.50

Item ID	Description	Completed By	Reported Hours
27935	PTO NOT KICKING OUT	Nick Depratto	1.50

Work Order:	16520	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Nick Depratto	Start Date:	10-28-2020
Kms:	8990	Stop Date:	10-29-2020
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
REESE KOCH	5.00	RT Shop Mech Rky	\$50.00	\$250.00
WALTER BOESCH	8.75	RT Shop Mech Rky	\$50.00	\$437.50
			Total Labor	\$687.50
1" QUICK COUPLER FEMALE [6601-16-16]	2.00	Each	\$75.32	\$150.64
AD-IS AIR DRYER DESSICANT FILTER CARTRIDGE [5008414PG {xr FLT109994, AC1001}]	1.00	Each	\$134.68	\$134.68
CAB & BUNK FILTER - W/O COVER PB 567 & KW T880 [CFR19012]	1.00	Each	\$12.98	\$12.98
CAB FILTER - PB 567 & KW T880 [F37-1018 {xr PA30269JAB}]	1.00	Each	\$40.49	\$40.49
CAB FILTER - W/O COVER PB 567 & KW T880 [CFR19013]	1.00	Each	\$11.45	\$11.45
DUMP PUMP AIR SHIFT DIRECT [DMD25ZLAS250]	1.00	Each	\$596.64	\$596.64
ENGINE AIR FILTER [P637453 {xr P621725}]	1.00	Each	\$139.10	\$139.10
ENGINE LUBE FILTER [DBL7900 {xr P559000, LF14000NN}]	1.00	Each	\$40.24	\$40.24
ENGINE SECONDARY FUEL FILTER [DBF6776 {xr FF5825NN}]	1.00	Each	\$44.61	\$44.61
Hydraulic, Spin-On [P550387 {HF6720}]	2.00	Each	\$14.60	\$29.20
MNPT-MALE JIC 37DEG STR [0103-16-16]	2.00	Each	\$6.20	\$12.40
MNPT-MALE JIC 37DEG STR [0103-20-20]	1.00	Each	\$12.44	\$12.44
PRIMARY ENGINE FUEL FILTER [P550849 {xr FS19764, FS19763}]	1.00	Each	\$18.61	\$18.61
WURTH BRAKE & PARTS CLEANER [WURTH]	1.00	Each	\$2.69	\$2.69
			Total Parts	\$1,246.15
			Total Equip	\$0.00
			Total Cost	\$1,933.65

Item ID	Description	Completed By	Reported Hours
---------	-------------	--------------	----------------

27013	REPLACE AIR DRYER	Walt Boesch	5.00
28066	30k/400hr Service - All Filters Replaced	Reese Koch	1.25
Perform regular check list with the below fluids & filters will be replaced every A service.			
26746	CRACKED WINDSHIELD	Walt Boesch	0.00
26808	HEATER FAN SOUNDS LIKE ITS BURNING OUT - PT 53271	Walt Boesch	0.50
28233	REPLACE SOLENOID FOR PTO	Walt Boesch	6.00
28234	REPLACE BUMPER	Walt Boesch	1.00
28272	REPAIR ANITSAIL HANGER	Walt Boesch	0.00

Work Order:	16600	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Nick Depratto	Start Date:	11-4-2020
Kms:	8990	Stop Date:	11-18-2020
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
REESE KOCH	1.50	RT Shop Mech Rky	\$50.00	\$75.00
			Total Labor	\$75.00
SOLENOID VALVE KIT [5602-01-020]	1.00	Each	\$69.23	\$69.23
WURTH BRAKE & PARTS CLEANER [WURTH]	1.00	Each	\$2.69	\$2.69
			Total Parts	\$71.92
			Total Equip	\$0.00
			Total Cost	\$146.92

Item ID	Description	Completed By	Reported Hours
28373	REPLACE PTO SOLENOID	Reese Koch	1.00
28601	INSTALL MISSING ASGA 6096 STICKER ON BUMPER	Reese Koch	0.50

Work Order:	17390	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Shop Operations - RMH	Business Unit:	Trucks Heavy
Created by:	Darcy Hallock	Start Date:	12-3-2020
Kms:	8990	Stop Date:	12-3-2020
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	3.50	RT Shop Tire Tech	\$35.00	\$122.50
			Total Labor	\$122.50
DRIVE TIRE - BRIDGESTONE [11R245M775]	8.00	Each	\$536.00	\$4,288.02
			Total Parts	\$4,288.02
			Total Equip	\$0.00
			Total Cost	\$4,410.52

Item ID	Description	Completed By	Reported Hours
30122	9166- 12/03/2020	Darcy Hallock	3.50

Work Order:	17465	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Nick Depratto	Start Date:	12-8-2020
Kms:	8990	Stop Date:	12-8-2020
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CLAYTON OLSON	4.25	RT Shop Mech Rky	\$50.00	\$212.50
H. KANIELA JOHNSON	1.00	RT Shop Weld Rky	\$49.00	\$49.00
			Total Labor	\$261.50
24" SHR.ANTI SAIL [AS2620C]	1.00	Each	\$9.08	\$9.08
ALARM - BACK UP (12V) [73040]	1.00	Each	\$19.64	\$19.64
PADDED WASHER [HWC05782]	2.00	Each	\$7.03	\$14.06
SCREW - WING M10X1.5X40MM [HWC09341]	2.00	Each	\$11.43	\$22.85
			Total Parts	\$65.64
			Total Equip	\$0.00
			Total Cost	\$327.14

Item ID	Description	Completed By	Reported Hours
28627	REPAIR ANITSAIL HANGER - PT 57107	Clayton Olson	0.25
30402	REPAIR CAUSE OF BACKUP ALARM NOT WORKING	Clayton Olson	3.00
29551	UPDATE VECU PROGRAMING WITH DAVIES - PROGRAM WITH BATTERY CHARGES	Clayton Olson	0.50
30403	REPAIR CRACKED DRIVER SIDE FENDER	Clayton Olson	1.50

29422 ADJUST CONTINOUS BUNK HEATER TIMER - SEE NICK OR COLTON Clayton Olson 0.00

30333 INSTALL NEXT YEARS ASGA STICKER Clayton Olson 0.00

Work Order:	17498	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Shop Operations - RMH	Business Unit:	Trucks Heavy
Created by:	Darcy Hallock	Start Date:	12-9-2020
Kms:	8990	Stop Date:	12-9-2020
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	2.50	RT Shop Tire Tech	\$35.00	\$87.50
			Total Labor	\$87.50
STEER TIRE - BRIDGESTONE [315/80R225M843]	2.00	Each	\$750.00	\$1,500.00
			Total Parts	\$1,500.00
			Total Equip	\$0.00
			Total Cost	\$1,587.50

Item ID	Description	Completed By	Reported Hours
30461	9166- 12/09/2020	Darcy Hallock	2.50

Work Order:	18613	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Colton Parker	Start Date:	2-16-2021
Kms:	8990	Stop Date:	2-17-2021
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
WALTER BOESCH	3.50	RT Shop Mech Rky	\$50.00	\$175.00
			Total Labor	\$175.00
DEF HOSE [M5060393233150]	1.00	Each	\$476.28	\$476.28
HOSE DEF [M50-6039-3233000]	1.00	Each	\$435.79	\$435.79
HOSE DEF [M50-6039-3233000]	1.00	Each	(\$435.79)	(\$435.79)
			Total Parts	\$476.28
			Total Equip	\$0.00
			Total Cost	\$651.28

Item ID	Description	Completed By	Reported Hours
---------	-------------	--------------	----------------

32759	DEF LEAKING	Walt Boesch	1.50
32760	TOWER SWITCHES NOT WORKING	Walt Boesch	2.00

Work Order: 19896 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 4-15-2021
Kms: 8990 **Stop Date:** 4-16-2021
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CLAYTON OLSON	0.25	RT Shop Mech Rky	\$50.00	\$12.50
			Total Labor	\$12.50
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$12.50

Item ID	Description	Completed By	Reported Hours
35693	BOOST. NO START	Clayton Olson	0.25

Work Order: 20866 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 5-27-2021
Kms: 8990 **Stop Date:** 5-31-2021
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CLAYTON OLSON	10.00	RT Shop Mech Rky	\$50.00	\$500.00
GARRY MELVIN	2.50	RT Shop Mech Rky	\$50.00	\$125.00
H. KANIELA JOHNSON	1.00	RT Shop Weld Rky	\$49.00	\$49.00
			Total Labor	\$674.00
1" MALE WING COUPLER NIPPLE HP CONNECT [6105-16]	1.00	Each	\$77.39	\$77.39
CAB & BUNK FILTER - W/COVER PB 567 & KW T880 [CF19012 {xr X1987001}]	1.00	Each	\$20.57	\$20.57
CAB & BUNK FILTER - W/O COVER PB 567 & KW T880 [CFR19012]	1.00	Each	\$11.36	\$11.36
CAB FILTER - PB 567 & KW T880 {PA30269JAB} [F37-1018]	1.00	Each	\$39.89	\$39.89
CAB FILTER - W/COVER PB 567 & KW T880 [CF19013]	1.00	Each	\$23.63	\$23.63
ENGINE AIR FILTER {P621725} [P637453]	1.00	Each	\$130.16	\$130.16

ENGINE LUBE FILTER {P559000, LF14000NN} [DBL7900]	1.00 Each	\$38.21	\$38.21
ENGINE SECONDARY FUEL FILTER {FF5825NN} [DBF6776]	1.00 Each	\$38.36	\$38.36
FNPT- CRIMP [10243-4-4]	2.00 Each	\$8.05	\$16.10
HOSE HYDRAULIC 1" 4 WIRE 4000PSI [722TC-16-RL]	13.00 Each	\$1.39	\$18.07
PRIMARY ENGINE FUEL FILTER [P550849 {xr FS19764, FS19763}]	1.00 Each	\$18.79	\$18.79
WHEEL SPACER BETWEEN RIMS [A5903]	6.00 Each	\$4.77	\$28.64
Total Parts			\$461.16
Total Equip			\$0.00
Total Cost			\$1,135.16

Item ID	Description	Completed By	Reported Hours
33439	LICENSE PLATE LIGHT MISSING - PT 64358	Blair MacAulay	0.00
37666	CVIP -- Annual Perform annual CVIP. Change hydraulic filter if applicable.	Clayton Olson	4.50
37733	SECURE FIRE EXTINGUISHER	Clayton Olson	0.25
37734	INSTALL REFLECTIVE STRIP ON REAR MUD FLAPS	Clayton Olson	0.25
37735	REPAIR LH EXHAUST BRACKET	Clayton Olson	0.50
37736	REPLACE HYDRAULIC PRESSURE HOSE	Clayton Olson	0.75
37737	REPAIR RH STACK BRACKET	Clayton Olson	0.50
37738	REPAIR TRAILER AIR LINES	Clayton Olson	0.25
37739	REPLACE A/C BELT	Clayton Olson	0.25
37740	#2 AXLE SHOCK BOLT MISSING. SECURE AIR LINES	Clayton Olson	0.50
37741	REPLACE LR MUD FLAP	Clayton Olson	0.25
37742	WELD R REAR FENDER	Clayton Olson	1.00
37027	30k/400hr Service - All Filters Replaced Perform regular check list with the below fluids & filters will be replaced every A service.	Blair MacAulay	4.50

Work Order:	21311	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Horburg Pit	Business Unit:	Trucks Heavy
Created by:	Darcy Hallock	Start Date:	6-14-2021
Kms:	8990	Stop Date:	6-14-2021
Hr:	9025		

Work Order Cost Summary			
Description	Quantity	Labor Type	Total

DARCY HALLOCK	0.25 RT	Shop Tire Tech	\$35.00	\$8.75
			Total Labor	\$8.75
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$8.75

Item ID	Description	Completed By	Reported Hours
38552	9166- 06/14/2021	Darcy Hallock	0.25

Work Order: 21476 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 6-20-2021
Kms: 8990 **Stop Date:** 6-22-2021
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CLAYTON OLSON	2.00	RT Shop Mech Rky	\$50.00	\$100.00
			Total Labor	\$100.00
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$100.00

Item ID	Description	Completed By	Reported Hours
38901	REPAIR CEL	Clayton Olson	2.00

Work Order: 21561 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:**
Kms: 8990 **Stop Date:**
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
HEADLAMP 23762 [H11-55/BP]	1.00	Each	\$9.98	\$9.98
			Total Parts	\$9.98
			Total Equip	\$0.00
			Total Cost	\$9.98

Item ID	Description	Completed By	Reported Hours
39069	REPLACE RH HEADLIGHT	Blair MacAulay	0.00

Work Order: 21806 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 7-1-2021
Kms: 8990 **Stop Date:** 7-5-2021
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CLAYTON OLSON	0.25	RT Shop Mech Rky	\$50.00	\$12.50
			Total Labor	\$12.50
FAN DRIVE BELT 12RIBS X 2180mm {D84-1000-6122180, FLTBT858K12} [858K12BLT]	1.00	Each	\$81.68	\$81.68
GLADHAND SEAL CLOSE [FS312A]	2.00	Each	\$0.57	\$1.13
			Total Parts	\$82.81
			Total Equip	\$0.00
			Total Cost	\$95.31

Item ID	Description	Completed By	Reported Hours
39643	REPLACE FAN BELT	Clayton Olson	0.25

Work Order: 22014 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Current Equipment Location **Business Unit:** Trucks Heavy
Created by: Nick Depratto **Start Date:** 7-8-2021
Kms: 8990 **Stop Date:** 7-9-2021
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
KW RD INV SR2004175[Custom]	1.00	Each	\$636.00	\$636.00
			Total Parts	\$636.00
			Total Equip	\$0.00
			Total Cost	\$636.00

Item ID	Description	Completed By	Reported Hours
40048	9166 - 7/7/2021 - KW RD - TRANS FAULT, TRUCK WILL NOT MOVE	Nick Depratto	0.00

Work Order: 22143
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Rocky Mountain House Shop
Created by: Blair MacAulay
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 7-13-2021
Stop Date: 7-13-2021

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
KIRBY BERGEN	1.50	RT Shop Mech Rky	\$50.00	\$75.00
			Total Labor	\$75.00
CAB & BUNK FILTER - W/O COVER PB 567 & KW T880 [CFR19012]	1.00	Each	\$11.31	\$11.31
CAB FILTER - PB 567 & KW T880 {PA30269JAB} [F37-1018]	1.00	Each	\$39.75	\$39.75
CAB FILTER - W/O COVER PB 567 & KW T880 [CFR19013]	1.00	Each	\$9.87	\$9.87
			Total Parts	\$60.93
			Total Equip	\$0.00
			Total Cost	\$135.93

Item ID	Description	Completed By	Reported Hours
40297	REPAIR A/C	Kirby Bergen	1.50

Work Order: 23187
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Rocky Mountain House Shop
Created by: Blair MacAulay
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 8-17-2021
Stop Date: 8-18-2021

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
BRETT LANGFORD	4.50	RT Shop Mech Rky	\$50.00	\$225.00
KIRBY BERGEN	0.50	RT Shop Mech Rky	\$50.00	\$25.00
MITCHELL WILLERT	0.50	RT Shop Mech Rky	\$50.00	\$25.00
			Total Labor	\$275.00
CAB & BUNK FILTER - W/O COVER PB 567 & KW T880 [CFR19012]	1.00	Each	\$11.63	\$11.63
CAB FILTER - PB 567 & KW T880 {PA30269JAB} [F37-1018]	1.00	Each	\$40.33	\$40.33
CAB FILTER - W/O COVER PB 567 & KW T880 [CFR19013]	1.00	Each	\$10.14	\$10.14
ENGINE AIR FILTER {P621725} [P637453]	1.00	Each	\$72.97	\$72.97
FILTER FUEL SEPARATOR {P550849} [FS19763]	1.00	Each	\$16.39	\$16.39
FILTER FUEL SPIN-ON {DBF6776} [FF5825NN]	1.00	Each	\$40.26	\$40.26
FILTER HYDRAULIC SPIN-ON {P550387} [HF6720]	2.00	Each	\$14.01	\$28.02
FILTER LUBE SPIN-ON {DBL7900} [LF1400NN]	1.00	Each	\$36.80	\$36.80
HANGER- MUDFLAP 32 1/2" [A253275RL]	1.00	Each	\$19.69	\$19.69

LIGHT GROTE - MICRONOVA MULTI-VOLT DOT LED LICENSE LIGHTS [60381]	1.00 Each	\$30.38	\$30.38
PIDHERNEY MUD FLAP - 24 X 24 [PB2424]	1.00 Each	\$26.36	\$26.36
		Total Parts	\$332.97
		Total Equip	\$0.00
		Total Cost	\$607.97

Item ID	Description	Completed By	Reported Hours
3921	ADJUST CLUTCH AS REQUIRED - 1/2" BETWEEN CLUTCH BRAKE AND RELEASE READING	Blair MacAulay	0.00
40334	REPLACE TRANSMISSION OIL AND FILTER (IF APPLICABLE) - USE TRANS 75-90	Blair MacAulay	0.50
40436	ADJUST CLUTCH AS REQUIRED - 1/2" BETWEEN CLUTCH BRAKE AND RELEASE READING	Blair MacAulay	0.00
39366	SOB - OIL DRAIN PLUG 1 - 10-27200-02	Blair MacAulay	0.00
42212	30k/400hr Service - All Filters Replaced Perform regular check list with the below fluids & filters will be replaced every A service.	Blair MacAulay	4.50
37902	REPLACE HYDRAULIC FILTER	Blair MacAulay	0.50

Work Order:	25125	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop, Shop Operations - RMH	Business Unit:	Trucks Heavy
Created by:	Nick Depratto	Start Date:	10-22-2021
Kms:	8990	Stop Date:	10-22-2021
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
BRETT LANGFORD	8.00	RT Shop Mech Rky	\$50.00	\$400.00
DARCY HALLOCK	1.75	RT Shop Tire Tech	\$35.00	\$61.25
			Total Labor	\$461.25
70 GAL TANK STR[Custom]	1.00	Each	\$156.00	\$156.00
ADIS AIR DRYER DESICCANT FILTER CARTRIDGE [5008414PG]	1.00	Each	\$134.58	\$134.58
ADIS, ADIP AIR DRYER PURGE VALVE [K022105]	1.00	Each	\$118.19	\$118.19
HYDRAULIC TANK [HYD70CP]	1.00	Each	\$989.00	\$989.00
PARTS FREIGHT [7540]	1.00	Each	\$200.00	\$200.00
SHOCK ABSORBER, SUSPENSION, FLEETLINE, EXTENDED, 20.59 IN., COLLAPSED, 13.03 IN., STROKE, 7.57 IN., [65176]	1.00	Each	\$92.94	\$92.94
SPEEDY INV 8728-613831[Custom]	1.00	Each	\$400.00	\$400.00
			Total Parts	\$2,090.71
			Total Equip	\$0.00
			Total Cost	\$2,551.96

Item ID	Description	Completed By	Reported Hours
---------	-------------	--------------	----------------

49902 CHECK WINDSHIELD Maintain Administrator 0.00

42848 E LONG ISSUES - PT 80463 Brett Langford 0.00

46106 REPAIR LEAKING PURGE VALVE Brett Langford 1.00

46107 REPAIR LOOSE SHOCK Brett Langford 2.00

45614 ADJUST CLUTCH AS REQUIRED - 1/2" BETWEEN CLUTCH BRAKE AND RELEASE Brett Langford 0.00

45043 REPLACE AIR DRYER CARTRIDGE FILTER Brett Langford 1.00

46105 REPAIR HYDRAULIC TANK LEAK Brett Langford 4.00

46110 9166- 10/22/2021 "ROTATE STEER TIRE" Darcy Hallock 1.75

Work Order:	25529	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Current Equipment Location	Business Unit:	Trucks Heavy
Created by:	Rob Hilton	Start Date:	11-7-2021
Kms:	8990	Stop Date:	11-7-2021
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
ROBERT HILTON	2.00	RT Shop Tire Tech	\$35.00	\$70.00
			Total Labor	\$70.00
TIRE STEER FIRESTONE [31580R225FS819]	2.00	Each	\$665.03	\$1,330.06
			Total Parts	\$1,330.06
			Total Equip	\$0.00
			Total Cost	\$1,400.06

Item ID	Description	Completed By	Reported Hours
46959	9166 - Replace steers	Rob Hilton	2.00

Work Order:	25599	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Nick Depratto	Start Date:	11-9-2021
Kms:	8990	Stop Date:	11-11-2021
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
-------------	----------	------------	------	-------

CLAYTON OLSON	10.00 RT	Shop Mech Rky	\$50.00	\$500.00
			Total Labor	\$500.00
GASKET - PTO SHIFTER COVER -X REF E716 [35P8]	1.00	Each	\$1.99	\$1.99
HYDRAULIC PUMP DUMP AIR SHIFT [DMD25ZLAS250]	1.00	Each	\$561.34	\$561.34
PB/KW FRAME AIR SOLENOID (PTO, DIFF LOCK, 5TH WHEEL, SUSPENSION DUMP) [5602-01-020]	1.00	Each	\$66.86	\$66.86
POWER TAKE OFF [489XQAHX-V3XK]	1.00	Each	\$766.08	\$766.08
			Total Parts	\$1,396.27
			Total Equip	\$0.00
			Total Cost	\$1,896.27

Item ID	Description	Completed By	Reported Hours
47089	REPAIR CAUSE OF NO HYDRAULICS	Clayton Olson	10.00

Work Order: 25894 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 11-22-2021
Kms: 8990 **Stop Date:** 11-24-2021
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
MITCHELL WILLERT	1.00	RT Shop Mech Rky	\$50.00	\$50.00
			Total Labor	\$50.00
LIGHT CORD TRAILER 4 WAY 15' [19-4015]	1.00	Each	\$41.57	\$41.57
			Total Parts	\$41.57
			Total Equip	\$0.00
			Total Cost	\$91.57

Item ID	Description	Completed By	Reported Hours
47639	REPAIR 4 WIRE PLUG	Blair MacAulay	1.00

Work Order: 26143 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 11-30-2021
Kms: 8990 **Stop Date:** 12-1-2021
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
BRETT LANGFORD	1.00	RT Shop Mech Rky	\$50.00	\$50.00
			Total Labor	\$50.00

CLAMP- V BAND 4" [90-0012]	2.00 Each	\$14.24	\$28.48
GASKET- EXHAUST CIRCULAR 4" [2866636CUM]	2.00 Each	\$12.77	\$25.55
		Total Parts	\$54.03
		Total Equip	\$0.00
		Total Cost	\$104.03

Item ID	Description	Completed By	Reported Hours
48042	REPAIR EXHAUST LEAK	Blair MacAulay	1.00

Work Order: 26278 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Current Equipment Location **Business Unit:** Trucks Heavy
Created by: Rob Hilton **Start Date:** 12-6-2021
Kms: 8990 **Stop Date:** 12-6-2021
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
ROBERT HILTON	3.50	RT Shop Tire Tech	\$35.00	\$122.50
			Total Labor	\$122.50
TIRE DRIVE BANDAG [11R245BDY2]	8.00	Each	\$292.60	\$2,340.80
			Total Parts	\$2,340.80
			Total Equip	\$0.00
			Total Cost	\$2,463.30

Item ID	Description	Completed By	Reported Hours
48350	9166 - Replace Drive x8	Rob Hilton	3.50

Work Order: 26515 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 12-15-2021
Kms: 8990 **Stop Date:** 12-17-2021
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
GARRY MELVIN	9.00	RT Shop Mech Rky	\$50.00	\$450.00
H. KANIELA JOHNSON	1.00	RT Shop Weld Rky	\$49.00	\$49.00
KIRBY BERGEN	6.00	RT Shop Mech Rky	\$50.00	\$300.00
			Total Labor	\$799.00
1-1/2" BALLVALVE [BV4103-K]	2.00	Each	\$31.94	\$63.88

FILTER AIR {AF55836} [W2084001]	1.00 Each	\$10.90	\$10.90
FILTER AIR {P621725} [P637453]	1.00 Each	\$119.68	\$119.68
FILTER CAB AIR PB 567 & KW T880 {PA30269JAB} [F37-1018]	1.00 Each	\$41.23	\$41.23
FILTER CAB AIR W/O COVER PB 567 & KW T880 [CFR19012]	1.00 Each	\$11.78	\$11.78
FILTER CAB AIR W/O COVER PB 567 & KW T880 [CFR19013]	1.00 Each	\$10.30	\$10.30
FILTER FUEL SEPARATOR {P550849} [FS19763]	1.00 Each	\$16.53	\$16.53
FILTER FUEL SPIN-ON {DBF6776} [FF5825NN]	1.00 Each	\$41.22	\$41.22
FILTER LUBE SPIN-ON {DBL7900, LF14000NN} [LF14001NN]	1.00 Each	\$32.82	\$32.82
Total Parts			\$348.34
Total Equip			\$0.00
Total Cost			\$1,147.34

Item ID	Description	Completed By	Reported Hours
47489	30k/400hr Service - All Filters Replaced Perform regular check list with the below fluids & filters will be replaced every A service.	Kirby Bergen	7.50
48176	SOB - HYDRAULIC TANK	Kirby Bergen	7.50
48964	REPAIR LR FENDER	Kani Johnson	1.00
48963	ADJUST RIDE HEIGHT	Kirby Bergen	0.00

Work Order: 26982 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 1-13-2022
Kms: 8990 **Stop Date:** 1-14-2022
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
BRETT LANGFORD	4.25	RT Shop Mech Rky	\$50.00	\$212.50
MITCHELL WILLERT	5.50	RT Shop Mech Rky	\$50.00	\$275.00
Total Labor				\$487.50
5603-01-020 KIT-BASE 1 SERVICE, NYLON[Custom]	1.00	Each	\$219.02	\$219.02
PB/KW FRAME AIR SOLENOID (PTO, DIFF LOCK, 5TH WHEEL, SUSPENSION DUMP) [5602-01-020]	6.00	Each	\$67.20	\$403.20
PB/KW FRAME AIR SOLENOID (PTO, DIFF LOCK, 5TH WHEEL, SUSPENSION DUMP) [5602-01-020]	1.00	Each	\$66.63	\$66.63
Total Parts				\$688.85
Total Equip				\$0.00
Total Cost				\$1,176.35

Item ID	Description	Completed By	Reported Hours
---------	-------------	--------------	----------------

49820	REPAIR TRACTION CONTROL	Mitchell Willert	0.50
49810	CHECK DIFF LOCK OPERATION	Mitchell Willert	9.25

Work Order: 27018 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: GREATWEST KENWORTH RED DEER **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 1-14-2022
Kms: 8990 **Stop Date:** 1-24-2022
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
GWK INV SR2005153[Custom]	1.00	Each	\$368.73	\$368.73
			Total Parts	\$368.73
			Total Equip	\$0.00
			Total Cost	\$368.73

Item ID	Description	Completed By	Reported Hours
49861	REPAIR DIFF LOCK CONTROLS	Blair MacAulay	0.00

Work Order: 27157 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 1-19-2022
Kms: 8990 **Stop Date:** 1-21-2022
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$0.00

Item ID	Description	Completed By	Reported Hours
50115	REPAIR RH WIPER	Blair MacAulay	0.00

Work Order: 27158 **Status:** Transferred

Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: MAIN YARD
Created by: Darcy Hallock
Kms: 8990
Hr: 9025

Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 1-19-2022
Stop Date: 1-19-2022

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	0.25	RT Shop Tire Tech	\$35.00	\$8.75
			Total Labor	\$8.75
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$8.75

Item ID	Description	Completed By	Reported Hours
50116	9166- 01/19/2022 "RE-TORQUE"	Darcy Hallock	0.25

Work Order: 27190
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Rocky Mountain House Shop
Created by: Blair MacAulay
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 1-20-2022
Stop Date: 1-24-2022

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
GARRY MELVIN	3.50	RT Shop Mech Rky	\$50.00	\$175.00
H. KANIELA JOHNSON	3.00	RT Shop Weld Rky	\$49.00	\$147.00
KIRBY BERGEN	1.00	RT Shop Mech Rky	\$50.00	\$50.00
			Total Labor	\$372.00
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$372.00

Item ID	Description	Completed By	Reported Hours
50193	REPAIR HYDRAULIC LEAK	Kirby Bergen	7.50

Work Order: 27497
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Rocky Mountain House Shop
Created by: Blair MacAulay
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 1-31-2022
Stop Date: 2-1-2022

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
BRENT EVANS	0.75	RT Shop Mech Rky	\$50.00	\$37.50
			Total Labor	\$37.50
TRAILER LIGHT CORD TARP 15' 2 POLE VERTICAL [212272]	1.00	Each	\$163.49	\$163.49
			Total Parts	\$163.49
			Total Equip	\$0.00
			Total Cost	\$200.99

Item ID	Description	Completed By	Reported Hours
---------	-------------	--------------	----------------

50817	REPAIR TARP CONTROL	Brent Evans	0.75
-------	---------------------	-------------	------

Work Order:	27629	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Blair MacAulay	Start Date:	2-7-2022
Kms:	8990	Stop Date:	2-8-2022
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
MITCHELL WILLERT	0.50	RT Shop Mech Rky	\$50.00	\$25.00
			Total Labor	\$25.00
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$25.00

Item ID	Description	Completed By	Reported Hours
---------	-------------	--------------	----------------

51164	REPAIR CEL	Mitchell Willert	0.50
-------	------------	------------------	------

Work Order:	27668	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Nick Depratto	Start Date:	2-7-2022
Kms:	8990	Stop Date:	2-11-2022
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
GWK SR2005256[Custom]	1.00	Each	\$0.01	\$0.01
GWK SR2005305[Custom]	1.00	Each	\$833.96	\$833.96

	Total Parts	\$833.97
	Total Equip	\$0.00
	Total Cost	\$833.97

Item ID	Description	Completed By	Reported Hours
51238	CHECK ENGINE LIGHT AND DEF PUMP FAULTS	Blair MacAulay	0.00

Work Order:	27951	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Brewster Pit	Business Unit:	Trucks Heavy
Created by:	Darcy Hallock	Start Date:	2-16-2022
Kms:	8990	Stop Date:	2-16-2022
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	3.00	RT Shop Tire Tech	\$35.00	\$105.00
			Total Labor	\$105.00
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$105.00

Item ID	Description	Completed By	Reported Hours
51749	9166- 02/16/2022 "INSPECT STEERS"	Darcy Hallock	3.00

Work Order:	28334	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Blackfalds Shop	Business Unit:	Trucks Heavy
Created by:	Oom Jarussirirat	Start Date:	3-4-2022
Kms:	8990	Stop Date:	3-7-2022
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
STEPHEN DEWOLFE	1.00	RT Shop Mech Blfds	\$49.00	\$49.00
			Total Labor	\$49.00
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$49.00

Item ID	Description	Completed By	Reported Hours
52670	TRANS SHIFTING ISSUE	Stephen DeWolfe	1.00

Work Order:	31090	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Blackfalds Shop	Business Unit:	Trucks Heavy
Created by:	Oom Jarussirirat	Start Date:	5-11-2022
Kms:	8990	Stop Date:	5-13-2022
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
BERNIE SEEFRIED	15.00	RT Shop Mech Blfds	\$49.00	\$735.00
STEPHEN DEWOLFE	5.00	RT Shop Mech Blfds	\$49.00	\$245.00
		Total Labor		\$980.00
16.50X8.62 BRAKE DRUM [38BD07AB]	4.00	Each	\$208.08	\$832.32
2 POLE SOCKET [15-328]	2.00	Each	\$23.82	\$47.65
5TH WHEEL SLIDER LOCK AIR COILED AIR LINE {FWSK-1} [KP155K]	1.00	Each	\$19.97	\$19.97
ADIS AIR DRYER COMPLETE [5010696]	1.00	Each	\$427.66	\$427.66
ADIS AIR DRYER COMPLETE CORE [5010696C]	1.00	Each	\$221.60	\$221.60
AIR DRYER - ADIS CORE[Custom]	1.00	Each	(\$218.07)	(\$218.07)
BRAKE DRUM [FLT4410B]	2.00	Each	\$258.98	\$517.96
BRAKE SHOE KIT[Custom]	2.00	Each	\$83.45	\$166.90
EXTENDED TRAILER STUD [102292]	20.00	Each	\$9.24	\$184.80
FILTER AIR {P621725} [P637453]	1.00	Each	\$145.91	\$145.91
FILTER CAB AIR W/O COVER PB 567 & KW T880 {X1987001, CFR19012} [AF55839]	1.00	Each	\$18.34	\$18.34
FILTER FUEL SEPARATOR {P550849} [FS19763]	1.00	Each	\$17.07	\$17.07
FILTER FUEL SPIN-ON {DBF6776} [FF5825NN]	1.00	Each	\$42.14	\$42.14
FILTER HYDRAULIC SPIN-ON {P550388} [HF6710]	2.00	Each	\$13.45	\$26.90
FILTER LUBE SPIN-ON {DBL7900, LF14000NN} [LF14001NN]	1.00	Each	\$38.76	\$38.76
GLADHAND SEAL CLOSE [FS312A]	2.00	Each	\$0.60	\$1.21
HARNESS - DIFF LOCK SENSOR [129047]	2.00	Each	\$41.15	\$82.31
ILS PINS AND BUSHINGS [RK10605]	1.00	Each	\$66.48	\$66.48
JUMP - WIRE MAGNETIC PICKUP [P92-1571-0600]	2.00	Each	\$87.44	\$174.89
KIT- BRA, NEW [KEG24711QP]	4.00	Each	\$126.63	\$506.52
LIGHT CORD 2 WIRE CABLE W' ENDS 15FT [21-2272]	2.00	Each	\$143.89	\$287.79
REFLECTOR[Custom]	1.00	Each	\$20.80	\$20.80
TEMPERATURE SENDER [Q21-1002]	2.00	Each	\$78.39	\$156.78
		Total Parts		\$3,786.68
		Total Equip		\$0.00
		Total Cost		\$4,766.68

Item ID	Description	Completed By	Reported Hours
---------	-------------	--------------	----------------

57086 30k/400hr Service - All Filters Replaced Stephen DeWolfe 2.25
Perform regular check list with the below fluids & filters will be replaced every A service.

57087 REPLACE HYDRAULIC FILTER Bernie Seefried 0.25

57171 NEED NEW GLAD HANDS RUBBER Bernie Seefried 0.25

57237 REPLACE WHEEL STUDS AS NECESSARY Bernie Seefried 0.75

57169 NEED NEW 5TH WHEEL PIN/BUSHING/COIL AIR LINE Bernie Seefried 0.75

57168 NEED A NEW TRL TARP CORD; ON DECK Bernie Seefried 1.25

57170 REPLACE DIFF TEMP/LOCK/HARNESS AS NECESSARY Bernie Seefried 0.50

57166 NEED ALL NEW BRAKES AND DRUMS Bernie Seefried 0.00

48476 INSTALL NEXT YEARS ASGA STICKER Bernie Seefried 0.25

57175 NEED TO FILL 1 DIFF; OIL LEVEL LOW Bernie Seefried 0.25

57174 ENG WEBASTO IS NOT WORKING Stephen DeWolfe 1.75

57156 REPLACE BRAKE SHOES AND DRUM AS NECESSARY Bernie Seefried 2.50

57172 LOOSE SHOCKS; #2 AXLE BOTH SIDES AND #3 RH Bernie Seefried 1.25

57173 REPLACE REFLECTOR AS NECESSARY Bernie Seefried 0.00

57167 NEED A NEW GOVERNOR FOR THE AIR DRYER Bernie Seefried 2.00

57069 AIR LEAKS ISSUE; UNDER THE CAB Bernie Seefried 0.50

56575 CVIP -- Annual Bernie Seefried 5.50

Perform annual CVIP. Change hydraulic filter if applicable.

Work Order: 31524
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: MAIN YARD
Created by: Darcy Hallock
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 5-24-2022
Stop Date: 5-24-2022

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	0.50	RT Shop Tire Tech	\$35.00	\$17.50
			Total Labor	\$17.50
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$17.50

Item ID	Description	Completed By	Reported Hours
57845	9166- 05/24/2022 "RE-TORQUE"	Darcy Hallock	0.50

Work Order: 31545
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Oom Jarussirirat
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 5-25-2022
Stop Date: 5-26-2022

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
KEVEN GILLOTT	2.50	RT Shop Mech Rky	\$50.00	\$125.00
			Total Labor	\$125.00
WHEEL SPACER BETWEEN RIMS [A5903]	1.00	Each	\$5.78	\$5.78
			Total Parts	\$5.78
			Total Equip	\$0.00
			Total Cost	\$130.78

Item ID	Description	Completed By	Reported Hours
57880	SHAKING IN THE FRONT ENDS; WHILE BRAKING	Keven Gillott	2.50

Work Order: 31652
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: MAIN YARD
Created by: Darcy Hallock
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 5-30-2022
Stop Date: 5-30-2022

LIGHT CORD TRAILER 4 WAY 15' [194015]	1.00 Each	\$45.26	\$45.26
		Total Parts	\$45.26
		Total Equip	\$0.00
		Total Cost	\$94.31

Item ID	Description	Completed By	Reported Hours
58894	REPAIR DUMP CONTROLS	Mike Gates	1.00

Work Order: 32989 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Blackfalds Shop **Business Unit:** Trucks Heavy
Created by: Oom Jarussirirat **Start Date:** 7-13-2022
Kms: 8990 **Stop Date:** 7-14-2022
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
KEVEN GILLOTT	0.50	RT Shop Mech Rky	\$49.05	\$24.53
			Total Labor	\$24.53
5" ALUM LAP CLAMP [33970]	1.00	Each	\$15.21	\$15.21
			Total Parts	\$15.21
			Total Equip	\$0.00
			Total Cost	\$39.73

Item ID	Description	Completed By	Reported Hours
60729	PS EXHAUST STACK RUBBING ON THE SLEEPER	Keven Gillott	0.50

Work Order: 33180 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Blackfalds Shop **Business Unit:** Trucks Heavy
Created by: Nick Depratto **Start Date:** 7-19-2022
Kms: 8990 **Stop Date:** 7-20-2022
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY PLATT	0.50	RT Shop Mech Blfds	\$52.07	\$26.04
JOSHUA BOTA	1.00	RT Shop Mech Blfds	\$52.07	\$52.07
WAYNE KIRK	5.50	RT Shop Mech Blfds	\$52.07	\$286.39
			Total Labor	\$364.49
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$364.49

Item ID	Description	Completed By	Reported Hours
61045	HYDRAULIC LEAK	Wayne Kirk	7.00

Work Order: 33283 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Blackfalds Shop **Business Unit:** Trucks Heavy
Created by: Nick Depratto **Start Date:** 7-21-2022
Kms: 8990 **Stop Date:** 7-25-2022
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
WAYNE KIRK	2.00	RT Shop Mech Blfds	\$52.07	\$104.14
			Total Labor	\$104.14
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$104.14

Item ID	Description	Completed By	Reported Hours
61177	TUBS WILL NOT DUMP	Wayne Kirk	2.00

Work Order: 33498 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Blackfalds Shop **Business Unit:** Trucks Heavy
Created by: Oom Jarussirrat **Start Date:** 7-29-2022
Kms: 8990 **Stop Date:** 7-30-2022
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
JOSHUA BOTA	4.00	RT Shop Mech Blfds	\$52.07	\$208.28
			Total Labor	\$208.28
1" WING NUT COUPLER [QD-BTTWC16-16F]	1.00	Each	\$54.98	\$54.98
EXPANSION VALVE [W2073001]	1.00	Each	\$89.86	\$89.86
			Total Parts	\$144.84
			Total Equip	\$0.00
			Total Cost	\$353.12

Item ID	Description	Completed By	Reported Hours
---------	-------------	--------------	----------------

61674 LEAKING HYD FITTING & CHECK HYD OIL LEVEL

Joshua Bota

0.50

61523 CHECK A/C SYSTEM; NEED A NEW EXPANSION VALVE

Joshua Bota

3.50

Work Order: 33634
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Oom Jarussirirat
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 8-2-2022
Stop Date: 8-3-2022

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
JOSHUA BOTA	1.00	RT Shop Mech Blfds	\$52.07	\$52.07
			Total Labor	\$52.07
FILTER HYDRAULIC SPIN-ON {P550388} [HF6710]	2.00	Each	\$12.33	\$24.66
			Total Parts	\$24.66
			Total Equip	\$0.00
			Total Cost	\$76.73

Item ID	Description	Completed By	Reported Hours
61784	HYD LEAKS ISSUE; INNER FILTER	Joshua Bota	1.00

Work Order: 34256
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Oom Jarussirirat
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 8-19-2022
Stop Date: 8-20-2022

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
TYLER SCHWARZ	1.75	RT Shop Mech Rky	\$49.05	\$85.84
			Total Labor	\$85.84
#16 4 WIRE HYDRAULIC HOSE 5500PSI [SN300-16]	27.00	Foot	\$11.05	\$298.35
#16 HOSE TO #16MPT [N16-16MP]	4.00	Each	\$15.86	\$63.44
1" QUICK COUPLER NIPPLE [QD-ISOAN16-16F]	2.00	Each	\$22.99	\$45.98
1" WING NUT COUPLER [QD-BTTWC16-16F]	1.00	Each	\$54.98	\$54.98
			Total Parts	\$462.75
			Total Equip	\$0.00
			Total Cost	\$548.59

Item ID	Description	Completed By	Reported Hours
62876	NEED NEW HYD HOSES ON DECK; BOTH PRESSURE & RETURN LINES	Tyler Schwarz	1.50
62865	NEED A NEW TARP EXTENSION CORD	Tyler Schwarz	0.25

Work Order:	34265	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Blackfalds Shop	Business Unit:	Trucks Heavy
Created by:	Oom Jarussirirat	Start Date:	8-29-2022
Kms:	8990	Stop Date:	8-30-2022
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
STEPHEN DEWOLFE	4.50	RT Shop Mech Blfds	\$52.07	\$234.32
WAYNE KIRK	5.00	RT Shop Mech Blfds	\$52.07	\$260.35
		Total Labor		\$494.67
BRAKE CHAMBER - TYPE 3030LS, 3.00" STROKE [FLT3030LCB20]	1.00	Each	\$66.73	\$66.73
BRAKE STROKE INDICATOR [S100]	1.00	Each	\$0.80	\$0.80
CLARITY AUTO WINDSHIELD [WINDSHIELD2]	1.00	Each	\$405.00	\$405.00
FILTER AIR {P621725} [P637453]	1.00	Each	\$150.11	\$150.11
FILTER CAB AIR W/O COVER PB 567 & KW T880 {X1987001, CFR19012, SR2000092} [AF55839]	1.00	Each	\$19.85	\$19.85
FILTER FUEL SEPARATOR {P550849, FS19764} [FS19763]	1.00	Each	\$18.28	\$18.28
FILTER FUEL SPIN-ON {DBF6776, FF5971NN} [FF5825NN]	1.00	Each	\$50.73	\$50.73
FILTER LUBE SPIN-ON {DBL7900, LF14000NN} [LF14001NN]	1.00	Each	\$44.77	\$44.77
		Total Parts		\$756.27
		Total Equip		\$0.00
		Total Cost		\$1,250.94

Item ID	Description	Completed By	Reported Hours
62086	EXTRACT OIL SAMPLE AND SEND TO NICK D	Stephen DeWolfe	0.25
63431	LEAKING BRAKE POT; #3 AXLE LH	Stephen DeWolfe	1.00
63424	NEED A NEW WINDSHIELD; DW 2038	Wayne Kirk	0.25
61623	30k/400hr Service - All Filters Replaced Perform regular check list with the below fluids & filters will be replaced every A service.	Wayne Kirk	7.00
63430	REAR FENDERS CRACKED	Wayne Kirk	1.00

Work Order: 34415
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Current Equipment Location
Created by: Darcy Hallock
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 8-25-2022
Stop Date: 8-25-2022

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	2.25	RT Shop Tire Tech	\$36.33	\$81.74
			Total Labor	\$81.74
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$81.74

Item ID	Description	Completed By	Reported Hours
63204	9166- 08/25/2022 "INSTALL RUNOUT"	Darcy Hallock	2.25

Work Order: 34631
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Rocky Mountain House Shop
Created by: Blair MacAulay
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 9-1-2022
Stop Date: 9-2-2022

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
KIRBY BERGEN	1.00	RT Shop Mech Rky	\$49.05	\$49.05
MICHAEL GATES	4.00	RT Shop Mech Rky	\$49.05	\$196.20
OLIVER TRAUTMANN	2.50	RT Shop Mech Rky	\$49.05	\$122.63
			Total Labor	\$367.88
GLASS - DOOR LH [R44-1110]	1.00	Each	\$514.53	\$514.53
LIGHT AMBER OVAL 6" STOP TAIL TURN LED W/SEALED CONNECTOR [54143]	1.00	Each	\$25.00	\$25.00
			Total Parts	\$539.53
			Total Equip	\$0.00
			Total Cost	\$907.41

Item ID	Description	Completed By	Reported Hours
63668	REPLACE DRIVER'S SIDE WINDOW	Blair MacAulay	6.00
63694	CHECK ALIGNMENT	Blair MacAulay	1.50

Work Order: 34712
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Oom Jarussirrat
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 9-6-2022
Stop Date: 9-7-2022

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
TYLER SCHWARZ	0.75	RT Shop Mech Rky	\$49.05	\$36.79
			Total Labor	\$36.79
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$36.79

Item ID	Description	Completed By	Reported Hours
63819	4 WIRES SYSTEM ISSUE; SIDE DUMP WILL TILT TO DUMP BUT I WON'T COME BACK	Tyler Schwarz	0.75

Work Order: 35361
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Oom Jarussirrat
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 9-27-2022
Stop Date: 9-28-2022

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
JOSHUA BOTA	7.50	RT Shop Mech Blfds	\$52.07	\$390.53
			Total Labor	\$390.53
200A BOSCH ALTERNATOR [PG309940124625098]	1.00	Each	\$568.10	\$568.10
A/C SECONDARY BELT - SERPENTINE - RIBS: 6 - EFFECTIVE LENGTH (IN): 64.0 {638K6BLT, D84-1000-306162} [D84-1000-6061620]	1.00	Each	\$31.22	\$31.22
FAN DRIVE BELT 12RIBS X 2180mm {FLTBT858K12, 858K12BLT} [D84-1000-6122180]	1.00	Each	\$102.02	\$102.02
HOSE - SILICONE 2.5" [F50-1548]	1.00	Each	\$32.53	\$32.53
TENSIONER, BELT [3690067]	1.00	Each	\$388.95	\$388.95
			Total Parts	\$1,122.81
			Total Equip	\$0.00
			Total Cost	\$1,513.34

Item ID	Description	Completed By	Reported Hours
65145	COOLANT LEAKS ISSUE	Joshua Bota	1.50

65157	REPLACE DUST COVERS AS NECESSARY	Joshua Bota	1.00
-------	----------------------------------	-------------	------

65158 GREASE Joshua Bota 1.00

65142 BROKEN FAN BELT; ALTERNATOR BEARING LET GO Joshua Bota 4.00

Work Order: 36270 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Nick Depratto **Start Date:** 10-24-2022
Kms: 8990 **Stop Date:** 10-28-2022
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
GWK INV SR2006659[Custom]	1.00	Each	\$0.01	\$0.01
			Total Parts	\$0.01
			Total Equip	\$0.00
			Total Cost	\$0.01

Item ID	Description	Completed By	Reported Hours
66852	RD KW - HARD SHIFTING ISSUES	Nick Depratto	0.00
49989	SAFETY RECALL 21 KWD DAYTIME RUNNING LAMP FUNCTIONALITY	Nick Depratto	0.00

Work Order: 36437 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Blackfalds Shop **Business Unit:** Trucks Heavy
Created by: Oom Jarussirrat **Start Date:** 10-28-2022
Kms: 8990 **Stop Date:** 10-29-2022
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
JOSHUA BOTA	0.50	RT Shop Mech Blfds	\$52.07	\$26.04
			Total Labor	\$26.04
HEADLAMP 23762 [H11-55/BP]	2.00	Each	\$9.36	\$18.73
			Total Parts	\$18.73
			Total Equip	\$0.00
			Total Cost	\$44.76

Item ID	Description	Completed By	Reported Hours
67129	LIGHTS ISSUE; ONE HEAD LIGHT BURN OUT	Joshua Bota	0.50

Work Order:	36451	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Blackfalds Shop	Business Unit:	Trucks Heavy
Created by:	Oom Jarussirirat	Start Date:	10-28-2022
Kms:	8990	Stop Date:	11-1-2022
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
KAL TIRE LABOUR CHARGES [KALTIREL]	1.00	Each	\$158.50	\$158.50
TIRE STEER - FS820/M843/FS821/FS819 [31580R225STEER]	2.00	Each	\$771.36	\$1,542.72
			Total Parts	\$1,701.22
			Total Equip	\$0.00
			Total Cost	\$1,701.22

Item ID	Description	Completed By	Reported Hours
67155	KAL INV 081471669	Oom Jarussirirat	0.00

Work Order:	36608	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Blackfalds Shop	Business Unit:	Trucks Heavy
Created by:	Oom Jarussirirat	Start Date:	11-2-2022
Kms:	8990	Stop Date:	11-5-2022
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
JOSHUA BOTA	7.00	RT Shop Mech Blfds	\$52.07	\$364.49
STEPHEN DEWOLFE	6.00	RT Shop Mech Blfds	\$52.07	\$312.42
			Total Labor	\$676.91
AIR DRYER FILTER CARTRIDGE ADIS [5008414PG]	1.00	Each	\$128.04	\$128.04
FILTER AIR {P621725} [P637453]	1.00	Each	\$151.50	\$151.50
FILTER CAB AIR W/O COVER PB 567 & KW T880 {X1987001, CFR19012, SR2000092} [AF55839]	1.00	Each	\$20.63	\$20.63
FILTER FUEL SEPARATOR {P550849, FS19764} [FS19763]	1.00	Each	\$19.85	\$19.85
FILTER FUEL SPIN-ON {DBF6776,FF5971NN} [FF5825NN]	1.00	Each	\$50.89	\$50.89
FILTER LUBE SPIN-ON {DBL7900, LF14000NN} [LF14001NN]	1.00	Each	\$42.02	\$42.02
KAL TIRE LABOUR CHARGES [KALTIREL]	1.00	Each	\$322.40	\$322.40
PADDED WASHER [HWC05782]	2.00	Each	\$8.03	\$16.07
TIRE DRIVE - M775/BDY2/S758 [11R245DRIVE6]	8.00	Each	\$480.89	\$3,847.15
			Total Parts	\$4,598.55

Total Equip \$0.00

Total Cost \$5,275.46

Item ID	Description	Completed By	Reported Hours
67554	NEED A NEW FIRE EXTINGUISHER	Stephen DeWolfe	0.25
67555	NEED TO TOP UP HYD TANK	Stephen DeWolfe	0.25
65788	REPLACE AIR DRYER CARTRIDGE FILTER	Stephen DeWolfe	0.50
67557	WELD CRACKS AS NECESSARY	Joshua Bota	2.00
67556	COOLANT LEAKS ISSUE; LOWER RAD HOSE	Joshua Bota	0.50
64787	30k/400hr Service - All Filters Replaced Perform regular check list with the below fluids & filters will be replaced every A service.	Joshua Bota	8.75
67495	KAL INV 092472190	Joshua Bota	0.75

Work Order: 36676 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Fisher Pit **Business Unit:** Trucks Heavy
Created by: Darcy Hallock **Start Date:** 11-4-2022
Kms: 8990 **Stop Date:** 11-4-2022
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	1.75	RT Shop Tire Tech	\$36.33	\$63.58
			Total Labor	\$63.58
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$63.58

Item ID	Description	Completed By	Reported Hours
67651	9166- 11/04/2022 "RE-TORQUE"	Darcy Hallock	1.75

Work Order: 37011 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Blackfalds Shop **Business Unit:** Trucks Heavy
Created by: Oom Jarussirirat **Start Date:** 11-15-2022
Kms: 8990 **Stop Date:** 11-16-2022
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY PLATT	0.50	RT Shop Mech Blfds	\$52.07	\$26.04
			Total Labor	\$26.04
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$26.04

Item ID	Description	Completed By	Reported Hours
67855	INSTALL QR WHEEL RETORQ STICKER ON THE INSIDE DRIVER SIDE WINDOW BEHIND THE CURT DECAL	Oom Jarussirirat	0.00
68315	HEATER FAN HUMM ON HIGH	Darcy Platt	0.50

Work Order: 37315 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Blackfalds Shop **Business Unit:** Trucks Heavy
Created by: Oom Jarussirirat **Start Date:** 11-24-2022
Kms: 8990 **Stop Date:** 11-26-2022
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CLAYTON BERG	4.00	RT Shop Mech Blfds	\$52.07	\$208.28
JOSHUA BOTA	3.00	RT Shop Mech Blfds	\$52.07	\$156.21
			Total Labor	\$364.49
BRAKE DRUM 165X5 10HOLE[Custom]	2.00	Each	\$333.45	\$666.90
L/H TIE ROD END[Custom]	1.00	Each	\$43.44	\$43.44
R/H TIE ROD END[Custom]	1.00	Each	\$43.44	\$43.44
TIE ROD CLUB[Custom]	1.00	Each	(\$43.44)	(\$43.44)
TIE ROD END[Custom]	1.00	Each	(\$43.44)	(\$43.44)
TIEROD QWIKTIE GREEN CAP, TYPICAL FOR 12K AXLES ASSEMBLY [QT967SS]	1.00	Each	\$332.26	\$332.26
			Total Parts	\$999.16
			Total Equip	\$0.00
			Total Cost	\$1,363.65

Item ID	Description	Completed By	Reported Hours
68922	SHAKES IN THE FRONT ENDS, WHEN BRAKING	Clayton Berg	7.00

Work Order: 37985 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: **Business Unit:** Trucks Heavy

Created by: Oom Jarussirat
Kms: 8990
Hr: 9025

Start Date:
Stop Date:

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$0.00

Item ID	Description	Completed By	Reported Hours
70260	LAD RADIO ISSUE	Oom Jarussirat	0.00

Work Order: 38071 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Blackfalds Shop **Business Unit:** Trucks Heavy
Created by: Oom Jarussirat **Start Date:** 12-16-2022
Kms: 8990 **Stop Date:** 12-17-2022
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CLAYTON BERG	0.25	RT Shop Mech Blfds	\$52.07	\$13.02
			Total Labor	\$13.02
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$13.02

Item ID	Description	Completed By	Reported Hours
69864	INSTALL NEXT YEARS ASGA STICKER	Oom Jarussirat	0.25

Work Order: 38418 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 1-9-2023
Kms: 8990 **Stop Date:** 1-10-2023
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$0.00

Item ID	Description	Completed By	Reported Hours
71032	REPAIR LH HEADLIGHT	Blair MacAulay	0.00

Work Order: 38974 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Blackfalds Shop **Business Unit:** Trucks Heavy
Created by: Oom Jarussirat **Start Date:** 1-23-2023
Kms: 8990 **Stop Date:** 1-24-2023
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
WAYNE KIRK	0.50 RT	Shop Mech Blfds	\$52.07	\$26.04
			Total Labor	\$26.04
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$26.04

Item ID	Description	Completed By	Reported Hours
71853	LIGHTS ISSUE; CAB BACK UP LIGHT	Wayne Kirk	0.50

Work Order: 39240 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 1-31-2023
Kms: 8990 **Stop Date:** 2-1-2023
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
JEREMY KEDDY	0.50 RT	Shop Mech Rky	\$49.05	\$24.53
			Total Labor	\$24.53
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$24.53

Item ID	Description	Completed By	Reported Hours
72267	TROUBLESHOOT DE-RATE	Jeremy Keddy	0.50

Work Order: 39246
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Nick Depratto
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 1-31-2023
Stop Date: 2-6-2023

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
RD PB INV 68133 [Custom]	1.00	Each	\$1,889.54	\$1,889.54
			Total Parts	\$1,889.54
			Total Equip	\$0.00
			Total Cost	\$1,889.54

Item ID	Description	Completed By	Reported Hours
72287	CEL & DERATE	Blair MacAulay	0.00

Work Order: 39812
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Oom Jarussirirat
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 2-21-2023
Stop Date: 2-22-2023

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
WAYNE KIRK	2.50	RT Shop Mech Blfds	\$52.07	\$130.18
			Total Labor	\$130.18
HEATER [8608423]	1.00	Each	\$165.95	\$165.95
			Total Parts	\$165.95
			Total Equip	\$0.00
			Total Cost	\$296.13

Item ID	Description	Completed By	Reported Hours
73344	LIGHTS ISSUE	Wayne Kirk	1.00

73358	NEED A NEW ENG BLOCK HEATER CORD; MELTED	Wayne Kirk	1.50
-------	--	------------	------

Work Order: 40187
Equipment: TRACTOR TANDEM KW T880 [9166]

Status: Transferred
Serial Number: 1XKZD40X7LJ969605

Work Location: Rocky Mountain House Shop
Created by: Blair MacAulay
Kms: 8990
Hr: 9025

Business Unit: Trucks Heavy
Start Date: 3-6-2023
Stop Date: 3-7-2023

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CLAYTON OLSON	0.50	RT Shop Mech Rky	\$49.05	\$24.53
			Total Labor	\$24.53
GLADHAND SEAL CLOSE [FS312A]	4.00	Each	\$0.66	\$2.63
			Total Parts	\$2.63
			Total Equip	\$0.00
			Total Cost	\$27.15

Item ID	Description	Completed By	Reported Hours
74194	REPLACE GLAD HAND RUBBERS	Clayton Olson	0.25
74195	REPAIR LH HEADLIGHT	Clayton Olson	0.25

Work Order: 40219
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Rocky Mountain House Shop
Created by: Blair MacAulay
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 3-7-2023
Stop Date: 3-8-2023

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CLAYTON OLSON	0.50	RT Shop Mech Rky	\$49.05	\$24.53
			Total Labor	\$24.53
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$24.53

Item ID	Description	Completed By	Reported Hours
74272	REPAIR LH HEADLIGHT	Clayton Olson	0.50

Work Order: 41649
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Oom Jarussirirat
Kms: 8990

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 4-21-2023
Stop Date: 4-22-2023

Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
BERNIE SEEFRIED	1.00	RT Shop Mech Blfds	\$52.07	\$52.07
HUNTER BOTA	5.00	RT Shop Mech Blfds	\$52.07	\$260.35
JOSHUA BOTA	6.00	RT Shop Mech Blfds	\$52.07	\$312.42
			Total Labor	\$624.84
BRAKE CHAMBER - TYPE 3030LS, 3.00" STROKE [FLT3030LCB20]	1.00	Each	\$51.34	\$51.34
FILTER AIR {P621725} [P637453]	1.00	Each	\$110.19	\$110.19
FILTER CAB AIR W/O COVER PB 567 & KW T880 {X1987001, CFR19012, SR2000092} [AF55839]	1.00	Each	\$26.61	\$26.61
FILTER FUEL SEPARATOR {P550849, FS19764} [FS19763]	1.00	Each	\$25.13	\$25.13
FILTER FUEL SPIN-ON {DBF6776,FF5971NN} [FF5825NN]	1.00	Each	\$52.03	\$52.03
FILTER LUBE SPIN-ON {DBL7900, LF14000NN} [LF14001NN]	1.00	Each	\$42.73	\$42.73
SHOCK ABSORBER, HYD LOCKOUT UNIT, 15.17 IN. COMP LENGTH, 24.13 IN. EXT LENGTH, 8.95 IN. TRAV LENGTH [65504]	2.00	Each	\$90.60	\$181.20
			Total Parts	\$489.23
			Total Equip	\$0.00
			Total Cost	\$1,114.07

Item ID	Description	Completed By	Reported Hours
76912	NEED A NEW BRAKE POT ON #2 AXLE LH	Joshua Bota	1.00
76849	NEED A NEW WINDSHILED; DW 2038	Oom Jarussirirat	0.00
76909	LOOSE SHOCK ON #3 AXLE LH	Joshua Bota	3.00
76910	CRACKS RHR FENDER	Joshua Bota	1.00
73099	30K SERVICE - REPLACE ALL FILTERS	Joshua Bota	6.00
76913	NEED TO TOP UP HYD TANK	Joshua Bota	0.75
76911	NEED A NEW ANTI-SAIL BRACKET ON #2 AXLE LH	Joshua Bota	0.25

Work Order: 42149
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Oom Jarussirirat
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 5-8-2023
Stop Date: 5-10-2023

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
HUNTER BOTA	13.50	RT Shop Mech Blfds	\$52.07	\$702.95
JOSHUA BOTA	6.00	RT Shop Mech Blfds	\$52.07	\$312.42
			Total Labor	\$1,015.37
16.50X8.62 BRAKE DRUM [38BD07AB]	3.00	Each	\$306.01	\$918.03
FILTER HYDRAULIC SPIN-ON {P550387} [HF6720]	2.00	Each	\$24.97	\$49.94
SENSOR, PARTICULATE[Custom]	1.00	Each	(\$796.29)	(\$796.29)
			Total Parts	\$171.68
			Total Equip	\$0.00
			Total Cost	\$1,187.04

Item ID	Description	Completed By	Reported Hours
77318	CVIP INSPECTION	Joshua Bota	12.75
77320	REPLACE HYDRAULIC FILTER	Joshua Bota	0.00
77756	HYD LEAKS ISSUE	Joshua Bota	4.75
77778	REPLACE BRAKE DRUM AS NECESSARY	Joshua Bota	2.00

Work Order:	42829	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Blackfalds Shop	Business Unit:	Trucks Heavy
Created by:	Oom Jarussirirat	Start Date:	5-31-2023
Kms:	8990	Stop Date:	6-1-2023
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CLAYTON BERG	9.00	RT Shop Mech Blfds	\$52.07	\$468.63
			Total Labor	\$468.63
DFN PRESSURE SENSOR [5492073]	1.00	Each	\$179.09	\$179.09
			Total Parts	\$179.09
			Total Equip	\$0.00
			Total Cost	\$647.72

Item ID	Description	Completed By	Reported Hours
78945	CEL ISSUE; DERATED 3 HRS WARNING	Oom Jarussirirat	9.00

Work Order: 43676
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Oom Jarussirirat
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 6-26-2023
Stop Date: 6-28-2023

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
HUNTER BOTA	5.25 RT	Shop Mech Blfds	\$52.07	\$273.37
WAYNE KIRK	4.00 RT	Shop Mech Blfds	\$52.07	\$208.28
Total Labor				\$481.65
Total Parts				\$0.00
Total Equip				\$0.00
Total Cost				\$481.65

Item ID	Description	Completed By	Reported Hours
80379	LEAKING HYD TANK	Oom Jarussirirat	9.25

Work Order: 43789
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Oom Jarussirirat
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 6-29-2023
Stop Date: 6-30-2023

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DAMIAN MYERS	3.00 RT	Shop Mech Blfds	\$52.07	\$156.21
HUNTER BOTA	3.50 RT	Shop Mech Blfds	\$52.07	\$182.25
JOSHUA BOTA	2.50 RT	Shop Mech Blfds	\$52.07	\$130.18
Total Labor				\$468.63
Total Parts				\$0.00
Total Equip				\$0.00
Total Cost				\$468.63

Item ID	Description	Completed By	Reported Hours
80580	HYD LEAKS ISSUE	Joshua Bota	9.00

Work Order: 44474
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Oom Jarussirirat

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 7-20-2023

Kms: 8990
Hr: 9025

Stop Date: 7-22-2023

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CLAYTON BERG	2.75	RT Shop Mech Blfds	\$52.07	\$143.19
			Total Labor	\$143.19
FILTER AIR {PAC: SR2000092, X1987001, FLG: AF55839} [CFR19012]	1.00	Each	\$38.21	\$38.21
SCREW - WING M10X1.5X40MM [HWC09341]	2.00	Each	\$16.56	\$33.12
			Total Parts	\$71.33
			Total Equip	\$0.00
			Total Cost	\$214.52

Item ID	Description	Completed By	Reported Hours
81744	CHECK A/C; NOT WORKING	Clayton Berg	2.75

Work Order: 45349 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Blackfalds Shop **Business Unit:** Trucks Heavy
Created by: Oom Jarussirirat **Start Date:** 8-21-2023
Kms: 8990 **Stop Date:** 8-22-2023
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DAMIAN MYERS	15.00	RT Shop Mech Blfds	\$52.07	\$781.05
			Total Labor	\$781.05
1" QUICK COUPLER FEMALE [QDISOAC1616F]	1.00	Each	\$57.04	\$57.04
1" QUICK COUPLER NIPPLE [QDISOAN1616F]	2.00	Each	\$24.49	\$48.98
1" WING NUT COUPLER [QDBTTWC1616F]	1.00	Each	\$41.75	\$41.75
FILTER AIR {DON: P621725} [P637453]	1.00	Each	\$170.37	\$170.37
FILTER AIR {PAC: SR2000092, X1987001, FLG: AF55839} [CFR19012]	1.00	Each	\$38.45	\$38.45
FILTER FUEL SEPARATOR {P550849, FS19764} [FS19763]	1.00	Each	\$22.17	\$22.17
FILTER FUEL SPIN-ON {DBF6776,FF5971NN} [FF5825NN]	1.00	Each	\$136.80	\$136.80
FILTER LUBE SPIN-ON {DBL7900, LF14000NN} [LF14001NN]	1.00	Each	\$45.22	\$45.22
SUMMER TRUCK WIPER BLADE 22" - J-HOOK [WP22031]	1.00	Each	\$8.29	\$8.29
TRAXXROD [8240-0000-560]	1.00	Each	\$209.63	\$209.63
VENDOR BUILT HOSE [HOSE]	2.00	Each	\$275.29	\$550.58
			Total Parts	\$1,329.28
			Total Equip	\$0.00
			Total Cost	\$2,110.33

Item ID	Description	Completed By	Reported Hours
---------	-------------	--------------	----------------

81948 30K SERVICE & INSPECTION Oom Jarussirrat 0.00

83030 NEED A NEW TORQUE ROD; ON TOP OF #2 DIFF Damian Myers 1.00

83249 WINDSHILED WASHER SYSTEM FAULT Damian Myers 0.50

83246 NEED NEW HYD HOSES ON DECK Damian Myers 1.00

80319 30K SERVICE - REPLACE ALL FILTERS Damian Myers 4.00

83224 NEED NEW REAR FENDERS Damian Myers 7.50

83248 COOLANT LEAKS ISSUE Damian Myers 1.00

Work Order:	47750	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Blair MacAulay	Start Date:	10-27-2023
Kms:	8990	Stop Date:	11-1-2023
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
GWK INV SR2008555-1[Custom]	1.00	Each	\$1,187.20	\$1,187.20
			Total Parts	\$1,187.20
			Total Equip	\$0.00
			Total Cost	\$1,187.20

Item ID	Description	Completed By	Reported Hours
87924	CHECK TRANSMISSION CODES SR2008555-1	Nick Depratto	0.00

Work Order:	48085	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Blair MacAulay	Start Date:	11-7-2023
Kms:	8990	Stop Date:	11-8-2023
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
JEREMY KEDDY	0.50	RT Shop Mech Rky	\$49.05	\$24.53
			Total Labor	\$24.53
TRAILER LIGHT CORD 7 WAY 15', WITH WEATHER-TITE™ PERMAPLUGS [302070]	1.00	Each	\$143.74	\$143.74
			Total Parts	\$143.74

Total Equip \$0.00

Total Cost \$168.27

Item ID	Description	Completed By	Reported Hours
88524	REPAIR LH SIGNAL LIGHT	Jeremy Keddy	0.50

Work Order: 48469 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Blackfalds Shop **Business Unit:** Trucks Heavy
Created by: Oom Jarussirirat **Start Date:** 11-17-2023
Kms: 8990 **Stop Date:** 11-20-2023
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CLAYTON BERG	2.50	RT Shop Mech Blfds	\$52.07	\$130.18
JOSHUA BOTA	1.00	RT Shop Mech Blfds	\$52.07	\$52.07
			Total Labor	\$182.25
5" ALUM LAP CLAMP [33970]	1.00	Each	\$13.93	\$13.93
POGO STICK, 40", CHROME W/ TEC CLAMP [9800G2]	1.00	Each	\$57.35	\$57.35
VENDOR BUILT HOSE [HOSE]	1.00	Each	\$686.47	\$686.47
			Total Parts	\$757.75
			Total Equip	\$0.00
			Total Cost	\$940.00

Item ID	Description	Completed By	Reported Hours
86090	NEED A NEW POGO STICK	Oom Jarussirirat	1.00
89265	BROKEN RH TOP EXHAUST STACK BRACKET	Oom Jarussirirat	0.00
89266	BENT DPF FILTERS MOUNTING BRACKET; PUSHED UP 6"	Clayton Berg	1.00
89267	LIGHTS ISSUE; REAR LIGHT BAR TAIL LAMP CIRCUIT	Clayton Berg	1.50

Work Order: 48685 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 11-23-2023
Kms: 8990 **Stop Date:** 11-24-2023
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
-------------	----------	------------	------	-------

OLIVER TRAUTMANN	0.50 RT	Shop Mech Rky	\$49.05	\$24.53
			Total Labor	\$24.53
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$24.53

Item ID	Description	Completed By	Reported Hours
89613	REPAIR AIR LEAKS	Blair MacAulay	0.50

Work Order:	49674	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Blackfalds Shop	Business Unit:	Trucks Heavy
Created by:	Oom Jarussirrat	Start Date:	1-3-2024
Kms:	8990	Stop Date:	1-4-2024
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CLAYTON BERG	2.50	RT Shop Mech Blfds	\$52.07	\$130.18
DAMIAN MYERS	8.00	RT Shop Mech Blfds	\$52.07	\$416.56
HUNTER BOTA	2.00	RT Shop Mech Blfds	\$52.07	\$104.14
			Total Labor	\$650.88
BRAKE CHAMBER - TYPE 3030LS, 3.00" STROKE [FLT3030LCB20]	1.00	Each	\$47.31	\$47.31
EXHAUST PIPE BELLOWS {M741020001, M6670910320} [EBPB11861]	1.00	Each	\$370.16	\$370.16
FILTER AIR {DON: P621725} [P637453]	1.00	Each	\$133.94	\$133.94
FILTER AIR {PAC: CFR19012, X1987001, CF19013, FLG: AF55839, NAV: 4070948C1} [SR2000092]	1.00	Each	\$54.52	\$54.52
FILTER AIR DRYER - BENDIX ADIS {BEN: 5008415PG} [5008414PG]	1.00	Each	\$153.85	\$153.85
FILTER FUEL SEPARATOR {DON: P550849, FLG: FS19764} [FS19763]	1.00	Each	\$22.13	\$22.13
FILTER FUEL SPIN-ON {DON: DBF6776, FLG: FF5971NN} [FF5825NN]	1.00	Each	\$54.48	\$54.48
FILTER LUBE SPIN-ON {FLG: LF14000NN, DON: DBL7900} [LF14001NN]	1.00	Each	\$46.00	\$46.00
GASKET- EXHAUST CIRCULAR 4" [2866636CUM]	1.00	Each	\$21.63	\$21.63
			Total Parts	\$904.03
			Total Equip	\$0.00
			Total Cost	\$1,554.90

Item ID	Description	Completed By	Reported Hours
91300	NEED A NEW FIRE EXTINGUISHER	Clayton Berg	0.50
84620	REPLACE AIR DRYER CARTRIDGE FILTER	Clayton Berg	1.00
91302	LEAKING EXHAUST FLEX PIPE AFTER THE TURBO.	Oom Jarussirrat	2.00
91303	NEED A NEW BRAKE POT ON #2 AXLE LH	Damian Myers	2.00

91301	CORRODED STARTER WIRES AND WIRES INSIDE THE BATTERY BOX	Damian Myers	2.00
91247	30K SERVICE	Damian Myers	5.00

Work Order:	49699	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Blackfalds Shop	Business Unit:	Trucks Heavy
Created by:	Darcy Hallock	Start Date:	1-3-2024
Kms:	8990	Stop Date:	1-3-2024
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	3.25	RT Shop Tire Tech	\$36.33	\$118.07
			Total Labor	\$118.07
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$118.07

Item ID	Description	Completed By	Reported Hours
91271	9166- 01/03/2024 "REPLACE STEERS (X2)"	Darcy Hallock	3.25

Work Order:	50079	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Blackfalds Shop	Business Unit:	Trucks Heavy
Created by:	Oom Jarussirirat	Start Date:	1-17-2024
Kms:	8990	Stop Date:	1-18-2024
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
HUNTER BOTA	0.25	RT Shop Mech Blfds	\$52.07	\$13.02
			Total Labor	\$13.02
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$13.02

Item ID	Description	Completed By	Reported Hours
91919	TRUCK WON'T START	Oom Jarussirirat	0.25

Work Order:	51332	Status:	Transferred
--------------------	-------	----------------	-------------

Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Oom Jarussirirat
Kms: 8990
Hr: 9025

Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 2-21-2024
Stop Date: 2-22-2024

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
HUNTER BOTA	1.25	RT Shop Mech Blfds	\$52.07	\$65.09
			Total Labor	\$65.09
VALVE, DRAIN [5004961]	1.00	Each	\$36.61	\$36.61
			Total Parts	\$36.61
			Total Equip	\$0.00
			Total Cost	\$101.70

Item ID	Description	Completed By	Reported Hours
94024	AIR LEAKS ISSUE	Hunter Bota	1.25

Work Order: 51344
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Oom Jarussirirat
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 2-22-2024
Stop Date: 2-23-2024

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
HUNTER BOTA	0.25	RT Shop Mech Blfds	\$52.07	\$13.02
			Total Labor	\$13.02
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$13.02

Item ID	Description	Completed By	Reported Hours
94044	AIR LEAKS ISSUE	Hunter Bota	0.25

Work Order: 51496
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Trace Pidherney
Created by: Trace Pidherney
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date:
Stop Date:

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
PIDHERNEY MUD FLAP - 24 X 24 [PB2424]	4.00	Each	\$55.81	\$223.23
SUNVISOR CLIP, LIGHT GRAY [S161023661]	1.00	Each	\$28.22	\$28.22
			Total Parts	\$251.45
			Total Equip	\$0.00
			Total Cost	\$251.45

Item ID	Description	Completed By	Reported Hours
94280	9166 - 02/27/2024 - DIRECT BILL	Trace Pidherney	0.00

Work Order: 51984 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Blackfalds Shop **Business Unit:** Trucks Heavy
Created by: Oom Jarussirirat **Start Date:** 3-12-2024
Kms: 8990 **Stop Date:** 3-13-2024
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CLAYTON BERG	2.00	RT Shop Mech Blfds	\$52.07	\$104.14
			Total Labor	\$104.14
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$104.14

Item ID	Description	Completed By	Reported Hours
95509	TRAP ISSUE	Clayton Berg	2.00

Work Order: 52158 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Blackfalds Shop **Business Unit:** Trucks Heavy
Created by: Oom Jarussirirat **Start Date:** 3-18-2024
Kms: 8990 **Stop Date:** 3-19-2024
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
ERIC SCHADT	1.00	RT Shop Mech Blfds	\$52.07	\$52.07
			Total Labor	\$52.07
12VOLT POWER OUTLET [10011018]	2.00	Each	\$6.53	\$13.06
TIRE DRIVE [11R245BDY2]	8.00	Each	\$516.33	\$4,130.64

WHEEL SPACER BETWEEN RIMS [A5903]	1.00 Each	\$2.91	\$2.91
		Total Parts	\$4,146.61
		Total Equip	\$0.00
		Total Cost	\$4,198.68

Item ID	Description	Completed By	Reported Hours
93403	QR CODE UPDATE	Oom Jarussirat	0.00
94745	INSTALL 2024 ASGA STICKERS	Oom Jarussirat	0.00
94895	INSTALL 2024 ASGA STICKERS	Oom Jarussirat	0.00
93524	QR CODE UPDATE	Eric Schadt	0.25
95808	12V SOCKETS ARE NOT WOKRING; BY COFFEE CUP HOLDER AND BUNK	Eric Schadt	0.50
95811	NEED TO TOP UP HYD TANK; HALF WAY UP THE SITE GLASS	Eric Schadt	0.25
95814	KAL INV 092495997 - NEEDS ALL NEW DRIVE TIRES; BDY2 11R24.5	Oom Jarussirat	0.00
91281	NEED A NEW WINDSHIELD; DW2038	Oom Jarussirat	0.00

Work Order:	52378	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Blackfalds Shop	Business Unit:	Trucks Heavy
Created by:	Oom Jarussirat	Start Date:	3-22-2024
Kms:	8990	Stop Date:	3-23-2024
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DAMIAN MYERS	1.25	RT Shop Mech Blfds	\$52.07	\$65.09
			Total Labor	\$65.09
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$65.09

Item ID	Description	Completed By	Reported Hours
96178	LIGHTS ISSUE; NO TAIL LIGHTS	Damian Myers	1.25

Work Order:	52868	Status:	Transferred
--------------------	-------	----------------	-------------

Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Oom Jarussirirat
Kms: 8990
Hr: 9025

Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 4-8-2024
Stop Date: 4-10-2024

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
WAYNE KIRK	2.00	RT Shop Mech Blfds	\$52.07	\$104.14
			Total Labor	\$104.14
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$104.14

Item ID	Description	Completed By	Reported Hours
97091	BROKEN RHR FENDER MOUTING BRACKET	Wayne Kirk	2.00

Work Order: 53105
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Oom Jarussirirat
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 4-15-2024
Stop Date: 4-17-2024

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DAMIAN MYERS	14.75	RT Shop Mech Blfds	\$52.07	\$768.03
DARCY PLATT	12.25	RT Shop Mech Blfds	\$52.07	\$637.86
			Total Labor	\$1,405.89
16.5 X 8.625, Q DUST SHIELD [K1T12109]	1.00	Each	\$86.14	\$86.14
CAGE BOLT {BH800921} [FS5620LS]	1.00	Each	\$3.72	\$3.72
CLAMP- V BAND 4" [900012]	1.00	Each	\$16.46	\$16.46
FAN DRIVE BELT 12RIBS X 2180mm {FLTBT858K12, 858K12BLT} [D8410006122180]	1.00	Each	\$118.47	\$118.47
FILTER AIR {CF19013, X1987001, FLG: AF55839, NAV: 4070948C1} [SR2000092]	1.00	Each	\$55.27	\$55.27
FILTER AIR {DON: P621725} [P637453]	1.00	Each	\$169.15	\$169.15
FILTER FUEL SEPARATOR {DON: P550849, FLG: FS19764} [FS19763]	1.00	Each	\$21.72	\$21.72
FILTER FUEL SPIN-ON {DON: DBF6776, FLG: FF5971NN} [FF5825NN]	1.00	Each	\$54.11	\$54.11
FILTER LUBE SPIN-ON {FLG: LF14000NN, DON: DBL7900} [LF14001NN]	1.00	Each	\$50.92	\$50.92
GASKET- EXHAUST CIRCULAR 4" [2866636CUM]	1.00	Each	\$21.63	\$21.63
HOSE DEF [M5060394413150]	1.00	Each	\$628.78	\$628.78
LEVELING VALVE - DUMP PORT AIR UP, NO AIR DOWN {VS228} [KD2429]	1.00	Each	\$216.57	\$216.57
PAR36 LED AUX/WORK LAMP [LED410019WP]	1.00	Each	\$25.20	\$25.20
POT PLUG {K034202} [TK90090]	1.00	Each	\$3.21	\$3.21

SIGNAL STAT {TRP: TL80030} [P276221]	1.00 Each	\$182.48	\$182.48
		Total Parts	\$1,653.83
		Total Equip	\$0.00
		Total Cost	\$3,059.72

Item ID	Description	Completed By	Reported Hours
97541	BROKEN DUST COVERS ON #3 AXLE LH	Darcy Platt	0.50
97546	NEEDS NEW ENG FAN AND A/C BELTS	Darcy Platt	0.50
97544	EXHAUST LEAKS ISSUE; OFF TURBO	Darcy Platt	0.50
97543	MISSING CAGIN BOLTS AND DUST PLUGS; ON BRAKE POTS	Darcy Platt	0.25
97545	LIGHTS ISSUE; RH REVERSE LIGHT	Damian Myers	1.00
97258	30K SERVICE	Darcy Platt	7.25
97540	CEL ISSUE; DEF LINE HEATER	Damian Myers	6.75
97539	LOOSE SIGNAL STAT; IN THE STEERING COLUMN	Damian Myers	1.00
97542	LH AIR BAG NOT INFLATING; CHECK RIDE HEIGHT 10"	Damian Myers	8.75
97492	TYDY UP ELD CODE; ON DASH	Damian Myers	0.50
97525	NEED A NEW WINDSHIELD; DW 2038	Oom Jarussirirat	0.00

Work Order:	53898	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Blackfalds Shop	Business Unit:	Trucks Heavy
Created by:	Oom Jarussirirat	Start Date:	5-9-2024
Kms:	8990	Stop Date:	5-14-2024
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
BRENT TURNEY	0.50	RT Shop Weld Rky	\$47.83	\$23.92
CLAYTON BERG	12.00	RT Shop Mech Blfds	\$52.07	\$624.84

			Total Labor	\$648.76
BRAKE CHAMBER - TYPE 3030LS, 3.00" STROKE [FLT3030LCB20]	1.00 Each		\$51.91	\$51.91
FILTER HYDRAULIC SPIN-ON {DON: P550387} [HF6720]	2.00 Each		\$19.11	\$38.23
GLADHAND STRAIGHT MOUNT BLUE [12006]	1.00 Each		\$5.98	\$5.98
GLADHAND STRAIGHT MOUNT RED [12008]	1.00 Each		\$5.35	\$5.35
STRUT-ASSIST, LOCKING HOOD [L711017]	1.00 Each		\$600.98	\$600.98
			Total Parts	\$702.44
			Total Equip	\$0.00
			Total Cost	\$1,351.19

Item ID	Description	Completed By	Reported Hours
98927	NEED A NEW HOOD SHOCK; WITH RED LOCKING TAB	Clayton Berg	0.50
99034	NEED NEW GLAD HANDS	Clayton Berg	0.50
97604	BF SOB - DUST COVER	Clayton Berg	1.00
99032	REPLACE GREASE NIPPLE AS NECESSARY	Clayton Berg	0.25
98540	CVIP INSPECTION - CV 7843389	Clayton Berg	7.50
99030	LIGHTS ISSUE	Clayton Berg	0.50
99029	NEED A NEW FIRE EXTINGUISHER	Clayton Berg	0.25
98543	REPLACE HYDRAULIC FILTER	Clayton Berg	0.50
99031	NEED A NEW BRAKE POT ON #3 AXLE RH	Oom Jarussirirat	1.00
99033	CRACKS ON LHR FENDER	Brent Turney	0.50

Work Order:	54040	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Fisher Pit	Business Unit:	Trucks Heavy
Created by:	Darcy Hallock	Start Date:	5-13-2024
Kms:	8990	Stop Date:	5-13-2024
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	1.75	RT Shop Tire Tech	\$36.33	\$63.58
			Total Labor	\$63.58
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$63.58

Item ID	Description	Completed By	Reported Hours
99153	9166- 05/13/2024 "RE-TORQUE"	Darcy Hallock	1.75

Work Order: 54601 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Blackfalds Shop **Business Unit:** Trucks Heavy
Created by: Oom Jarussirirat **Start Date:** 6-3-2024
Kms: 8990 **Stop Date:** 6-4-2024
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
WAYNE KIRK	0.50	RT Shop Mech Blfds	\$52.07	\$26.04
			Total Labor	\$26.04
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$26.04

Item ID	Description	Completed By	Reported Hours
100133	LIGHTS ISSUE	Wayne Kirk	0.50

Work Order: 54615 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: **Business Unit:** Trucks Heavy
Created by: Travis Young **Start Date:**
Kms: 8990 **Stop Date:**
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
TRAILER LIGHT CORD 7 WAY 15', WITH WEATHER-TITE™ PERMAPLUGS [302070]	1.00	Each	\$148.54	\$148.54
			Total Parts	\$148.54
			Total Equip	\$0.00
			Total Cost	\$148.54

Item ID	Description	Completed By	Reported Hours
100149	9166 - 03-06-24 - DIRECT BILL	Jeremy Detema	0.00

Work Order: 55821
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Rocky Mountain House Shop
Created by: Blair MacAulay
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 7-8-2024
Stop Date: 7-9-2024

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
KIRBY BERGEN	1.00	RT Shop Mech Rky	\$49.05	\$49.05
			Total Labor	\$49.05
BLOWER MOTOR ASSY {CR705002} [CR705003]	1.00	Each	\$552.20	\$552.20
FILTER AIR {CF19013, X1987001, FLG: AF55839, NAV: 4070948C1} [SR2000092]	1.00	Each	\$57.10	\$57.10
			Total Parts	\$609.30
			Total Equip	\$0.00
			Total Cost	\$658.35

Item ID	Description	Completed By	Reported Hours
102168	REPAIR A/C	Blair MacAulay	0.00
102172	REPLACE CAB FAN AND FILTER	Blair MacAulay	1.00

Work Order: 56028
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Oom Jarussirirat
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 7-15-2024
Stop Date: 7-16-2024

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
BRENT TURNEY	3.00	RT Shop Weld Rky	\$47.83	\$143.49
JOSHUA BOTA	10.00	RT Shop Mech Blfds	\$52.07	\$520.70
			Total Labor	\$664.19
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$664.19

Item ID	Description	Completed By	Reported Hours
102521	AIR LEAKS ISSUE	Joshua Bota	2.50
102522	CHECK FRON ENDS; SHIMMY	Joshua Bota	3.00

102520 CRACK LHR FENDER MOUNTING BRACKET Joshua Bota 4.50

101036 LOOSE STORAGE BOX ON PS Joshua Bota 3.00

Work Order: 56659 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Blackfalds Shop **Business Unit:** Trucks Heavy
Created by: Nick Depratto **Start Date:** 8-2-2024
Kms: 8990 **Stop Date:** 8-2-2024
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DAMIAN MYERS	2.00	RT Shop Mech Blfds	\$52.07	\$104.14
			Total Labor	\$104.14
FILTER DEF {CUM: 4388378, PAC: 2122909PE} [UF106]	1.00	Each	\$115.00	\$115.00
			Total Parts	\$115.00
			Total Equip	\$0.00
			Total Cost	\$219.14

Item ID **Description** **Completed By** **Reported Hours**

103711 REPAIR CAUSE OF FAN ON ALL THE TIME AND AC NOT WORKING CORRECTLY Damian Myers 1.50

100883 DEF PUMP FILTER REPLACEMENT Damian Myers 0.50

Work Order: 57056 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Blackfalds Shop **Business Unit:** Trucks Heavy
Created by: Oom Jarussirrat **Start Date:** 8-14-2024
Kms: 8990 **Stop Date:** 8-16-2024
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY PLATT	3.00	RT Shop Mech Blfds	\$52.07	\$156.21
			Total Labor	\$156.21
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$156.21

Item ID **Description** **Completed By** **Reported Hours**

104309	FUEL ISSUE; ON SUCKING OUT OF RH TANK	Darcy Platt	3.00
--------	---------------------------------------	-------------	------

Work Order:	57159	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Blackfalds Shop	Business Unit:	Trucks Heavy
Created by:	Oom Jarussirirat	Start Date:	8-20-2024
Kms:	8990	Stop Date:	8-21-2024
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
BRENT TURNEY	4.00	RT Shop Weld Rky	\$47.83	\$191.32
WAYNE KIRK	14.50	RT Shop Mech Blfds	\$52.07	\$755.02
			Total Labor	\$946.34
BUSHING - SPRING PIN {AUTOMANN: MTB186} [B131002]	4.00	Each	\$36.39	\$145.57
FILTER AIR {CF19013, X1987001, FLG: AF55839, NAV: 4070948C1} [SR2000092]	1.00	Each	\$55.71	\$55.71
FILTER AIR {DON: P621725} [P637453]	1.00	Each	\$123.35	\$123.35
FILTER FUEL SEPARATOR {DON: P550849, FLG: FS19764} [FS19763]	1.00	Each	\$21.63	\$21.63
FILTER FUEL SPIN-ON {DON: DBF6776, FLG: FF5971NN} [FF5825NN]	1.00	Each	\$55.57	\$55.57
FILTER LUBE SPIN-ON {FLG: LF14000NN, DON: DBL7900} [LF14001NN]	1.00	Each	\$48.61	\$48.61
PIN - SPRING {KW: B656008} [M5447]	4.00	Each	\$24.00	\$96.01
			Total Parts	\$546.44
			Total Equip	\$0.00
			Total Cost	\$1,492.78

Item ID	Description	Completed By	Reported Hours
104266	30K SERVICE	Wayne Kirk	2.50
104591	AIR LEAKS ISSUE; BY THE AIR DRYER	Wayne Kirk	1.50
104590	NEED A NEW FIRE EXTINGUISHER	Wayne Kirk	0.25
104592	LIGHTS ISSUE	Wayne Kirk	0.25
102536	NEED NEW REAR SPRING PINS/BUSHINGS ON BOTH SIDES (UPPER AND LOWER	Wayne Kirk	14.00

Work Order:	57287	Status:	Transferred
--------------------	-------	----------------	-------------

Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Fisher Pit
Created by: Darcy Hallock
Kms: 8990
Hr: 9025

Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 8-21-2024
Stop Date: 8-21-2024

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	0.75	RT Shop Tire Tech	\$36.33	\$27.25
Total Labor				\$27.25
Total Parts				\$0.00
Total Equip				\$0.00
Total Cost				\$27.25

Item ID	Description	Completed By	Reported Hours
104753	9166- 08/21/2024 "RE-TORQUE"	Darcy Hallock	0.75

Work Order: 57302
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Oom Jarussirirat
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 8-21-2024
Stop Date: 8-22-2024

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
JOSHUA BOTA	1.50	RT Shop Mech Blfds	\$52.07	\$78.11
Total Labor				\$78.11
A/C SECONDARY BELT - SERPENTINE - RIBS: 6 - EFFECTIVE LENGTH (IN): 64.0 {638K6BLT, 640K6BLT} [D8410006061620]	1.00	Each	\$43.03	\$43.03
FAN DRIVE BELT 12RIBS X 2180mm {FLTBT858K12, 858K12BLT} [D8410006122180]	1.00	Each	\$94.13	\$94.13
TENSIONER [3691282]	1.00	Each	\$585.49	\$585.49
Total Parts				\$722.64
Total Equip				\$0.00
Total Cost				\$800.75

Item ID	Description	Completed By	Reported Hours
104777	SEIZED FAN BELT TENSIONER BEARING	Joshua Bota	1.50

Work Order: 57475
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Oom Jarussirirat
Kms: 8990

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 8-27-2024
Stop Date: 8-28-2024

Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CLAYTON BERG	5.00	RT Shop Mech Blfds	\$52.07	\$260.35
			Total Labor	\$260.35
A/C SECONDARY BELT - SERPENTINE - RIBS: 6 - EFFECTIVE LENGTH (IN): 64.0 {638K6BLT, 640K6BLT} [D8410006061620]	1.00	Each	\$24.29	\$24.29
COMPRESSOR - SHD A/C SLIMLINE [LF4106]	1.00	Each	\$298.15	\$298.15
CORE ITEM - SENSOR NITROGEN OXIDE NOX CUMMINS (REMAN) [3687930RX]	1.00	Each	\$966.74	\$966.74
CORE ITEM - SENSOR NITROGEN OXIDE[Custom]	1.00	Each	(\$187.00)	(\$187.00)
CUMMINS INTAKE NOX SENSOR CONNECTOR {CUM: 6384924} [5394263]	1.00	Each	\$69.96	\$69.96
HOSE [1673866C2]	1.00	Each	\$101.41	\$101.41
SENSOR, TEMPERATURE EGR [5461596]	1.00	Each	\$222.55	\$222.55
WASHER PUMP W/GROMMET {PAC: 600208S, T4695001, WB6035402PUMP AUTO: HLK7046} [WB6035402PUMP]	1.00	Each	\$18.31	\$18.31
			Total Parts	\$1,514.41
			Total Equip	\$0.00
			Total Cost	\$1,774.76

Item ID	Description	Completed By	Reported Hours
105109	WINDSHIELD WASHER FLUID LEAKING	Clayton Berg	0.50
105108	CEL ISSUE	Clayton Berg	2.00
105061	A/C IS NOT WORKING	Clayton Berg	2.50

Work Order: 57648 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Blackfalds Yard **Business Unit:** Trucks Heavy
Created by: Bernie Seefried **Start Date:** 8-29-2024
Kms: 8990 **Stop Date:** 8-29-2024
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
BERNIE SEEFRIED	1.50	RT Shop Mech Blfds	\$52.07	\$78.11
			Total Labor	\$78.11
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$78.11

Item ID	Description	Completed By	Reported Hours
105366	INSTALL NEW GPS SYSTEM	Bernie Seefried	1.50

Work Order:	58150	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Blackfalds Shop	Business Unit:	Trucks Heavy
Created by:	Oom Jarussirirat	Start Date:	9-12-2024
Kms:	8990	Stop Date:	9-13-2024
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DUSTIN BOON	2.00	RT Shop Tire Tech	\$36.33	\$72.66
			Total Labor	\$72.66
TIRE STEER [31580R225FS821]	2.00	Each	\$831.06	\$1,662.13
			Total Parts	\$1,662.13
			Total Equip	\$0.00
			Total Cost	\$1,734.79

Item ID	Description	Completed By	Reported Hours
106430	NEED NEW STEER TIRES; CHUNK MISSING DOWN TO CORD	Dustin Boon	2.00

Work Order:	59132	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Blackfalds Shop	Business Unit:	Trucks Heavy
Created by:	Oom Jarussirirat	Start Date:	10-4-2024
Kms:	8990	Stop Date:	10-5-2024
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DAMIAN MYERS	1.00	RT Shop Mech Blfds	\$52.07	\$52.07
			Total Labor	\$52.07
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$52.07

Item ID	Description	Completed By	Reported Hours
108181	PERFORM ULTRASHIFT TRANS GREASE PROCEDURE	Damian Myers	1.00

Work Order:	59932	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605

Work Location: Blackfalds Shop
Created by: Oom Jarussirirat
Kms: 8990
Hr: 9025

Business Unit: Trucks Heavy
Start Date: 10-24-2024
Stop Date: 10-25-2024

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
JOSHUA BOTA	2.50	RT Shop Mech Blfds	\$52.07	\$130.18
			Total Labor	\$130.18
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$130.18

Item ID	Description	Completed By	Reported Hours
109581	LIGHTS ISSUE; TRL CIRCUIT KEEP BLOWING FUESES.	Joshua Bota	2.50

Work Order: 60250
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Oom Jarussirirat
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 10-31-2024
Stop Date: 11-1-2024

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$0.00

Item ID	Description	Completed By	Reported Hours
110122	CHUNK MISSING OFF TIRES; DOWN TO CORE	Dustin Boon	0.00

Work Order: 60259
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: CP1603 - 50th Ave. Redevelopment Ph. 3 - UG
Created by: Dustin Boon
Kms: 8990
Hr: 9025

Status: Transferred
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 10-31-2024
Stop Date: 10-31-2024

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DUSTIN BOON	4.00	RT Shop Tire Tech	\$36.33	\$145.32

Total Labor	\$145.32
Total Parts	\$0.00
Total Equip	\$0.00
Total Cost	\$145.32

Item ID	Description	Completed By	Reported Hours
110146	9166 - needs a runout on the RHI	Dustin Boon	4.00

Work Order: 60303 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Fisher Pit **Business Unit:** Trucks Heavy
Created by: Darcy Hallock **Start Date:** 11-1-2024
Kms: 8990 **Stop Date:** 11-1-2024
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	0.75	RT Shop Tire Tech	\$36.33	\$27.25
			Total Labor	\$27.25
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$27.25

Item ID	Description	Completed By	Reported Hours
110265	9166- 11/01/2024 "RE-TORQUE"	Darcy Hallock	0.75

Work Order: 60819 **Status:** Transferred
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Blackfalds Yard **Business Unit:** Trucks Heavy
Created by: Darcy Hallock **Start Date:** 11-13-2024
Kms: 8990 **Stop Date:** 11-13-2024
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	3.00	RT Shop Tire Tech	\$36.33	\$108.99
			Total Labor	\$108.99
TIRE {M775, BDY2, FST835} [11R245DRIVE]	8.00	Each	\$408.91	\$3,271.32
			Total Parts	\$3,271.32
			Total Equip	\$0.00
			Total Cost	\$3,380.31

Item ID	Description	Completed By	Reported Hours
111097	9166- 11/13/2024 "REPLACE DRIVES (X8)"	Darcy Hallock	3.00

Work Order:	61435	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Blackfalds Shop	Business Unit:	Trucks Heavy
Created by:	Oom Jarussirirat	Start Date:	12-4-2024
Kms:	8990	Stop Date:	12-6-2024
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY PLATT	4.00	RT Shop Mech Blfds	\$52.07	\$208.28
JOSHUA BOTA	14.50	RT Shop Mech Blfds	\$52.07	\$755.02
KENT WOOLSEY	1.50	RT Shop Mech Blfds	\$52.07	\$78.11
		Total Labor		\$1,041.40
BEARING STRAP RETAINER KIT [2507018X]	2.00	Each	\$19.79	\$39.57
CLAMP - V BAND [5304600CUM]	1.00	Each	\$92.18	\$92.18
CLARITY INV 1724361[Custom]	1.00	Each	\$429.40	\$429.40
EXH GASKET [2880215]	1.00	Each	\$26.01	\$26.01
FILTER AIR {CF19013, X1987001, FLG: AF55839, NAV: 4070948C1} [SR2000092]	1.00	Each	\$57.75	\$57.75
FILTER AIR {DON: P621725} [P637453]	1.00	Each	\$112.45	\$112.45
FILTER AIR DRYER - BENDIX ADIS {BEN: 5008415PG} [5008414PG]	1.00	Each	\$179.46	\$179.46
FILTER FUEL SEPARATOR {DON: P550849, FLG: FS19764} [FS19763]	1.00	Each	\$22.32	\$22.32
FILTER FUEL SPIN-ON {DON: DBF6776, FLG: FF5971NN} [FF5825NN]	1.00	Each	\$56.00	\$56.00
FILTER LUBE SPIN-ON {FLG: LF14000NN, DON: DBL7900} [LF14001NN]	1.00	Each	\$52.03	\$52.03
FILTER POWER STEERING {DON: P550830, 3937557S} [87904M]	1.00	Each	\$28.25	\$28.25
GASKET - AFM DEVICE/DPF {CUM: 5304868, PAC: 2188190PE} [5417859]	2.00	Each	\$87.86	\$175.72
RD PB INV 71012[Custom]	1.00	Each	\$366.95	\$366.95
RD PB INV[Custom]	1.00	Each	\$366.95	\$366.95
U JOINT [SPL2503X]	1.00	Each	\$199.58	\$199.58
V BAND, CLAMP [5304849]	2.00	Each	\$126.37	\$252.74
		Total Parts		\$2,457.37
		Total Equip		\$0.00
		Total Cost		\$3,498.77

Item ID	Description	Completed By	Reported Hours
112629	NEED TO TOP UP HYD TANK (HALF WAY UP THE SITE GLASS)	Joshua Bota	0.50
112333	CHECK ENG BLOCK HEATER	Joshua Bota	0.50
112332	REPLACE POWER STEERING FILTER (WAIT UNTIL NEXT SERVICE OR CVIP)	Joshua Bota	0.50

112630	NEED A NEW U-JOINT ON #1 DIFF INPUT	Joshua Bota	1.00
106221	REPLACE AIR DRYER CARTRIDGE FILTER	Joshua Bota	2.00
112334	FILL ALCOHOL EVAP CANISTOR	Joshua Bota	0.50
112545	CLARITY INV 1724361 - NEED A NEW WINDSHIED; DW 2038	Oom Jarussirirat	0.00
111339	30K SERVICE	Oom Jarussirirat	3.00
112631	NEED 5TH WHEEL ADJUSTMENT	Oom Jarussirirat	1.00
112580	BENT DRIVER'S STEPS	Oom Jarussirirat	0.00
112647	CEL ISSUE; DPF ASH LOAD FAULT	Darcy Platt	9.50
112628	LHR FENDER CRACKED	Kent Woolsey	1.50

Work Order:	61752	Status:	Transferred
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Blackfalds Shop	Business Unit:	Trucks Heavy
Created by:	Dustin Boon	Start Date:	12-9-2024
Kms:	8990	Stop Date:	12-9-2024
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DUSTIN BOON	0.50	RT Shop Tire Tech	\$36.33	\$18.17
			Total Labor	\$18.17
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$18.17

Item ID	Description	Completed By	Reported Hours
113155	9166 - flat on LHI #2 axle	Dustin Boon	0.50

Work Order:	62416	Status:	Closed
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:		Business Unit:	Trucks Heavy
Created by:	Oom Jarussirirat	Start Date:	
Kms:	8990	Stop Date:	
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
TIRE {M775, BDY2, FST835} [11R245DRIVE]	1.00	Each	\$510.54	\$510.54
			Total Parts	\$510.54
			Total Equip	\$0.00
			Total Cost	\$510.54

Item ID	Description	Completed By	Reported Hours
114238	FLAT TIRE ON REAR AXLE PS INNER	Oom Jarussirirat	0.00

Work Order:	66537	Status:	Closed
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Blair MacAulay	Start Date:	4-29-2025
Kms:	8990	Stop Date:	5-9-2025
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
BLAINE STEFFAN	1.00	RT Shop Mech Rky	\$49.05	\$49.05
DARCY HALLOCK	0.25	RT Shop Tire Tech	\$36.33	\$9.08
KEVIN HUMMEL	23.00	RT Shop Mech Rky	\$49.05	\$1,128.15
MAXWELL KRABBen	1.00	RT Shop Mech Rky	\$49.05	\$49.05
PHOENIX GRAHAM	21.50	RT Shop Mech Rky	\$49.05	\$1,054.58
			Total Labor	\$2,289.91
1" QUICK COUPLER NIPPLE [66021616]	1.00	Each	\$49.43	\$49.43
5TH WHEEL BRACKET PINS AND BUSHINGS FOR ILS - KIT - HOLLAND FW35 [RK10605]	1.00	Each	\$79.44	\$79.44
AIR BAG **SEE ATACHMENT** {67043002} [W013589865]	2.00	Each	\$230.57	\$461.14
AIR BAG **SEE ATACHMENT** {67043002} [W013589865]	2.00	Each	\$226.67	\$453.34
MNPT- CRIMP [101431616]	1.00	Each	\$31.47	\$31.47
MNPT- CRIMP [101431616]	3.00	Each	\$32.31	\$96.94
PEAK INV 12473[Custom]	1.00	Each	\$450.00	\$450.00
			Total Parts	\$1,621.77
			Total Equip	\$0.00
			Total Cost	\$3,911.67

Item ID	Description	Completed By	Reported Hours
121696	CVIP INSPECTION CV8131085	Blair MacAulay	25.00
121898	REPLACE FIRE EXTINGUISHER	Blair MacAulay	0.25
121895	REPLACE AIR BAGS	Blair MacAulay	6.00

121894	REPAIR LEAK AT PTO FLANGE	Blair MacAulay	5.25
121896	REPLACE 5TH WHEEL PINS AND BUSHINGS	Blair MacAulay	2.00
121695	PERFORM VALVE SET	Blair MacAulay	2.00
121697	PEAK INV 12473 - REPLACE WINDSHIELD	Blair MacAulay	0.00
121897	REPLACE HYDRAULIC HOSES	Blair MacAulay	6.00
121804	9166- 04/29/2025 "B-STONE/UPDATE FOR CVIP"	Darcy Hallock	0.25

Work Order: 67740 **Status:** Closed
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 5-28-2025
Kms: 8990 **Stop Date:** 5-29-2025
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
OLIVER TRAUTMANN	1.50	RT Shop Mech Rky	\$49.05	\$73.58
			Total Labor	\$73.58
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$73.58

Item ID	Description	Completed By	Reported Hours
123782	REPAIR RH INNER FENDER HEAD LIGHT COVER	Blair MacAulay	1.50

Work Order: 67790 **Status:** Closed
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: MAIN YARD **Business Unit:** Trucks Heavy
Created by: Darcy Hallock **Start Date:** 5-29-2025
Kms: 8990 **Stop Date:** 5-29-2025
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	0.25	RT Shop Tire Tech	\$36.33	\$9.08
			Total Labor	\$9.08
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$9.08

Item ID	Description	Completed By	Reported Hours
123886	9166- 05/29/2025 "B-STONE TIRE CHECK"	Darcy Hallock	0.25

Work Order:	68018	Status:	Closed
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Blair MacAulay	Start Date:	6-3-2025
Kms:	8990	Stop Date:	6-4-2025
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
MICHAEL GATES	4.50	RT Shop Mech Rky	\$49.05	\$220.73
			Total Labor	\$220.73
FILTER AIR {CF19013, X1987001, FLG: AF55839, NAV: 4070948C1} [SR2000092]	1.00	Each	\$56.25	\$56.25
FILTER CAB AIR W/BLACK COVER PB367 [CF19013]	1.00	Each	\$34.27	\$34.27
			Total Parts	\$90.52
			Total Equip	\$0.00
			Total Cost	\$311.25

Item ID	Description	Completed By	Reported Hours
124312	REPAIR AIR LEAKS	Blair MacAulay	1.00
124310	FUNCTION TEST A/C AND CAB FAN	Blair MacAulay	2.50
124311	CLEAN OIL UNDER BUNK	Blair MacAulay	1.00

Work Order:	68287	Status:	Closed
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	MAIN YARD	Business Unit:	Trucks Heavy
Created by:	Darcy Hallock	Start Date:	6-6-2025
Kms:	8990	Stop Date:	6-6-2025
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	0.25	RT Shop Tire Tech	\$36.33	\$9.08
			Total Labor	\$9.08
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$9.08

Item ID	Description	Completed By	Reported Hours
---------	-------------	--------------	----------------

124742 9166- 06/06/2025 "TIRE CHECK" Darcy Hallock 0.25

Work Order: 68314 **Status:** Closed
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 6-9-2025
Kms: 8990 **Stop Date:** 6-10-2025
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
MICHAEL GATES	1.00	RT Shop Mech Rky	\$49.05	\$49.05
			Total Labor	\$49.05
TRAILER LIGHT CORD TARP 15' 2 POLE VERTICAL [212272]	1.00	Each	\$199.24	\$199.24
			Total Parts	\$199.24
			Total Equip	\$0.00
			Total Cost	\$248.29

Item ID	Description	Completed By	Reported Hours
124793	REPAIR TARP CONTROL	Mike Gates	1.00

Work Order: 68382 **Status:** Closed
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 6-10-2025
Kms: 8990 **Stop Date:** 6-11-2025
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
OLIVER TRAUTMANN	3.25	RT Shop Mech Rky	\$49.05	\$159.41
			Total Labor	\$159.41
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$159.41

Item ID	Description	Completed By	Reported Hours
124902	CLEAN CONTAMINATED DEF TANK	Blair MacAulay	3.25

Work Order: 68430 **Status:** Closed

Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location:
Created by: Nick Depratto
Kms: 8990
Hr: 9025

Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date:
Stop Date:

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$0.00

Item ID	Description	Completed By	Reported Hours
124697	PROGRAM VECU & TRANSMISSION WITH PROPER PARAMETERS	Nick Depratto	0.00

Work Order: 68930
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: ROCKY VIEW COUNTY 2025 GRAVEL PROGRAM
Created by: Bernie Seefried
Kms: 8990
Hr: 9025

Status: Closed
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 6-18-2025
Stop Date: 6-18-2025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
BERNIE SEEFRIED	0.75	RT Shop Mech Blfds	\$52.07	\$39.05
			Total Labor	\$39.05
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$39.05

Item ID	Description	Completed By	Reported Hours
125671	OVERHEATING	Bernie Seefried	0.75

Work Order: 69532
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Rocky Mountain House Shop
Created by: Blair MacAulay
Kms: 8990
Hr: 9025

Status: Closed
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 7-2-2025
Stop Date: 7-3-2025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CLAYTON OLSON	0.75	RT Shop Mech Rky	\$49.05	\$36.79

	Total Labor	\$36.79
	Total Parts	\$0.00
	Total Equip	\$0.00
	Total Cost	\$36.79

Item ID	Description	Completed By	Reported Hours
126727	REPLACE 4 WIRE PLUG	Clayton Olson	0.75

Work Order:	70482	Status:	Closed
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Blair MacAulay	Start Date:	7-21-2025
Kms:	8990	Stop Date:	7-23-2025
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
BLAINE STEFFAN	12.00	RT Shop Mech Rky	\$49.05	\$588.60
DARCY HALLOCK	0.25	RT Shop Tire Tech	\$36.33	\$9.08
OLIVER TRAUTMANN	8.00	RT Shop Mech Rky	\$49.05	\$392.40
		Total Labor		\$990.08
5TH WHEEL BRACKET PINS AND BUSHINGS FOR ILS - KIT - HOLLAND FW35 [RK10605]	1.00	Each	\$10.09	\$10.09
5TH WHEEL BRACKET PINS AND BUSHINGS FOR ILS - KIT - HOLLAND FW35 [RK10605][Custom]	1.00	Each	(\$10.09)	(\$10.09)
A/C SECONDARY BELT - SERPENTINE - RIBS: 6 - EFFECTIVE LENGTH (IN): 64.0 {638K6BLT, 640K6BLT} [D8410006061620]	1.00	Each	\$29.59	\$29.59
ALARM - BACK UP (12V) {3009546} [73040]	1.00	Each	\$21.26	\$21.26
BRAKE DRUM - 16.5 X 8.62 {3807AX} [165X8BD]	1.00	Each	\$169.38	\$169.38
BUSHING-MOUNTING EXHAUST {AUTO: M13109} [M131009]	2.00	Each	\$34.47	\$68.94
BUSHING-PIN ISOLATOR [M136004]	4.00	Each	\$11.06	\$44.23
FAN DRIVE BELT 12RIBS X 2180mm {FLTBT858K12, 858K12BLT} [D8410006122180]	1.00	Each	\$71.14	\$71.14
FILTER AIR {CF19013, X1987001, FLG: AF55839, NAV: 4070948C1} [SR2000092]	1.00	Each	\$45.34	\$45.34
FILTER AIR {DON: P621725} [P637453]	1.00	Each	\$114.26	\$114.26
FILTER FUEL SEPARATOR {DON: P550849, FLG: FS19764} [FS19763]	1.00	Each	\$23.69	\$23.69
FILTER FUEL SPIN-ON {DON: DBF6776, FLG: FF5971NN} [FF5825NN]	1.00	Each	\$61.19	\$61.19
FILTER HYDRAULIC SPIN-ON {FLG: HF6720, DON: P550388 DON: P550387, STAUFF: SF6720} [HF6710]	2.00	Each	\$17.26	\$34.53
FILTER LUBE SPIN-ON {FLG: LF14000NN, DON: DBL7900, SMS: 6002111341, CUMMINS: 5575298} [LF14001NN]	1.00	Each	\$55.12	\$55.12
GLADHAND SEAL CLOSE [FS312A]	2.00	Each	\$0.64	\$1.29
PADDED WASHER [HWC05782]	1.00	Each	\$12.34	\$12.34
PEAK INV 13420[Custom]	1.00	Each	\$450.00	\$450.00
REAR SHOES 16.5 X 8.625 [4711QP]	1.00	Each	\$156.25	\$156.25
RETAINER KIT [1707018X]	1.00	Each	\$23.56	\$23.56

SCREW - WING M10X1.5X40MM [HWC09341]	1.00 Each	\$20.37	\$20.37
SHAFT - EXHAUST [M051007]	2.00 Each	\$85.10	\$170.20
		Total Parts	\$1,572.68
		Total Equip	\$0.00
		Total Cost	\$2,562.76

Item ID	Description	Completed By	Reported Hours
128182	PEAK INV 13420 - REPLACE WINDSHIELD	Blair MacAulay	0.00
128317	REPLACE 5TH WHEEL	Blair MacAulay	4.00
128205	30K SERVICE	Blair MacAulay	5.00
128296	RELACE UPPER EXHAUST STACK BUSHINGS	Blair MacAulay	1.00
121969	REPLACE HYDRAULIC FILTER	Blair MacAulay	1.00
128290	REPLACE BACK UP ALARM	Blair MacAulay	0.50
128294	REPLACE GLAD HAND RUBBERS	Blair MacAulay	0.25
128313	REPAIR 2 WAY ANTENNA CABLE	Blair MacAulay	2.00
128295	REPLACE SHOES AND DRUM #3LH	Blair MacAulay	2.00
128183	REPLACE BELTS	Blair MacAulay	0.00
128297	RETORQUE PINION NUT #1 DIFF OUTPUT	Blair MacAulay	1.00
128291	REPLACE FAN CLUTCH AIR LINE	Blair MacAulay	1.00
128292	TIGHTEN SHOCK #2LH	Blair MacAulay	0.25
128310	REPLACE SHOES AND DRUM #3LH	Blair MacAulay	2.00
128211	9166- 07/21/2025 "TIRE CHECK"	Darcy Hallock	0.25

Work Order:	70667	Status:	Closed
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	MAIN YARD	Business Unit:	Trucks Heavy
Created by:	Darcy Hallock	Start Date:	7-24-2025
Kms:	8990	Stop Date:	7-24-2025
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	0.25	RT Shop Tire Tech	\$36.33	\$9.08
		Total Labor		\$9.08

	Total Parts	\$0.00
	Total Equip	\$0.00
	Total Cost	\$9.08

Item ID	Description	Completed By	Reported Hours
128476	9166- 07/24/2025 "TIRE CHECK"	Darcy Hallock	0.25

Work Order:	70824	Status:	Closed
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	MAIN YARD	Business Unit:	Trucks Heavy
Created by:	Darcy Hallock	Start Date:	7-28-2025
Kms:	8990	Stop Date:	7-28-2025
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	0.25	RT Shop Tire Tech	\$36.33	\$9.08
			Total Labor	\$9.08
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$9.08

Item ID	Description	Completed By	Reported Hours
128854	9166- 07/28/2025 "TIRE CHECK"	Darcy Hallock	0.25

Work Order:	70904	Status:	Closed
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:		Business Unit:	Trucks Heavy
Created by:	Kevin Gordan	Start Date:	
Kms:	8990	Stop Date:	
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
LIGHT CORD TRAILER 4 WAY 15' [194015]	1.00	Each	\$69.15	\$69.15
OIL FILL CAP ISX LARGE INSIDE THREAD {572.4003} [3687932]	1.00	Each	\$84.31	\$84.31
PADDED WASHER [HWC05782]	2.00	Each	\$12.66	\$25.31
PADDED WASHER [HWC05782]	1.00	Each	\$14.27	\$14.27
SCREW - WING M10X1.5X40MM [HWC09341]	2.00	Each	\$18.35	\$36.69
SCREW - WING M10X1.5X40MM [HWC09341]	1.00	Each	\$20.56	\$20.56

SIDEDUMP TARP CORD, 15', 2 POLE VERTICAL {PHI: 212272} [212272]	2.00 Each	\$215.69	\$431.38
		Total Parts	\$681.66
		Total Equip	\$0.00
		Total Cost	\$681.66

Item ID	Description	Completed By	Reported Hours
128944	9166-07/28/25-DIRECT BILL	Kevin Gordan	0.00

Work Order: 71214 **Status:** Closed
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 8-5-2025
Kms: 8990 **Stop Date:** 8-6-2025
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
JEFF DUBEAU	7.00	RT Shop Mech Rky	\$49.05	\$343.35
MICHAEL GATES	9.00	RT Shop Mech Rky	\$49.05	\$441.45
			Total Labor	\$784.80
FITTING HYD PLUG - MJIC(1") [ECH_2408-16]	1.00	Each	\$8.35	\$8.35
FITTING HYD PLUG - MJIC(1-1/4") [ECH_2408-20]	1.00	Each	\$5.52	\$5.52
			Total Parts	\$13.87
			Total Equip	\$0.00
			Total Cost	\$798.67

Item ID	Description	Completed By	Reported Hours
129558	REPAIR LEAK IN HYDRAULIC TANK	Blair MacAulay	16.00

Work Order: 71417 **Status:** Closed
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: MAIN YARD **Business Unit:** Trucks Heavy
Created by: Darcy Hallock **Start Date:** 8-8-2025
Kms: 8990 **Stop Date:** 8-8-2025
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	0.50	RT Shop Tire Tech	\$36.33	\$18.17
			Total Labor	\$18.17
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$18.17

Item ID	Description	Completed By	Reported Hours
129358	TIRE PRESSURE & TREAD DEPTH CHECK - ENTER INTO BS TOOLBOX	Darcy Hallock	0.50

Work Order: 71795 **Status:** Closed
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 8-15-2025
Kms: 8990 **Stop Date:** 8-18-2025
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
BRENT EVANS	2.00	RT Shop Mech Rky	\$49.05	\$98.10
			Total Labor	\$98.10
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$98.10

Item ID	Description	Completed By	Reported Hours
130578	REPAIR AIR LEAK	Blair MacAulay	2.00

Work Order: 72392 **Status:** Closed
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 8-28-2025
Kms: 8990 **Stop Date:** 8-29-2025
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
BLAINE STEFFAN	6.25	RT Shop Mech Rky	\$49.05	\$306.56
DARCY HALLOCK	1.00	RT Shop Tire Tech	\$36.33	\$36.33
			Total Labor	\$342.89
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$342.89

Item ID	Description	Completed By	Reported Hours
131648	TROUBLESHOOT TRANSMISSION FAULT	Blair MacAulay	6.00

131652	REPAIR DAMAGED AIR LINE	Blair MacAulay	0.25
--------	-------------------------	----------------	------

131678 9166- 08/28/2025 "VERTICLE ROTATE STEERS" Darcy Hallock 1.00

Work Order: 73121 **Status:** Closed
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 9-15-2025
Kms: 8990 **Stop Date:** 9-16-2025
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
MICHAEL GATES	0.50	RT Shop Mech Rky	\$49.05	\$24.53
			Total Labor	\$24.53
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$24.53

Item ID	Description	Completed By	Reported Hours
133125	REPAIR RF MARKER LIGHT	Blair MacAulay	0.50

Work Order: 73199 **Status:** Closed
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Bernie Seefried **Start Date:** 9-16-2025
Kms: 8990 **Stop Date:** 9-16-2025
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$0.00

Item ID	Description	Completed By	Reported Hours
133270	FENDER ISSUE	Bernie Seefried	0.00

Work Order: 73268 **Status:** Closed
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 9-18-2025

Kms: 8990
Hr: 9025

Stop Date: 9-19-2025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
BRENT EVANS	0.50	RT Shop Mech Rky	\$49.05	\$24.53
			Total Labor	\$24.53
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$24.53

Item ID	Description	Completed By	Reported Hours
133402	REPAIR TRAILER SERVICE AIR LINE	Brent Evans	0.50

Work Order: 73766 **Status:** Closed
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 9-29-2025
Kms: 8990 **Stop Date:** 9-30-2025
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
BLAINE STEFFAN	0.75	RT Shop Mech Rky	\$49.05	\$36.79
CHANCE NICOLAY	2.00	RT Shop Mech Rky	\$49.05	\$98.10
			Total Labor	\$134.89
A/C SECONDARY BELT - SERPENTINE - RIBS: 6 - EFFECTIVE LENGTH (IN): 64.0 {638K6BLT, 640K6BLT} [D8410006061620]	1.00	Each	\$32.97	\$32.97
CORE ITEM - BATTERY GROUP 31 12V 730CCA {BD31S71EXCH} [7T31]	4.00	Each	\$149.24	\$596.95
TENSIONER, BELT [3690067]	1.00	Each	\$509.64	\$509.64
			Total Parts	\$1,139.56
			Total Equip	\$0.00
			Total Cost	\$1,274.45

Item ID	Description	Completed By	Reported Hours
131653	REPLACE AC BELT AND TENSIONER	Blair MacAulay	1.00
134209	REPLACE BATTERIES	Blair MacAulay	1.50
134190	LOAD TEST BATTERIES	Blair MacAulay	0.25

Work Order: 74326 **Status:** Closed
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Blackfalds Shop **Business Unit:** Trucks Heavy

Created by: Nick Depratto
Kms: 8990
Hr: 9025

Start Date: 10-10-2025
Stop Date: 10-15-2025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
GWK INV SR2012620[Custom]	1.00	Each	\$778.61	\$778.61
			Total Parts	\$778.61
			Total Equip	\$0.00
			Total Cost	\$778.61

Item ID	Description	Completed By	Reported Hours
135182	GWK INV SR2012620 - TRANSMISSION WILL NOT GO INTO GEAR	Nick Depratto	0.00

Work Order: 74562
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Oom Jarussirrat
Kms: 8990
Hr: 9025

Status: Closed
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 10-17-2025
Stop Date: 10-18-2025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
JOSHUA BOTA	1.00	RT Shop Mech Blfds	\$52.07	\$52.07
WAYNE KIRK	0.50	RT Shop Mech Blfds	\$52.07	\$26.04
			Total Labor	\$78.11
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$78.11

Item ID	Description	Completed By	Reported Hours
135650	AIR LEAKS ISSUE	Oom Jarussirrat	1.50

Work Order: 75285
Equipment: TRACTOR TANDEM KW T880 [9166]
Work Location: Blackfalds Shop
Created by: Oom Jarussirrat
Kms: 8990
Hr: 9025

Status: Closed
Serial Number: 1XKZD40X7LJ969605
Business Unit: Trucks Heavy
Start Date: 11-4-2025
Stop Date: 11-5-2025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
JOSHUA BOTA	1.00	RT Shop Mech Blfds	\$52.07	\$52.07
			Total Labor	\$52.07

Total Parts	\$0.00
Total Equip	\$0.00
Total Cost	\$52.07

Item ID	Description	Completed By	Reported Hours
137259	TRUCK WON'T START	Joshua Bota	1.00

Work Order:	75326	Status:	Closed
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Blackfalds Shop	Business Unit:	Trucks Heavy
Created by:	Oom Jarussirirat	Start Date:	11-6-2025
Kms:	8990	Stop Date:	11-11-2025
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
ADRIEL MEDALLA	2.00	RT Shop Tire Tech	\$36.33	\$72.66
BLAKE HOPKINS	14.50	RT Shop Mech Blfds	\$52.07	\$755.02
KENT WOOLSEY	2.00	RT Shop Mech Blfds	\$52.07	\$104.14
MITCHELL ROHRBACH	10.00	RT Shop Mech Blfds	\$52.07	\$520.70
		Total Labor		\$1,452.52
10" RISER FOR ILS SLIDE [RK106894]	1.00	Each	\$798.00	\$798.00
5TH WHEEL FW35 BRACKET PINS AND BUSHINGS FOR ILS - KIT {AUT:KP154} [HOL_RK10605]	1.00	Each	\$32.73	\$32.73
5TH WHEEL FW35 POCKET INSERTS REPLACEMENT [HOL_RKPKT2]	1.00	Each	\$58.90	\$58.90
AIR DRYER FILTER (ADIS) [BEN_5008414PG]	1.00	Each	\$188.60	\$188.60
BEARING STRAP RETAINER KIT [SPI_2507018X]	1.00	Each	\$20.54	\$20.54
BLOWER MOTOR ASSY {CR705002} [CR705003]	1.00	Each	\$545.50	\$545.50
BRAKE CHAMBER - TYPE 3030LS, WELDED CLEVIS {TRP: SB3030CLWCR, NT3030ELS-WC} [GC3030LCW]	1.00	Each	\$108.63	\$108.63
ESPAR AIRTRONIC D2 BURNER [ESP_252069100100]	1.00	Each	\$388.22	\$388.22
ESPAR AIRTRONIC D2/D4 - GASKET, BLOWER [ESP_252069010003]	1.00	Each	\$5.48	\$5.48
ESPAR AIRTRONIC GLOW PIN 12V W/WRENCH [ESP_252069011300]	1.00	Each	\$222.23	\$222.23
FILTER AIR {CF19013, X1987001, FLG: AF55839, NAV: 4070948C1} [SR2000092]	1.00	Each	\$41.05	\$41.05
FILTER AIR {DON: P621725} [P637453]	1.00	Each	\$112.33	\$112.33
FILTER FUEL SEPARATOR {DON: P550849, FLG: FS19764} [FS19763]	1.00	Each	\$23.39	\$23.39
FILTER FUEL SPIN-ON {DON: DBF6776, FLG: FF5971NN} [FF5825NN]	1.00	Each	\$60.75	\$60.75
FILTER LUBE SPIN-ON {FLG: LF14000NN, DON: DBL7900, SMS: 6002111341, CUMMINS: 5575298} [LF14001NN]	1.00	Each	\$55.94	\$55.94
FILTER POWER STEERING {DON: P550830, 3937557S} [87904M]	2.00	Each	\$32.53	\$65.05
GASKET - OIL PAN [4026684]	1.00	Each	\$403.04	\$403.04
MERITOR RZ-XX-166 INPUT DIFF YOKE NUT W/WASHER {40X1233} [MER_KIT2638]	1.00	Each	\$39.40	\$39.40
PAN, OIL [5647538CUM]	1.00	Each	\$1,763.25	\$1,763.25

PIDHERNEYS MUD FLAP - 24 X 30 [NM_PB2430]	1.00 Each	\$63.24	\$63.24
SHOCK ABSORBER {GBL: 85989} [65176]	1.00 Each	\$109.48	\$109.48
TRACKER [17148]	1.00 Each	\$17.10	\$17.10
TRAILER LIGHT CORD 7 WAY 15', WITH WEATHER-TITE™ PERMAPLUGS [302070]	1.00 Each	\$226.60	\$226.60
		Total Parts	\$5,349.47
		Total Equip	\$0.00
		Total Cost	\$6,801.98

Item ID	Description	Completed By	Reported Hours
137469	R & R SHOCKS AS NECESSARY	Mitchell Rohrbach	0.50
137474	MISSING THE HOSE HANGER ON POGO STICK	Blake Hopkins	0.25
137463	NEED A NEW 7 WIRES EXTENSION CORD ON DECK	Blake Hopkins	0.25
137356	30k Service Inspection	Mitchell Rohrbach	6.00
137360	CHECK ENG AND BUNK WEBASTO (DRIVER SAID THEY ARE NOT WORKING)	Mitchell Rohrbach	4.00
137466	LOOSE RH EXHASUT STACK	Mitchell Rohrbach	0.50
137359	CHECK BATTERIES; CLEAN , CHARGE, & LOAD TEST (HAD TO BE BOOSTED)	Blake Hopkins	1.00
132856	REPLACE AIR DRYER CARTRIDGE FILTER	Mitchell Rohrbach	1.00
137472	NEEDS TO TOP UP HYD TANK (HALF WAY UP SITE GLASS)	Mitchell Rohrbach	0.50
137361	FILL ALCOHOL EVAP CANISTOR	Blake Hopkins	0.25
137464	LH STTER HUB VERY LOW ON FLUID (CHECK FOR LEAKS)	Blake Hopkins	0.25
137358	REPLACE POWER STEERING FILTER (WAIT UNTIL NEXT SERVICE OR CVIP)	Blake Hopkins	0.25
137362	NEED A NEW OIL PAN GASKET	Oom Jarussirirat	3.00
137465	NEED NEW 5TH WHEEL PIVOT PINS & BUSHINGS	Oom Jarussirirat	2.00
137468	REPLACE MUD FLAP AS NECESSARY	Oom Jarussirirat	0.00
137467	#1 DIFF INPUT YOKE NUT LOOSE	Oom Jarussirirat	1.00
137355	TIRE PRESSURE & TREAD DEPTH CHECK - ENTER INTO BS TOOLBOX	Adriel Medalla	2.00
137471	HAVAC FAN ISSUE	Oom Jarussirirat	2.50
137473	AIR LEAKS ISSUE	Oom Jarussirirat	0.50
137357	REPLACE HYDRAULIC TANK CAP - TRUCK & WAGON (P# HBF16) TRACTORS (P#	Blake Hopkins	0.75

137470	CRACKED FENDER	Oom Jarussirrat	2.00
--------	----------------	-----------------	------

Work Order: 76034 **Status:** Closed
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 11-25-2025
Kms: 8990 **Stop Date:** 11-28-2025
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CHANCE NICOLAY	10.00	RT Shop Mech Rky	\$49.05	\$490.50
			Total Labor	\$490.50
EVOLUTION PEDAC-20J COOLER [RAH1354]	1.00	Each	\$1,579.52	\$1,579.52
PRESSURE CAP [GW20938]	1.00	Each	\$17.14	\$17.14
RADIATOR, PB/KW {TRP: RADS10316TRP, 770015} [N3800003]	1.00	Each	\$888.21	\$888.21
WASHER PUMP W/GROMMET {PAC: 600208S, T4695001, WB6035402PUMP AUTO: HLK7046} [WB6035402PUMP]	1.00	Each	\$19.58	\$19.58
WINTERFRONT, BLACK - KWT880 [WF257B]	1.00	Each	\$148.20	\$148.20
			Total Parts	\$2,652.65
			Total Equip	\$0.00
			Total Cost	\$3,143.15

Item ID	Description	Completed By	Reported Hours
138740	REPLACE RADIATOR	Blair MacAulay	6.00
138687	REPAIR COOLANT LEAK	Blair MacAulay	4.00

Work Order: 77073 **Status:** Closed
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Blackfalds Shop, Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Oom Jarussirrat **Start Date:** 12-15-2025
Kms: 8990 **Stop Date:** 12-16-2025
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CLAYTON OLSON	2.25	RT Shop Mech Rky	\$49.05	\$110.36
DARCY HALLOCK	1.75	RT Shop Tire Tech	\$36.33	\$63.58
			Total Labor	\$173.94
TIRE {BST_M863, FS_821} [KAL_STEER31580R225]	2.00	Each	\$904.79	\$1,809.58
			Total Parts	\$1,809.58
			Total Equip	\$0.00
			Total Cost	\$1,983.52

141044	REPLACE BATTERIES	Clayton Olson	1.00
--------	-------------------	---------------	------

Work Order:	77494	Status:	Closed
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Blair MacAulay	Start Date:	1-5-2026
Kms:	8990	Stop Date:	1-6-2026
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CLAYTON OLSON	0.50	RT Shop Mech Rky	\$49.05	\$24.53
OLIVER TRAUTMANN	3.00	RT Shop Mech Rky	\$49.05	\$147.15
			Total Labor	\$171.68
CORE ITEM - BATTERY GROUP 31 12V 730CCA {BD31S71EXCH, ARTIC: TPGA31S} [7T31]	4.00	Each	\$153.51	\$614.05
PADDED WASHER [HWC05782]	1.00	Each	\$14.25	\$14.25
			Total Parts	\$628.31
			Total Equip	\$0.00
			Total Cost	\$799.98

Item ID	Description	Completed By	Reported Hours
141070	REPLACE RH HIGH BEAM	Blair MacAulay	3.50

Work Order:	78249	Status:	Closed
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Blair MacAulay	Start Date:	1-27-2026
Kms:	8990	Stop Date:	1-28-2026
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CHANCE NICOLAY	9.25	RT Shop Mech Rky	\$49.05	\$453.71
JEFF DUBEAU	7.00	RT Shop Mech Rky	\$49.05	\$343.35
			Total Labor	\$797.06
CORE ITEM - FAN HUB HORTON DM ADVANTAGE TWO-SPEED REMAN [79A9782RMAN]	1.00	Each	\$2,164.31	\$2,164.31
CORE ITEM - FAN HUB HORTON DM ADVANTAGE TWO-SPEED REMAN [79A9782RMAN][Custom]	1.00	Each	(\$484.00)	(\$484.00)
EGR COOLER KIT - X15 {5405901} [5693915CUM]	1.00	Each	\$3,834.56	\$3,834.56
HOSE-PLAIN {561.90223} [3687223CUM]	1.00	Each	\$114.75	\$114.75
			Total Parts	\$5,629.62
			Total Equip	\$0.00
			Total Cost	\$6,426.68

Item ID	Description	Completed By	Reported Hours
142287	REPLACE EGR COOLER	Blair MacAulay	6.75
142499	REPLACE FAN HUB	Blair MacAulay	2.50
142273	REPAIR COOLANT LEAKS	Blair MacAulay	2.00
142274	REPAIR WINDOW CONTROLS	Blair MacAulay	1.00
142275	CHECK FAN HUB AIR LEAK	Blair MacAulay	2.50
142272	REPAIR DUMP CONTROLS	Blair MacAulay	1.50

Work Order:	79737	Status:	Closed
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Blair MacAulay	Start Date:	2-5-2026
Kms:	8990	Stop Date:	2-9-2026
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	2.50	RT Shop Tire Tech	\$36.33	\$90.83
			Total Labor	\$90.83
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$90.83

Item ID	Description	Completed By	Reported Hours
144360	9166- 02/05/2026 "TIRE CHECK/INSTALL RUNOUT DRIVES (X4)"	Darcy Hallock	2.50
144330	REPLACE WINDSHIELD	Blair MacAulay	0.00
144331	TROUBLESHOOT TRANSMISSION CODES	Blair MacAulay	0.00

Work Order:	80197	Status:	Closed
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Blair MacAulay	Start Date:	2-17-2026
Kms:	8990	Stop Date:	2-18-2026
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
MICHAEL GATES	1.00	RT Shop Mech Rky	\$49.05	\$49.05
			Total Labor	\$49.05
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$49.05

Item ID	Description	Completed By	Reported Hours
145148	REPAIR TARP CONTROL	Blair MacAulay	1.00

Work Order: 80562 **Status:** Closed
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Blackfalds Shop **Business Unit:** Trucks Heavy
Created by: Oom Jarussirrat **Start Date:** 2-24-2026
Kms: 8990 **Stop Date:** 3-6-2026
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$0.00

Item ID	Description	Completed By	Reported Hours
145700	GWK RD -CLUTCH SLIPPING FAULTS	Blair MacAulay	0.00

Work Order: 81088 **Status:** Closed
Equipment: TRACTOR TANDEM KW T880 [9166] **Serial Number:** 1XKZD40X7LJ969605
Work Location: Rocky Mountain House Shop **Business Unit:** Trucks Heavy
Created by: Blair MacAulay **Start Date:** 3-4-2026
Kms: 8990 **Stop Date:** 3-5-2026
Hr: 9025

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
			Total Labor	\$0.00
FILTER DEF [PE17001JAB]	1.00	Each	\$63.31	\$63.31
			Total Parts	\$63.31
			Total Equip	\$0.00
			Total Cost	\$63.31

Item ID	Description	Completed By	Reported Hours
---------	-------------	--------------	----------------

Work Order:	81154	Status:	Closed
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Blackfalds Shop	Business Unit:	Trucks Heavy
Created by:	Oom Jarussirirat	Start Date:	3-6-2026
Kms:	8990	Stop Date:	3-7-2026
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
JOSHUA BOTA	3.00	RT Shop Mech Blfds	\$52.07	\$156.21
			Total Labor	\$156.21
			Total Parts	\$0.00
			Total Equip	\$0.00
			Total Cost	\$156.21

Item ID	Description	Completed By	Reported Hours
146660	LIGHTS ISSUE. NO TAILLIGHTS	Joshua Bota	3.00

Work Order:	81257	Status:	Closed
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	Rocky Mountain House Shop	Business Unit:	Trucks Heavy
Created by:	Nick Depratton	Start Date:	3-11-2026
Kms:	8990	Stop Date:	3-17-2026
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
CHANCE NICOLAY	18.00	RT Shop Mech Rky	\$49.05	\$882.90
DARCY HALLOCK	1.00	RT Shop Tire Tech	\$36.33	\$36.33
H. KANIELA JOHNSON	1.00	RT Shop Mech Rky	\$49.05	\$49.05
TYLER STEFFAN	22.00	RT Shop Mech Rky	\$49.05	\$1,079.10
			Total Labor	\$2,047.38
AIR DRYER FILTER (ADIS) [BEN_5008414PG]	1.00	Each	\$185.65	\$185.65
ALUM DRIVER FENDER [M11305D]	1.00	Each	\$435.50	\$435.50
ALUM DRIVER FENDER {M11305L} [M11305D]	1.00	Each	\$344.59	\$344.59
BRAKE SHOE HARDWARE KIT {E2769HD, BHK051,MKT4515QHD-B} [KIT8000HD]	1.00	Each	\$12.77	\$12.77
CAM SHAFT REPAIR KIT FOR CAM 2210K7603 AND 2210L7604 {AUTOMAN 1102207} [KIT8042]	1.00	Each	\$19.59	\$19.59
Edit Delete ALUM DRIVER FENDER {M11305L} [M11305D][Custom]	1.00	Each	(\$435.50)	(\$435.50)
EXHAUST STACK TIP 5X48 STL [EP50CS248C]	2.00	Each	\$152.98	\$305.96
HUB CAP DRIVE AXLE 8" (BOSCH: FLTCR16930SP, FGI: 80012C) [MW11031BK]	4.00	Each	\$6.47	\$25.88
HUB CAP STEER AXLE W/HOLE - 5 NOTCH (PB, KW: MW12851H) [205H1]	2.00	Each	\$9.50	\$19.00

LUG NUT COVER 33mm (BOSCH: FLTCR18210SP, FGI: TNUTF2) [MW1262BK]	60.00 Each	\$1.08	\$64.80
MW2303BK LONG 33M NUT COVERS[Custom]	20.00 Each	\$2.15	\$43.00
PADDED WASHER [HWC05782]	1.00 Each	\$12.66	\$12.66
PASSENGER SIDE FENDER {M11305R} [M11305P]	1.00 Each	\$344.59	\$344.59
SCAM SHAFT RH 1.5" D, 14.95" 28 SPLINE {2210P7660} [E11576]	1.00 Each	\$129.45	\$129.45
WIPER BLADE 22" WINTER *NOTES [WW2210]	2.00 Each	\$16.53	\$33.05
		Total Parts	\$1,540.98
		Total Equip	\$0.00
		Total Cost	\$3,588.36

Item ID	Description	Completed By	Reported Hours
146986	REPLACE REAR FENDERS	Blair MacAulay	14.25
146820	SALE PREP	Blair MacAulay	10.50
146985	CVIP INSPECTION CV8531410	Blair MacAulay	7.50
147006	REPLACE S CAM #3RH	Blair MacAulay	3.00
147009	REPLACE AIR LINE #3RH	Blair MacAulay	0.50
147011	REPLACE EXHAUST TIPS	Blair MacAulay	4.00
147010	REPAIR LIGHTS	Blair MacAulay	0.50
147007	REPLACE TRAILER EMERGENCY AIR LINE	Blair MacAulay	0.50
147008	REPAIR AIR LEAKS	Blair MacAulay	0.25
147264	9166- 03/16/2026 "INSTALL POLISHED WHEELS"	Darcy Hallock	1.00

Work Order:	82687	Status:	Closed
Equipment:	TRACTOR TANDEM KW T880 [9166]	Serial Number:	1XKZD40X7LJ969605
Work Location:	MAIN YARD	Business Unit:	Trucks Heavy
Created by:	Darcy Hallock	Start Date:	4-14-2026
Kms:	8990	Stop Date:	4-14-2026
Hr:	9025		

Work Order Cost Summary

Description	Quantity	Labor Type	Rate	Total
DARCY HALLOCK	0.25	RT Shop Tire Tech	\$36.33	\$9.08
			Total Labor	\$9.08
FRONT CHROME HUB COVERS 4 NOTCH [MW12811H]	2.00	Each	\$20.97	\$41.94
			Total Parts	\$41.94
			Total Equip	\$0.00
			Total Cost	\$51.02

Item ID	Description	Completed By	Reported Hours
149409	9166- 04/14/2026 "INSTALL CHROME COVERS"	Darcy Hallock	0.25