

| <u>Work Order</u>     | <u>Request</u>        | <u>Request Type</u>         | <u>Description</u>                     |
|-----------------------|-----------------------|-----------------------------|----------------------------------------|
| <a href="#">56978</a> | <a href="#">74959</a> | BIS - Pending Closure       | BAS - T/S ENG CODES                    |
| <a href="#">63235</a> | <a href="#">82076</a> | Running Repair              | BAS - CHECK TIRES                      |
| <a href="#">5140</a>  | <a href="#">6141</a>  | Preventative Maintenance... | 2000 HR PM Service                     |
| <a href="#">25215</a> | <a href="#">35769</a> | Running Repair              | ML - FLAT TIRE                         |
| <a href="#">12384</a> | <a href="#">17428</a> | Running Repair              | CEN - RIGHT FRONT TIRE - SMALL LEAK    |
| <a href="#">50116</a> | <a href="#">66995</a> | Monitor                     | CEN - R/F DUO CONE SEAL LEAKING        |
| <a href="#">38965</a> | <a href="#">53455</a> | Running Repair              | CEN - T/S FUEL PRESSURE CODES          |
| <a href="#">2552</a>  | <a href="#">3033</a>  | BIS - Pending Closure       | BAS - AFTERTREATMENT FAULT, WILL NO... |
| <a href="#">12717</a> | <a href="#">17961</a> | Running Repair              | CEN - FRONT RIGHT HEADLIGHT BURNT ...  |
| <a href="#">9223</a>  | <a href="#">12372</a> | BIS - Pending Closure       | CEN - REPLACE IDLE SWITCH              |
| <a href="#">3293</a>  | <a href="#">3843</a>  | BIS - Pending Closure       | 500 HR PM Service                      |
| <a href="#">51073</a> | <a href="#">68059</a> | Running Repair              | CEN - REPLACE DAMAGED SEAT             |
| <a href="#">3137</a>  | <a href="#">3767</a>  | Running Repair              | RIGHT FENDER RATTILING                 |
| <a href="#">54158</a> | <a href="#">71568</a> | Running Repair              | BAS - T/S NO CAB HEAT                  |
| <a href="#">10656</a> | <a href="#">14822</a> | Running Repair              | CEN - WASHER NOZZLES NOT WORKING       |
| <a href="#">10656</a> | <a href="#">14744</a> | Running Repair              | CEN - SEAT SLIDES WORN                 |
| <a href="#">10656</a> | <a href="#">14741</a> | Running Repair              | CEN - FUEL LEAK                        |
| <a href="#">10656</a> | <a href="#">14743</a> | BIS - Pending Closure       | CEN - TRANS LEAKING                    |
| <a href="#">10656</a> | <a href="#">14742</a> | BIS - Pending Closure       | CEN - PM ASSESSMENT                    |
| <a href="#">3010</a>  | <a href="#">3619</a>  | BIS - Pending Closure       | L03 RED CODE                           |

|                       |                       |                             |                                      |
|-----------------------|-----------------------|-----------------------------|--------------------------------------|
| <a href="#">45319</a> | <a href="#">61122</a> | Preventative Maintenance... | 250 HR PM Service                    |
| <a href="#">13053</a> | <a href="#">14775</a> | Preventative Maintenance... | 250 HR PM Service                    |
| <a href="#">47913</a> | <a href="#">64393</a> | Vendor Repairs              | ACH - VENDOR REPAIRS (TECHNICHROM... |
| <a href="#">3108</a>  | <a href="#">3732</a>  | Running Repair              | NEEDS NEW WIPER BLADE                |
| <a href="#">29910</a> | <a href="#">41308</a> | BIS - Pending Closure       | CEN - T/S EMISSION CODES             |
| <a href="#">1464</a>  | <a href="#">1358</a>  | Preventative Maintenance... | 250 HR PM Service                    |
| <a href="#">1464</a>  | <a href="#">1738</a>  | Preventative Maintenance... | 1000 HR PM Service                   |
| <a href="#">1464</a>  | <a href="#">1739</a>  | Preventative Maintenance... | 500 HR PM Service                    |
| <a href="#">30760</a> | <a href="#">42324</a> | Running Repair              | ML - T/S REAR TRANS NOISE            |
| <a href="#">2631</a>  | <a href="#">3114</a>  | BIS - Pending Closure       | BAS - Aftertreatment Code            |
| <a href="#">43400</a> | <a href="#">58759</a> | BIS - Pending Closure       | BR - OUTGOING INSPECTION             |
| <a href="#">43400</a> | <a href="#">59068</a> | Running Repair              | BR - REPLACE REAR WIPER              |
| <a href="#">43400</a> | <a href="#">59067</a> | Running Repair              | BR - REPLACE D/S MIRROR              |
| <a href="#">14663</a> | <a href="#">20953</a> | Running Repair              | CEN - WASHER SPRAYER NOT WORKING     |
| <a href="#">46888</a> | <a href="#">63106</a> | Running Repair              | CEN - T/S 2 WAY                      |
| <a href="#">30179</a> | <a href="#">41612</a> | Running Repair              | ML - 2-WAY RADIO ISSUES              |
| <a href="#">16252</a> | <a href="#">23262</a> | Preventative Maintenance... | ACH - SOS                            |
| <a href="#">48648</a> | <a href="#">65312</a> | Preventative Maintenance... | CEN - 500HR PM SERVICE               |
| <a href="#">16430</a> | <a href="#">23565</a> | Running Repair              | CEN - REPLACE ROCKER SWITCH ASSY     |
| <a href="#">6778</a>  | <a href="#">8350</a>  | BIS - Pending Closure       | CEN - WHEEL SEAL (SMS WARRANTY)      |
| <a href="#">58121</a> | <a href="#">76290</a> | Running Repair              | BAS - CAB & BODY REPAIRS             |
| <a href="#">42530</a> | <a href="#">57682</a> | BIS - Pending Closure       | BR - T/S 2 WAY RADIO ISSUES          |

|                       |                       |                             |                                       |
|-----------------------|-----------------------|-----------------------------|---------------------------------------|
| <a href="#">42530</a> | <a href="#">57683</a> | BIS - Pending Closure       | BR - REPLACE SIGNAL LIGHT             |
| <a href="#">22307</a> | <a href="#">20587</a> | Preventative Maintenance... | 500 HR PM Service                     |
| <a href="#">6342</a>  | <a href="#">7569</a>  | Running Repair              | CEN- INSPECTION                       |
| <a href="#">3159</a>  | <a href="#">3786</a>  | BIS - Pending Closure       | LOW DOSING PRESSURE                   |
| <a href="#">2704</a>  | <a href="#">3191</a>  | BIS - Pending Closure       | BAS - REPLACED BURN OUT HEADLIGHT     |
| <a href="#">58906</a> | <a href="#">77294</a> | BIS - Pending Closure       | BAS - INSTALL TAILGATE BRACKETS       |
| <a href="#">58906</a> | <a href="#">77159</a> | BIS - Pending Closure       | BAS - REPLACE END GATE GREASE LINE    |
| <a href="#">11283</a> | <a href="#">15745</a> | Running Repair              | CEN - R/S STEERING WHEEL HUB PLUGG... |
| <a href="#">26964</a> | <a href="#">37803</a> | Preventative Maintenance... | ML - 1000 HR PM                       |
| <a href="#">54193</a> | <a href="#">71614</a> | Running Repair              | BAS - FUSE BUS / NO POWER             |
| <a href="#">58224</a> | <a href="#">76399</a> | Preventative Maintenance... | 500 HR PM Service                     |
| <a href="#">64208</a> | <a href="#">83201</a> | Preventative Maintenance... | TIRE INSPECTIOIN                      |
| <a href="#">11282</a> | <a href="#">15744</a> | Running Repair              | CEN - RADIO ISSUES                    |
| <a href="#">8966</a>  | <a href="#">11914</a> | BIS - Pending Closure       | CEN - ENGINE DERATED                  |
| <a href="#">51886</a> | <a href="#">68968</a> | BIS - Pending Closure       | CEN - REPAIR STEP                     |
| <a href="#">55039</a> | <a href="#">72645</a> | BIS - Pending Closure       | BAS - WINDSHIELD DAMAGE               |
| <a href="#">59426</a> | <a href="#">77812</a> | BIS - Pending Closure       | BAS - T/S DEF CODE                    |
| <a href="#">45135</a> | <a href="#">60918</a> | Running Repair              | CEN - T/S SCR EFFICIENCY LOW CODE     |
| <a href="#">10471</a> | <a href="#">14398</a> | BIS - Pending Closure       | CEN - 500HR SERVICE                   |
| <a href="#">42073</a> | <a href="#">57108</a> | Preventative Maintenance... | 500 HR PM Service                     |
| <a href="#">63356</a> | <a href="#">82200</a> | Running Repair              | ACH - AUCTION PREP                    |
| <a href="#">14820</a> | <a href="#">21197</a> | Preventative Maintenance... | CEN - 2000HR SERVICE                  |
| <a href="#">50422</a> | <a href="#">67306</a> | Preventative Maintenance... | CEN - 250HR SERVICE                   |



|                       |                       |                             |                                        |
|-----------------------|-----------------------|-----------------------------|----------------------------------------|
| <a href="#">36940</a> | <a href="#">50903</a> | Running Repair              | CEN - T/S ACTIVE CODES                 |
| <a href="#">14752</a> | <a href="#">21092</a> | Running Repair              | CEN - HIGH COOLANT TEMP                |
| <a href="#">39216</a> | <a href="#">56692</a> | BIS - Pending Closure       | CEN - PARTS MISSED ON WO / SEAT BEL... |
| <a href="#">39216</a> | <a href="#">53756</a> | Running Repair              | CEN - SEATBELT REPLACEMENT             |
| <a href="#">39216</a> | <a href="#">53755</a> | Running Repair              | CEN - WEEP AT LR HUB SEAL              |
| <a href="#">39216</a> | <a href="#">53735</a> | Running Repair              | CEN - OUTGOING INSPECTION              |
| <a href="#">10985</a> | <a href="#">15284</a> | Running Repair              | CEN - DRIVELINE INSPECTION             |
| <a href="#">59615</a> | <a href="#">78029</a> | Preventative Maintenance... | 250 HR PM Service                      |
| <a href="#">31082</a> | <a href="#">44438</a> | Running Repair              | ML - REPAIR TIRE                       |
| <a href="#">31082</a> | <a href="#">45084</a> | Running Repair              | ML - MARKER LIGHT REPLACEMENT          |
| <a href="#">31082</a> | <a href="#">42718</a> | BIS - Pending Closure       | ML - OUTGOING INSPECTION               |
| <a href="#">11643</a> | <a href="#">16249</a> | Running Repair              | CEN - DEF TANK LEAK                    |
| <a href="#">22177</a> | <a href="#">32019</a> | Running Repair              | ML - RE-INSTALL TIRE DRAG              |
| <a href="#">61644</a> | <a href="#">80347</a> | Running Repair              | BAS - PM ASSESSMENT                    |
| <a href="#">22699</a> | <a href="#">32638</a> | Running Repair              | ML - LOW TIRE                          |
| <a href="#">57804</a> | <a href="#">75949</a> | Running Repair              | BAS - LOOSE STEPS                      |
| <a href="#">13969</a> | <a href="#">19924</a> | Running Repair              | CEN - L/H LIGHTS NOT WORKING           |
| <a href="#">22484</a> | <a href="#">32387</a> | Running Repair              | ML - REPAIR TIRE DRAG SHACKLE          |
| <a href="#">62676</a> | <a href="#">81456</a> | Running Repair              | BAS - REMOVE TAILGATE                  |
| <a href="#">55038</a> | <a href="#">72644</a> | BIS - Pending Closure       | BAS - REPAIR LOOSE LH MIRROR           |
| <a href="#">58733</a> | <a href="#">76959</a> | Preventative Maintenance... | BAS - RESAMPLE ENGINE OIL              |
| <a href="#">26717</a> | <a href="#">37504</a> | Breakdown / Emergency       | KL - T/S - RPR REGEN ISSUES            |

|                       |                       |                             |                                        |
|-----------------------|-----------------------|-----------------------------|----------------------------------------|
| <a href="#">57933</a> | <a href="#">76095</a> | BIS - Pending Closure       | BAS - T/S LEAKING BRAKE COOLING HOS... |
| <a href="#">15001</a> | <a href="#">21474</a> | Running Repair              | CEN - REPLACE RF TIRE                  |
| <a href="#">2300</a>  | <a href="#">2768</a>  | Running Repair              | BAS - DIFFERENTIAL SENSOR              |
| <a href="#">35581</a> | <a href="#">49282</a> | Running Repair              | CEN - REPLACE STEER TIRES              |
| <a href="#">34535</a> | <a href="#">47737</a> | Running Repair              | CEN - WORN HYD HOSE                    |
| <a href="#">21666</a> | <a href="#">31336</a> | Running Repair              | ML - T/S 2 WAY RADIO                   |
| <a href="#">59029</a> | <a href="#">77293</a> | BIS - Pending Closure       | BAS - LIGHT REPAIRS                    |
| <a href="#">44736</a> | <a href="#">60786</a> | Running Repair              | CEN - BROKEN ROUND MIRROR              |
| <a href="#">44736</a> | <a href="#">60400</a> | Running Repair              | CEN - JOB COST *RPL MIRROR*            |
| <a href="#">49194</a> | <a href="#">65961</a> | Running Repair              | CEN - REPAIR BENT STEPS                |
| <a href="#">51553</a> | <a href="#">68589</a> | BIS - Pending Closure       | CEN - TIRE DAMAGE                      |
| <a href="#">45682</a> | <a href="#">61554</a> | Running Repair              | CEN - T/S - RPR SCR CODES              |
| <a href="#">41410</a> | <a href="#">56286</a> | BIS - Pending Closure       | CEN - FIRE EXT REPLACEMENT             |
| <a href="#">41410</a> | <a href="#">56282</a> | Running Repair              | CEN - DRIVERS SEATBELT GETS STUCK      |
| <a href="#">41410</a> | <a href="#">56284</a> | Running Repair              | CEN - T/S WINDSHIELD WASH SPRAYER      |
| <a href="#">41410</a> | <a href="#">56287</a> | BIS - Pending Closure       | CEN - OUTGOING INSPECTION              |
| <a href="#">41410</a> | <a href="#">56285</a> | Running Repair              | CEN - DEF TANK LEAKING                 |
| <a href="#">41583</a> | <a href="#">56493</a> | BIS - Pending Closure       | BR - REPAIR L03 CODE                   |
| <a href="#">19316</a> | <a href="#">27841</a> | Running Repair              | ML - WELD & INSTALL TEAR DROP LUGS     |
| <a href="#">45561</a> | <a href="#">61405</a> | Running Repair              | CEN - REPLACE FIRE EXT                 |
| <a href="#">19323</a> | <a href="#">27849</a> | Preventative Maintenance... | 2000 HR PM Service                     |
| <a href="#">13627</a> | <a href="#">19315</a> | Breakdown / Emergency       | CEN - FRONT RIGHT TIRE LEAKING         |
| <a href="#">29636</a> | <a href="#">41053</a> | Running Repair              | KL - POSITIVE AIR INOP                 |

|                       |                       |                       |                                       |
|-----------------------|-----------------------|-----------------------|---------------------------------------|
| <a href="#">29636</a> | <a href="#">41052</a> | Running Repair        | KL - WORK LIGHT REPAIRS               |
| <a href="#">29636</a> | <a href="#">40987</a> | Running Repair        | KL - OUTGOING INSPETION               |
| <a href="#">6241</a>  | <a href="#">7451</a>  | BIS - Pending Closure | CEN- EMISSION CODES                   |
| <a href="#">59324</a> | <a href="#">77704</a> | BIS - Pending Closure | BAS - T/S EMISSIONS CODES             |
| <a href="#">8151</a>  | <a href="#">10503</a> | BIS - Pending Closure | CEN - SEATBELT EXPIRED                |
| <a href="#">8151</a>  | <a href="#">10507</a> | BIS - Pending Closure | CEN - 3 BROKEN CAB LOUVERS            |
| <a href="#">8151</a>  | <a href="#">11248</a> | BIS - Pending Closure | CEN - INSTALLED WASHER TANK           |
| <a href="#">8151</a>  | <a href="#">10499</a> | BIS - Pending Closure | CEN - GEAR SELECTOR BROKEN            |
| <a href="#">8151</a>  | <a href="#">10498</a> | BIS - Pending Closure | CEN - FRONT TOW HOOKS BENT            |
| <a href="#">8151</a>  | <a href="#">10505</a> | BIS - Pending Closure | CEN - WINDSHEILD CRACKED              |
| <a href="#">8151</a>  | <a href="#">10496</a> | BIS - Pending Closure | CEN - NEEDS FIRE EXT                  |
| <a href="#">8151</a>  | <a href="#">10504</a> | Running Repair        | CEN - DEF DRAIN DOOR BENT             |
| <a href="#">8151</a>  | <a href="#">10508</a> | Running Repair        | CEN - LF STEP BENT                    |
| <a href="#">8151</a>  | <a href="#">10506</a> | Running Repair        | CEN - REAR WINDOW WASHER FLUID N...   |
| <a href="#">8151</a>  | <a href="#">10502</a> | Running Repair        | CEN - LOOSE BOLTS FOR FAN MOTOR CO... |
| <a href="#">8151</a>  | <a href="#">10497</a> | Running Repair        | CEN - LH BOX LIGHT HOUSING DENTED     |
| <a href="#">8151</a>  | <a href="#">10509</a> | BIS - Pending Closure | CEN - VALVE CAPS MISSING              |
| <a href="#">8151</a>  | <a href="#">11793</a> | BIS - Pending Closure | CEN - CHECK TIRE PRESSURE             |
| <a href="#">8151</a>  | <a href="#">10500</a> | Running Repair        | CEN - ENGINE OIL DIPSTICK CRACKED     |
| <a href="#">8151</a>  | <a href="#">11320</a> | Running Repair        | CEN - REPLACED INDICATOR              |
| <a href="#">8151</a>  | <a href="#">10495</a> | BIS - Pending Closure | CEN - STEERING CYL ROD END BUSHINGS   |
| <a href="#">8151</a>  | <a href="#">10501</a> | Running Repair        | CEN - LH HOIST CYL LEAKING            |
| <a href="#">8151</a>  | <a href="#">10474</a> | BIS - Pending Closure | CEN - INCOMING INSPECTION             |



|                              |                              |                             |                                    |
|------------------------------|------------------------------|-----------------------------|------------------------------------|
| <a href="#"><u>13626</u></a> | <a href="#"><u>19314</u></a> | Breakdown / Emergency       | CEN - BLOWN BRAKE COOLING HOSE     |
| <a href="#"><u>21663</u></a> | <a href="#"><u>31333</u></a> | Running Repair              | ML - REPAIR LIGHTS                 |
| <a href="#"><u>21113</u></a> | <a href="#"><u>30565</u></a> | Running Repair              | ML - TIRE DRAG REPAIRS             |
| <a href="#"><u>2713</u></a>  | <a href="#"><u>3200</u></a>  | Preventative Maintenance... | 250 HR PM Service                  |
| <a href="#"><u>30290</u></a> | <a href="#"><u>41762</u></a> | Running Repair              | ML - 2-WAY RADIO ISSUES            |
| <a href="#"><u>2603</u></a>  | <a href="#"><u>3085</u></a>  | Preventative Maintenance... | 250 HR PM Service                  |
| <a href="#"><u>44418</u></a> | <a href="#"><u>60029</u></a> | Running Repair              | CEN - WASH UNIT                    |
| <a href="#"><u>44418</u></a> | <a href="#"><u>60028</u></a> | Running Repair              | CEN - MUDFLAP WORN                 |
| <a href="#"><u>44418</u></a> | <a href="#"><u>60095</u></a> | Running Repair              | CEN - T/S LIGHTS                   |
| <a href="#"><u>44418</u></a> | <a href="#"><u>60004</u></a> | Running Repair              | CEN - INCOMING INSPECTION          |
| <a href="#"><u>8592</u></a>  | <a href="#"><u>11206</u></a> | BIS - Pending Closure       | CEN - PARK BRAKE NOT TAKING GREASE |
| <a href="#"><u>22262</u></a> | <a href="#"><u>32127</u></a> | Running Repair              | ML - BURNT WORK LIGHTS             |
| <a href="#"><u>45505</u></a> | <a href="#"><u>61338</u></a> | Running Repair              | CEN - REPLACE BOX SAFETY PIN       |
| <a href="#"><u>21347</u></a> | <a href="#"><u>30746</u></a> | Preventative Maintenance... | 250 HR PM Service                  |
| <a href="#"><u>53151</u></a> | <a href="#"><u>70446</u></a> | BIS - Pending Closure       | CEN - REPAIR BEACON LIGHT MOUNT    |
| <a href="#"><u>53151</u></a> | <a href="#"><u>70445</u></a> | BIS - Pending Closure       | CEN - REPAIR LIGHT                 |
| <a href="#"><u>53151</u></a> | <a href="#"><u>70357</u></a> | Running Repair              | CEN - OUTGOING INSPECTION          |
| <a href="#"><u>50361</u></a> | <a href="#"><u>67249</u></a> | BIS - Pending Closure       | CEN - LOW BEAM LIGHTS NOT WORKING  |
| <a href="#"><u>30104</u></a> | <a href="#"><u>41517</u></a> | Running Repair              | ML - T/S HYD LEAK                  |
| <a href="#"><u>13976</u></a> | <a href="#"><u>19934</u></a> | Running Repair              | CEN - REPLACE REAR AXLE ORING      |
| <a href="#"><u>16484</u></a> | <a href="#"><u>23644</u></a> | Preventative Maintenance... | 250 HR PM Service                  |
| <a href="#"><u>58861</u></a> | <a href="#"><u>77108</u></a> | BIS - Pending Closure       | BAS - BLOWN ALT BELT               |
| <a href="#"><u>27965</u></a> | <a href="#"><u>39046</u></a> | Preventative Maintenance... | 250 HR PM Service                  |

|                       |                       |                             |                                       |
|-----------------------|-----------------------|-----------------------------|---------------------------------------|
| <a href="#">22366</a> | <a href="#">32224</a> | Running Repair              | ML - STEERING COLUMN WONT ADJUST      |
| <a href="#">45251</a> | <a href="#">61045</a> | Monitor                     | CEN - T/S BURNING SMELL IN CAB        |
| <a href="#">16448</a> | <a href="#">23587</a> | Running Repair              | CEN - WASHER MOTOR REPAIRS            |
| <a href="#">2426</a>  | <a href="#">2891</a>  | BIS - Pending Closure       | BAS - L04 Codes                       |
| <a href="#">18737</a> | <a href="#">26990</a> | Running Repair              | ML - LIGHT REPAIRS                    |
| <a href="#">7026</a>  | <a href="#">7239</a>  | Preventative Maintenance... | 250 HR PM Service                     |
| <a href="#">39786</a> | <a href="#">54370</a> | BIS - Pending Closure       | CEN - STRAIGHTEN STEPS                |
| <a href="#">20011</a> | <a href="#">29008</a> | Running Repair              | ML - TIRE DRAG INSTALL                |
| <a href="#">55208</a> | <a href="#">72875</a> | Preventative Maintenance... | 250 HR PM Service                     |
| <a href="#">45492</a> | <a href="#">61325</a> | Breakdown / Emergency       | CEN - T/S PARK BRAKE DRAGGING         |
| <a href="#">54322</a> | <a href="#">71782</a> | Running Repair              | BAS - REPLACE HEADLIGHT               |
| <a href="#">18026</a> | <a href="#">25958</a> | Running Repair              | CEN - TOP ALL FLUIDS                  |
| <a href="#">18026</a> | <a href="#">25890</a> | Running Repair              | CEN - POSITIVE AIR SHUT OFF NOT WO... |
| <a href="#">18026</a> | <a href="#">25884</a> | Running Repair              | CEN - OUTGOING INSPECTION             |
| <a href="#">1091</a>  | <a href="#">1114</a>  | Preventative Maintenance... | 2000 HR PM Service                    |
| <a href="#">8828</a>  | <a href="#">11675</a> | BIS - Pending Closure       | BAS - INSTALL GREASE WHIPS            |
| <a href="#">11000</a> | <a href="#">15301</a> | Running Repair              | CEN - PINION SEAL LEAK                |
| <a href="#">48057</a> | <a href="#">64567</a> | Running Repair              | CEN - WHEEL CHECKS                    |
| <a href="#">23076</a> | <a href="#">33144</a> | Running Repair              | ML - REPLACE 2 WAY MIC                |
| <a href="#">63092</a> | <a href="#">81929</a> | Running Repair              | BAS - RPL MISSING ENG COVER           |
| <a href="#">9108</a>  | <a href="#">12146</a> | BIS - Pending Closure       | CEN- CODES AND ALARM                  |
| <a href="#">20237</a> | <a href="#">29454</a> | Running Repair              | ML - RETORQUE RF WHEEL                |
| <a href="#">49226</a> | <a href="#">65995</a> | Running Repair              | CEN - T/S - RPR SCR CODES             |



|                       |                       |                             |                                        |
|-----------------------|-----------------------|-----------------------------|----------------------------------------|
| <a href="#">62645</a> | <a href="#">81425</a> | Preventative Maintenance... | 1000 HR PM Service                     |
| <a href="#">2946</a>  | <a href="#">3494</a>  | BIS - Pending Closure       | NEEDS BATTERIES/FUEL SHUT OFF SOLE...  |
| <a href="#">27022</a> | <a href="#">37869</a> | Running Repair              | KL- REPLACE RH FOG AND LH LOW BEAM     |
| <a href="#">21309</a> | <a href="#">30867</a> | Running Repair              | ML - TIRE DRAG CABLE REPLACEMENT       |
| <a href="#">13490</a> | <a href="#">19079</a> | Running Repair              | CEN - REPAIR RUBBER FENDER FLARE       |
| <a href="#">26683</a> | <a href="#">37457</a> | BIS - Pending Closure       | KL - PERFORM REGEN                     |
| <a href="#">22200</a> | <a href="#">32054</a> | Running Repair              | ML - REPLACE LEFT LOW BEAM HEADLIG...  |
| <a href="#">24961</a> | <a href="#">34404</a> | Preventative Maintenance... | 250 HR PM Service                      |
| <a href="#">57803</a> | <a href="#">75948</a> | Running Repair              | BAS - LIGHT REPAIRS                    |
| <a href="#">10952</a> | <a href="#">15244</a> | Preventative Maintenance... | CEN - 500HR SERVICE                    |
| <a href="#">14975</a> | <a href="#">21432</a> | Running Repair              | CEN - DRIVELINE INSPECTION             |
| <a href="#">10487</a> | <a href="#">14420</a> | Breakdown / Emergency       | CEN - REAR WHEEL SEAL LEAK             |
| <a href="#">63093</a> | <a href="#">81930</a> | BIS - Pending Closure       | BAS - T/S GREASING ISSUES              |
| <a href="#">2706</a>  | <a href="#">3193</a>  | BIS - Pending Closure       | BAS - GENERAL INSPECTION               |
| <a href="#">42724</a> | <a href="#">57905</a> | Running Repair              | BR - T/S EMISSIONS ISSUES              |
| <a href="#">3082</a>  | <a href="#">3700</a>  | Running Repair              | L03 CODE                               |
| <a href="#">27843</a> | <a href="#">38897</a> | Running Repair              | KL - OUTGOING INSPECTION               |
| <a href="#">52312</a> | <a href="#">69439</a> | BIS - Pending Closure       | CEN - T/S SCR FAULT CODES              |
| <a href="#">60363</a> | <a href="#">78915</a> | BIS - Pending Closure       | BAS - REPLACE WIPER                    |
| <a href="#">26534</a> | <a href="#">37286</a> | BIS - Pending Closure       | KL - INSPECTION                        |
| <a href="#">42445</a> | <a href="#">57568</a> | BIS - Pending Closure       | BR - PM ASSESSMENT                     |
| <a href="#">7681</a>  | <a href="#">9666</a>  | BIS - Pending Closure       | CEN - PM ASSESSMENT                    |
| <a href="#">52125</a> | <a href="#">69222</a> | Preventative Maintenance... | CEN - 2000HR PM                        |
| <a href="#">49195</a> | <a href="#">65962</a> | BIS - Pending Closure       | CEN - REPAIR COOLANT LEAK              |
| <a href="#">19577</a> | <a href="#">28230</a> | Breakdown / Emergency       | ML - REPLACE FAILING FRONT & REAR U... |
| <a href="#">64642</a> | <a href="#">83688</a> | Running Repair              | POP - REPLACE TIRES                    |
| <a href="#">23492</a> | <a href="#">33677</a> | BIS - Pending Closure       | ML - T/S REGEN CODE                    |
| <a href="#">22203</a> | <a href="#">32057</a> | Running Repair              | ML - INSTALL TIRE DRAG                 |
| <a href="#">46990</a> | <a href="#">63235</a> | Running Repair              | CEN - SEATBELT REPLACEMENT             |
| <a href="#">9511</a>  | <a href="#">12809</a> | Preventative Maintenance... | TIRE INSPECTIONS                       |



## PARTS INVOICE

SMS EQUIPMENT INC.  
22K HIGHWAY 63 NORTH  
FORT MCMURRAY AB T9H 3G2  
TEL: +1-780-714-5300  
SMS CONTACT: AMANDA BOYD

INVOICE # : PSI/71416909  
INVOICE DATE : 2024-Jan-14  
CUSTOMER PO : 143392  
ORDER # : S45171692  
ORDER DATE : 2024-Jan-13  
SHIP DATE : 2024-Jan-13  
PAYMENT TERMS : NET 30 DAYS  
DELIVERY TERMS : FOB

BILL TO: C00011241  
MORGAN CONSTRUCTION &  
ENVIRONMENTAL LTD.  
4TH FLOOR, 16901 - 109 AVENUE  
EDMONTON AB T5P 4P6

SHIP TO:  
MORGAN CONSTRUCTION &  
ZONE 6  
AB

|                        |                            |
|------------------------|----------------------------|
| Manufacturer : KOMATSU | Customer Unit No : 01-6360 |
| Model : HM400-5        | Meter Reading : 11347.6    |
| Serial Number : 11519  | SMS Unit No : MD0035520    |

| DESCRIPTION                                       | ORDER QTY | B/O | INV QTY | UNIT PRICE | EXT AMT  |
|---------------------------------------------------|-----------|-----|---------|------------|----------|
| Unit 01-6360 WO 23492 Zone 6<br>BOL 89375 C235038 |           |     |         |            |          |
| KO 01010-E1235 BOLT                               | 4         | 0   | 4       | 7.00       | 28.00    |
| KO 01020-11235 BOLT                               | 4         | 0   | 4       | 45.55      | 182.20   |
| KO 01643-31232 WASHER                             | 4         | 0   | 4       | 1.48       | 5.92     |
| KO 07005-01212 SEAL                               | 4         | *   | 0       | 4.21       | 16.84    |
| KO 07005-01412 SEAL                               | 16        | *   | 0       | 6.02       | 96.32    |
| KO 07281-00197 CLAMP                              | 6         | 0   | 6       | 3.71       | 22.26    |
| KO 07281-00359 CLAMP                              | 8         | 0   | 8       | 4.45       | 35.60    |
| KO 182088H1 CLAMP-HOSE,SIZE                       | 2         | 0   | 2       | 10.79      | 21.58    |
| KO 07299-00095 CLAMP                              | 2         | 0   | 2       | 65.54      | 131.08   |
| KO 569-02-82180 CLAMP                             | 2         | 0   | 2       | 20.85      | 41.70    |
| KO 22B-46-24380 WASHER                            | 4         | 0   | 4       | 19.54      | 78.16    |
| KO 56B-02-51420 COVER                             | 1         | 0   | 1       | 2,594.65   | 2,594.65 |
| KO 56B-02-52111 HOSE                              | 1         | *   | 0       | 578.71     | 578.71   |
| KO 6138-13-4510 BOLT                              | 4         | 0   | 4       | 36.77      | 147.08   |
| KO 6151-51-8721 GASKET                            | 1         | *   | 0       | 5.22       | 5.22     |
| KO 6155-11-4420 HOSE                              | 1         | *   | 0       | 170.37     | 170.37   |
| KO 6212-11-5940 GASKET                            | 1         | *   | 0       | 159.06     | 159.06   |
| KO 6221-51-8160 GASKET                            | 2         | *   | 0       | 3.62       | 7.24     |
| KO 6252-21-7160 HOSE                              | 3         | *   | 0       | 87.62      | 262.86   |
| KO 6252-21-7290 GASKET                            | 1         | *   | 0       | 12.66      | 12.66    |
| KO 6252-61-6270 O-RING                            | 2         | *   | 0       | 22.57      | 45.14    |
| KO 6261-11-5850 GASKET                            | 1         | *   | 0       | 45.89      | 45.89    |
| KO 6262-11-5470 SEAL RING                         | 1         | *   | 0       | 535.73     | 535.73   |
| KO 6262-11-5480 SEAL                              | 1         | *   | 0       | 251.05     | 251.05   |
| KO 6262-11-5491 GASKET                            | 2         | *   | 0       | 40.72      | 81.44    |
| KO 6262-11-6860 HOSE                              | 1         | *   | 0       | 55.76      | 55.76    |
| KO 6520-71-1050 ISOLATOR                          | 1         | 0   | 1       | 27.02      | 27.02    |
| KO 6520-71-1070 GASKET                            | 1         | *   | 0       | 90.64      | 90.64    |

\* Non Returnable

GST/TPS 89548 3022



## PARTS INVOICE

SMS EQUIPMENT INC.  
22K HIGHWAY 63 NORTH  
FORT MCMURRAY AB T9H 3G2  
TEL: +1-780-714-5300  
SMS CONTACT: AMANDA BOYD

INVOICE # : PSI/71416909  
INVOICE DATE : 2024-Jan-14  
CUSTOMER PO : 143392  
ORDER # : S45171692  
ORDER DATE : 2024-Jan-13  
SHIP DATE : 2024-Jan-13  
PAYMENT TERMS : NET 30 DAYS  
DELIVERY TERMS : FOB

| DESCRIPTION                                       | ORDER QTY | B/O | INV QTY | UNIT PRICE | EXT AMT   |
|---------------------------------------------------|-----------|-----|---------|------------|-----------|
| Unit 01-6360 WO 23492 Zone 6<br>BOL 89375 C235038 |           |     |         |            |           |
| KO R6508-12-5010 TURBOCHARGER                     | 1         | 0   | 1       | 10,378.85  | 13,458.79 |
| CORE                                              |           |     |         | 3,079.94   |           |
| KO 6252-21-7670 HOSE                              |           | 1   |         |            |           |
| KO 6262-11-5410 RING                              |           | 1   |         |            |           |
| KO 6262-11-5970 BOLT                              |           | 4   |         |            |           |
| KO 6262-11-6870 HOSE                              |           | 1   |         |            |           |
| KO 6262-11-8430 COVER                             |           | 1   |         |            |           |
| KO 6520-71-1060 BOLT                              |           | 2   |         |            |           |

THANK YOU FOR YOUR BUSINESS!

REMIT PAYMENT TO:

SUBTOTAL 19,188.97

VIA REGULAR MAIL:

or

VIA COURIER:

GST/TPS 959.45

Indicate this address on the waybill

SMS EQUIPMENT INC.  
C/O CX2572C (CAD PAYMENT)  
OR CX2572U (USD PAYMENT)  
PO BOX 2591  
CALGARY, AB T2P 0A3

SYMCOR WHOLESALE LOCKBOX  
C/O CIBC LOCKBOX -  
C/O CX2572C (CAD PAYMENT)  
OR CX2572U (USD PAYMENT)  
SMS EQUIPMENT INC.  
3663 63RD AVE NE  
CALGARY, AB T3J 0G6

TOTAL (CAD) 20,148.42

\* Non Returnable

GST/TPS 89548 3022





## PARTS INVOICE

SMS EQUIPMENT INC.  
22K HIGHWAY 63 NORTH  
FORT MCMURRAY AB T9H 3G2  
TEL: +1-780-714-5300  
SMS CONTACT: AMANDA BOYD

INVOICE # : PSI/71401053  
INVOICE DATE : 2023-Nov-19  
CUSTOMER PO : 139714  
ORDER # : S45169259  
ORDER DATE : 2023-Nov-19  
SHIP DATE : 2023-Nov-19  
PAYMENT TERMS : NET 30 DAYS  
DELIVERY TERMS : FOB

BILL TO: C00011241  
MORGAN CONSTRUCTION &  
ENVIRONMENTAL LTD.  
17303 - 102 AVENUE  
EDMONTON AB T6S 1J8

SHIP TO:  
MORGAN CONSTRUCTION &  
ZONE 15  
AB BLACK ROD

| DESCRIPTION                                            | ORDER QTY | B/O | INV QTY | UNIT PRICE | EXT AMT  |
|--------------------------------------------------------|-----------|-----|---------|------------|----------|
| Unit 01-6360 zone 15 Attn Richard<br>BOL 87514 C229929 |           |     |         |            |          |
| KO 56B-20-31110 SPIDER ASS'Y                           | 2         | 0   | 2       | 982.84     | 1,965.68 |
| KO 423-20-32750 FITTING                                | 4         | 0   | 4       | 28.89      | 115.56   |
| KO 56B-20-32110 SPIDER ASS'Y                           | 2         | 0   | 2       | 776.62     | 1,553.24 |
| KO 56B-20-32130 FITTING                                | 4         | 0   | 4       | 21.23      | 84.92    |
| KO 566-20-41220 BOLT                                   | 21        | 4   | 17      | 38.79      | 659.43   |
| Old Replaced Part: 421-20-12690                        |           |     | KO      |            |          |
| KO 01050-61260 BOLT                                    | 24        | 0   | 24      | 10.32      | 247.68   |
| KO 56B-20-15100 SPIDER                                 | 1         | 0   | 1       | 626.10     | 626.10   |
| Old Replaced Part: 56B-20-35110                        |           |     | KO      |            |          |
| KO 56C-27-19591 SEAL                                   | 1         | *   | 0       | 246.60     | 246.60   |
| KO 421-20-33621 SPIDER<br>ASS'Y                        |           | 1   |         |            |          |
| KO 56B-27-32410 SHAFT                                  |           | 1   |         |            |          |
| KO 566-20-41220 BOLT                                   |           | 3   |         |            |          |

THANK YOU FOR YOUR BUSINESS!

|                   |    |              |                |
|-------------------|----|--------------|----------------|
| REMIT PAYMENT TO: |    | SUBTOTAL     | 5,499.21       |
| VIA REGULAR MAIL: | or | VIA COURIER: | GST/TPS 274.96 |

Indicate this address on the waybill

SMS EQUIPMENT INC.  
C/O CX2572C (CAD PAYMENT)  
OR CX2572U (USD PAYMENT)  
PO BOX 2591  
CALGARY, AB T2P 0A3

SYMCOR WHOLESALE LOCKBOX  
C/O CIBC LOCKBOX -  
C/O CX2572C (CAD PAYMENT)  
OR CX2572U (USD PAYMENT)  
SMS EQUIPMENT INC.  
3663 63RD AVE NE  
CALGARY, AB T3J 0G6

TOTAL (CAD) 5,774.17

\* Non Returnable

GST/TPS 89548 3022



## PARTS INVOICE

SMS EQUIPMENT INC.  
22K HIGHWAY 63 NORTH  
FORT MCMURRAY AB T9H 3G2  
TEL: +1-780-714-5300  
SMS CONTACT: RAPHAEL MURPHY

INVOICE # : PSI/71320137  
INVOICE DATE : 2023-Mar-07  
CUSTOMER PO : 125688  
ORDER # : S45156580  
ORDER DATE : 2023-Mar-02  
SHIP DATE : 2023-Mar-02  
PAYMENT TERMS : NET 30 DAYS  
DELIVERY TERMS : FOB

**BILL TO: C00011241**  
MORGAN CONSTRUCTION &  
ENVIRONMENTAL LTD.  
17303 - 102 AVENUE  
EDMONTON AB T6S 1J8

**SHIP TO:**  
MORGAN CONSTRUCTION &  
ZONE 7  
FORT MCMURRAY AB

| DESCRIPTION                                                  | ORDER QTY | B/O | INV QTY | UNIT PRICE | EXT AMT  |
|--------------------------------------------------------------|-----------|-----|---------|------------|----------|
| ZONE 7<br>UNIT 01-6360<br>ATTN ALEX<br><br>BOL 77987 C202221 |           |     |         |            |          |
| KO 6540-71-2510 PUMP ASS'Y                                   | 1         | 0   | 1       | 3,009.51   | 3,009.51 |
| ZZ EFI FREIGHT FREIGHT                                       | 1         | 0   | 1       | 100.00     | 100.00   |

THANK YOU FOR YOUR BUSINESS!

REMIT PAYMENT TO:

SUBTOTAL

3,109.51

VIA REGULAR MAIL:

or

VIA COURIER:

GST/TPS

155.48

Indicate this address on the waybill

SMS EQUIPMENT INC.  
C/O CX2572C (CAD PAYMENT)  
OR CX2572U (USD PAYMENT)  
PO BOX 2591  
CALGARY, AB T2P 0A3

SYMCOR WHOLESALE LOCKBOX  
C/O CIBC LOCKBOX -  
C/O CX2572C (CAD PAYMENT)  
OR CX2572U (USD PAYMENT)  
SMS EQUIPMENT INC.  
3663 63RD AVE NE  
CALGARY, AB T3J 0G6

**TOTAL (CAD)**

3,264.99

\* Non Returnable

GST/TPS 89548 3022