

JBS Mechanical Inc
Box 353
Whitecourt, AB T7S 1N5

jbsmechanical.service@gmail.com

GST/HST No. 828463240

Invoice



JBS Mechanical Inc.
1-780-779-6759

K20-9

Invoice #	Date
30431	5/21/2023

P.O. No.	Terms
	Net 30

Invoice To

NEWGEN ENERGY SERVICES

Location	Work Order #	Make/Model	Unit Number
ST-13	6716		204L

Item	Description of Item	Bin	Qty	Rate	Area	Amount
CVIP Trailer ...	CVIP - 3 Axle		1	210.00		210.00
Regular Time	Inspection and repair axle 2 r/h brake pot not releasing remove and replace clevis axle 1 l/h inside tire fails, 5th wheel jaws seized, remove 5th wheel and get free, axle 1,2,3 wheel seals, remove and replace, remove and replace 5th wheel bushings		11	150.00		1,650.00
KP10605	HOLL. ILS PIN & BUSHING KIT	PR 5 C	1	67.70		67.70
46300	TRAILER WHEEL SEAL	S 10 D	6	52.95		317.70
330-3009	OIL HUB CAP GASKET 3009	End 1	6	2.85		17.10
75W901LJ	75W90 SYNTHETIC OIL 1L JUG	PR 6 FL...	6	19.80		118.80
FS-5082A	CLEVIS ASSY 5/8-1/2 PIN	S 12 A	1	3.60		3.60
Shop Supplies	8% of Base Labour		12	12.00		144.00

If we have had your wheels off re-tourque within 100 km's.

Flat rate charges may be subjected to a 75% increase for siezed or aftermarket parts.
A 25% increase in flat rate labor charge may occur due to excessive mud or snow on
units.

Parts warranty subject to manufactures approval.

If customer does not request old parts back they will be disposed of by JBS
Mechanical.

No return on electrical components or special order parts.

UNAUTHORIZED ENGINE MODIFICATIONS OR DPF DELETES DO NOT
QUALIFY FOR WARRANTY

Subtotal \$2,528.90

GST/HST \$126.45

Total \$2,655.35

Payment \$0.00

Balance Due \$2,655.35

NEW GEN

ENERGY SERVICES CORP

139

Date: May 4 2023	Hours: —	Requested by: Mario Gtz
Unit #: DL-204	KMs: —	

What issues were found?

- Service

Describe what repairs were completed

- Adjust Brakes

- Grease

- Look for cracks (All good)

- Top up Gear oil in hubs.

- cleaned Electrical Plugs on
Lead and Pup.

Completed by: Mario

Date: May 4 23

Management Signature:

