10 October, 2025 1:26 PM

Tryson Energy Services Inc Work Order History Report

Page 1

Equipment: 09-501

Work Order#	Invoice#	Completed Date		Name	Total Labor	Total Parts	Total Returns	Total Sublet	Shop Supplies	Tax Total	Total	Cur.
1103		06/Dec/24	09-501		750.00	.00.	.00	.00	.00	.00	750.00	CAD
1113		12/Nov/24	09-501		100,00	.00	.00	.00	.00	.00	100.00	CAD
1169		12/Dec/24	09-501		2,250,00	1,173.88	-924,00	8,118,71	.00	.00	10.618.59	CAD
1220		13/Dec/24	09-501		450.00	298.32	.00.	.00	.00	.00	748,32	
1262		15/Jan/25	09-501		1,800.00	997.63	.00	.00.	.00.	.00	2,797.63	
1267		13/Dec/24	09-501		.00	1,423.37	.00	.00.	.00	.00	1,423.37	
1339		10/Jan/25	09-501		900.00	260.41	.00	.00.	.00	.00	1,160,41	
1362		17/Jan/25	09-501		400.00	.00	.00	202.65	.00	.00	602.65	
1422		09/Feb/25	09-501		300.00	1,552,23	.00	.00	.00	.00	1,852,23	
1533		08/Mar/25	09-501		750.00	260,70	.00	6,270.00	.00.	.00	7,280,70	
1559		06/Mar/25	09-501		1,650,00	283.08	.00.	.00	.00.	.00	1,933.08	
1640		18/Mar/25	09-501		.00	.00	.00.	86.55	.00	.00	88.55	
1660		07/Apr/25	09-501		440,00	304.13	.00	35.86	.00	,00	780,09	
1777		01/May/25	09-501		850,00	45.95	.00	.00	.00	.00	995.95	
1817		08/May/25	09-501		955.00	1,096.95	.00	.00	.00.	.00	2,051.95	
1932		20/Jun/25	09-501		100.00	.00.	.00	.00	.00.	.00	100.00	
1980		19/Jun/25	09-501		600.00	121.58	.00.	.00.	.00	.00	721.58	
2075		21/Aug/25	09-501		160.00	4,472,53	.00	2,937.02	.00	.00	7,509.55	
2106		19/Aug/25	09-501		680.00	1,035.26	.00	.00	.00.	.00	1,715.26	
2258		•	09-501		.00	.00.	.00	.00	.00.	.00	.,, 10.20	
2320			09-501		1,260,00	.00,	.00	.00	.00	.00,	1,260.00	
					14,435,00	13,326.02	-924.00	17,650.89	.00	.00	44,487,91	CAD

Now - 38,862 hours - 1,273,263 km

December 2024 - New Turbo - 36894 hrs

March 2024 - New air to air - 34870 hrs

Dec 2023 - Rebuilt auxiliary - 34175 hrs

April 2023 Engine and OEM harness - 32469 hrs

Tryson Energy Services Inc Work Order History Report

Equipment: 09-501

Category		Description		Mechanic	Actual Hours	Quantity/Hours	Price/Rate	Amount	Cur
Work Order #: 1	103	Invoice#:	Complete	d Date: 06/Dec/24		eter: 1,207,382		r As Of: 05/Nov g As Of: 05/Nov	
Labor	_					30,713 11	ours reading	1 AS OI. 03/1909	1124
014	Frame gin pole	incl tool boxes, 5th wheel, mud t es	flaps, deck,	ALLEN	1,00	1.00	100.00	100,00	l
014	Frame gin pole	incl tool boxes, 5th wheel, mud t es	îlaps, deck,	PETE	3.00	3.00	100.00	300.00	ļ
200	PM.			CLAUDE	3.50	3.50	100.00	350.00	<i>i</i>
Work Descripti Leave open un		contractor November ti	me is ent	ered	7.50	7.50	Total Labor	750.00	
Engine service	due w	ith oil filter only.							
Claude									
Nov 5 2024									
Travel to Step,	Help g	et 5th wheel unlatched	l .						
Back at shop - pin.	get 5th	ı wheel release lever ba	ack in pla	ce and install no	ew cotter				
Allen - Nov 13	2024								
36,803 hrs I 210 283 KM	- Nov 1	3							
SERVICE DON	IE BEF	ORE INVENTORY WA	S ENTER	RED					
							Total .	750.00	CAE
Work Order #: 11	13	Invoice#:	Completed	i Date: 12/Nov/24		eter: 1,208,633		r As Of: 08/Nov g As Of: 08/Nov	
-abor 122	Differen	tial		JOSH	1.00	1.00	100.00	100.00	
	J			50311	1.00	1.00	Total Labor	100.00	•
Work Descriptic Oriver side rea		asket leaking.			1.00	1.50	iotal Essoi	100.00	
losh changed i	n the v	vash bay							
Nov 8 2024									
							Total	100.00	CAE
Vork Order #: 11	69	Invoice#:	Completed	l Date: 12/Dec/24	09-501 Odomo Hours:	eter: 1,213,283		r As Of: 21/Nov I As Of: 21/Nov	
.abor 45	ECM	d angine electricat				•		•	
32	Starting	d engine electrical		JOSH CLAUDE	2.00 4.50	2.00 4.50	100.00 100.00	200.00 450.00	
41 00		e incl turbo r fabrication		CLAUDE ALLEN	3.50 1.00	3.50 1.00	100.00 100.00	350.00 100.00	
00	PM .			GRAHAM	1,00	1.00	100.00	100.00	

Tryson Energy Services Inc Work Order History Report

Equipment: 09-501

Category	Description	Mechanic	Actual Hours	Quantity/Hours	Price/Rate	Amount	Cur.
			22.50	22.50	Total Labor	2,250.00	
Parts	BSGA31S, BATTERYS DW1707, WINDSHIELD 5495621RXCUM, TURBOCHARGER		.00. 00. 00.	2.00 1.00 1.00	109.95 29,98 924,00	219.90 29.98 924.00	
					Total Parts	1,173.88	
Returns	5495621RXCUM - Used Core, TURBOCHARGER - Used Core		.00	-1.00	924.00	-924.00	
					Total Returns	-924,00	
Sublet	06AP308651 / Edmonton Kenworth Ltd. CM405496A / Glover Trucks PR2200255 / Greatwest Kenworth LTD PR22500323 / Greatwest Kenworth LTD 46099W / Wolf Transport Ltd		.00. 00. 00. 00.	1.00 1.00 1.00	7,798.82 -51.76 170.15 122.78 78.72	7,798.82 -51.76 170.15 122.78 78.72	
	•				Total Sublet	8,118.71	

Work Description

Leave open until Subcontractor November time is entered

Smell of rotten eggs -- Claude checked-batteries and ended-up changing the front

Asked Josh to change intake manifold sensor.

Evidence of oil coming through the intake side - Probably turbo

Nov 21, 2024 - Josh and Claude

Install new Turbo - Claude - Nov 22,2024

Went to work Nov 25 - morning - stuttered a couple of times

Checking electrical

Graham cleaned alot of power and ground connections and cleared codes.

Norm took it out and it has acted ok since

Nov 26, 2024 - 1,215,037 km - 36,904 hours

					Total	10,618.59 CA	AD
Work Order #	t: 1220 Invoice#:	Completed Date: 13/Dec/24	4 09-501 Odometer Hours:		• • • • • • • • • • • • • • • • • • • •	ns Of: 06/Dec/24 ns Of: 06/Dec/24	
Labor 200	РМ	CLAUDE	4.50	4.50	100.00	450.00 450.00	
Parts	LF14000, OIL FILTER FS1000, FUEL FILTER FF2200, FUEL FILTER 77E0850, OIL SAMPLES		.00 .00 .00 .00	1.00 1.00 1.00 1.00 45.00	46.24 16.93 22.95 25.00 4.16	46.24 16.93 22.95 25.00 187.20	
	15w40, OIL		.00	49.00	Total Parts	298.32	

Work Description

Page 3

Tryson Energy Services Inc Work Order History Report

Equipment: 09-501

Actual Category Description Mechanic Hours Quantity/Hours Price/Rate Amount Cur.

Leave open until December sub contractor time is entered

Service due with oil and fuel filters.

Oil and filter done at 36,715 hours

Claude did Dec 6 2024

Dec 13 2024 - completing so parts will update - needs labour updated

Total 748.32 CAD

Work Order #: 1262 Invoice#: Completed Date: 15/Jan/25 09-501

Odometer: 1,222,539 Odometer As Of: 31/Dec/24 Hours: 37,228 Hours Reading As Of: 31/Dec/24 Labor 013 Brakes incl air system and valves SHELDON 1.00 1,00 100.00 100.00 013 Brakes incl air system and valves 8.50 100.00 JOSH 8.50 850.00 023 Clutch GRAHAM 8.50 8.50 100.00 850.00 18.00 18.00 Total Labor 1,800,00 **Parts** AF25247, AIR FILTER .00 2,00 73.01 146,02 170.K022105, PURGE VALVE 00. 00. 00. 00. 00. 00. 1.00 45.31 45.31 170,5008414, DRYER CARTRIDGE 28.47 7.99 29.27 1.00 28.47 LF3604, DIFF FILTER 15.98 HF6177, HYD FILTER 2.00 58,54 LF637, PWR STEER FILTER 1.00 16.76 16.76 4707, BRAKE SHOE CORE 47697, SEAL 3.00 46.00 138.00 5.00 51.95 43761. SEAL 1.00 46.24 46.24 330-3106, AXLE GSK .00 6.00 3.03 18.18 3050A, LIGHT .00 2.00 7.25 14.50 FR4707, BRAKE SHOE KIT 60 69.96 3.00 209.88 **Total Parts** 997.63

Work Description

WORK DONE DEC 31 - WAITING FOR LABOUR TO BE PUT ON

DEC CVIP DUE -

Replace all filters

Replace all 6 drive axle wheel seals and axle gaskets

Replace 3 sets of brake shoes on drive - both across the front axle and the PS middle

Move tires from the rear axle to the center axle

Steering tires were not removed - they had new shoes and drums last year and were inspected by removing the covers only.

Sticker 8311963 was put on unit

Work was done Dec 31 - Josh, Graham, Roger

Total 2,797.63 CAD

Work Order #: 1267

Invoice#:

Completed Date: 13/Dec/24 09-501

602,65 CAD

Total

10 October, 2025 9:09 AM

Tryson Energy Services Inc Work Order History Report

Equipment: 09-501

Category	Description	Mechanic	Actual Hours	Quantity/Hours	Price/Rate	Amount	Cur.
Parts	495375, TIRE CHAINS JW0551771, HEADLIGHT		.00. 00.	4.00 1.00	275.00 323.37	1,100.00 323.37	
Work Descripti PARTS ONLY					Total Parts	1,423.37	
					Total	1,423.37	CAD
Work Order #: 1	1339 Invoice#:	Completed Date: 10/Jan/25	09-50 Odom Hours:	eter: 1,222,53		r As Of: 31/Dec g As Of: 31/Dec	
Labor ²⁰⁰	РМ	ROGER	9.00		100.00 Total Labor	900.00	
Parts	LF14000, OIL FILTER 77E0850, OIL SAMPLES 15w40, OIL		9,00 00. 00.	1.00 1.00 45.00	46.24 26.97 4.16	46.24 26.97 187.20	
					Total Parts	260.41	

Work Description

WAITING FOR LABOUR TO BE ADDED BEFORE CLOSING

While doing CVIP, seen it is 15 hrs from service and there is a busy week ahead

Oil and fuel done at 36993

Change engine oil and filter - grease

Dec 31, 2024

					Total	1,160,41	CAD
Work Order #: 1	362 Invoice#:	Completed Date: 17/Jan/25	09-501 Odometer Hours:			As Of: 06/Jan/2 As Of: 06/Jan/2	
Labor 003	Cab - glass, mirrors, gauges, wipers	ALLEN	4.00	4.00	100.00	400.00	
	• • • • • • • • • • • • • • • • • • • •		4.00	4.00	Total Labor	400.00	
Sublet	PR2204345 / Greatwest Kenworth LT	TD OT	.00	1,00	202.65	202,65	
					Total Sublet	202,65	
Work Descripti	on indow regulator needs chan	ned					

Drivers door window regulator needs changed

Will not move even with power directly to it

Allen - Jan 6 2024

Work Order #	: 1422	Invoice#:	Completed Date: 09/Feb/25	09-501 Odomete ours:			s Of: 27/Jan/25 s Of: 27/Jan/25
Labor	PM		ROGER	3.00	3.00	100.00	300.00

Tryson Energy Services Inc Work Order History Report

Equipment: 09-501

Category	Description	Mechanic	Actual Hours	Quantity/Hours	Price/Rate	Amount (Cur.
Parts			3.00	3.00	Total Labor	300.00	
raits	LF14000, OIL FILTER		00	4.00	47 57	47.67	
	FF2200, FUEL FILTER		00. 00.	1.00 2.00	47.57 24.20	47.57 48.40	
	FS1000, FUEL FILTER		.00	1.00	18.18	18.18	
	77E0850, OIL SAMPLES		.00	1.00	26.97	26.97	
	15w40, OIL		.00	45,00	4.16	187,20	
	4050R, LIGHT		.00	1.00	21.31	21.31	
	94993, PIGTAIL		.00	1.00	2.60	2,60	
	464221, TIRE CHAINS		.00	4.00	300,00	1,200.00	
					Total Parts	1.552.23	

Work Description

Service due in 25 hrs with oil and fuel filters

Oil in at 37228 hrs

Used 2 of FS2200 - first one leaked after a day of driving

Roger Jan 27 2025

Total 1,852,23 CAD Work Order #: 1533 Invoice#: Completed Date: 06/Mar/25 09-501 Odometer: 1,234,733 Odometer As Of: 14/Feb/25 Hours: 37,682 Hours Reading As Of: 14/Feb/25 Labor 041 056 Air intake incl turbo ALLEN 3.00 3.00 100.00 300.00 PTO and hydraulics SHELDON CLAUDE 1.00 1.00 100.00 100.00 041 Air intake incl turbo 3.50 3.50 100.00 350.00 7.50 7.50 750.00 **Total Labor Parts** .00 .00 24.16 13.15 429-8220, STUD 2.00 48.32 52.60 21.06 24.24 498-5492, NUT 4.00 286-6636, GASKET .00 1.00 21.06 368-4355, GASKET 10028-6, V-BAND CLAMP .00 1.00 24.24 .00 3.00 38,16 114.48 **Total Parts** 260.70 **Sublet** 250206 / Ultimate Services Ltd 1.00 .00 6,270.00 6,270.00 **Total Sublet** 6,270.00

Work Description
Sub contractor

REPLACED TURBO - oil in exhaust

Next day the actuator on the new turbo acted up, so Allen put the actuator from the original turbo on it and calibrated it.

						Total	7,280.70 CAD
Work Order #: 1	559 Invoice#:	Completed	Date: 06/Mar/25	Odometer		•	As Of: 24/Feb/25 As Of: 24/Feb/25
Labor 200 200 014	PM PM Frame incl tool boxes, 5th whee gin poles	K	ALLEN KADE SHELDON	6.00 9.00 1.50	6.00 9.00 1.50	100.00 100.00 100.00 —— Total Labor	600.00 900.00 150.00

Tryson Energy Services Inc Work Order History Report

Equipment: 09-501

Category		Description	Mechanic	Actual Hours	Quantity/Hours	Price/Rate	Amount	Cur.
Parts	77E0850 15w40, 0	, CIL FILTER , OIL SAMPLES DIL X, STRAP KITS		.00. 00. 00.	1.00 1.00 45.00 1.00	47.57 26.97 4.16 21.34	47.57 26.97 187.20 21.34	
Work Description Service due	on					Total Parts	283.08	
Allen / Kade - F	Feb 24,	2025						
Tighten aux inp	put yoke	:						
						Total	1,933.08	CAD
Work Order #: 10	640	Invoice#:	Completed Date: 18/Mar/25	09-501				
Gubiet	9251340	9 / Kal Tire		.00	1.00	86.55	86.55	
Work Description Charges from I		 invoice 92513409 - :	\$86.55 - flat repair			Total Sublet	86.55	
						Total	86.55	CAE
Work Order #: 10	660	Invoice#:	Completed Date: 07/Apr/25		eter: 1,242,61		r As Of: 14/Mar g As Of: 14/Mar	
Labor 200	РМ	Invoice#:	•	Odom	eter: 1,242,61			
Labor		Invoice#:	BRODY	Odom Hours: 2.00	eter: 1,242,61 38,000 2.00	Hours Reading	As Of: 14/Mar 140.00	
Labor 200	PM PM LF14000 FF2200, FS1000,), OIL FILTER FUEL FILTER FUEL FILTER), OIL SAMPLES	BRODY	Odom Hours: 2.00 3.00	eter: 1,242,61 38,000 2.00 3.00	70.00 100.00 Total Labor 47.57 24.20 18.18 26.98 4.16	9 As Of: 14/Mar 140.00 300.00 440.00 47.57 24.20 18.18 26.98 187.20	·/25
Labor 200 200	PM PM LF14000 FF2200, FS1000, 77E0850 15w40, 0), OIL FILTER FUEL FILTER FUEL FILTER), OIL SAMPLES DIL	BRODY	Odom Hours: 2.00 3.00 5.00 .00 .00 .00	eter: 1,242,61 38,000 2.00 3.00 5.00 1.00 1.00 1.00	70.00 100.00 Total Labor 47.57 24.20 18.18 26.98	9 As Of: 14/Mar 140.00 300.00 440.00 47.57 24.20 18.18 26.98	/25
Labor 200 200 Parts	PM PM LF14000 FF2200, FS1000, 77E0850 15w40, 0), OIL FILTER FUEL FILTER FUEL FILTER), OIL SAMPLES	BRODY	Odom Hours: 2.00 3.00 5.00 .00 .00	eter: 1,242,61 38,000 2.00 3.00 5.00 1.00 1.00 1.00 45.00	70.00 100.00 Total Labor 47.57 24.20 18.18 26.98 4.16 Total Parts	440.00 300.00 440.00 47.57 24.20 18.18 26.98 187.20	
Labor 200 200 Parts	PM PM LF14000 FF2200, FS1000, 77E0850 15w40, 0	o, OIL FILTER FUEL FILTER FUEL FILTER D, OIL SAMPLES DIL 22 / Gregg Distributors LP	BRODY	Odom Hours: 2.00 3.00 5.00 .00 .00 .00	eter: 1,242,61 38,000 2.00 3.00 5.00 1.00 1.00 1.00 45.00	70.00 100.00 Total Labor 47.57 24.20 18.18 26.98 4.16 Total Parts	As Of: 14/Mar 140.00 300.00 440.00 47.57 24.20 18.18 26.98 187.20 304.13	
Labor 200 200 Parts Sublet Work Description	PM PM LF14000 FF2200, FS1000, 77E0850 15w40, 0	o, OIL FILTER FUEL FILTER FUEL FILTER D, OIL SAMPLES DIL 22 / Gregg Distributors LP	BRODY	Odom Hours: 2.00 3.00 5.00 .00 .00 .00	eter: 1,242,61 38,000 2.00 3.00 5.00 1.00 1.00 1.00 45.00	70.00 100.00 Total Labor 47.57 24.20 18.18 26.98 4.16 Total Parts	As Of: 14/Mar 140.00 300.00 440.00 47.57 24.20 18.18 26.98 187.20 304.13	
Labor 200 200 Parts Sublet Work Descriptions of the contractor	PM PM LF14000 FF2200, FS1000, 77E0850 15w40, 0 59-7299 on r - Marcl	o, OIL FILTER FUEL FILTER FUEL FILTER O, OIL SAMPLES OIL 22 / Gregg Distributors LP on 14, 2025 and fuel filters	BRODY	Odom Hours: 2.00 3.00 5.00 .00 .00 .00	eter: 1,242,61 38,000 2.00 3.00 5.00 1.00 1.00 1.00 45.00	70.00 100.00 Total Labor 47.57 24.20 18.18 26.98 4.16 Total Parts	As Of: 14/Mar 140.00 300.00 440.00 47.57 24.20 18.18 26.98 187.20 304.13	
Labor 200 200 Parts Sublet Work Description Sub contractor Service due with Oil only done a	PM PM LF14000 FF2200, FS1000, 77E0850 15w40, 0 59-7299 on r - Marcl ith oil ar	o, CIL FILTER FUEL FILTER FUEL FILTER D, OIL SAMPLES DIL 22 / Gregg Distributors LP The 14, 2025 and fuel filters I hours	BRODY	Odom Hours: 2.00 3.00 5.00 .00 .00 .00	eter: 1,242,61 38,000 2.00 3.00 5.00 1.00 1.00 1.00 45.00	70.00 100.00 Total Labor 47.57 24.20 18.18 26.98 4.16 Total Parts	As Of: 14/Mar 140.00 300.00 440.00 47.57 24.20 18.18 26.98 187.20 304.13	
Labor 200 200 Parts Sublet Work Description Sub contractor Service due with Oil only done a	PM PM LF14000 FF2200, FS1000, 77E0850 15w40, 0 59-7299 on r - Marcl ith oil ar	o, CIL FILTER FUEL FILTER FUEL FILTER D, OIL SAMPLES DIL 22 / Gregg Distributors LP The 14, 2025 and fuel filters I hours	BRODY ROCKY	Odom Hours: 2.00 3.00 5.00 .00 .00 .00	eter: 1,242,61 38,000 2.00 3.00 5.00 1.00 1.00 1.00 45.00	70.00 100.00 Total Labor 47.57 24.20 18.18 26.98 4.16 Total Parts	As Of: 14/Mar 140.00 300.00 440.00 47.57 24.20 18.18 26.98 187.20 304.13	-
Labor 200 200 Parts Sublet Work Description Sub contractor Service due with Oil only done a	PM PM LF14000 FF2200, FS1000, 77E0850 15w40, 0 59-7299 on r - Marcl ith oil ar at 37761	o, CIL FILTER FUEL FILTER FUEL FILTER D, OIL SAMPLES DIL 22 / Gregg Distributors LP The 14, 2025 and fuel filters I hours	BRODY ROCKY s - PO 2008 - Greggs Completed Date: 01/May/2	Odom Hours: 2.00 3.00 5.00 .00 .00 .00	eter: 1,242,61 38,000 2.00 3.00 5.00 1.00 1.00 45.00 1.00	Total Sublet Total Sublet Total Sublet	As Of: 14/Mar 140.00 300.00 440.00 47.57 24.20 18.18 26.98 187.20 304.13 35.96	CAI

100.00 CAD

Total

Tryson Energy Services Inc Work Order History Report

Equipment: 09-501

Category	De	escription	Mechanic	Actual Hours	Quantity/Hours	Price/Rate	Amount	Cui
)13	Brakes incl air system	and valves	ALLEN	2.00	2.00	100.00	200.00	
Parts				9,50	9.50	Total Labor	950.00	
u	30/30, BRAKE POT			.00	1.00	45.95	45.95	
Nork Descripti Norm says the	on re is an oil leak a	t auxiliary. Pos	sibly a hose			Total Parts	45.95	
Allen changed	both hoses to an	d from auxiliar	oil cooler (in house bui	It hoses)			
April 14 2025								
l feet 1/2" hos								
PS rear brake	pot leaking air - A	illen changed it	- April 21, 2025			- Total	995,95	CAI
Vork Order #: 1	B17 Invoice#	t: Co	empleted Date: 08/May/25	09-501 Odomo			As Of: 24/Apri	
. abor 00	PM		BRODY					
00	PM		ROCKY	6.50 5.00	6.50 5.00	70,00 100.00	455.00 500.00	
arts				11.50	11.50	Total Labor	955.00	
	LF14000, OIL FILTER 77E0850, OIL SAMPL			.00. 00.	1.00 1.00	47.57 26.98	47.57 26.98	
	15w40, OIL SH501R, SAFETY LIC			.00.	45.00 2.00	4.16 17.60	187.20 35.20	
	200' X 1", WINCH LIN			.00	1.00	800.00	00.008	
Vork Description Subcontractor						Total Parts	1,096.95	
Service due wi	th oil filter and sa	mple only						
Oil and fuel do	ne at 38007 hrs							
Rocky / Brody	April 24, 2025							
						Total	2,051.95	CA
Vork Order #: 19	932 Invoice#	t: Co	empleted Date: 20/Jun/25	09-501				
26	Main transmission ma	nual	JOSH	1.00	1.00	100.00	100.00	
Vork Description		Jooking	·	1.00	1.00	Total Labor	100,00	
nam dansmiss	ion oil cooler line	eleaking						

Tryson Energy Services Inc Work Order History Report

Equipment: 09-501

Category	Description	Mechanic	Actual Hours	Quantity/Hours	Price/Rate	Amount	Cur.
Work Order #: 19	980 Invoice#:	Completed Date: 19/Jun/	25 09-501 Odome Hours:			r As Of: 10/Jun/ g As Of: 10/Jun/	
Labor 200 200 014	PM PM Frame incl tool boxes, 5th wheel, mu gin poles	ROCKY ROCKY d flaps, deck, SHELDON	2.00 2.00 2.00	2.00 2.00 2.00 2.00	100.00 100.00 100.00 Total Labor	200,00 200,00 200,00 600.00	
Parts	LF14000, OIL FILTER FS1000, FUEL FILTER FF2200, FUEL FILTER 77E0850, OIL SAMPLES 15w40, OIL		.00 .00 .00 .00	1.00 1,00 1.00 1.00 1.00	47.57 18.39 24.48 26.98 4.16 Total Parts	47.57 18.39 24.48 26.98 4.16	

Work Description

Sub contractor - June - Rocky

Service due with oil and fuel filters

Oil in at 38258

Change the coolant hoses from engine to the transmission cooler - Rocky

Sheldon welded some big cracks on the 5th wheel

					Total	721.58	CAD
Work Order #: 20	075 Invoice#:	Completed Date: 21/Aug/25	09-501 Odometer:	1,267,970	Odometer As	s Of: 03/Jul/2	25
Labor 034	Lighting and electrical	ROGER	1.00	1.00	100.00	100.00	
•••		-	1.00	1.00	Total Labor	100.00	
Parts	21101, FLAGS 12-MAGNET, MAGNET WITH C. 11R24.5 RECAP, RECAP DRIVE 425X65X22.5 BST, TIRE L315		.00 .00 .00 .00	1.00 1.00 8.00 2.00	2.70 6.95 377.00 723.44	2.70 6.95 3,016.00 1,446.88	
					Total Parts	4,472.53	
Sublet	92520740 / Kal Tire 92520740 / Kal Tire 92520740 / Kal Tire	\$.00 .00 .00	1.00 1.00 1.00	2,078.36 564.00 294.66	2,078.36 564.00 294.66	
					Total Sublet	2,937.02	

Work Description Kal July Charges

Jun 30 2025 - Roger repaired a wire to the Pass side low beam

July 3 2025 - Norm took to Kal - 6 drive tires were down to point of changing - 12 Yokohama BDY2 recap drives put on - 8 Tryson recaps AND 4 TIRES FROM KAL TO MAKE A SET - 2 Sailun 425 steer tires put on

 2 Sailun 425 steer tires put on See PO 2999

Tryson Energy Services Inc Work Order History Report

Equipment: 09-501

Category	Description	Mechanic	Actual Hours	Quantity/Hours	Price/Rate	Amount	Cui
Work Order #: 2106	Invoice#:	Completed Date: 19/Aug/		eter: 1,271,221 38,789 H		r As Of: 14/Jul/2 g As Of: 14/Jul/2	
L abor 200 PN	A	BRODY	4.00	4.00	70.00	200.00	
00 Pt		ROCKY	4.00	4.00 4.00	70.00 100.00	280.00 400.00	
'arts			8.00	8.00	Total Labor	680.00	
LF 77 15 45 30 1-	14000, OIL FILTER E0850, OIL SAMPLES w40, OIL 583, LIGHT 50, LIGHT 1/8" X 28', SLING 3"-1/2", RATCHET BOOMERS		.00 .00 .00 .00 .00 .00	1,00 1,00 45,00 1,00 1,00 1,00 4,00	47.57 26.97 4.22 34.34 7.48 189.00 135.00	47.57 26.97 189.90 34.34 7.48 189.00 540.00	
ork Description ub Contractor	July - Rocky / Brody				Total Parts	1,035.26	
service due with o	oil filter and sample onl	у					
il and fuel done	on W/O 1980 @ 38,25	8 hrs					
Drive axle slack		8 hrs tened up - rear diff banjo lea	aking Aux				
Drive axle slack eaking	adjusters needed tight		aking Aux				
Drive axle slack eaking	adjusters needed tight		aking Aux		Total	1,715.26	CAD
	adjusters needed tight ace light Invoice#:		aking Aux 09-501		Total	1,715.26	CAD
Drive axle slack eaking Repair PS clearar Vork Order #: 2258 Vork Description	adjusters needed tight ace light Invoice#:	tened up - rear diff banjo lea	·		Total Total		
Drive axle slack eaking Repair PS clearar Fork Order #: 2258 Fork Description Fet ready for auct	adjusters needed tight nce light Invoice#:	tened up - rear diff banjo lea	·				CAD
Drive axle slack eaking Repair PS clearar Vork Order #: 2258 Vork Description Set ready for auch	adjusters needed tight ace light Invoice#: Invoice#: O and hydraulics O and hydraulics	tened up - rear diff banjo lea	09-501	4,50 8,50 5,00			
Drive axle slack eaking Repair PS clearar Vork Order #: 2258 Vork Description Get ready for auch Vork Order #: 2320 abor 56 PT 56 PT 17 Tir	adjusters needed tight ace light Invoice#: Invoice#: O and hydraulics O and hydraulics	tened up - rear diff banjo lea Completed Date: Completed Date: BRODY BRODY	09-501 09-501 4.50 8.50	8.50	Total 70.00 70.00	.00 315.00 595.00	
Drive axle slack eaking Repair PS clearar Vork Order #: 2258 Vork Description Set ready for auch Vork Order #: 2320 abor 56 PT 56 PT 17 Tr	adjusters needed tight ace light Invoice#: Invoice#: O and hydraulics O and hydraulics	tened up - rear diff banjo lea Completed Date: Completed Date: BRODY BRODY	09-501 09-501 4.50 8.50 5.00	8.50 5.00	70.00 70.00 70.00 70.00	.00 315.00 595.00 350.00	

Remove the hydraulic cylinders for 5th wheel Weld in lower position Build and install a new cover over the hole where the cylinders were

Send to Halls for painting as lined up by Lorne

Total	1,260,00	CAD

Tryson Energy Services Inc Work Order History Report

Page 10 '

Equipment: 09-501

Category	Description	Mechanic	Actual Hours	Quantity/Hours	Price/Rate	Amount	Cur.
			153.50	587.50		44,487.91	CAD

¥