

EDGE ENERGY
LOGISTICS

Location: LB Shop

[illegible]

Location: Leckie

Date: 07/24/2024

Truck/Trailer Information		
Unit #: <u>R-72</u>	Kilometres: <u>421040</u>	Hours: <u>7507</u>
Make: <u>Kenworth</u>	VIN: <u>1NKCXBTX27R995124</u>	Plate #: <u>0-CL400</u>
Parts and Materials		
<u>1-170-70-18x u-joint strap bit</u>		
<u>2- Edge Energy mud flaps</u>		
<u>2- Mud flap anti-sail bracket</u>		
Description of Work Completed		
<u>Check over unit</u>		
<u>Grease unit</u>		
<u>Check all fluid levels</u>		
<u>Tighten loose output yoke #3 axle & replace u-joint strap bit</u>		
<u>Remove air compressor discharge line & inspect threads, found threads</u>		
<u>damaged</u>		
<u>Disassemble air line @ compressor, Remove discharge fitting & retap threads in</u>		
<u>compressor head. Remove discharge fittings & assemble. Repair air line @ governor</u>		
<u>to dryer fittings</u>		
<u>Fill drain shock absorbers</u>		
<u>Replace #3 RH ABS modulator valve</u>		
<u>Remove unit number decal</u>		
<u>Install Edge mud flaps & anti sail brackets on front bumper</u>		
<u>Install license plate</u>		
Completed By: <u>Tyler Janzen</u>	Signature: <u>Tyler Janzen</u>	Date: <u>07/24/2024</u>
Completed By:	Signature:	Date:
Manager:	Signature:	Date:

