

GW22-1

01-2019-4974 REPAIR CLOSED 10/25/2019 C
OCT. 24/19 - RECEIVED REPORT THAT THE BATTERY LIGHT IS ON, ENGINE DIED
. LOCATED TWP ROAD 29 0 & RR 6 2.

OCT. 25/19 @ 7198 HRS. - TRAVELLED TO UNIT E-1401 NORTH ANS EAST OF CERIA
L. VISUALLY CHECKED THE UNIT FOR OBVIOUS PROBLEMS. BELT IS GOOD, NO BROKE

28	BATTERIES	99
00	ENGINE	99
69	TRAVEL TIME	

01-2019-5095 REPAIR CLOSED 11/01/2019 T
- HAYWORTH MECHANICAL INV# 006081 - (\$480.00)

UPDATE HRS ONCE RECIEVE THEM

PUTTING 1 NEW FRONT TIRE ON THE FRONT TO MATCH OTHER NEW TIRE

08	TIRES AND RIMS	99
69	TRAVEL TIME	
67	SERVICE	99

01-2019-5379 REPAIR CLOSED 11/25/2019 C
NOV. 25/19 @ 7215 HRS. - RECEIVED A REPORT THAT THE UNIT WILL NOT START
. NO BATTERY POWER. IN CEREAL SHOP.

NOV. 25/19 @ 7215 HRS. - CHECKED THE BATTERY VOLTAGE ON ET AND AT THE
BATTERIES, BOTH WERE 21 VDC. ANY LOAD INTRODUCED CAUSED THE VOLTAGE TO DR

28	BATTERIES	99
11	AIR INTAKE SYSTEMS	99
27	ELECTRICAL SYSTEM	

01-2019-5403 REPAIR CLOSED 11/26/2019 C
NOV. 25/19 @ 7215 - ASKED TO TAKE A COMPRESSED AIR MAXIMUM PRESSURE RE
LIEF VALVE FOR THIS UNIT. NO REASON GIVEN.

NOV. 25/19 @ 7215 HRS. - INSTALLED A PRESSURE GAUGE ON THE COMPRESSED
AIR SYSTEM AND FOUN D THE MAXIMUM PRESSURE RELIEF VALVE WOULD OPEN AS THE

24	COMPRESSED AIR SYSTEM	
----	-----------------------	--

01-2020-255 REPAIR CLOSED 01/14/2020 C
JAN. 14/20 @ 7247 HRS. - REPORTED THAT THIS UNIT HAS AN OIL LEAK ON A
WHEEL MOTOR.

JAN. 14/20 @ 7247 HRS. - CHECKED FOR LEAK ON THE RIGHT STEERING POSITI
ON WHEEL MOTOR. UNABLE TO SEE THE ORIGIN OF THE OIL. CLEANED THE INNER WH

02	TRANSMISSION	99
27	ELECTRICAL SYSTEM	
37	HYDRAULIC SYSTEM	

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							69	TRAVEL TIME	
	01-2020-356	REPAIR	CLOSED	01/23/2020		O			
	- REPLACING CAB AIR FILTERS ON UNIT -								
							11	AIR INTAKE SYSTEMS	99
	01-2020-369	REPAIR	CLOSED	01/24/2020		C			
	JAN. 23/2020 @ 7264 HRS. - OPERATOR REPORTS STORED CODES VISIBLE ON THE MESSENGER DISPLAY.								
	JAN. 23/2020 @ 7264 HRS. - CONNECTED CAT ET AND CHECKED FOR CODES. STORED CODES WERE:								
							27	ELECTRICAL SYSTEM	
							66	INSPECTIONS / DIAGNOSTICS	99
	01-2020-1142	REPAIR	CLOSED	03/31/2020		C			
	COMPLAINT THAT OIL IS LEAKING FROM UNDER THE VERY FRONT COVER								
	REMOVED THE COVER AND FOUND THAT AN ORING ON ONE OF THE LARGE HOSES WAS LEAKING. REMOVED SEVERAL MORE HOSES TO GET TO THE ONE THAT WAS LEAKING. REPLACED ORING AND ALL THE HOSES								
							37	HYDRAULIC SYSTEM	99
							69	TRAVEL TIME	
	01-2020-1232	PM	CLOSED	04/09/2020					
	PM 500 HOUR SERVICE BY OPERATOR								
	INSPECT AND MAINTAIN MACHINE AS PER CHECKLIST								
	CHANGE ENGINE OIL AND FILTER, OBTAIN SAMPLE								
	CHECK/CHANGE AIR FILTERS								
	CHANGE FUEL FILTERS								
							A	A PREVENTIVE MAINTENANCE IN	
							M	ANNUAL INSPECTION	
							00	ENGINE	99
							02	TRANSMISSION	99
							11	AIR INTAKE SYSTEMS	99
							20	FUEL SYSTEM	99
							37	HYDRAULIC SYSTEM	99
	01-2020-1289	REPAIR	CLOSED	04/20/2020		T			
	PLACE NEW O-RING INTO THE LEFT REAR TANDEM TIRE								
	CHECK REST OF THE TIRE AND RIM CLEAN RIM IF NEEDED								
	WILL UPDATE HOURS UPON RECEIVING THEM								
							08	TIRES AND RIMS	99
							69	TRAVEL TIME	
	01-2020-1329	REPAIR	CLOSED	04/23/2020		P			

|JOHN HOGAN TOOK L.H. HEADLIGHT TO REPLACE BURNT OUT ONE.

| 27 ELECTRICAL SYSTEM 99 |

|01-2020-1368 REPAIR CLOSED 04/28/2020 E
|REPLACE LEFT HAND DOOR GLASS

- 2 GLASS CHARGED OUT AS ONE GLASS WAS BROKE BY TECH WHEN LOADING INTO S
ERVICE TRUCK

| 63 GLASS 99 |
| 69 TRAVEL TIME |
| 62 BODY |

|01-2020-1400 REPAIR CLOSED 05/01/2020 C
|CHANGED AND FLUSHED CIRCLE GEAR BOX AS RE SAMPLE THAT CAME BACK

| 57 CIRCLE AND MOLDBOARD |
| 00 ENGINE 99 |
| 37 HYDRAULIC SYSTEM 99 |

|01-2020-1445 REPAIR CLOSED 05/01/2020 C
| - REPLACE WRIST CUSHION

| 52 CAB AND CONTROLS 99 |

|01-2020-1583 REPAIR CLOSED 05/19/2020 C
|JOHN HOGAN TOOK OUTER AIR FILTER

| 11 AIR INTAKE SYSTEMS 99 |

|01-2020-2269 REPAIR CLOSED 07/03/2020 P
|CHRIS REPLACED LEAKING HYDRAULIC HOSE ON BLADE TILT CYLINDER

CLH JULY 3/20

-BUILD A NEW HOSE IN THE SHOP TO REPLACED THE FAILED HOSE.
-REMOVE THE FAILED HOSE FROM THE UNIT.

| 37 HYDRAULIC SYSTEM 99 |
| 69 TRAVEL TIME |
| 52 CAB AND CONTROLS 99 |

|01-2020-2558 PM CLOSED 07/21/2020

|PM 4000 HOUR SERVICE

INSPECT AND MAINTAIN MACHINE AS PER CHECKLIST

CHANGE FUEL FILTERS

CHECK/CHANGE AIR FILTERS

CHANGE ENGINE OIL & FILTER, OBTAIN SAMPLE

| A A PREVENTIVE MAINTENANCE IN |

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							M	ANNUAL INSPECTION	
							00	ENGINE	99
							02	TRANSMISSION	99
							11	AIR INTAKE SYSTEMS	99
							20	FUEL SYSTEM	99
							37	HYDRAULIC SYSTEM	99
							67	SERVICE	
							69	TRAVEL TIME	

	01-2020-2560	PM	CLOSED	07/21/2020		I			
	*****UPDATE MACHINE HOURS & TECHNICIAN ID*****								
	TECHNICIAN COMMENTS TO FOLLOW								
	CHECK AND ADJUST VALVE LASH								
	JULY 28/20 ADJUSTED ALL VALVES TO SPEC								
							34	AIR CONDITIONING AND HEATIN	99
							37	HYDRAULIC SYSTEM	99
							02	TRANSMISSION	99
							A	A PREVENTIVE MAINTENANCE IN	
							M	ANNUAL INSPECTION	
							00	ENGINE	
							58	ATTACHMENTS	

	01-2020-2618	REPAIR	CLOSED	07/23/2020		C			
	COMPLAINT OF STEERING CODE								
	CODE # 1472-4 IS SHORT TO GROUND FOR STEERING SENSOR								
	ORDERED NEW JOYSTICK JULY 23								
	JULY 24/20 INSTALLED NEW JOYSTICK AND THIS CODE STAYED UNTIL MACHINE MOVE								
							52	CAB AND CONTROLS	99
							27	ELECTRICAL SYSTEM	99
							69	TRAVEL TIME	
							44	STEERING	

	01-2020-2667	REPAIR	CLOSED	07/28/2020		C			
	JULY 28/20 CHECKED MAIN RELAY AND CONNECTIONS ARE TIGHT. ENG NEEDS A NEW								
	DIP STICK								
	JULY 29/20 REPLACED ENG DIPSTICK								
							00	ENGINE	99
							27	ELECTRICAL SYSTEM	

	01-2020-2922	REPAIR	CLOSED	08/13/2020		C			
	HYD HOSE FOR THE BLADE SLIDE SPRUNG A LEAK								
	OPERATOTR BROUGHT HOSE TO SHOP AND WE BUILT A NEW HOSE OPERATOR INSTALLED								
	AND SUPPLIED OPERATOR WITH PAIL OF OIL								
							37	HYDRAULIC SYSTEM	99

	01-2020-3350	REPAIR	CLOSED	09/09/2020		C			

| COMPLAINT THAT THE CHARGE LIGHT FLASHES ON AND OFF

*****UPDATE HRS WHEN COMPLETE*****

			27	ELECTRICAL SYSTEM	99	
			29	ALTERNATOR		
			59	AUXILLIARY EQUIPMENT		
			69	TRAVEL TIME		
			28	BATTERIES	99	
			24	COMPRESSED AIR SYSTEM	99	

| 01-2020-3766 REPAIR CLOSED 10/01/2020 T
| RIGHT REAR TANDEM TIRE IS LEAKING AIR AND OPERATOR HAS TO FILL TIRE UP EVERY 2 DAYS.

WILL PUT NEW ORING IN AND INSPECT THE TIRE AND RIM.

			08	TIRES AND RIMS	99	
			69	TRAVEL TIME		

| 01-2020-4315 REPAIR CLOSED 11/10/2020 C
| PLOW PIN MOUNTS OUT OF ALLIGNMENT....REPAIR/ADJUST AS NEEDED

NOV. 12, 2020 @ 8302 HRS. - ASKED TO CHECK AND REPAIR THE CAUSE OF NOT BEING ABLE TO INSTALL THE V-PLOW PINS. (CEREAL SHOP)

			80	FABRICATION AND WELDING		
			59	AUXILLIARY EQUIPMENT		
			69	TRAVEL TIME		

| 01-2020-4474 REPAIR CLOSED 11/24/2020 C
| - REPLACE V-PLOW PIN

			17	BOLTS- NUTS- WASHERS AND MI	99	
--	--	--	----	-----------------------------	----	--

| 01-2020-4603 REPAIR CLOSED 12/02/2020 C
| - REPLACE BLADE SLIDES

			57	CIRCLE AND MOLDBOARD	99	
--	--	--	----	----------------------	----	--

| 01-2020-4762 REPAIR CLOSED 12/21/2020 C
| - JOHN PICKED UP CIRCLE SHIMS FOR UNIT

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							57	CIRCLE AND MOLDBOARD	99

	01-2020-4799	REPAIR	CLOSED	12/29/2020		C			
	COMPLAINT THAT THE ARTICULATION IS OUT AND CAN ONLY GET 6TH GEAR AND LOWE R								
	ORDERED NEW ARTICULATION LINKAGE DEC 29								
							27	ELECTRICAL SYSTEM	99
							69	TRAVEL TIME	

	01 2021-49	PM	CLOSED	01/04/2021		O			
	PM 500 HOUR SERVICE COMPLETED 11 JAN 2021								
	INSPECT AND MAINTAIN MACHINE AS PER CHECKLIST								
	CHANGE ENGINE OIL AND FILTER, OBTAIN SAMPLE								
	CHECK/CHANGE AIR FILTERS								
							00	ENGINE	99
							02	TRANSMISSION	99
							11	AIR INTAKE SYSTEMS	99
							20	FUEL SYSTEM	99
							37	HYDRAULIC SYSTEM	99
							67	SERVICE	99
							A	A PREVENTIVE MAINTENANCE IN	
							M	ANNUAL INSPECTION	

	01-2021-149	REPAIR	CLOSED	01/14/2021		C			
	BLADE PIVOT PINS HAVE LOTS OF PLAY (AS PREVIOUSLY REPORTED WO#4606								
	JAN 14 ORDERED NEW UPDATED GREASABLE PINS GD								
	JAN 22 REMOVED PIVOT PINS AND STRTED TO CUT OUT THE BUSHINGS BUFFED THE								
							57	CIRCLE AND MOLDBOARD	99
							17	BOLTS- NUTS- WASHERS AND MI	99
							14	CHEMICALS	99

	01-2021-460	REPAIR	CLOSED	02/09/2021		P			
	- JOHN REPLACING WING CABLE								
							86	SAFETY SUPPLIES	99

	01-2021-735	REPAIR	CLOSED	03/05/2021		C			
	MARCH 5, 2021- KF								
	INSTALLED BLADES AT 8621HRS								
	NEW HARDWARE PUT ONTO BLADES AND OLD BLADES AND HARDWARE LEFT AT THE CERE AL SHOP								
							64	GROUND ENGAGING TOOLS	
							69	TRAVEL TIME	

|01-2021-1189 REPAIR CLOSED 04/14/2021 E
|THE RH AND LH DOOR GLASS NEED REPLACEMENT

TRAVELLED TO CEREAL AND REPLACED BOTH DOOR GLASS
HAD TO TRAVEL BACK TO YOUNGSTOWN SHOP TO GRAB SOME TOOLS THAT HADNT BEEN
PUT BACK INTO THE WINDOW KIT.

	63	GLASS	99	
	69	TRAVEL TIME		
	52	CAB AND CONTROLS		

|01-2021-1272 REPAIR CLOSED 04/21/2021 C
|APRIL 21/21 FOUND SYSTEM WAS FULL BUT NOT TURNING ON. FOUND BROKEN WIRES
ON A/C,ALTERNATOR HARNESS AND OPERATOR COMPLAINED ABOUT FAN MAKING NOISE.

APRIL 23/21 PUT IN ORDER FOR HARNESS AND FAN MOTOR ALSO MALE CONNECTORS

	27	ELECTRICAL SYSTEM	99	
	69	TRAVEL TIME		
	66	INSPECTIONS / DIAGNOSTICS		
	34	AIR CONDITIONING AND HEATIN	99	
	52	CAB AND CONTROLS	99	
	21	COOLING SYSTEM		

|01-2021-1365 REPAIR CLOSED 04/28/2021 C
|JOHN HOGAN TOOK AIR FILTERS AND TOW OIN

GREGR TOOK PRECLEANER FOR UNIT AT LATER DATE

	11	AIR INTAKE SYSTEMS	99	
	01	CLUTCH	99	

|01-2021-1382 REPAIR CLOSED 04/28/2021 C
|INSTALL SAFTEY CHAIN ON TOW BAR

	60	CHAINS	99	
	69	TRAVEL TIME		
	80	FABRICATION AND WELDING		

|01-2021-2020 REPAIR CLOSED 06/04/2021 C
|JOHN MILES TOOK A HITCH PIN

	59	AUXILLIARY EQUIPMENT	99	
--	----	----------------------	----	--

|01-2021-2059 PM CLOSED 06/07/2021
|PM 1000 HOUR SERVICE
COMPLETED 11 JUNE 2021
INSPECT AND MAINTAIN MACHINE AS PER CHECKLIST.
CHANGE FUEL FILTERS
INSPECT AIR PRECLEANER AND CLEAN OR REPAIR AS REQUIRED

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							A	A PREVENTIVE MAINTENANCE IN	
							M	ANNUAL INSPECTION	
							00	ENGINE	99
							11	AIR INTAKE SYSTEMS	99
							20	FUEL SYSTEM	99
							37	HYDRAULIC SYSTEM	99
							99	MISCELLANEOUS	99
							57	CIRCLE AND MOLDBOARD	99
							27	ELECTRICAL SYSTEM	99
							69	TRAVEL TIME	
							67	SERVICE	

	01-2021-2063	REPAIR	CLOSED	06/07/2021		C			
	MOD GRADER HITCH TO FIT NEW TRUCK								
							80	FABRICATION AND WELDING	

	01-2021-2186	REPAIR	CLOSED	06/15/2021		C			
	JUNE 11, 2021- KF								
	WHEN DOING THE 1000HR SERVICE IT WAS NOTICED THAT THE SEALS ON THE BACK S								
	IDE OF TRANSMISSION WERE LEAKING. WAS TOLD TO LEAVE THEM FOR NOW AND THEY								
	WILL GET DONE ON A RAIN DAY.								
	AUGUST 17, 2021 - 4 O-RINGS HAVE BEEN ORDERED AND ARE ON THE SHELF FOR								
							02	TRANSMISSION	99
							27	ELECTRICAL SYSTEM	99
							37	HYDRAULIC SYSTEM	99

	01-2021-3173	REPAIR	CLOSED	08/05/2021		C			
	AUG. 4, 2021 @ 9309 HRS. - REPORT OF STEERING SYSTEM CODES RECEIVED.								
	AUG. 4, 2021 @9309 HRS. JAKE EVANS WAS SENT TO TROUBLESHOOT THIS COM								
	PLAINT. TRAVEL TO UNIT NORTHWEST OF OYEN. OPERATOR HAD COMPLAINTS OF STEER								
	ING ALARMS. OPERATOR TURNED MASTER OFF, WAITED 15 MINS AND TURNED BACK ON								
	. NO ACTIVE CODES WERE PRESENT WHEN I GOT THERE. CONNECTED CAT ET AND SCA								
							44	STEERING	
							69	TRAVEL TIME	
							27	ELECTRICAL SYSTEM	

	01-2021-4052	PM	CLOSED	09/16/2021					
	PM 500 HOUR SERVICE								
	COMPLETED 20 SEPT 2021								
	INSPECT AND MAINTAIN MACHINE AS PER CHECKLIST								
	CHANGE ENGINE OIL AND FILTER, OBTAIN SAMPLE								
	CHECK/CHANGE AIR FILTERS								
							A	A PREVENTIVE MAINTENANCE IN	
							M	ANNUAL INSPECTION	
							11	AIR INTAKE SYSTEMS	99
							20	FUEL SYSTEM	99
							37	HYDRAULIC SYSTEM	99
							52	CAB AND CONTROLS	99

			00	ENGINE	99	
			02	TRANSMISSION	99	
			67	SERVICE	99	

	01-2021-4138	REPAIR CLOSED	09/22/2021	R		
--	--------------	---------------	------------	---	--	--

|INSTALL NEW JENNER FIRE CODE PLUG

			33	COMMUNICATIONS		
--	--	--	----	----------------	--	--

	01-2021-4568	REPAIR CLOSED	10/08/2021	C		
--	--------------	---------------	------------	---	--	--

|THIS IS ANOTHER ONE OF THE UNITS THAT KEEPS COMING UP WITH STEERING FAULT CODES

TODD FROM FINNING WENT TO UNIT ON OCTOBER 7 AND UPDATED THE COMPUTOR SOFTWARE ON THIS UNIT HOPFULLY THAT WILL FIX THE STEERING CODES FROM APPEARING

			44	STEERING	99	
			66	INSPECTIONS / DIAGNOSTICS		

	01-2021-4629	REPAIR CLOSED	10/14/2021	C		
--	--------------	---------------	------------	---	--	--

| OPERATOR STATES THERE IS A STEERING MALFUNCTION PROMPTING HER TO SHUT DOWN.

THERE IS A SHORT SOMEWHERE IN THE CHASIS HARNESS BETWEEN THE CAB AND THE TRANSMISSION ECM CAUSING A VOLTAGE DROP ON THE #2 STEERING SENSOR RESULTING

			44	STEERING		
			68	STEAM AND PAINT		
			99G	HOUSEKEEPING (SHOP)		
			27	ELECTRICAL SYSTEM		
			69	TRAVEL TIME		

	01-2021-4924	REPAIR CLOSED	11/01/2021	C		
--	--------------	---------------	------------	---	--	--

| NOVEMBER 1, 2021 @ 9633 HRS. - WHILE WORKING ON WORK ORDER 4923 I NOTICED THIS CYLINDER WAS LEAKING UPON INSPECTING IT I SEE THE ROD WIPER SEAL IS PROTRUDING FROM THE CYLINDER HEAD CAP.

WELDCO SEAL KIT # (CT)558-021-0634 REQUIRED.

1 7/8 INCH SOCKET REQUIRED FOR ROD NUT.

			69	TRAVEL TIME		
			80	FABRICATION AND WELDING		
			58	ATTACHMENTS	99	
			37	HYDRAULIC SYSTEM		

	01-2021-4927	REPAIR CLOSED	11/01/2021	C		
--	--------------	---------------	------------	---	--	--

| NOVEMBER 1, 2021 @ 9633 HRS. - REQUESTED THAT I REPAIR A FLUID LEAK AT THE REAR OF THIS GRADER.

NOVEMBER 1, 2021 @ 9633 HRS. - TRAVELLED TO E-1401 LOCATED IN THE CE REAL SHOP YARD. CHECKED IT FOR EVIDENCE OF LEAKS AND FOUND 1 SMALL OIL LEAK ON THE LEFT SIDE OF THE TRANSMISSION. STARTED THE MACHINE AND MOVED IT

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							21	COOLING SYSTEM	99
							00	ENGINE	99
							02	TRANSMISSION	
							69	TRAVEL TIME	

	01-2021-5156	REPAIR	CLOSED	11/25/2021		O			
	JOHN HOGAN TOOK OUTER, INNER AIR FILTER, FUEL FILTERS AND WATER SEPARATOR FILTER. UNIT IS SMOKING								
							11	AIR INTAKE SYSTEMS	99
							20	FUEL SYSTEM	99
							21	COOLING SYSTEM	99

	01-2022-73	REPAIR	CLOSED	01/04/2022		C			
	OPERATOR STATES THAT THERE WAS NO RESPONSE FROM THE BRAKES AS HE WAS APPROACHING AN INTERSECTION. ALSO STATES THAT THE LH BLADE SLIDE HOSE HAS FAILED.								
	EXTREME COLD COUPLED WITH NOT HAVING USED THE BRAKES FOR A PERIOD DUE TO								
							57	CIRCLE AND MOLDBOARD	99
							69	TRAVEL TIME	
							37	HYDRAULIC SYSTEM	
							41	BRAKES	

	01-2022-314	REPAIR	CLOSED	01/24/2022		T			
	REPLACE TIRE USED								
							08	TIRES AND RIMS	99

	01-2022-387	REPAIR	CLOSED	01/28/2022		C			
	JAN 28/22 WENT TO UNIT AND FOUND THE ARTICULATION HAD FAULT CODES. CLEANED MUD FROM AROUND SWITCH AND RECALIBRATED SYSTEM. RAN IT BACK AND FORTH WITH ARTICULATION AND NO CODES HAD RETURNED AFTER THEY WERE CLEARED								
							27	ELECTRICAL SYSTEM	
							69	TRAVEL TIME	

	01-2022-510	REPAIR	CLOSED	02/08/2022		C			
	FEB. 7, 2022 @ 9878 HRS. - OPERATOR REPORTS OIL LEAK(S) ON THE RIGHT FRONT WHEEL MOTOR.								
	FEB. 7, 2022 @ 9878 HRS. - CHECKED THE LEAK(S) AND FOUND 1 SMALLER HOSE LEAKING FROM THE CRIMP ON THE MOTOR END. THIS HOSE WILL BE REQUESTED FEB. 8, 2022. (D. UNSWORTH)								
							37	HYDRAULIC SYSTEM	99
							69	TRAVEL TIME	

|01-2022-606 REPAIR CLOSED 02/17/2022 C
 |GORDON OLDS PICKED UP PARTS TO REPLACE BLADE SLIDES

	64	GROUND ENGAGING TOOLS	99	
	28	BATTERIES	99	

 |01-2022-766 PM CLOSED 03/01/2022 O
 |PM 2000 HOUR SERVICE
 COMPLETED 11 MAR 2022
 INSPECT AND MAINTAIN MACHINE AS PER CHECKLIST.
 CHANGE FUEL FILTERS
 CHECK/CHANGE AIR FILTERS

	14	CHEMICALS	99	
	A	A PREVENTIVE MAINTENANCE IN		
	M	ANNUAL INSPECTION		
	00	ENGINE	99	
	02	TRANSMISSION	99	
	11	AIR INTAKE SYSTEMS	99	
	20	FUEL SYSTEM	99	
	34	AIR CONDITIONING AND HEATIN	99	
	37	HYDRAULIC SYSTEM	99	
	67	SERVICE	99	
	80	FABRICATION AND WELDING		
	63	GLASS	99	
	52	CAB AND CONTROLS	99	
	58	ATTACHMENTS	99	
	59	AUXILIARY EQUIPMENT		

 |01-2022-780 REPAIR CLOSED 03/02/2022 P
 |REPLACE BURNT OUT RIGHT HAND HEADLIGHT

	27	ELECTRICAL SYSTEM	99	
--	----	-------------------	----	--

 |01-2022-870 REPAIR CLOSED 03/09/2022 C
 |OPERATOR STATES THERE IS A KNOCK COMING FROM THE ENGINE.

MAIN SUPPLY LINE FROM THE COMPRESSOR TO THE AIR TANK FAILED. AIR PRESSURE
 FROM THE COMPRESSOR LEAKING THROUGH THE HOSE IS MAKING AKNOCKING SOUND A
 T THE SIDE OF THE ENGINE.

	44	STEERING	99	
	00	ENGINE		
	69	TRAVEL TIME		

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							24	COMPRESSED AIR SYSTEM	

	01-2022-886	REPAIR	CLOSED	03/10/2022		C			
OPERATOR STATES THAT THE RH DOOR SEAL IS NOT SEATING CORRECTLY AND SNOW/DUST IS BLOWING IN.									
CLH APRIL 11/22*									
-REMOVE OLD DOOR SEAL.									
							63	GLASS	99

	01-2022-895	REPAIR	CLOSED	03/11/2022		R			
ANTENNA WAS BROKEN REPLACED ANTENNA									
							33	COMMUNICATIONS	99

	01 2022 963	REPAIR	CLOSED	03/16/2022		C			
WHEN PREFORMING WINTER INSPECTION FOUND THE LEFT HAND PIVOT TANDEM SEAL LEAKING									
CLH									
-JACK UP THE LH SIDE OF THE UNIT AND PLACE ON STANDS.									
							07	TANDEM AND AXLE	99
							58	ATTACHMENTS	99
							14	CHEMICALS	99
							41	BRAKES	99
							44	STEERING	99
							02	TRANSMISSION	99
							80	FABRICATION AND WELDING	
							57	CIRCLE AND MOLDBOARD	

	01-2022-968	REPAIR	CLOSED	03/16/2022		C			
RH STEERING CYLINDER END HAS PLAY IN IT. WINTER INSPECTION REPAIRS ALSO									
CLH									
REPLACE ROD END BEARING ON RH STEERING CYLINDER.									
-REPLACE MULTIPLE LEAKING/DAMAGED LINES.									
							10	HYDROSTATIC SYSTEMS	
							58	ATTACHMENTS	99
							07	TANDEM AND AXLE	99
							67	SERVICE	
							44	STEERING	99
							57	CIRCLE AND MOLDBOARD	99
							37	HYDRAULIC SYSTEM	99

	01-2022-969	REPAIR	CLOSED	03/16/2022		C			
BOTH BLADE PIVOT PINS ARE WORN OUT AND NEED TO BE REPLACED. POSITION GRADER BLADE TO ACCESS PIVOT PINS. SUPPORT BLADE AND REMOVE BOLT ON COLLARS. HAMMER PINS OUT AND INSPECT. FOUND PINS WERE NOT WORN AS BAD AS ORIGINAL Y THOUGHT. ASKED TODD AND HE ALSO AGREED THAT NEW PINS AND BUSHINGS WOULD									

NT MAKE MUCH OF A DIFFERENCE. INSTALL OLD PINS BACK ONTO MACHINE.

57	CIRCLE AND MOLDBOARD	99
37	HYDRAULIC SYSTEM	

01-2022-1240 REPAIR CLOSED 04/06/2022 C

OPERATOR STATES THE UNIT SMOKES A LOT AND IS BURNING ABOUT 2 L OF ENGINE OIL PER SHIFT.

FUEL IN WATER SEPARATOR IS VERY DARK INDICATING THAT ENGINE OIL IS GETTING INTO THE FUEL SYSTEM MOST LIKELY THROUGH THE INJECTOR O-RINGS.

20	FUEL SYSTEM	99
19	EXHAUST SYSTEM	99
00	ENGINE	
80	FABRICATION AND WELDING	

01-2022 1258 REPAIR CLOSED 04/07/2022 C

SET VALVE LASH WHILE THE VALVE COVER IS OPEN TO CHANGE INJECTORS

W/O1240 CLH @9993HRS

00	ENGINE	
----	--------	--

01-2022 1304 REPAIR CLOSED 04/12/2022 C

APRIL 12/22 HARDWARE ON BACKORDER FOR FENDER AND ORDERED ONE FITTING FOR WING HOSE STOCK HAS THE OTHER END FOR HOSE REPAIR,

CLH APRIL 13/22

-INSTALL FENDER

67	SERVICE	
80	FABRICATION AND WELDING	
37	HYDRAULIC SYSTEM	99

01-2022-1320 REPAIR CLOSED 04/13/2022 C

AFTER CHANGING INJECTORS A KNOCK CAN BE HEARD FROM THE TOP END OF THE ENGINE. FOUND NO ISSUES WITH VALVE TRAIN AND KNOCK GOES AWAY WHEN INJECTOR # 5 IS CUT OUT.

CLH APRIL 13/22

00	ENGINE	
20	FUEL SYSTEM	99

01-2022 1383 REPAIR CLOSED 04/21/2022 C

JOHN HOGAN PICKED UP NEW CARBIDE BLADES FOR UNIT

64	GROUND ENGAGING TOOLS	99
----	-----------------------	----

01-2022-1623 REPAIR CLOSED 05/06/2022 C

JOHN HOGAN EMAILED IN FOR A 10MM ALLAN WRENCH

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							71	SHOP TOOLS	99
	01-2022-2164	REPAIR	CLOSED	06/06/2022		R			
	REMOVE OLD EQUIPMENT AND REPLACE WITH TITAN DEVICE								
							33	COMMUNICATIONS	
	01-2022-2438	REPAIR	CLOSED	06/23/2022		C			
	OPERATOR STATES THAT A STEERING CODE POPPED UP AND A SHUT DOWN PROMPT. ALSO LOST PRIMARY STEERING.								
	FAILURE OF THE #2 STEERING POSITION SENSOR INSIDE THE LH JOYSTICK CAUSING THE ECM TO NOT KNOW THE POSITION OF THE JOYSTICK RELATIVE TO THE WHEEL R								
							21	COOLING SYSTEM	99
							44	STEERING	
							69	TRAVEL TIME	
							27	ELECTRICAL SYSTEM	
	01-2022-3186	REPAIR	CLOSED	08/02/2022		P			
	ISSUED PRIMARY AND SECONDARY ENGINE AIR FILTERS FOR REPLACEMENT								
							11	AIR INTAKE SYSTEMS	99
							17	BOLTS- NUTS- WASHERS AND MI	99
	01-2022-3208	REPAIR	CLOSED	08/03/2022		C			
	MODIFY TOW BAR HITCH								
							80	FABRICATION AND WELDING	
	01-2022-3275	REPAIR	CLOSED	08/08/2022		C			
	JOHN HOGAN EMAILED IN FOR ENGINE AIR FILTERS								
							00	ENGINE	99
	01-2022-3525	REPAIR	CLOSED	08/23/2022		T			
	AUG. 23 REAR TANDEM TIRE WENT FLAT CALLED ARDELL TO TRAVEL TO GRADER AND REPAIR OR REPLACE TIRE GRADER LOCATED 30-4 AND 5-0								

				08	TIRES AND RIMS	
				37	HYDRAULIC SYSTEM	
				69	TRAVEL TIME	

|01-2022-3571 REPAIR CLOSED 08/26/2022 O

|500 HOUR SERVICE BY OPERATOR
 COMPLETED 26 AUG 2022
 INSPECT AND MAINTAIN MACHINE AS PER CHECKLIST
 CHANGE ENGINE OIL AND FILTER, OBTAIN SAMPLE
 CHECK/CHANGE AIR FILTERS

				00	ENGINE	99	
				11	AIR INTAKE SYSTEMS	99	
				20	FUEL SYSTEM	99	
				37	HYDRAULIC SYSTEM	99	
				52	CAB AND CONTROLS	99	
				67	SERVICE	99	

|01-2022-3810 REPAIR CLOSED 09/07/2022 C

| THIS JOB WAS COMPLETED BY CHRIS HOFFMAN AS I WAS DISPATCHED TO ANOTHER
 MACHINE. (D. UNSWORTH)

CLH
 -REPLACE FRONT WINDOW AS THE PREVIOUS ONE WAS TOO PITTED TO SEE OUT OF.

				63	GLASS	99	
				69	TRAVEL TIME		
				52	CAB AND CONTROLS		

|01-2022-3988 REPAIR CLOSED 09/16/2022 C

|JOHN HOGAN EMAILED IN FOR AIR FILTERS

				11	AIR INTAKE SYSTEMS	99	
--	--	--	--	----	--------------------	----	--

|01-2022 4035 REPAIR CLOSED 09/20/2022 C

|COMPLAINT 1
 THERE IS AN ENGINE KNOCK AND SMOKING
 GOT TO UNIT AND IT ISN'T SMOKING BUT I COULD HEAR A KNOCK. DID A CYLINDER
 R CUTOUT TEST TWICE AND ALL THE CYLINDERS PASSED COULD NOT DETERMINE THE

				00	ENGINE	99	
				27	ELECTRICAL SYSTEM	99	
				66	INSPECTIONS / DIAGNOSTICS		
				69	TRAVEL TIME		

|01-2022-4704 REPAIR CLOSED 11/01/2022 C

|JOHN HOGAN EMAILED IN FOR SUPPLIES FOR UNIT

				03	DRIVELINE AND 'U' JOINTS	99	
				64	GROUND ENGAGING TOOLS	99	

|01-2022-5031 PM CLOSED 11/28/2022

|PM 1000 HOUR SERVICE
 COMPLETED 14 DEC 2022
 INSPECT AND MAINTAIN MACHINE AS PER CHECKLIST.
 CHANGE FUEL FILTERS

INSPECT AIR PRECLEANER AND CLEAN OR REPAIR AS REQUIRED

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							A	A PREVENTIVE MAINTENANCE IN	
							M	ANNUAL INSPECTION	
							57	CIRCLE AND MOLDBOARD	99
							00	ENGINE	99
							02	TRANSMISSION	99
							04	FINAL DRIVE / DIFFERENTIAL	99
							34	AIR CONDITIONING AND HEATIN	99
							37	HYDRAULIC SYSTEM	99
							07	TANDEM AND AXLE	99
							20	FUEL SYSTEM	99
							11	AIR INTAKE SYSTEMS	99
							67	SERVICE	
							69	TRAVEL TIME	

	01-2022-5179	REPAIR	CLOSED	12/02/2022		O			
	BRUCE GILLESPIE PICKUP 1 PRIMARY AIR FILTER FOR GRADER								
							67	SERVICE	99

	01-2022-5226	REPAIR	CLOSED	12/07/2022		C			
	OPERATOR STATES THERE IS A CODE FOR THE ARTICULATION AND THE MACHINE IS LIMITED TO 6TH GEAR.								
	ARTICULATION ANGLE SENSOR HAS FAILED INTERNALLY DUE TO MOISTURE AND THE FREEZE/THAW CYCLE RESULTING IN THE MACHINE BEING LIMITED TO 6TH GEAR.								
							27	ELECTRICAL SYSTEM	
							69	TRAVEL TIME	

	01-2022-5273	REPAIR	CLOSED	12/12/2022		C			
	JOHN HOGAN ORDERED RATCHET STRAP FOR GRADER								
							18	FASTNERS & TIE DOWNS	99

	01-2022-5280	REPAIR	CLOSED	12/13/2022		C			
	LH DOOR GLASS DAMAGED.								
	CLH DEC. 13/22								
	-REPLACE LH DOOR GLASS AND SEAL.								
							69	TRAVEL TIME	
							52	CAB AND CONTROLS	
							63	GLASS	99

	01-2022-5287	REPAIR	CLOSED	12/13/2022		C			
	JOHN HOGAN EMAILED IN FOR SHEAR PIN								

01-2022-5309 REPAIR CLOSED 12/14/2022 C
OPERATOR STATES THERE IS A FAULT CODE FOR THE FAN/PUMP BYPASS SOLENOID.

CODE 3382-5: FAN/BRAKE PUMP LOAD SENSE BYPASS SOLENOID; CURRENT BELOW NORMAL.

27 ELECTRICAL SYSTEM
69 TRAVEL TIME

01-2022-5325 REPAIR CLOSED 12/16/2022 C
OPEN NEW WO IN 2023 IF REQUIRED AND REFERENCE WO 22 5325

OPERATOR STATES THE UNIT IS LACKING POWER AND HAS A VIBRATION IN 7TH/8TH GEAR.

69 TRAVEL TIME
03 DRIVELINE AND 'U' JOINTS 99
20 FUEL SYSTEM 99

01-2022-5350 REPAIR CLOSED 12/20/2022 C
OPERATOR STATES THE V-PLOW CYLINDER IS LEAKING BADLY.

ORDER A NEW CYLINDER AND A SEAL KIT TO REPAIR THE FAILED ONE.

3 JAN 2023 PKG

01-2023-76 REPAIR CLOSED 01/03/2023 C
REF. W/O 5325

HAUL GRADER TO YSC FOR REPAIR
PUSH ROD IS MIA
TODD DIAGNOSED ENGINE AND WAS DECIDED TO INSTAL A REMAN ENGINE.
ENGINE COMPLETED MARCH 14-2023

99H PARTS DELIVERY/PICKUP
00 ENGINE 99
02 TRANSMISSION 99
21 COOLING SYSTEM 99
37 HYDRAULIC SYSTEM 99
34 AIR CONDITIONING AND HEATIN 99
58 ATTACHMENTS 99

01-2023-549 REPAIR CLOSED 02/03/2023 C
WORK CONT. FROM W/O5350 AND W/O5325

REPLACE DRIVE SHAFT U JOINTS. - BILLED OUT ON W/O 5325 (MH)
REPLACE DIFF INPUT SEAL
REPLACE PLOW LIFT CYLINDER - BILLED OUT ON W/O 5350 (MH)

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							05	REAR AXLE	
							37	HYDRAULIC SYSTEM	99
							57	CIRCLE AND MOLDBOARD	99
							04	FINAL DRIVE / DIFFERENTIAL	99
							03	DRIVELINE AND 'U' JOINTS	

	01-2023-669	REPAIR	CLOSED	02/10/2023		T			
OPEN 2023 WO IF REQUIRED AND REFERENCE WO 22 5017									
NOV 25 - 2022									
RIGHT FRONT TANDEM HAS A SLOW LEAK. ARDELL GOING TO DO REPAIR.									
MOST LIKELY THE O-RING NEEDS REPLACING									
							08	TIRES AND RIMS	99

	01-2023-1092	REPAIR	CLOSED	03/14/2023		T			
LEFT FRONT TANDEM TIRE HAS A SLOW LEAK. SUSPECT IT IS THE O-RING									
INTEGRA TIRE AT YSC TO REPAIR TIRE ON MARCH 14, 2023									
							08	TIRES AND RIMS	99

	01-2023-1124	REPAIR	CLOSED	03/15/2023		C			
CLINTON YAKE PICKUP NUTS AND BOLTS FOR GRADER									
							18	FASTNERS & TIE DOWNS	99

	01-2023-1601	REPAIR	CLOSED	04/21/2023		C			
FIX CRACKED FENDER BRACKET IN CEREAL SHOP									
RIGHT HAND FRONT FENDER									
FRONT BRACKET									
							69	TRAVEL TIME	
							80	FABRICATION AND WELDING	

	01-2023-1659	REPAIR	CLOSED	04/25/2023		C			
JOHNNY HOGAN PICKED UP 1 FOR UNIT									
							17	BOLTS- NUTS- WASHERS AND MI	99
							08	TIRES AND RIMS	99

	01-2023-1809	REPAIR	CLOSED	05/02/2023		C			
MARY LOU PICKED UP BLOW GUN FOR UNIT									

			24	COMPRESSED AIR SYSTEM	99

01 2023 1877	REPAIR CLOSED	05/05/2023	O		
JOHN HOGAN PICKED UP INNER/OUTER AIR FILTERS FOR UNIT					
REPLACE WORN CUR RIGHT AND LEFT HAND DOOR AND REAR WINDOW WIPER BLADES					
			11	AIR INTAKE SYSTEMS	99
			63	GLASS	99

01-2023-2046	REPAIR CLOSED	05/16/2023	C		
-TRAVEL TO UNIT IN CEREAL					
-CHECK ALL FLUID LEVELS, THEY WERE GOOD					
-HAVE OPERATOR SHOW ME WHERE THE LEAK WAS AS IT WAS OBVIOUS					
-LEAK APPEARS TO BE COMING FROM HOSES RUNNING BESIDE ENGINE INTO THE ARTI					
CULATION POINT					
			34	AIR CONDITIONING AND HEATIN	
			37	HYDRAULIC SYSTEM	
			69	TRAVEL TIME	

01-2023-2135	REPAIR CLOSED	05/23/2023	P		
- JOHN HOGAN TOOK 3/4 X 3 INCH BOLTS AND NUTS FOR MOLD BOARD BLADES					
			57	CIRCLE AND MOLDBOARD	99

01 2023 2208	REPAIR CLOSED	05/29/2023	C		
MAY 30/23 REPLACED ENG AIR FILTER COVER-PWB					
			58	ATTACHMENTS	99
			11	AIR INTAKE SYSTEMS	99

01-2023-2210	REPAIR CLOSED	05/29/2023	C		
MAY 30/23 REPLACED ALL LOWER WEAR PLATES AND ADJUSTED CIRCLE-PWB					
			57	CIRCLE AND MOLDBOARD	
			69	TRAVEL TIME	

01-2023-2429	REPAIR CLOSED	06/08/2023	C		
6/8/2023 RB					
PACK UP SERVICE TRUCK AND GATHER PARTS					
-TRAVEL TO AND FROM UNIT AT SEDALIA					
-CONNECT GUAGES AND CHECK REFRIGERANT CHARGE, FOUND THERE WAS NEXT TO NOT					
HING LEFT IN IT					
			14	CHEMICALS	99
			34	AIR CONDITIONING AND HEATIN	99
			69	TRAVEL TIME	

01-2023-2587	REPAIR CLOSED	06/16/2023	C		

JOHN HOGAN EMAILED IN FOR AIR FILTERS

[The following text is extremely faint and largely illegible. It appears to be a collection of lines, possibly representing an email or a list of items, but the specific content cannot be discerned.]

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							11	AIR INTAKE SYSTEMS	99
							86	SAFETY SUPPLIES	99

	01-2023-2777	PM	CLOSED	06/27/2023					
	PM 500 HOUR SERVICE COMPLETED 11 JULY 2023 INSPECT AND MAINTAIN MACHINE AS PER CHECKLIST CHANGE ENGINE OIL AND FILTER, OBTAIN SAMPLE CHECK/CHANGE AIR FILTERS								
							A	A PREVENTIVE MAINTENANCE IN	
							M	ANNUAL INSPECTION	
							00	ENGINE	99
							02	TRANSMISSION	99
							07	TANDEM AND AXLE	99
							11	AIR INTAKE SYSTEMS	99
							20	FUEL SYSTEM	99
							34	AIR CONDITIONING AND HEATIN	99
							37	HYDRAULIC SYSTEM	99
							57	CIRCLE AND MOLDBOARD	99
							67	SERVICE	99

	01-2023-3084	REPAIR	CLOSED	07/13/2023		P			
	REPLACE DRAIN ANF FILL DIFF PLUGS THAT ARE STRIPPED REPLACE BURNT OUT HIGH BEAM BULBS GREASE FOR UNIT								
							04	FINAL DRIVE / DIFFERENTIAL	99
							14	CHEMICALS	99
							27	ELECTRICAL SYSTEM	99

	01 2023 3127	REPAIR	CLOSED	07/17/2023		C			
	WELD NUT TO FRONT PLANETARY DRAIN PLUG BOTH SIDES TRAVEL TO CEREAL TO DO THIS								
							69	TRAVEL TIME	
							80	FABRICATION AND WELDING	

	01-2023-3481	REPAIR	CLOSED	08/03/2023		C			
	JOHN HOGAN EMAILED IN FOR HYD OIL								
							37	HYDRAULIC SYSTEM	99

	01-2023-3644	REPAIR	CLOSED	08/14/2023		C			
	OPERATOR STATES THE A/C FADES AS THE DAY GOES ON. THERE IS A LOW SIDE RESTRICTION CAUSING HIGH PRESSURE IN THE LOW SIDE, RE								

SULTING IN THE SYSTEM FREEZING OFF AND QUITING AFTER A FEW HOURS OF OPERA
TION.

				34	AIR CONDITIONING AND HEATIN	99
				69	TRAVEL TIME	

01-2023-4032 REPAIR CLOSED 09/05/2023 C
JOHN HOGAN PICKED UP PRIMARY AND SECONDARY AIR FILTERS

				11	AIR INTAKE SYSTEMS	99
--	--	--	--	----	--------------------	----

01-2023-4044 REPAIR CLOSED 09/06/2023 T
CHANGE OUT ALL 6 TIRES AS THEY ARE WORE OUT

ARDELL HAYWORTH INTEGRA TIRE IS DOING THIS WORK IN CEREAL AT THE MAINTANC
E SHOP

				99H	PARTS DELIVERY/PICKUP	
				08	TIRES AND RIMS	99

01-2023-4360 REPAIR CLOSED 09/26/2023 P
JOHN HOGAN TOOK GREASE TUBES TO GREASE UNIT

				14	CHEMICALS	99
--	--	--	--	----	-----------	----

01-2023-4632 PM CLOSED 10/11/2023 O
PM 12000 HOUR SERVICE BY TECHNICIAN
COMPLETED 30 OCT 2023
INSPECT AND MAINTAIN MACHINE AS PER CHECKLIST.
CHANGE FUEL FILTERS
CHECK/CHANGE AIR FILTERS

				67	SERVICE	
				A	A PREVENTIVE MAINTENANCE IN	
				00	ENGINE	99
				02	TRANSMISSION	99
				11	AIR INTAKE SYSTEMS	99
				37	HYDRAULIC SYSTEM	99
				M	ANNUAL INSPECTION	

01-2023-4856 REPAIR CLOSED 10/24/2023 C
JOHN HOGAN PICKED UP CABLE FOR WING

				58	ATTACHMENTS	99
--	--	--	--	----	-------------	----

01-2023-4863 REPAIR CLOSED 10/25/2023 C
JOHN HOGAN PICKED UP LIGHTS

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							27	ELECTRICAL SYSTEM	99

	01-2023-5009	REPAIR	CLOSED	10/31/2023		C			
	REPAIRS FROM SERVICE								
	LEFT SIDE BOTTOM STEP								
	RIGHT HAND INNER CAB WORK LIGHT								
	-2 TRANSMISSION LINES								
	-2 FRONT ATTACHMENT HYDRAULIC LINES								
							71	SHOP TOOLS	99
							58	ATTACHMENTS	99
							37	HYDRAULIC SYSTEM	99
							27	ELECTRICAL SYSTEM	99
							67	SERVICE	99
							66	INSPECTIONS / DIAGNOSTICS	
							52	CAB AND CONTROLS	
							02	TRANSMISSION	
							59	AUXILLIARY EQUIPMENT	

	01-2023-5144	REPAIR	CLOSED	11/14/2023		C			
	JOHN HOGAN EMAILED IN FOR DIESEL CONDITIONER								
							20	FUEL SYSTEM	99

	01-2023-5395	REPAIR	CLOSED	12/06/2023		C			
	JOHN HOGAN EMAILED IN FOR BLADE BOLTS AND NUTS, WASHER FLUID								
							58	ATTACHMENTS	99
							64	GROUND ENGAGING TOOLS	99

	01-2024-464	REPAIR	CLOSED	02/01/2024		C			
	COMPLAINT THAT CAB WORK LIGHTS DONT WORK								
	-TRAVEL TO UNIT								
	-CHECK FUSES, FOUND F14 FUSE BLOWN. REPLACED FUSE BUT IT BLEW AS SOON AS THE LIGHTS WERE TURNED ON								
							27	ELECTRICAL SYSTEM	
							69	TRAVEL TIME	

	01-2024-1361	REPAIR	CLOSED	04/16/2024		C			
	OPERATOR STATES THE ENGINE AND TRANSMISSION IS OVERHEATING DURING NORMAL OPERATOR.								
	RAD IS PLUGGED WITH MUD AND FINE DUST. OPERATOR IS WASHING THE UNIT OUT BEFORE EACH SHIFT WITHOUT ALLOWING THE WATER TO DRY OR BLOWING IT OUT CAUSI								
							69	TRAVEL TIME	
							21	COOLING SYSTEM	

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							18	FASTNERS & TIE DOWNS	99
							11	AIR INTAKE SYSTEMS	99
							69	TRAVEL TIME	

	01-2024-3010	REPAIR	CLOSED	07/24/2024		C			
	COMPLAINT THAT AM/FM RADIO DID NOT WORK								
	ATTENDED MACHINE TO REPLACE RADIO AND THE USED RADIOS EMPLOYEE TOOK DIDN								
	'T WORK								
	TOOK RADIO FROM E-1803 TO TEST UNIT AND APPEARS THE SPEAKERS MAY NOT BE F								
	UNCTIONING PROPERLY								
							33	COMMUNICATIONS	

	01-2024-3057	REPAIR	CLOSED	07/26/2024		C			
	ERIC ASKED ME TO ORDER SPEAKERS FOR CAB AS CURRENT ONES NOT WORKING								
							27	ELECTRICAL SYSTEM	99

	01-2024-3607	REPAIR	CLOSED	08/27/2024		C			
	JOHN HOGAN EMAILED IN FOR AIR FILTERS								
							11	AIR INTAKE SYSTEMS	99

	01-2024-4481	REPAIR	CLOSED	10/23/2024		C			
	JOHN HOGAN EMAILED IN FOR ENGINE OIL								
							00	ENGINE	99

END OF REPORT									