

# Unit # BTP 56

# ALLAT

Mileage\_\_\_\_\_

Hrs\_\_\_\_\_

EOI-28  
BLUE

Serial # 82A188

Date	Description of Work	Parts Costs	Labour Costs
Oct 2 /13	Change lift pump and replace with used one. Repair head. Repair right side auger bearing. Replace all fuel line. Drain out fuel tank (clean out) and install new fuel filters.		
NOV/13	FABRICATE NEW AIR INTAKE FOR ENGINE, CHECK AND REPAIR QUGERS – NEW BUSHINGS AND BEARINGS, CHECK DRIVE CHAINS – INSTALL NEW CHAINS 100 HD, WASH, CHECK FLUID IN FINAL DRIVES (GILBERT & LEO) INSTALL SOME NEW SECTIONS ON AUGERS.		
Dec 2-14	Change engine. Install new chime coupler chains (hydro pumps). Check drive chains. Change auger bearings. Change screen bearings. Change some hyd hoses under engine. Wash. Install new propane torches.		
Oct 29/15 WO#0174	Change bearing on augers and screed. Check chains (drive)- Ok. Change oil and service engine (Check all fluid levels). Repair fuel brake. Wash. Reseal forward and reverse control valve. Reseal right hand side extention cylinder. Repair bolts on tracks. Repair spray gun. Check oil in final drives.		
Nov 10/17 wo0255	Wash,sevice engine, check drive chains & adjust. Install new chains for augers. Install new auger bearings & adj bearings. Repair tracks, replace broken bolts. Repair torches for screed. Install new pins & bushings .		
Nov15/18 WO#0276	Wash, service engine. New air filter. Check all fluids, check drive chains and sprockets.(good) New screed adj. bearings. New auger bearings. Check bolts on tracks. Repair hydraulic cylinder. LHS gate.		
Nov 4/19 WO#0314	Wash. Change oil and grease. Change sprockets and chains. Install new auger and bearings. Install new screed and adjust bearings.		
Dec8/20 WO#0412	Wash. Check drive chains and replace liftside (newchain). Change out screed bearings. Change out auger bearings. Service engine (change oil).		
May4/21 WO#0454	Check air filter, levels and start to get ready for season.		
Nov3/21 WO#0434	Wash. Check drive chains. Change oil in engine. Change out track to good used ones. Repair idler wheel.		
July11/22 WO#0666	Work on charging system on small paver. System tested ok. Is charging 13.5 and should be ok.		
Dec14/23 WO#0577	Wash. Service engine. Repair Hydraulic leak. Adjust drive chains.		