

EOI-51  
BLUE

# Unit # BTP 88

# 1997 IHC

SERIAL # VC023130

Date	Description of Work	Parts Costs	Labour Costs
Jan/13 WO#0003	Repair output seal on 2 axle differential, clean battery posts & service batteries. Change input pinion seal #3 axle. Do all brakes, front axle & 2 rear axles, adjust clutch. New slack adjuster RR #3 axles, new seals all wheels. Torque wheels 450 lbs. Reseal #2 axle diff. (GILBERT & LEO) CVIP(B&D) MILEAGE 242,525	88.96 190.23	
JUL/13 WO#55	REPLACE BATTERIES & SERVICE, CHECK ALL FLUIDS, CHECK ALL LIGHTS, CHECK ALL TIRE PRESSURES (LEO) MILEAGE 242,525	568.64	
AUG/13 WO#62	Replace left front steer tire with good used one, send unit to B&D for alignment (B&D)		
AUG/13 WO#67	Remove PTO and trans from truck, repair bolts and thread on clutch housing, install PTO and transmission, adjust clutch, repair fuel leak, replace splitter valve, install new windshield washer tank and pump assembly, replace #2 axle sway bar, check trans fluid and grease. (LEO) MILEAGE 254196.5		
Nov/13 WO #84	Repair front grill (made new grill), check transmission oil leak, change input shaft bearing & seal trans. check clutch, install Pilot bearing & release bearing. Install new torque arm on #3 axle. CVIP install new straps on v joint #2axle input (install new Wipers) Weld crack in front bumper & repair left fender. Change glade hands , rubbers seals on truck MILEAGE 255,270		
Nov 27/14	Install new air filter. Install new CB radio and antennas and cable. Repair hood cable. Check all lights and repair. Install new relay switch for tarp. Install new am/fm radio. 274,330 Gilbert		
Jan 13-15	CVIP, change brake pot #3 axle. Right side. Change backing plate. Repair battery cable. Wire truck for ABS cable. Mileage: 274334.8		
Sept-24-15	Install 4 new batteries (supplied by RP&S. Mileage 274335 Serial N# VC023130 Model 9300		
Feb 12/16 WO#0202	CVIP. Repair exhaust leak at muffler. Repair trailer hook up light. Put new mud flap-RH Side. Check all fluids and grease. Check tire pressure. Mileage: 274338 CVIP done by B&D Industrial		
Feb 17/17	CVIP done by B&D Industrial Service – Invoice #22298	351.20	
Jan17/17 WO#0222	Remove all wheels for CVIP, service truck, grease, fill diffs with oil, install new seals. MILEAGE 276157		
Jan 9/18	CVIP done by B & D Industrial: Invoice 24219	361.07	
Jan 12/18 WO#0263	CVIP done. Rotate rear wheels. Adjust toe in and install new front tires. MILEAGE 303371		

BTP88			
Dec 10/18	CVIP new front tires, change out hyd tank (old one leaking), install new muffler & check exhaust leak at manifold, new tank brackets, repair all lights, new windshield lh side, repair rust build up on air bag cross members, repara cab shock & buhings, repair exhaust manifold leak		
Jan20/2020 WO#0318	CVIP. Repair coolant hose. Change shock on RHS #2 axle. RH front clevis pin loose. RH air tank valve seized. (repaired) Red glad hand leak. (new seal) Adjust all brakes. Repair windshield washer. Heater ok and lower head lamps ok. Clean battery connections. Repair brake indicator lamp. TRUCK IS NOT WIRED OR DOES NOT HAVE A CIRCUIT FOR E BRAKE LIGHT.		
July2/20 WO#0369	Start mounting and disconnect switches on batteries. Completed BTP88. Disconnect switches.		
Dec 2/2020 WO#0401	CVIP. Wash and check all lights. Check and repair u joint cap. Repair exhaust leak at muffler. Loosen #3 LH clevis pin. (change pin). Adjust brakes on truck. #2 and #3 RH brake pot hoses rubbing. MILEAGE 307781		
Apr14/21 WO#0396	ABS not working on trailer. No power coming from truck to trailer. Trace wiring back.		
Nov9/2021 WO#0437	CVIP. Wash. All repairs as per list done. MILEAGE 313628		
Nov12/21 WO#0486	CVIP. Repairs as per list.		
Dec8/22 WO#0544	CVIP. Change fuel filters and check valve in full processor. Remove front wheel and measure drums. MILEAGE 313882.7		
Nov20/23 WO#0565	CVIP. Remove front wheels and measure brakes. Install new strap kit on front drive input. Repair diff leak. (change oil in front diff.) Install first aid kit.		
OCT16/25 WO#0593	WASH AND CLEAN CAB. INSTALL NEW BATTERIES. CVIP. CHANGE OUT EXHAUST CLAMP.		