

Unit # BTP 66

1970 CHEV C60

E01-73
BLUE

SERIAL # CE6371119624

Date	Description of Work	Parts Costs	Labour Costs
JAN/13 WO#0013	CHANGE OIL, REPAIR DOOR & WINDOW, INSTALL NEW TAIL LAMP, INSTALL NEW ID LAMP, CHANGE OIL IN DISTRIBUTOR, MOUNT ELECTRIC FUEL PUMP, INSTALL TWO NEW TIGER TORCHES, REPAIR AIR LINE ON COMPRESSOR, REPAIR SPEEDO, ADJUST CLUTCH (GILBERT)		
JUN/13 WO#51	INSTALL NEW STARTER ON POWER UNIT (LEO) MILEAGE 961604	326.20	
JUL/13 WO#57	REPAIR SPRAY BAR CYLINDER, INSTALL NEW SEAL KIT (LEO)		
Jan 8/14	CVIP, change engine oil & check all fluids, change oil in power unit, check all lights, check air in tires, change oil in compressor. Left rear inside tire flat, fix tube. Change output seal at trans & repair & reline e brake.		
Feb 3-15	Service, CVIP, repair engine oil leak, new valve cover gaskets, adjust park brake, repair dash lights, check tires, repair flat new tube. Change oil in small engine. Repair 3 way valve install new spring. Install new battery for main engine (truck) repair all dash lights. Spray bar needs work waiting until spring to do the work outside. Mileage: 96573.1		
Jan 27/16 WO #0192	Service: check all fluids, check all lights, check all tires (air pressure). CVIP – Pass CVIP done by B&D Industrial		
Jan30/17 WO#0227	Remove all wheels for CVIP, install new seals, new front brake drums, install new wiper blades. MILEAGE 96740		
Jan31/17	CVIP done by B&D Industrial	290.62	318.88
May 8/17 WO#0244	Remove power unit from distributor, take out clutch. Reline clutch at Edmonton Brake. Reinstall clutch & install power unit. Make new hose. Fabricate & install new front bumper. Wash & repair wiring on power unit. Mileage 96742.5		
Jan 24/18 WO#0268	CVIP. Repair as requested. Repair accelerator. Change out right side exhaust manifold. Change fan belts. Secure fire extinguisher. Change oil in both engines. Mileage 96833		
Jan25/18	CVIP done by B & D Industrial: Invoice 24341	361.07	
Jan8/19 WO#0294	CVIP. Service engine. Install rebuilt booster(rebuilt by Superior Frictions) Repair signal and hazard lights. Oil tank fasteners loose-retighten. Mileage 96957		
Jan 27/20 WO#0325	CVIP. Adjust park brake. Check oil leak dripping onto brakes. Check all lights. (including instrument lights) Check back-up alarm. Install bulk head tape. Install reflectors. Check hold down bolts on tank. Install new spring on transfer valve. Change two circulation hoses. Remove wheels from unit and measure brakes. Mileage 97199.7		
DEC 8/20 WO#0410	CVIP. Engine tune up (Bert G). Set up parking brake and install new nuts on axle flanges. Mileage 97293.7		
Dec8/20 WO0385	Tune up unit, replaced spark plugs and rotor. Set timing and carb. Set up E brake on unit, and complete CVIP list.		

	BTB 66		
June4/21 WO#0460	Rewire battery feed to charge battery at rear of unit to run tac oil motor.		
Nov24/21 WO#0490	CVIP. Check broken booster. Booster lacking vacuum. Adjust all brakes and drop off at B&D.		
Nov22/21 WO#0449	CVIP. Repair brakes. Remove wheels for inspection. Mileage 97457		
Apr11/22 WO#0509	Change oil and filter. Grease and check all fluids and add. Check air in tires and add. Check and add fluid in distributor. Mileage 97458		
July6/22 WO#0664	Engine not running properly. Check magneto and carburetor. Pulled mag and check cap, rotor, and point all look good. Adjust points to .015 gap. Installed mag and pulled carb and cleaned. Very dirty inside and outside. Soak carb in varsol to clean tack oil on outside of carb. Assembled carb and set up. Look at engine again. Pulled mag again and all good. Adjusted governor. Linkage is loose. Increase RPM and is now pulling load.		
Nov25/22 WO#0539	CVIP. Repair rear power unit (Hercules engine) Repair heater fan. Repair dash lights. Install new exhaust, instake manifold corburator. Parts from Hercules Propulsion in Ohio USA. Mileage 97534.5		
Nov10/23 WO#0558	CVIP. Check all lights. Recharge First aid kit (replaced with a new one) Remove wheels & inspect brakes and drum. Mileage 97596.3		
OCT16/25 WO#0589	WASH AND CLEAN CAB. INSTALL NEW BATTERY. CHECK AND REPAIR ALL LIGHTS. CVIP		