



3010 - 50th Avenue · Red Deer, Alberta T4R 1M5
 Parts Direct (403) 343-2433 · Parts Fax (403) 346-1751
 www.mgmfordlincoln.com

DISCLAIMER OF WARRANTIES

Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

X07-1
GR-FEB:

ALL CLAIMS AND RETURNED GOODS MUST BE ACCOMPANIED BY THIS INVOICE. NO RETURNS ON ELECTRICAL OR SPECIAL ORDER PARTS. NO RETURNS AFTER 30 DAYS. 25% RE-STOCK CHARGE ON ALL RETURNED PARTS.

DATE ENTERED 17 DEC 25	YOUR ORDER NO. NEE99041	DATE SHIPPED 17 DEC 25	INVOICE DATE 17 DEC 25	INVOICE NUMBER 201579
---------------------------	----------------------------	---------------------------	---------------------------	--------------------------

S
O
L
D
T
O

ACCOUNT NO.
CAN AM AUTO INC

S
H
I
P
T
O

PAGE 1 OF 1

SHIP VIA DELIVER		SLSM. 3856	B/L NO.	TERMS WCHG	F.O.B. RED DEER, AB	
QTY 1	SHIP 1	B.O. 0	PART NUMBER LC3Z*17626*AA	DESCRIPTION MEZ-6 PANEL	LIST 467.71	NET AMOUNT 280.63
			METHOD OF PAYMENT: WCHG			
R103663001				PARTS	280.63	
				SUBLET		
				FREIGHT	0.00	
				SALES TAX	14.03	
15:21				TOTAL	\$294.66	

*Thank
You
For
Your
Business!*

CUSTOMER COPY

90 MGM FORD-LINCOLN

3010 - 50th Avenue · Red Deer, Alberta T4R 1M5
 Parts Direct (403) 343-2433 · Parts Fax (403) 346-1751
 www.mgmfordlincoln.com

DISCLAIMER OF WARRANTIES

Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

ALL CLAIMS AND RETURNED GOODS MUST BE ACCOMPANIED BY THIS INVOICE. NO RETURNS ON ELECTRICAL OR SPECIAL ORDER PARTS. NO RETURNS AFTER 30 DAYS. 25% RE-STOCK CHARGE ON ALL RETURNED PARTS.

DATE ENTERED 03 DEC 25	YOUR ORDER NO. NEE99041	DATE SHIPPED 03 DEC 25	INVOICE DATE 03 DEC 25	INVOICE NUMBER 201038
---------------------------	----------------------------	---------------------------	---------------------------	--------------------------

ACCOUNT NO.
CAN AM AUTO INC

PAGE 2 OF 2

S
O
L
D
T
O

S
H
I
P
T
O

SHIP VIA DELIVER	SLSM. 3153	B/L NO.	TERMS WCHG	F.O.B. RED DEER, AB			
ORD.	SHIP	B.O.	PART NUMBER	DESCRIPTION	LIST	NET	AMOUNT
ALL PARTS IN STOCK METHOD OF PAYMENT: WCHG							
R103663001				PARTS			817.26
10:00				SUBLET			
				FREIGHT			0.00
				SALES TAX			40.85
				TOTAL			\$858.11

*Thank
You
For
Your
Business!*

CUSTOMER COPY



FORD-LINCOLN

3010 - 50th Avenue · Red Deer, Alberta T4R 1M5
Parts Direct (403) 343-2433 · Parts Fax (403) 346-1751
www.mgmfordlincoln.com

DISCLAIMER OF WARRANTIES

Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

ALL CLAIMS AND RETURNED GOODS MUST BE ACCOMPANIED BY THIS INVOICE. NO RETURNS ON ELECTRICAL OR SPECIAL ORDER PARTS. NO RETURNS AFTER 30 DAYS. 25% RE-STOCK CHARGE ON ALL RETURNED PARTS.

DATE ENTERED	YOUR ORDER NO.	DATE SHIPPED	INVOICE DATE	INVOICE NUMBER
03 DEC 25	NEE99041	03 DEC 25	03 DEC 25	201030

ACCOUNT NO.

PAGE 1 OF 1

S
L
P
T
O
S
H
I
P
P
T
O

CAN AM AUTO INC
PO BOX 21147 RPO BOWER MALL
RED DEER, AB T4R 2M1

SHIP VIA	SLSM.	B/L NO.	TERMS	WCHG	F.O.B.	RED DEER, AB
DELIVER	3856					
ORD SHIP	B.O.	PART NUMBER	DESCRIPTION	LIST	NET	AMOUNT
1	0	VHC3Z*16C900*C	*OB50	137.90	125.49	125.49
METHOD OF PAYMENT: WCHG						
PARTS 125.49						
SUBLET 0.00						
FREIGHT 6.27						
SALES TAX						
TOTAL \$131.76						

Thank
You
For
Your
Business!

R103663001

08:35

CUSTOMER COPY

90 MGM FORD-LINCOLN

3010 - 50th Avenue · Red Deer, Alberta T4R 1M5
 Parts Direct (403) 343-2433 · Parts Fax (403) 346-1751
 www.mgmfordlincoln.com

DISCLAIMER OF WARRANTIES

Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

ALL CLAIMS AND RETURNED GOODS MUST BE ACCOMPANIED BY THIS INVOICE. NO RETURNS ON ELECTRICAL OR SPECIAL ORDER PARTS. NO RETURNS AFTER 30 DAYS. 25% RE-STOCK CHARGE ON ALL RETURNED PARTS.

DATE ENTERED 20 NOV 25	YOUR ORDER NO. NKF03149	DATE SHIPPED 21 NOV 25	INVOICE DATE 21 NOV 25	INVOICE NUMBER 200515
---------------------------	----------------------------	---------------------------	---------------------------	--------------------------

S
O
L
D
T
O

ACCOUNT NO.
CAN AM AUTO INC

S
H
I
P
T
O

PAGE 1 OF 1

SHIP VIA DELIVER	SLSM. 3856	B/L NO.	TERMS WCHG	F.O.B. RED DEER, AB			
ORD.	SHIP	B.O.	PART NUMBER	DESCRIPTION	LIST	NET	AMOUNT
1	1	0	NL3Z*1562901*FB METHOD OF PAYMENT: WCHG	COVER	338.10	202.87	202.87
R103663001						PARTS	202.87
						SUBLET	
						FREIGHT	0.00
						SALES TAX	10.14
						TOTAL	\$213.01

*Thank
You
For
Your
Business!*

07:24

CUSTOMER COPY



1FT8W3B69NEE99041

Date Completed: _____

Year: 2022 Make/Model: F350 Serial #: 25NEE99041

Can-Am Inspection/Work Report

Exterior	
Drivers' side Body	
Pass side Body	
Front End Body	
Grill/Bumper	
Rear end Body	
Bumper	
Tail Lights	
Roof	
Hood Release	
Windshiled	
Side Windows	
Pass Mirror	
Drivers Mirror	
Drivers Front Tire	
Tread	
Sidewall	
Rims	
Pressure	
Pass Front / Tire	
Tread	
Sidewall	
Rims	
Pressure	
Drivers Rear Tire	
Tread	
Sidewall	
Rims	
Pressure	
Pass Rear Tire	
Tread	
Sidewall	
Rims	
Pressure	

Mechanical	
Oil	
Trans Fluid Level	
Brake Fluid	
Coolent Level	
Radiator	
Radiator Hoses	
Belts/Pully's	
Power Steering Fluid/operation	
Washer Fluid	
Battery Connections	
Battery Load Test	
Head Lights Hi/Low	
Turn Signals	
Hazards	
Reverse Lights	
Oil Leaks	
Exhaust System	
Drive Line/U-Joints	
Frame	
Spare Tire	
Brakes/ABS	
Drivers Front	
Brake Pad	
Rotor	
Pass Front	
Brake Pad	
Rotor	
Drivers Rear	
Brake Pad	
Rotor	
Pass Rear	
Brake Pad	
Rotor	

Interior	
Horn	
Dash	
Interior Mirror	
Door Locks	
Tilt Wheel	
No ABS Lights	
Guages	
Radio	
Nav	
Back up Camera	
Wipers	
Heater/A/C	
Driver Seat Belt	
Driver Seat Adj	
Front Seats Condition	
Rear Seats Condition	
Carpets	
Headliner	
Sun Roof	
Park Brake	
4x4 engage Hi/Low	
Engine Starter	
Engine Runs Smooth	

TOTAL HRS

TOTAL PARTS

MECHANIC INITIAL

OFFICE INITIAL

TOTAL CHARGE

COMMENTS/REPAIRS REQUIRED	DATE/HOURS
Wind map	
Brig Deflectors broken	
RIP Airt. Seal leaking	
Both vacuum seals don't hold vacuum	
Reverse loop out RR	
Both Port Side Mucles humata	
LR lower stop lamp bulb out	
LH license plate bulb out	
RR upper/lower bulbs map tail lamp broken	
p0496 evap system high purge flow pending	
p0420 Cat system efficiency below threshold bank 1	

INSPECTOR SIGNATURE: _____