

X07-3.
GR-FEB



Date Completed: 12.22/29

Year: 22 Make/Model: F150 Serial #: 25NKFO3149

Can-Am Inspection/Work Report

| Exterior | |
|--------------------|--|
| Drivers side Body | |
| Pass side Body | |
| Front End Body | |
| Grill/Bumper | |
| Rear end Body | |
| Bumper | |
| Tail Lights | |
| Roof | |
| Hood Release | |
| Windshiled | |
| Side Windows | |
| Pass Mirror | |
| Drivers Mirror | |
| Drivers Front Tire | |
| Tread | |
| Sidewall | |
| Rims | |
| Pressure | |
| Pass Front / Tire | |
| Tread | |
| Sidewall | |
| Rims | |
| Pressure | |
| Drivers Rear Tire | |
| Tread | |
| Sidewall | |
| Rims | |
| Pressure | |
| Pass Rear Tire | |
| Tread | |
| Sidewall | |
| Rims | |
| Pressure | |

| Mechanical | |
|--------------------------------|--|
| Oil | |
| Trans Fluid Level | |
| Brake Fluid | |
| Coolent Level | |
| Radiator | |
| Radiator Hoses | |
| Belts/Pully's | |
| Power Steering Fluid/operation | |
| Washer Fluid | |
| Battery Connections | |
| Battery Load Test | |
| Head Lights Hi/Low | |
| Turn Signals | |
| Hazards | |
| Reverse Lights | |
| Oil Leaks | |
| Exhaust System | |
| Drive Line/U-Joints | |
| Frame | |
| Spare Tire | |
| Brakes/ABS | |
| Drivers Front | |
| Brake Pad | |
| Rotor | |
| Pass Front | |
| Brake Pad | |
| Rotor | |
| Drivers Rear | |
| Brake Pad | |
| Rotor | |
| Pass Rear | |
| Brake Pad | |
| Rotor | |

| Interior | |
|-----------------------|--|
| Horn | |
| Dash | |
| Interior Mirror | |
| Door Locks | |
| Tilt Wheel | |
| No ABS Lights | |
| Guages | |
| Radio | |
| Nav | |
| Back up Camera | |
| Wipers | |
| Heater/A/C | |
| Driver Seat Belt | |
| Driver Seat Adj | |
| Front Seats Condition | |
| Rear Seats Condition | |
| Carpets | |
| Headliner | |
| Sun Roof | |
| Park Brake | |
| 4x4 engage Hi/Low | |
| Engine Starter | |
| Engine Runs Smooth | |

TOTAL HRS

TOTAL PARTS

MECHANIC INITIAL
C.S

OFFICE INITIAL
T.K.

TOTAL CHARGE
2.0 hr.

