

X07-6
GR-FRB

1FT8W3BT9MED83875

Date Completed: JAN. 27/26

Year: 2021

Make/Model: F-1000

350

Serial #: 24 MED83875

Can-Am Inspection/Work Report

Exterior

| | |
|--------------------|--|
| Drivers side Body | |
| Pass side Body | |
| Front End Body | |
| Grill/Bumper | |
| Rear end Body | |
| Bumper | |
| Tail Lights | |
| Roof | |
| Hood Release | |
| Windshield | |
| Side Windows | |
| Pass Mirror | |
| Drivers Mirror | |
| Drivers Front Tire | |

| | |
|----------|--|
| Tread | |
| Sidewall | |
| Rims | |
| Pressure | |

Pass Front / Tire

| | |
|----------|--|
| Tread | |
| Sidewall | |
| Rims | |
| Pressure | |

Drivers Rear Tire

| | |
|----------|--|
| Tread | |
| Sidewall | |
| Rims | |
| Pressure | |

Pass Rear Tire

| | |
|----------|--|
| Tread | |
| Sidewall | |
| Rims | |
| Pressure | |

TOTAL HRS

Mechanical

| | |
|--------------------------------|-----------|
| Oil | |
| Trans Fluid Level | |
| Brake Fluid | |
| Coolent Level | |
| Radiator | |
| Radiator Hoses | |
| Belts/Pully's | |
| Power Steering Fluid/operation | |
| Washer Fluid | |
| Battery Connections | |
| Battery Load Test | |
| Head Lights Hi/Low | |
| Turn Signals | |
| Hazards | |
| Reverse Lights | |
| Oil Leaks | |
| Exhaust System | |
| Drive Line/U-Joints | |
| Frame | |
| Spare Tire | |
| Brakes/ABS | |
| Drivers Front | |
| | Brake Pad |
| | Rotor |
| Pass Front | |
| | Brake Pad |
| | Rotor |
| Drivers Rear | |
| | Brake Pad |
| | Rotor |
| Pass Rear | |
| | Brake Pad |
| | Rotor |

Interior

| | |
|-----------------------|--|
| Horn | |
| Dash | |
| Interior Mirror | |
| Door Locks | |
| Tilt Wheel | |
| No ABS Lights | |
| Guages | |
| Radio | |
| Nav | |
| Back up Camera | |
| Wipers | |
| Heater/A/C | |
| Driver Seat Belt | |
| Driver Seat Adj | |
| Front Seats Condition | |
| Rear Seats Condition | |
| Carpets | |
| Headliner | |
| Sun Roof | |
| Park Brake | |
| 4x4 engage Hi/Low | |
| Engine Starter | |
| Engine Runs Smooth | |

MECHANIC INITIAL

C.S

OFFICE INITIAL

T.K.

TOTAL CHARGE

5.00

| COMMENTS/REPAIRS REQUIRED | DATE/HOURS |
|--|---------------|
| P221C Reduced heater to current bottom diag. | Jan 22 2.5hrs |
| Mgmt heater line. | Q#192 5/8 |
| Ontario 316.47, HC32-55249EE | |
| Remove & Replace Mgmt heater line. Perform | Jan 27 2.5hr |
| Service Room Verify Repair | |
| | |
| | |
| | |
| | |
| | |

INSPECTOR SIGNATURE: _____



IMGI
FORD-LINCOLN

DISCLAIMER OF WARRANTIES

Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of the product.

3010 - 50th Avenue • Red Deer, Alberta T4R 1M5
Parts Direct (403) 343-2433 • Parts Fax (403) 346-1751

www.mgmfordlincoln.com

1. 613 Direct (403) 343-2433 : Parts Fax (403) 346-1751
www.mgmfordlincoln.com

ACCOUNT NO. 21 JAN 26 NUMBER 2

PAGE 1 OF 1

0-4010
CAN AM AUTO INC
RECONN. NO. 0-4100
PAGE 1 OF 1



Automotive Village Red Deer
6870 Gaetz Ave
Red Deer, AB T4N 4E3
P: 403-314-9469
F: 403-343-2450

Page: 1 of 1

Bill To:
CAN-AM AUTO INC.

Ship To:
CAN-AM AUTO INC.

Invoice

RVN500725

GST Number:
88977 2109 RT0001

Order Number: MED83875

Web Order Number:

Invoice Date: 1/5/2026
Operator: CGS

Payment Terms: Net 10TH
Delivery Method: DLV - Deliver P

| Quantity Ordered | Quantity Shipped | Back Ordered | Part Number & Description | Code | List Price | Selling Price | Net Amount |
|------------------|------------------|--------------|---------------------------|------|------------|---------------|------------|
|------------------|------------------|--------------|---------------------------|------|------------|---------------|------------|


2021 Ford F-350 Super Duty 6.7L DIESEL V8-406 OHV (VIN T,MFI)

| | | | | | | | |
|---|---|-------------|----------------------|-----|--------|--------|--------|
| 1 | 0 | INTMTP-65HD | 30MFR 850CCA Battery | AVR | 284.58 | 199.97 | 199.97 |
| 1 | 0 | INTMTP-65HD | ** CORE CHARGE ** | | 16.00 | 16.00 | 16.00 |

We are open 7 days a week to serve our customers
Monday to Friday 8 to 8, Saturday 8 to 6 and Sunday 9 to 5

| | | |
|----------------------|-------------|--------|
| Goods Received By: | Net Total | 215.97 |
| | Tax | 10.80 |
| Time Prepared: 11:16 | Grand Total | 226.77 |

Thank You For Your Business!



SO # 1262722

Status

**SERVICE INVOICE
CUSTOMER COPY**



User

991451

Page 1

| | | | | | |
|------------------|---------------|-----------------------------|----------------------|---------------------|-----------------|
| Customer No | Advisor | Josh Torres | Promised | 12/30/2025 5:00 PM | Tag# |
| CAN-AM AUTO INC. | Shop | S2 | Opened | 12/30/2025 12:25 PM | Location, |
| | Priority | | Cashiered | | PO # 2411083875 |
| Home | License | Odom In | Odom Out | In Service Date | Stock No |
| Cell | | 162615 | 162615 | | |
| Email | Year | Make | Model | Model Number | Colour |
| | 2021 | FORD | SUPER DUTY F-350 SRW | W3B | |
| | Vehicle ID No | Selling Dealer | Extended Warranty | | Delivery Date |
| | | 1FT8W3BT9MED83875 | | | |
| | Engine | 6.7L 4V OHV POWER STROKE V8 | Fleet # | | |
| Type W | | | | | |
| Term Charge | | | | | |

| Request | Description | Job | CSR | Status |
|------------|--|-----|--------|-------------------|
| MA11 | LUBE, OIL AND FILTER CHANGE - DIESEL | 1 | 991451 | Original |
| Labour | Description | | | Amount |
| MA11 | LUBE, OIL AND FILTER CHANGE - DIESEL | | | 44.99 |
| MA11 | LUBE, OIL AND FILTER CHANGE - DIESEL | | | 0.00 |
| Part | Description | Shp | SL | Amount |
| 19254719 | FILTER | 1 | 10607 | 49.30 |
| 88865794 | 15W40 BULK OIL | 10 | TANK | 5.25 |
| ENV50 | ENVIRONMENTAL CHARGE | 3 | SOP | 0.55 |
| 88865794 | 15W40 BULK OIL | 3 | TANK | 5.99 |
| ENV10 | FEES | 3 | SOP | 0.11 |
| Technician | 991451 - Josh Torres 991462 - Vanden Nguyen | | | Parts Total |
| | | | | 121.75 |
| Cause | LUBE, OIL AND FILTER | | | Labour Total |
| Correction | Engine Oil & Filter changed, Completed Inspection Tire pressures set to spec, oil life reset and windshield sticker replaced WT; VANDEN DT; JOSH TIRES 13/32nds ALL AROUND AIR FILTER YELLOW CABIN FILTER YELLOW WIPERS GOOD TIRE PRESSURE SET TO SPEC DRIVELINE CLEAN NO LEAKS COOLANT LEVEL IS LOW | | | Request Sub-total |
| | | | | 166.74 |

| Request | Description | Job | CSR | Status |
|-------------|---|-----|--------|----------|
| GM MPVI STD | GM MPVI Standard | 2 | 991451 | Original |
| Request | Description | Job | CSR | Status |
| GMS | You may receive an email survey from General Motors in the next few weeks regarding your visit. If for any reason you cannot grade us COMPLETELY SATISFIED please contact your service consultant. Thank you. | 3 | 991451 | Original |
| Labour | Description | | | Amount |
| GMS | You may receive an email survey from General Motors in the next few weeks regarding your visit. If for any reason you cannot grade us COMPLETELY SATISFIED please contact your service consultant. Thank you. | | | 0.00 |
| Technician | 999 - Sublet Technician | | | |

SO # 1262722

Status

**SERVICE INVOICE
CUSTOMER COPY**



User 991451

Page 2

| | | | | |
|--------------------|--|--|--|--|
| Customer No | | | | |
| CAN-AM AUTO INC. | | | | |
| Home | | | | |
| Cell | | | | |
| Email | | | | |
| Type | | | | |
| W | | | | |
| Term Charge | | | | |

| | | | | |
|----------------------|------------------------------------|--------------------------|------------------------|-----------------|
| Advisor | Josh Torres | Promised | 12/30/2025 5:00 PM | Tag# |
| Shop | S2 | Opened | 12/30/2025 12:25 PM | Location |
| Priority | | Cashiered | | PO # |
| License | Odom In | Odom Out | In Service Date | Stock No |
| | 162615 | 162615 | | |
| Year | Make | Model | Model Number | Colour |
| 2021 | FORD | SUPER DUTY F-350 SRW | W3B | |
| Vehicle ID No | Selling Dealer | Extended Warranty | Delivery Date | |
| 1FT8W3BT9MED83875 | | | | |
| Engine | 6.7L 4V OHV POWER STROKE V8 | Fleet # | | |

| | |
|----------------------|---------------|
| Labour | 44.99 |
| Parts | 121.75 |
| Supplies | 3.00 |
| Sub-Total | 169.74 |
| GST | 8.49 |
| Total Invoice | 178.23 |

| | |
|--------------------------------|-------------------|
| VIN: 1FT8W3BT9MED83875 | RO #: 1262722 |
| Customer: CAN-AM AUTO INC. | Date: 12/30/2025 |
| Model: | Year: |
| Advisor: 991246 - Noel Melchor | Odometer: 162,615 |

KIPP SCOTT GMC BUICK
6841 50th Avenue Red Deer, AB T4N 4E2
Phone: null
<https://www.kippscott.ca/>

Recommended Maintenance - Modified (K1)

PERFORM 160,000KM SERVICE

Additional

- LUBE, OIL AND FILTER CHANGE - DIESEL

Declined

- PERFORM Engine Oil & Filter Replacement - Dexos
- INSTALL Engine Oil Fortifier - Improved Engine Protection
- PERFORM MPVI Multipoint Inspection - "Health check" - INCLUDES Tire Rotation
- PERFORM Cooling System Service - Dex Cool
- REPLACE Windshield Wipers
- REPLACE Cabin Air Filter - Gas Vehicles
- PERFORM Four Wheel Alignment - Stock Vehicle

Maintenance

| | |
|---------------|------------------|
| Menu Total: | \$ 140.00 |
| Shop Charges: | \$ 18.20 |
| Tax: | \$ 7.91 |
| TOTAL: | \$ 166.11 |

ACCEPTED

Services suggested in this maintenance schedule are this dealer's recommendations. Although this schedule may contain manufacturer's general recommendations our maintenance schedules are designed to meet the demands of area weather and driving conditions. Prices do not include sales tax. Some prices may vary by model and are subject to change without notice.

Customer Signature

MULTI-POINT VEHICLE INSPECTION

Customer: CAN-AM AUTO INC.
 Service Order: 1262722
 Service Advisor: Josh Torres
 Technician: Josh Torres

Vehicle: 2021 FORD SUPER DUTY F-350 SRW
 VIN: 1FT8W3BT9MED83875
 Odometer:
 Date:

KIPP SCOTT

GMC  **BUICK**

Checked and OK

May Require Attention Soon

Requires Immediate Attention

Not Applicable

ONSTAR DIAGNOSTICS

- OnStar Active
- Enrolled in Advanced Diagnostics Report
- Enrolled in Dealer Maintenance Notification
- Service History/Recall Check

ENGINE OIL & FILTER

- Engine oil life
- % Oil life monitor
- Reset oil life monitor

LIGHTS

- Exterior lights

WINDSHIELD & WIPERS

- Wiper blade-driver
- Wiper blade-passenger
- Wiper blade-rear
- Windshield condition

BATTERY

- X Battery test results - _____ volts
- X Battery visual inspection
- X Battery cables & connections

SYSTEMS, FLUIDS & VISIBLE LEAK INSPECTION

Filled?

- Engine oil X
- Transmission X
- Drive axle X
- Transfer case X
- Engine cooling system X
- Power steering X
- Fuel system X
- Brake fluid reservoir X
- Windshield washer fluid X
- Diesel exhaust fluid X

TIRE INSPECTION

| | |
|---|--|
| Driver Front psi before _____ psi set to _____ <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> Tread depth <u>13</u> /32" <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> Wear pattern/damage | Passenger Front psi before _____ psi set to _____ <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> Tread depth <u>13</u> /32" <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> Wear pattern/damage |
| Driver Rear psi before _____ psi set to _____ <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> Tread depth <u>13</u> /32" <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> Wear pattern/damage | Passenger Rear psi before _____ psi set to _____ <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> Tread depth <u>13</u> /32" <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> Wear pattern/damage |
| Tire Inspection <input checked="" type="checkbox"/> X Balance needed <input checked="" type="checkbox"/> X Rotation needed <input checked="" type="checkbox"/> X Alignment needed | <input checked="" type="checkbox"/> X Reset tire pressure monitor |

BRAKES

| | |
|---|---|
| Front Brakes mm <input checked="" type="checkbox"/> X Driver front _____ <input checked="" type="checkbox"/> X Passenger front _____ | Rear Brakes mm <input checked="" type="checkbox"/> X Driver rear disc brake _____ <input checked="" type="checkbox"/> X Passenger rear disc brake _____ <input checked="" type="checkbox"/> X Driver rear drum brake _____ <input checked="" type="checkbox"/> X Passenger rear drum brake _____ |
| Brake Inspection <input checked="" type="checkbox"/> X Brake system <input checked="" type="checkbox"/> X Parking brake | |

VISIBLE & FUNCTIONAL INSPECTIONS

| INSPECT (FIT, FORM, & FUNCTION) | CHECK OPERATION |
|--|--|
| <input checked="" type="checkbox"/> Safety belt components | <input checked="" type="checkbox"/> Horn |
| <input checked="" type="checkbox"/> Exhaust system | <input checked="" type="checkbox"/> Ignition lock |
| <input checked="" type="checkbox"/> Accelerator pedal | <input checked="" type="checkbox"/> Starter switch |
| <input checked="" type="checkbox"/> Passenger compartment air filter | <input checked="" type="checkbox"/> Evaporative control system |
| <input checked="" type="checkbox"/> Engine air filter | <input checked="" type="checkbox"/> Backup camera |
| <input checked="" type="checkbox"/> Hoses | |
| <input checked="" type="checkbox"/> Belts | |
| <input checked="" type="checkbox"/> Shocks and struts | |
| <input checked="" type="checkbox"/> Steering components | |
| <input checked="" type="checkbox"/> Axle boots or driveshaft & u-joints | |
| <input checked="" type="checkbox"/> Compartment lift struts | |
| <input checked="" type="checkbox"/> Floor mat secured, no interference with pedals | |
| LUBRICATE | |
| | <input checked="" type="checkbox"/> Chassis components |

Comments: