

T23-4
BLUE-MAR

Unit Being Sold

Polished

WORK ORDER



| Part Number | Description | Cost |
|-------------|-------------|------|
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

Job#
Mechanic's name Mitch
Date Fri 12 / 26
M.M

Unit T1238
K.M 89,374
Location Adison

- Cui Limited
- RH Headlight Mtr - Replaced
- Chrome
- Polish
- LH Front Subframe Bolt Missing

SUBLET

| | | | | | |
|--|--|--|--------------|--------|--|
| | | | SUBLET: | | |
| | | | Shop Time: | Sublet | |
| | | | Total Hours: | Labour | |
| | | | | Parts | |
| | | | | G/S | |
| | | | Total Hours | Total | |

WORK ORDER



Job# _____

Mechanic's name _____

Date *MAR 9 2024*

Unit *TR238*

K.M. _____

H.M. _____

Location *AcH*

*Hook up To Pup
Re wire trailer plug
Re Boot trailer Air lines*

| Quan | Part Number | Discription | Cost |
|------|-------------|-------------|------|
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

SUBLET

| | | | | |
|--------------|--|--|--------|--|
| SUBLET: | | | Sublet | |
| Shop Time: | | | Labour | |
| Total Hours: | | | Parts | |
| | | | S/S | |
| Total Hours | | | Total | |

WORK ORDER



| Quan | Part Number | Discription | Cost |
|------|-------------|------------------------|------|
| 2 | 4896 | LIC LIGHT ASSY | |
| 1 | 614002 | Hand Red Light | |
| 2 | 1/2" | Quick Copper's Coolant | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

Unit TBL 238
K.M 13801
Location ACH

Job# _____
Mechanic's name JK
Date FEB 26 2024
H.M _____

- ✓ CHECK OVER FOR CUIP
- ✓ LIC LIGHT seal work done
- ✓ Right MARBLE WHEEL WORK DONE
- ✓ AIR UP TIRE'S TO 110

| | | | |
|--------|--|--|--|
| SUBLET | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

| | | |
|--------------|--------|--|
| SUBLET: | Sublet | |
| Shop Time: | Labour | |
| Total Hours: | Parts | |
| | S/S | |
| Total Hours | Total | |

WORK ORDER



| Quan | Part Number | Discription | Cost |
|------|-------------|-------------|------|
| 1 | A4731800909 | DEFLECTOR | |
| | 15-40 | OIL | |
| 1 | A4700903151 | FUEL | |
| 1 | A00083651 | FUEL | |
| 2 | 1100 24.5 | TIRE CHAIN | |
| 1 | 2 way | RAID | |

Pump unit

Unit TR 238

K.M 11347

Location Johnson

✓ Pick up unit
✓ DEFLECTOR CAP

✓ TIRE CHAINS
✓ 2 way RAID

✓ DRILL HOLES IN TOOL BOXES
✓ LOOSEN UP BOX ~~WITH~~ LUBS BRACKET

✓ SERVICE UNIT

✓ DECALS

✓ INSTALL AND SPILL DRAIN PLUG

✓ AIR UP TIRES

~~REMOVE~~ LICENSURE PLAT

Job#

Mechanic's name

Date JAN 22 / 21

H.M 293

FP 641 1144

SUBLET

SUBLET:

Shop Time:

Total Hours:

Total Hours

Sublet:

Labour

Parts

S/S

Total