

PO9-4  
MAY

## Maintenance Summary – Asset #6035

Total Maintenance Records: 515

Maintenance Period: 2012-08-22 to 2025-06-14

This equipment has been consistently maintained with documented service history.

## Detailed Maintenance Records

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2025-06-14 00:00:00	Cooling System	Road test overheating	Dominique Denis	3.0	11,399	Flush radiator with acid Missing lower radiator hose Job ongoing
2025-05-28 00:00:00	Cooling System	Road test overheating	Nik Delsordo	5.0	11,411	Removed grille and loosen to all cooling package mounting bolts. Tilt the cooling package forward. Removed and replaced fan, the existing fan clutch felt pretty tight/normal. P...
2025-05-21 00:00:00	Hydraulics	Build new box tip cylinder rod			11,399	-Build ram rod for haul truck -Freight (manitoulin) -Material 70mm IHCP x 103.50 -Machine new cylinder rod 10.5hr -Repair threads on trunnion 3/4hr
2025-05-20 00:00:00	Cylinder	box cylinder mounts worn out.			11,399	Build new rod for dump cylinder. Supply material + freight 70mm IHCP Machine new rod, repair threads on trunnion.
2025-05-20 00:00:00	Cooling System	Road test overheating	Ethan rich	1.5	11,398	Drained coolant flushed rad then re filled with coolant and bled system
2025-05-15 00:00:00	Cooling System	Road test overheating	Dominique Denis	9.0	11,399	Looking for overheating
2025-05-14 00:00:00	Cooling System	Road test overheating	Dominique Denis	1.0	11,399	Road test overheating
2025-05-13 00:00:00	Cylinder	box cylinder mounts worn out.	Dominique Denis	5.0	11,399	disassemble cylinder, could not remove trunnion. Remove rod from barrel.
2025-05-12 00:00:00	Cooling System	Change water pump	Dominique Denis	2.0	11,399	Coolant pressure test
2025-05-10 00:00:00	Cooling System	Change water pump	Dominique Denis	5.0	11,399	Finish water pump Put coolant Running Test
2025-05-09 00:00:00	Cylinder	box cylinder mounts worn out.	Dominique Denis	1.5	11,399	Work on Cylinder end
2025-05-08 00:00:00	Cylinder	Put back cylinder	Dominique Denis	1.0	11,399	Put back cylinder

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Maintenance	Description of Maintenance
2025-05-06 00:00:00	Cooling System	Change water pump	Dominique Denis	5.0	11,400	Change water pump
2025-04-27 00:00:00	Inspection	Post job inspection: Rear cab window cracked Body heat exhaust flex pipe Loose/wet hydraulic line by drop box Air leak on firewall Engine overheats leaks from bottom pan MDU 7003.0 ECU 110.0 ECU 1569.31 Middle diff plug leak			11,399	Correction: Chassis / Chassis / -Box heater flex hose disconnected -Rear engine bottom guards bent back -LH front strut sweating -Loose hydraulic by drop box -Rear window crac...
2025-04-21 00:00:00	Inspection	Post job inspection: Rear cab window cracked Body heat exhaust flex pipe Loose/wet hydraulic line by drop box Air leak on firewall Engine overheats leaks from bottom pan MDU 7003.0 ECU 110.0 ECU 1569.31 Middle diff plug leak	Kade Proctor	1.0	11,401	Inspect task gather materials and tools Remove old exhaust clamp and install new clamp and connect flex pipe Complete

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2025-04-21 00:00:00	Inspection	Post job inspection: Rear cab window cracked Body heat exhaust flex pipe Loose/wet hydraulic line by drop box Air leak on firewall Engine overheats leaks from bottom pan MDU 7003.0 ECU 110.0 ECU 1569.31 Middle diff plug leak	Kade Proctor	6.0	11,401	Inspect task gather materials and tools Diagnose active codes found codes for park lights (8013.5) and code for steering column 7000.31 Check all fuses the fuses were all good ...
2024-10-10 00:00:00	Inspect & Service	General inspect & repair	Kade Proctor	8.0	11,264	Change batteries, check all hoses, fluids, change leaking drain plug on middle diff, check all lights. Wash.
2024-10-07 00:00:00	Suspension	Front strut leaking	Nik Delsordo	4.0	11,264	Dissassemble front strut. Clean and prep for rebuild. Reseal internals and put back together. Fill with thf oil following procedure. Completed
2024-10-02 00:00:00	Drive Train	Left rear final drive cover leaking	Kade Proctor	4.0	11,264	Inspect task gather materials and tools Drain oil and remove left rear final drive cover Clean final cover and clean final Jack up rear axle to rotate final to install final ...
2024-09-27 00:00:00	Body	(Fix and install broken hood shock)	Kade Proctor	1.0	11,264	Inspect task gather materials and tools Remove damaged hood shock Use of welder to weld eye back onto shock Install shock and test Complete
2024-09-26 00:00:00	Suspension	(Front right shock damaged)	Kade Proctor	6.0	11,264	(Continue on installing shock) Jack up axle and install front right tire back on unit Use of nitrogen to fill both shocks to correct ride height Take unit for test drive Ins...

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2024-09-25 00:00:00	Suspension	(Front right shock damaged)			11,263	Assist with strut charge, lift unit with jack so strut was at ride height and fill nitrogen to 500 psi. lowered and test drive. readjust rideheight and confirm.
2024-09-18 00:00:00	Suspension	(Front right shock damaged)	Kade Proctor	8.0	11,263	(Continue on installing front right shock) -lift shock up into place -install top and bottom shock bolts -found that bottom bolt hole was damaged -use of tap to fix damage t...
2024-08-22 00:00:00	Engine	Engine light comes on intermittently	Kade Proctor	2.0	11,263	Inspect task gather materials and tools -Remove old pressure relief valve and fitting -install fitting on new pressure relief valve and install new valve -use of diagnostic t...
2024-08-19 00:00:00	Suspension	(Front right shock damaged)	Kade Proctor	2.0	11,263	Continue on removing front right shock -Use of jacks to lower down front axle -Release nitrogen from shock and remove shock from unit To be continued
2024-08-16 00:00:00	Engine	Engine light comes on intermittently	Kade Proctor	4.0	11,263	Inspect task gather materials and tools -Use of diagnostic tool to check for active and stored codes -Found that there was a code for low rail pressure changed out fuel rail pr...
2024-08-16 00:00:00	Suspension	(Front right shock damaged)	Kade Proctor	3.0	11,263	Inspect task gather materials and tools -Jack up front axle and remove tire -Remove shock guard -Remove top and bottom shock bolts To be continued

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2024-07-16 00:00:00	Engine	Air to air rad pipe broken clamps.	Henry Silva	3.0	11,235	Drove figure lake. On km 10. On left side engine. Air to air pipe that connects to the turbo. They put work clamp on hose Remove main pipe from air to air rad. Bottom clamp ...
2024-06-25 00:00:00	Servicing Needed	Drop Box Breather Filter Replace (2000hr)	Henry Silva	0.2	11,151	Complete
2024-06-25 00:00:00	Servicing Needed	Secondary Air Filter Replace (2000hr)	Henry Silva	0.1	11,151	Complete

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Maintenance	Description of Maintenance
2024-06-25 00:00:00	Cab	Inspect/Replace Cab Fresh and Recirculating Filters (600hr)	Henry Silva	0.1	11,151	Complete
2024-06-25 00:00:00	Servicing Needed	Replace Front Diff Oil (2000hr)	Henry Silva	0.5	11,151	Complete
2024-06-25 00:00:00	Inspection	Inspection check over	Henry Silva	4.0	11,151	When through the check list. Grease unit. Check lights. Repair wire wiper motor. Check pressure tires. Check all levels.
2024-06-25 00:00:00	Transmission	Transmission Oil Replace (1000hr)	Henry Silva	0.5	11,151	Complete
2024-06-25 00:00:00	Hydraulics	Replace Hydraulic Oil (4000hr)	Henry Silva	1.0	11,151	Complete
2024-06-25 00:00:00	Servicing Needed	Grease/Top Up (600hr)	Henry Silva	0.2	11,151	Complete
2024-06-25 00:00:00	Transmission	Transmission Oil Filter Replace (1000hr)	Henry Silva	0.5	11,151	Complete
2024-06-25 00:00:00	Steering	Inspect Steering Components (600hr)	Henry Silva	0.1	11,151	Complete
2024-06-25 00:00:00	Hydraulics	Hydraulic Oil Filter Replace (1000hr)	Henry Silva	0.1	11,151	Complete
2024-06-25 00:00:00	Brakes	Inspect Park Brake Function (600hr)	Henry Silva	0.1	11,151	Complete
2024-06-25 00:00:00	Oil & Filter Change	Replace Engine Oil and Filters (600hr)	Henry Silva	0.5	11,151	Complete
2024-06-25 00:00:00	Frame	Engine Mounts Inspect (1000hr)	Henry Silva	0.1	11,151	Complete
2024-06-25 00:00:00	Servicing Needed	Replace Breathers-Axle, Trans, and Transfer Case (1000hr)	Henry Silva	0.2	11,151	Complete
2024-06-25 00:00:00	Fuel System	Water Separator Replace (600hr)	Henry Silva	0.5	11,151	Complete
2024-06-25 00:00:00	Fuel System	Water Separator Replace (600hr)	Henry Silva	0.1	11,151	Complete

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Maintenance	Description of Maintenance
2024-06-25 00:00:00	Fuel System	Fuel Filters Replace (600hr)	Henry Silva	0.5	11,151	Complete
2024-06-25 00:00:00	Servicing Needed	Inspect/Replace Primary Air Filter (600hr)	Henry Silva	0.1	11,151	Complete
2024-06-25 00:00:00	Electrical	Inspect and Test Batteries (600hr)	Henry Silva	0.5	11,151	Complete
2024-06-25 00:00:00	Belts	Inspect Belt Condition and Tension (600hr)	Henry Silva	0.1	11,151	Complete
2024-05-15 00:00:00	Inspection	(Full inspection and repairs)	Kade Proctor	4.0	11,104	(Full inspection and repairs) -check all lights -inspect brakes and suspension -check tire pressures and tire wear -check all fluids -inspect all hydraulic lines and hoses ...
2023-08-10 00:00:00	Differential	Rear pinion bearing blown	Nik Delsordo	5.0	10,873	Clean out differential housing with brake clean Crane rebuild diff Into place Tighten all bolts Install axles into carrier Install planetary onto truck Fill diff and planets w...
2023-08-09 00:00:00	Differential	Rear pinion bearing blown	Nik Delsordo	5.0	10,865	Complete rebuild of differential Test and install pinion shims, multiple times to get the correct pinion drag of 17 in lbs Install ring gear and set carrier end play to 0inches, ...
2023-07-17 00:00:00	Differential	Rear pinion bearing blown	Nik Delsordo	5.0	10,865	Tool up and travel to figure lake Drain differential, finals Remove planetary covers, pull both axles Remove all pumpkin bolts and remove from diff housing with crane Travel b...
2023-07-17 00:00:00	Exhaust	Box heater Flex pipe disconnected at clamp	Nik Delsordo	1.0	10,865	Undo exh clamp at flex pipe, install flex pipe back onto hard pipe. Install existing exh clamp. Tighten all exh clamps on flex pipe

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2023-07-17 00:00:00	Hydraulics	Hyd leak under cab	Nik Delsordo	1.0	10,865	Found leak under cab Lifted cab and found hyd hose leaking at flange Removed libe and replace o ring, tourqued line back in place and tested repair by firing up machine and looki...
2023-07-11 00:00:00	Cooling System	Overheating	Patrick D	5.0	10,843	Wash out rad setup pressure washer Travel to and from location
2023-07-08 00:00:00	Cooling System	Engine overheating	Tim Gardner	5.0	10,832	Blow out radiator: Rad packed with mud - wash and blow out Coolant temp after blow down was 58c operator made one trip and coolant was 92c opertor made another two trips and ...
2023-06-26 00:00:00	Cooling System	Engine overheating	Patrick D	4.0	10,798	Blew out the rad with air both directions
2023-06-23 00:00:00	General (No Category)	Fire extinguisher out of date transmission breather broken off Left highbeam out window washer plugged Replace spill kit	Patrick D	6.0	10,798	Fire extinguisher - Replaced with a new one. Transmission breather - Welded on new bracket Left high beam - New high beam installed Window washer - Got it unplugged Replaced s...
2023-03-06 00:00:00	Windshield	FRONT WIPER NOT WORKING	Richard Schalin	6.5	10,651	Remove windshield wiper motor. Splines wore off. Install new motor and wiper Replace left hand broken headlight Removed and installed park brake disc and pads

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2023-02-27 00:00:00	Servicing Needed	Grease/Top Up (600hr)	Nik Delsordo	0.3	10,651	Complete
2023-02-27 00:00:00	Servicing Needed	Replace Rear Planetary Oil (2000hr)	Rudy Schalin	0.5	10,651	Complete
2023-02-27 00:00:00	Servicing Needed	Replace Middle Planetary Oil (2000hr)	Richard Schalin	0.5	10,651	Complete
2023-02-27 00:00:00	Servicing Needed	Replace Front Planetary Oil (2000hr)	Rudy Schalin	0.5	10,651	Complete
2023-02-27 00:00:00	Frame	Inspect Box Pivot Shims (1000hr)	Nik Delsordo	0.1	10,651	Complete
2023-02-27 00:00:00	Brakes	Inspect Park Brake Function (600hr)	Nik Delsordo	0.1	10,651	Complete
2023-02-27 00:00:00	Frame	Drop Box Mounts Inspect (1000hr)	Nik Delsordo	0.1	10,651	Complete
2023-02-27 00:00:00	Servicing Needed	Replace Rear Diff Oils (2000hr)	Nik Delsordo	0.6	10,651	Complete
2023-02-27 00:00:00	Servicing Needed	Replace Middle Diff Oil (2000hr)	Nik Delsordo	0.6	10,651	Complete
2023-02-27 00:00:00	Cab	Inspect/Replace Cab Fresh and Recirculating Filters (600hr)	Kade Proctor	0.2	10,651	Complete
2023-02-27 00:00:00	Frame	Inspect Axle Mounts (1000hr)	Nik Delsordo	0.1	10,651	Complete
2023-02-27 00:00:00	Steering	Inspect Steering Components (600hr)	Nik Delsordo	0.1	10,651	Complete
2023-02-27 00:00:00	Fuel System	Water Separator Replace (600hr)	Richard Schalin	0.2	10,651	Complete
2023-02-27 00:00:00	Body	Drop and Clean out Belly Pan (1000hr)	Kade Proctor	0.1	10,651	Complete
2023-02-27 00:00:00	Servicing Needed	Inspect/Replace Primary Air Filter (600hr)	Rudy Schalin	0.3	10,651	Complete

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2023-02-27 00:00:00	Frame	Load Body Rubber Cushion Clearance Check (1000hr)	Nik Delsordo	0.1	10,651	Complete
2023-02-27 00:00:00	Oil & Filter Change	Replace Engine Oil and Filters (600hr)	Kade Proctor	0.1	10,651	Complete
2023-02-27 00:00:00	Belts	Inspect Belt Condition and Tension (600hr)	Kade Proctor	0.3	10,651	Complete
2023-02-27 00:00:00	Electrical	Inspect and Test Batteries (600hr)	Kade Proctor	0.1	10,651	Complete
2023-02-27 00:00:00	Fuel System	Fuel Filters Replace (600hr)	Richard Schalin	0.3	10,651	Complete
2023-02-27 00:00:00	Fuel System	Fuel Tank Water Sediment Drain (1000hr)	Kade Proctor	0.2	10,651	Complete
2023-02-27 00:00:00	Air System	Air Drier Cartridge Replace (1000hr)	Richard Schalin	0.3	10,651	Complete
2023-02-27 00:00:00	Frame	Articulation Hitch Bearing Inspect (1000hr)	Nik Delsordo	0.1	10,651	Complete
2023-02-27 00:00:00	Brakes	Inspect Brake Components (1000hr)	Nik Delsordo	0.1	10,651	Complete
2022-08-21 00:00:00	LINKAGE	Hydraulic leak.	Nik & helper	2.5	10,458	Diagnose leak under cab, lift cab for hose access, remove leaking steering crossover hose and rubbed through hose, plug lines to minimize fluid loss and send lines to shop for new,...
2022-08-21 00:00:00	General (No Category)	Drivers side bottom step missing.	Nik & helper	0.5	10,458	Ladder on drivers side missing. Remove ladder and hardware from Pass. side install on drivers side.
2022-06-01 00:00:00	Hydraulics	Leaks			10,356	Diag/Repair Hydraulic Leak. Work order attached.
2021-12-10 00:00:00	Fuel System	Machine stalled, wont start.	Shane Witney	2.0	10,176	Change fuel filters, fuel system will not prime. Check power & ground to lift pump ok. Order new lift pump, install, ok.

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2021-12-03 00:00:00	Electrical	Lost all electrical power	Jesse Watson	1.0	10,062	Found batteries have come loose, main positive cable came off. Open top access, straighten out batteries & secure, clamp positive cable on.
2021-11-19 00:00:00	Cylinder	Right steer cylinder leaking.	Richard & helper	5.0	10,022	Remove cylinder, disassemble & install new seals, install in chassis.

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2021-11-19 00:00:00	General (No Category)	Check complaint "seat kinda broken" and windshield wipers dont work	Rudy Schalin	0.4	10,022	Replace 3 broken springs from seat track adjuster. Replace 2 missing slide bushings.
2021-11-13 00:00:00	Brakes	Inspect Park Brake Function (600hr)	Richard Schalin	0.2	10,022	complete
2021-11-13 00:00:00	Servicing Needed	Grease/Top Up (600hr)	Richard Schalin	0.4	10,022	complete
2021-11-13 00:00:00	Transmissi on	Transmission Oil Replace (1000hr)	Richard Schalin	0.5	10,022	complete
2021-11-13 00:00:00	Hydraulics	Replace Hydraulic Breather Filter (2000hr)	Richard Schalin	0.2	10,022	complete
2021-11-13 00:00:00	Servicing Needed	Replace Drop Box Oil (2000hr)	Richard Schalin	0.5	10,022	complete
2021-11-13 00:00:00	Cab	Inspect/Replace Cab Fresh and Recirculating Filters (600hr)	Richard Schalin	0.3	10,022	complete
2021-11-13 00:00:00	Frame	Inspect Axle Mounts (1000hr)	Richard Schalin	0.3	10,022	complete
2021-11-13 00:00:00	Servicing Needed	Secondary Air Filter Replace (2000hr)	Richard Schalin	0.2	10,022	complete
2021-11-13 00:00:00	Transmissi on	Transmission Oil Filter Replace (1000hr)	Richard Schalin	0.4	10,022	complete
2021-11-13 00:00:00	Steering	Inspect Steering Components (600hr)	Richard Schalin	0.2	10,022	complete
2021-11-13 00:00:00	Hydraulics	Hydraulic Oil Filter Replace (1000hr)	Richard Schalin	1.0	10,022	complete
2021-11-13 00:00:00	Body	Drop and Clean out Belly Pan (1000hr)	Richard Schalin	0.4	10,022	complete
2021-11-13 00:00:00	Fuel System	Fuel Tank Water Sediment Drain (1000hr)	Richard Schalin	0.2	10,022	complete
2021-11-13 00:00:00	Servicing Needed	Replace Breathers-Axle, Trans, and Transfer Case (1000hr)	Richard Schalin	0.4	10,022	complete

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2021-11-13 00:00:00	Frame	Articulation Hitch Bearing Inspect (1000hr)	Jesse Watson	0.3	10,022	complete
2021-11-13 00:00:00	Fuel System	Water Separator Replace (600hr)	Richard Schalin	0.2	10,022	complete
2021-11-13 00:00:00	Fuel System	Fuel Filters Replace (600hr)	Richard Schalin	0.5	10,022	complete
2021-11-13 00:00:00	Servicing Needed	Inspect/Replace Primary Air Filter (600hr)	Richard Schalin	0.2	10,022	complete
2021-11-13 00:00:00	Electrical	Inspect and Test Batteries (600hr)	Richard Schalin	0.4	10,022	complete
2021-11-13 00:00:00	Belts	Inspect Belt Condition and Tension (600hr)	Richard Schalin	0.2	10,022	complete
2021-11-13 00:00:00	Oil & Filter Change	Replace Engine Oil and Filters (600hr)	Richard Schalin	1.0	10,022	complete
2021-10-21 00:00:00	General (No Category)	Check complaint "seat kinda broken" and windshield wipers dont work	Tim Gardner	0.5	9,968	Inspect wiper, tighten retaining nut & test-ok
2021-03-08 00:00:00	Transmission	transmission pressurizing	Kole Snyder	2.5	9,851	Tilt cab, try to locate breather. No breather, believe wrong dipstick/fill tube installed. Remove fill tube, braze fitting on & install breather. Install tube.
2020-03-23 00:00:00	Steering	Right Steer Cylinder Is Leaking And Bearing Needs Replacement	Shane Witney	0.5	9,757	-Install last fitting. -Put hose on. -Test machine, everything was functioning properly. *Installed on 7623 COMPLETE
2020-02-27 00:00:00	Steering	Right Steer Cylinder Is Leaking And Bearing Needs Replacement	Shane Witney / Jesse Watson	2.0	9,757	-Installed steer cylinder. *Tested machine, Everything was good. COMPLETE
2020-02-21 00:00:00	Steering	Right Steer Cylinder Is Leaking And Bearing Needs Replacement	Shane Witney / Jesse Watson	4.0	9,750	-Removed old bushings. -Removed seals and o-rings. ONGOING

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Maintenance	Description of Maintenance
2020-02-21 00:00:00	Steering	Right Steer Cylinder Is Leaking And Bearing Needs Replacement	Marshall Grabski / Jesse Watson	2.0	9,750	-Replaced with new seal and o-ring kit. -Pressed in new bushing. -Put cylinder back together. COMPLETE
2020-02-20 00:00:00	Steering	Steering Motor Not Functioning Properly	Shane Witney	2.5	9,757	-Unhook lines from motor. -Take mounting bolts out. -Pull monitor screen out of cab, loosen nut off steering shaft -Tried pulling steering shaft out of steering wheel collar won...
2020-02-20 00:00:00	Windshield Wipers	windshield wiper not working	Shane Witney	0.25	9,757	-Tighten nuts on wipers. *Tested they work COMPLETE

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2020-02-20 00:00:00	Steering	Right Steer Cylinder Is Leaking And Bearing Needs Replacement	Shane Witney	0.5	9,757	Checked all lines going to right steer cylinder not leaking. *Cylinder seal is leaking need to be replaced. ONGOING
2020-02-20 00:00:00	Steering	Right Steer Cylinder Is Leaking And Bearing Needs Replacement	Shane Witney	2.0	9,757	-Bushing gone on right steer cylinder. -Removed cylinder. -Taking back to shop to get new bushing installed. ONGOING
2019-06-23 00:00:00	Oil & Filter Change	Replace Engine Oil and Filters (600hr)	Kole Snyder	0.5	9,542	Done.
2019-06-11 00:00:00	Exhaust	Box heat bent	Kole Snyder	0.5	9,515	Straighten flex pipe for box heat Install new 4" step clamp
2019-05-30 00:00:00	Electrical	Battery lights on	Kole Snyder and helper	3.0	9,459	Perform electrical test Find battery balancer not functioning properly Remove dash covers and battery box covers Install new converter and mount install covers Test - goo...
2019-05-30 00:00:00	Mirrors	Replace mirror	Kole Snyder and helper	0.15	9,459	Replace mirror .
2019-05-29 00:00:00	A/C	NO A/C	Rudy Schalin	1.5	9,459	Check function, no A/C Blow out cab filter and order new one. Check A/C pressures , low side extremely high , compressor not engaging . Diagnose low pressure switch open -failed....
2019-05-23 00:00:00	Cooling System	Replace Coolant (6000hr)	Kole Snyder	0.5	9,542	Done.
2019-05-23 00:00:00	Engine	Coolant reservoir overflowing			9,542	COMPLAINT : Exhaust gases bubbling in surge tank CORRECTION: Find machine outside and check all fluid levels .Good Remove surge tank cap and start engine. After around 1 m...
2019-05-23 00:00:00	Engine	Engine Valve Lash (4000hr)	Kole Snyder	0.15	9,542	Done.