

PO9-5
MAY

Maintenance Summary – Asset #5230

Total Maintenance Records: 457

Maintenance Period: 2013-04-04 to 2025-07-09

This equipment has been consistently maintained with documented service history.

Detailed Maintenance Records

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2025-07-09 00:00:00	Engine	Power issues	Nik Delsordo	4.0	12,320	Travel to dump Remove and install new throttle pedal. Cleared throttle pedal codes and test drove truck for a few loads. Throttle response was good, no power issues. Put cover ba...
2025-06-19 00:00:00	Engine	Power issues	Nik Delsordo	4.0	12,317	Diagnose power issues. Found EGR codes, throttle pedal codes. Followed procedure for throttle pedal diagnostic. Harness and connectors all good. Not receiving pedal position sign...
2025-06-12 00:00:00	Brake System	Left front caliper leaking, (back one)	Derek Partyka	3.0	12,307	Remove wheel, found caliper pistons pushed out too far as pads are worn out. Replace seals and pads, install wheel.
2025-05-20 00:00:00	Exhaust	Box heater flex pipe falling off upper clamp, causing exhaust fumes in cab	Nik Delsordo	0.5	12,265	R and r upper exhaust clamp Completed
2025-05-14 00:00:00	Transmissi on	Complaint truck won't shift out of 1st gear under load/under powered	Nik Delsordo	2.0	12,258	Hook up computer and connect to engine, no fault codes active. Connect to transmission, no fault cldes active. Pulled up live data and drive to the clay cut. Load myself and test...
2025-05-14 00:00:00	A/C	AC blowing warm	Nik Delsordo	1.0	12,258	Installed guages, found pressure low but not empty. Added 1.5lbs to system. Blew out cab filters and tested heat valve actuator to ensure it's working correctly. Ac pressure set t...

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2025-05-07 00:00:00	Cylinder	Cylinder			12,256	Attempt to remove seized trunion thread from cylinder rod 2 men for 1.5hrs - Build new cylinder rod (material) -Freight on new rod -Machine new cylinder rod -Cylinder#2: -Diss...
2025-05-06 00:00:00	Inspection	Full inspection	Ethan rich	1.5	12,349	Tapped holes for upper cylinder mount and ensured bolts threaded on correctly then move cylinder into place and installed and tightened all bolts. Removed slings then replaced 0-ri...
2025-05-05 00:00:00	Inspection	Full inspection	Ethan rich	5.0	12,249	Assembles lift cylinder slinger it up and went to install truck was dead and was not charging again. Consulted repair mauls did alternator test and found alternator was still good ...
2025-04-30 00:00:00	Inspection	Full inspection	Ethan rich	8.0	12,259	Removed and replaced strut, installed and torqued wheel greased unit and checked fluid levels
2025-04-29 00:00:00	Inspection	Full inspection	Ethan rich	8.0	12,249	Changed final drive oils , replaced alternator and cabin air filter lifted unit and removed tire
2025-04-28 00:00:00	Inspection	Full inspection	Ethan rich	4.0	12,249	Changed diff oils, replaced heater valve
2025-04-27 00:00:00	Inspection	Full inspection			12,249	Correction: Chassis / Chassis / Had to boost unit to start -Drop box front flange leaking -Recommend changing both sweating hoses from drop box -Front RH strut sweating -RH st...
2025-04-17 00:00:00	Servicing Needed	Replace Middle LH Planetary Oil (2000hr)	Ethan rich	0.3	12,250	Complete
2025-04-17 00:00:00	Servicing Needed	Replace Drop Box Oil (2000hr)	Kade Proctor	0.5	12,250	Complete

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2025-04-17 00:00:00	Fuel System	Fuel Tank Vent Filter Replace (1200hr)	Ethan rich	0.3	12,250	Complete
2025-04-17 00:00:00	Frame	Inspect Box Pivot Shims (1200hr)	Ethan rich	0.2	12,250	Complete
2025-04-17 00:00:00	Servicing Needed	Replace Front LH Planetary Oil (2000hr)	Ethan rich	0.3	12,250	Complete
2025-04-17 00:00:00	Servicing Needed	Replace Front RH Planetary Oil (2000hr)	Ethan rich	0.3	12,250	Complete
2025-04-17 00:00:00	Servicing Needed	Grease/Top Up (600hr)	Kade Proctor	0.2	12,250	Complete
2025-04-17 00:00:00	Servicing Needed	Replace Middle RH Planetary Oil (2000hr)	Ethan rich	0.3	12,250	Complete
2025-04-17 00:00:00	Servicing Needed	Replace Rear LH Planetary Oil (2000hr)	Ethan rich	0.3	12,250	Complete
2025-04-17 00:00:00	Servicing Needed	Replace Rear RH Planetary Oil (2000hr)	Ethan rich	0.3	12,250	Complete
2025-04-17 00:00:00	Transmission	Transmission Breather Filter Replace/Clean (2000hr)	Kade Proctor	0.5	12,250	Complete
2025-04-17 00:00:00	Transmission	Transmission Oil Replace (2000hr)	Kade Proctor	1.0	12,250	Complete
2025-04-17 00:00:00	Hydraulics	Replace Hydraulic Oil (4000hr)	Kade Proctor	1.0	12,250	Complete
2025-04-17 00:00:00	Frame	Drop Box Mounts Inspects (1200hr)	Elson Walker	0.3	12,250	Complete
2025-04-17 00:00:00	Servicing Needed	Drop Box Breather Filter Replace (2000hr)	Ethan rich	0.2	12,250	Complete
2025-04-17 00:00:00	Drive Train	Differential Breather Filters Replace (2000hr)	Ethan rich	0.5	12,250	cleaned
2025-04-17 00:00:00	Fuel System	Water Separator Replace (600hr)	Ethan rich	0.2	12,250	Complete

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2025-04-17 00:00:00	Servicing Needed	Replace Rear Diff Oils (2000hr)	Ethan rich	1.5	12,250	Complete
2025-04-17 00:00:00	Belts	Inspect Belt Condition and Tension (600hr)	Kade Proctor	0.2	12,250	Complete
2025-04-17 00:00:00	Electrical	Inspect and Test Batteries (600hr)	Kade Proctor	0.3	12,250	Complete
2025-04-17 00:00:00	Servicing Needed	Replace Primary Air Filter (600hr)	Ethan rich	0.2	1,250	Complete
2025-04-17 00:00:00	Fuel System	Fuel Filters Replace (600hr)	Ethan rich	0.3	12,250	Complete
2025-04-17 00:00:00	Oil & Filter Change	Replace Engine Oil and Filters (600hr)	Ethan rich	1.0	12,250	Complete
2025-04-17 00:00:00	Body	Drop and Clean out Belly Pan (1200hr)	Kade Proctor	0.2	12,249	Complete
2025-04-17 00:00:00	Transmissi on	Transmission Oil Filter Replace (1200hr)	Kade Proctor	0.5	12,250	Complete
2025-04-17 00:00:00	Frame	Inspect Axle Mount (1200hr)	Ethan rich	1.0	12,250	Complete
2025-04-17 00:00:00	Cab	Replace Cab Fresh and Recirculating Filters (2000hr)	Ethan rich	0.5	12,250	Complete
2025-04-17 00:00:00	Servicing Needed	Replace Front Diff Oil (2000hr)	Ethan rich	1.5	12,250	Complete
2025-04-17 00:00:00	Servicing Needed	Replace Middle Diff Oil (2000hr)	Ethan rich	1.5	12,250	Complete
2025-02-26 00:00:00	Battery	Battery cables shorting out on frame	Nik Delsordo	2.0	12,250	Bring truck into wash bay Remove battery cover and find where cables are shorting out. New master was installed in machine and ground cables were used. The positive cables were b...
2025-01-27 00:00:00	Windows	Rear window broken	Nik Delsordo	2.0	12,249	Removed cracked rear windows, cleared off all old urethane. Cleaned new windows, primed edge and waited 10 mins. Applied urethane and got helpt to install new windows. Completed

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2024-10-27 00:00:00	Cooling System	Complaint no cab heat	Henry Silva	4.0	87,472	I found a leak at the heater core system there was a hose with a damage clamp replace the clamps I put coolant into the system to the right level I blew out where the core was full...

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2024-10-25 00:00:00	Cooling System	Complaint no cab heat	Nick Rogne	7.0	12,189	Pull vacuum on coolant system Remove thermostats Install new thermostats Get to running temp No heat. Further investigate Open heater box Supply coolant line cold Remo...
2024-10-24 00:00:00	Cooling System	Complaint no cab heat	Nick Rogne	4.0	12,189	Diagnose no cab heat No coolant flow to heater box No coolant heat/ running temp low Diagnoses- thermostat bad
2024-09-16 00:00:00	Inspect & Service	General inspect & repair. Complaint of seat back wont adjust and tilt column lever missing.			12,189	Repair tilt handle- found bolt broken off, drill out and retap and install lever. Applied lube to seat tilt mechanism and confirm function. Travel
2024-07-22 00:00:00	Inspection	Full Inspection	Henry Silva	1.0	12.095	finished off inspection Blow rad and replace air filter. Blow cab filters.
2024-07-19 00:00:00	Inspection	Full Inspection	Henry Silva	4.0	12,095	Inspection Check the pressures on the tires The left headlight is damaged grease the unit check for leaks in the engine everything okay check all levels check the exhaust syste...
2024-06-07 00:00:00	Charging System	Charging system check alternator battery.	Henry Silva	10.0	11,984	I went to Martin hills.load test the I boost the unit.batteries not good very low. I check the voltage on the alternator it was only giving 23 volts. Unbolt the belly pan remove f...
2024-05-17 00:00:00	Inspection	(Full inspection and repairs)	Kade Proctor	8.0	11,958	(Continue on inspection and repairs) -Test lights found that both rear signal lights not working and left parking light -diagnose why the lights aren't working properly found ope...

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2024-05-16 00:00:00	AM/FM Radio	Stereo not working	Kade Proctor	1.0	11,989	(Install new AM/FM radio) Remove old radio Install new radio/connect all wiring Test Complete
2024-05-16 00:00:00	Inspection	(Full inspection and repairs)	Kade Proctor	7.0	11,989	(Full inspection and repairs) -check all fluids -inspect tire pressures and wear -inspect windshield wipers and washers -inspect hydraulic lines and hoses -inspect batteri...
2023-10-10 00:00:00	Tires	Front left tire flat	Nick Rogne	4.0	11,961	Lift front axle with hydraulic jacks Replace tire o-ring Fill tire Let down front axle
2023-09-29 00:00:00	A/C	A/C compressor clutch	Nick Rogne	2.0	11,961	Unbolt stump pan Remove a/c compressor lines Remove mounting bolts Mount new compressor with bolts Incomplete.
2023-06-23 00:00:00	Inspection	Full equipment inspection	Nik Delsordo	1.25	11,863	Inspect unit Grease unit Tidy cab quickly
2023-06-15 00:00:00	Wash	interior detail	Caleb Neil	0.5	11,863	Interior detailed
2023-04-24 00:00:00	Cooling System	Check for coolant leak	Kade Proctor	1.0	11,863	Inspect task Gather tools/materials Inspect coolant lines Pressure test/connect coolant pressure gage Check for leaks No leaks found
2023-04-24 00:00:00	General (No Category)	right rear signal light inop. Install fire extinguisher & bracket.	Kade Proctor	1.5	11,863	Inspect task Gather tools/materials Remove battery cover Drill holes to mount the fire extinguisher bracket Grab new hardware Mount down bracket Put new fire extinguisher ...

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Maintenance	Description of Maintenance
2023-04-24 00:00:00	Tires	Left mid axle tire flat	Nik Delsordo	2.5	11,863	Remove mid left tire Clean rim, locking ring, 2nd piece rim. All pieces caked in rubber and dirt Install new valve stem Install new o ring Install tire and outer rim and lockin...
2022-11-28 00:00:00	Tires	Front left tire flat			11,814	Tire run flat put tire on no air to load up
2022-09-27 00:00:00	Servicing Needed	Aspen leaf job, Traveled to job site to check out truck that seems to stall on random occasions, checked out the codes, there was no recent codes that came up to explain why the truck would stall. Inspected the fuel system, noticed the fuel tank was pressuring up, could use a new fuel cap as the vent in the cap must be faulty. Left the fuel cap a little loose and has not stalled since.	Service provider	3.0	11,809	Aspen leaf job, Traveled to job site to check out truck that seems to stall on random occasions, checked out the codes, there was no recent codes that came up to explain why the t...
2022-09-17 00:00:00	Air System	Air Drier Cartridge Replace (2000hr)	Nick Rogne	0.2	11,725	complete
2022-09-07 00:00:00	Fuel System	Fuel Tank Water Sediment Drain (1000hr)	Nick Rogne	0.1	11,725	complete
2022-09-07 00:00:00	Servicing Needed	Grease/Top Up (600hr)	Nick Rogne	0.3	11,725	complete
2022-09-07 00:00:00	Engine	Engine Valve Lash (4000hr)	Nik & helper	6.5	11,725	complete
2022-09-07 00:00:00	Servicing Needed	Secondary Air Filter Replace (2000hr)	Nik Delsordo	0.1	11,725	complete

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2022-09-07 00:00:00	Steering	Inspect Steering Components (1200hr)	Nik Delsordo	0.2	11,725	complete
2022-09-07 00:00:00	Brakes	Inspect Park Brake Function (1200hr)	Nik Delsordo	0.2	11,725	complete
2022-09-07 00:00:00	Body	Drop and Clean out Belly Pan (1200hr)	Nick Rogne	0.2	11,725	complete
2022-09-07 00:00:00	Frame	Load Body Rubber Cushion Clearance Check (1000hr)	Nick Rogne	1.0	11,725	complete
2022-09-07 00:00:00	Hydraulics	Hydraulic Oil Return Filter Replace (1200hr)	Nik Delsordo	1.0	11,725	complete
2022-09-07 00:00:00	Exhaust	Exhaust leak, broken flex hose.	Nick Rogne	0.6	11,725	Remove & replace bin heat hose.
2022-09-07 00:00:00	Frame	Engine Mounts Inspect (1000hr)	Nik Delsordo	0.4	11,725	complete

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2022-09-07 00:00:00	Servicing Needed	Replace Primary Air Filter (600hr)	Nik Delsordo	0.1	11,725	complete
2022-09-07 00:00:00	Brakes	Inspect Brake Components (1200hr)	Nik Delsordo	0.2	11,725	complete
2022-09-07 00:00:00	Belts	Inspect Belt Condition and Tension (600hr)	Nick Rogne	0.1	11,725	complete
2022-09-07 00:00:00	Electrical	Inspect and Test Batteries (600hr)	Nick Rogne	0.2	11,725	complete
2022-09-07 00:00:00	Oil & Filter Change	Replace Engine Oil and Filters (600hr)	Nick Rogne	1.0	11,725	complete
2022-09-07 00:00:00	Fuel System	Fuel Filters Replace (600hr)	Nick Rogne	0.2	11,725	complete
2022-09-07 00:00:00	Fuel System	Water Separator Replace (600hr)	Nick Rogne	0.1	11,725	complete
2022-09-07 00:00:00	Frame	Articulation Hitch Bearing Inspect (1200hr)	Nik Delsordo	1.0	11,725	complete
2022-08-21 00:00:00	Exhaust	Exhaust leak, broken flex hose.	Nik Delsordo	0.5	11,673	Diagnose leak, unit fired up, broken flex pipe broken behind cab.
2022-06-30 00:00:00	Oil & Filter Change	Replace Engine Oil and Filters (600hr)			11,427	Change engine oil & filter. Blow out air filters, check trans fluid & coolant.
2022-02-22 00:00:00	Electrical	Ground cable broken off master switch	Shane Whitney	1.0	11,295	Go to town for new cable, install ok.
2022-02-22 00:00:00	Electrical	Ground cable broken off master switch			11,292	Supply battery cable and solder on ends.
2022-02-01 00:00:00	Brake System	Oil leak at rear of machine	Shane Whitney	1.5	11,285	Inspect found a broken brake line at rear of frame. Remove & make new hose, install, top up oil.
2022-01-12 00:00:00	Tires	Left center tire flat off bead			11,292	Service Call, flat repair in field.
2022-01-11 00:00:00	Tires	Left center tire flat off bead	Shane Whitney + helper	3.0	11,213	Jack up axle, press lock ring into rim & change out oring. Lube rim & ring, could not get tire to bead up; Integra tire to come out & air up.

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2021-12-08 00:00:00	Cylinder	Left box cylinder lower bushing worn out	Richard & helper	4.0	11,111	Remove & replace lower bushing. Found top bushing also needs replacement, remove knuckle.
2021-12-04 00:00:00	Cylinder	Left box cylinder lower bushing worn out	Jesse Watson	7.0	11,111	Remove left box cylinder, wait for replacement from 7623, install on truck.
2021-12-02 00:00:00	Air System	Complaint of park brake freezing up	Jesse Watson	1.0	11,085	Drain air tanks, slight moisture present. Remove drier cartridge & inspect, ok. Remove lines to tanks, slight moisture residue; Add antifreeze to tanks, cycle air system; test fu...
2021-11-12 00:00:00	Tires	Left front tire leaking.	Jesse Watson	2.0	11,039	Lift left front corner, drain air from tire, break Bead. Remove & replace o-ring, air tire to 50 psi.
2021-11-10 00:00:00	General (No Category)	Pre-Job Inspect	Jesse Watson	2.5	11,039	Left front tire low, found oring leaking. Battery cables behind disconnect had rubbed through & shorted. Remove access panels, Clean up cables & heat shrink, Insulate all to prev...
2021-05-10 00:00:00	Electrical	Battery disconnect is not working will not contact	Kole Snyder	3.0	10,904	Remove master switch assembly. Build bracket for new switch, Install & route cables properly.
2021-03-08 00:00:00	Accessory	Windshield washer not working	Jesse Watson	0.5	10,856	Test for power at pump, ok. Check resistance is high in pump. Rob pump from 3551 & install, ok.
2020-03-31 00:00:00	Steering	right steer cylinder leaking	Jesse Watson / Richard Schalin	3.0	10,833	-Installed new seal kit. ONGOING
2020-03-31 00:00:00	Steering	right steer cylinder leaking	Jesse Watson	2.0	10,833	-Installed steering cylinder. COMPLETE

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2020-03-31 00:00:00	Steering	right steer cylinder leaking	Shane Whitney / Jesse Watson	1.0	10,833	-Pulled cylinder apart for new seal kit. ONGOING
2020-03-31 00:00:00	Exhaust	Broken Bin Heat Clamp.	Shane Whitney / Jesse Waston / Richard Schalin	1.0	10,833	-Installed new bolts and gasket for bin heat. COMPLETE
2020-03-27 00:00:00	Hydraulics	Cycle Hydraulic Oil Through Filter Caddy, Change Return Filter Sample	Jesse Watson	4.0	10,833	-Pulled off guard on top of hydraulic tank. -Grabbed filter caddy, caddy not working. -Pulled apart caddy pump to see whats wrong. -Lubed up pump and installed back on filter ca...
2020-03-27 00:00:00	Exhaust	Broken Bin Heat Clamp.	Jesse Watson	0.5	10,833	-Pulled apart lower bin heat exhaust clamp. -Ordered 3 new bolt and spring assembly and gasket. ONGOING
2020-03-27 00:00:00	Steering	right steer cylinder leaking	Jesse Watson	2.0	10,833	-Pulled off top lines on cylinder, plugged and capped. -Pulled bolts to remove cylinder. -Took apart bearings end of cylinder. ONGOING.
2020-03-26 00:00:00	Fuel System	Water Separator Replace (600hr)	Jesse Watson	0.05	10,833	COMPLETE

Date of Maintenance	Maint Task Category	Maint Task Description	Maint Done By	Labour Hours	Odometer at Main	Description of Maintenance
2020-03-26 00:00:00	Servicing Needed	Grease/Top Up (600hr)	Jesse Watson	1.0	10,833	COMPLETE
2020-03-26 00:00:00	Servicing Needed	Replace Rear Diff Oils (2000hr)	Jesse Watson	0.1	10,833	Sampled COMPLETE
2020-03-26 00:00:00	Servicing Needed	Replace Middle Diff Oil (2000hr)	Jesse Watson	0.1	10,833	Sampled. COMPLETE
2020-03-26 00:00:00	Servicing Needed	Replace Front Diff Oil (2000hr)	Jesse Watson	0.15	10,833	Sampled COMPLETE
2020-03-26 00:00:00	Cab	cab lift valve is leaking	Jesse Watson	1.0	10,833	-Pulled off lift valve fittings and changed o-rings. COMPLETE
2020-03-26 00:00:00	Fuel System	Fuel Filters Replace (600hr)	Jesse Watson	0.1	10,833	COMPLETE
2020-03-26 00:00:00	Servicing Needed	Replace Primary Air Filter (600hr)	Jesse Watson	0.05	10,833	COMPLETE
2020-03-26 00:00:00	Electrical	Inspect and Test Batteries (600hr)	Jesse Watson	0.2	10,833	COMPLETE
2020-03-26 00:00:00	Belts	Inspect Belt Condition and Tension (600hr)	Jesse Watson	0.15	10,833	COMPLETE
2020-03-26 00:00:00	Oil & Filter Change	Replace Engine Oil and Filters (600hr)	Jesse Watson	0.5	10,833	COMPLETE
2020-03-06 00:00:00	Engine	Broken Pre-Cleaner.	Jesse Watson	0.15	10,833	-Pulled off broken pre-cleaner. *One on order. ONGOING
2020-02-19 00:00:00	Leak	Oil Leak	Shane Witney	0.5	10,734	-Tighten up oil filter. COMPLETE
2019-08-24 00:00:00	Tires	Flat Tire Left steer			10,516	- 1 Repair On LH Steer -Service Callout after hours \$371.35 -Fuel surcharge- HIAB \$12.00 EA (X1) -Service Call Mileage HIAB Truck 242KM @ \$3.05 = 738.10 -750/65/25 Repair \$224....
2019-07-11 00:00:00	Exhaust	Box heat flex hose needs replacing.	Scott Allan / Shane Witney	1.0	10,501	R&R; flex hose for the box heat. COMPLETE
2019-05-19 00:00:00	Cylinder	Steering cylinder (HIGHMARK MECHANICAL)			10,393	Disassemble steering cylinder , order seal kit . Assemble and test.