

Z10-17
MAY

3089 - REPAIR TRAILER LIGHTS [144493]

Closed: 3089 - REPAIR TRAILER LIGHTS [79813]

[3089 \[16X83 DUMP TRAILER 2X7000LBS DAY RATE\]](#)

Requested by RANDY WEARMOUTH on 2/6/2026

Location
SHELL 16.28.55.21.4 [20260053]

Type
Light Duty Trailer
Problem Code

Priority
LOW
Notes

▼ Comments

Comment

Replaced trailer plug, repaired brake wires, greased unit and checked over.



▼ Attachments

There are no attachments on this request.



Added By
Tanner Feddeema

Added On

2/6/2026

BRAKE ISSUE; BRAKE AWAY SWITCH MELTED. [132916]

[3089 \[16X83 DUMP TRAILER 2X7000LBS DAY RATE\]](#)

Closed: [3089 - 09/11/2025 \[73000\]](#)

Requested by OOM JARUSSIRIRAT on 9/11/2025

Location

SHELL 16.28.55.21.4 [20260053]

Type

Trailer Work Order

Problem Code

Priority

HIGH

Notes

▼ Comments

Comment

Replaced brake away switch and charged battery.tested operation of brakes,ok



▼ Attachments

There are no attachments on this request.



Added By

Darcy Platt

Added On

9/11/2025

CHECK ALL WHEELS BEARTINGS PRELOAD [125268]

[3089 \[16X83 DUMP TRAILER 2X7000LBS DAY RATE\]](#)

Closed: [3089 - 06/12/2025 - GEN CHECK OVER \[68583\]](#)

Requested by [OOM_JARUSSIRIRAT](#) on [6/13/2025](#)

Location
SHELL 16.28.55.21.4 [20260053]

Type
Trailer Work Order
Problem Code

Priority

MED

Notes

▼ **Comments**

Comment

Check preload, good to go

+ 

▼ **Attachments**

There are no attachments on this request.

+ 

Added By
Damian Myers

Added On
6/13/2025

SUSPENSIONS ISSUE [125266]

3089 [16X83 DUMP TRAILER 2X7000LBS DAY RATE]

Closed: 3089 - 06/12/2025 - GEN CHECK OVER [68583]

Requested by OOM JARUSSIRAT on 6/13/2025

Location
SHELL 16.28.55.21.4 [20260053]

Type
Trailer Work Order
Problem Code

Priority
MED
Notes

▼ Comments

Comment

R and R suspension bushings, reinstall wheels, torque wheels to 120ft/lbs

+

▼ Attachments

There are no attachments on this request.

+

Added By

Damian Myers

Added On

6/13/2025