

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780-

T20-3
MAY

INVOICE

36723

Org. Est. # 053481

INVOICE

Printed Date: 08/12/2022 Work Completed: 08/12/2022

PLATINUM HYDROVAC AND HDD

3135-4TH STREET
NISKU, ALBERTA T9E 8L1
Home 780-440-1152 -- Office 780-886-8148

2016 CARGO MATE - UTILITY TRAILER UNIT#TR250 -
Lic # : 5BS-814 Odometer In : 0
Unit # : TR250
VIN # : 5NHUEH018 GB457449

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
7 WAY RV MALE PLUG-STK 12-706	1.00	6.83	6.83	(1) REPAIR REAR DOOR LATCH AS REQUIRED * REPLACE REAR DOOR LOCKING BAR.	195.00
AMBER RECTANGULAR MARKER LIGHT-STK 19200Y	1.00	2.92	2.92		
72" CAMLOCK KIT -ORDER NTP53372	1.00	163.80	163.80		
Shop Supplies			9.75		

Org. Estimate 10.24 Revisions 0.00 Current Estimate 10.24

Labor:	195.00
Parts:	183.30
SubTotal:	378.30
Tax:	18.92
Total:	397.22
Bal Due:	\$397.22

[Payments -]

STK. 20

Vehicle Received: 11/5/2021

Customer Number : 3735

GST#865376503RT0001

Signature _____ Date _____

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

036723

Org. Est. # 053481

REPAIR ORDER - RO

Scheduled : 11/05/2021 03:16 PM

Print Date : 7/26/2022

PLATINUM HYDROVAC AND HDD

3135-4TH STREET
NISKU, ALBERTA T9E 8L1
Home 780-440-1152 --- Office 780-886-8148
Cust ID :
Last Service : 12/6/2019

2016 CARGO MATE - UTILITY TRAILER UNIT#TR250 -
Lic # : 5BS-814 - ALBERTA
Unit # : TR250
VIN # : 5NHUEH018 **GB457449**
MFG Date : 5/23/2018
Current Odom : 0
Elapsed : 0

Labor Requested / Part SubTotal

Extended

(1) REPAIR REAR DOOR LATCH AS REQUIRED

Parts Subtotal 9.75

Parts: 9.75
Labor: 0.00

Tax: 0.49

Total: 10.24
Balance: 10.24

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ___ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts ____. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By _____ Date _____ Time _____

Technician Work Sheet Service Writer : VERSTRAETE, AMIEE

Print Date: 7/26/2022

2016 CARGO MATE - UTILITY TRAILER UNIT#

Hat # :

Repair Order #

VIN # : 5NHUEH018 GB457449

Color :

036723

Engine :

Location :

Lic # : 5BS-814

Lic. State : ALBERTA

PLATINUM HYDROVAC AND HDD

Schedule : 11/05/21 3:30 P.M.

Home 780-440-1152 --- Office 780-886-8148

Promised Date : 11/05/21 5:00 P.M.

Inspection Date : 5/23/18

Status :

Last Service : 12/06/19

Unit # : TR250

Current Odometer : 0

Trans :

Previous Mileage : 0

Brakes :

Elapsed Mileage : 0

Manufacture Date : 5/23/18

Part Number	Part Description	Qty	Part Location
<input type="checkbox"/> 12-706	7 WAY RV MALE PLUG-STK	1.00	62-5 LOWER
<input type="checkbox"/> 19200Y	AMBER RECTANGULAR MARKER LIGHT-STK	1.00	44-5F MEZ

Labor Description	Charged Hours
<input type="checkbox"/> (1) REPAIR REAR DOOR LATCH AS REQUIRED Technician : <none>	

OUT ODOMETER :

Hours out: 0.00

Tech Notes
