



Davco Welding Ltd.
780-842-5559
www.DavcoLtd.com

Wainwright, AB Lloydminster, AB
Box 2904, T9W 1S8 5101 65TH Street
402 4th Ave South

WORK ORDER

W.O # : _____
W.O Date : Nov 18/25
UNIT # : 122
KMS : _____
HOURS : _____
NEXT SERVICE: _____

Hyd leak.

WORK COMPLETED	EMPLOYEE	HOURS
<u>- fix up cab, found and replaced line, filled Hyd oil washed engine and under cab areas.</u>	<u>MB</u>	

PARTS & MATERIALS	VENDOR	QUANTITY
<u>Hyd line</u>	<u>B to B</u>	<u>1</u>
<u>Zip ties</u>	<u>B to B</u>	<u>10</u>

OTHER COMMENTS

SIGNATURE Nathan B

COMPLETED: _____



WORK ORDER

Davco Welding Ltd.
780-842-5559
www.DavcoLtd.com

Wainwright, AB Lloydminster, AB
Box 2904, T9W 1S8 5101 65TH Street
402 4th Ave South

W.O # : _____

W.O Date : 7/24/25

UNIT # : V-122

KMS _____

HOURS _____

NEXT SERVICE: _____

- replace broken glass door.

WORK COMPLETED	EMPLOYEE	HOURS
----------------	----------	-------

- removed & replaced broken glass door, install weather seal & connectors.

PARTS & MATERIALS	VENDOR	QUANTITY
-------------------	--------	----------

OTHER COMMENTS

SIGNATURE

COMPLETED:

7/24/25



Lloydminster
 Box 10039 • Lloydminster, AB T9V 3A2
 Tel: 780.875.4471 Fax:780.875.6606
 www.horizonagturf.com

Ship to: IN STORE PICKUP

Invoice to: DAVCO INDUSTRIAL LTD.
 402 4TH AVE S
 WAINWRIGHT AB T9W 0C5

Branch		LLOYDMINSTER		CNNYYY
Date	07/24/25	Time	10:35:16 (O)	Page
Account No.	8425559	Phone No.	780-842-3331	Invoice No.
Ship Via		Purchase Order		P26734
BC-122				Salesperson
				JDF

PARTS INVOICE

ORDER#: 025768

Have you heard about MyDealer yet? We have a great way to help you stay connected to your equipment. Either mobile or laptop - look up parts, order them online, view past purchases, or book a service appointment, you are in control. Ask a parts or service member about MyDealer today!

Part#	Description	Bin	ORD	ISS	SHP	B/O	UTTTT	Price	Amount
A-7120401	Windshield	BLK14	1	1	1		*	267.99	267.99

UNIT 122

SUB TOTAL==> 267.99
 GST #70762 9879 RT0001 13.40
 TOTAL CREDIT CARD 281.39

024416 XXXXXXXXXXXXX3389

APPROVED
 Authorization Number:024416
 Account Number:*****3389
 Card Type:Mastercard
 Entry Mode:Contactless
 Application Name:Mastercard
 Application Id:A0000000041010
 Cryptogram:ARQC 8A9DFA9A7522D791
 Response:0 - Approved
 Transaction Date:07/24/2025 12:35:12 PM
 Transaction Id:884602502
 Approved Amount:\$281.39
 Reference Number:01.01.21.025768
 Transaction Type:Sale
 Signature Not Required

LATE CHARGE OF 2% PER MONTH (24% PER ANNUM), SPECIAL ORDER PARTS WILL BE SUBJECT TO FREIGHT AND PRE-PAYMENT.
 TERMS: DUE 25TH OF MONTH FOLLOWING DATE OF INVOICE
RETURN POLICY - ORIGINAL INVOICE MUST BE SUPPLIED, NO RETURNS AFTER 30 DAYS OF RECEIPT. A 25% RE-STOCKING FEE PLUS APPLICABLE RETURN FREIGHT CHARGES WILL BE CHARGED ON SPECIAL ORDERED PARTS, ELECTRICAL PARTS ARE NON-RETURNABLE AFTER PACKAGING IS OPENED - NO EXCEPTIONS. ITEMS UNDER \$20.00 ARE NON-RETURNABLE.



SIGNATURE
 RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



1761180 ALBERTA LTD O/A OK TIRE (WAINWRIGHT)

PO Box 3626
 Wainwright, AB T9W 1T5
 780-842-0982
 Email: 1761180ab@gmail.com
 Tax ID# 805077930 RT0001

Invoice

Bill To Davco Industrial Ltd.
 402 4th Ave SOUTH
 Wainwright, AB T9W 0C5
 Canada

Plate AB BC-0122
 Description Bobcat
 VIN
 Unit BC-0122
 Odometer 5,726

DAVE +1 (780) 209-0110
 RON +1 (780) 806-6414
 Email ron.laferriere@davcoltd.com

Invoice Date 2025-01-07 6:32 AM
 Appointment 2025-01-06 8:00 AM
 Promised 2025-01-06 8:00 AM

Invoice # 12352
 Work Order # 20550
 Purchase Order # J25004-000-002
 Service Advisor Eric Corkum
 Technician Sales, Misc

Service

Cash / Counter Sale Parts

The following is a list of material items you purchased which are not associated with services or repairs.

24C-6 - BATTERY	1 Unit	\$185.28 / Unit	\$205.28 G
* Includes \$20.00 core charge.			
		Sub	\$205.28

Total Parts		\$205.28
Total Labor		\$0.00
Total Before Taxes & Miscellaneous Charges		\$205.28
(G) Canadian Goods and Services Tax (GST)	5 %	\$10.26
Grand Total		\$215.54

Davco Industrial Ltd. charged \$215.54 to Account - 24 - Davco Industrial Ltd. - Net 30 Days

Thanks for the Business!

** WHEEL MANUFACTURERS RECOMMEND CHECKING THE TORQUE ON FASTENERS BETWEEN 80-150 KM AFTER EACH WHEEL REMOVAL AND INSTALL. HOWEVER IF RE-TORQUE IS NOT COMPLETED BY OK TIRE (WAINWRIGHT) WE ASSUME NO RESPONSIBILITY IN THE EVENT OF A WHEEL OFF SITUATION.**

I acknowledge receipt of the vehicle and the indebtedness indicated herein.

Customer Signature: _____

EXPENSE APPROVAL

NON-BILLABLE

Approver:
Ron Laferriere

Job:

WBS:

PO:

Cost expense to the job.

Approver confirms the good and/or services on this invoice have been satisfactorily received.



YOU WILL RECEIVE A REVIEW REQUEST THE DAY FOLLOWING YOUR APPOINTMENT. PLEASE TAKE A MOMENT TO LEAVE A REVIEW, IT WOULD BE VERY HELPFUL.



Lloydminster
 Box 10039 • Lloydminster, AB T9V 3A2
 Tel: 780.875.4471 Fax:780.875.6606
 www.horizonagturf.com

BC122

Ship to: IN STORE PICKUP

Invoice to: DAVCO INDUSTRIAL LTD.
 402 4TH AVE S
 WAINWRIGHT AB T9W 0C5

Branch LLOYDMINSTER		CNNYYY
Date 12/19/24	Time 14:45:13 (O)	Page 01
Account No. 8425559	Phone No. 780-842-3331	Invoice No. P11780
Ship Via	Purchase Order 24004-000-201	
		Salesperson JDF

PARTS INVOICE

ORDER#: 011998

Have you heard about MyDealer yet? We have a great way to help you stay connected to your equipment. Either mobile or laptop - look up parts, order them online, view past purchases, or book a service appointment, you are in control. Ask a parts or service member about MyDealer today!

Part#	Description	Bin	ORD	ISS	SHF	B/O	UTTTT	Price	Amount
7246781	COUPLER, FF FEM	C12H3	1	1	1		*	77.52	77.52
								SUB TOTAL==>	77.52
								GST #70762 9879 RT0001	3.88
								TOTAL CREDIT CARD	81.40

APPROVED
 Authorization Number:019940
 Account Number:*****2261
 Card Type:Mastercard
 Entry Mode:Contactless
 Application Name:Mastercard
 Application Id:A0000000041010
 Cryptogram:ARQC 5D91C980AF1A3A5E
 Response:0 - Approved
 Transaction Date:12/19/2024 16:45:08 PM
 Transaction Id:905701824
 Approved Amount:\$81.40
 Reference Number:01.01.21.011998
 Transaction Type:Sale
 Signature Not Required

LATE CHARGE OF 2% PER MONTH (24% PER ANNUM), SPECIAL ORDER PARTS WILL BE SUBJECT TO FREIGHT AND PRE-PAYMENT.
 TERMS: DUE 25TH OF MONTH FOLLOWING DATE OF INVOICE
RETURN POLICY - ORIGINAL INVOICE MUST BE SUPPLIED, NO RETURNS AFTER 30 DAYS OF RECEIPT. A 25% RE-STOCKING FEE PLUS APPLICABLE RETURN FREIGHT CHARGES WILL BE CHARGED ON SPECIAL ORDERED PARTS, ELECTRICAL PARTS ARE NON-RETURNABLE AFTER PACKAGING IS OPENED - NO EXCEPTIONS. ITEMS UNDER \$20.00 ARE NON-RETURNABLE.



SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
 Box 10039 • Lloydminster, AB T9V 3A2
 Tel: 780.875.4471 Fax:780.875.6606
 www.horizonagturf.com

PACKING SLIP - NOT AN INVOICE

BC-122

Ship to:

IN STORE PICKUP

Invoice to:

DAVCO INDUSTRIAL LTD.
 402 4TH AVE S
 WAINWRIGHT AB T9W 0C5

Branch LLOYDMINSTER		ANYYYY
Date 08/21/24	Time 14:14:42 (O)	Page 01
Account No. 8425559	Phone No. 780-842-3331	Invoice No. PICPAK
Ship Via	Purchase Order J24004-000-110	
		Salesperson JDF

PACKING SLIP - NOT AN INVOICE

ORDER#: 001060.01

Have you heard about MyDealer yet? We have a great way to help you stay connected to your equipment. Either mobile or laptop - look up parts, order them online, view past purchases, or book a service appointment, you are in control. Ask a parts or service member about MyDealer today!

Part#	Description	Bin	ORD	ISS	SHP	B/O	UTTTT	Price	Amount
7025094	COIL		1	1	1		*	117.77	117.77 <0
780-546-9166 COHL									

SUB TOTAL==> 117.77
 GST #70762 9879 RT0001 5.89
 TOTAL CREDIT CARD 123.66

?XXXXXXXXXXXX

PAID With
 Colton's
 CC



1761180 ALBERTA LTD O/A OK TIRE (WAINWRIGHT)

PO Box 3626
 Wainwright, AB T9W 1T5
 780-842-0982
 Email: 1761180ab@gmail.com
 Tax ID# 805077930 RT0001

Invoice

Bill To Davco Industrial Ltd.
 402 4th Ave SOUTH
 Wainwright, AB T9W 0C5
 Canada

Plate AB BC-0122
 Description Bobcat
 VIN
 Unit BC-0122
 Odometer 5,725

DAVE +1 (780) 209-0110
 RON +1 (780) 806-6414
 Email ron.laferriere@davcoltd.com

Invoice # 11115
 Work Order # 18970
 Purchase Order # RON L
 Service Advisor Eric Corkum
 Technician Chris Marchand

Invoice Date 8/8/2024 7:35 AM
 Appointment 8/6/2024 1:00 PM
 Promised 8/6/2024 5:00 PM

Inspection

Reason for Today's Visit

Service

1. Skidsteer Tire Repair - LOOSE

Diagnose leak. Inspect all components. Clean as required. Repair. Fill to proper PSI.

TIRE LEAKING DUE TO BENT RIM. REMOVED TIRE STRAIGHTENED RIM AS BEST AS POSSIBLE, CLEANED RIM AND SEALED BEADS WHEN TIRE WAS RE-MOUNTED.

Labor		\$45.00 *G
	Discount	(\$3.15)
	Sub	\$41.85
<hr/>		
Total Parts		\$0.00
Total Labor		\$41.85
Total Before Taxes & Miscellaneous Charges		\$41.85
<hr/>		
(*) Materials and Consumables		\$5.00 G
(H) Hazard/Enviro/Carbon Fee/Disposal		\$2.50 G
(G) Canadian Goods and Services Tax (GST)	5 %	\$2.47
Grand Total		\$51.82

Total discounts applied is \$3.15

Davco Industrial Ltd. charged \$51.82 to Account - 24 - Davco Industrial Ltd. - Net 30 Days

Thanks for the Business!

** WHEEL MANUFACTURERS RECOMMEND CHECKING THE TORQUE ON FASTENERS BETWEEN 80-150 KM AFTER EACH WHEEL REMOVAL AND INSTALL. HOWEVER IF RE-TORQUE IS NOT COMPLETED BY OK TIRE (WAINWRIGHT) WE ASSUME



YOU WILL RECEIVE A REVIEW REQUEST THE DAY FOLLOWING YOUR APPOINTMENT. PLEASE TAKE A MOMENT TO LEAVE A REVIEW, IT WOULD BE VERY HELPFUL.



1761180 ALBERTA LTD

PO Box 3626

Wainwright, AB T9W 1T5

780-842-0982

Email: 1761180ab@gmail.com

Tax ID# 805077930 RT0001

Invoice

Bill To Davco Welding Ltd.
PO Box 2904
Wainwright, AB T9W 1S8
Canada

Plate AB BC-0122
Description Bobcat
VIN
Unit BC-0122
Odometer 5,724

DAVE +1 (780) 209-0110
Eugene +1 (780) 806-8967
Email Sean.Naagle@DavcoLtd.com

Invoice # 7586
Work Order # 11897
Purchase Order # NA
Service Advisor Eric Corkum
Technician Kevin Koppenol

Invoice Date 2023-02-02 6:40 AM
Appointment 2023-02-01 8:00 AM
Promised 2023-02-01 5:00 PM

Service

1. Service Truck Repair

REPLACE DAMAGED HYD LINES AND FITTINGS. RESECURE HYD LINES AND TEST FOR LEAKS.

Labor			\$917.16 *G
hose fittings - hydraulic hose fittings	1 Unit	\$348.00 / Unit	\$348.00 G
hose & fittings - hydraulic hose and fittings	1 Unit	\$594.84 / Unit	\$594.84 G
P CLAMP LARGE - P CLAMP 545.112//545.2//545.1	3 Unit	\$5.62 / Unit	\$16.86 G
553.3300 - Dual Clamp Zipties	5 Unit	\$8.34 / Unit	\$41.70 G
553.59001 - Black Ziptie 0.30 x 15"	6 Unit	\$1.19 / Unit	\$7.14 G
129-8 - 1/2" BRASS COLLAR	1 Unit	\$9.05 / Unit	\$9.05 G
		Discount	-\$137.57
		Sub	\$1,797.18

Total Parts	\$1,017.59
Total Labor	\$779.59
Total Before Taxes & Miscellaneous Charges	\$1,797.18

(*) Materials and Consumables	\$70.16 G
(*1) Grade 8 Fasteners*	\$1.97 G
(H) Hazardous Waste	\$11.69 G
(G) Canadian Goods and Services Tax (GST)	5 % \$94.05
Grand Total	\$1,975.05

Total discounts applied is \$137.57

WE OFFER FINANCING FOR TIRES AND REPAIRS! QUICK APPROVAL! ASK US HOW!

Davco Welding Ltd. charged \$1,975.05 to Account - 24 - Davco Welding Ltd. - Net 30 Days

Thanks for the Business!

** WHEEL MANUFACTURERS RECOMMEND CHECKING THE TORQUE ON FASTENERS BETWEEN 80-150 KM AFTER EACH WHEEL REMOVAL AND INSTALL. HOWEVER IF RE-TORQUE IS NOT COMPLETED BY OK TIRE (WAINWRIGHT) WE ASSUME NO RESPONSIBILITY IN THE EVENT OF A WHEEL OFF SITUATION.**

I acknowledge receipt of the vehicle and the indebtedness indicated herein.

Customer Signature: _____

WE OFFER FINANCING FOR TIRES AND REPAIRS! QUICK APPROVAL! ASK US HOW!



Davco Welding Ltd.
780-842-5559
www.DavcoLtd.com

Wainwright, AB
Box 2904, T9W 1S8
402 4th Ave South

Lloydminster, AB
5101 65th Street

Vehicle Servicing Report

S600-MP-120 2019-December-31

Date: 11/24/22

Time: 1:00

Unit Number: 122

Hrs/Odometer: 5605

Next Service Due: 5855

CVIP Decal & All Documentation: _____

Entered *EPD* OK N/A

: 360° perimeter inspection

- | | |
|--|---|
| <input checked="" type="checkbox"/> Windshield | <input checked="" type="checkbox"/> Headlight |
| <input checked="" type="checkbox"/> Cracked | <input checked="" type="checkbox"/> Fog Lamp |
| <input checked="" type="checkbox"/> Chipped | <input checked="" type="checkbox"/> Signal Lights |
| <input checked="" type="checkbox"/> Sandblasted | <input checked="" type="checkbox"/> Hazard Light |
| <input checked="" type="checkbox"/> Mirrors | <input checked="" type="checkbox"/> Dome Light |
| <input checked="" type="checkbox"/> Side Windows | <input checked="" type="checkbox"/> Washer System |
| <input checked="" type="checkbox"/> Wiper/arm | <input checked="" type="checkbox"/> Brake light |
| <input checked="" type="checkbox"/> Back-up Lights | <input checked="" type="checkbox"/> Work lights |

: diesel components

- | | | |
|-------------------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Air filter restriction gauge and housing |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Water in fuel dash light |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Charge air cooling piping/ air intake system |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Turbocharger |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Auto Shut Off - Tested |

: Inventory

- | | | |
|-------------------------------------|-------------------------------------|--------------------|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Fire Extinguisher |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | First Aid Kit |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Flares / Triangles |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Unit Binder |

: under hood inspection

- | | | |
|-------------------------------------|-------------------------------------|---|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Drive Belts |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Air Filter & minder |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Radiator, hoses/clamps and Coolant condition to: - ____°C |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Horn |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Interior Hood Light |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Block Heater |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Heater hoses/clamps |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Air Conditioning Hoses |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Cabin/pollen air filter |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Battery/cables/clamps |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Battery performance 1 |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | COLD CRANKING AMPS: FACTORY SPECS. ____Actual |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Battery performance 2 |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | COLD CRANKING AMPS: FACTORY SPECS. ____Actual |

: under vehicle inspection

- | | | |
|-------------------------------------|-------------------------------------|-----------------------------------|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Steering components |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Suspension components |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Shocks leakage damage |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Struts leakage damage |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Exhaust system |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | CV drive axle boots (if equipped) |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Driveline Front & Rear |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | CHECK FOR Damage |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Front Fenders _____ |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Doors _____ |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Bumpers _____ |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Back deck/box _____ |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Tailgate _____ |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Interior _____ |

: fluid level check and fill

- | | | |
|-------------------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Engine oil |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Window washer fluid |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Transmission fluid level/color |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Brake fluid/color |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Power steering fluid |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Coolant recovery reservoir level |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | 4X4 transfer case/front drive/clutch & Rear Diff |

: Pickerss

- | | | |
|-------------------------------------|-------------------------------------|------------------------|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Oil Level |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Hoses |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Levers |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Leaks |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Function |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Security of Components |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Lubricate / grease |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Outriggers |

: brake inspection BRAKE INSPECTION NOT REQUIRED WITH THIS SERVICE

- | | | | | | |
|--|-------------------------------------|----------------------|--|-------------------------------------|----------------------|
| RF <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | _____mm (Lining/pad) | RR <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | _____mm (Lining/pad) |
| | <input checked="" type="checkbox"/> | Rotor | | <input checked="" type="checkbox"/> | Rotor |
| | <input checked="" type="checkbox"/> | Caliper | | <input checked="" type="checkbox"/> | Caliper |
| | <input checked="" type="checkbox"/> | Line/hoses | | <input checked="" type="checkbox"/> | Line/hoses |
| LF <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | _____mm (Lining/pad) | LR <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | _____mm (Lining/pad) |
| | <input checked="" type="checkbox"/> | Rotor | | <input checked="" type="checkbox"/> | Rotor |
| | <input checked="" type="checkbox"/> | Caliper | | <input checked="" type="checkbox"/> | Caliper |
| | <input checked="" type="checkbox"/> | Line/hoses | | <input checked="" type="checkbox"/> | Line/hoses |

: tire inspection

- | | | | | | | | | | | | | | | |
|--|-------------------------------------|-----------|-------------------------------------|-------------------------------------|-----------|-------------------------------------|-------------------------------------|----------|--|-------------------------------------|-----------|-------------------------------------|-------------------------------------|-------------------------------------|
| RF <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | _____ PSI | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | _____ PSI | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | _____ MM | RR <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | _____ PSI | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | _____ MM |
| | <input checked="" type="checkbox"/> | | | <input checked="" type="checkbox"/> | | | <input checked="" type="checkbox"/> | | | <input checked="" type="checkbox"/> | | <input checked="" type="checkbox"/> | | <input checked="" type="checkbox"/> |
| LF <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | _____ PSI | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | _____ PSI | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | _____ MM | LR <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | _____ PSI | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | _____ MM |
| | <input checked="" type="checkbox"/> | | | <input checked="" type="checkbox"/> | | | <input checked="" type="checkbox"/> | | | <input checked="" type="checkbox"/> | | <input checked="" type="checkbox"/> | | <input checked="" type="checkbox"/> |

RECOMMEND: ROTATION REPLACEMENT ALIGNMENT BALANCE

Oil Filter Wix 51085 Fuel Filter fleet guard FS 1235 Fuel Filter _____ Air Filter fleet guard AF 27999, AF 27998
Hyd Filter _____ Filter _____ Filter _____ Filter _____

Comments

Mechanic: DAVE MCGEE

Signature: [Signature]



Davco Welding Ltd.
780-842-5559
www.DavcoLtd.com

Wainwright, AB
Box 2904, T9W 1S8
402 4th Ave South

Lloydminster, AB
5101 65th Street

Vehicle Servicing Report

S600-MP-120 2019-December-31

Date: Aug. 4, 2021

Time: _____

Unit Number: 122

Hrs/Odometer: 5060

Next Service Due: 5360

CVIP Decal & All Documentation: _____

OK N/A

: 360° perimeter inspection

- | | |
|--|---|
| <input checked="" type="checkbox"/> Windshield | <input checked="" type="checkbox"/> Headlight |
| <input checked="" type="checkbox"/> Cracked | <input checked="" type="checkbox"/> Fog Lamp |
| <input checked="" type="checkbox"/> Chipped | <input checked="" type="checkbox"/> Signal Lights |
| <input checked="" type="checkbox"/> Sandblasted | <input checked="" type="checkbox"/> Hazard Light |
| <input checked="" type="checkbox"/> Mirrors | <input checked="" type="checkbox"/> Dome Light |
| <input checked="" type="checkbox"/> Side Windows | <input checked="" type="checkbox"/> Washer System |
| <input checked="" type="checkbox"/> Wiper/arm | <input checked="" type="checkbox"/> Brake light |
| <input checked="" type="checkbox"/> Back-up Lights | <input checked="" type="checkbox"/> Work lights |

: diesel components

- | | | |
|-------------------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Air filter restriction gauge and housing |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Water in fuel dash light |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Charge air cooling piping/ air intake system |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Turbocharger |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Auto Shut Off - Tested |

: Inventory

- | | | |
|-------------------------------------|-------------------------------------|--------------------|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Fire Extinguisher |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | First Aid Kit |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Flares / Triangles |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Unit Binder |

: under hood inspection

- | | | |
|-------------------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Drive Belts |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Air Filter & minder |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Radiator, hoses/clamps and |
| | <input checked="" type="checkbox"/> | Coolant condition to: <u>40</u> °C |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Horn |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Interior Hood Light |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Block Heater |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Heater hoses/clamps |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Air Conditioning Hoses |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Cabin/pollen air filter |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Battery/cables/clamps |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Battery performance 1 |
| | <input checked="" type="checkbox"/> | COLD CRANKING AMPS: FACTORY SPECS. <u>824</u> Actual |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> | Battery performance 2 |
| | <input type="checkbox"/> | COLD CRANKING AMPS: FACTORY SPECS. _____ Actual |

: under vehicle inspection

- | | | |
|-------------------------------------|-------------------------------------|-----------------------------------|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Steering components |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Suspension components |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Shocks leakage damage |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Struts leakage damage |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Exhaust system |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | CV drive axle boots (if equipped) |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Driveline Front & Rear |
| | <input checked="" type="checkbox"/> | CHECK FOR Damage |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Front Fenders |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Doors |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Bumpers |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Back deck/box |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Tailgate |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Interior |

: fluid level check and fill

- | | | |
|-------------------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Engine oil |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Window washer fluid |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Transmission fluid level/color |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Brake fluid/color |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Power steering fluid |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Coolant recovery reservoir level |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | 4X4 transfer case/front drive/clutch & Rear Diff |

: Pickerss

- | | | |
|-------------------------------------|-------------------------------------|------------------------|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Oil Level |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Hoses |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Levers |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Leaks |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Function |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Security of Components |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Lubricate / grease |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Outriggers |

: brake inspection BRAKE INSPECTION NOT REQUIRED WITH THIS SERVICE

- | | |
|--|--|
| RF <input checked="" type="checkbox"/> _____ mm (Lining/pad) | RR <input checked="" type="checkbox"/> _____ mm (Lining/pad) |
| <input checked="" type="checkbox"/> Rotor | <input checked="" type="checkbox"/> Rotor |
| <input checked="" type="checkbox"/> Caliper | <input checked="" type="checkbox"/> Caliper |
| <input checked="" type="checkbox"/> Line/hoses | <input checked="" type="checkbox"/> Line/hoses |
| LF <input checked="" type="checkbox"/> _____ mm (Lining/pad) | LR <input checked="" type="checkbox"/> _____ mm (Lining/pad) |
| <input checked="" type="checkbox"/> Rotor | <input checked="" type="checkbox"/> Rotor |
| <input checked="" type="checkbox"/> Caliper | <input checked="" type="checkbox"/> Caliper |
| <input checked="" type="checkbox"/> Line/hoses | <input checked="" type="checkbox"/> Line/hoses |

: tire inspection

- | | | |
|--|---|---|
| RF <input checked="" type="checkbox"/> <u>35</u> PSI <u>5</u> <input checked="" type="checkbox"/> <u>35</u> PSI <u>10</u> MM | RR <input checked="" type="checkbox"/> _____ PSI _____ MM | <input type="checkbox"/> _____ PSI _____ MM |
| LF <input checked="" type="checkbox"/> <u>35</u> PSI <u>4</u> <input checked="" type="checkbox"/> <u>35</u> PSI <u>5</u> MM | LR <input checked="" type="checkbox"/> _____ PSI _____ MM | <input type="checkbox"/> _____ PSI _____ MM |
| | <input type="checkbox"/> _____ PSI _____ MM | <input type="checkbox"/> _____ PSI _____ MM |


RECOMMEND: ROTATION REPLACEMENT ALIGNMENT BALANCE

Oil Filter LF3604 Fuel Filter FS1235 Fuel Filter _____ Air Filter AF27998
Hyd Filter _____ Filter _____ Filter _____ Filter _____

Comments

Mechanic: _____

Signature: _____



Davco Welding Ltd.
780-842-5559
www.DavcoLtd.com

Wainwright, AB
Box 2904, T9W 1S8
402 4th Ave South

Lloydminster, AB
5101 65th Street

Vehicle Servicing Report

S600-MP-120 2019-December-31

Date: May 13, 2021

Time: _____

Unit Number: 122

Hrs/Odometer: 4940

Next Service Due: 5240

CVIP Decal & All Documentation: _____

OK [] N/A [x]

: 360 perimeter inspection

- Windshield: [x] Cracked, [x] Chipped, [x] Sandblasted
Mirrors: [x]
Side Windows: [x]
Wiper/arm: [x]
Back-up Lights: [x]
Headlight: [x]
Fog Lamp: [x]
Signal Lights: [x]
Hazard Light: [x]
Dome Light: [x]
Washer System: [x]
Brake light: [x]
Work lights: [x]

: diesel components

- Air filter restriction gauge and housing: [x]
Water in fuel dash light: [x]
Charge air cooling piping/ air intake system: [x]
Turbocharger: [x]
Auto Shut Off - Tested: [x]

: Inventory

- Fire Extinguisher: [x]
First Aid Kit: [x]
Flares / Triangles: [x]
Unit Binder: [x]

: under hood inspection

- Drive Belts: [x]
Air Filter & minder: [x]
Radiator, hoses/clamps and Coolant condition to: 90c
Horn: [x]
Interior Hood Light: [x]
Block Heater: [x]
Heater hoses/clamps: [x]
Air Conditioning Hoses: [x]
Cabin/pollen air filter: [x]
Battery/cables/clamps: [x]
Battery performance 1: [x]
COLD CRANKING AMPS: FACTORY SPECS. Actual
Battery performance 2: [x]
COLD CRANKING AMPS: FACTORY SPECS. Actual

: under vehicle inspection

- Steering components: [x]
Suspension components: [x]
Shocks leakage damage: [x]
Struts leakage damage: [x]
Exhaust system: [x]
CV drive axle boots (if equipped): [x]
Driveline Front & Rear: [x]

: fluid level check and fill

- Engine oil: [x]
Window washer fluid: [x]
Transmission fluid level/color: [x]
Brake fluid/color: [x]
Power steering fluid: [x]
Coolant recovery reservoir level: [x]
4X4 transfer case/front drive/clutch & Rear Diff: [x]

CHECK FOR Damage

- Front Fenders: [x]
Doors: [x]
Bumpers: [x]
Back deck/box: [x]
Tailgate: [x]
Interior: [x]

: Pickerss

- Oil Level: [x]
Hoses: [x]
Levers: [x]
Leaks: [x]
Function: [x]
Security of Components: [x]
Lubricate / grease: [x]
Outriggers: [x]

: brake inspection BRAKE INSPECTION NOT REQUIRED WITH THIS SERVICE

- RF [x] mm (Lining/pad) Rotor, Caliper, Line/hoses
RR [x] mm (Lining/pad) Rotor, Caliper, Line/hoses
LF [x] mm (Lining/pad) Rotor, Caliper, Line/hoses
LR [x] mm (Lining/pad) Rotor, Caliper, Line/hoses

: tire inspection

- RF [x] PSI [x] MM RR [x] PSI [x] MM
LF [x] PSI [x] MM LR [x] PSI [x] MM


RECOMMEND: [] ROTATION [] REPLACEMENT [] ALIGNMENT [] BALANCE

Oil Filter LF3759 Fuel Filter FS1235 Fuel Filter Air Filter AF27998
Hyd Filter Filter Filter Filter

Comments

Mechanic: _____

Signature: _____



Davco Welding Ltd.
780-842-5559
www.DavcoLtd.com

Wainwright, AB
Box 2904, T9W 1S8
402 4th Ave South

Lloydminster, AB
5101 65th Street

Repair Request

S600-MP-200 2020-October-22

Employee Name: Knights M. Date: 16 / 12 / 2020

Direct Supervisor: Alex MacLure

Item / Unit / Location / Area: 122. - Skid Steer

Detailed Description of Issue: Bob-tach will not open all the way on
unit 122. - Seems loose / mis-aligned

Captain

Reviewed & Authorization:

Priority: High Medium Low (see below legend)

Manager: Alex MacLure Date: Dec 17, 2020

Issued To: Wes Bateman

Corrective Actions:

Completed by: _____ Date: _____

Priority Scale:
High = ASAP
Medium = 1-3 weeks
Low = 4-8 weeks



Davco Welding Ltd.
780-842-5559
www.DavcoLtd.com

Wainwright, AB
Box 2904, T9W 1S8
402 4th Ave South

Lloydminster, AB
5101 65th Street

Vehicle Servicing Report

S600-MP-120 2019-December-31

Date: June 26, 2020

Time: _____

Unit Number: 172

Hrs/Odometer: 4567

Next Service Due: 4815

CVIP Decal & All Documentation: _____

OK N/A

: 360° perimeter inspection

- | | |
|--|---|
| <input checked="" type="checkbox"/> Windshield | <input checked="" type="checkbox"/> Headlight |
| <input checked="" type="checkbox"/> Cracked | <input checked="" type="checkbox"/> Fog Lamp |
| <input checked="" type="checkbox"/> Chipped | <input checked="" type="checkbox"/> Signal Lights |
| <input checked="" type="checkbox"/> Sandblasted | <input checked="" type="checkbox"/> Hazard Light |
| <input checked="" type="checkbox"/> Mirrors | <input checked="" type="checkbox"/> Dome Light |
| <input checked="" type="checkbox"/> Side Windows | <input checked="" type="checkbox"/> Washer System |
| <input checked="" type="checkbox"/> Wiper/arm | <input checked="" type="checkbox"/> Brake light |
| <input checked="" type="checkbox"/> Back-up Lights | <input checked="" type="checkbox"/> Work lights |

: diesel components

- | | |
|-------------------------------------|--|
| <input checked="" type="checkbox"/> | Air filter restriction gauge and housing |
| <input checked="" type="checkbox"/> | Water in fuel dash light |
| <input checked="" type="checkbox"/> | Charge air cooling piping/ air intake system |
| <input checked="" type="checkbox"/> | Turbocharger |
| <input checked="" type="checkbox"/> | Auto Shut Off - Tested |

: Inventory

- | | |
|-------------------------------------|--------------------|
| <input checked="" type="checkbox"/> | Fire Extinguisher |
| <input checked="" type="checkbox"/> | First Aid Kit |
| <input checked="" type="checkbox"/> | Flares / Triangles |
| <input checked="" type="checkbox"/> | Unit Binder |

: under hood inspection

- | | |
|-------------------------------------|--|
| <input checked="" type="checkbox"/> | Drive Belts |
| <input checked="" type="checkbox"/> | Air Filter & minder |
| <input checked="" type="checkbox"/> | Radiator, hoses/clamps and Coolant condition to: <u>40°C</u> |
| <input checked="" type="checkbox"/> | Horn |
| <input checked="" type="checkbox"/> | Interior Hood Light |
| <input checked="" type="checkbox"/> | Block Heater |
| <input checked="" type="checkbox"/> | Heater hoses/clamps |
| <input checked="" type="checkbox"/> | Air Conditioning Hoses |
| <input checked="" type="checkbox"/> | Cabin/pollen air filter |
| <input checked="" type="checkbox"/> | Battery/cables/clamps |
| <input checked="" type="checkbox"/> | Battery performance 1 |
| <input checked="" type="checkbox"/> | COLD CRANKING AMPS: FACTORY SPECS <u>67</u> Actual |
| <input checked="" type="checkbox"/> | Battery performance 2 |
| <input checked="" type="checkbox"/> | COLD CRANKING AMPS: FACTORY SPECS. ____ Actual |

: under vehicle inspection

- | | |
|-------------------------------------|-----------------------------------|
| <input checked="" type="checkbox"/> | Steering components |
| <input checked="" type="checkbox"/> | Suspension components |
| <input checked="" type="checkbox"/> | Shocks leakage damage |
| <input checked="" type="checkbox"/> | Struts leakage damage |
| <input checked="" type="checkbox"/> | Exhaust system |
| <input checked="" type="checkbox"/> | CV drive axle boots (if equipped) |
| <input checked="" type="checkbox"/> | Driveline Front & Rear |

: fluid level check and fill

- | | |
|-------------------------------------|--|
| <input checked="" type="checkbox"/> | Engine oil |
| <input checked="" type="checkbox"/> | Window washer fluid |
| <input checked="" type="checkbox"/> | Transmission fluid level/color |
| <input checked="" type="checkbox"/> | Brake fluid/color |
| <input checked="" type="checkbox"/> | Power steering fluid |
| <input checked="" type="checkbox"/> | Coolant recovery reservoir level |
| <input checked="" type="checkbox"/> | 4X4 transfer case/front drive/clutch & Rear Diff |

- CHECK FOR Damage**
- | | |
|-------------------------------------|---------------|
| <input checked="" type="checkbox"/> | Front Fenders |
| <input checked="" type="checkbox"/> | Doors |
| <input checked="" type="checkbox"/> | Bumpers |
| <input checked="" type="checkbox"/> | Back deck/box |
| <input checked="" type="checkbox"/> | Tailgate |
| <input checked="" type="checkbox"/> | Interior |

: Pickers (Hyd.)

- | | |
|-------------------------------------|------------------------|
| <input checked="" type="checkbox"/> | Oil Level |
| <input checked="" type="checkbox"/> | Hoses |
| <input checked="" type="checkbox"/> | Levers |
| <input checked="" type="checkbox"/> | Leaks |
| <input checked="" type="checkbox"/> | Function |
| <input checked="" type="checkbox"/> | Security of Components |
| <input checked="" type="checkbox"/> | Lubricate / grease |
| <input checked="" type="checkbox"/> | Outriggers |

: brake inspection BRAKE INSPECTION NOT REQUIRED WITH THIS SERVICE

- | | | | |
|--|-----------------------|--|-----------------------|
| RF <input checked="" type="checkbox"/> | _____ mm (Lining/pad) | RR <input checked="" type="checkbox"/> | _____ mm (Lining/pad) |
| | Rotor | | Rotor |
| | Caliper | | Caliper |
| | Line/hoses | | Line/hoses |
| LF <input checked="" type="checkbox"/> | _____ mm (Lining/pad) | LR <input checked="" type="checkbox"/> | _____ mm (Lining/pad) |
| | Rotor | | Rotor |
| | Caliper | | Caliper |
| | Line/hoses | | Line/hoses |

: tire inspection

- | | | | | | | | |
|--|---------------|-------------------------------------|---------------|-------------|--|-----------|----------|
| RF <input checked="" type="checkbox"/> | <u>32</u> PSI | <input checked="" type="checkbox"/> | <u>35</u> PSI | <u>6</u> MM | RR <input checked="" type="checkbox"/> | _____ PSI | _____ MM |
| | | | | | | _____ PSI | _____ MM |
| LF <input checked="" type="checkbox"/> | <u>35</u> PSI | <input checked="" type="checkbox"/> | <u>35</u> PSI | <u>7</u> MM | LR <input checked="" type="checkbox"/> | _____ PSI | _____ MM |
| | | | | | | _____ PSI | _____ MM |

RECOMMEND: ROTATION REPLACEMENT ALIGNMENT BALANCE

Oil Filter LF3604 Fuel Filter FS1235 Fuel Filter _____ Air Filter AF27998
 Hyd Filter _____ Filter _____ Filter _____ Air Filter AF27999

Comments

Mechanic: _____

Signature: _____