



SCHWAB CHEVROLET BUICK GMC LTD.

6503 SPARROW DRIVE, LEDUC, AB T9E 7C7
PHONE: (780) 986-2277 FAX: (780) 986-1123 PARTS DIRECT: (780) 986-4571
TOLL FREE: 1-866-986-2276
www.schwabs.ca G.S.T # R105587950

SO # 90317
Status

SERVICE ORDER CUSTOMER COPY



User 83 Page 2

Customer No	
JONNYS LIGHT OILFIELD P.O. BOX 214 2120 SPARROW DRIV NISKU, AB T9E 8A2	
Home	Bus (780) 955-9399
Cell	Today
Email	
Type	
Term	MasterCard

Advisor	Dawson Miller	Promised	12/04/2025 5:00 PM	Tag#	
Shop	S2	Opened	12/04/2025 2:56 PM	Location	
Priority		Cashiered	12/04/2025 3:25 PM	PO #	

License	Odom In	Odom Out	In Service Date	Stock No
CRT- 9342	122533	122533	01/09/2024	24166
Year	Make	Model	Model Number	Colour
2024	CHEVROLET	SILVERADO CREW CAB	CK10543	SUMMIT WHITE
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
3GCUUDE84RG126575	SCHWAB		01/09/2024	
Engine	DURAMAX 3.0L TURBO-DIESEL I6	Fleet #		

Labour	34.95
Parts	140.00
Recycle Fee	1.50
RECYCLE FEE	2.00
CONVENIENCE FEE	0.00
Supplies	0.00
Sub-Total	178.45
GST	8.92
Total Invoice	187.37
MasterCard	187.37

Recommended/Deferred Services

Code	Description	Amount
	VISUAL UNDER HOOD CHECKUP - Engine Air Cleaner Filter	
	VISUAL UNDER HOOD CHECKUP - Passenger Compartment Air Filter	

** Deferred Services prices are subject to change

TERMS		INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$_____ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: NET 30 DAYS, INTEREST OF 2% PER MONTH (24% PER ANNUM) CHARGED ON ALL OVERDUE ACCOUNTS.
<input type="checkbox"/> CASH	- PLEASE PAY ON INVOICE. NO STATEMENT WILL BE ISSUED.	
<input type="checkbox"/> CREDIT CARD	- NO REFUNDS OR EXCHANGE ON PARTS AFTER 30 DAYS.	
<input type="checkbox"/> CHEQUE	- NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS, GLASS OR SPECIAL ORDERS.	
<input type="checkbox"/> DEDUCTIBLE	- PARTS RETURNED FOR CREDIT THAT HAVE BEEN SUPPLIED AS ORDERED ARE SUBJECT TO A 15% HANDLING CHARGE.	
	- NO REFUNDS WITHOUT THIS INVOICE.	X _____ CUSTOMER SIGNATURE DATE

Name: **JONNYS LIGHT OILFIELD** Year/Make/Model: **2024 CHEVROLET SILVERADO** Date: **12/04/2025**
 VIN: **3GCUDE84RG126575** Odometer: **122533** Licence Plate #: **CREW CAB CRT- 9342**
 Service Consultant: _____ RO #: **90317**

Lube / Oil & Filter: Good Better Best Tire Rotation: Car Wash:
 CHECKED and OK FUTURE ATTENTION REQUIRED IMMEDIATE MAINTENANCE/REPAIR REQUIRED NOT INSPECTED



VISUAL EXTERIOR CHECKUP

Floor Mat Safety Check		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Horn		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Oil Life Monitor	29	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Reset Oil Life Monitor		<input type="checkbox"/>	<input type="checkbox"/>	
Active Dash Warning Lights		<input type="checkbox"/>		
Front Exterior Lamps		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Left & Right Front Wiper Blades		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Rear Wiper Blade		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Rear Exterior Lamps		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Spare Tire Checked		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Tires Inflated to Specification		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cameras / Sensors Cleaned		<input type="checkbox"/>	<input type="checkbox"/>	
Reset Tire Pressure Monitoring System		<input type="checkbox"/>	<input type="checkbox"/>	



VISUAL UNDER HOOD CHECKUP

Engine Oil Level	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Coolant Recovery Reservoir	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Power Steering Fluid	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Windshield Washer Fluid	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Brake Fluid Reservoir	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Transmission Fluid	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Diesel Exhaust Fluid (DEF)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Hoses: Engine, Power Steering & HVAC	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Belts: Engine, Accessory, Serpentine and/or V-Drive	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Battery Cables & Connections	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Engine Air Cleaner Filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Passenger Compartment Air Filter	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Notes: _____

Notes: _____



VISUAL UNDER VEHICLE CHECKUP

Vehicle Tire Type		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Left Front Tire Tread Depth	12	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
*Left Front Brake Lining		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Left Side CV Drive Axle Boots		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
*Left Rear Brake Lining		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Left Rear Tire Tread Depth	12	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Tire DOTs Within 6 Years		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Front Drive Axle		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Rear Drive Axle		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Transfer Case		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Right Front Tire Tread Depth	12	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
*Right Front Brake Lining		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Right Side CV Drive Axle Boots		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
*Right Rear Brake Lining		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Right Rear Tire Tread Depth	12	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Steering/Suspension, Shocks/Struts		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Driveshafts and U-Joints		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Exhaust System Components		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes: _____

This complimentary inspection does not replace the "Tire Rotation & Required Service" as required every 12,000 km per your owner's manual.
 *Only inspected when the "Tire rotation" service is purchased. See your Service Consultant for details.



SCHWAB CHEVROLET BUICK GMC LTD.

6503 SPARROW DRIVE, LEDUC, AB T9E 7C7
 PHONE: (780) 986-2277 FAX: (780) 986-1123 PARTS DIRECT: (780) 986-4571
 TOLL FREE: 1-866-986-2276
 www.schwabs.ca G.S.T # R105587950

SO # 93283
 Status

SERVICE ORDER CUSTOMER COPY



User 89 Page 1

Customer No
 JONNYS LIGHT OILFIELD
 P.O. BOX 214 2120 SPARROW DRIV
 NISKU, AB T9E 8A2

Home Bus (780) 955-9399
 Cell Today
 Email

Type
 Term MasterCard

Advisor Dawson Miller	Promised 02/25/2026 5:00 PM	Tag#
Shop S2	Opened 02/25/2026 12:52 PM	Location
Priority	Cashiered 02/25/2026 1:23 PM	PO #

License CRT-9342	Odom In 136259	Odom Out 136259	In Service Date 01/09/2024	Stock No 24166
Year 2024	Make CHEVROLET	Model SILVERADO CREW CAB	Model Number CK10543	Colour SUMMIT WHITE
Vehicle ID No 3GCUUDE84RG126575	Selling Dealer SCHWAB	Extended Warranty	Delivery Date 01/09/2024	
Engine DURAMAX 3.0L TURBO-DIESEL 16	Fleet #			

Request	Description	Job	CSR	Status				
201BM	3.0L DURAMAX LOF \$174.95 [EXSL] - OIL CHANGE	1	7903	Original				
Labour	Description	Type	Amount					
201B	3.0L DURAMAX LOF \$174.95 [EXSL]	CP						
Part	Description	Shp	SL	Bin	Type	Retail	Price	Amount
19370139	DEXOS D 0W20 1LIT	7		SWALL	CRO			
12735608	PF66 FILTER	1		03A5	CRO			
89022225	WWASHER FLUID	3		BULK	CRO			
Technician	7903 -				Est Parts			140.00
Cause	REQUESTED DEXOS D 0W20 LOF BAY3 TOP 8917 8923 BOTTOM 7914				Est Labour			34.95
Correction	COMPLETED DEXOS D 0W20 LOF OLM AT 61%				Request Sub-total			174.95

Request	Description	Job	CSR	Status
GM-EXPRSS	GM Canada Certified Service Express Inspection - N/C	2	7903	Original
				Est Parts 0.00
				Est Labour 0.00

Cherd ATB
 5056 unit 117

<input type="checkbox"/> CASH <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> CHEQUE <input type="checkbox"/> DEDUCTIBLE	TERMS	INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: NET 30 DAYS, INTEREST OF 2% PER MONTH (24% PER ANNUM) CHARGED ON ALL OVERDUE ACCOUNTS. X _____ CUSTOMER SIGNATURE DATE
	- PLEASE PAY ON INVOICE. NO STATEMENT WILL BE ISSUED.	
	- NO REFUNDS OR EXCHANGE ON PARTS AFTER 30 DAYS.	
	- NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS, GLASS OR SPECIAL ORDERS.	
	- PARTS RETURNED FOR CREDIT THAT HAVE BEEN SUPPLIED AS ORDERED ARE SUBJECT TO A 15% HANDLING CHARGE.	
	- NO REFUNDS WITHOUT THIS INVOICE.	



SCHWAB CHEVROLET BUICK GMC LTD.

6503 SPARROW DRIVE, LEDUC, AB T9E 7C7
PHONE: (780) 986-2277 FAX: (780) 986-1123 PARTS DIRECT: (780) 986-4571
TOLL FREE: 1-866-986-2276
www.schwabs.ca G.S.T # R105587950

SO # 93283
Status

SERVICE ORDER CUSTOMER COPY



User 89 Page 2

Customer No JONNYS LIGHT OILFIELD P.O. BOX 214 2120 SPARROW DRIV NISKU, AB T9E 8A2		Advisor Dawson Miller	Promised 02/25/2026 5:00 PM	Tag#
Home Cell Email	Bus Today (780) 955-9399	Shop S2	Opened 02/25/2026 12:52 PM	Location
Type Term MasterCard		Priority	Cashiered 02/25/2026 1:23 PM	PO #
		License CRT-9342	Odom In 136259	Odom Out 136259
		Year Make 2024 CHEVROLET	Model SILVERADO CREW CAB	In Service Date 01/09/2024
		Vehicle ID No 3GCUDE84RG126575	Selling Dealer SCHWAB	Model Number CK10543
		Engine DURAMAX 3.0L TURBO-DIESEL I6	Extended Warranty	Stock No 24166
			Fleet #	Colour SUMMIT WHITE
				Delivery Date 01/09/2024

Labour	34.95
Parts	140.00
RECYCLE FEE	2.00
CONVENIENCE FEE	0.00
Recycle Fee	1.50
Supplies	0.00
Sub-Total	178.45
GST	8.92
Total Invoice	187.37
MasterCard	187.37

Recommended/Deferred Services

Code	Description	Amount
	VISUAL UNDER HOOD CHECKUP - Passenger Compartment Air Filter	
	VISUAL UNDER HOOD CHECKUP - Engine Air Cleaner Filter	

** Deferred Services prices are subject to change

TERMS

- CASH - PLEASE PAY ON INVOICE. NO STATEMENT WILL BE ISSUED.
- CREDIT CARD - NO REFUNDS OR EXCHANGE ON PARTS AFTER 30 DAYS.
- CHEQUE - NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS, GLASS OR SPECIAL ORDERS.
- DEDUCTIBLE - PARTS RETURNED FOR CREDIT THAT HAVE BEEN SUPPLIED AS ORDERED ARE SUBJECT TO A 15% HANDLING CHARGE.
- NO REFUNDS WITHOUT THIS INVOICE.

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: NET 30 DAYS, INTEREST OF 2% PER MONTH (24% PER ANNUM) CHARGED ON ALL OVERDUE ACCOUNTS.

X _____
CUSTOMER SIGNATURE DATE

Name: **JONNYS LIGHT OILFIELD** Year/Make/Model: **2024 CHEVROLET SILVERADO** Date: **02/25/2026**
 VIN: **3GCUDD84RG126575** Odometer: **136259** **CREW CAB** Licence Plate #: **CRT-9342** 12:52:18 PM
 Service Consultant: _____ RO #: **93283**

Lube / Oil & Filter: Good Better Best Tire Rotation: Car Wash:
 CHECKED and OK FUTURE ATTENTION REQUIRED IMMEDIATE MAINTENANCE/REPAIR REQUIRED NOT INSPECTED



VISUAL EXTERIOR CHECKUP

Floor Mat Safety Check		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Horn		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Oil Life Monitor	%	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Reset Oil Life Monitor		<input type="checkbox"/>	<input type="checkbox"/>		
Active Dash Warning Lights		<input type="checkbox"/>			
Front Exterior Lamps		<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>
Left & Right Front Wiper Blades		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Rear Wiper Blade		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Rear Exterior Lamps		<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>
Spare Tire Checked		<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>
Tires Inflated to Specification		<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>
Cameras / Sensors Cleaned		<input type="checkbox"/>	<input type="checkbox"/>		
Reset Tire Pressure Monitoring System		<input type="checkbox"/>	<input type="checkbox"/>		



VISUAL UNDER HOOD CHECKUP

Engine Oil Level		<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>
Coolant Recovery Reservoir		<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>
Power Steering Fluid		<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>
Windshield Washer Fluid		<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>
Brake Fluid Reservoir		<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>
Transmission Fluid		<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>
Diesel Exhaust Fluid (DEF)		<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>
Hoses: Engine, Power Steering & HVAC		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>
Belts: Engine, Accessory, Serpentine and/or V-Drive		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>
Battery Cables & Connections		<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>
Engine Air Cleaner Filter		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>
Passenger Compartment Air Filter		<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>

Notes: _____

Notes: _____



VISUAL UNDER VEHICLE CHECKUP

Vehicle Tire Type					
Left Front Tire Tread Depth	11	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
*Left Front Brake Lining		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Left Side CV Drive Axle Boots		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
*Left Rear Brake Lining		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Left Rear Tire Tread Depth	11	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Tire DOTs Within 6 Years		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Front Drive Axle		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Rear Drive Axle		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Transfer Case		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Right Front Tire Tread Depth	11	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
*Right Front Brake Lining		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Right Side CV Drive Axle Boots		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
*Right Rear Brake Lining		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Right Rear Tire Tread Depth	11	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Steering/Suspension, Shocks/Struts		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Driveshafts and U-Joints		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Exhaust System Components		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Notes: _____

111A



11/11/60

111

George ...

... ..

... ..

Messiah

Schwab

SCHWAB CHEVROLET BUICK GMC LTD.

6503 SPARROW DRIVE, LEDUC, AB T9E 7C7
PHONE: (780) 986-2277 FAX: (780) 986-1123 PARTS DIRECT: (780) 986-4571
TOLL FREE: 1-866-986-2276
www.schwabs.ca G.S.T # R105587950

SO# 76625
Status

117

SERVICE ORDER CUSTOMER COPY

Transportation

User 62 Page 1

Customer No
JONNYS LIGHT OILFIELD
P.O. BOX 214 2120 SPARROW DRIV
NISKU, AB T9E 8A2

Home Cell Email
Bus (780) 955-9399
Today
Type Term Cash

Advisor Trevor Wolfe	Promised 12/31/2024 5:00 PM	Tag# 3419
Shop S1	Opened 12/09/2024 11:55 AM	Location
Priority 30	Cashiered	PO #

License CRT- 9342	Odom In 47229	Odom Out 47232	In Service Date 01/09/2024	Stock No 24166
Year 2024	Make CHEVROLET	Model SILVERADO CREW CAB	Model Number CK10543	Colour SUMMIT WHITE
Vehicle ID No 3GCUDE84RG126575	Selling Dealer SCHWAB	Extended Warranty	Delivery Date 01/09/2024	
Engine DURAMAX 3.0L TURBO-DIESEL I6	Fleet #			

Request	Description	Job	CSR	Status			
098D	CHECK ENGINE LIGHT IS ON. code's u02ap/p045b/p059f	1	62	Original			
Labour	Description	Type	Amount				
098D	CHECK ENGINE LIGHT IS ON	W					
Part	Description	Shp	SL	Bin	Type	Price	Amount
13549888	PUMP	1		06F1	WP		
10953456	COOLANT PREMIX 4 LIT	1		SWALL	WP		
Technician	147 -			Est Parts			0.00
Cause	U02A9 - Lost Communication with Charge Air Cooler Coolant Pump - p/f P045B - Exhaust Gas Recirculation Valve 2 Open Position Performance - p/f P059F - Active Grille Air Shutter 1 Performance - p/f			Est Labour			0.00

Found #23-NA-102: This condition may be caused by one or more of the following: for U02A9

CAC pump electrical connector, active grill shutter electrical connector, engine wiring harness contacting the alternator bracket, loose ground at the front of the engine. Raised vehicle up, disconnect connector at CAC pump, connector is good. Confirm engine harness not contacting alternator bracket. Grill shutter connector is good, verify ground at front of engine is good. Attempt to command pump speed on using scan tool, actual and desired do not match, perform circuit testing - circuits are good. Fault with CAC pump causing U02A9 to set.

Correction Raised vehicle up, remove front skid plate, disconnect electrical connector and both coolant hoses from CAC pump. Install new pump, reinstall hoses/secured using existing clamps, reconnect electrical connector. Lowered vehicle, vac filled system with 50/50 premix dexcool. Cleared dtc, now able to command pump speed - confirm actual and desired do match. Road test vehicle, good now.

DIAG - 1.0
R&R - 0.8

Warranty for f. inc

Request	Description	Job	CSR	Status	
098D	REDUCED POWER DISPLAYED	2	62	Original	
Labour	Description	Type	Amount		
098D	REDUCED POWER DISPLAYED	W			
Technician	147 -			Est Parts	0.00

<input type="checkbox"/> CASH <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> CHEQUE <input type="checkbox"/> DEDUCTIBLE	TERMS	INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: NET 30 DAYS, INTEREST OF 2% PER MONTH (24% PER ANNUM) CHARGED ON ALL OVERDUE ACCOUNTS. X _____ CUSTOMER SIGNATURE DATE
	- PLEASE PAY ON INVOICE. NO STATEMENT WILL BE ISSUED.	
	- NO REFUNDS OR EXCHANGE ON PARTS AFTER 30 DAYS.	
	- NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS, GLASS OR SPECIAL ORDERS.	
	- PARTS RETURNED FOR CREDIT THAT HAVE BEEN SUPPLIED AS ORDERED ARE SUBJECT TO A 15% HANDLING CHARGE.	
	- NO REFUNDS WITHOUT THIS INVOICE.	



SCHWAB CHEVROLET BUICK GMC LTD.

6503 SPARROW DRIVE, LEDUC, AB T9E 7C7
PHONE: (780) 986-2277 FAX: (780) 986-1123 PARTS DIRECT: (780) 986-4571
TOLL FREE: 1-866-986-2276
www.schwabs.ca G.S.T # R105587950

SO# 76625

Status

SERVICE ORDER CUSTOMER COPY

Transporation

User 62 Page 2

Customer No
JONNYS LIGHT OILFIELD
P.O. BOX 214 2120 SPARROW DRIV
NISKU, AB T9E 8A2

Home Bus (780) 955-9399
Cell Today
Email

Type
Term Cash

Advisor	Trevor Wolfe	Promised	12/31/2024 5:00 PM	Tag#	3419
Shop	S1	Opened	12/09/2024 11:55 AM	Location	
Priority	30	Cashiered		PO #	

License	Odom In	Odom Out	In Service Date	Stock No
CRT- 9342	47229	47232	01/09/2024	24166
Year	Make	Model	Model Number	Colour
2024	CHEVROLET	SILVERADO CREW CAB	CK10543	SUMMIT WHITE
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
3GCUUDE84RG126575	SCHWAB		01/09/2024	
Engine	DURAMAX 3.0L TURBO-DIESEL I6	Fleet #		

Cause P059F - Active Grille Air Shutter 1 Performance - p/f
Inspected grille shutter for any signs of ice/debris causing shutter to get stuck, all looks ok. Attempt to command shutter using scan tool, shutter does not move. Additional time required to remove intake air splash shield, front grille and fascia to continue diagnosis for P059F. Removed shutter to inspect/test circuits, found slightly corroded wire approx. 5" from J109. **Est Labour** 0.00

Correction Repaired wire, reinstall shutter, intake air splash shield, front grille and fascia. Cleared dtc, now able to command shutter using scan tool. Road test to verify and good now.

Connector endview doc ID -.6369231
Grid location - D2

DIAG - 0.3
E.T. DISASSEMBLE - 0.5
WIRE REPAIR - 0.5
E.T. REASSEMBLE - 0.5

Request	Description	Job	CSR	Status
RECALL	N242435631 - Serial Data Gateway Module	3	62	Original
Labour	Description	Type	Amount	
RECALL	N242435631 - Serial Data Gateway Module	W		
Technician	147 -			
		Est Parts		0.00
Cause	N242435631 - Serial Data Gateway Module	Est Labour		0.00
Correction	Reprogrammed SDGM with latest software calibrations using SPS.			

WCC: 0SYY250939735

Labour	0.00
Parts	0.00
Supplies	0.00
Sub-Total	0.00
GST	0.00
Total Invoice	0.00

<input type="checkbox"/> CASH <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> CHEQUE <input type="checkbox"/> DEDUCTIBLE	TERMS	INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: NET 30 DAYS, INTEREST OF 2% PER MONTH (24% PER ANNUM) CHARGED ON ALL OVERDUE ACCOUNTS. X _____ CUSTOMER SIGNATURE DATE
	- PLEASE PAY ON INVOICE. NO STATEMENT WILL BE ISSUED.	
	- NO REFUNDS OR EXCHANGE ON PARTS AFTER 30 DAYS.	
	- NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS, GLASS OR SPECIAL ORDERS.	
	- PARTS RETURNED FOR CREDIT THAT HAVE BEEN SUPPLIED AS ORDERED ARE SUBJECT TO A 15% HANDLING CHARGE.	
	- NO REFUNDS WITHOUT THIS INVOICE.	



SCHWAB CHEVROLET BUICK GMC LTD.

6503 SPARROW DRIVE, LEDUC, AB T9E 7C7
PHONE: (780) 986-2277 FAX: (780) 986-1123 PARTS DIRECT: (780) 986-4571
TOLL FREE: 1-866-986-2276
www.schwabs.ca G.S.T # R105587950

SO# 72829

Status

SERVICE ORDER CLOSING COPY - IN PROGRESS

Transportion

User 67 Page 1

Customer No	
TYLER WINTERS 100 WALTERS PLACE LEDUC, AB T9E 0G3	
Home	Bus
Cell	Today
Email	
Type	
Term Cash	

Advisor	Brittany Hartley	Promised	10/05/2024 5:30 PM	Tag#	2490
Shop	S1	Opened	09/03/2024 10:15 AM	Location	
Priority	30	Cashiered		PO #	

License	Odom In	Odom Out	In Service Date	Stock No
CRT- 9342	26360	26361	01/09/2024	24166
Year	Make	Model	Model Number	Colour
2024	CHEVROLET	SILVERADO CREW CAB	CK10543	SUMMIT WHITE
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
3GCUDE84RG126575	SCHWAB		01/09/2024	
Engine	DURAMAX 3.0L TURBO-DIESEL I6	Price	Number	

Request	Description	Job	CSR	Status
098D	CHECK FOR ENGINE LIGHT ON PLEASE ADVISE	1	67	Original
Labour	Description	Type	Tech	Amount
098D	CHECK FOR ENGINE LIGHT ON PLEASE ADVISE	W	7831	
Technician	7831 -			
Cause	scanned and found code p138c set current - bulletin 24-NA-094 applies - found ECM not up-to-date - programmed and ran the vehicle under the condition for setting the DTC - all ok			
Correction	updated ECM			
	warranty code: 11YY231324922			

Labour	0.00
Parts	0.00
Supplies	0.00
Sub-Total	0.00
GST	0.00
Total Invoice	0.00

117