







# JONNYS

LIGHT OILFIELD HAULING


1107 - 11 Street, Nisku, AB T9E 0C6  
 Phone / Fax: 780-955-9399  
 Email: info@jonnys.ca



20240401-6649

## GARAGE REPAIR ORDER

5649

QTY	PART NO. AND DESCRIPTION	PRICE	Date: Feb 24/26	Unit #: 89	Driver's Name: Ryan Dasj
			Year:	Odometer:	Hours:
			VIN #:	Make:	
			Lic. #:	Model:	
			Work Performed by:		
HRS.	WORK PERFORMED	COST			
	- Lines on both outrigger jacks (front) are reversed, operates backward's, up & down, down is up. <del>DTW</del> switch, outrigger lines around				
	↳ Test operation				
	Remove in Cab toolbox				
<p><b>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</b></p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>			Total Parts Total Labour Shop Supply Misc.		
 _____ Authorized by			Subtotal GST 855519435RT0001 TOTAL		







20150520 - 0033

# GARAGE REPAIR ORDER

5375

QTY	PART NO. AND DESCRIPTION	PRICE	Date: December 17th 2025		Unit #: 89 Luke Eisner
			Year: 2012	Odometer: 57645	Hours: <del>21332</del> 22832
			VIN #: SK1CUALDR5CPBL2077		Make: Western star
			Lic. #:	Model: 4900	
			Work Performed by:		
	HRS.	WORK PERFORMED	COST		
		check <del>engine</del> engine light and stop engine light come on intermittently with a beeping			
	JZ	Crane cab heater not working, correctly appears the windshield washer / fluid for crane cab has kerosene in it a well			
	BW	missing fifth wheel puller			
		<p><b>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</b></p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p> <p>_____</p> <p>Authorized by</p>	Total Parts		
			Total Labour		
			Shop Supply		
			Misc.		
			Subtotal		
			GST 855519435RT0001		
			TOTAL		





Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive  
 Nisku, AB T9E 8A2  
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

# GARAGE REPAIR ORDER

5096

QTY	PART NO. AND DESCRIPTION	PRICE	Date:	Unit #:
★	TORQUED WHEELS TO 500/FT LBS AND PUT A RETORQUE TAG IN THE TRUCK ★		OCTOBER 9 2025	89
			Year: 2012	Odometer: 55331
			Hours: 21223	
			VIN #: 5KKUALDR5CPBL2077	Make: WESTERN STAR
			Lic. #: U39429	Model: B0188
			Work Performed by: TYLER TOKAREK	
HRS.	WORK PERFORMED	COST		
	★ ALL WHEELS REMOVED AT THE TIME OF INSPECTION ★			
	REPLACED BOTH D.S. STEER WHEEL SEALS			
	REPLACED BOTH DRIVE AXLE WHEEL SEALS #1 AXLE			
	REPLACED ALL 6 REAR BRAKE DRUMS.			
	REPLACED THE CENTER AXLE DIFF LOCK INDICATOR			
	CHECKED AND ADJUSTED TIRE PRESSURES.			
	CHECKED AND ADJUSTED THE 5TH WHEEL			
	CHECKED OIL LEVELS.			
	REPLACED THE R.M. DRIVE AXLE BRAKE POT			
	GREASED UNIT, SET BRAKES			
	REPLACED THE D.S. BACK-UP LIGHT.			
	HAD FOUNTAIN TIRE REPAIR ONE FLAT TIRE			
<p>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>			Total Parts	
			Total Labour	
			Shop Supply	
			Misc.	
			Subtotal	
			GST 855519435RT0001	
			TOTAL	
			Authorized by	



Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive  
 Nisku, AB T9E 8A2  
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

# GARAGE REPAIR ORDER

5112

QTY	PART NO. AND DESCRIPTION	PRICE	Date: <u>Sept 9, 2025</u>		Unit #: <u>89</u>	
	<u>Please Replace windshield washer cap.</u>		Year:	Odometer: <u>54423</u>	Hours: <u>21187</u>	
		VIN #:	Make: <u>WESTERN STAR</u>			
		Lic. #:	Model:			
		Work Performed by: <u>TYLER T.</u>				
	<u>Its Broken Thanks</u>		HRS.	WORK PERFORMED	COST	
				<u>REPLACED THE WINDSHIELD WASHER RESERVOIR CAP.</u>		
			<p><b>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</b></p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>		Total Parts Total Labour Shop Supply Misc. Subtotal GST 855519435RT0001 TOTAL	
			<p>_____            Authorized by</p>			





Jonny's Light Oilfield Hauling Ltd.

*Mike Mc*

PO Box #214, 2120 Sparrow Drive  
Nisku, AB T9E 8A2  
Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

# GARAGE REPAIR ORDER

4857

QTY	PART NO. AND DESCRIPTION	PRICE	Date: <i>May 16/25</i>		Unit #: <i>89</i>
	<i>Passenger seat need replacing Broken</i>		Year:	Odometer:	Hours:
			VIN #:	Make:	
			Lic. #:	Model:	
			Work Performed by: <i>Tyler W</i>		
	<i>Drivers air seat Bags Blown needs Replaced</i>	<i>BW says NO</i>	HRS.	WORK PERFORMED	COST
				<i>Blow out tank Breathers</i>	
	<i>Dash Panel Right Lower passenger side is now in sleeper Need to be put on came lose on the way home just complete 200km off road trip very rough - TW Re attached</i>				
	<i>Top hatch on Rigging cabinet is broken Drivers side New Latch Linkage TW</i>				
<p><b>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</b></p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>					Total Parts Total Labour Shop Supply Misc. Subtotal GST 855519435RT0001 TOTAL
_____ Authorized by					









Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive  
Nisku, AB T9E 8A2  
Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

# GARAGE REPAIR ORDER

## 4544

QTY	PART NO. AND DESCRIPTION	PRICE	Date: Feb 24/25		Unit #: 89
			Year:	Odometer:	Hours:
			VIN #:	Make:	
			Lic. #:	Model:	
			Work Performed by: Tyler W		
HRS.	WORK PERFORMED				COST
	New trailer cord from #2 steel				
	To trailer plug receptical				
	Test operation of lights ✓				
	2x torpedo levels ordered for driver				
	<p><b>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</b></p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>				Total Parts
	<p>_____</p> <p>Authorized by</p>				Total Labour
					Shop Supply
					Misc.
					Subtotal
					GST 855519435RT0001
					TOTAL

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive  
 Nisku, AB T9E 8A2  
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

# GARAGE REPAIR ORDER

4513

QTY	PART NO. AND DESCRIPTION	PRICE	Date: Feb 12, 2025	Unit #: 89
			Year:	Odometer: 44505
			VIN #:	Hours: 20727
			Lic. #:	Make: WESTERN STAR
			Model:	
			Work Performed by: TYLER T & TYLER W.	
			HRS.	WORK PERFORMED
				COST
	Driver side window rolls up to resistance and gear skips. (Note window is not completely sealed when the gear skips.			COMPLETE SERVICE - OIL ONLY
				WILL REPLACE WINDOW REGULATOR AT A LATER DATE
				20727
				250
				<u>20977 HRS.</u>
	20 HOURS AWAY FROM SERVICE ✓			
	7 WIRE CORD FOR TRAILER NEEDS TO BE REPLACED FROM THE CAB BACK TO THE PLUG ✓ T.W.			BUILT A NEW TRAILER CORD - WILL INSTALL AT A LATER DATE.
			<p>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>	
			<p>Total Parts</p> <p>Total Labour</p> <p>Shop Supply</p> <p>Misc.</p> <p>Subtotal</p> <p>GST 855519435RT0001</p> <p>TOTAL</p>	
			<p>Authorized by _____</p>	

0283

RECEIVED  
FEDERAL BUREAU OF INVESTIGATION  
U.S. DEPARTMENT OF JUSTICE

REC'D  
FBI  
MAY 1 1964

REPORT

DATE

BY

TITLE

CHARACTER OF SUBJECT

TOPIC

341 11 POE 000 152

RECEIVED  
FEDERAL BUREAU OF INVESTIGATION  
U.S. DEPARTMENT OF JUSTICE

REPORT

DATE

BY

TITLE

CHARACTER OF SUBJECT

TOPIC

341 11 POE 000 152

RECEIVED  
FEDERAL BUREAU OF INVESTIGATION  
U.S. DEPARTMENT OF JUSTICE

REPORT

DATE

BY

TITLE

CHARACTER OF SUBJECT

TOPIC

341 11 POE 000 152



# Driver Vehicle Inspection Reports — 89 ☆

INSPECTION TYPE	ORGANIZATION/CARRIER NAME	AUTHOR/AGENT/DRIVER NAME	DATE	LOCATION
Pre-trip	JONNY'S OILFIELD HAULING	Keith Breland	Dec 18, 1:39 PM	14710 Ellerslie Road SW, Edmonton, AB, T6W 1A4

DURATION	VEHICLE NAME	ODOMETER	LICENSE PLATE
1m 22s	<u>89</u>	43,173 km	U39429

## Resolve Defects

Check off defects below and click 'Resolve Defects' to resolve them.

### Vehicle Defects

#### Heater Defroster

Added Dec 18, 1:38 PM

Does not make heat driving down the road *AW*

#### Attachments

None

Unresolved ▼

+ Add mechanic note

#### Windshield Wipers

Added Dec 18, 1:38 PM

Upper wiper on swing cab does not work *TW*

#### Attachments

None

Unresolved ▼

+ Add mechanic note

## Activity

Driver Signature

Dec 18, 1:39 PM

I declare that the vehicle shown above has been inspected in accordance with the applicable requirements of Schedule 1 and/or jurisdiction legislation.

Keith Breland

**Author/Agent/Driver Signature**

Mechanic signature

Resolve all defects in this DVIR to add a 2nd signature.

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive  
 Nisku, AB T9E 8A2  
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

# GARAGE REPAIR ORDER

4247

QTY	PART NO. AND DESCRIPTION	PRICE	Date: Dec 17, 2024		Unit #: 89
			Year:	Odometer:	Hours:
			VIN #:	Make:	
			Lic. #:	Model:	
			Work Performed by: Tyler W		
HRS.	WORK PERFORMED				COST
	- Cruise Control doesn't work				
	- Headgasket? no to little heat in cab, Engine ERRADIC. New Core + Water Valve				
	- Swing cab heater not working (FAN on habasto?) New heater swing cab				
	- Drivers Side Window Regulator needs replaced window manual				
	- Only mirror lights work for Back up lights working, just on different switch				
	December 26 completed				
<p>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>					<p>Total Parts</p> <p>Total Labour</p> <p>Shop Supply</p> <p>Misc.</p>
<p><u>Tommy Gilman</u>            Authorized by</p>					<p>Subtotal</p> <p>GST 855519435RT0001</p> <p>TOTAL</p>

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive  
 Nisku, AB T9E 8A2  
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

# GARAGE REPAIR ORDER

4230

QTY	PART NO. AND DESCRIPTION	PRICE	Date:	Unit #:
★	TORQUED WHEELS TO 500 FT/LBS AND PUT A RETORQUE TAG IN THE TRUCK		DEC 12' 24	89
			Year:	Odometer: 42035
			VIN #:	Hours: 20605
			Lic. #:	Make: WESTERN STAR.
			Model:	
			Work Performed by: TYLER T.	
HRS.	WORK PERFORMED	COST		
	DRAWER/SWAMPER INFORMED ME THAT THE PICKER CAB HEATER WAS NOT WORKING			
	- BROUGHT UNIT IN & TESTED OUT - WORKED FINE			
	- ALSO INFORMED ME THAT THEY LOST THE COVER FOR THE PICKER CAB.			
	- THUMPED THE TIRES WHILE INSIDE - FOUND THE W.R.I WAS RIGHT OFF THE BEAD. REMOVED TIRE, AIRED UP AND CHECKED FOR LEAKS.			
	Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.		Total Parts	
	I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.		Total Labour	
			Shop Supply	
			Misc.	
			Subtotal	
			GST 855519435RT0001	
			TOTAL	
			Authorized by _____	

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive  
Nisku, AB T9E 8A2  
Ph/Fax: 780-955-9399 Email: info@jonnys.ca



# GARAGE REPAIR ORDER

3730

20150520 - 0033

★ CV8033479 ★

QTY	PART NO. AND DESCRIPTION	PRICE	Date:	Unit #:
★	TORQUED WHEELS TO 500 FT/LBS AND PUT A RETORQUE TAG IN THE TRUCK ★		OCTOBER 30 2024	89
			Year: 2012	Odometer: 40615 KM
			Hours: 20502	Make: WESTERN STAR
			VIN #: 5KKUALDR5CABL2077	Model: CONVENTIONAL
			Lic. #: U39429	Boiler
			Work Performed by: TYLER TOKAREK	
HRS.	WORK PERFORMED	COST		
★	ALL WHEELS REMOVED AT THE TIME OF INSPECTION ★ REPLACED BOTH D.S. STEER AXLE WHEEL SEALS. REPLACED ALL 4 STEER TIRES REPLACED ONE EXHAUST CLAMP ADJUSTED THE 5TH WHEEL REPLACED THE D.S. FENDER CLEARANCE LIGHT GREASED UNIT ADJUSTED THE BRAKES REPLACED POWER STEERING OIL AND FILTER HAD ALIATEC REPLACE THE D.S. WINDSHIELD REPLACED BOTH HYDRAULIC FILTERS REPLACED ONE TAIL LIGHT.			
			Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.	
			I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.	
			Authorized by _____	
			Total Parts	
			Total Labour	
			Shop Supply	
			Misc.	
			Subtotal	
			GST 855519435RT0001	
			TOTAL	







Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive  
 Nisku, AB T9E 8A2  
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



# GARAGE REPAIR ORDER

4393

20150520 - 0033

QTY	PART NO. AND DESCRIPTION	PRICE	Date: <i>Sept. 16, 2024</i>		Unit #: <i>T-89</i>
			Year:	Odometer:	Hours:
			VIN #:	Make:	
			Lic. #:	Model:	
			Work Performed by:		
	HRS.	WORK PERFORMED	COST		
		<i>Turn signal &amp; hazards lights not working</i>			
		<i>PURCHASED A NEW SIGNAL SWITCH FROM WESTERN STAR - SWAPPED IT OUT AND IT STILL DID NOT FIX THE PROBLEM - TRIED TO TROUBLE SHOOT FOR APPROX 6 HOURS AND GOT NO WHERE. - SENT UNIT TO WESTERN STAR FOR REPAIR.</i>			
		<p><b>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</b></p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p> <p>_____</p> <p>Authorized by</p>	Total Parts		
			Total Labour		
			Shop Supply		
			Misc.		
			Subtotal		
			GST 855519435RT0001		
		TOTAL			

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive  
 Nisku, AB T9E 8A2  
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

# GARAGE REPAIR ORDER

4384

QTY	PART NO. AND DESCRIPTION	PRICE	Date: <u>Sept. 12, 2024</u>		Unit #: <u>T-89</u>
			Year:	Odometer: <u>36938 km</u>	Hours: <u>20373</u>
			VIN #:	Make:	
			Lic. #:	Model:	
			Work Performed by:		
HRS.	WORK PERFORMED				COST
	marker lights & brake running lights not working ✓ <del>⊗</del>				
	FOUND D.S. INSIDE CENTER AXLE TIRE WAS FLAT - SWAPPED OUT BOTH TIRES WITH GOOD USED ONE				
	TORQUED WHEELS TO 500 FT/LBS AND PUT A RETORQUE TAG IN THE TRUCK				
	<p><b>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</b></p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>				Total Parts
					Total Labour
		Shop Supply			
		Misc.			
		Subtotal			
		GST 855519435RT0001			
		TOTAL			
	<p>_____</p> <p>Authorized by</p>				

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive  
 Nisku, AB T9E 8A2  
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

# GARAGE REPAIR ORDER

4374

QTY	PART NO. AND DESCRIPTION	PRICE	Date:	Unit #:
			Sept. 9, 2024	89
			Year:	Odometer:
			VIN #:	Make:
			Lic. #:	Model:
			Work Performed by:	
			<b>HRS.</b>	<b>WORK PERFORMED</b>
				All on crane keeps going off even though it looks like nothing is wrong ✓
				- SENT UNIT TO CROPAC FOR REPAIR
			<p><b>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</b></p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p> <p>_____</p> <p>Authorized by</p>	
			Total Parts	
			Total Labour	
			Shop Supply	
			Misc.	
			Subtotal	
			GST 855519435RT0001	
			TOTAL	













1000

5100

1000

1000

1000