

A26-11
MAY

WORK PERFORMED & SERVICE REPORT

WORK ORDER # 0796

DATE: Apr 16/26 SERVICE MAN: Scott / Jonathan
 UNIT NO.: 34P02 HRS.: _____ MILEAGE: _____
 SERIAL NO.: NONE ATTACHMENTS: _____
 MAKE: Manufacted MODEL: Storage tank
 DATE OPENED: Apr 16/26 DATE CLOSED: Apr 16/26

WORK REQUESTED

CVIP

Repair Plug in socket
change flags
CVIP completed.

LABOUR	HRS.	RATE	AMOUNT	TOTAL LABOUR
				TOTAL PARTS
				SUBLET WORKSHOP
				SHOP SUPPLIES
TOTAL				

WORK PERFORMED & SERVICE REPORT

repair pipe between screw stand
 rem hole bigger
 make 2 handles
 adjust brakes
 check and repair air clearance
 light and rear, entire
 replace mud flap
 grease brakes and add screw
 stands

WORK ORDER # 0940

DATE: May 3, 07 SERVICEMAN: _____
 UNIT NO.: 34P02 HRS.: _____ MILEAGE: _____
 SERIAL NO.: _____ ATTACHMENTS: _____
 MAKE: Storage Tank Trailer MODEL: Tank
 DATE OPENED: _____ DATE CLOSED: _____

WORK REQUESTED

- = TRAILER INSPECTION
- = repair pipe that is from stand to stand
- = make up handle stands and weld ~~out~~
- = possible install hub KM indicator
- = check tire pressure
- = check brakes
- = check lights
- = grease
- = install hub meter
- = replace tires

LABOUR	HRS.	RATE	AMOUNT	
				TOTAL LABOUR
				TOTAL PARTS
				SUBLET WORKSHOP
				SHOP SUPPLIES
				TOTAL
inspection Cert. CV1131022				