

R26-3
MAY

	CAT Track Type Tractor Maintenance Record	LC-107
---	--	---------------

V: P=Pass F=Fail R=Repaired N/A=Not Applicable

UNIT #:	SS-0334	ODOMETER:	ENGINE HOURS:	6655	DATE:	June 6/25			
						P	F	R	N/A
1	LOCKOUT IN PLACE		21	Radiator, Debris, Damage, Leaks		✓			
2	WHEEL CHOCKS IN PLACE		22	All Hoses Cracks, Wear Spots, Leaks		✓			
3	Ripper, Cylinder Damage, Wear, Leaks		23	Overall Engine Compartment Trash Or Dirt Buildup, Leaks		✓			
4	Track Assembly Tightness		24	Roll Over Protection System Damage		✓			
5	Drive Sprockets Wear, Damage, Loose Bolts		25	Seat Adjustment, Brake Travel		✓			
6	Idlers & Rollers Leaks, Damage, Wear		26	Seat Belt & Mounting Damage, Wear, Adjustment		✓			
7	Blade Cutting Edge, Moldboard Excessive Wear Or Damage		27	Horn, backup alarm, lights Proper Function		✓			
8	Blade Tilt Cylinders Excessive Wear, Damage, Leaks		28	Overall Cab Interior Cleanliness		✓	✓	✓	
9	Pusharm, Trunnion: Damage, Loose Bolts, Clearance		29	Pivot Shaft Oil Level					✓
10	Underneath Of Machine Final Drive Leaks, Damage		30	Windsfield Wipers & Washers Wear, Damage, Fluid Level		✓			
11	Overall Undercarriage Packing/Debris Buildup		31	Hydraulic Oil Tank Fluid Level, Damage, Leaks		✓			
12	Ripper Shank, GET Wear Or Damage		32	Fuel Tank Fuel Level, Damage, Leaks					
13	Steps And Handholds Condition And Cleanliness		33	FIRE EXT. CONDITION, DATE, TAG, LOCK, MOUNT		✓			
14	Overall Machine: Loose Or Missing Nuts & Bolts, Loose Guards, Cleanliness		34	INSPECTION TAG DATE					June 2025
15	Batteries & Hold Downs Cleanliness, Loose Bolts & Nuts		35	FIRE EXTINGUISHER #:					
16	Engine Oil Fluid Level and Condition		36	SPILL KIT PROVIDED		✓			
17	Transmission Oil Fluid Level		37	Heating Operation		✓			
18	Engine Coolant Fluid Level and Strength		38	Air Conditioning Operation		✓			
19	Air Filter Restriction Indicator		39						
20	All Belts Tightness, Wear, Cracks		40						



CAT Track Type Tractor Maintenance Record

LC-107

FLUIDS	CHECKED	CHANGED	QUANTITY ADDED & GRADE	SOS SAMPLE
Engine Oil		✓	5-40 13L	✓
Transmission Oil	N/A			
Hydraulic Oil		✓	ISO 32 36L	✓
Final Drive L.H.		✓	75-90	✓
Final Drive R.H.		✓	75-90	✓
Winch Oil	N/A	✓	_____	
Coolant	✓		50/50	

FILTERS	CHECKED	CHANGED	PART #
Engine Oil		✓	377-6969
Fuel		✓	416-5884
Transmission	N/A	✓	_____
Hydraulic		✓	348-1862
Water Seperator		✓	363-5819
Inner Air		✓	AF25558
Outer Air		✓	AF25557
Cab Filter		✓	PA5770 / PA5774

COMMENTS

-Flushed Final Drives with low
-Topped up washer fluid.

Technician (Print Name)

Wyatt


Technician
(Signature)



CAT Track Type Tractor Maintenance Record

LC-107

UNIT #: <u>S6-0334</u>		ODOMETER:				ENGINE HOURS: <u>6303</u>		DATE: <u>Feb 12/24</u>			
		P	F	R	N/A			P	F	R	N/A
1	LOCKOUT IN PLACE	/				22	Primary/Secondary Fuel Filters: Leaks, Drain Water Separator	/			
2	WHEEL CHOCKS IN PLACE	/				23	Air Filter: Restriction Indicator	/			
3	Overall Cab Interior: Cleanliness	/				24	Heating and Cooling System: Proper Function	/			
4	Overall Machine: Loose/Missing Nuts, Bolts, Loose Guards, Cleanliness	/				25	Hydraulic Oil Tank: Fluid Level, Damage, Leaks	/			
5	Air Conditioning Operation	/				26	Hydraulic Oil Filter: Leaks	/			
6	Swing Drive Pinion Grease: Water	/				27	Radiator: Fin Blockage, Leaks	/			
7	Fuel Tank: Fuel Level, Damage, Leaks	/				28	AC Condenser: Fin Blockage, Leaks	/			
8	All Hoses: Cracks, Wear Spots, Leaks	/				29	Hydraulic Oil Cooler: Fin Blockage, Leaks	/			
9	All Belts: Tightness, Wear, Cracks	/				30	Lights and Mirrors: Damage and Function	/			
10	Overall Engine Compartment: Trash or Dirt Buildup, Leaks	/				31	Engine Oil Filter: Leaks and Condition	/			
11	Bucket, GET: Excessive Wear, Damage, Cracks	/				32	Hydraulic Oil Filter: Leaks	/			
12	Bucket Cylinder & Linkage: Excessive Wear, Damage, Leaks, Lubricate	/				33	FIRE EXT. CONDITION, DATE, TAG, LOCK, MOUNT	/			
13	Stick, Cylinder: Wear, Damage, Leaks, Lubricate	/				34	INSPECTION TAG DATE				
14	Boom, Cylinder: Wear, Damage, leaks, Lubricate	/				35	FIRE EXTINGUISHER #:				
15	Underneath Machine: Final Drive Leaks, Swing Drive Leaks, Damage	/				36	Horn, Travel Alarm, Lights: Proper Function	/			
16	Carbody: Cracks, Damage	/				37	Indicators: Proper Function	/			
17	Undercarriage: Wear, Damage, Tension	/				38	Monitor Panel: Proper Function	/			
18	Steps and Handholds: Condition and Cleanliness	/				39	Switches: Proper Function	/			
19	Batteries & Hold Downs: Cleanliness, Loose Bolts & Nuts	/				40	Travel Controls: Correct Operation	/			
20	Windshield Wipers & Washers: Wear, Damage, Fluid Level	/				41	Mirrors: Adjustment, Damage and Fogging	/			
21	Heating Operation	/				42	Roll Over Protection System: Damage, Loose Mounting Bolts	/			



CAT Track Type Tractor Maintenance Record

LC-107

FLUIDS	CHECKED	CHANGED	QUANTITY ADDED & GRADE	SOS SAMPLE
Engine Oil	/	/	12L / 0W40	/
Transmission Oil	/			
Hydraulic Oil	/			
Final Drive L.H.	/			
Final Drive R.H.	/			
Winch Oil				
Coolant	/			

FILTERS	CHECKED	CHANGED	PART #
Engine Oil		/	377-6969
Fuel		/	416-5884 / 363-5819
Transmission	/		
Hydraulic	/		
Water Seperator			
Inner Air		/	110-6326
Outer Air		/	110-6326
Cab Filter	/		

COMMENTS

[Empty dashed box for comments]

Technician (Print Name) Jeff

Technician (Signature)

Jeff Miller

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

AW

INVOICE

38583

Org. Est. # 055352

INVOICE

Printed Date: 09/08/2022 Work Completed: 09/08/2022

CHEMCO-OFF ROAD

3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20226 -

Lic # :
Unit # : SS-0334
VIN # : A9Z00334

Odometer In : 0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
---------------------------	-----	------	-----	-------------------	-----

				(1) SITE RETURN INSPECTION ** NOT COMPLETED AT THIS TIME **	n/c
--	--	--	--	--	-----

Org. Estimate	0.00	Revisions	0.00	Current Estimate	0.00
---------------	------	-----------	------	------------------	------

Labor:	0.00
Parts:	0.00
SubTotal:	0.00
Tax:	0.00
Total:	0.00
Bal Due:	\$0.00

[Payments -]

Vehicle Received: 9/8/2022

Customer Number : 3904

GST#865376503RT0001

Signature _____ Date _____

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

038583

Org. Est. # 055352

REPAIR ORDER - RO

Scheduled : 06/27/2022 09:03 AM

Print Date : 6/27/2022

CHEMCO-OFF ROAD

3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570
Cust ID : 3904
Last Service : 4/27/2022

2014 Cat - 289D SKIDSTEER UNIT#20226 -
Lic # : - AB
Unit # : SS-0334
VIN # : A9Z00334
MFG Date : 6/17/2015
Current Odom : 0

Previous Odom : 4424

Elapsed : 0

Labor Requested / Part SubTotal

Extended

(1) SITE RETURN INSPECTION

195.00

Parts Subtotal 0.00

Shop Supplies

9.75

Parts: 0.00
Labor: 195.00

Supplies: 9.75

Tax: 10.24

Total: 214.99
Balance: 214.99

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ___ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts ___. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By _____ Date _____ Time _____

Technician Work Sheet Service Writer : **GLAZIER, RUSSELL**

Print Date: **6/27/2022**

2014 Cat - 289D SKIDSTEER UNIT#20226 TRA

Hat # :

Repair Order #

VIN # : A9Z00334

Color : **CAT YELLOW**

038583

Engine :

Location :

Lic # :

Lic. State : **AB**

CHEMCO-OFF ROAD

Schedule : 6/27/22 9:15 A.M.

Office 780-436-9570

Promised Date : 6/27/22 5:00 P.M.

Inspection Date : 6/17/15

Status :

Last Service : 4/27/22

Unit # : SS-0334

Current Odometer : 0

Trans :

Previous Mileage : 4,424

Brakes :

Elapsed Mileage : 0

Manufacture Date : 6/17/15

Labor Description

Charged Hours

(1) SITE RETURN INSPECTION

3.00

Technician : <none>

OUT ODOMETER :

Total Hours Charged :

3.00

Hours out: 0.00

Tech Notes



Track & Rubber Tire Type Skid Steer Loader Inspection Record

PDI-0121

√ P = Pass F = Fail R = Repaired N/A = Not Applicable

Track & Rubber Tire Type																
UNIT #:		ODOMETER:					ENGINE HOURS:		DATE:							
		P	F	R	N/A					P	F	R	N/A			
1	GENERAL OVERALL					25	Condition and cleanliness, damage									
2	SPILL Kit Provided					26	Inflation, leaks, damage, wear, loose lug nuts /valve stems/ caps									
3	Check CHEMCO Decaling and Numbers: repair as Needed.					27	Damage, deep cuts, abrasions, embedded foreign matter, proper adjustment									
4	Fire Extinguisher Charge, Damage, and Mounting					28	Damage, wear, mounting bolts									
5	Fire Extinguisher inspection date:					29	Dirt, debris, tension, excessive damage									
6	Fire extinguisher Number					30	Damage, leaks									
7	Lights					31	Fluid level									
8	Grab irons, steps, handholds					32	Damage, leaks, mounting hardware									
9	Tires, rims					33	Fuel level, damage, leaks; drain water and sediment									
10	Tracks and drive lugs					34	Cracks, welds, debris									
11	Sprocket rings and sleeves					35	Debris between lift arm and work tool, damage									
12	Idlers and bogies					36	Structural damage, cracks, welds									
13	Undercarriage					37	Fluid level, check for debris buildup									
14	Electrical and hydraulic lines					38	Loose or missing nuts & bolts, loose guards, cleanliness, fluid leaks									
15	Hydraulic oil					39	ENGINE									
16	Hydraulic cylinders, tubes, hoses, and fittings					40	Engine oil									
17	Fuel tank					41	Engine coolant									
18	Lift arms					42	Air filter									
19	Work tool					43	Radiator									
20	Body					44	All hoses									
21	Diesel exhaust fluid (DEF) tank (if equipped)					45	All belts									
22	Overall machine					46	Covers and guards									
23	Broken lamps, lenses, operation					47	Overall engine compartment									
24	Cab securely bolted/tightened down					48	Batteries and hold downs									

√ P = Pass F = Fail R = Repaired N/A = Not Applicable

Track & Rubber Tire Type														
		P	F	R	N/A					P	F	R	N/A	
49	Fluid level, condition of oil					69	Seat belt & mounting							
50	Fluid level					70	Fire extinguisher (if equipped)							
51	Restriction indicator (if equipped)					71	Windows and mirrors							
52	Fin blockage, leaks					72	Horn, backup alarm, lights							
53	Cracks, wear spots, leaks					73	All switches, gauges, and controls							
54	Tension, wear, cracks					74	Floor pedals and controls							
55	Cleanliness, loose nuts and bolts, connections					75	Cab air filter							
56	Trash or dirt buildup, leaks					76	ROPS							
57						77	Overall cab interior							
58	ON THE MACHINE, OUTSIDE THE CAB						78	Adjustment-height/weight, able to reach pedals						
59	Lights, lenses					79	Damage, wear, adjustment, age of seat belt, installation date							
60	Mirrors, windows					80	Charge, damage, inspection tag current							
61	Windshield wipers & washers					81	Condition, clean and adjust							
62	ROPS					82	Proper function							
63	Housing or lens damage, cleanliness					83	Correct operation, damage, cleanliness							
64	Damage, cleanliness, movement					84	Functional and clear of debris							
65	Wear, damage to arm, fluid level					85	Dirt, dust							
66	Damage, loose mounting bolts					86	Damage, loose mounting bolts							
67	INSIDE THE CAB						87	Cleanliness, free from debris						
68	Seat					88	GPS							

√ P = Pass F = Fail R = Repaired N/A = Not Applicable

Charging System TEST							
VOLTS:		AMPS:		RPM:			
Tire Pressure (If not recorded on prescribed Alberta Inspection Record) [] psi [] kPa							
LF:		RF:		LR:		RR	

FUEL LEVEL:	TEST / DRIVE																	
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th colspan="4" style="text-align: center;">CLEANING</th> </tr> <tr> <th style="width:25%;"></th> <th style="width:5%;">Date</th> <th style="width:10%;">Time</th> <th style="width:60%;">Signature</th> </tr> <tr> <td>Washed (Fine Cleaned) <input type="checkbox"/></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Disinfectant Mist (Clubroot) <input type="checkbox"/></td> <td></td> <td></td> <td></td> </tr> </table>	CLEANING					Date	Time	Signature	Washed (Fine Cleaned) <input type="checkbox"/>				Disinfectant Mist (Clubroot) <input type="checkbox"/>				TEST []	or TEST DRIVE []
	CLEANING																	
		Date	Time	Signature														
Washed (Fine Cleaned) <input type="checkbox"/>																		
Disinfectant Mist (Clubroot) <input type="checkbox"/>																		
Comments:																		
Technician (Print Name)		Technician Signature																

MAINTENANCE REQUIRED/REMARKS:

INSPECTION REPORT SIGN-OFF		
Technician (Print Name)	Technicians Signature	Supervisors Signature

FINAL PRE-DELIVERY INSPECTION & TEST DRIVE		<input type="checkbox"/> Checklist Reviewed/Verified	<input type="checkbox"/> Test Drive
Technician (Print Name)	Technicians Signature	Date	

Job # 1192-001

1192-001-ER-00368

chemco	Heavy Equipment Receiving Inspection Record	MTE-0015
---------------	--	-----------------

√ P = Pass F = Fail R = Repaired N/A = Not Applicable

UNIT #:	SS 0334	Type/Description:				289D CAT Skid Steer					
		ODOMETER:				ENGINE HOURS:	5886	DATE:	June 22/22		
		P	F	R	N/A		P	F	R	N/A	
1	OVERALL CONDITION OF UNIT	✓				17	FIRE EXTINGUISHER & MOUNT		✓		
2	EXTERIOR CONDITION/CLEANLINESS		✓			18	FIRE EXTINGUISHER ID	NONE			
3	UNIT #'S, DECALS & WARNING DECALS	✓				19	FIRE EXTINGUISHER INSPECTION DATE				
4	WINDSHIELD/GLASS	✓				20	DOOR/TAILGATE/ TAILGATE CABLES/ HANDLE	✓			
5	BODY & DOORS	✓				21	PAINT	✓			
6	TIRES, TRACKS, UNDERCARRIAGE		✓			22	BACKUP ALARM	✓			
7	CHEMICO ID TAGS & NUMBERS	✓				23	FUEL LEVEL				1/2
8	INTERIOR CONDITION / CLEANLINESS		✓			24	SERVICE STICKER	✓			
9	SEAT COVER / BELTS	✓				25	PINS & BUSHINGS	✓			
10	KEYS	✓				26	WEAR PARTS (TEETH, CUTTING EDGES)	✓			
11	INSPECTION BOOK		✓			27	GREASE JOINTS	✓			
12	OPERATOR'S, OWNER'S MANUALS	✓				28	ACCESSORIES				✓
13	LIGHTS, GAUGES/SWITCHES	✓				29	SPILL KIT FOR UNITS HAVING HYDRAULICS		✓		
14	MIRRORS	✓				30					
15	FLUID LEVELS	✓				31					
16	LEAKS	✓				32					

MAINTENANCE REQUIRED/REMARKS:
*Tracks Worn out
 Right side Track makes Noise
 Service @ 5900hr - NO F/E or mount*

INSPECTION REPORT SIGN-OFF		
<i>Collin C</i> Receiver (Print Name)	 Receiver's Signature	 Supervisors Signature

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

INVOICE

37272

Org. Est. # 054032

INVOICE

Ref #: 5563 HOURS

Date: 02/24/2022

CHEMCO-OFF ROAD

3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20226 -

Lic # :
Unit # : SS-0334
VIN # : A9Z00334
Engine Hrs In : 5563.0

Odometer In : 0

Engine Hours Out : 5563.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
CABIN AIR FILTER -ORDER WP10034	1.00	26.15	26.15	(1) SERVICE AS REQUIRED * SERVICE UNIT * PRIMING PUMP IN-OP WILL NOT START * REPLACED PRIMING PUMP, STILL NOT WORKING. FOUND BAD CONTACT ON RELAY	585.00
FUEL TRANSFER PUMP -ORDER 552-5534	1.00	341.24	341.24		
AIR FILTER -ORDER PA5774	1.00	18.11	18.11		
AIR FILTER PRIMARY -ORDER AF25557	1.00	53.21	53.21		
AIR FILTER SECONDARY -ORDER AF25558	1.00	22.54	22.54		
SYNTHETIC 5W40 OIL-STK 5W40SYN	11.00	6.27	68.97		
BRAKE KLEEN-STK B/C	1.00	2.05	2.05		
LUBE FILTER-STK 377-6969	1.00	16.68	16.68		
FUEL FILTER-STK 416-5884	1.00	14.15	14.15		
FUEL FILTER ELEMENT-STK 363-5819	1.00	23.55	23.55		
Shop Supplies			29.25		

Org. Estimate 57.10 Revisions 0.00 Current Estimate 57.10

Labor:	585.00
Parts:	615.90
SubTotal:	1,200.90
Tax:	60.05
Total:	1,260.95
Bal Due:	\$1,260.95

STK 155

[Payments -]
Vehicle Received: 1/20/2022

Customer Number : 3904

GST#865376503RT0001

Signature _____ Date _____

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

037272

Org. Est. # 054032

REPAIR ORDER - RO

Scheduled : 01/20/2022 07:29 AM

Print Date : 2/7/2022

CHEMCO-OFF ROAD

3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570
Cust ID : 3904
Last Service : 11/15/2021

2014 Cat - 289D SKIDSTEER UNIT#20226 -

Lic # : - AB
Unit # : SS-0334
VIN # : A9Z00334

MFG Date : 6/17/2015

Previous Odom : 4424

Current Odom : 0

Elapsed : 0

Labor Requested / Part SubTotal

Extended

(1) SERVICE AS REQUIRED

Parts Subtotal 54.38

Parts: 54.38
Labor: 0.00

Tax: 2.72

Total: 57.10
Balance: 57.10

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ___ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts ___. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By _____ Date _____ Time _____

Technician Work Sheet Service Writer : CARTER, AMIEE

Print Date: 2/07/2022

2014 Cat - 289D SKIDSTEER UNIT#20226 TRA

Hat # :

Repair Order #

VIN # : A9Z00334

Color : CAT YELLOW

037272

Engine :

Location :

Lic # :

Lic. State : AB

CHEMCO-OFF ROAD

Office 780-436-9570

Schedule : 1/20/22 7:30 A.M.

Promised Date : 1/20/22 5:00 P.M.

Inspection Date : 6/17/15

Status :

Last Service : 11/15/21

Unit # : SS-0334

Current Odometer : 0

Trans :

Previous Mileage : 4,424

Brakes :

Elapsed Mileage : 0

Manufacture Date : 6/17/15

Part Number	Part Description	Qty	Part Location
<input type="checkbox"/> 377-6969	LUBE FILTER-STK	1.00	56-2 MEZ
<input type="checkbox"/> 416-5884	FUEL FILTER-STK	1.00	54-3 MEZ
<input type="checkbox"/> 363-5819	FUEL FILTER ELEMENT-STK	1.00	54-2 MEZ

Labor Description	Charged Hours
<input type="checkbox"/> (1) SERVICE AS REQUIRED Technician : <none>	

OUT ODOMETER :

Hours out: 0.00

Tech Notes

Unit #:

S/N:

Odometer: 5

Hours: 5563

Lab#	Repair Description	Date	Location	Tech Name	Hours
-	Service Skid steer	Feb 7	shop	TB	6
		8			3
-	Replace Air Filters, primary + secondary				
-	Replace primary + secondary cabin Filters				
-	LOF, change oil + Filter, SW40				
-	Replace Fuel Filters				
	↳ priming pump in-op? will not start				
-	Replaced priming pump, still didn't work				
	↳ Found bad contact on relay				

Parts

Mechanic ID: 126096A

Mechanic Signature: 

Qty.	Part #	Description	STK/ORD	Qty.	Part #	Description	STK/ORD
✓	377-6969	oil Filter					
✓	416-5884	Fuel Filter					
✓	363-5819	Fuel Filter.					
✓	WP10034	air Filter					
✓	PA5774	air Filter					
✓	46562	air Filter					
✓	AF25558	air Filter.					
1/4		SW40					
✓	552-5534	pump					

INVOICE

Ref #: 5239 HOURS

Date: 11/15/2021

CHEMCO-OFF ROAD
 3135-4 ST
 NISKU, ALBERTA T9E-8L1
 Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20226 -
 Lic # : Odometer In : 0
 Unit # : SS-0334
 VIN # : A9Z00334
 Engine Hrs In : 5239.0 Engine Hours Out : 5239.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
AIR FILTER-STK PA5770	1.00	14.23	14.23	(1) SERVICE AS REQUIRED * SERVICE UNIT * REPLACE OIL, FUEL, AND ALL AIR FILTERS	227.50
AIR FILTER-STK PA5774	1.00	16.76	16.76		
AIR FILTER PRIMARY-STK AF25557	1.00	39.41	39.41		
AIR FILTER SECONDARY-STK AF25558	1.00	21.14	21.14		
LUBE FILTER-STK 377-6969	1.00	16.68	16.68		
FUEL FILTER-STK 416-5884	1.00	14.22	14.22		
FUEL FILTER ELEMENT-STK 363-5819	1.00	23.55	23.55		
SYNTHETIC 5W40 OIL-STK 5W40SYN	13.00	5.50	71.50		
Shop Supplies			11.38		

Org. Estimate 224.95 Revisions 0.00 Current Estimate 224.95

Labor:	227.50
Parts:	228.87
SubTotal:	456.37
Tax:	22.82
Total:	479.19
Bal Due:	\$479.19

STH 228.87

[Payments -]
 Vehicle Received: 10/5/2021

Customer Number : 3904

GST#865376503RT0001

Signature _____ Date _____

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

036456

Org. Est. # 053213

REPAIR ORDER - RO

Scheduled : 10/05/2021 10:46 AM

Print Date : 10/5/2021

CHEMCO-OFF ROAD

3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570
Cust ID : 3904
Last Service : 9/2/2021

2014 Cat - 289D SKIDSTEER UNIT#20226 -

Lic # : - AB
Unit # : SS-0334
VIN # : A9Z00334
MFG Date : 6/17/2015
Current Odom : 0

Previous Odom : 4424

Elapsed : 0

<i>Labor Requested / Part SubTotal</i>	Extended
(1) SERVICE AS REQUIRED	65.00
Shop Supplies	3.25
Parts Subtotal	145.99

Parts: 145.99
Labor: 65.00

Supplies: 3.25

Tax: 10.71

Total: 224.95
Balance: 224.95

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ___ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts ___. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By _____ Date _____ Time _____

Technician Work Sheet Service Writer : CARTER, AMIEE

Print Date: 10/05/2021

2014 Cat - 289D SKIDSTEER UNIT#20226 TRA

Hat # :

Repair Order #

VIN # : A9Z00334

Color : CAT YELLOW

036456

Engine :

Location :

Lic # :

Lic. State : AB

CHEMCO-OFF ROAD

Schedule : 10/05/21 11:00 A.M.

Office 780-436-9570

Promised Date : 10/05/21 5:00 P.M.

Inspection Date : 6/17/15

Status :

Last Service : 9/02/21

Unit # : SS-0334

Current Odometer : 0

Trans :

Previous Mileage : 4,424

Brakes :

Elapsed Mileage : 0

Manufacture Date : 6/17/15

Part Number	Part Description	Qty	Part Location
<input type="checkbox"/> PA5770	AIR FILTER-STK	1.00	21-3 MEZ
<input type="checkbox"/> PA5774	AIR FILTER-STK	1.00	21-3 MEZ
<input type="checkbox"/> AF25557	AIR FILTER PRIMARY-STK	1.00	24-1 MEZZ
<input type="checkbox"/> AF25558	AIR FILTER SECONDARY-STK	1.00	24-1 MEZ
<input type="checkbox"/> 377-6969	LUBE FILTER-STK	1.00	55-2 MEZ
<input type="checkbox"/> 416-5884	FUEL FILTER-STK	1.00	54-3 MEZ
<input type="checkbox"/> 363-5819	FUEL FILTER ELEMENT-STK	1.00	54-2 MEZ

Labor Description	Charged Hours
<input type="checkbox"/> (1) SERVICE AS REQUIRED Technician : <none>	1.00

OUT ODOMETER : Total Hours Charged : 1.00
Hours out: 0.00

Tech Notes

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780-

INVOICE

36037

Org. Est. # 052792

INVOICE

Ref #: 5015 HOURS

Work Completed : 09/02/2021

Date: 09/21/2021

CHEMCO-OFF ROAD
3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20226 -
Lic # : Odometer In : 0
Unit # : SS-0334
VIN # : A9Z00334
Engine Hrs In : 5015.0 Engine Hours Out : 5015.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
SEAL -ORDER 3866028	326.00	0.15	48.90	(1) REPLACE BROKEN DOOR GLASS * REPLACE BROKEN DOOR GLASS AND SEAL	260.00
GLASS DOOR -ORDER 3456230	1.00	540.34	540.34		
WIPER COVER -ORDER 3456282	1.00	13.03	13.03		
LATCH COVER -ORDER 5430607	1.00	14.30	14.30		
Shop Supplies			13.00		

Org. Estimate 4.77 Revisions 0.00 Current Estimate 4.77

Labor:	260.00
Parts:	629.57
SubTotal:	889.57
Tax:	44.48
Total:	934.05
Bal Due:	\$934.05

[Payments -]
Vehicle Received: 8/18/2021

STK 13

Customer Number : 3904

GST#865376503RT0001

Signature _____ Date _____

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

036037

Org. Est. # 052792

REPAIR ORDER - RO

Scheduled : 08/18/2021 02:18 PM

Print Date : 9/3/2021

CHEMCO-OFF ROAD
3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570
Cust ID : 3904
Last Service : 8/24/2021

2014 Cat - 289D SKIDSTEER UNIT#20226 -
Lic # : - AB
Unit # : SS-0334
VIN # : A9Z00334
MFG Date : 6/17/2015
Current Odom : 0

Previous Odom : 4424

Elapsed : 0

Labor Requested / Part SubTotal

Extended

(1) REPLACE BROKEN DOOR GLASS

Parts Subtotal 0.00

Parts: 0.00

Labor: 0.00

Total: 0.00

Balance: 0.00

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ___ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts ___. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By _____ Date _____ Time _____

Technician Work Sheet Service Writer : CARTER, AMIEE

Print Date: 9/03/2021

2014 Cat - 289D SKIDSTEER UNIT#20226 TRA

Hat # :

Repair Order #

VIN # : A9Z00334

Color : CAT YELLOW

036037

Engine :

Location :

Lic # :

Lic. State : AB

CHEMCO-OFF ROAD

Office: 780-436-9570

Schedule : 8/18/21 2:30 P.M.

Promised Date : 8/18/21 5:00 P.M.

Inspection Date : 6/17/15

Status :

Last Service : 8/24/21

Unit # : SS-0334

Current Odometer : 0

Trans :

Previous Mileage : 4,424

Brakes :

Elapsed Mileage : 0

Manufacture Date : 6/17/15

Labor Description

Charged Hours

(1) REPLACE BROKEN DOOR GLASS

Technician : <none>

OUT ODOMETER :

Hours out: 0.00

Tech Notes

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780-

INVOICE

35653

INVOICE

Ref #: 4775 HOURS

Date: 07/08/2021

CHEMCO-OFF ROAD
3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20226 -
Lic # : Odometer In : 0
Unit # : SS-0334
VIN # : A9Z00334
Engine Hrs In : 4775.0 Engine Hours Out : 4775.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
SYNTHETIC 5W40 OIL-STK 5W40SYN	12.00	5.50	66.00	(1) SERVICE REPAIRS AS REQUIRED AT TELUS	325.00
FUEL FILTER ELEMENT-STK 363-5819	1.00	24.45	24.45	*SERVICE UNIT	
LUBE FILTER-STK 377-6969	1.00	16.68	16.68	* LOF CHANGE OIL AND FILTERS, 5W40	
AIR FILTER-STK PA5774	1.00	16.76	16.76	* REPLACE BOTH AIR FILTERS, FUEL FILTERS, & CABIN FILTERS	
AIR FILTER-STK PA5770	1.00	13.70	13.70	* REMOVE WEAR BLADE FROM BUCKET AND FLIP	
FUEL FILTER-STK 416-5884	1.00	14.79	14.79		
AIR FILTER SECONDARY-STK AF25558	1.00	19.11	19.11		
AIR FILTER PRIMARY-STK AF25557	1.00	45.40	45.40		
Shop Supplies			16.25		

Org. Estimate 586.05 Revisions 0.00 Current Estimate 586.05

Labor:	325.00
Parts:	233.14
SubTotal:	558.14
Tax:	27.91
Total:	586.05
Bal Due:	\$586.05

STK 233

[Payments -]

Vehicle Received: 7/8/2021

GST#865376503RT0001

Customer Number : 3904

Signature _____ Date _____

Technician Work Sheet Service Writer : **ANDREW, RYAN**

Print Date: 7/06/2021

2014 Cat - 289D SKIDSTEER UNIT#20226 TRA

Hat # :

Repair Order #

VIN # : A9Z00334

Color : **CAT YELLOW**

035653

Engine :

Location :

Lic # :

Lic. State : **AB**

CHEMCO-OFF ROAD

Office 780-436-9570

Schedule :

Promised Date : 6/29/21 5:00 P.M.

Inspection Date : 6/17/15

Status :

Last Service : 2/08/21

Unit # : SS-0334

Current Odometer : 0

Trans :

Previous Mileage : 4,424

Brakes :

Elapsed Mileage : 0

Manufacture Date : 6/17/15

Part Number	Part Description	Qty	Part Location
<input type="checkbox"/> 363-5819	FUEL FILTER ELEMENT-STK	1.00	54-2 MEZ
<input type="checkbox"/> 377-6969	LUBE FILTER-STK	1.00	56-3 MEZ
<input type="checkbox"/> PA5774	AIR FILTER-STK	1.00	21-3 MEZ
<input type="checkbox"/> PA5770	AIR FILTER-STK	1.00	21-3 MEZ
<input type="checkbox"/> 416-5884	FUEL FILTER-STK	1.00	54-2 MEZ
<input type="checkbox"/> AF25558	AIR FILTER SECONDARY-STK	1.00	24-1 MEZ
<input type="checkbox"/> 5W40SYN	SYNTHETIC 5W40 OIL-STK	12.00	BULK
<input type="checkbox"/> AF25557	AIR FILTER PRIMARY-STK	1.00	24-1 MEZZ

Labor Description	Charged Hours
<input type="checkbox"/> (1) SERVICE REPAIRS AS REQUIRED AT TELUS Technician: <none>	

OUT ODOMETER :

Hours out: 0.00

Tech Notes

WRENCHHEAD MECHANICAL

3135 4 ST
 NISKU, ALBERTA. T9E-8L1
 Phone: 780-436-9570 Fax: 780- *AK*

INVOICE

34517

INVOICE

Ref #: 4424 HOURS

Date: 02/08/2021

CHEMCO-OFF ROAD
 3135-4 ST
 NISKU, ALBERTA T9E-8L1
 Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20226 -
 Lic # : Odometer In : 4424
 Unit # : SS-0334
 VIN # : A9Z00334
 Engine Hrs In : 4424.0 Engine Hours Out : 4424.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
SYNTHETIC 5W40 OIL-STK 5W40SYN	10.00	5.50	55.00	(1) SERVICE UNIT AT TELUS	195.00
REDTAC #2 GREASE-STK MULTI-P-220-2-14	1.00	4.53	4.53	* TRAVEL TO MAIN SHOP	
OIL SAMPLE JAR-STK 3202711103-50	1.00	23.60	23.60	* SERVICE UNIT	
75W90 SYNTHETIC GEAR OIL-STK 75W90SYN	4.00	8.14	32.56	* CHANGE OIL/FILTER	
FUEL FILTER-STK 416-5884	1.00	14.90	14.90	* REPLACE FUEL FILTERS, CAB FILTER, AND AIR FILTERS	
OIL FILTER-ORDER 57730	1.00	10.63	10.63	* CHANGE FINAL DRIVE OILS	
AIR FILTER-ORDER RS3544	1.00	37.83	37.83	* GREASE UNIT	
AIR FILTER-ORDER RS3545	1.00	21.25	21.25	* INSTALL NEW BOLT IN BATTERY HOLD-DOWN	
CAB AIR FILTER-ORDER PA5770	1.00	15.50	15.50	* TRAVEL BACK TO SHOP	
AIR FILTER-ORDER PA5774	1.00	18.66	18.66		
FUEL FILTER ELEMENT-STK 363-5819	1.00	24.45	24.45		
Shop Supplies			9.75		

Org. Estimate 486.84 Revisions 0.00 Current Estimate 486.84

Labor:	195.00
Parts:	268.66
SubTotal:	463.66
Tax:	23.18
Total:	486.84
Bal Due:	\$486.84

[Payments -]
 Vehicle Received: 2/8/2021

STK-165

Customer Number : 3904

GST#865376503RT0001

Signature _____ Date _____

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780-

INVOICE

33457

Org. Est. # 050201

INVOICE

Date: 09/15/2020

CHEMCO-OFF ROAD
3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20226 -

Lic # :
Unit # : SS-0334
VIN # : A9Z00334

Odometer In : 0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
5/8 HEX NUT-STK FAS178015	22.00	0.31	6.82	(1) REPAIRS AS REQUIRED AT TELUS * SEE TECH SHEETS * NO HOURS RECORDED	390.00
GLASS SEAL-ORDER 3866028	326.00	0.17	55.42		
DOOR GLASS-ORDER 3456230	1.00	569.83	569.83		
H3 12V BULB-STK H3/12V	1.00	2.58	2.58		
5/8 X 2.25 PLOW BOLT-STK PB.625X2.25	22.00	1.01	22.22		
Shop Supplies			19.50		

Org. Estimate 1,119.69 Revisions 0.00 Current Estimate 1,119.69

Labor:	390.00
Parts:	676.37
SubTotal:	1,066.37
Tax:	53.32
Total:	1,119.69
Bal Due:	\$1,119.69

[Payments -]
Vehicle Received: 2020-09-15

STK.51

Customer Number : 3904

GST#865376503RT0001

Signature _____ Date _____

Unit #: 55-0339 S/N:

Odometer:

Hours:

Lab#

Repair Description

Date

Location

Tech Name

Hours

- Replace Glass door + Seal unit

Sept 2

CTI North

TJB

4

- Replace RH upper light bulb

Parts

Qty.

Part #

Description

Mechanic ID:

1260944

Mechanic Signature:

1 386-6028

Seal

1 345-6230

Glass door

1 143-12V

bulb

STK/ORD

Qty.

Part #

Description

STK/ORD

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780-



INVOICE

33375

Org. Est. # 050119

INVOICE

Date: 08/22/2020

CHEMCO-OFF ROAD
3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20226 -
Lic # :
Unit # : SS-0334
VIN # : A9Z00334

Odometer In : 0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
ACTUATOR ASSY-ORDER 5137585	1.00	1,141.24	1,141.24	(1) REPAIRS AS REQUIRED AT TELUS JOB #1192 * SEE TECH SHEET * NO HOURS RECORDED	195.00
75W90SYN/1L-STK SYN-75W90-1 Shop Supplies	2.00	9.74	19.48		
			9.75		

Org. Estimate 1,433.74 Revisions 0.00 Current Estimate 1,433.74

Labor:	195.00
Parts:	1,170.47
SubTotal:	1,365.47
Tax:	68.27
Total:	1,433.74
Bal Due:	\$1,433.74

STK-30

[Payments -]
Vehicle Received: 2020-08-22

Customer Number : 3904

GST#865376503RT0001

Signature _____ Date _____

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780-

INVOICE

33273

Org. Est. # 050014

INVOICE

Ref # : 4112 HOURS

Date: 08/18/2020

CHEMCO-OFF ROAD
3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20226 -
Lic # : Odometer In : 4112
Unit # : SS-0334
VIN # : A9Z00334
Engine Hrs In : 4112.0 Engine Hours Out : 4112.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
HOSE ASSEMBLY-ORDER HH1	1.00	32.96	32.96	(1) REPAIRS AS REQUIRED AT TELUS JOB#1192 * SEE TECH SHEET	325.00
DOOR STRUT-ORDER 4247	1.00	22.96	22.96		
DOOR STRUT-ORDER 4248	1.00	22.96	22.96		
AIR FILTER-STK 265-6619	1.00	24.19	24.19		
R134A/LB-STK Size: 30LB R134A	2.20	7.08	15.58		
Shop Supplies			16.25		

Org. Estimate 482.90 Revisions 0.00 Current Estimate 482.90

Labor:	325.00
Parts:	134.90
SubTotal:	459.90
Tax:	23.00
Total:	482.90
Bal Due:	\$482.90

STK.47

[Payments -]
Vehicle Received: 2020-08-18

GST#865376503RT0001

Signature _____ Date _____

Customer Number : 3904

Unit #: 55-0334 S/N:

Steve/Telis Yard

Hours: 4112

Lab# Repair Description

Odometer: Date

Location

Tech Name

Hours

- check for blown A/C hose
- remove blown hose

Aug 7

Telis yard

Steve

2

- Replace A/C hose
- recharge & test A/C system

Aug 13

Telis yard

Steve

3

Parts

Qty

Description

STK/ORD Qty

Part #

Description

STK/ORD

Mechanic ID: 486257

Mechanic Signature:

1 2.2 RS

A/C hose
R134A

0 5

Cabin Air filter

1

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

INVOICE

32492

Org. Est. # 049223

INVOICE

Date: 04/30/2020

CHEMCO-OFF ROAD
3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20226 -
Lic # :
Unit # : SS-0334
VIN # : A9Z00334

Odometer In : 0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
REDTAC #2 GREASE-STK MULTI-P-220-2-14 Shop Supplies	1.00	4.65	4.65	(1) REPAIRS AS REQUIRED ** SEE TECH SHEET ** ** NO ENGINE HOURS RECORDED **	260.00
			13.00		

Org. Estimate 286.65 Revisions 0.00 Current Estimate 286.65

Labor:	260.00
Parts:	17.65
SubTotal:	277.65
Tax:	13.88
Total:	291.53
Bal Due:	\$291.53

STK-18

[Payments -]
Vehicle Received: 2020-04-30

Customer Number : 3904

GST#865376503RT0001

Signature _____ Date _____

