

R26-5
MAY



CAT Track Type Tractor Maintenance Record

LC-107

✓ P = Pass F = Fail R = Repaired N/A = Not Applicable

UNIT #:	SS-0351	ODOMETER:		ENGINE HOURS:	6108 HRS	DATE:	APRIL 25 2025			
							P	F	R	N/A
1	LOCKOUT IN PLACE			21	Radiator. Debris, Damage, Leaks		✓			
2	WHEEL CHOCKS IN PLACE			22	All Hoses Cracks, Wear Spots, Leaks		✓			
3	Ripper Cylinder Damage, Wear, Leaks			23	Overall Engine Compartment Trash Or Dirt Buildup, Leaks		✓			
4	Track Assembly Tightness	✓		24	Roll Over Protection System Damage		✓			
5	Drive Sprockets Wear, Damage, Loose Bolts	✓		25	Seat Adjustment, Brake Travel		✓			
6	Idlers & Rollers Leaks, Damage, Wear	✓		26	Seat Belt & Mounting Damage, Wear, Adjustment		✓			
7	Blade Cutting Edge, Moldboard Excessive Wear Or Damage	✓		27	Horn, backup alarm, lights Proper Function		✓			
8	Blade Tilt Cylinders Excessive Wear, Damage, Leaks			28	Overall Cab Interior Cleanliness		✓			
9	Pusharm, Trunnion Damage, Loose Bolts, Clearance			29	Pivot Shaft Oil Level		✓			
10	Underneath Of Machine Final Drive Leaks, Damage	✓		30	Windshield Wipers & Washers Wear, Damage, Fluid Level		✓			
11	Overall Undercarriage Packing/Debris Buildup	✓		31	Hydraulic Oil Tank Fluid Level, Damage, Leaks		✓			
12	Ripper Shank, GET Wear Or Damage			32	Fuel Tank Fuel Level, Damage, Leaks		✓			
13	Steps And Handholds Condition And Cleanliness	✓		33	FIRE EXT. CONDITION, DATE, TAG, LOCK, MOUNT					
14	Overall Machine: Loose Or Missing Nuts & Bolts, Loose Guards, Cleanliness	✓		34	INSPECTION TAG DATE					
15	Batteries & Hold Downs Cleanliness, Loose Bolts & Nuts	✓		35	FIRE EXTINGUISHER #:					
16	Engine Oil Fluid Level and Condition	✓		36	SPILL KIT PROVIDED					
17	Transmission Oil Fluid Level			37	Heating Operation		✓			
18	Engine Coolant Fluid Level and Strength	✓		38	Air Conditioning Operation		✓			
19	Air Filter Restriction Indicator	✓		39						
20	All Belts Tightness, Wear, Cracks	✓		40						



CAT Track Type Tractor Maintenance Record

LC-107

FLUIDS	CHECKED	CHANGED	QUANTITY ADDED & GRADE	SOS SAMPLE
Engine Oil		✓	0w40 12L	✓
Transmission Oil				
Hydraulic Oil	✓			
Final Drive L.H.				
Final Drive R.H.				
Winch Oil				
Coolant	✓			

FILTERS	CHECKED	CHANGED	PART #
Engine Oil		✓	377-6969
Fuel		✓	363-5819
Transmission			
Hydraulic			
Water Seperater		✓	416-5884
Inner Air		✓	AF25558
Outer Air		✓	AF25557
Cab Filter			

COMMENTS

Technician (Print Name) Jordy Foland

Technician (Signature)

Jordy Foland



Track & Rubber Tire Type Skid Steer Loader Maintenance Record

LC-121

V P = Pass F = Fail R = Repaired N/A = Not Applicable

Track Type

UNIT #: <u>SS-0351</u>		ODOMETER:				ENGINE HOURS: <u>5755</u>				<u>Mar-13/2024</u>				
		P	F	R	N/A					P	F	R	N/A	
1	LOCKOUT IN PLACE	/				23	Parking Brake, Foot Pedals, Hand Controls, and Steering Controls: Check Operation				/			
2	WHEEL CHOCKS IN PLACE	/				24	Track Sprocket Nuts: Check Torque, Tighten as Needed.				/			
3	SPILL KIT PROVIDED	/				Every 100 Hours								
4	Oil Samples	/				25	Spark Arrestor Muffler: Clean The Spark Chamber.				/			
5	Grease Gun & Grease	/				26	Battery: Check Cables, Connections, And Electrolyte Levels.				/			
6	Heating Operation	/												
7	Air Conditioning Operation	/												
Every 8-10 Hours						Every 250 Hours Plus, 8-10 Hrs. 50 Hrs. &, 100 Hrs. Or Every 3 Months								
8	Engine Oil: Check Engine Oil Level and Condition	/				27	Fuel Filter: Replace.				/			
9	Air Filter and Air System: Check Display Panel, Condition, Leaks	/				28	Engine and Hydraulic Drive Belts: Check Wear, Cracks, Tension, and Idlers				/			
10	Engine Cooling System: Clean Cooler and Radiator Grills, Add Coolant as Required.	/				29	A/C, Alternator, Water Pump Belt: Check Condition and Tension Replace as Needed				/			
11	Fuel Filter: Remove trapped Water.	/				30	Change Engine Oil and inspect Engine area for Debris.				/			
12	Lift Arms, Pivot Pins, and Wedges: Lubricate and Inspect	/				Every 500 Hours Plus 8-10 Hrs. 50 Hrs. 100 Hrs. & 250 Hrs. Or Every 6 Months								
13	Seat Bar, Control Interlocks, Seat Belt, Seat Belt Retractors: Inspect Clean and Repair.	/				31	Change Hydraulic Filters, Change Filter Reservoir Breather.				/			
14	Interlock Controls: Lift and Tilt Functions Should have NO Operation with Bar Up	/				32	Change Engine Oil and complete 250 Hour Inspection as listed above.				/			
15	Safety Signs and Safety Treads: Inspect for Damage Repair As Necessary.	/				33	Change Oil in Hydrostatic Motor Carrier.				/			
16	Operator Cab: Check for Loose Bolts, Damage, and Cleanliness.	/				Every 1000 Hours Plus 8-10 Hrs. 50 Hrs. 100 Hrs. 250 Hrs. & 500 Hrs. Or Every 12 Months.								
17	Indicators and Lights: Function, Damage, and Attachments	/				34	Hydraulic Reservoirs - Replace The Fluid				/			
18	Heater and A/C Filters: Clean or Replace as Needed.	/				35	Case Drain Filters: Replace Filters				/			
19	Check Location Cats Decaling and Numbers: repair as Needed.	/				36	Engine Valves: Adjust the Valve Clearance				/			
Every 50 Hours						Coolant: replace Every 2 Years or 1500 Hours whichever First								
20	Roll Over Protection: Check for Damage or Loose Bolts.	/												




Track & Rubber Tire Type Skid Steer Loader
Maintenance Record

LC-121

V P = Pass F = Fail R = Repaired N/A = Not Applicable

Charging System TEST

VOLTS:		AMPS:		RPM:			
Tire Pressure (If not recorded on prescribed Alberta Inspection Record) [] psi [] kPa							
LF:		RF:		LR:		RR	

FUEL LEVEL (Mark Level)	TEST / DRIVE	
	TEST []	or TEST DRIVE []
	Comments:	
	Technician (Print Name)	Technician Signature

MAINTENANCE REQUIRED/REMARKS:

1.377-6969 oil filter
1.416-5884 fuel
1.363-5819 fuel
1.110-6331 Inner
1.1106326 outer

INSPECTION REPORT SIGN-OFF

<p>Jeff Technician (Print Name)</p>	<p><i>Jeff Miller</i> Technicians Signature</p>	<p>Supervisors Signature</p>
---	---	------------------------------

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

AK

INVOICE

42793

Org. Est. # 059568

INVOICE

Printed Date: 10/04/2023 Work Completed: 10/04/2023

CHEMCO-OFF ROAD
3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20215 -
Lic # : Odometer In : 0
Unit # : SS-0351
VIN # : A9Z00351
Engine Hrs In : 5555.0 Engine Hours Out : 5555.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
3/4" NIPPLE-ORDER FFH-08-34-SAE-M	1.00	45.38	45.38	(1) GET SITE READY ** SEE TECH SHEET	227.50
50/50 LONGLIFE ANTIFREEZE-STK PREGD3000 Shop Supplies	1.00	2.98	2.98		
			11.38		

Org. Estimate 71.66 Revisions 0.00 Current Estimate 71.66

Labor:	227.50
Parts:	59.74
SubTotal:	287.24
Tax:	14.36
Total:	301.60
Bal Due:	\$301.60

[Payments -]

STK-15

Vehicle Received: 10/3/2023

Customer Number : 3904

GST#865376503RT0001

Signature _____ Date _____

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

042793

Org. Est. # 059568

REPAIR ORDER - RO

Scheduled : 10/03/2023 12:17 PM

Print Date : 10/3/2023

CHEMCO-OFF ROAD

3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570
Cust ID : 3904
Last Service : 5/24/2023

2014 Cat - 289D SKIDSTEER UNIT#20215 -
Lic # : - AB
Unit # : SS-0351
VIN # : A9Z00351
MFG Date : 6/17/2015
Current Odom : 0

Previous Odom : 3420

Elapsed : 0

Labor Requested / Part SubTotal

Extended

(1) GET SITE READY

65.00

Shop Supplies

Parts Subtotal 0.00

3.25

Parts: 0.00
Labor: 65.00

Supplies: 3.25

Tax: 3.41

Total: 71.66
Balance: 71.66

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ___ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts ____. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By _____ Date _____ Time _____

Technician Work Sheet Service Writer : GLAZIER, RUSSELL

Print Date: 10/03/2023

2014 Cat - 289D SKIDSTEER UNIT#20215 TRA

Hat # :

Repair Order #

VIN # : A9Z00351

Color : CAT YELLOW

042793

Engine :

Location :

Lic # :

Lic. State : AB

CHEMCO-OFF ROAD

Schedule : 10/03/23 12:30 P.M.

Office 780-436-9570

Promised Date : 10/03/23 5:00 P.M.

Inspection Date : 6/17/15

Status :

Last Service : 5/24/23

Unit # : SS-0351

Current Odometer : 0

Trans :

Previous Mileage : 3,420

Brakes :

Elapsed Mileage : 0

Manufacture Date : 6/17/15

Labor Description

Charged Hours

<input checked="" type="checkbox"/> (1) GET SITE READY	1.00
--	------

Technician : <none>

OUT ODOMETER :

Total Hours Charged :

1.00

Hours out: 0.00

Tech Notes

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

INVOICE

41420

Org. Est. # 058192

INVOICE

Printed Date: 05/24/2023 Work Completed: 05/24/2023

CHEMCO-OFF ROAD
3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20215 -
Lic # : Odometer In : 0
Unit # : SS-0351
VIN # : A9Z00351
Engine Hrs In : 5513.0 Engine Hours Out : 5513.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
LUBE FILTER-STK 377-6969	1.00	18.71	18.71	(1) REPAIRS AS REQUIRED ** SEE TECH SHEET	812.50
AIR FILTER -STK AF25557	1.00	46.37	46.37		
AIR FILTER SECONDARY-STK AF25558	1.00	24.41	24.41		
FUEL FILTER ELEMENT-STK 363-5819	1.00	25.75	25.75		
AIR FILTER-STK PA5770	1.00	20.32	20.32		
AIR FILTER-STK PA5774	1.00	23.49	23.49		
FUEL FILTER-STK 416-5884	1.00	15.61	15.61		
O RING SEAL-ORDER 482-8803	1.00	2.58	2.58		
VALVE-ORDER 480-8589	1.00	549.01	549.01		
Shop Supplies			40.63		

Org. Estimate 310.33 Revisions 0.00 Current Estimate 310.33

Labor:	812.50
Parts:	766.88
SubTotal:	1,579.38
Tax:	78.97
Total:	1,658.35
Bal Due:	\$1,658.35

[Payments -]

stk-216

Vehicle Received: 5/11/2023

Customer Number : 3904

GST#865376503RT0001

Signature _____ Date _____

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

041420

Org. Est. # 058192

REPAIR ORDER - RO

Scheduled : 05/11/2023 08:33 AM

Print Date : 5/11/2023

CHEMCO-OFF ROAD

3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570
Cust ID : 3904
Last Service : 4/20/2023

2014 Cat - 289D SKIDSTEER UNIT#20215 -

Lic # : - AB
Unit # : SS-0351
VIN # : A9Z00351
MFG Date : 6/17/2015
Current Odom : 0

Previous Odom : 3420

Elapsed : 0

Labor Requested / Part SubTotal

Extended

(1) 500 HOUR SERVICE

130.00

Shop Supplies

Parts Subtotal 0.00

6.50

Parts: 0.00
Labor: 130.00

Supplies: 6.50

Tax: 6.83

Total: 143.33
Balance: 143.33

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ___ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts ____. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By _____ Date _____ Time _____

Technician Work Sheet Service Writer : GLAZIER, RUSSELL

Print Date: 5/11/2023

2014 Cat - 289D SKIDSTEER UNIT#20215 TRA

Hat # :

Repair Order #

VIN # : A9Z00351

Color : CAT YELLOW

041420

Engine :

Location :

Lic # :

Lic. State : AB

CHEMCO-OFF ROAD

Schedule : 5/11/23 8:45 A.M.

Office 780-436-9570

Promised Date : 5/11/23 5:00 P.M.

Inspection Date : 6/17/15

Status :

Last Service : 4/20/23

Unit # : SS-0351

Current Odometer : 0

Trans :

Previous Mileage : 3,420

Brakes :

Elapsed Mileage : 0

Manufacture Date : 6/17/15

Labor Description	Charged Hours
<input checked="" type="checkbox"/> (1) 500 HOUR SERVICE	2.00
Technician : <none>	

OUT ODOMETER :

Total Hours Charged : 2.00

Hours out: 0.00

Tech Notes



ORDER CONFIRMATION

THANK YOU FOR YOUR ORDER!

Order Number: 0014275165
 Order Date: May 15, 2023, 4:07 PM

ORDER INFORMATION

Account Number
 0024205-CHEMCO ELECTRICAL CONTRACTORS LTD
Dealer Store
 Edmonton RDC
Equipment
 Model # - 289D
 Serial # - A9Z00351
Order Type
 Emergency
Ordered By
 RUSS GLAZIER
Email Address
 rglazier@chemco.com
Phone number
 780-306-1159
Request by date
 May 17, 2023

PICKUP & DELIVERY

Shipping Method
 Finning Parts Express
Shipping Address
 RUSS GLAZIER
 3135-4 st
 Nisku, Alberta T9E 8L1
 Canada
 780-306-1159
 rglazier@chemco.com
 chemco Shipping
Shipping Instructions
 PrePaid

BILLING & PAYMENT

Billing Method
 Dealer Credit
Billing Address
 CHEMCO ELECTRICAL CONTRACTORS LTD
 3135 4 STREET
 NISKU, Alberta T9E 8L1
 Canada
 780-306-1159
 rglazier@chemco.com
Purchase Order Number
 41420-SS0351

ITEMS IN YOUR ORDER

2 items

Quantity	Product Description	Notes	Availability ⓘ	Total Price (CAD)
1) 1	480-8589: Valve Assembly-Water (Electronic) 0.25 kg		By May 16	\$549.01 \$557.37 ea. \$549.01 ea.
2) 1	482-8803: O-Ring 0.0 kg		In Stock	\$2.58 \$2.62 ea. \$2.58 ea.

ORDER SUBTOTAL: \$551.59 CAD
Shipping/Miscellaneous: ... \$0.00 CAD
Total Tax: \$27.58 CAD
GST/HST & PST: \$27.58 CAD
ORDER TOTAL: **\$579.17 CAD**

† Availability information is based on a single line item. If the same part number exists in multiple lines, availability may be inaccurate.



REQUEST FOR SERVICE FORM

Requested by: Dave Repko

Date Required: _____

(Please note that 7 days is the norm.
5 day or less is considered a RUSH.)

Deliver To: Receiving

Item	Unit	Make	Model
1	SS0351	CAT	SKIDSTEER
Description:			
Item	Unit	Make	Model
2			
Description:			
Item	Unit	Make	Model
3			
Description:			
Item	Unit	Make	Model
4			
Description:			

Special Instructions: Code for 500hr service , no A.C

Attachments: [YES] [NO]

REQUEST NOTES:

- * Please email request sheet to orderdesk@chemco.com
- * A confirmation will be sent to you once the req has been placed.

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -



INVOICE

40483

Org. Est. # 057254

INVOICE

Printed Date: 02/06/2023 Work Completed: 02/06/2023

CHEMCO-OFF ROAD
3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20215 -
Lic # : Odometer In : 0
Unit # : SS-0351
VIN # : A9Z00351
Engine Hrs In : 5398.0 Engine Hours Out : 5398.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
0W40 SYN OIL PER/L -STK 0W40SYN	12.00	9.27	111.24	(1) LOF SERVICE ** SEE TECH SHEET	390.00
75W90 SYNTHETIC GEAR OIL-STK 75W90SYN	2.00	11.33	22.66		
FUEL FILTER ELEMENT-STK 363-5819	1.00	25.22	25.22		
AIR FILTER -STK AF25557	1.00	46.37	46.37		
AIR FILTER SECONDARY-STK AF25558	1.00	24.41	24.41		
LUBE FILTER-STK 377-6969	1.00	18.71	18.71		
FUEL FILTER-STK 416-5884	1.00	15.61	15.61		
AIR FILTER-STK PA5770	1.00	20.32	20.32		
AIR FILTER-STK PA5774	1.00	23.48	23.48		
Shop Supplies			19.50		

Org. Estimate 279.96 Revisions 0.00 Current Estimate 279.96

Labor:	390.00
Parts:	327.52
SubTotal:	717.52
Tax:	35.88
Total:	753.40
Bal Due:	\$753.40

[Payments -]

stk-328

Vehicle Received: 1/31/2023

Customer Number : 3904

GST#865376503RT0001

Signature _____ Date _____

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

040483

Org. Est. # 057254

REPAIR ORDER - RO

Scheduled : 01/31/2023 01:04 PM

Print Date : 1/31/2023

CHEMCO-OFF ROAD

3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570
Cust ID : 3904
Last Service : 7/28/2022

2014 Cat - 289D SKIDSTEER UNIT#20215 -
Lic # : - AB
Unit # : SS-0351
VIN # : A9Z00351
MFG Date : 6/17/2015
Current Odom : 0

Previous Odom : 3420

Elapsed : 0

Labor Requested / Part SubTotal		Extended
<i>(1) LOF SERVICE</i>		162.50
	Shop Supplies	8.13
		Parts Subtotal 0.00

Parts: 0.00	Supplies: 8.13	Tax: 8.53	Total: 179.16
Labor: 162.50			Balance: 179.16

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ___ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts ___. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By _____ Date _____ Time _____

Technician Work Sheet Service Writer : GLAZIER, RUSSELL

Print Date: 1/31/2023

2014 Cat - 289D SKIDSTEER UNIT#20215 TRA

Hat # :

Repair Order #

VIN # : A9Z00351

Color : CAT YELLOW

040483

Engine :

Location :

Lic # :

Lic. State : AB

CHEMCO-OFF ROAD

Office 780-436-9570

Schedule : 1/31/23 1:15 P.M.

Promised Date : 1/31/23 5:00 P.M.

Inspection Date : 6/17/15

Status :

Last Service : 7/28/22

Unit # : SS-0351

Current Odometer : 0

Trans :

Previous Mileage : 3,420

Brakes :

Elapsed Mileage : 0

Manufacture Date : 6/17/15

Labor Description

Charged Hours

<input checked="" type="checkbox"/> (1) LOF SERVICE	2.50
Technician : <none>	

OUT ODOMETER :

Total Hours Charged : 2.50

Hours out: 0.00

Tech Notes



REQUEST FOR SERVICE FORM

Requested by: Dave Repko

Date Required: _____

(Please note that 7 days is the norm.
5 day or less is considered a RUSH.)

Deliver To: Receiving

Item	Unit	Make	Model
1	SS0351		SKIDSTEER
Description:			
Item	Unit	Make	Model
2			
Description:			
Item	Unit	Make	Model
3			
Description:			
Item	Unit	Make	Model
4			
Description:			

Special Instructions: Due for servicing

Attachments:

[YES] [NO]

REQUEST NOTES:

- * Please email request sheet to orderdesk@chemco.com
- * A confirmation will be sent to you once the req has been placed.

WRENCHHEAD MECHANICAL

3135 4 ST
 NISKU, ALBERTA. T9E-8L1
 Phone: 780-436-9570 Fax: 780- -

INVOICE

37251
 Org. Est. # 054011

INVOICE

Printed Date: 07/28/2022 Work Completed: 07/28/2022

CHEMCO-OFF ROAD
 3135-4 ST
 NISKU, ALBERTA T9E-8L1
 Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20215 -
 Lic # : Odometer In : 0
 Unit # : SS-0351
 VIN # : A9Z00351
 Engine Hrs In : 5020.0 Engine Hours Out : 5020.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
COMPRESSOR -ORDER 758102	1.00	550.00	550.00	(1) REPAIRS AS REQUIRED SITE RETURN	2,112.50
SEAL -RETURNED Size: 0 9X-7378	0.00	0.00	n/c	** REPAIR A/C **	
SEAL/O-RING -ORDER 9X-7380	2.00	4.03	8.06	** REPAIR HORN **	
ORING -RETURNED 9X-7382	0.00	0.00	n/c	** SECURE MIRROR **	
ACCUMULATOR -ORDER 416-5513	1.00	130.44	130.44	** TOP UP HYDRAULIC OIL **	
VHF ANTENNA KIT-STK VHF M	1.00	49.95	49.95	** WASH UNIT **	
CHEMCO MASTER VHF RADIO-STK NX3720M	1.00	275.97	275.97	** REPAIR TAIL LIGHTS **	
HOSE ASSY -ORDER 388-8012	1.00	276.38	276.38		
COIL ASSY -ORDER 552-8375	1.00	875.07	875.07		
#6 CAGE CLIP -ORDER 1F40104-6C	2.00	0.94	1.88		
#6 E-Z CLIP CAGE -ORDER 1F40105-6C	1.00	1.71	1.71		
#8 PILOT FITTING ORING -ORDER 22546-13	1.00	0.23	0.23		
#8 PILOT 90-#6HSE -ORDER FJ5985-8-6	1.00	60.69	60.69		
TUBE -ORDER 232-1384	1.00	25.58	25.58		
VALVE -ORDER 480-8589	1.00	483.35	483.35		
HYD OIL-STK AW-32	3.00	3.91	11.73		
Shop Supplies			100.00		

WRENCHHEAD MECHANICAL
 3135 4 ST
 NISKU, ALBERTA. T9E-8L1
 Phone: 780-436-9570 Fax: 780- -

INVOICE

37251

Org. Est. # 054011

INVOICE

Printed Date: 07/28/2022 **Work Completed: 07/28/2022**

CHEMCO-OFF ROAD
 3135-4 ST
 NISKU, ALBERTA T9E-8L1
 Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20215 -
 Lic # : Odometer In : 0
 Unit # : SS-0351
 VIN # : A9Z00351
 Engine Hrs In : 5020.0 Engine Hours Out : 5020.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
---------------------------	-----	------	-----	-------------------	-----

Org. Estimate 1,216.77 Revisions 0.00 Current Estimate 1,216.77

Labor:	2,112.50
Parts:	2,851.04
SubTotal:	4,963.54
Tax:	248.18
Total:	5,211.72
Bal Due:	\$5,211.72

STK-438

[Payments -]

Vehicle Received: 6/28/2022

Customer Number : 3904

GST#865376503RT0001

Signature _____ Date _____

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

037251

Org. Est. # 054011

REPAIR ORDER - RO

Scheduled : 01/14/2022 01:37 PM

Print Date : 5/11/2022

CHEMCO-OFF ROAD

3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570
Cust ID : 3904
Last Service : 1/11/2021

2014 Cat - 289D SKIDSTEER UNIT#20215 -

Lic # : - AB
Unit # : SS-0351
VIN # : A9Z00351
MFG Date : 6/17/2015
Current Odom : 0

Previous Odom : 3420

Elapsed : 0

<i>Labor Requested / Part SubTotal</i>	Extended
(1) REPAIRS AS REQUIRED SITE RETURN	130.00
Shop Supplies	6.50
Parts Subtotal	0.00

Parts: 0.00 Supplies: 6.50 Tax: 6.83 Total: 143.33
Labor: 130.00 Balance: 143.33

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ___ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts ____. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By _____ Date _____ Time _____

Technician Work Sheet Service Writer : **GLAZIER, RUSSELL**

Print Date: 5/11/2022

2014 Cat - 289D SKIDSTEER UNIT#20215 TRA

Hat # :

Repair Order #

VIN # : A9Z00351

Color : CAT YELLOW

037251

Engine :

Location :

Lic # :

Lic. State : AB

CHEMCO-OFF ROAD

Office 780-436-9570

Schedule : 1/14/22 1:45 P.M.

Promised Date : 1/14/22 5:00 P.M.

Inspection Date : 6/17/15

Status :

Last Service : 1/11/21

Unit # : SS-0351

Current Odometer : 0

Trans :

Previous Mileage : 3,420

Brakes :

Elapsed Mileage : 0

Manufacture Date : 6/17/15

Labor Description	Charged Hours
<input checked="" type="checkbox"/> (1) REPAIRS AS REQUIRED SITE RETURN Technician: <none>	2.00

OUT ODOMETER :

Total Hours Charged : 2.00

Hours out: 0.00

Tech Notes

UNIT #:	SS-0351	UNIT TYPE/DESCRIPTION:			
	ODOMETER:		ENGINE HOURS:	5020	DATE: MAY 13/22

ITEM	REPAIR DESCRIPTION	QUOTED HOURS	ACTUAL HOURS
	REPLACE FE & SPILL KIT		
	GPS MOUNTED TO ROOF? REMOVE?		
Done	REPAIR CAB BRIGADE MOUNT		
DM	TOP UP FUEL		
Done	SERVICE DUE @ 5377 UPDATE DEZAL		
Done	TIGHTEN LOOSE MIRROR		
Done	HORN NOT WORKING DIAGNOSE		
Done	UHF INSTALLED?		
Done	TOP UP HYD OIL		
Done	TAIL LIGHTS NOT WORKING		
Done	POSITIVE AIR LINKAGE RATTLING/LOOSE		
Done	A/C BLOWS HOT DIAGNOSE		
Done	GREASE UNIT		
Done	BOLT CAB BACK DOWN		

DM

Technician (Print Name)

Technicians Signature

FINNING (CANADA): ORDER CONFIRMATION

Order Number: 0013829034

Order Date: June 15, 2022, 03:38 PM

ORDER INFORMATION

Account Number: 0024205-
 CHEMCO ELECTRICAL
 CONTRACTORS LTD
 Dealer Store: West Edmonton
 Parts AB
 Request By Date: June 17, 2022
EQUIPMENT:
 Serial # - a9z
 Ordered By: RUSS GLAZIER
 Email Address:
 rglazier@chemco.com
 Phone Number: 780-306-1159





PICKUP & DELIVERY INFORMATION

Pickup Method: PickUp
 Store Location:
 Your items can be picked up at the following location:
 West Edmonton Parts AB
 10910 170 St NW
 Edmonton, ALBERTA T5S 1H6
 Canada
 1-888-FINNING (346-6464)
 Pickup Instructions:
 Collect
 Special Instructions:
 WILL CALL

BILLING / PAYMENT INFORMATION

Billing Address:
 CHEMCO ELECTRICAL CONTR
 ACTORS LTD
 3135 4 STREET
 NISKU, Alberta T9E 8L1
 Canada
 Billing Method: Dealer Credit
 Purchase Order Number: 37251-SS0351

ITEMS IN YOUR ORDER

Quantity	Item	Weight	Availability	Unit Price (CAD)	Total Price (CAD)
1)	1 9X-7378: SEAL-O-RING 	0.0 kg	1 CAT-SPOKANE	\$3.87 (Was \$4.03)	\$3.87
2)	2 9X-7380: SEAL-O-RING 	0.0 kg	2 In Stock	\$4.03 (Was \$4.20)	\$8.06
3)	1 9X-7382: SEAL-O-RING 	0.0 kg	1 In Stock	\$4.04 (Was \$4.21)	\$4.04
4)	1 416-5513: Accumulator-GD 	1.57 kg	1 In Stock	\$130.44 (Was \$135.88)	\$130.44

ORDER SUBTOTAL: \$146.41 CAD
Shipping/Miscellaneous: \$0.00 CAD
Total Tax: \$7.32 CAD
 GST/HST & PST: \$7.32 CAD
ORDER TOTAL: \$153.73 CAD

V P = Pass F = Fail R = Repaired N/A = Not Applicable

Track & Rubber Tire Type

UNIT #:		ODOMETER:				ENGINE HOURS:		DATE:			
SS-0351						5020		MAY 13/22			
		P	F	R	N/A			P	F	R	N/A
1	GENERAL OVERALL					25	Condition and cleanliness, damage				
2	SPILL Kit Provided	/				26	Inflation, leaks, damage, wear, loose lug nuts /valve stems/ caps				
3	Check CHEMCO Decaling and Numbers: repair as Needed.	/				27	Damage, deep cuts, abrasions, embedded foreign matter, proper adjustment				
4	Fire Extinguisher Charge, Damage, and Mounting					28	Damage, wear, mounting bolts				
5	Fire Extinguisher inspection date:					29	Dirt, debris, tension, excessive damage				
6	Fire extinguisher Number					30	Damage, leaks				
7	Lights	/				31	Fluid level				
8	Grab irons, steps, handholds	/				32	Damage, leaks, mounting hardware				
9	Tires, rims				/	33	Fuel level, damage, leaks; drain water and sediment				
10	Tracks and drive lugs	/				34	Cracks, welds, debris				
11	Sprocket rings and sleeves	/				35	Debris between lift arm and work tool, damage				
12	Idlers and bogies	/				36	Structural damage, cracks, welds				
13	Undercarriage	/				37	Fluid level, check for debris buildup				
14	Electrical and hydraulic lines	/				38	Loose or missing nuts & bolts, loose guards, cleanliness, fluid leaks				
15	Hydraulic oil	/				39	ENGINE				
16	Hydraulic cylinders, tubes, hoses, and fittings	/				40	Engine oil				
17	Fuel tank	/				41	Engine coolant				
18	Lift arms	/				42	Air filter				
19	Work tool	/				43	Radiator				
20	Body	/				44	All hoses				
21	Diesel exhaust fluid (DEF) tank (if equipped)				/	45	All belts				
22	Overall machine	/				46	Covers and guards				
23	Broken lamps, lenses, operation	7				47	Overall engine compartment				
24	Cab securely bolted/tightened down	/				48	Batteries and hold downs				

✓ P = Pass F = Fail R = Repaired N/A = Not Applicable

Track & Rubber Tire Type

		P	F	R	N/A			P	F	R	N/A
49	Fluid level, condition of oil	40				69	Seat belt & mounting	✓			
50	Fluid level	40				70	Fire extinguisher (if equipped)	✓			
51	Filter Restriction indicator (if equipped)	?			✓	71	Windows and mirrors	60			
52	Fin blockage, leaks	43				72	Horn, backup alarm, lights	✓			
53	Cracks, wear spots, leaks	✓				73	All switches, gauges, and controls	✓			
54	Tension, wear, cracks	45				74	Floor pedals and controls	✓			
55	Cleanliness, loose nuts and bolts, connections	✓				75	Cab air filter	✓			
56	Trash or dirt buildup, leaks	✓				76	ROPS	✓			
57						77	Overall cab interior	✓			
58	ON THE MACHINE, OUTSIDE THE CAB					78	Adjustment-height/weight, able to reach pedals	?			
59	Lights, lenses	7				79	Damage, wear, adjustment, age of seat belt, installation date	✓			
60	Mirrors, windows	✓				80	Charge, damage, inspection tag current	?			
61	Windshield wipers & washers	✓				81	Condition, clean and adjust	?			
62	ROPS	✓				82	Proper function	✓			
63	Housing or lens damage, cleanliness	7				83	Correct operation, damage, cleanliness	?			
64	Damage, cleanliness, movement	?				84	Functional and clear of debris	✓			
65	Wear, damage to arm, fluid level	?				85	Dirt, dust	X	✓		
66	Damage, loose mounting bolts	?				86	Damage, loose mounting bolts	✓			
67	INSIDE THE CAB					87	Cleanliness, free from debris	✓			
68	Seat	✓				88	GPS	✓			

chemco	Track & Rubber Tire Type Skid Steer Loader Inspection Record	PDI-0121
---------------	---	-----------------

√ P = Pass F = Fail R = Repaired N/A = Not Applicable

Charging System TEST							
VOLTS:		AMPS:		RPM:			
Tire Pressure (If not recorded on prescribed Alberta Inspection Record) [] psi [] kPa							
LF:		RF:		LR:		RR	

FUEL LEVEL:	TEST / DRIVE																				
	TEST []	or TEST DRIVE []																			
	Comments:																				
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th colspan="4" style="text-align: center;">CLEANING</th> </tr> <tr> <th style="width:25%;"></th> <th style="width:5%;"></th> <th style="width:20%;">Date</th> <th style="width:20%;">Time</th> <th style="width:30%;">Signature</th> </tr> <tr> <td>Washed (Fine Cleaned)</td> <td style="text-align: center;"><input type="checkbox"/></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Disinfectant Mist (Clubroot)</td> <td style="text-align: center;"><input type="checkbox"/></td> <td></td> <td></td> <td></td> </tr> </table>	CLEANING						Date	Time	Signature	Washed (Fine Cleaned)	<input type="checkbox"/>				Disinfectant Mist (Clubroot)	<input type="checkbox"/>					
CLEANING																					
		Date	Time	Signature																	
Washed (Fine Cleaned)	<input type="checkbox"/>																				
Disinfectant Mist (Clubroot)	<input type="checkbox"/>																				
	Technician (Print Name)	Technician Signature																			

MAINTENANCE REQUIRED/REMARKS:

INSPECTION REPORT SIGN-OFF		
Technician (Print Name)	Technicians Signature	Supervisors Signature

FINAL PRE-DELIVERY INSPECTION & TEST DRIVE	<input type="checkbox"/> Checklist Reviewed/Verified	<input type="checkbox"/> Test Drive
Technician (Print Name)	Technicians Signature	Date

√ P = Pass F = Fail R = Repaired N/A = Not Applicable


UNIT #:		Type/Description:				Skid steer					
JOB #:		ODOMETER:		ENGINE HOURS:		DATE:					
600		0		5020		5/10/2022					
		P	F	R	N/A			P	F	R	N/A
1	OVERALL CONDITION OF UNIT	×				17	INTERIOR CONDITION / CLEANLINESS	×			
2	COMMAND START	×				18	DOOR / TAILGATE HANDLE / TAILGATE CABLES				×
3	KEYS	×				19	TIRES				×
4	WINDSHIELD / GLASS	×				20	BACK UP ALARM	×			
5	SPARE TIRE				×	21	BUGGY WHIP				×
6	SEAT COVER / BELTS	×				22	EXTERIOR CONDITION / CLEANLINESS	×			
7	LICENCE PLATE / STICKER				×	23	ACCESSORIES				×
8	INSURANCE / REGISTRATION				×	24	UNIT # / DECALS / WARNING DECALS	×			
9	CVIP PAPERWORK				×	25	CHEMCO ID TAGS / NUMBERS	×			
10	FOSS CARD				×	26	MIRRORS				×
11	LIGHTS / GAUGES / SWITCHES	×				27	PAINT	×			
12	FLOOR MATS	×				28	FIRE EXTINGUISHER / MOUNT ID: 49658 INSPECTION: 5/10/2022	×			
13	HUB CAPS				×	29	DEER WHISTLES				×
14	MUD FLAPS				×	30	SPILL KIT FOR UNITS HAVING HYDRAULICS		×		
15	BODY / DOORS	×				31					
16	LEAKS	×				32					

MAINTENANCE REQUIRED/REMARKS:

Screen shows 500hour service due as well as 1000 hour hydraulic filter due.
 Unable to read fire extinguisher inspection date.
 No spill kit noticed on machine.

INSPECTION REPORT SIGN-OFF


Melissa Hamilton Receiver (Print Name)	 Receiver's Signature	Supervisors Signature
---	---	-----------------------











Job # 1306-001 ✓ P=Pass F=Fail R=Repaired N/A=Not Applicable

UNIT #: SS 0351 Type/Description: CAT Skid Steer
 ODOMETER: _____ ENGINE HOURS: 5020 DATE: May 25 2022

		P	F	R	N/A		P	F	R	N/A
1	OVERALL CONDITION OF UNIT	✓				17	INTERIOR CONDITION/CLEANLINESS	✓		
2	COMMAND START				✓	18	DOOR / TAILGATE HANDLE, TAILGATE CABLES	✓		
3	KEYS	✓				19	TIRES			✓
4	WINDSHIELD/GLASS	✓				20	BACK UP ALARM			
5	SPARE TIRE				✓	21	BUGGY WHIP			✓
6	SEAT COVER, BELTS	✓				22	EXTERIOR CONDITION/CLEANLINESS	✓		
7	LICENCE PLATE / STICKER				✓	23	OPERATOR, OWNERS MANUALS		✓	
8	INSURANCE / REGISTRATION				✓	24	UNIT #'S, DECALS, & WARNING DECALS	✓		
9	CVIP PAPERWORK				✓	25	CHEMCO ID TAGS & NUMBERS	✓		
10	FOSS CARD				✓	26	MIRRORS	✓		
11	INSPECTION BOOK		✓			27	PAINT	✓		
12	FLOOR MATS	✓				28	FIRE EXTINGUISHER & MOUNT		✓	
13	HUB CAPS				✓	29	DEER WHISTLES			✓
14	MUD FLAPS				✓	30	LIGHTS/GAUGES/SWITCHES	✓		
15	BODY & DOORS	✓				31	ACCESSORIES			
16	LEAKS	✓				32	SPILL KIT FOR UNITS HAVING HYDRAULICS		✓	

MAINTENANCE REQUIRED/REMARKS:
Fire Extinguisher Expired
Service Due @ 5111 hr

INSPECTION REPORT SIGN-OFF
Collin C _____

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

RM

INVOICE

33766

Org. Est. # 050510

INVOICE

Date: 10/07/2020

CHEMCO-OFF ROAD
3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570

2014 Cat - 289D SKIDSTEER UNIT#20215 -
Lic # :
Unit # : SS-0351
VIN # : A9Z00351
Engine Hrs In : 4592.0
Odometer In : 0
Engine Hours Out : 4592.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
GLASS DOOR-ORDER 3456230	1.00	555.81	555.81	(1) REPLACE BROKEN DOOR GLASS ** SEE TECH SHEET **	97.50
GASKET-ORDER 2584075	4.00	6.61	26.44		
LATCH-ORDER 2583289	1.00	47.33	47.33		
Shop Supplies			4.88		

Org. Estimate 768.56 Revisions 0.00 Current Estimate 768.56

Labor:	97.50
Parts:	634.46
SubTotal:	731.96
Tax:	36.60
Total:	768.56
Bal Due:	\$768.56

STK-5

[Payments -]
Vehicle Received: 2020-10-07

GST#665376503RT0001

Signature _____ Date _____

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

033766

Org. Est. # 050510

REPAIR ORDER - RO

Scheduled : 10/06/2020 02:39 PM

Print Date : 10/7/2020

CHEMCO-OFF ROAD
3135-4 ST
NISKU, ALBERTA T9E-8L1
Office 780-436-9570
Cust ID : 3904
Last Service : 2020-09-29

2014 Cat - 289D SKIDSTEER UNIT#20215 -
Lic # : - AB
Unit # : SS-0351
VIN # : A9Z00351
MFG Date : 6/17/2015

Previous Odom : 3420

Current Odom : 0

Elapsed : 0

Engine Hours In: 4592.0 Hours Out : 4592.0

Labor Requested / Part SubTotal

Extended

(1) REPLACE BROKEN DOOR GLASS

97.50

Parts Subtotal 629.58

Shop Supplies

4.88

Parts: 629.58
Labor: 97.50

Supplies: 4.88

Tax: 36.60

Total: 768.56
Balance: 768.56

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ___ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts ___. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By _____ Date _____ Time _____

Unit #: 55-0351 S/N:

Odometer:

Hours: 45.92

Lab: Repair Description

Date

Location

Tech Name

Hours

- REPAIR DOOR WINDOW

OCT. 5

Platinum

Comy

1.5

Parts

Mechanic ID:

Mechanic Signature:

Qty.

Part #

Description

STK/ORD

Qty.

Part #

Description

STK/ORD

1 258 3209

LATCH ASS.

4 258 4075

RUBBER

1 345 6230

GLASS-DOOR.