

X42-1  
MAY

SCANNED

Vehicle Service Report

Unit #: 20-01

Date: 11/06/2025

Mileage: 219065

Hours: \_\_\_\_\_

Grease  Yes  No

Fuel Filters Changed  Yes  No

Oil Changes  Yes  No

Air Filter Changed  Yes  No

Fluids	Good	Changed	Add	Amount
Main	/			
Aux.	/			
Diff Front	/			
Diff. Rear	/			
Winch				
Steering Box				
Steering Reservoir	/			
Radiator	/			

Lights Checked  Yes  No

Tire Pressure Checked  Yes  No

Brakes Set Up  Yes  No

Add Coolant Condition  Yes  No

Add Windshield Washer Fluid  Yes  No

Oil Hubs  Yes  No

Batteries Checked  Yes  No

Belts Checked  Yes  No

Glass Checked  Yes  No

Tire Tread Checked  Yes  No

Fire Extinguisher Checked  Yes  No

First Aid Kit Checked  Yes  No

Emergency Flare Kit  Yes  No

Communication Test  Yes  No

Vehicle Interior Clean  Yes  No

Exterior Washed  Yes  No

Overall Condition of Vehicle:

\_\_\_\_\_

Major or Minor Repairs:

\_\_\_\_\_

Technician: Lukas Parsons

Reviewed by: \_\_\_\_\_

SCANNED

Vehicle Service Report

Unit #: 20-01

Date: August 28/2025

Mileage: 212 000 Kms

Hours: \_\_\_\_\_

Grease  Yes  No

Fuel Filters Changed  Yes  No

Oil Changes  Yes  No

Air Filter Changed  Yes  No

Fluids	Good	Changed	Add	Amount
Main	/			
Aux.	/			
Diff Front	/			
Diff. Rear		/		2.5 approx
Winch				
Steering Box				
Steering Reservoir	/			
Radiator	/			

Lights Checked  Yes  No

Tire Pressure Checked  Yes  No

Brakes Set Up  Yes  No

Add Coolant Condition  Yes  No

Add Windshield Washer Fluid  Yes  No

Oil Hubs  Yes  No

Batteries Checked  Yes  No

Belts Checked  Yes  No

Glass Checked  Yes  No

Tire Tread Checked  Yes  No

Fire Extinguisher Checked  Yes  No

First Aid Kit Checked  Yes  No

Emergency Flare Kit  Yes  No

Communication Test  Yes  No

Vehicle Interior Clean  Yes  No

Exterior Washed  Yes  No

Overall Condition of Vehicle:

Rear diff oil changed / cabin air filter changed  
coolant sucked down (over filled)

Major or Minor Repairs:

remove grill and top cowl wash and blow out rad and coolers

Technician: Lukas Parsons

Reviewed by: \_\_\_\_\_

SCANNED

Vehicle Service Report

Unit #: 20-01

Date: June 4, 2025

Mileage: 201817 Kms

Hours:

Grease  Yes  No

Fuel Filters Changed  Yes  No

Oil Changes  Yes  No

Air Filter Changed  Yes  No

Fluids	Good	Changed	Add	Amount
Main	/			
Aux.	/			
Diff Front	/			
Diff Rear	/			
Winch				
Steering Box				
Steering Reservoir	/			
Radiator	/			

Lights Checked

Yes  No

Tire Pressure Checked

Yes  No

Brakes Set Up

Yes  No

Add Coolant Condition

Yes  No

Add Windshield Washer Fluid

Yes  No

Oil Hubs

Yes  No

Batteries Checked

Yes  No

Belts Checked

Yes  No

Glass Checked

Yes  No

Tire Tread Checked

Yes  No

Fire Extinguisher Checked

Yes  No

First Aid Kit Checked

Yes  No

Emergency Flare Kit

Yes  No

Communication Test

Yes  No

Vehicle Interior Clean

Yes  No

Exterior Washed

Yes  No

Overall Condition of Vehicle:

Front = 60 psi  
Rear = 70 psi

Major or Minor Repairs:

9 rock chips in windshield all should be repaired before it cracks

Technician: Lukas Parsons

Reviewed by:

## Vehicle Service Report

SCANNED

Unit #: 20-01

Date: 02/11/2025

Mileage: 193641

Hours: \_\_\_\_\_

Grease  Yes  No

Fuel Filters Changed  Yes  No

Oil Changes  Yes  No

Air Filter Changed  Yes  No

Fluids	Good	Changed	Add	Amount
Main	/			
Aux.	/			
Diff Front	/			
Diff Rear	/			
Winch				
Steering Box				
Steering Reservoir	/			
Radiator	/			

Lights Checked  Yes  No

Tire Pressure Checked  Yes  No

Brakes Set Up  Yes  No

Add Coolant Condition  Yes  No

Add Windshield Washer Fluid  Yes  No

Oil Hubs  Yes  No

Batteries Checked  Yes  No

Belts Checked  Yes  No

Glass Checked  Yes  No

Tire Tread Checked  Yes  No

Fire Extinguisher Checked  Yes  No

First Aid Kit Checked  Yes  No

Emergency Flare Kit  Yes  No

Communication Test  Yes  No

Vehicle Interior Clean  Yes  No

Exterior Washed  Yes  No

Overall Condition of Vehicle: \_\_\_\_\_

Major or Minor Repairs:

NEEDS a new bulb socket for LH plate light

Technician: hukas / Cde

Reviewed by: \_\_\_\_\_

Vehicle Service Report

**SCANNED**

Unit #: 20-01

Date: Sept 27, 2024

Mileage: 185044

Hours: \_\_\_\_\_

Grease  Yes  No

Fuel Filters Changed  Yes  No

Oil Changes  Yes  No

Air Filter Changed  Yes  No

Fluids	Good	Changed	Add	Amount
Main	✓			
Aux.	✓			
Diff Front	✓			
Diff Rear	✓			
Winch	✓			
Steering Box	✓			
Steering Reservoir	✓			
Radiator	✓			

Lights Checked  Yes  No

Tire Pressure Checked  Yes  No

Brakes Set Up  Yes  No

Add Coolant Condition  Yes  No

Add Windshield Washer Fluid  Yes  No

Oil Hubs  Yes  No

Batteries Checked  Yes  No

Belts Checked  Yes  No

Glass Checked  Yes  No

Tire Tread Checked  Yes  No

Fire Extinguisher Checked  Yes  No

First Aid Kit Checked  Yes  No

Emergency Flare Kit  Yes  No

Communication Test  Yes  No

Vehicle Interior Clean  Yes  No

Exterior Washed  Yes  No

Overall Condition of Vehicle:

\_\_\_\_\_

Major or Minor Repairs:

\_\_\_\_\_

Technician: Mike

Reviewed by: \_\_\_\_\_

FILE COPY



300-740 ST. ALBERT ROAD

"EXPRESS OIL CHANGE" ST. ALBERT AB T8N 7H5

DATE 08/24/2023 14:35
INVOICE NO. 00009-140799
TRANSACTION NO. 23082400140799
EMPLOYEES MAR16E RAI03E CO003

CUSTOMER INFORMATION

VEHICLE INFORMATION

RR#4, Eckville, AB
Eckville, AB TOM OX0

(403) 746-5744

YEAR 2020 LICENSE PLATE AB-CGR4181
MAKE GMC TRUCKS ALTERNATE ID
MODEL SIERRA 3500 PICKUP MILEAGE 150204
ENGINE 8cyl 6.6L Diesel Turbo 4wd
VIN# VIN: 1GT49SEY0LF310684

L SKOCDOPOLE CONSTRUCTION

UNIT# 20-01
DRIVERS NAME CHRIS

SERVICE HISTORY

LID DATE MILEAGE SERVICES
08/24/23 150204 FS OEM AF RPF

SERVICE CHECKLIST

DESCRIPTION

QTY. PRICE

- 1. BRAKE FLUID FULL
2. POWER STEERING FLUID FULL
3. WASHER FLUID LOW
4. BATTERY HYDROMETER EYE APPEARS OK
5. AIR FILTER REPLACED
6. SKID PLATE N/A
7. PCV VALVE N/A
8. WIPER BLADES\* APPEARS OK
9. SERPENTINE BELT\* APPEARS OK
10. ENGINE COOLANT 45 DEGS. C
11. TRANSMISSION\* APPEARS OK
12. REAR DIFFERENTIAL\* N/A
13. FRONT DIFFERENTIAL\* N/A
14. TRANSFER CASE\* N/A
15. EXTERIOR LIGHTS APPEARS OK
16. TIRE TREAD 8 32nds
17. WINDOWS/LUBRICATE HNGE DONE/DONE
18. TIRE PRESSURE F50 R50
19. UNDER CARRIAGE VISUAL\* APPEARS OK
20. LEAKS\* APPEARS OK

- DURAMAX PACKAGE SYNTHETIC 1.00 219.99
S11878 SYN. OIL FILTER 1.00 17.99
PREMIUM FILTER 1.00 0.00
MOTOSOL 15/40 DIESEL SYN. 9.50 0.00
OIL LEVEL FULL ON ARRIVAL 1.00 0.00
CHASSIS SEALED-NO LUBE 1.00 0.00
A CHANGE FOR THE BETTER 1.00 0.00
BATTERY TEST PASSED 1.00 0.00
EMAIL SAVINGS PROGRAM-NO 1.00 0.00
ENVIRO/SHOP SUPPLIES FEE 1.00 6.99
XA11888 AIR FILTER 1.00 37.99
REC. FUEL FILTER 1.00 0.00

SUBTOTAL 282.96
DISCOUNT (FLT) 28.30-
SALE 254.66
GST (5%) 12.73
TOTAL 267.39
CHARGE 267.39

COMMENTS

THANK YOU!

GST#896127677

MESSAGES

Recommend next service on 11/22/2023 or 155204 km.
Tire pricing available at www.lubecity.ca/tires
Now OPEN Sundays!



OIL WARNING!

If your oil warning light comes on (or your gauge loses pressure) STOP your car immediately! NEVER operate your engine when the oil warning light is on!

DOING SO WILL VOID WARRANTY!
See Over For Additional Information

X
I have authorized the work to be performed without a written estimate.
See reverse of invoice for Personal Information Protection Policy

SCANNED

Vehicle Service Report

Unit #: 20-01

Date: June 17, 2024

Mileage: 176,216

Hours:

Grease  Yes  No

Fuel Filters Changed  Yes  No

Oil Changes  Yes  No

Air Filter Changed  Yes  No

Fluids	Good	Changed	Add	Amount
Main	✓			
Aux.	✓			
Diff Front	✓			
Diff. Rear	✓			
Winch	✓			
Steering Box	✓			
Steering Reservoir	✓			
Radiator	✓			

Lights Checked  Yes  No

Tire Pressure Checked  Yes  No

Brakes Set Up  Yes  No

Add Coolant Condition  Yes  No

Add Windshield Washer Fluid  Yes  No

Oil Hubs  Yes  No

Batteries Checked  Yes  No

Belts Checked  Yes  No

Glass Checked  Yes  No

Tire Tread Checked  Yes  No

Fire Extinguisher Checked  Yes  No

First Aid Kit Checked  Yes  No

Emergency Flare Kit  Yes  No

Communication Test  Yes  No

Vehicle Interior Clean  Yes  No

Exterior Washed  Yes  No

Overall Condition of Vehicle: New rear brake pads, rotate tires, New batteries

Major or Minor Repairs:

Install studor to retorque all wheels to 140ft/lbs at 176,360km

Technician: Mike

Reviewed by:

SCANNED

Vehicle Service Report

Unit #: 20-01

Date: 04/14/2023

Mileage: 133,888

Hours:

Grease  Yes  No

Fuel Filters Changed  Yes  No

Oil Changes  Yes  No

Air Filter Changed  Yes  No

Fluids	Good	Changed	Add	Amount
Main	<input checked="" type="checkbox"/>			
Aux.	<input checked="" type="checkbox"/>			
Diff Front	<input checked="" type="checkbox"/>			
Diff Rear	<input checked="" type="checkbox"/>			
Winch	<input type="checkbox"/>			
Steering Box	<input type="checkbox"/>			
Steering Reservoir	<input checked="" type="checkbox"/>			
Radiator	<input checked="" type="checkbox"/>			

Lights Checked  Yes  No

Tire Pressure Checked  Yes  No

Brakes Set Up  Yes  No

Add Coolant Condition  Yes  No

Add Windshield Washer Fluid  Yes  No

Oil Hubs  Yes  No

Batteries Checked  Yes  No

Belts Checked  Yes  No

Glass Checked  Yes  No

Tire Tread Checked  Yes  No

Fire Extinguisher Checked  Yes  No

First Aid Kit Checked  Yes  No

Emergency Flare Kit  Yes  No

Communication Test  Yes  No

Vehicle Interior Clean  Yes  No

Exterior Washed  Yes  No

Overall Condition of Vehicle:

Major or Minor Repairs: Replaced RR Mud flap, Replaced fuel filter, canister lid.

Technician: Nathan

Reviewed by: [Signature]

Vehicle Service Report

**SCANNED**

Unit #: 20-01

Date: Feb 28, 2024

Mileage: 167,367

Hours: \_\_\_\_\_

Grease  Yes  No

Fuel Filters Changed  Yes  No

Oil Changes  Yes  No

Air Filter Changed  Yes  No

Fluids	Good	Changed	Add	Amount
Main	✓			
Aux.	✓			
Diff Front	✓			
Diff. Rear	✓			
Winch	✓			
Steering Box	✓			
Steering Reservoir	✓			
Radiator	✓			


- |                             |   |                       |   |
|-----------------------------|---|-----------------------|---|
| Lights Checked              | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | Tire Pressure Checked | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |
| Brakes Set Up               | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Add Coolant Condition | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| Add Windshield Washer Fluid | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | Oil Hubs              | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| Batteries Checked           | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | Belts Checked         | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |
| Glass Checked               | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | Tire Tread Checked    | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |
| Fire Extinguisher Checked   | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | First Aid Kit Checked | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |
| Emergency Flare Kit         | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | Communication Test    | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| Vehicle Interior Clean      | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Exterior Washed       | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |

Overall Condition of Vehicle: \_\_\_\_\_

Major or Minor Repairs: \_\_\_\_\_

Technician: Mike

Reviewed by: \_\_\_\_\_



300-740 ST. ALBERT ROAD  
ST. ALBERT AB T8N 7H5

SCANNED

DATE 11/10/2023 15:57  
INVOICE NO. 00009-142188  
TRANSACTION NO. 23111000142188  
EMPLOYEES SIN11E RAI03E SIN11

CUSTOMER INFORMATION

RR#4, Eckville, AB  
Eckville, AB TOM 0X0  
(403) 746-5744

VEHICLE INFORMATION

YEAR 2020 LICENSE PLATE AB-CGR4181  
MAKE GMC TRUCKS ALTERNATE ID  
MODEL SIERRA 3500 PICKUP MILEAGE 158807  
ENGINE 8cyl 6.6L Diesel Turbo 4wd  
VIN# VIN: 1GT49SEY0LF310684

UNIT# L SKOCCOPOLE CONSTRUCTION  
DRIVERS NAME CHRIS FLAMAND

SERVICE HISTORY

DATE	MILEAGE	FS	OEM AF	SERVICES
11/10/23	158807	FS	OEM AF	
08/24/23	150204	FS	OEM AF	RFF

SERVICE CHECKLIST

DESCRIPTION

QTY. PRICE

- BRAKE FLUID FULL
- POWER STEERING FLUID FULL
- WASHER FLUID LOW
- BATTERY HYDROMETER EYE APPEARS OK
- AIR FILTER REPLACED
- SKID PLATE N/A
- PCV VALVE N/A
- WIPER BLADES\* APPEARS OK
- SERPENTINE BELT\* APPEARS OK
- ENGINE COOLANT 45 DEGS. C
- TRANSMISSION\* APPEARS OK
- REAR DIFFERENTIAL\* N/A
- FRONT DIFFERENTIAL\* N/A
- TRANSFER CASE\* N/A
- EXTERIOR LIGHTS APPEARS OK
- TIRE TREAD 8 32nds
- WINDOWS/LUBRICATE HNGE DECL/DECL
- TIRE PRESSURE F60 R80
- UNDER CARRIAGE VISUAL\* APPEARS OK
- LEAKS\* APPEARS OK

DURAMAX PACKAGE SYNTHETIC	1.00	219.99
S11878 SYN. OIL FILTER	1.00	17.99
PREMIUM FILTER	1.00	0.00
MOTOSOL 5/40 DIESEL SYN.	9.50	0.00
OIL LEVEL FULL ON ARRIVAL	1.00	0.00
CHASSIS SEALED-NO LUBE	1.00	0.00
A CHANGE FOR THE BETTER	1.00	0.00
BATTERY TEST PASSED	2.00	0.00
EMAIL SAVINGS PROGRAM-YES	1.00	0.00
ENVIRO/SHOP SUPPLIES FEE	1.00	6.99
XA11888 AIR FILTER	1.00	39.99

COMMENTS


THANK YOU!

SUBTOTAL	284.96
DISCOUNT (FLT)	28.50-
SALE	256.46
GST (5%)	12.82
TOTAL	269.28
CHARGE	269.28

GST#896127677

MESSAGES

Recommend next service on 02/08/2024 or 163807 km.  
Tire pricing available at [www.lubecity.ca/tires](http://www.lubecity.ca/tires)  
Now OPEN Sundays!



OIL WARNING!

If your oil warning light comes on (or your gauge loses pressure) **STOP** your car immediately! **NEVER** operate your engine when the oil warning light is on!

**DOING SO WILL VOID WARRANTY!**  
See Over For Additional Information

X  
I have authorized the work to be performed without a written estimate  
See reverse of invoice for Personal Information Protection Policy



Jiffy lube

PRIMCO COMMERCIAL LP

O/A JIFFY LUBE #1107  
2100 - 8TH AVENUE  
COLD LAKE, AB T9M 1C2  
(780) 639-9539  
1107@jiffylubestores.ca

SCANNED

DATE 1/31/2023 2:19 PM  
TRANSACTION NO 23013132322293  
INVOICE NO 01107-32322293  
VEHICLE ID AB-CGR4181

Page 1 of 1

FILE COPY

Customer Information	Service History
Skocdopole Lethbridge Lethbridge, AB T0M 0X0 (403) 746-5744	DATE KILOMETERS SERVICES 1/31/23 125190 FS OF OIL  20-01
Vehicle Information	
2020 GMC TRUCKS SIERRA 3500 PICKUP 8cyl 6.6L Diesel Turbo VIN 1GT49SEY0LF310684 KILOMETERS 125190 ALT ID	

Employees	Service Comments
UPPER LOWER DOUBLES CASHIER OP JK OP	THANK YOU!

Service Checklist	Description	Qty.	Price
1. ENGINE OIL	AMSOIL	1.00	174.99
2. OIL FILTER	HE OIL FILTER	1.00	0.00
3. AIR FILTER	CHECKED	1.00	0.00
4. CABIN AIR FILTER	NOT ACCESSIBLE	9.50	0.00
5. POWER STEERING FLUID	CHECKED	2.00	0.00
6. RADIATOR FLUID	CHECKED	1.00	4.00
7. BRAKE FLUID	LEVEL GOOD	1.00	1.00
8. FRONT DIFFERENTIAL FLUID	CHECKED		
9. TRANSFER CASE FLUID	CHECKED		
10. REAR DIFFERENTIAL FLUID	CHECKED		
11. TRANSMISSION/TRANSAXLE FLUID	CHECKED		
12. BELTS & HOSES	CHECKED		
13. WASHER FLUID	ADDED		
14. WINDOWS	DECLINED		
15. WIPER BLADES	CHECKED		
16. TIRE PRESSURE	Declined		
17. LIGHT CHECK	CHECKED		
18. CHASSIS LUBRICATION	6 GREASE POINTS		
19. SHOCKS & STRUTS	APPEARS OK		
20. BATTERY TEST	NEW BATTERY		
21. OIL LIFE MONITOR	RESET		
	GM DIESEL SYNTHETIC		
	SIGNATURE CHECKLIST		
	oil filter PF26 OEM		
	ROTELLA T6 5W40 CK-4		
	WINDSHIELD WASHER FLUID		
	SHOP SUPPLIES		
	ENVIRONMENTAL FEE		
	SUBTOTAL		\$179.99
	SALE		\$179.99
	TAXABLE PARTS	179.99	
	GST TAX		9.00
	<b>TOTAL</b>		<b>\$188.99</b>
	VISA 6722 AUTH: 013384		188.99
	<b>CHANGE</b>		<b>\$0.00</b>

Warranty Statement

This Jiffy Lube centre warrants all workmanship against failure for 7 days from the date of service. This warranty does not apply when the customer tampers with or alters the centre's products or alters the manufacturer's original equipment or when corrective action is taken without prior written approval from this Jiffy Lube service centre. The customer must have the limited warranty certificate and must retain a sample of the product(s) involved.  Oil Level Shown  Oil Filter Tight  Drain Plug Tight  Rear Diff Chk Plug  Front Diff Chk Plug  Transfer Case Chk Plug  Transmission Chk Plug

WE APPRECIATE YOUR BUSINESS :) GST#: 85231 0788RT0001  
APPROPRIATE, WARRANTY-APPROVED PRODUCT MAY HAVE BEEN SUBSTITUTED.

X

Recommend next service on 05/01/2023 or 130190 km.

Cardholder acknowledges receipt of goods and/or services in the amount shown hereon and agrees to perform the obligations set forth in the Cardholder's agreement with the issuer.

SCANNED

Vehicle Service Report

Unit #: 20-01

Date: 11/04/2022

Mileage: 111848

Hours:

Grease  Yes  No

Fuel Filters Changed  Yes  No

Oil Changes  Yes  No

Air Filter Changed  Yes  No

Fluids	Good	Changed	Add	Amount
Main	<input checked="" type="checkbox"/>			
Aux.	<input checked="" type="checkbox"/>			
Diff Front	<input checked="" type="checkbox"/>			
Diff Rear	<input checked="" type="checkbox"/>			
Winch				
Steering Box				
Steering Reservoir	<input checked="" type="checkbox"/>			
Radiator	<input checked="" type="checkbox"/>			

Lights Checked  Yes  No

Tire Pressure Checked  Yes  No

Brakes Set Up  Yes  No

Add Coolant Condition  Yes  No

Add Windshield Washer Fluid  Yes  No

Oil Hubs  Yes  No

Batteries Checked  Yes  No

Belts Checked  Yes  No

Glass Checked  Yes  No

Tire Tread Checked  Yes  No

Fire Extinguisher Checked  Yes  No

First Aid Kit Checked  Yes  No

Emergency Flare Kit  Yes  No

Communication Test  Yes  No

Vehicle Interior Clean  Yes  No

Exterior Washed  Yes  No

Overall Condition of Vehicle:

Changed cabin air filter, change trailer plug and test fire extinguisher missing so replaced, New flare kit

Major or Minor Repairs:

2 new wipers, tires set to door spec

Technician: Lukas Parsons

Reviewed by:

SCANNED

Vehicle Service Report

Unit #: 20-01

Date: Aug 17, 2022

Mileage: 99,043

Hours:

Grease  Yes  No

Fuel Filters Changed  Yes  No

Oil Changes  Yes  No

Air Filter Changed  Yes  No

Fluids	Good	Changed	Add	Amount
Main	✓			
Aux.	✓			
Diff Front	✓			
Diff. Rear	✓			
Winch	✓			
Steering Box	✓			
Steering Reservoir	✓			
Radiator	✓			

- Lights Checked  Yes  No
- Brakes Set Up  Yes  No
- Add Windshield Washer Fluid  Yes  No
- Batteries Checked  Yes  No
- Glass Checked  Yes  No
- Fire Extinguisher Checked  Yes  No
- Emergency Flare Kit  Yes  No
- Vehicle Interior Clean  Yes  No
- Tire Pressure Checked  Yes  No
- Add Coolant Condition  Yes  No
- Oil Hubs  Yes  No
- Belts Checked  Yes  No
- Tire Tread Checked  Yes  No
- First Aid Kit Checked  Yes  No
- Communication Test  Yes  No
- Exterior Washed  Yes  No

Overall Condition of Vehicle:

\_\_\_\_\_

Major or Minor Repairs: Repair - left light, new windshield, change oil and filter

Technician: Mike

Reviewed by: \_\_\_\_\_

Vehicle Service Report

**SCANNED**

Unit #: 20-01

Date: 05/31/2022

Mileage: 88074

Hours: \_\_\_\_\_

Grease  Yes  No

Fuel Filters Changed  Yes  No

Oil Changes  Yes  No

Air Filter Changed  Yes  No

Fluids	Good	Changed	Add	Amount
Main	<input checked="" type="checkbox"/>			
Aux.	<input checked="" type="checkbox"/>			
Diff Front	<input checked="" type="checkbox"/>			
Diff. Rear	<input checked="" type="checkbox"/>			
Winch				
Steering Box				
Steering Reservoir	<input checked="" type="checkbox"/>			
Radiator	<input checked="" type="checkbox"/>			

Lights Checked  Yes  No

Tire Pressure Checked  Yes  No

Brakes Set Up  Yes  No

Add Coolant Condition  Yes  No

Add Windshield Washer Fluid  Yes  No

Oil Hubs  Yes  No

Batteries Checked  Yes  No

Belts Checked  Yes  No

Glass Checked  Yes  No

Tire Tread Checked  Yes  No

Fire Extinguisher Checked  Yes  No

First Aid Kit Checked  Yes  No

Emergency Flare Kit  Yes  No

Communication Test  Yes  No

Vehicle Interior Clean  Yes  No

Exterior Washed  Yes  No

Overall Condition of Vehicle:


wheels rotated and torqued to 140 lbs  
Slip fault repaired by Ed. (crack in back corner seam)

Major or Minor Repairs:

SW-40 (9.5L)

Technician: Lucas Parsons

Reviewed by: \_\_\_\_\_



**BROOKS LUBE & ALIGNMENT LTD. TREADPRO**

BOX 580 619 2nd STREET W  
BROOKS, AB. T1R 1B5  
Phone: 403-362-6441 Fax: 403-362-5860

**INVOICE**

**243694**

100662485RT GST BLA  
B178929 AMVIC

**SCANNED**

**INVOICE**

Printed Date: 03/30/2022 Work Completed: 03/30/2022

**SKOCDOPOLE CONST.**

2020 GMC - Sierra 3500 HD - 6.6L V8 (403CI) VIN(Y)

Lic # : CGR4181

Odometer In : 79100

Unit # : 20-01

VIN # : 1GT49SEY0 LF310684

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
5W-40 DIESEL FULL SYNTHETIC Size: BULK EOKL-HD3099	9.50	0.00	n/c	ENVIROMENTAL CHARGE		4.95
OIL FILTER OFB40150 Shop Supplies	1.00	1.75	1.75	FULL SYNTHETIC SERVICE (UP TO 10 LITERS) CHANGED ENGINE OIL. REPLACED OIL FILTER. CHECKED AIR FILTER. (REPLACE IF REQUESTED) CHECKED ALL FLUIDS. (TOP AND UNDERNEATH) GREASED FRONT END AND DRIVE SHAFTS (IF APPLICABLE)	1.49	155.95
			11.26			

Org. Estimate 182.61 Revisions 0.00 Current Estimate 182.61

Labor:	155.95
Parts:	13.01
Sublet:	4.95
<b>SubTotal:</b>	<b>173.91</b>
Tax:	8.70
<b>Total:</b>	<b>182.61</b>
Bal Due:	\$0.00

[ Payments - Interac - \$182.61 ]

Vehicle Received: 3/30/2022

Customer Number : 13143

Indebtness is hereby acknowledged in the sum of \$\_\_\_\_\_ being the total amount of balance owing for repairs, parts and accessories described in this work order. Conditions as set forth under comments are also hereby acknowledged. If your service visit required the removal of your vehicles wheels, The wheel nuts will need to be retorqued after the first 100 kms. Failure to do so could cause the wheels to become loose. (\$10.00 min) per month on overdue accounts, some exemptions apply. Returned Cheque: A service charge of \$25.00 will be applied.

\*eTransfers gladly accepted at - brlube@telusplanet.net\*

Signature \_\_\_\_\_ Date \_\_\_\_\_

Visit us on the web: <https://www.brookslubeandalignmentltd.ca/>

Email Address: [brlube@telusplanet.net](mailto:brlube@telusplanet.net)

Service Advisor : RICHARD, SHANTEL, Tech : BOSMAN, COLTAN; LOEWEN, EI

Vehicle Service Report

Unit #: 20-01

Date: 01/21/2022

Mileage: 69981

Hours: \_\_\_\_\_

Grease  Yes  No

Fuel Filters Changed  Yes  No

Oil Changes  Yes  No

Air Filter Changed  Yes  No

Fluids	Good	Changed	Add	Amount
Main	/			
Aux.	/			
Diff Front	/			
Diff. Rear	/			
Winch				
Steering Box				
Steering Reservoir	/			
Radiator	/			

Lights Checked  Yes  No

Tire Pressure Checked  Yes  No

Brakes Set Up  Yes  No

Add Coolant Condition  Yes  No

Add Windshield Washer Fluid  Yes  No

Oil Hubs  Yes  No

Batteries Checked  Yes  No

Belts Checked  Yes  No

Glass Checked  Yes  No

Tire Tread Checked  Yes  No

Fire Extinguisher Checked  Yes  No

First Aid Kit Checked  Yes  No

Emergency Flare Kit  Yes  No

Communication Test  Yes  No

Vehicle Interior Clean  Yes  No

Exterior Washed  Yes  No

Overall Condition of Vehicle:

Found 11 code's going to chevy in rocky for repairs  
Damaged box and bumper repairs will be done else where

Major or Minor Repairs:

5W-40 oil (9.5L)

Technician: Lukas Parsons

Reviewed by: \_\_\_\_\_



Vehicle Service Report

**SCANNED** SEP 14 2021

Unit #: 20-01

Date: Aug 30, 2021

Mileage: 44,153 Km's

Hours: \_\_\_\_\_

Grease  Yes  No

Fuel Filters Changed  Yes  No

Oil Changes  Yes  No

Air Filter Changed  Yes  No

Fluids	Good	Changed	Add	Amount
Main	✓			
Aux.	✓			
Diff Front	✓			
Diff. Rear	✓			
Winch				
Steering Box				
Steering Reservoir	✓			
Radiator	✓			

Lights Checked  Yes  No

Tire Pressure Checked  Yes  No

Brakes Set Up  Yes  No

Add Coolant Condition  Yes  No

Add Windshield Washer Fluid  Yes  No

Oil Hubs  Yes  No

Batteries Checked  Yes  No

Belts Checked  Yes  No

Glass Checked  Yes  No

Tire Tread Checked  Yes  No

Fire Extinguisher Checked  Yes  No

First Aid Kit Checked  Yes  No

Emergency Flare Kit  Yes  No

Communication Test  Yes  No

Vehicle Interior Clean  Yes  No

Exterior Washed  Yes  No

Overall Condition of Vehicle:

\_\_\_\_\_

Major or Minor Repairs:

\_\_\_\_\_

Technician: Milo Dubois

Reviewed by: \_\_\_\_\_

SEP 17 2021  
**SCANNED**

Vehicle Service Report

Unit #: 20-01

Date: Oct 13, 2021

Mileage: 46,564

Hours: 52.5

Grease  Yes  No

Fuel Filters Changed  Yes  No

Oil Changes  Yes  No

Air Filter Changed  Yes  No

Fluids	Good	Changed	Add	Amount
Main				
Aux.				
Diff Front				
Diff. Rear				
Winch				
Steering Box				
Steering Reservoir				
Radiator				

Lights Checked  Yes  No

Tire Pressure Checked  Yes  No

Brakes Set Up  Yes  No

Add Coolant Condition  Yes  No

Add Windshield Washer Fluid  Yes  No

Oil Hubs  Yes  No

Batteries Checked  Yes  No

Belts Checked  Yes  No

Glass Checked  Yes  No

Tire Tread Checked  Yes  No

Fire Extinguisher Checked  Yes  No

First Aid Kit Checked  Yes  No

Emergency Flare Kit  Yes  No

Communication Test  Yes  No

Vehicle Interior Clean  Yes  No

Exterior Washed  Yes  No

Overall Condition of Vehicle:

\_\_\_\_\_

Major or Minor Repairs:

New windshield

\_\_\_\_\_

Technician: \_\_\_\_\_

Reviewed by: \_\_\_\_\_

Vehicle Service Report

JUL - 9 2021

**SCANNED**

Unit #: 20-01

Date: July 5, 2021

Mileage: 34259

Hours: \_\_\_\_\_

Grease  Yes  No

Fuel Filters Changed  Yes  No

Oil Changes  Yes  No

Air Filter Changed  Yes  No *Blown out \**

Fluids	Good	Changed	Add	Amount
Main	/			
Aux.	/			
Diff Front	/			
Diff. Rear	/			
Winch				
Steering Box				
Steering Reservoir	/			
Radiator	/			

Lights Checked  Yes  No

Tire Pressure Checked  Yes  No

Brakes Set Up  Yes  No

Add Coolant Condition  Yes  No

Add Windshield Washer Fluid  Yes  No

Oil Hubs  Yes  No

Batteries Checked  Yes  No

Belts Checked  Yes  No

Glass Checked  Yes  No

Tire Tread Checked  Yes  No

Fire Extinguisher Checked  Yes  No

First Aid Kit Checked  Yes  No

Emergency Flare Kit  Yes  No

Communication Test  Yes  No

Vehicle Interior Clean  Yes  No

Exterior Washed  Yes  No

Overall Condition of Vehicle:

rotated tires wheels torqued to 140 ft lbs  
5W-40 syn (9-5C)

Major or Minor Repairs:

Code - P12A6 Found. (Possible crank no start / Extended crank)  
(caused by having to boost truck / confirmed with Chris)

Technician: Lukas Persons

Reviewed by: \_\_\_\_\_

# Edwards

## Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
 Telephone: (403)845-3328 · Fax: (403)845-4661  
 GST #101584076

INVOICE ORIGINAL  
 Work Order #352195 **SCANNED**  
 Skocdopole Construction Ltd  
 April 28, 2021  
 Svc. Adv Steedsman, Debbie  
 Cust. Ph. (403) 746-5744  
 Tag# 2195 **FILE COPY**  
 Page 1 of 2  
 04/29/2021 09:30:13

<b>To Skocdopole Construction Ltd</b>  RR 4  Eckville AB TOM OXO	Year: 2020 Veh Id: 71978 Unit #: SKOC20-01 Make: GMC License #: CGR4181 Model: 3500 Sierra 4WD Crew Cab Odo. In: 23,999 Colour: G7C Cardinal Red Odo. Out: V.I.N.#: 1GT49SEY0LF310684 Next Service: 10/28/2021 Date In: 04/28/2021 In Service Date: 09/30/2020 Out: 04/28/2021 Cases: 2 Ext. War - - ( mo/ ) - D: \$0.00 Promised Time: 00/00/0000 00:00:00 AM Call When Ready: No
---	--

Case: 1 \*Certi Oil Life Rem 13%  
 \*Certified Correction not defined.  
 CAUSE: Oil Life Rem 13%  
 CORRECTION: LOF done  
 Coolant good to -36'c (JG)

Quantity	Description/Correction	Retail	Price	Total
1.00	12684038L - PF26 Oil Filter - 20+Dmax - Warranty (FP)	\$19.68	\$0.00	\$0.00
9.50	88865794L - 15W40 Conventional-Bulk - Warranty	\$5.72	\$0.00	\$0.00
3.00	WWL - Washer Fluid - Warranty	\$1.09	\$0.00	\$0.00
			\$0.00	\$0.00
• *Certi Oil Life Rem 13%• *Certified Correction not defined. • CAUSE: Oil Life Rem 13%• CORRECTION: LOF done • Coolant good to -36'c (JG) - Warranty • Completed by Technician number: 0498				
			\$0.00	\$0.00

Misc \$0.00 Labour \$0.00 Parts \$0.00 Prepaid Parts Amt: \$0.00 Case Total: \$0.00

Case: 2 Fuel Filter GM Diesel 6.6L Replacement (2017 and newer)

Quantity	Description/Correction	Retail	Price	Total
1.00	13539108L - FILTER KIT-FUEL	\$68.72	\$0.00	\$0.00
			\$124.95	\$124.95
• Tech Cause: Cause not defined. • Tech Comments: Correction not defined. • Completed by Technician number: 0498				

# Edwards

## Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
 Telephone: (403)845-3328 · Fax: (403)845-4661  
 GST #101584076

INVOICE ORIGINAL  
 Work Order  
 #352195  
 Skocdopole Construction Ltd  
 April 28, 2021  
 Svc.Adv Steedsman, Debbie  
 Cust.Ph. (403) 746-5744  
 Tag# 2195  
 Page 2 of 2  
 04/29/2021 09:30:14

Misc \$0.00	Labour \$71.85	Parts \$53.10	Prepaid Parts Amt: \$0.00	<b>Case Total: \$124.95</b>
				\$0.00

O U T	Indebtedness is hereby acknowledged for the "Total Charges" being all or the balance owing to repairs, parts & accessories described in this work order. Interest will be charged at 2 % monthly / 24 % annually on overdue invoices. Privacy-Personal information is collected in accordance with applicable privacy legislation and is governed by EDWARDS GARAGE LIMITED Privacy Policy. Your privacy is important to us. Ask us if you would like information about EDWARDS GARAGE LIMITED Privacy Policy. I agree to receive Edwards Garage newsletter containing news, updates and promotions regarding Edwards Garage products. You can withdraw your consent at anytime. I would like to unsubscribe from receiving: ___All messages from Edwards Garage. ___All promotional messages from Edwards.	Currency:	Labour:	\$71.85
			Parts:	\$53.10
		Payment Ref:	Misc:	\$0.00
		Expiry Date:	Sub Total:	\$124.95
	P/O#: GM	G/HST:	\$6.25	
	G/HST Reg # R101584076	PST:	\$0.00	
		Tax Adjustment:	\$0.00	
04/28/2021	Date	Signature	Payment Type	Charge
			Total:	\$131.20

Payee	Payment Type	Reference	Date	
Skocdopole Construction Ltd	Charge		04/28/2021	\$131.20
			<b>Balance Owing:</b>	<b>\$131.20</b>

Reference:

SCANNED

# L&D MARINE RENTALS LTD

FILE COPY

**INVOICE**

20-01

Date: January 31, 2021

Make Check Payable to:

L&D Marine Rentals Ltd  
Box 10012 - 61116 Hwy 28 West  
Bonnyville, Alberta T9N 0A6  
Phone 780-201-0154

Invoice #: 20210131-11

14,587 Kms

Bill to: Skocdopole Construction  
Phone Number: 403-892-9320

2020 6.6L Chevrolet Diesel  
Unit# 2001

Product #	Item	Quantity	Size	Amount	Total	
ADOTP	5W40 Diesel Oil	1	9.46L	95.15	95.15	
EAO11	Oil Filter	1	11	19.05	19.05	
	Labor	1		40.00	40.00	
				<b>Paid Credit Card</b>	<b>SUBTOTAL</b>	<b>\$154.20</b>
				GST:	7.71	
				<b>TOTALS</b>	<b>\$161.91</b>	



6413 - 50 Avenue  
Bonnyville, AB  
T9N 2L9

Phone: 780-826-3301

Fax: 780-826-5381

INVOICE ORIGINAL

Work Order

#237888

Skocdopole Conctruction

January 28, 2021

Svc. Adv Amiot, Bonnie

Cust. Ph. (403) 746-5744

Tag# 2644

Page 1

01/29/2021 15:26:26

FILE COPY

To: Skocdopole Conctruction		Year: 2020 Veh Id: 61993 Unit #:
Range Road 4	20-01	Make: GMC License #:
Eckville	AB	Model: Crew CAB Pickup 4WD Odo. In: 14,523
TOM OXO		Colour: White Odo. Out:
		V.I.N.#: 1GT49SEY0LF310684 Next Service:
		Date In: 01/28/2021 In Service Date: 09/30/2020
		Out: 01/29/2021 Cases: 1
		Ext. War - - ( mo/ ) - D: \$0.00
		Promised Time: 00/00/0000 00:00:00 AM Call When Ready:

Case: 1 SES Light, Emissions error on dash, truck going into reduced power

Quantity	Description/Correction	Retail	Price	Total					
1.00	84996345 - TANK ASM-EMIS RDCN FLUID - Warranty (FP)	\$1,678.92	\$0.00	\$0.00					
3.00	88865654 - FLUID,DIESEL EXHAUST (DEF) ACDELCO 9.46L - Warranty	\$21.24	\$0.00	\$0.00					
			\$0.00	\$0.00					
	• Tech Cause: Scanned and found code: P21DD								
	• Tech Comments: Replaced reductant tank. Reset tank level. Function tested all 3 heaters. Cleared DTCs. Complete - Warranty								
	• Completed by Technician number: 4029		\$0.00	\$0.00					
	• Warranty Shuttle - Warranty		\$0.00	\$0.00					
Misc	\$0.00	Labour	\$0.00	Parts	\$0.00	Prepaid Parts Amt:	\$0.00	Case Total:	\$0.00
									\$0.00

If your wheels have been removed, they need to be re-torqued after 150kms.

# Edwards

## Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
 Telephone: (403)845-3328 · Fax: (403)845-4661  
 GST #101584076

INVOICE ORIGINAL

Work Order  
 #346861

SCANNED

Skocdopole Construction Ltd

December 09, 2020

Svc. Adv Leclair, Timothy

Cust. Ph. (403) 746-5744

Tag# 6861

FILE COPY

Page 1

12/09/2020 09:13:27

<b>To: Skocdopole Construction Ltd</b>  RR 4  Eckville AB TOM OXO	Year: 2020 Veh Id: 71978 Unit #: SKOC20-01 Make: GMC License #: Model: 3500 Sierra 4WD Crew Cab Odo. In: 7,889 Colour: G7C Cardinal Red Odo. Out: V.I.N.#: 1GT49SEY0LF310684 Next Service: 12/30/2020 Date In: 12/09/2020 In Service Date: 09/30/2020 Out: 12/09/2020 Cases: 1 Ext. War - - ( mo/ ) - D: \$0.00 Promised Time: 00/00/0000 00:00:00 AM Call When Ready: No
--	---

Case: 1 \*Certified GM 2 year maintenance (\$93) (GM 2 year maintenance service)

CAUSE: Requested  
 Oil life remaining 34%  
 CORRECTION: LOF done  
 Coolant good to -36°c  
 t.l.

Quantity	Description/Correction	Retail	Price	Total
1.00	12684038L - PF26 Oil Filter - 20+Dmax - Warranty	\$19.68	\$0.00	\$0.00
3.00	WWL - Washer Fluid - Warranty	\$1.09	\$0.00	\$0.00
9.50	19367368L - 15W40 Conventional-Bulk - Warranty	\$4.68	\$0.00	\$0.00
			\$0.00	\$0.00
	*Certified GM 2 year maintenance (\$93) (GM 2 year maintenance service)• CAUSE: Requested • Oil life remaining 34%• CORRECTION: LOF done • Coolant good to -36°c • t.l. - Warranty • Completed by Technician number: 7105		\$0.00	\$0.00

Misc \$0.00    Labour \$0.00    Parts \$0.00    Prepaid Parts Amt: \$0.00    Case Total: \$0.00  
 \$0.00

Skocdopole Construction Ltd.

Date Rec'd \_\_\_\_\_ Job # \_\_\_\_\_

Chq. # \_\_\_\_\_ Unit # 20-01

Date Mailed \_\_\_\_\_ GL # 50150-02

Approved by *Sandy Henning*

RECEIVED  
 SCANNED  
 OCT 26 2020

Vehicle Service Report

Unit #: 20-01

Date: 10/22/2020

Mileage: 254 KM's

Hours: 5.1 hrs

Grease  Yes  No

Fuel Filters Changed  Yes  No

Oil Changes  Yes  No

Air Filter Changed  Yes  No

Fluids	Good	Changed	Add	Amount
Main	/			
Aux.	/			
Diff Front	/			
Diff. Rear	/			
Winch				
Steering Box	<del>///</del>			
Steering Reservoir	/			
Radiator	/			

Lights Checked  Yes  No

Tire Pressure Checked  Yes  No

Brakes Set Up  Yes  No

Add Coolant Condition  Yes  No

Add Windshield Washer Fluid  Yes  No

Oil Hubs  Yes  No

Batteries Checked  Yes  No

Belts Checked  Yes  No

Glass Checked  Yes  No

Tire Tread Checked  Yes  No

Fire Extinguisher Checked  Yes  No

First Aid Kit Checked  Yes  No

Emergency Flare Kit  Yes  No

Communication Test  Yes  No

Vehicle Interior Clean  Yes  No

Exterior Washed  Yes  No

Overall Condition of Vehicle:

Install gps, 2way radio, inverter, cell phone booster, beacon, 1 work light  
Skos (7pin plug), running boards, front and rear med flaps  
slip tack, tool box, fire extinguisher bracket, wood liner for box

Major or Minor Repairs:

seat cover front and rear, floor mats (husky), headache rack and  
rails, back up alarm (on a switch), Shocker pass (esd)  
Used a junction box to connect all 3 trailer plugs (by spare tire)

Technician: Lukas Parsons

Reviewed by: \_\_\_\_\_





# Headwind Solutions

4331 - 41 Street  
Camrose AB. T4V 3V8  
1-844-304-7277  
1-780-672-2775

**SCANNED** Invoice

**FILE COPY**

Date	Invoice #
9/28/2020	23664

Invoice To
Cash Sales

Ship To
Skocdopole Construction Eckville, AB Hold for P/U 403-746-5744 Puro# 4399786

GST/HST No. 853140457

P.O. #	Terms
20-01	COD - Payme...

Via
Purolator Colle

Quantity	Item	Description	Price Each	Amount
		Unit 20-01		
1	PASS-DUR-L5P-2020-AR	Positive Air Shutoff System-GM Duramax L5P-2020>-VIN 8th digit Y-12 volt- Auto Reset	1,553.00	1,553.00
1	WH-0001-R5	Wire harness R5 -9' 12ga. power leads 12/24 volt	120.00	120.00
		GST on Sales	5.00%	83.65
			<b>Sales Tax</b>	CAD 83.65
			<b>Total</b>	CAD 1,756.65

A 20 % stocking fee will apply on all returns, if returned within 30 days.  
No returns after 30 days.  
Call for RMA# BEFORE returning.

<b>Payments/Credits</b>	CAD 0.00
<b>Balance Due</b>	CAD 1,756.65

**Thank you for your business.**

Headwind Automotive Solutions Ltd.