

M.A.P.

EARTHWORKS LTD.

Water & Sewer Services Ltd.

Tel: 780-453-6996
Fax: 780-455-5257

14303 - 116 Avenue
Edmonton, AB T5M 4G2

ENTERED FEB 28 2026

L96-2
MAY

SERVICE REPORT

DATE: Feb 27/26

CUSTOMER: _____

JOBSITE ADDRESS: _____ *Shop*

MACHINE SERIAL # A10432 UNIT NUMBER: E129 E129 YEAR: _____
350

MACHINE MAKE: _____ MACHINE HRS: 15910 next 16410

VEHICLE SERIAL # _____ UNIT NUMBER: _____ YEAR: _____

VEHICLE MAKE: _____ MILEAGE: _____

WORK DONE: 500 hr oil change

changed ^{hyd} eng oil

MAJOR PARTS USED:

| PART NO. | ITEM | PRICE |
|--|----------------------------|-------|
| <u>P55 3000</u> | <u>oil</u> | |
| <u>P55 1864</u> | <u>P550881 Fuel</u> | |
| <u>P60885, P777 869, P50881, P5578</u> | <u>P500138, PA4372 air</u> | |
| | | |
| | | |

TIME STARTED: _____ SERVICEMAN NAME: Maurice

TIME FINISHED: _____

TOTAL HOURS: 3

[Red Signature]

CUSTOMER SIGNATURE

SERVICEMAN SIGNATURE



SMS EQUIPMENT INC.
16116 - 111 AVENUE
EDMONTON AB T5M 2S1

PICKING LIST

ORDER # : S29212437
SHIPMENT ID : OS6033498
PAGE # : 1
CUSTOMER ORDER NO # : E179-JB
PAY TERMS : N30
PRINT DATE & TIME : 25-Dec-15 17:14

BILL TO : C00011211
M.A.P. WATER AND SEWER
SERVICES LTD.
14303 - 116 AVENUE
EDMONTON AB T5N 4G2

SHIP TO : C00011211
M.A.P. WATER AND SEWER
SERVICES LTD.
14303 - 116 AVENUE
EDMONTON AB T5M 4G2

PHONE :

PHONE : +1-780-453-6996

| DATE OPENED | CUSTOMER UNIT # | UNIT # | SOLD BY | SHIP VIA | FREIGHT TERMS |
|-------------|-----------------|--------|------------------|-----------------|---------------|
| 25-Dec-11 | | | MAC COLLINS-HOOD | CUSTOMER PICKUP | FOB |

| POS | PROD LINE | PART NUMBER | DESCRIPTION | WEIGHT KG | R T | ORDERED | DELIVERED | BACK ORDER | UNIT PRICE | PRICE |
|-----------------------|-----------|--------------|-------------|-----------|-----|---------|-----------|------------|------------|--------|
| 10 | KO | 6745-22-3130 | COVER | 2.56 | | 1 | 1 | | 284.84 | 284.84 |
| PARTS SUBTOTAL | | | | | | | | | | 284.84 |

Net Weight : 2.56 KG
Gross Weight: _____ KG

Note: Returns must include a copy of SMS Equipment Inc.'s Packing Slip or Invoice

SHIPPED FROM :
PS129 Edmonton
SMS Equipment Inc.

RT: Parts Return Indicator
* : Non-Returnable Parts

I hereby acknowledge my indebtedness in the amount of
being the total amount of balance owing as shown hereon

Customer's Signature

*** WARNING *** PRICES SHOWN FOR CUSTOMER REFERENCE. ALL TAXES WILL BE REFLECTED ON YOUR INVOICE.
PLEASE DO NOT PAY USING PACKING SLIP. - SMS OPERATIONS

RECEIVED DEC 16 2015



PICKING LIST

SMS EQUIPMENT INC.
16116 - 111 AVENUE
EDMONTON AB T5M 2S1

ORDER # : S29212445
SHIPMENT ID : OS6029743
PAGE # : 1
CUSTOMER ORDER NO # : E129-JB
PAY TERMS : N30
PRINT DATE & TIME : 25-Dec-11 16:25

BILL TO : C00011211
M.A.P. WATER AND SEWER
SERVICES LTD.
14303 - 116 AVENUE
EDMONTON AB T5N 4G2

SHIP TO : C00011211
M.A.P. WATER AND SEWER
SERVICES LTD.
14303 - 116 AVENUE
EDMONTON AB T5M 4G2

PHONE :

PHONE : +1-780-453-6996

| DATE OPENED | CUSTOMER UNIT # | UNIT # | SOLD BY | SHIP VIA | FREIGHT TERMS |
|-------------|-----------------|--------|------------|-----------------|---------------|
| 25-Dec-11 | | | AARON RYAN | CUSTOMER PICKUP | FOB |

| POS | PROD LINE | PART NUMBER | DESCRIPTION | WEIGHT KG | R T | ORDERED | DELIVERED | BACK ORDER | UNIT PRICE | PRICE |
|-----------------------|-----------|--------------|-------------|-----------|-----|---------|-----------|------------|------------|--------|
| 1 | KO | 20Y-60-A1221 | ACCUMULATOR | 1.40 | | 1 | 1 | | 389.29 | 389.29 |
| 2 | KO | 207-63-76170 | BUSHING | | | 1 | | 1 | 212.91 | |
| PARTS SUBTOTAL | | | | | | | | | | 389.29 |

Net Weight : 1.40 KG

Gross Weight: _____ KG

Note: Returns must include a copy of SMS Equipment Inc.'s Packing Slip or Invoice

| | |
|---|--|
| SHIPPED FROM : PS129 Edmonton SMS Equipment Inc. | I hereby acknowledge my indebtedness in the amount of being the total amount of balance owing as shown hereon <hr/> <p style="text-align: center;">Customer's Signature</p> |
|---|--|

*** WARNING *** PRICES SHOWN FOR CUSTOMER REFERENCE. ALL TAXES WILL BE REFLECTED ON YOUR INVOICE. PLEASE DO NOT PAY USING PACKING SLIP. - SMS OPERATIONS

RECEIVED DEC 12 2025

Order #
S29207273

Sales Office
EDMONTON

Order Date
05-Aug-2025

Order Total
CAD 283.71

Customer #
C00011211

Order Information

Order Details

PO # E129-DS

Ship Complete No

Delivery Date 05-Aug-2025

Special Instructions DENNIS 780-699-8265

Equipment Details

Serial #

Model

Unit #

Shipping & Billing Information

Shipping Details

14303 - 116 AVENUE ,
EDMONTON ,ALBERTA -T5M 4G2 ,
CANADA

Invoice Details

14303 - 116 AVENUE ,
EDMONTON ,ALBERTA -T5N 4G2 ,
CANADA

Shipping Method

Ship Via
CUSTOMER PICK
UP

Parts Information

| Part Details | Quantity Details | | Price Details (CAD) | | Amount (CAD) | |
|--|------------------|----|---------------------|-------|--------------|-------|
| 01010-62075 KO KOMATSU BOLT Unit: EACH Weight: 0.227 KG | Ordered | 10 | Your Price | 27.02 | Tax | 13.51 |
| | Back Order | 0 | List Price | 28.44 | Core Charges | 0.00 |
| | | | | | | Total |

| | |
|--------------------------|---------------|
| Total Weight | 2.270 KG |
| Gross Amount (CAD) | 284.40 |
| Discount (CAD) | 14.20 |
| Sub Total (CAD) | 270.20 |
| Tax Amount (CAD) | 13.51 |
| Env. Charge (CAD) | 0.00 |
| Order Total (CAD) | 283.71 |

*Discount is not applicable on Core Charge.

unmarked copy

Packing Slip

Technichrome

TECHNICHROME INDUSTRIES LTD.
HARD CHROME PLATING AND HYDRAULIC CYLINDER REPAIR SPECIALISTS

Date Shipped: 2025-07-31 **Ship To:** MAP Water and Sewer
Carrier: Delivery Truck 14303 - 116 Ave
Tracking: NA Edmonton, AB T5M 4G2
Shipped By: Jennifer Lefaivre
Package #: 36684 **Box #:** 1 of 2

| Work Order | Purchase Order | Quantity | Part | Description | Price | 3% Environmental Fee |
|------------|----------------|----------|----------------|--|-----------|----------------------|
| 31881 | E129-05565 | 1 | TRACK ADJUSTER | Rechrome rod and hone barrel, seals supplied by customer | \$1775.00 | \$53.25 |

| Totals: | |
|---------|---|
| Orders: | 1 |
| Parts: | 1 |

RECEIVED AUG 13 2025

Received By: _____ Date: _____

Technichrome, 10442/10408 David Road, Acheson, AB T7X 6A4 - (780) 960-9500
<http://www.technichrome.ca>

original copy

Packing Slip

Technichrome

TECHNICHROME INDUSTRIES LTD.
HARD CHROME PLATING AND HYDRAULIC CYLINDER REPAIR SPECIALISTS

Date Shipped: 2025-07-31 **Ship To:** MAP Water and Sewer
Carrier: Delivery Truck 14303 - 116 Ave
Tracking: NA Edmonton, AB T5M 4G2
Shipped By: Jennifer Lefaivre
Package #: 36685 **Box #:** 2 of 2

| Work Order | Purchase Order | Quantity | Part | Description | Price | 3% Environmental Fee |
|------------|----------------|----------|----------------|--|-----------|----------------------|
| 31880 | E129-05565 | 1 | TRACK ADJUSTER | Rechrome rod and hone barrel, seals supplied by customer | \$1775.00 | \$53.25 |

| Totals: | |
|---------|---|
| Orders: | 1 |
| Parts: | 1 |

Received By: _____ **Date:** _____

Technichrome, 10442/10408 David Road, Acheson, AB T7X 6A4 - (780) 960-9500
<http://www.technichrome.ca>



WATER & SEWER SERVICES LTD.
EARTHWORKS LTD.

OW 05565

OUTSIDE WORK REQUEST

14303 - 116 Avenue NW
Edmonton, AB T5M 4G2

Tel: 780-453-6996
Fax: 780-455-5257

DATE: July 29/25

CHARGE TO: MAP water & sewer PO #: E129/05565

CONTACT: Lennie 780-777-7184

VENDOR: Technichrome

MACHINE SERIAL # _____ UNIT NUMBER: E129 YEAR: _____

MACHINE MAKE: _____ MACHINE HRS: _____

VEHICLE SERIAL # _____ UNIT NUMBER: _____ YEAR: _____

VEHICLE MAKE: _____ MILEAGE: _____

PARTS / COMPONENT / EQUIPMENT

| PART NO. | ITEM |
|--------------|-------------|
| 207-30-74120 | Shaft x2 |
| 207-30-71441 | Cylinder x2 |
| | |
| | |
| | |

WORK REQUIRED:

Rechrome

Bush machine down

Return to JHK

Justin MK

REQUESTED BY

Tom B

DELIVERED BY

Jenn

RECEIVED BY

M.A.P.

14303 - 116 Avenue
Edmonton, AB T5M 4G2

EARTHWORKS LTD.
Water & Sewer Services Ltd.

Tel: 780-453-6996
Fax: 780-455-5257

ENTERED JUL 10 2025

SERVICE REPORT

DATE: July 9/25

CUSTOMER: _____

JOB SITE ADDRESS: Villanova

MACHINE SERIAL # A-10432 UNIT NUMBER: E21A E12A YEAR: _____

MACHINE MAKE: 350 MACHINE HRS: 15475 next 15975

VEHICLE SERIAL # _____ UNIT NUMBER: _____ YEAR: _____

VEHICLE MAKE: _____ MILEAGE: _____

WORK DONE: 2000 hr oil change

MAJOR PARTS USED:

| PART NO. | ITEM | PRICE |
|--------------------|--|---------------------|
| <u>P551064</u> | <u>P550881. fuel</u> | |
| <u>P553000</u> | <u>oil</u> | |
| <u>20x602-1470</u> | <u>breather PA5276, P502578 breather, housing.</u> | |
| <u>P500138</u> | <u>PA4372, P608835, P777869 air</u> | <u>6150-21-5710</u> |
| <u>P554071</u> | <u>coolant</u> | |
| <u>P550787</u> | <u>HYD</u> | |

TIME STARTED: _____ SERVICEMAN NAME: Mauro

TIME FINISHED: _____

TOTAL HOURS: 5 CUSTOMER SIGNATURE: [Signature] SERVICEMAN SIGNATURE: _____



**WATER & SEWER SERVICES LTD.
EARTHWORKS LTD.**

- 250 Hr. _____
- 500 Hr. _____
- 750 Hr. _____
- 1000 Hr. _____
- 1250 Hr. _____
- 1500 Hr. _____
- 1750 Hr. _____
- 2000 Hr.
- Other _____

Customer Name: _____

Unit #: E129

Technician Name: Maurie

Model: 35

Hours: 15975

Date: July 9/25

| Inspection Items (safety/ walk around) | | Good | Fair | Poor | Start Machine | | Good | Fair | Poor |
|--|---|-------------------------------------|-------------------------------------|------|--|--|-------------------------------------|------|-------------------------------------|
| 1 | Grab bars & steps (Loose/missing) | <input checked="" type="checkbox"/> | | | 28 | Lever control & accumulator (Function) | <input checked="" type="checkbox"/> | | |
| 2 | Sheet metal (Damaged/loose) | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | | 29 | Ripper or work equipment (function/damaged) | | | |
| 3 | Glass & mirrors (Missing/broken) | <input checked="" type="checkbox"/> | | | 30 | Boom (function/damaged) | | | |
| 4 | Fender/Bumpers (Damaged/loose) | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | | 31 | Arm (function/damaged) | | | |
| 5 | Frame, body, Rops, Mounting bolts (missing/loose/damaged) | <input checked="" type="checkbox"/> | | | 32 | Bucket (function/damaged) | | | |
| 6 | Boom, arm, push arms (Cracking/damaged/bent) | <input checked="" type="checkbox"/> | | | 33 | Lift (function/damaged) | <input checked="" type="checkbox"/> | | |
| 7 | Any other exterior breakage/damage | | <input checked="" type="checkbox"/> | | 34 | Tilt (function/damaged) | | | |
| Pre Start Up | | Good | Fair | Low | 35 | Dump (function/damaged) | <input checked="" type="checkbox"/> | | |
| 8 | Engine Oil Level | <input checked="" type="checkbox"/> | | | 36 | Parking brake (function/damaged) | <input checked="" type="checkbox"/> | | |
| 9 | Transmission/PT Oil Level | <input checked="" type="checkbox"/> | | | 37 | Brake accumulator/ Pedal operation (function) | | | |
| 10 | Hydraulic Oil Level | <input checked="" type="checkbox"/> | | | 38 | Head lamps (function, missing, broken) | <input checked="" type="checkbox"/> | | |
| 11 | Final Drive/Differential Oil Level | | | | Work Equipment And U/C or Tires | | Good | Fair | Poor |
| 12 | Swing Machinery Oil Level | | | | 39 | Get condition (worn/missing) | | | |
| 13 | Coolant level | <input checked="" type="checkbox"/> | | | 40 | Cylinders (leaking/damaged) | | | |
| Cab Interior | | Good | Fair | Poor | 41 | Idler & track assembly (adjust/leaks/worn/loose) | | | <input checked="" type="checkbox"/> |
| 14 | Monitor Panel Screen (scratched/broken) | | <input checked="" type="checkbox"/> | | 42 | Rollers & roller guards (leaks/ worn/missing/damaged) | | | <input checked="" type="checkbox"/> |
| 15 | Record error codes from monitor panel | <input checked="" type="checkbox"/> | | | 43 | Sprockets (worn/damaged) | | | <input checked="" type="checkbox"/> |
| | | | | | 44 | Track or Tire condition (worn/damaged) | | | <input checked="" type="checkbox"/> |
| | | | | | Power Train | | Good | Fair | Poor |
| 16 | Rear camera functionality (if equipped) | <input checked="" type="checkbox"/> | | | 45 | Hoses (leaking/worn/damaged) | <input checked="" type="checkbox"/> | | |
| 17 | Cab Filters (Plugged/missing) | <input checked="" type="checkbox"/> | | | 46 | Belts (Noisy/worn/missing) | <input checked="" type="checkbox"/> | | |
| 18 | Cab lights, bulbs, fuses & switches | <input checked="" type="checkbox"/> | | | 47 | Engine (leaks) | <input checked="" type="checkbox"/> | | |
| 19 | Seat operation & safety belt | <input checked="" type="checkbox"/> | | | 48 | KCGT (Turbo) (leaks/smoking) | <input checked="" type="checkbox"/> | | |
| 20 | Fire extinguisher (available/charged) | <input checked="" type="checkbox"/> | | | 49 | Dozer piping (leaks/damage) | <input checked="" type="checkbox"/> | | |
| 21 | Wiper function & blade condition | <input checked="" type="checkbox"/> | | | 50 | EGR assembly (leaks/connected) | <input checked="" type="checkbox"/> | | |
| 22 | Windows; Latches (missing/function) & glass | <input checked="" type="checkbox"/> | | | 51 | DPF assembly & heat shielding (damaged/funcitning) | <input checked="" type="checkbox"/> | | |
| 23 | (missing/function) | <input checked="" type="checkbox"/> | | | 52 | Transmission & P/T (leaks) | <input checked="" type="checkbox"/> | | |
| 24 | AC/Heater operations & louvers (broken/missing/function) | <input checked="" type="checkbox"/> | | | 53 | Transmission Cooler (leaks) | <input checked="" type="checkbox"/> | | |
| 25 | Horn & Back up alarm (Function) | <input checked="" type="checkbox"/> | | | 54 | Final drives and differentials (check every 500 Hours) | <input checked="" type="checkbox"/> | | |
| 26 | Hour meter (funtion/broken) | <input checked="" type="checkbox"/> | | | 55 | Hydraulic cooler fins (dent/damaged/leaking) | <input checked="" type="checkbox"/> | | |
| | | | | | 56 | Radiator Fins & Radiator Cap (bent/damaged/leaking) | <input checked="" type="checkbox"/> | | |
| Greasing | | Good | Fair | Poor | 57 | Fan motor & fan blade (leaks/damaged) | <input checked="" type="checkbox"/> | | |
| | Grease Fittings (Loose/damaged/missing) | | | | 58 | Battery Electrolyte level | <input checked="" type="checkbox"/> | | |
| | Grease Points (Taking grease) | <input checked="" type="checkbox"/> | | | 59 | Fuel Tank cap (missing/leaking) | <input checked="" type="checkbox"/> | | |
| | Drive Line (grease every 1000 hours) | | | | 60 | Air Filter (plugged/missing) | <input checked="" type="checkbox"/> | | |

Overall Comments:

BM



EARTHWORKS LTD.
Water & Sewer Services Ltd.

14303 - 116 Avenue
 Edmonton, AB T5M 4G2

Tel: 780-453-6996
 Fax: 780-455-5257

ENTERED OCT 21 2024

SERVICE REPORT

DATE: Oct 18/24

CUSTOMER: _____

JOB SITE ADDRESS: 199th St

MACHINE SERIAL # A10432 UNIT NUMBER: E129 YEAR: _____

MACHINE MAKE: 350 MACHINE HRS: 15030 next 15530

VEHICLE SERIAL # _____ UNIT NUMBER: _____ YEAR: _____

VEHICLE MAKE: _____ MILEAGE: _____

WORK DONE: 500 hr oil change

changed eng oil

MAJOR PARTS USED:

| PART NO. | ITEM | PRICE |
|--|------|-------|
| 600 P108885, P777869, P A4372, P 500138 air | | |
| P 553000 oil | | |
| P 551864, P 550881 Fuel | | |
| | | |
| | | |
| | | |

TIME STARTED: _____ SERVICEMAN NAME: Maurice

TIME FINISHED: _____

TOTAL HOURS: 3 _____

B.M. Wa
 CUSTOMER SIGNATURE

 SERVICEMAN SIGNATURE

M.A.P.

14303 - 116 Avenue
Edmonton, AB T5M 4G2

EARTHWORKS LTD.

Water & Sewer Services Ltd.

Tel: 780-453-6996
Fax: 780-455-5257

ENTERED JUN 03 2024

SERVICE REPORT

DATE: June 21/24

CUSTOMER: _____

JOB SITE ADDRESS: Alces

MACHINE SERIAL # A10432 UNIT NUMBER: E129 YEAR: _____

MACHINE MAKE: 350 MACHINE HRS: 14590 next 18090

VEHICLE SERIAL # _____ UNIT NUMBER: _____ YEAR: _____

VEHICLE MAKE: _____ MILEAGE: _____

WORK DONE: 1000 hr oil change

sampled hyd

changed
 — pump dr
 — swing dr
 — filters
 — eng

MAJOR PARTS USED:

| PART NO. | ITEM | PRICE |
|---|--------------------------------|-------|
| <u>P550787</u> | <u>Hyd, 07000-15195 O-ring</u> | |
| <u>P502518, PA5276</u> | <u>breather</u> | |
| <u>P551864, P550881</u> | <u>Fuel</u> | |
| <u>P553000</u> | <u>oil</u> | |
| <u>PA4312, P500138, P60885, P777869</u> | | |

TIME STARTED: _____ SERVICEMAN NAME: Maur

TIME FINISHED: _____

TOTAL HOURS: 08 B. McNamara

CUSTOMER SIGNATURE

SERVICEMAN SIGNATURE



WATER & SEWER SERVICES LTD. EARTHWORKS LTD.

- 250 Hr.
500 Hr.
750 Hr.
1000 Hr.
1250 Hr.
1500 Hr.
1750 Hr.
2000 Hr.
Other

Customer Name: _____

Unit #: E129

Technician Name: Maurin

Model: 350

Hours: 14590

Date: June 12 4

Inspection Items (safety/ walk around) table with columns for Good, Fair, Poor and Start Machine. Includes sections for Pre Start Up, Cab Interior, Greasing, and Work Equipment And U/C or Tires.

Overall Comments: BM