

WORK ORDER

BHULLAR TRANSPORTATION.

157 BEARDSLEY CRESENT
FORT MCMURRAY ,AB

DATE MAY 21,2026
UNIT#/PLATE# 2013 ARNES /6VE168
ODOMETER _____
HOURS (IF AVAILABLE) _____

SERVICE		HOURS	
	1 ST AXLE BOTH SIDES BRAKE SHOES AND DRUMS REPLACED		
	2ND AXLE BOTH SIDES BRAKE SHOES AND DRUMS REPLACED		
	3RD AXLE BOTH SIDES BRAKE SHOES AND DRUMS REPLACED		
	4TH AXLE BOTH SIDES BRAKE SHOES AND DRUMS REPLACED		
	1ST AXLE LH SHOCK REPLACED		
	2ND AXLE LH SHOCK REPLACED		
	1ST AXLE LH S-CAM REPLACED		
	4TH AXLE BOTH SIDE SHOCK REPLACED		
	2ND AXLE LH WHEEL SEAL REPLACED		
	1ST AXLE BOTH SIDES FENDER REPLACED		
	4TH AXLE RH FENDER REPLACED		
	REPLACED 2 TAIL LIGHTS		
	PAINT BOX AND FRAME WITH ENDURA PAINT		
	INSTALLED 6 NEW TIRES / 2 REAR MUDFLAPS		
	PARTS		
	MUDFLAPS		2.00
	S-CAM AND BUSHING KIT		1.00
	4707 BRAKE SHOES		8.00
	3600 DRUMS		8.00
	ALUMINUM FENDER		3.00
	22.5 TIRES		6.00
	TAIL LIGHTS		2.00
	46300 WHEEL SEAL		1.00