

**WRENCHHEAD MECHANICAL**  
 3135 4 ST  
 NISKU, ALBERTA. T9E-8L1  
 Phone: 780-436-9570 Fax: 780- -

*D41-4  
 JUN  
 AM*

**INVOICE**

**49923**

**INVOICE**

Printed Date: 08/01/2025 Work Completed: 08/01/2025

**CHEMCO-OFF ROAD**  
 3135-4 ST  
 NISKU, ALBERTA T9E-8L1  
 Office 780-436-9570

2001 ChAMPION - 730A GRADER UNIT#E032 - ser# 46023877  
 Lic # : Odometer In : 0  
 Unit # : MG-1429  
 VIN # : 031429

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
10W TO-4 OIL-STK TO4-10-TOTE	39.00	4.02	156.78	(1) PARTS ONLY NEKTAR W/O 389	n/c
SYNTHETIC 5W40 OIL-STK 5W40SYN	4.00	6.92	27.68		
75W90 SYNTHETIC GEAR OIL-STK 75W90SYN	30.00	8.49	254.70		
HYD OIL-STK AW-32	90.00	2.57	231.30		

Org. Estimate 703.98 Revisions 0.00 Current Estimate 703.98

Labor:	0.00
Parts:	670.46
SubTotal:	670.46
Tax:	33.52
Total:	703.98
Bal Due:	\$703.98

[ Payments - ]

*STK-671*

Vehicle Received: 8/1/2025

Customer Number : 3904

GST#865376503RT0001

Signature \_\_\_\_\_ Date \_\_\_\_\_

**WRENCHHEAD MECHANICAL**

3135 4 ST  
NISKU, ALBERTA. T9E-8L1  
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

**049923**

**REPAIR ORDER - RO**

Scheduled : 08/01/2025 01:02 PM

Print Date : 8/1/2025

**CHEMCO-OFF ROAD**

3135-4 ST  
NISKU, ALBERTA T9E-8L1  
Office 780-436-9570  
Cust ID :  
Last Service : 7/23/2025

2001 ChAMPION - 730A GRADER UNIT#E032 - ser# 4602

Lic # : -  
Unit # : MG-1429  
VIN # : 031429

MFG Date : 10/15/2013

Previous Odom : 13523

Current Odom : 0

Elapsed : 0

**Labor Requested / Part SubTotal**

**Extended**

(1) PARTS ONLY NEKTAR W/O 389

Parts Subtotal 670.46

Parts: 670.46

Labor: 0.00

Tax: 33.52

Total: 703.98

Balance: 703.98


TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within \_\_\_ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts \_\_\_\_. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By \_\_\_\_\_ Date \_\_\_\_\_ Time \_\_\_\_\_

**From:** Nektar Notifications <notifications@nektar.io>  
**Sent:** Monday, July 28, 2025 7:14 AM  
**To:**  
**Subject:** EXTERNAL: 1000 Hour Service on 82020030549 (MG-1429 • CHMP • 730A)



This email was generated by the [Nektar](#) asset management platform. Below you will find details about a task the user has requested to be shared with you.



A **1000 Hour Service** task has been updated. You have been sent this email as a part of the task notification named **Record of 1000HR for updating titan**.

Pressing '**Reply**' will reply to Rob Mueller ([rmueller@chemco.com](mailto:rmueller@chemco.com))

**Comments From User:** No comments included.



## Task Summary

### 1000 Hour Service

Service

Recorded By: Tyce Chappell (tyce.chemco) - 7/25/2025 4:06:00 PM (-6)

Engine hours	14033	Change Engine Oil and Filter	1. Pass
Engine Oil Sample Taken/Submitted	1. Pass	Change Fuel Filters	1. Pass
Change Water Seperator	1. Pass	Change Engine Air Filters	1. Pass
Change Cabin Air Filters	1. Pass	Change Transmission Filters	1. Pass
Grease Complete unit	1. Pass	Change Hydraulic Filters	1. Pass

Change Packer Drum Oil	1. Pass	Check All Fluid Levels	1. Pass
Inspect Pins and Bushings	1. Pass	Inspect Undercarriage	4. N/A
Inspect Tire Wear/Condition	1. Pass	Update Service Decal	1. Pass
Next Service Due @	14533	Fluids Used (Quantity/ Type)	0
Maintenance Remarks (defects/complaints)	-	Defect Picture 1	-
Defect Picture 2	-	Defect Picture 3	-
Defect Picture 4	-	Front Left Picture	-
Front Right Picture	-	Rear Left Picture	-
Rear Right Picture	-	Technicians sign off	
Service Manager Approved			




Nektar Inc.  
14420 154 Ave, Edmonton, Alberta T6V 0K8

You are receiving this email on behalf of Chemco, who is a client of [Nektar](#).  
[Unsubscribe](#) [Preferences](#)

**From:** Nektar Notifications <notifications@nektar.io>  
**Sent:** Monday, July 28, 2025 7:15 AM  
**To:**  
**Subject:** EXTERNAL: 2000 Hour Service on 82020030549 (MG-1429 • CHMP • 730A)



This email was generated by the [Nektar](#) asset management platform. Below you will find details about a task the user has requested to be shared with you.



A **2000 Hour Service** task has been updated. You have been sent this email as a part of the task notification named **Record of 2000HR for updating titan**.

Pressing '**Reply**' will reply to Rob Mueller ([rmueller@chemco.com](mailto:rmueller@chemco.com))

**Comments From User:** No comments included.



## Task Summary

### 2000 Hour Service

Service

Recorded By: Tyce Chappell (tyce.chemco) - 7/25/2025 4:02:00 PM (-6)

Engine hours	14033	Change Engine Oil and Filter	1. Pass
Engine Oil Sample Taken/Submitted	1. Pass	Change Fuel Filters	1. Pass
Change Water Seperator	1. Pass	Change Engine Air Filters	1. Pass
Change Cabin Air Filters	1. Pass	Grease Complete unit	1. Pass
Valve Set	1. Pass	Final Drive Service	1. Pass

Differential Service	1. Pass	Transmission Service	1. Pass
Swing Motor Service	1. Pass	Pump Drive Service	1. Pass
Transercase Service	1. Pass	Drop Box Service	1. Pass
Hub Service	1. Pass	Tandem Drive Service	1. Pass
Circle Drive Service	1. Pass	Check All Fluid Levels	1. Pass
Update Service Decal	1. Pass	Next Service Due @	14533
Fluids Used (Quantity/ Type)	(39L) 10w transmission oil (28L) 5w-40 engine oil (30L) 75-90 rear differential oil	Maintenance Remarks (defects/complaints)	-
Defect Picture 1	-	Defect Picture 2	-
Defect Picture 3	-	Defect Picture 4	-
Front Left Picture	-	Front Right Picture	-
Rear Left Picture	-	Rear Right Picture	-
Technicians sign off			
Service Manager Approved			




Nektar Inc.  
14420 154 Ave, Edmonton, Alberta T6V 0K8

You are receiving this email on behalf of Chemco, who is a client of [Nektar](#).  
[Unsubscribe Preferences](#)

**From:** Nektar Notifications <notifications@nektar.io>  
**Sent:** Monday, July 28, 2025 7:16 AM  
**To:**  
**Subject:** EXTERNAL: 3000 Hour Service on 82020030549 (MG-1429 • CHMP • 730A)



This email was generated by the [Nektar](#) asset management platform. Below you will find details about a task the user has requested to be shared with you.



A **3000 Hour Service** task has been updated. You have been sent this email as a part of the task notification named **Record of 3000HR for updating titan**.

Pressing '**Reply**' will reply to Rob Mueller ([rmueller@chemco.com](mailto:rmueller@chemco.com))

**Comments From User:** No comments included.



## Task Summary

### 3000 Hour Service

Service

Recorded By: Tyce Chappell (tyce.chemco) - 7/25/2025 3:58:00 PM (-6)

Engine hours	14033	Change Engine Oil and Filter	1. Pass
Engine Oil Sample Taken/Submitted	1. Pass	Change Fuel Filters	1. Pass
Change Water Seperator	1. Pass	Change Engine Air Filters	1. Pass
Change Cabin Air Filters	1. Pass	Hydraulic Service	1. Pass
Grease Complete unit	1. Pass	Check All Fluid Levels	1. Pass

Update Service Decal	1. Pass	Next Service Due @	14533
Fluids Used (Quantity/ Type)	(90L) AW-32 hydraulic oil	Maintenance Remarks (defects/complaints)	-
Defect Picture 1	-	Defect Picture 2	-
Defect Picture 3	-	Defect Picture 4	-
Front Left Picture	-	Front Right Picture	-
Rear Left Picture	-	Rear Right Picture	-
Technicians sign off			
Service Manager Approved			



Nektar Inc.  
14420 154 Ave, Edmonton, Alberta T6V 0K8

You are receiving this email on behalf of Chemco, who is a client of Nektar.  
[Unsubscribe](#) [Preferences](#)

**WRENCHHEAD MECHANICAL**

3135 4 ST  
 NISKU, ALBERTA. T9E-8L1  
 Phone: 780-436-9570 Fax: 780- -

*AH*

**INVOICE**

**49798**

**INVOICE**

Printed Date: 07/23/2025 Work Completed: 07/23/2025

**CHEMCO-OFF ROAD**  
 3135-4 ST  
 NISKU, ALBERTA T9E-8L1  
 Office 780-436-9570

2001 ChAMPION - 730A GRADER UNIT#E032 - ser# 46023877  
 Lic # :  
 Unit # : MG-1429  
 VIN # : 031429  
 Odometer In : 0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
OIL FILTER-STK LF9009	1.00	46.30	46.30	(1) PARTS ONLY. NEKTAR W/O 389	n/c
FUEL FILTER-STK FF5018	1.00	19.55	19.55		
FUEL FILTER-STK FF149	1.00	7.68	7.68		
HYDRAULIC FILTER-STK HF6587	2.00	0.00	n/c		
OIL SAMPLE JAR-STK 320271103-50	7.00	25.44	178.08		
PLASTIC OIL SAMPLE TUBE-STK 4C-4057	7.00	1.38	9.66		
SYNTHETIC 5W40 OIL-STK 5W40SYN	24.00	6.92	166.08		

Org. Estimate 448.72 Revisions 0.00 Current Estimate 448.72

Labor:	0.00
Parts:	427.35
<b>SubTotal:</b>	<b>427.35</b>
Tax:	21.37
<b>Total:</b>	<b>448.72</b>
Bal Due:	\$448.72

[ Payments - ]

*STK - 428*

Vehicle Received: 7/23/2025

Customer Number : 3904

GST#885376503RT0001

Signature \_\_\_\_\_ Date \_\_\_\_\_

**WRENCHHEAD MECHANICAL**

3135 4 ST  
NISKU, ALBERTA. T9E-8L1  
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

**049798**

**REPAIR ORDER - RO**

Scheduled : 07/23/2025 07:45 AM

Print Date : 7/23/2025

**CHEMCO-OFF ROAD**

3135-4 ST  
NISKU, ALBERTA T9E-8L1  
Office 780-436-9570  
Cust ID :  
Last Service : 4/16/2025

2001 ChAMPION - 730A GRADER UNIT#E032 - ser# 4602:  
Lic # : -  
Unit # : MG-1429  
VIN # : 031429  
MFG Date : 10/15/2013  
Current Odom : 0  
Elapsed : 0

Previous Odom : 13523

**Labor Requested / Part SubTotal**

**Extended**

(1) PARTS ONLY. NEKTAR W/O 389

**Parts Subtotal 427.35**

**Parts: 427.35**

**Labor: 0.00**

**Tax: 21.37**

**Total: 448.72**

**Balance: 448.72**

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within \_\_\_ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts \_\_\_\_. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By \_\_\_\_\_ Date \_\_\_\_\_ Time \_\_\_\_\_

**WRENCHHEAD MECHANICAL**  
 3135 4 ST  
 NISKU, ALBERTA. T9E-8L1  
 Phone: 780-436-9570 Fax: 780- -

*RH*

**INVOICE**  
**48716**

**INVOICE**

Printed Date: 04/16/2025 Work Completed: 04/16/2025

**CHEMCO-OFF ROAD**  
 3135-4 ST  
 NISKU, ALBERTA T9E-8L1  
 Office 780-436-9570

2001 ChAMPION - 730A GRADER UNIT#E032 - ser# 46023877  
 Lic # :  
 Unit # : MG-1429  
 VIN # : 031429  
 Engine Hrs In : 14026.0  
 Odometer In : 0  
 Engine Hours Out : 14026.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
WINDSHIELD WASHER FLUID/1L-STK WW	2.00	1.04	2.08	(1) CHANGE OUT ICE EDGES TO STRAIGHT EDGE * SEE TECH SHEET	390.00
EDGE, 3/4X8X84 (5/8)-ORDER 5D-9559	2.00	141.85	283.70		
PLOW BOLT 5/8X2-1/2-ORDER PB.625X2.5	30.00	1.81	54.30		
5/8" GR8 NUT-ORDER FAS178015	30.00	0.55	16.50		
5/8" FLATWASHER-ORDER FASFW5P8247	30.00	0.30	9.00		
REDTAC #2 GREASE-STK RED-2-14	3.50	7.88	27.58		
Shop Supplies			19.50		

Org. Estimate 525.00 Revisions 0.00 Current Estimate 525.00

Labor:	390.00
Parts:	412.66
SubTotal:	802.66
Tax:	40.03
Total:	842.69
Bal Due:	\$842.69

[ Payments - ]

*STK-50*

Vehicle Received: 4/15/2025

Customer Number : 3904

GST#865376503RT0001  
 Signature \_\_\_\_\_ Date \_\_\_\_\_

**WRENCHHEAD MECHANICAL**

3135 4 ST  
NISKU, ALBERTA. T9E-8L1  
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

**048716**

**REPAIR ORDER - RO**

Scheduled : 04/14/2025 03:04 PM

Print Date : 4/14/2025

**CHEMCO-OFF ROAD**  
3135-4 ST  
NISKU, ALBERTA T9E-8L1  
Office 780-436-9570  
Cust ID :  
Last Service : 10/31/2024

2001 ChAMPION - 730A GRADER UNIT#E032 - ser# 4602:  
Lic # : -  
Unit # : MG-1429  
VIN # : 031429  
MFG Date : 10/15/2013  
Current Odom : 0  
Elapsed : 0

Previous Odom : 13523

<b>Labor Requested / Part SubTotal</b>	<b>Extended</b>
(1) CHANGE OUT ICE EDGES TO STRAIGHT EDGE	130.00
Shop Supplies	6.50
<b>Parts Subtotal</b>	<b>0.00</b>

<b>Parts:</b> 0.00	<b>Supplies:</b> 6.50	<b>Tax:</b> 6.83	<b>Total:</b> 143.33
<b>Labor:</b> 130.00			<b>Balance:</b> 143.33

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within \_\_\_ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts \_\_\_\_. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By \_\_\_\_\_ Date \_\_\_\_\_ Time \_\_\_\_\_

Technician Work Sheet      Service Writer : GLAZIER, RUSSELL

Print Date: 4/14/2025

2001 ChAMPION - 730A GRADER UNIT#E032

Hat # :

Repair Order #

VIN # : 031429

Color :

**048716**

Engine : ser# 46023877 6.8L

Location :

Lic # :

Lic. State :

**CHEMCO-OFF ROAD**

Schedule :

Office 780-436-9570

Promised Date : 4/14/25 5:00 P.M.

Inspection Date : 10/15/13

Status :

Last Service : 10/31/24

Unit # : MG-1429

Current Odometer : 0

Trans :

Previous Mileage : 13,523

Brakes :

Elapsed Mileage : 0

Manufacture Date : 10/15/13

**Labor Description**

**Charged Hours**

(1) CHANGE OUT ICE EDGES TO STRAIGHT EDGE 2.00

Technician : <none>

OUT ODOMETER :

**Total Hours Charged : 2.00**

Hours out: 0.00

**Tech Notes**

---

---

---

Unit #:

S/N:

Odometer:

Hours:

Lab#

Repair Description

Date

Location

Tech Name

Hours

**Parts**

Mechanic ID:

Mechanic Signature:

Qty.

Part #

Description

STK/ORD

Qty.

Part #

Description

STK/ORD



UNIT #:	MG-1429	UNIT TYPE/DESCRIPTION:	730A Champion Series V1 grader			
	ODOMETER:	N/A	ENGINE HOURS:	14026	DATE:	Apr 15 2025

ITEM	REPAIR DESCRIPTION	QUOTED HOURS	ACTUAL HOURS
1	Keep eye on rear L/S tire (was at 18 psi) now 60 psi		
2	Ac belt needs to be replaced		
3	in proper hitch pin (replace with proper)		
4	four hydraulic lines on top of circle drive are cracked badly		
5	hydraulic sweat -> underneath cab on transmission tank		
6	front bottom L/S window cracked		
7	front top R/S marker light out (on top of windshield)		
8	looks like oil pan gasket is leaking (wash for further diag)		
9	runs poorly, most likely due for valve set		
10	coolant temp gauge cracked		
11	park brake lever lock button does not work anymore		
12	look into L/S front wheel seal (sweat)		
13	wash unit to fix or diag lots of these ?		

Tyce Chappell  
 Technician (Print Name)

Tyce Chappell  
 Technicians Signature



**WRENCHHEAD MECHANICAL**  
 3135 4 ST  
 NISKU, ALBERTA. T9E-8L1  
 Phone: 780-436-9570 Fax: 780- -

*RM*

**INVOICE**  
**46922**

**INVOICE**

Printed Date: 10/31/2024 Work Completed: 10/31/2024

**CHEMCO-OFF ROAD**  
 3135-4 ST  
 NISKU, ALBERTA T9E-8L1  
 Office 780-436-9570

2001 ChAMPION - 730A GRADER UNIT#E032 - ser# 46023877  
 Lic # :  
 Unit # : MG-1429  
 VIN # : 031429  
 Engine Hrs In : 13991.0 Engine Hours Out : 13991.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
24" WIPER BLADE ANCO-STK 31-24	1.00	11.63	11.63	(1) PERFORM INSPECTION AS PER CHECKLIST, SERVICE UNIT AS REQUIRED (OIL SAMPLE IF REQ), VERIFY OPERATIONS * SEE TECH SHEET	942.50
4" LED WORK LIGHT-STK X0024E62F3	1.00	12.00	12.00		
H4 75/70W HEADLIGHT BULB-STK H4-13342	1.00	8.66	8.66		
WINDSHIELD WASHER FLUID/1L-STK WWW	1.00	1.04	1.04		
75W90 SYNTHETIC GEAR OIL-STK 75W90SYN	26.00	11.33	294.58		
REDTAC #2 GREASE-STK RED-2-14	2.00	7.88	15.76		
Shop Supplies			47.13		

Org. Estimate 214.99 Revisions 0.00 Current Estimate 214.99

Labor:	942.50
Parts:	390.80
SubTotal:	1,333.30
Tax:	66.61
Total:	1,399.91
Bal Due:	\$1,399.91

[ Payments - ]

*STK-391*

Vehicle Received: 10/28/2024

Customer Number : 3904

GST#865376503RT0001  
 Signature \_\_\_\_\_ Date \_\_\_\_\_

**WRENCHHEAD MECHANICAL**

3135 4 ST  
NISKU, ALBERTA. T9E-8L1  
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

**046922**

**REPAIR ORDER - RO**

Scheduled : 10/28/2024 03:42 PM

Print Date : 10/28/2024

**CHEMCO-OFF ROAD**  
3135-4 ST  
NISKU, ALBERTA T9E-8L1  
Office 780-436-9570  
Cust ID :  
Last Service : 2/14/2023

2001 ChAMPION - 730A GRADER UNIT#E032 - ser# 4602:  
Lic # : -  
Unit # : MG-1429  
VIN # : 031429  
MFG Date : 10/15/2013  
Current Odom : 0  
Elapsed : 0

Previous Odom : 13523

<i>Labor Requested / Part SubTotal</i>	<b>Extended</b>
(1) PERFORM INSPECTION AS PER CHECKLIST, SERVICE UNIT AS REQUIRED (OIL SAMPLE IF REQ), VERIFY OPERATIONS.	195.00
Shop Supplies	9.75
<b>Parts Subtotal</b>	0.00

**Parts:** 0.00      **Supplies:** 9.75      **Tax:** 10.24      **Total:** 214.99  
**Labor:** 195.00      **Balance:** 214.99

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within \_\_\_ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts \_\_\_. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By \_\_\_\_\_ Date \_\_\_\_\_ Time \_\_\_\_\_

Technician Work Sheet      Service Writer : ANDREW, RYAN

Print Date: 10/28/2024

2001 ChAMPION - 730A GRADER UNIT#E032

Hat # :

Repair Order #

VIN # : 031429

Color :

046922

Engine : ser# 46023877 6.8L

Location :

Lic # :

Lic. State :

**CHEMCO-OFF ROAD**

Schedule :

Office 780-436-9570

Promised Date : 10/28/24 5:00 P.M.

Inspection Date : 10/15/13

Status :

Last Service : 2/14/23

Unit # : MG-1429

Current Odometer : 0

Trans :

Previous Mileage : 13,523

Brakes :

Elapsed Mileage : 0

Manufacture Date : 10/15/13

**Labor Description**

**Charged Hours**

<input checked="" type="checkbox"/>	(1) PERFORM INSPECTION AS PER CHECKLIST, SERVICE UNIT AS REQUIRED (OIL SAMPLE IF REQ), VERIFY OPERATIONS. Technician : <none>	3.00
-------------------------------------	--	------

OUT ODOMETER : 13991 H

Total Hours Charged : 3.00

Hours out: 0.00

**Tech Notes**

---



---



---

Unit #: MG-1429      WO # 0469      S/N: \_\_\_\_\_      Odometer: \_\_\_\_\_      Hours: 1399 1/4

Lab#	Repair Description	Date	Location	Tech Name	Hours
1	Drive out to yard and check out MG-1429 tires and starting unit. Started But Rear Left side tire flat fill up and bring in to shop for a yearly inspection.	Oct 28, 24	Shop/yard	Brent Garcia	3h.
1	Remove Top light and get parts. Replace bulb and dc hook all good, put Daily Inspection Book in unit and spill kit, Replace Fire ext. on unit, Top up gear oil in the Tandom chain Drives and Diff, Diff Tooks 5L of oil. Check for coolant Heater operation and Hyd oil Heater function Both work, wash out front filter for fresh air intake, grease unit, fixed washer Sprayers on front windshield and Rear windshield, fill tank, and Start on Right side work light. Remove and start tabbing Bracket.	Oct 29, 24	shop	Brent Garcia	10h
1	Finish up wiring on Right side Light on lower mole Board	Oct 30, 24	shop	Brent Garcia	1 1/2h.
					14.5

Parts \_\_\_\_\_      Mechanic ID: \_\_\_\_\_      Mechanic Signature: \_\_\_\_\_

Qty.	Part #	Description	STK/ORD	Qty.	Part #	Description	STK/ORD
✓ 1	P43+27342	H4 24V 75/70w (E1)	STK.				
✓ 1	31-24	Wiper Blade.	STK.				
✓ 26L	75w 90	gear oil	STK.				
✓ 1		Jug of washer fluid.	STK.				
✓ 2		Tubes of grease	STK.				
✓ 1		Light pad. Work Light.	STK.				

√ P = Pass F = Fail R = Repaired N/A = Not Applicable

UNIT #:	ODOMETER:					ENGINE HOURS:	DATE:				
<i>MG-1429</i>						<i>13991H</i>	<i>OCT. 28, 24</i>				
		P	F	R	N/A			P	F	R	N/A
1	LOCKOUT IN PLACE				✓	22	Mirrors, windows Damage, cleanliness	✓			
2	WHEEL CHOCKS IN PLACE	✓				23	Windshield Wipers & Washers Winter Washer Fluid Only	✓	✓	✓	
3	Oil Samples				✓	24	Engine Oil Level 0w -40 Synthetic in Winter	✓			→
4	Batteries & Hold Downs Cleanliness, loose bolts & nuts	✓				25	Engine Coolant Fluid level and Strength	✓	✓	✓	
5	Covers and guards Damage, secured	✓				26	Engine Pre-cleaner Dirt buildup	✓			
6	Tires, Lug Nuts, Brakes Inflation, damage, stem covers	✓				27	Air Filter Restriction indicator	✓			
7	Tandem housings Trash, dirt buildup, leaks	✓				28	Radiator Debris, damage, leaks	✓			
8	Articulation area Trash or dirt buildup	✓				29	All Hoses Cracks, wear spots, leaks	✓	✓	✓	
9	Air reservoir Drain water and sediment				✓	30	All Belts Tightness, wear, cracks	✓			
10	Transmission Leaks	✓				31	Overall Engine Compartment Trash or dirt buildup, leaks	✓			
11	Underneath Of Machine Differential and tandem leaks	✓				32	Seat Adjustment, pedal travel	✓			
12	Hydraulic Oil Tank Fluid level, damage, leaks	✓	✓	✓		33	Seat Belt & Mounting Damage, wear, adjustment	✓			
13	Fuel Tank: Fuel level, damage, leaks; drain water and sediment	✓				34	Roll Over Protection System Damage, cracks	✓			
14	Circle drive Leaks	✓				35	Horn, backup alarm, lights Proper Function	✓			
15	Hydraulic cylinders, tubes, hoses and fittings: Damage, leaks	✓				36	Controls, gauge lenses Damage, cleanliness, operational	✓			
← 16	Front wheel spindle bearings Leaks	✓				37	Overall Cab Interior Cleanliness	[Handwritten Box]			✓ ←
17	All wheel drive motors Damage, leaks				✓	38	FIRE EXT. CONDITION, DATE, TAG, LOCK, MOUNT	✓	✓	✓	
18	Blade linkage Damage, loose or missing bolts	✓				39	INSPECTION TAG DATE	<i>OCT 2025</i>			
19	Blade and end Parts Excessive wear or damage	✓				40	FIRE EXTINGUISHER TAG #:	<i>4438 0966</i>			
20	Overall Machine: Loose or missing nuts & bolts, Loose guards, cleanliness	✓				41	SPILL KIT PROVIDED	✓			
21	Lights, lenses Damage, cleanliness	✓	✓	✓		42	Daily Inspection Booklet	✓	✓	✓	

V P = Pass F = Fail R = Repaired N/A = Not Applicable

	P	F	R	N/A		P	F	R	N/A
43	✓	✓	✓		48				✓
44	✓				49	✓			
45	✓					✓			
46	✓								✓
47				✓		✓			

**TIRE PRESSURE** (If not recorded on prescribed Alberta Inspection Record) [ ] psi [ ] kPa

60psi LF:      60psi RF:      60psi LR:      60psi RR:

**Charging System TEST**

VOLTS: 24V      AMPS: 80Amps      RPM: 1000Rpm

FUEL LEVEL: Full

**TEST / DRIVE**

TEST [✓] or TEST DRIVE [ ]

Comments:  
unit functions properly No problems

**CLEANING**

	Date	Time	Signature
Washed (Fine Cleaned) <input type="checkbox"/>			
Disinfectant Mist (Clubroot) <input type="checkbox"/>			

Brent Garcia  
Technician (Print Name)

*[Signature]*  
Technician Signature

**MAINTENANCE REQUIRED/REMARKS:**

**INSPECTION REPORT SIGN-OFF**

Brent Garcia  
Technician (Print Name)

*[Signature]*  
Technicians Signature

Supervisors Signature

UNIT #:	MG-1429	UNIT TYPE/DESCRIPTION:			
wo#046922	ODOMETER:	ENGINE HOURS:	13991H	DATE:	OCT, 28, 24

ITEM	REPAIR DESCRIPTION	QUOTED HOURS	ACTUAL HOURS
Done 1	Left Side Top of cab work Light Not working Diagnose.		
Done 2	Rightside Lower Blade Light NOT working Diagnose.		
Done 3	Front whipper Blade worn out Needs Replacing.		
N.A 4	Beacon Light Not working Diagnose.		
Done 5	washer pump Not working Diagnose		
Done 6	Low on coolant need to top up.		
Done 7	Hydraulic oil at Halfway full Needs to Be Toped up		
Done 8	front Hub on Left side Looks Like it Has been Sweating grease cleanup Re grease Both.		
Done 9	Tandom Drives Need To Be Toped up and check for leaks		
cleaned out Done 10	Needs cabin air filters full of dust and fuzz, or clean out?		
Done 11	Brake fluid low check and fill		
Done 12	Need a new Fire Extinguisher		
Done 13	Need a Daily inspection Booklet.		
Done 14	Need To protect some lines on Circle Drive Hyd Lines.		

Brent Garcia  
 Technician (Print Name)
 

  
 Technicians Signature

chemco

Parts Requisition

MTE-0130

UNIT #	MG-1429	ODOMETER		ENGINE HOURS	13991H.	DATE	OCT, 29, 24
EQUIPMENT TYPE / DESCRIPTION			2001 Champion 730A		WO #	046922	

ITEM	QTY	PART#	DESCRIPTION	IN STOCK	ORDER
1	1	31-24	27" windshield wiper blade Front window.		— STK
2					
3					
4					
5					
6					
7					
8					

10/29/24  
RA

Brent Garcia  
Technician (Print Name)

*Brent Garcia*  
Technicians Signature



REQUEST FOR SERVICE FORM

Requested by: Receiving \_\_\_\_\_

Date Required: \_\_\_\_\_

(Please note that 7 days is the norm.  
5 day or less is considered a RUSH.)

Deliver To: Receiving \_\_\_\_\_

Item	Unit	Make	Model
1	MG-1429	Champion	Grader
Description:			
Item	Unit	Make	Model
2			
Description:			
Item	Unit	Make	Model
3			
Description:			
Item	Unit	Make	Model
4			
Description:			

Special Instructions: Please Get Winter Ready \_\_\_\_\_  
\_\_\_\_\_

Attachments: [YES]  [NO]

REQUEST NOTES:

- \* Please email request sheet to [orderdesk@chemco.com](mailto:orderdesk@chemco.com)
- \* A confirmation will be sent to you once the req has been placed.

**WRENCHHEAD MECHANICAL**

3135 4 ST  
NISKU, ALBERTA. T9E-8L1  
Phone: 780-436-9570 Fax: 780- -

*Rd*

**INVOICE**

**40563**

Org. Est. # 057334

**INVOICE**

Printed Date: 02/14/2023 Work Completed: 02/14/2023

**CHEMCO-OFF ROAD**

3135-4 ST  
NISKU, ALBERTA T9E-8L1  
Office 780-436-9570

2001 ChAMPION - 730A GRADER UNIT#E032 - ser# 46023877  
Lic # :  
Unit # : MG-1429  
VIN # : 031429  
Odometer In : 0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
ICE EDGE-ORDER 5D9559ICE	2.00	162.05	324.10	(1) CHANGE OUT ICE EDGE ** REPLACED WORN OUT ICE EDGE	162.50
PLOW BOLT-ORDER .625X2.5	30.00	1.54	46.20		
PLOW BOLT NUT 5/8-ORDER .625	30.00	0.71	21.30		
Shop Supplies			8.13		

Org. Estimate 590.34 Revisions 0.00 Current Estimate 590.34

Labor:	162.50
Parts:	399.73
SubTotal:	562.23
Tax:	28.11
Total:	590.34
Bal Due:	\$590.34

[ Payments - ]

*STK-9*

Vehicle Received: 2/14/2023

Customer Number : 3904

GST#865376503RT0001

Signature \_\_\_\_\_ Date \_\_\_\_\_

**WRENCHHEAD MECHANICAL**

3135 4 ST  
NISKU, ALBERTA. T9E-8L1  
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

**040563**

Org. Est. # 057334

**REPAIR ORDER - RO**

Scheduled : 02/10/2023 12:03 PM

Print Date : 2/13/2023

**CHEMCO-OFF ROAD**

3135-4 ST  
NISKU, ALBERTA T9E-8L1  
Office 780-436-9570  
Cust ID :

2001 ChAMPION - 730A GRADER UNIT#E032 - ser# 4602:

Lic # : -  
Unit # : MG-1429  
VIN # : 031429  
MFG Date : 10/15/2013  
Current Odom : 0

Last Service : 2/11/2022

Previous Odom : 13523

Elapsed : 0

<i>Labor Requested / Part SubTotal</i>	<b>Extended</b>
(1) CHANGE OUT ICE EDGE	162.50
Shop Supplies	8.13
<b>Parts Subtotal</b>	0.00

**Parts: 0.00**                      **Supplies: 8.13**                      **Tax: 8.53**                      **Total: 179.16**  
**Labor: 162.50**                      **Balance: 179.16**

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within \_\_\_ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts \_\_\_\_. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By \_\_\_\_\_ Date \_\_\_\_\_ Time \_\_\_\_\_

Technician Work Sheet      Service Writer : GLAZIER, RUSSELL

Print Date: 2/13/2023

2001 ChAMPION - 730A GRADER UNIT#E032

Hat # :

Repair Order #

VIN # : 031429

Color :

040563

Engine : ser# 46023877 6.8L

Location :

Lic # :

Lic. State :

**CHEMCO-OFF ROAD**

Office 780-436-9570

Schedule : 2/10/23 12:15 P.M.

Promised Date : 2/10/23 5:00 P.M.

Inspection Date : 10/15/13

Status :

Last Service : 2/11/22

Unit # : MG-1429

Current Odometer : 0

Trans :

Previous Mileage : 13,523

Brakes :

Elapsed Mileage : 0

Manufacture Date : 10/15/13

**Labor Description**

**Charged Hours**

(1) CHANGE OUT ICE EDGE

2.50

Technician : <none>

OUT ODOMETER :

Total Hours Charged :

2.50

Hours out: 0.00

**Tech Notes**

---

---

---



DATE

TIME

ODOMETER

HOURS

TRUCK

UNIT

TRAILER

ADDITIONAL TRAILER

### REPAIRS NEEDED

Serrated blade needs to be replaced.

*FEB 10-23*

*11:25 AM*

### SUPPLIES NEEDED

PICKER

DISPATCHER

PRINT

SIGN

SIGNDATE



REQUEST FOR SERVICE FORM

Requested by: Dave Repko

Date Required: \_\_\_\_\_

(Please note that 7 days is the norm.  
5 day or less is considered a RUSH.)

Deliver To: Receiving

Item	Unit	Make	Model
1	MG-1429	Champion	Series VI
Description:	Grader		
Item	Unit	Make	Model
2			
Description:			
Item	Unit	Make	Model
3			
Description:			
Item	Unit	Make	Model
4			
Description:			

Special Instructions: please replace cutting edge

Attachments: [YES]  [NO]

REQUEST NOTES:  
\* Please email request sheet to [orderdesk@chemco.com](mailto:orderdesk@chemco.com)  
\* A confirmation will be sent to you once the req has been placed.



FOUNTAIN TIRE (LEDUC) LTD.

7126 SPARROW DR  
LEDUC AB T9E 8A5

Invoice

Order Number: 017SWO00212047  
Service Contact: JEAN PAUL BENOIT

Phone: 780.980.0000  
Fax 780.986.1786  
F017@FOUNTAINTIRE.COM  
856181748RT0001

Date: 12/11/2022  
Invoice: 0171196497  
PO#: MG1429  
AirMiles # :  
Terms of payment Net\_30

Bill to Customer

Ship to Customer:

Year: NA Unit: MG1429  
Make: CHAMPION  
Model: GRADER  
Design: 730 AUHP  
Engine:  
License: NOPLATE, AB Colour: YELLOW  
Vin: 031429  
Mileage: 13859 Hours: 0

CHEMCO ELECTRICAL CONTRACTORS L' CHEMCO ELECTRICAL CONTRACTORS L'  
3135 4 ST 3135 4 ST  
NISKU AB T9E 8L1 NISKU AB T9E 8L1

Item number	Item description	Qty	Unit price	Total
<b>OTR Tires, Wheels and Service</b>				
TSF051	Flat Repair Dry 1300,1400-24/25	1.00	\$105.00	\$105.00
<b>Tire and Wheel Parts / Hardware</b>				
ORING	OTR ORING	1.00	\$18.95	\$18.95
VS1	OTR Valve Stem Grommet	1.00	\$8.95	\$8.95
VS1	OTR Valve Stem	1.00	\$16.95	\$16.95
<b>Service Call</b>				
SC051	Service Call Crane Hour Rate	1.00	\$150.00	\$150.00
FUEL	Fuel Surcharge	1.00	\$25.00	\$25.00
<b>Other Miscellaneous Items</b>				
SHOP	Shop Supplies	1.00	\$10.50	\$10.50

Customer requirements

PURCHASE ORDER # MG1429  
TRAILER # Grader  
ODOMETER/HUBDOMETER 13859  
LIC # & STATE NOPLATE  
VEH/FLEET/TRLR/UNIT # MG1429

Air Miles: 0

*FILE*

Invoice comment

refer to wo 029361  
service done Nov 7/2022, service call to customer yard, repaired the left middle tire on grader. replaced o-ring in wheel assembly that was leaking, and installed new valve stem in wheel.

I acknowledge: (1) receipt of goods and services; and (2) Fountain Tire may conduct a registry search to verify the VIN on my vehicle if required for collection purposes on unpaid invoices related to my vehicle.

The customer is to ensure all wheel lugs are re torqued by a qualified technician before the vehicle has travelled 100 kilometers.

Parts: \$18.95  
Services: \$316.40  
Sub Total: \$335.35  
GST: \$16.77  
Total: (CAD) \$352.12

Pay type: CFA \$352.12

Please Remit Payment to:

Fountain Tire Ltd.  
Fountain Tire Place  
#301 - 1006-103A Street SW  
Edmonton, Alberta T6W 2P6

X \_\_\_\_\_



FOUNTAIN TIRE (LEDUC) LTD.

7126 SPARROW DR  
LEDUC AB T9E 8A5

Invoice

Order Number: 017SWO00208758  
Service Contact: JEAN PAUL BENOIT

Phone: 780.980.0000  
Fax 780.986.1786  
F017@FOUNTAINTIRE.COM  
856181748RT0001

Date: 16/09/2022  
Invoice: 0171193521  
PO#: MG-1429  
AirMiles # :  
Terms of payment - Net\_30

Bill to Customer

Ship to Customer:

Year: NA Unit: MG1429  
Make: CHAMPION  
Model: GRADER  
Design: 730 AUHP  
Engine:  
License: NOPLATE, AB Colour: YELLOW  
Vin: 031429  
Mileage: 13858 Hours: 0

CHEMCO ELECTRICAL CONTRACTORS L' CHEMCO ELECTRICAL CONTRACTORS  
3135 4 ST 3135 4 ST  
NISKU AB T9E 8L1 NISKU AB T9E 8L1

Item number	Item description	Qty	Unit price	Total
<b>Tire and Wheel Parts / Hardware</b>				
ORING	OTR ORING	2.00	\$18.95	\$37.90
<b>Service Call</b>				
SC031	YARD - Service Call	1.00	\$85.00	\$85.00
FUEL	Fuel Surcharge	1.00	\$25.00	\$25.00
<b>Chassis and Steering Parts and Service</b>				
017-M74425	Flat Repair Dry 1300,1400-24/25	2.00	\$105.00	\$210.00
<b>Heavy Duty Parts and Service</b>				
43442-BLIN	OTR Valve Stem Grommit	2.00	\$8.95	\$17.90
43442-BLIN	OTR Valve Stem	2.00	\$16.95	\$33.90
<b>Other Miscellaneous Items</b>				
SHOP	Shop Supplies	1.00	\$31.26	\$31.26

Customer requirements	
PURCHASE ORDER #	MG-1429
TRAILER #	Grader
ODOMETER/HUBDOMETER	13858
LIC # & STATE	NOPLATE
VEH/FLEET/TRLR/UNIT #	MG1429

Air Miles: 0

FILE

Invoice comment

refer to wo 027560  
service done Aug 23/2022, service call to customer yard, repaired the right front tire, and the left middle tires on grader. replaced o-rings in wheels and cleaned rusted wheel components.

I acknowledge: (1) receipt of goods and services; and (2) Fountain Tire may conduct a registry search to verify the VIN on my vehicle if required for collection purposes on unpaid invoices related to my vehicle.

The customer is to ensure all wheel lugs are re torqued by a qualified technician before the vehicle has travelled 100 kilometers.

Parts:	\$299.70
Services:	\$141.26
Sub Total:	\$440.96
GST:	\$22.05
<b>Total: (CAD)</b>	<b>\$463.01</b>

Pay type: CFA \$463.01

Please Remit Payment to:

Fountain Tire Ltd.  
Fountain Tire Place  
#301 - 1006-103A Street SW  
Edmonton, Alberta T6W 2P6

X \_\_\_\_\_

**37387**

Org. Est. # 054148

**INVOICE**

Ref #: 13769

Date: 02/11/2022

**CHEMCO-OFF ROAD**  
 3135-4 ST  
 NISKU, ALBERTA T9E-8L1  
 Office 780-436-9570

2001 ChAMPION - 730A GRADER UNIT#E032 - ser# 46023877  
 Lic # :  
 Unit # : MG-1429  
 VIN # : 031429  
 Engine Hrs In : 13769.0 Engine Hours Out : 13769.0  
 Odometer In : 0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
FUEL SEPERATOR FILTER-ORDER FS1280	1.00	12.73	12.73	(1) SERVICE UNIT AND INSPECT CUTTING EDGES * QUICK INSPECTION OF UNIT	715.00
OIL FILTER-ORDER LF3000	1.00	43.06	43.06	* TESTED BLOCK HEATER AND LOAD TESTED BATTERIES	
AIR FILTER-ORDER AF975M	1.00	113.23	113.23	* DRAINED ENGINE OIL AND CHANGED FILTERS	
CABIN FILTER -ORDER VOE12725424	1.00	121.04	121.04	* REMOVE CUTTING EDGE AND CLEAN SURFACE. INSTALL NEW CUTTING EDGES AND BOLTS	
ICE EDGE-ORDER 5D9559ICE	2.00	141.00	282.00	* REMOVE DECALS ON UNIT	
PLOW BOLT-ORDER .625X2.5	30.00	1.23	36.90	* GREASE UNIT AND TIGHTEN OIL PAN BOLTS	
PLOW BOLT NUT 5/8-ORDER .625	30.00	0.55	16.50		
OIL SAMPLE JAR-STK 3202711103-50	1.00	23.93	23.93		
FUEL FILTER-STK FF5018	1.00	19.55	19.55		
FUEL FILTER-STK FF149	1.00	5.29	5.29		
SYNTHETIC 5W40 OIL-STK 5W40SYN	24.00	6.23	149.52		
REDTAC #2 GREASE-STK RED-2-14	1.00	4.50	4.50		
BRAKE KLEEN-STK B/C	4.00	2.05	8.20		
Shop Supplies			35.75		

Org. Estimate 1,073.98 Revisions 0.00 Current Estimate 1,073.98

Labor:	715.00
Parts:	872.20
<b>SubTotal:</b>	<b>1,587.20</b>
<b>Tax:</b>	<b>79.36</b>
<b>Total:</b>	<b>1,666.56</b>
<b>Bal Due:</b>	<b>\$1,666.56</b>

STK 247

[ Payments - ]  
 Vehicle Received: 2/2/2022

GST#865376503RT0001  
 Signature \_\_\_\_\_ Date \_\_\_\_\_  
 Customer Number : 3904

**WRENCHHEAD MECHANICAL**

3135 4 ST  
NISKU, ALBERTA. T9E-8L1  
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

**037387**

Org. Est. # 054148

**REPAIR ORDER - RO**

Scheduled : 02/02/2022 08:47 AM

Print Date : 2/2/2022

**CHEMCO-OFF ROAD**

3135-4 ST  
NISKU, ALBERTA T9E-8L1  
Office 780-436-9570  
Cust ID :  
Last Service : 2/1/2022

2001 ChAMPION - 730A GRADER UNIT#E032 - ser# 4602  
Lic # : -  
Unit # : MG-1429  
VIN # : 031429  
MFG Date : 10/15/2013  
Current Odom : 0  
Elapsed : 0

Previous Odom : 13523

**Labor Requested / Part SubTotal**

**Extended**

(1) SERVICE UNIT AND INSPECT CUTTING EDGES

65.00

Shop Supplies

Parts Subtotal 0.00

3.25

Parts: 0.00

Supplies: 3.25

Labor: 65.00

Tax: 3.41

Total: 71.66

Balance: 71.66

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within \_\_\_ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts \_\_\_\_. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By \_\_\_\_\_ Date \_\_\_\_\_ Time \_\_\_\_\_

07608

Technician Work Sheet      Service Writer : GLAZIER, RUSSELL

Print Date: 2/02/2022

2001 ChAMPION - 730A GRADER UNIT#E032

Hat # :

Repair Order #

VIN # : 031429

Color :

**037387**

Engine : ser# 46023877 6.8L

Location :

Lic # :

Lic. State :

**CHEMCO-OFF ROAD**

Schedule : 2/02/22 9:00 A.M.

Office 780-436-9570

Promised Date : 2/02/22 5:00 P.M.

Inspection Date : 10/15/13

Status :

Last Service : 2/01/22

Unit # : MG-1429

Current Odometer : 0

Trans :

Previous Mileage : 13,523

Brakes :

Elapsed Mileage : 0

Manufacture Date : 10/15/13

**Labor Description**

**Charged Hours**

<input checked="" type="checkbox"/> (1) SERVICE UNIT AND INSPECT CUTTING EDGES	1.00
Technician: <none>	

OUT ODOMETER :

**Total Hours Charged : 1.00**

Hours out: 0.00

**Tech Notes**

---



---



---

Unit #: MG-1429

S/N:

Odometer: N/A

Hours: 13769

Lab#	Repair Description	Date	Location	Tech Name	Hours
	Quick inspection of unit wrote up labour and parts req's tested Block heater and load tested batteries	Feb 3/22	Misku	Chase V	8
	Drained Engine oil and changed Filter Replaced Fuel Filters and air Filters remove cutting edge and clean surface remove decals on unit for city Grease unit tighten oil Pan bolts				
	Move unit outside clean-up and Paper work	Feb 4/22	Nisku	Chase V	2
	INSTALL CUTTING EDGES + HARDWARE	FEB 3/22	SHIP	DANNYL M	1

## Parts

Mechanic ID:

Mechanic Signature: \_\_\_\_\_

Qty.	Part #	Description	STK/ORD	Qty.	Part #	Description	STK/ORD
✓ 2		SEPERATED CUTTING EDGES		✓		Grease tube	STK
✓		CUTTING EDGE HARDWARE		✓			
✓ 1	LF3000	oil filter	ORD				
✓ 24		Sw-40	STK				
✓ 1	FS1280	Water seperator	ORD				
✓ 1	AF975M	air filter	ORD				
✓ 1	BF988	Fuel Filter	ORD				
✓ 1	FF149	Fuel Filter	ORD				
✓ 1	VOE12725424	Cab Filter	ORD				









DATE: January 31st, 2022 TIME: \_\_\_\_\_ UNIT: MG-1429

KILOMETERS: \_\_\_\_\_ HOURS: \_\_\_\_\_ NAME: Brian Bittner

TRUCK:

Requires full service and inspect blade, replace if required.  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

TRAILER: # \_\_\_\_\_ & \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

SUPPLIES REQUIRED:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

SIGNATURE: Brian Bittner DISPATCHER: \_\_\_\_\_

SUPPLY PICKER: \_\_\_\_\_