

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780-

C17-9

INVOICE

33959

Org. Est. # 050707

INVOICE

Date: 11/05/2020

CHEMCO ELECTRICAL-EQUIPMENT

3135-4th ST
NISKU, AB T9E-8L1
Office 780-436-9570 -- Fax 780-434-0811

2016 TRAILTECH - TRI AXLE TILT UNIT#08814 -

Lic # : 5FL945

Odometer In : 0

Unit # : TR-8451

VIN # : 46UFU2437 **G1178451**

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
2 5/16" HITCH COUPLER-ORDER NTP81906	1.00	43.78	43.78	(1) PERFORM INSPECTION AS PER CHECKLIST, SERVICE UNIT AS REQUIRED (OIL SAMPLE IF REQ), VERIFY OPERATIONS. * CHECKOVER UNIT * UNSEIZE TILT LATCH * INSTALL BALL STYLE HITCH * VERIFY 2 ARGOS FIT * REPLACE 3 MARKER LIGHTS * REPLACE LATCH ON TOOL BOX	390.00
HITCH CHANNEL MOUNT-ORDER NTP8978XL	1.00	44.24	44.24		
3/4 HITCH PLATE-ORDER NTP716625750	1.00	150.84	150.84		
3/4" LED RED LIGHT/GROMMET-STK 33050-R	2.00	9.59	19.18		
3/4" LED AMBER LIGHT/GROMMET-STK 33050-Y	1.00	13.09	13.09		
Shop Supplies			19.50		

Org. Estimate 465.79 Revisions 0.00 Current Estimate 465.79

Labor:	390.00
Parts:	290.63
SubTotal:	680.63
Tax:	34.03
Total:	714.66
Bal Due:	\$714.66

[Payments -]
Vehicle Received: 2020-10-30

STK-53

Customer Number : 2548

GST#865376503RT0001

Signature _____ Date _____

WRENCHHEAD MECHANICAL

3135 4 ST
NISKU, ALBERTA. T9E-8L1
Phone: 780-436-9570 Fax: 780- -

REPAIR ORDER #

033959

Org. Est. # 050707

REPAIR ORDER - RO

Scheduled : 10/30/2020 12:38 PM

Print Date : 10/30/2020

CHEMCO ELECTRICAL-EQUIPMENT

3135-4th ST
NISKU, AB T9E-8L1
Office 780-436-9570 --- Fax 780-434-0811
Cust ID :
Last Service : 2020-02-26

2016 TRAILTECH - TRI AXLE TILT UNIT#08814 -

Lic # : 5FL945 - AB
Unit # : TR-8451
VIN # : 46UFU2437 **G1178451**
MFG Date : 11/8/2017
Current Odom : 0

Elapsed : 0

Labor Requested / Part SubTotal

Extended

(1) PERFORM INSPECTION AS PER CHECKLIST, SERVICE UNIT AS REQUIRED (OIL SAMPLE IF REQ), VERIFY OPERATIONS.

195.00

Parts Subtotal 238.86

Shop Supplies

9.75

Parts: 238.86
Labor: 195.00

Supplies: 9.75

Tax: 22.18

Total: 465.79
Balance: 465.79

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ___ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts ____. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO MY VEHICLE OR ARTICLES LEFT IN VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ALL VEHICLES LEFT MUST HAVE OWN INSURANCE. ANY VEHICLES LEFT OVER 30 DAYS WITHOUT CONSENT WILL BE PROPERTY OF WRENCHHEAD MECHANICAL.

Authorized By _____ Date _____ Time _____

2016 TRAILTECH - TRI AXLE TILT UNIT#08814

Hat # :

Repair Order #

VIN # : 46UFU2437 G1178451

Color :

033959

Engine :

Location :

Lic # : 5FL945

Lic. State : AB

CHEMCO ELECTRICAL-EQUIPMENT

Schedule : 10/30/20 12:45 P.M.

Office 780-436-9570 --- Fax 780-434-0811

Promised Date : 10/30/20 5:00 P.M.

Inspection Date : 11/08/17

Status :

Last Service : 2/26/20

Unit # : TR-8451

Current Odometer : 0

Trans :

Previous Mileage : 0

Brakes :

Elapsed Mileage : 0

Manufacture Date : 11/08/17

Part Number	Part Description	Qty	Part Location
<input type="checkbox"/> NTP81906	2 5/16" HITCH COUPLER-ORDER	1.00	
<input type="checkbox"/> NTP8978XL	HITCH CHANNEL MOUNT-ORDER	1.00	
<input type="checkbox"/> NTPTNP716625750	3/4 HITCH PLATE-ORDER	1.00	

Labor Description	Charged Hours
<input type="checkbox"/> (1) PERFORM INSPECTION AS PER CHECKLIST, SERVICE UNIT AS REQUIRED (OIL SAMPLE IF REQ), VERIFY OPERATIONS. Technician : <none>	3.00

OUT ODOMETER :

Total Hours Charged : 3.00

Hours out: 0.00

Tech Notes
